


# SCHRADER TIRE PRESSURE MONITORING SYSTEMS

## ▶▶ 2013 SENSOR & SERVICE PACK APPLICATION CATALOG



# Table of Contents

TPMS Tools and Accessories.....	1-7
TPMS Sensors/Transmitters & Service Packs - Alphabetical Listing .....	8-74
Manufacturers' Part Numbers.....	75-76
TPMS Sensors/Transmitters - Numerical Listing.....	77-92
TPMS Service Packs - Numerical Listing .....	93-108
NHTSA TREAD Act.....	Inside Back Cover

## **Schrader International, Inc. Limited Warranty**

Schrader International, Inc. ("Schrader") warrants that its products will be free from defects in materials and workmanship for a period of twelve (12) months from the date of shipment from Schrader's facility or delivery (whichever occurs first). Schrader will, at its option, replace or repair any product proved defective in materials or workmanship, or both, during the warranty period. This shall be the sole and exclusive remedy for breach of warranty. THE FOREGOING WARRANTY IS EXCLUSIVE AND IN LIEU OF ALL OTHER WARRANTIES EXCEPT THAT OF TITLE, WHETHER WRITTEN, ORAL OR IMPLIED, IN FACT OR IN LAW (INCLUDING ANY WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE). LIABILITY FOR SPECIAL, INDIRECT, INCIDENTAL, PUNITIVE OR CONSEQUENTIAL DAMAGES (INCLUDING, WITHOUT LIMITATION, DAMAGES FOR LOSS OF PROFITS, BUSINESS INTERRUPTION OR ANY OTHER LOSS), HEREBY ARE EXPRESSLY EXCLUDED TO THE EXTENT PERMITTED BY LAW, WHETHER BASED IN CONTRACT, NEGLIGENCE, TORT, WARRANTY OR OTHER WRONGFUL ACT OR OMISSION OF SELLER AND EVEN IF SELLER HAS BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES.

This warranty does not extend to (a) any defects or losses due to misuse, accident, abuse, neglect, or normal wear and tear; (b) any use not recommended in writing by Schrader; (c) any defects or losses relating to or caused by purchaser or a third party; or (d) any defects or losses relating to or caused by the effects of weathering, air pollution, corrosion, or exposure to harmful/caustic materials and/or chemicals.

Additionally, due to the variety of operating conditions or applications, the customer is responsible to perform their own testing to insure performance, safety and warning requirements for the intended application. Schrader has not tested the compatibility of the Goods with non-Schrader products for fit and suitability for use in conjunction with the Goods. Defects, damages or losses caused by use of non-Schrader products, replacement parts and/or service packs are not covered by Schrader's limited warranty.

► **Nut Torque Tool with Sockets – 20138**

Torque wrench for valve nuts on TPMS installations. Kit includes 12mm and 11mm sockets for the two nut sizes used today, plus screwdriver handle for easy use. Torque range from 4.25 N.m. to 7.5 N.m. Accuracy plus or minus 4 percent. Includes plastic storage case. (One per carton)



► **Nut Torque Wrench Kit – 20139**

Torque tool and precision quality torque wrench for installing TPMS sensor nuts. Includes 12 mm and 11 mm sockets. Torque range from 2 N.m. to 10 N.m. Accuracy plus or minus 2 percent. Includes plastic storage tray. (One per carton)



► **T-10 Torque Tool – 20140**

Installs replacement snap-in valves to Schrader® OE sensors. T-10 Torx head installs screws to recommended torque for proper sealing and secure installation. Order individually. (One per box)



► **Valve Core Torque Tool – 20141**

Tighten valve cores to OE specifications. Helps guard against over or under-torquing. Meets Tire and Rim Association (TRA) recommended torque values of 3" to 5" lbs. on TRC1 valve cores. Serves as both a core remover and installer. Order individually. (One per box)



► **Universal Nut Torque Tool – 20142**

Serves as a torque wrench for valve nuts on TPMS installations. Kit includes 11mm and 12mm sockets and T-handle torque wrench with ergonomic design. Torque range from 30 to 90 in/lbs. (One per plastic storage case)



► **Replacement 11mm Socket – 21310**

Order Individually.

► **Replacement 12mm Socket – 21315**

Order Individually.

▶ **Grommet Removal Tool – 20144**

This hand tool is designed to safely remove the rubber grommet from the aluminum stem of a TPMS sensor. Receiving hole can be used to install a new grommet. (10 per carton)



▶ **T-20 Torque Tool – 20145**

A pre-set torque tool specially designed for use with TPMS sensors that use a T-20 screw to attach the aluminum valve stem to the sensor body. The T-20 Torx head installs screws to recommended torque for proper sealing and secure installation.



▶ **Schrader TPMS Training DVD (English) – 21355**

Order Individually.

▶ **Schrader TPMS Training DVD (French) – 21356**

Order Individually.

▶ **Schrader TPMS Training DVD (Spanish) – 21357**

Order Individually.



▶ **Nissan® Reset Tool – 21370**

This trigger tool activates the TPMS learning mode on late model Nissans. (One per carton)





## Chrome Caps and Sleeves

Make your TPMS valve stems look as good as the rest of your ride with dress-up sleeves. Chrome finish dress up kits are available for rubber snap-in sensors. Each kit includes a fully plated sleeve and sealing cap to resist galvanic corrosion of TPMS sensors.


### ► Chrome caps and sleeves for rubber snap-in sensor

22005 Order in multiples of 50.  
Bulk Packaged (50 caps and 50 sleeves per carton)



### ► Complete snap-in valve service pack with chrome caps and sleeves

22008 Individual bags. (50 bags per carton)  
Each bag contains one sleeve, one cap and one TT valve. Order in multiples of 50.



## Banded TPMS Replacement Parts

All of the components required to repair banded TPMS systems. These parts to be used with sensor part numbers 28385, 28390 and 28395.


### ► Replacement Clip

22100 Order individually.  
Bulk Packaged. (25 per box)



### ► Replacement Cradle

22101 Order individually. (10 per carton)










### ► Universal band

Fits rims 14-26"

22102 Order individually. (One per bag)



### ▶ Accessory and loose part items

- 20055 nickel-plated valve cores – 100/box 
- 20395 plastic sealing valve caps – 100/box 
- 20595 long black sealing valve caps for Schrader snap-in sensors  
Fits EZ-sensors 33000 & 33100, replacement sensors 20153,  
20398, 28203, 28206, 28308, 28362, 28434, 28461 & 28505,  
and Service Pack 20008 & 20018 valves – 100/box 
- 20695 long green (Nitrogen) sealing valve caps for snap-in sensors – 100/box 
- 20795 green (Nitrogen) sealing valve caps – 100/box 
- 20895 replacement T-10 screw – 25/bag 
- 20995 long black sealing valve caps for Ford snap-in sensors  
Fits EZ-sensors 33000 & 33100, replacement sensor 20315  
and Service Pack 20008 & 20018 valves – 100/box 

### ▶ TPMS Retrofit Kits

Schrader® TPMS Retrofit Kits install on vehicles not equipped with original equipment systems. The stand-alone kits include a dash-mounted receiver display, four wheel-mounted transmitters that fit most wheel applications and installation instructions.



#### TPMS retrofit kits:

- Continually monitor tire pressure in all four tires
- Monitor tire temperature
- Signal audible warning at under-inflation of 25 percent or more
- Capable of monitoring spare tire (Fifth sensor sold separately as part no. 20154)

**TPMS systems monitor proper tire pressure to maintain vehicle performance and support safety.**

#### Properly inflated tires:

- Improve vehicle handling
- Reduce braking distances
- Lower the risk of hydroplaning
- Decrease tire wear
- Improve fuel efficiency

#### Schrader offers two kits:

- **SCH-WRK-4PC** - hard wired display
- **SCH-BRK-4PC** - battery operated display (two AA batteries included)
- **20154** - 433 MHz sensor (Fits both kits)

# EZ-SENSOR TOOL COMPATIBILITY

## ▶▶ PROGRAM EZ-SENSOR WITH ANY OF THESE TPMS TOOLS



Snap-On	OTC	MAC	Matco	Schrader	NAPA	Bartec	Bartec	Bartec	Bartec	Bartec
---------	-----	-----	-------	----------	------	--------	--------	--------	--------	--------

TPMS2	3834	ET3824	TPR3834	21230	92-1525	Tech300SD	Tech400	Tech400+	Tech400SD	TPMS Pad
-------	------	--------	---------	-------	---------	-----------	---------	----------	-----------	----------

Combination tools provide BOTH activation and scan tool functions

### ▶ 21230 Accessories

The Schrader® **21225** OBD adapter kit enables current owners of the **21220** learn tool to upgrade their tool to a **21230** learn tool and enjoy all of the benefits listed above.

**NOTE: Parts can be ordered separately.**

- OBD Connector – Part Number **21225-OB1**
- OBD Cable – Part Number **21225-OB2**
- OBD tool only – Part Number **21230-R**



### 21230 Components

- **21230** DBL+ learn and test tool
- Hard plastic case – Part Number **21222**
- One USB cable – Part Number **21219**
- Magnet (necessary to activate some sensors) – Part Number **20143**
- Protective rubber boot – Part Number **21221**
- Rechargeable 9-volt battery – Part Number **21216**
- Charger – Part Number **21218**
- OBD connector and cable
- User guide

## Learn Tools - Continued

### ▶ **21250 TPMS Toyota® Reset Tool**

If a Toyota sensor has been broken or a new one installed (without being programmed to the car) AND THE RESET BUTTON WAS PUSHED, the vehicle can get caught in a "loop" and therefore cannot be repaired. There is only one way to fix this issue. The initialization process must be reset before new sensors can be registered to the vehicle. The Solution: The Toyota Reset Tool from Schrader. Simply plug the 21250 (Toyota Reset Tool) into the OBD and push and hold the button for 30 seconds. The system will reset and you can now repair and relearn the vehicle.



### ▶ **EZ-sensor Programming Fixture – 35300**

This fixture positions the 21230 scan/programming tool and EZ-sensor programmable sensor in the optimum orientation for programming.



### ▶ **EZ-sensor Programming Fixture – 35400**

This fixture positions the Bartec Tech400 and Tech400SD scan/programming tools and EZ-sensor programmable sensor in the optimum orientation for programming.



### ▶ **Aluminum clamp-in style valve – 34000**

Aluminum stem service pack to rebuild the Schrader rubber valve snap-in sensor with an aluminum clamp-in style valve stem to match or upgrade existing look.

Fits Schrader OE replacement sensor part numbers: 20153, 20315, 20398, 28203, 28206, 28308, 28434, 28461, 28362, 28505

Fits Schrader EZ-sensor part numbers: 33000, 33100






## ► Service Pack Assortment

Schrader® offers a Service Pack Assortment that contains the most popular vehicle-specific service packs in a handy plastic box.

**20598** assortment with 8 each of twelve service packs.

Contents:	Qty.
20002	8
20003	8
20004	8
20008	8
20013	8
20014	8
20020	8
20021	8
20023	8
20030	8
20032	8
20036	8



**CAUTION:** Always use new grommets, nuts, valve caps and valve cores when performing any tire service. Use nickel-plated electroless valve cores with aluminum valve stems and use rubber snap-in replacement stems when servicing snap-in sensors. Refer to manufacturer's specifications for proper torque requirements when replacing nuts and valve cores.

## Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
<b>► Acura</b>				<b>► Acura - Continued</b>			
<b>2013</b>				<b>2004</b>			
<b>MDX; RDX</b>				<b>MDX</b>			
Sensor .....	20098	35	4	Sensor .....	28981	35	4
<b>2012</b>				Service Pack; Includes Valve .....	20036	35	4
<b>MDX; RDX</b>				Service Pack; Does Not Include Valve .	20021	35	4
Sensor .....	20098	35	4	<b>► Audi</b>			
<b>TL</b>				<b>2012</b>			
Sensor .....	20720	35	4	<b>A3; A4; A5; Q5</b>			
Service Pack .....	20019	35	4	Sensor .....	20088	71	8
<b>TSX</b>				Service Pack .....	20017	71	8
Sensor .....	20098	35	4	<b>Q7; R8</b>			
<b>2011-2009</b>				Sensor; Includes Transmitter Only .....	20103	35	4
<b>CSX</b>				Service Pack; Does Not Include Valve .	20023	35	4
EZ-sensor - 315 MHz .....	↔33000	11.5	1.3	Service Pack; W/43mm Silver Insert ...	20037	35	4
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Service Pack; W/48mm Green Insert ...	20038	35	4
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack; W/49mm Black Insert .....	20039	35	4
Sensor .....	28720	35	4	Service Pack; W/51mm Orange Insert .	20040	35	4
Service Pack .....	20019	35	4	<b>S5</b>			
<b>MDX; RDX</b>				Sensor .....	20088	71	8
Sensor .....	20098	35	4	Service Pack .....	20017	71	8
<b>RL</b>				<b>2011</b>			
Sensor .....	28981	35	4	<b>A3; A4; A5</b>			
Service Pack; Includes Valve .....	20036	35	4	Sensor .....	20088	71	8
Service Pack; Does Not Include Valve .	20021	35	4	Service Pack .....	20017	71	8
<b>TL</b>				<b>A6</b>			
Sensor .....	20720	35	4	Sensor; Includes Transmitter Only .....	20077	35	4
Service Pack .....	20019	35	4	Service Pack; Does Not Include Valve .	20023	35	4
<b>TSX</b>				Service Pack; W/43mm Silver Insert ...	20037	35	4
Sensor .....	20098	35	4	Service Pack; W/48mm Green Insert ...	20038	35	4
<b>2008</b>				Service Pack; W/49mm Black Insert .....	20039	35	4
<b>CSX</b>				Service Pack; W/51mm Orange Insert .	20040	35	4
EZ-sensor - 315 MHz .....	↔33000	11.5	1.3	<b>Q5</b>			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor .....	20088	71	8
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack .....	20017	71	8
Sensor .....	28720	35	4	<b>Q7</b>			
Service Pack .....	20019	35	4	Sensor; Includes Transmitter Only .....	20077	35	4
<b>MDX; RDX</b>				Service Pack; Does Not Include Valve .	20023	35	4
Sensor .....	20098	35	4	Service Pack; W/43mm Silver Insert ...	20037	35	4
<b>RL; TL</b>				Service Pack; W/48mm Green Insert ...	20038	35	4
Sensor .....	28981	35	4	Service Pack; W/49mm Black Insert .....	20039	35	4
Service Pack; Includes Valve .....	20036	35	4	Service Pack; W/51mm Orange Insert .	20040	35	4
Service Pack; Does Not Include Valve .	20021	35	4	<b>R8</b>			
<b>TSX</b>				Sensor .....	20103	35	4
Sensor .....	20098	35	4	Service Pack; Does Not Include Valve .	20023	35	4
<b>2007</b>				Service Pack; W/43mm Silver Insert ...	20037	35	4
<b>MDX; RDX</b>				Service Pack; W/48mm Green Insert ...	20038	35	4
Sensor .....	20098	35	4	Service Pack; W/49mm Black Insert .....	20039	35	4
<b>RL; TL</b>				Service Pack; W/51mm Orange Insert .	20040	35	4
Sensor .....	28981	35	4	<b>S4; S5</b>			
Service Pack; Includes Valve .....	20036	35	4	Sensor .....	20088	71	8
Service Pack; Does Not Include Valve .	20021	35	4	Service Pack .....	20017	71	8
<b>TSX</b>				<b>S6</b>			
Sensor .....	20098	35	4	Sensor; Includes Transmitter Only .....	20077	35	4
<b>2006-2005</b>				Service Pack; Does Not Include Valve .	20023	35	4
<b>MDX; RL; TL</b>				Service Pack; W/43mm Silver Insert ...	20037	35	4
Sensor .....	28981	35	4	Service Pack; W/48mm Green Insert ...	20038	35	4
Service Pack; Includes Valve .....	20036	35	4	Service Pack; W/49mm Black Insert .....	20039	35	4
Service Pack; Does Not Include Valve .	20021	35	4	Service Pack; W/51mm Orange Insert .	20040	35	4
<b>TT</b>				Sensor .....	20088	71	8
<b>2006-2005</b>				Service Pack .....	20017	71	8
<b>MDX; RL; TL</b>							
Sensor .....	28981	35	4				
Service Pack; Includes Valve .....	20036	35	4				
Service Pack; Does Not Include Valve .	20021	35	4				

↔ Programming Tool Required.

## Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
<b>► Audi - Continued</b>				<b>► Audi - Continued</b>			
<b>2010</b>				<b>2009 - Continued</b>			
<b>A3; A4; A5</b>				<b>Q7; R8; S4</b>			
Sensor .....	20088	71	8	Sensor; Includes Transmitter Only .....	20078	35	4
Service Pack .....	20017	71	8	Service Pack; Does Not Include Valve .	20023	35	4
<b>A6</b>				Service Pack; W/43mm Silver Insert ....	20037	35	4
Sensor; Includes Transmitter Only .....	20103	35	4	Service Pack; W/48mm Green Insert ...	20038	35	4
Service Pack; Does Not Include Valve .	20023	35	4	Service Pack; W/49mm Black Insert .....	20039	35	4
Service Pack; W/43mm Silver Insert ....	20037	35	4	Service Pack; W/51mm Orange Insert .	20040	35	4
Service Pack; W/48mm Green Insert ...	20038	35	4	<b>S5</b>			
Service Pack; W/49mm Black Insert ....	20039	35	4	Sensor .....	20088	71	8
Service Pack; W/51mm Orange Insert .	20040	35	4	Service Pack .....	20017	71	8
<b>A8</b>				<b>S6</b>			
Sensor; Includes Transmitter Only .....	20077	35	4	Sensor; Includes Transmitter Only .....	20078	35	4
Service Pack; Does Not Include Valve .	20023	35	4	Service Pack; Does Not Include Valve .	20023	35	4
Service Pack; W/43mm Silver Insert ....	20037	35	4	Service Pack; W/43mm Silver Insert ....	20037	35	4
Service Pack; W/48mm Green Insert ...	20038	35	4	Service Pack; W/48mm Green Insert ...	20038	35	4
Service Pack; W/49mm Black Insert ....	20039	35	4	Service Pack; W/49mm Black Insert .....	20039	35	4
Service Pack; W/51mm Orange Insert .	20040	35	4	Service Pack; W/51mm Orange Insert .	20040	35	4
<b>Q5</b>				<b>S8</b>			
Sensor .....	20088	71	8	Sensor; Includes Transmitter Only .....	20077	35	4
Service Pack .....	20017	71	8	Service Pack; Does Not Include Valve .	20023	35	4
<b>Q7; R8</b>				Service Pack; W/43mm Silver Insert ....	20037	35	4
Sensor; Includes Transmitter Only .....	20103	35	4	Service Pack; W/48mm Green Insert ...	20038	35	4
Service Pack; Does Not Include Valve .	20023	35	4	Service Pack; W/49mm Black Insert .....	20039	35	4
Service Pack; W/43mm Silver Insert ....	20037	35	4	Service Pack; W/51mm Orange Insert .	20040	35	4
Service Pack; W/48mm Green Insert ...	20038	35	4	<b>TT</b>			
Service Pack; W/49mm Black Insert ....	20039	35	4	Sensor .....	20088	71	8
Service Pack; W/51mm Orange Insert .	20040	35	4	Service Pack .....	20017	71	8
<b>S4; S5</b>				<b>2008</b>			
Sensor .....	20088	71	8	<b>A3</b>			
Service Pack .....	20017	71	8	Sensor .....	20088	71	8
<b>S6</b>				Service Pack .....	20017	71	8
Sensor; Includes Transmitter Only .....	20103	35	4	<b>A4</b>			
Service Pack; Does Not Include Valve .	20023	35	4	Sensor; Includes Transmitter Only .....	20078	35	4
Service Pack; W/43mm Silver Insert ....	20037	35	4	Service Pack; Does Not Include Valve .	20023	35	4
Service Pack; W/48mm Green Insert ...	20038	35	4	Service Pack; W/43mm Silver Insert ....	20037	35	4
Service Pack; W/49mm Black Insert ....	20039	35	4	Service Pack; W/48mm Green Insert ...	20038	35	4
Service Pack; W/51mm Orange Insert .	20040	35	4	Service Pack; W/49mm Black Insert .....	20039	35	4
<b>TT</b>				Service Pack; W/51mm Orange Insert .	20040	35	4
Sensor .....	20088	71	8	<b>A5</b>			
Service Pack .....	20017	71	8	Sensor .....	20088	71	8
<b>2009</b>				Service Pack .....	20017	71	8
<b>A3; A4; A5</b>				<b>A6</b>			
Sensor .....	20088	71	8	Sensor; Includes Transmitter Only .....	20078	35	4
Service Pack .....	20017	71	8	Service Pack; Does Not Include Valve .	20023	35	4
<b>A6</b>				Service Pack; W/43mm Silver Insert ....	20037	35	4
Sensor; Includes Transmitter Only; Exc.				Service Pack; W/48mm Green Insert ...	20038	35	4
Quattro .....	20078	35	4	Service Pack; W/49mm Black Insert .....	20039	35	4
Sensor; Includes Transmitter Only;				Service Pack; W/51mm Orange Insert .	20040	35	4
Quattro .....	20103	35	4	<b>A8</b>			
Service Pack; Does Not Include Valve .	20023	35	4	Sensor; Includes Transmitter Only .....	20077	35	4
Service Pack; W/43mm Silver Insert ....	20037	35	4	Service Pack; Does Not Include Valve .	20023	35	4
Service Pack; W/48mm Green Insert ...	20038	35	4	Service Pack; W/43mm Silver Insert ....	20037	35	4
Service Pack; W/49mm Black Insert ....	20039	35	4	Service Pack; W/48mm Green Insert ...	20038	35	4
Service Pack; W/51mm Orange Insert .	20040	35	4	Service Pack; W/49mm Black Insert .....	20039	35	4
<b>A8</b>				Service Pack; W/51mm Orange Insert .	20040	35	4
Sensor; Includes Transmitter Only .....	20077	35	4	<b>Q7; R8; RS4; S4</b>			
Service Pack; Does Not Include Valve .	20023	35	4	Sensor; Includes Transmitter Only .....	20078	35	4
Service Pack; W/43mm Silver Insert ....	20037	35	4	Service Pack; Does Not Include Valve .	20023	35	4
Service Pack; W/48mm Green Insert ...	20038	35	4	Service Pack; W/43mm Silver Insert ....	20037	35	4
Service Pack; W/49mm Black Insert ....	20039	35	4	Service Pack; W/48mm Green Insert ...	20038	35	4
Service Pack; W/51mm Orange Insert .	20040	35	4	Service Pack; W/49mm Black Insert .....	20039	35	4
<b>Q5</b>				Service Pack; W/51mm Orange Insert .	20040	35	4
Sensor .....	20088	71	8	<b>2007</b>			
Service Pack .....	20017	71	8	<b>A3</b>			



## Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
<b>► Audi - Continued</b>				<b>► Bentley - Continued</b>			
<b>2004 - Continued</b>				<b>2010-2006 - Continued</b>			
<b>S4 - Continued</b>				<b>Continental - Continued</b>			
Service Pack; W/51mm Orange Insert .	20040	35	4	Service Pack; Does Not Include Valve .	20023	35	4
<b>2003</b>				Service Pack; W/43mm Silver Insert ....	20037	35	4
<b>A4</b>				Service Pack; W/48mm Green Insert ...	20038	35	4
Sensor; Includes Transmitter Only .....	20078	35	4	Service Pack; W/49mm Black Insert .....	20039	35	4
Service Pack; Does Not Include Valve .	20023	35	4	Service Pack; W/51mm Orange Insert .	20040	35	4
Service Pack; W/43mm Silver Insert ....	20037	35	4	<b>2005-2003</b>			
Service Pack; W/48mm Green Insert ...	20038	35	4	<b>Continental</b>			
Service Pack; W/49mm Black Insert .....	20039	35	4	Sensor; Includes Transmitter Only .....	20077	35	4
Service Pack; W/51mm Orange Insert .	20040	35	4	Service Pack; Does Not Include Valve .	20023	35	4
<b>A8</b>				Service Pack; W/43mm Silver Insert ....	20037	35	4
Sensor; Includes Transmitter Only;				Service Pack; W/48mm Green Insert ...	20038	35	4
Chassis No. 4E300001 & After .....	20077	35	4	Service Pack; W/49mm Black Insert .....	20039	35	4
Sensor; Includes Transmitter Only;				Service Pack; W/51mm Orange Insert .	20040	35	4
Chassis No. 4D3004999 & Before ....	20079	35	4	<b>► BMW</b>			
Service Pack; Does Not Include Valve .	20023	35	4	<b>2013</b>			
Service Pack; W/43mm Silver Insert ....	20037	35	4	<b>135I; 135IS; 328I; 335I; 335IS; 528I; 535I; 550I; 640I; 650I; 740I; 740LI; 750I; 750LI; M3; M5; M6; X1; X3; X5; X6; Z4</b>			
Service Pack; W/48mm Green Insert ...	20038	35	4	Sensor; Includes Transmitter Only .....	28081	31	3.5
Service Pack; W/49mm Black Insert .....	20039	35	4	Service Pack; Does Not Include Valve .	20023	31	3.5
Service Pack; W/51mm Orange Insert .	20040	35	4	Service Pack; W/43mm Silver Insert ....	20037	31	3.5
<b>Allroad Quattro</b>				Service Pack; W/48mm Green Insert ...	20038	31	3.5
Sensor; Includes Transmitter Only .....	20079	35	4	Service Pack; W/49mm Black Insert .....	20039	31	3.5
Service Pack; Does Not Include Valve .	20023	35	4	Service Pack; W/51mm Orange Insert .	20040	31	3.5
Service Pack; W/43mm Silver Insert ....	20037	35	4	<b>2012</b>			
Service Pack; W/48mm Green Insert ...	20038	35	4	<b>128I; 135I; 328I; 335D; 335I; 335IS; 528I; 535I; 550I; 640I; 650I; 740I; 740LI; 750I; 750LI</b>			
Service Pack; W/49mm Black Insert .....	20039	35	4	Sensor; Includes Transmitter Only .....	28081	31	3.5
Service Pack; W/51mm Orange Insert .	20040	35	4	Service Pack; Does Not Include Valve .	20023	31	3.5
<b>S8</b>				Service Pack; W/43mm Silver Insert ....	20037	31	3.5
Sensor; Includes Transmitter Only;				Service Pack; W/48mm Green Insert ...	20038	31	3.5
Chassis No. 4E300001 & After .....	20077	35	4	Service Pack; W/49mm Black Insert .....	20039	31	3.5
Sensor; Includes Transmitter Only;				Service Pack; W/51mm Orange Insert .	20040	31	3.5
Chassis No. 4D3004999 & Before ....	20079	35	4	<b>ActiveE</b>			
Service Pack; Does Not Include Valve .	20023	35	4	Sensor; Includes Transmitter Only .....	28081	31	3.5
Service Pack; W/43mm Silver Insert ....	20037	35	4	<b>M1; M3; X1; X3; X5; X6; Z4</b>			
Service Pack; W/48mm Green Insert ...	20038	35	4	Sensor; Includes Transmitter Only .....	28081	31	3.5
Service Pack; W/49mm Black Insert .....	20039	35	4	Service Pack; Does Not Include Valve .	20023	31	3.5
Service Pack; W/51mm Orange Insert .	20040	35	4	Service Pack; W/43mm Silver Insert ....	20037	31	3.5
<b>2002</b>				Service Pack; W/48mm Green Insert ...	20038	31	3.5
<b>A4</b>				Service Pack; W/49mm Black Insert .....	20039	31	3.5
Sensor; Includes Transmitter Only .....	20078	35	4	Service Pack; W/51mm Orange Insert .	20040	31	3.5
Service Pack; Does Not Include Valve .	20023	35	4	<b>2011</b>			
Service Pack; W/43mm Silver Insert ....	20037	35	4	<b>128I</b>			
Service Pack; W/48mm Green Insert ...	20038	35	4	Sensor; Includes Transmitter Only .....	20083	31	3.5
Service Pack; W/49mm Black Insert .....	20039	35	4	Service Pack; Does Not Include Valve .	20023	31	3.5
Service Pack; W/51mm Orange Insert .	20040	35	4	Service Pack; W/43mm Silver Insert ....	20037	31	3.5
<b>A8; Allroad Quattro; S8</b>				Service Pack; W/48mm Green Insert ...	20038	31	3.5
Sensor; Includes Transmitter Only .....	20079	35	4	Service Pack; W/49mm Black Insert .....	20039	31	3.5
Service Pack; Does Not Include Valve .	20023	35	4	Service Pack; W/51mm Orange Insert .	20040	31	3.5
Service Pack; W/43mm Silver Insert ....	20037	35	4	<b>328I; 335D; 335I</b>			
Service Pack; W/48mm Green Insert ...	20038	35	4	Sensor; Includes Transmitter Only .....	28081	31	3.5
Service Pack; W/49mm Black Insert .....	20039	35	4	Service Pack; Does Not Include Valve .	20023	31	3.5
Service Pack; W/51mm Orange Insert .	20040	35	4	Service Pack; W/43mm Silver Insert ....	20037	31	3.5
<b>2001</b>				Service Pack; W/48mm Green Insert ...	20038	31	3.5
<b>A8; Allroad Quattro; S8</b>				Service Pack; W/49mm Black Insert .....	20039	31	3.5
Sensor; Includes Transmitter Only .....	20079	35	4	Service Pack; W/51mm Orange Insert .	20040	31	3.5
Service Pack; Does Not Include Valve .	20023	35	4	<b>528I; 535I; 550I; 740I; 740LI; 750I; 750LI; 760LI</b>			
Service Pack; W/43mm Silver Insert ....	20037	35	4	Sensor; Includes Transmitter Only .....	20083	31	3.5
Service Pack; W/48mm Green Insert ...	20038	35	4	Service Pack; Does Not Include Valve .	20023	31	3.5
Service Pack; W/49mm Black Insert .....	20039	35	4	Service Pack; W/43mm Silver Insert ....	20037	31	3.5
Service Pack; W/51mm Orange Insert .	20040	35	4	Service Pack; W/48mm Green Insert ...	20038	31	3.5
<b>► Bentley</b>				Service Pack; W/49mm Black Insert .....	20039	31	3.5
<b>2010-2006</b>				Service Pack; W/51mm Orange Insert .	20040	31	3.5
<b>Continental</b>				<b>2010-2006</b>			
Sensor; Includes Transmitter Only .....	20078	35	4	<b>Continental</b>			





## Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
<b>► BMW - Continued</b>				<b>► BMW - Continued</b>			
<b>2007</b>				<b>2005</b>			
<b>323I; 328I; 328XI; 335I; 335XI; 525I; 525XI; 530I; 530XI; 550I; 650I; 750I; 750LI; 760LI; Alpina B7; M5; M6</b>				<b>320I; 325CI; 325I; 325XI; 330CI; 330I; 330XI; 525I; 530I; 545I; 645CI; 745I; 745LI; 760I</b>			
Sensor; Includes Transmitter Only .....	20083	31	3.5	Sensor; Includes Transmitter Only .....	20080	31	3.5
Service Pack; Does Not Include Valve .	20023	31	3.5	Service Pack; Does Not Include Valve .	20023	31	3.5
Service Pack; W/43mm Silver Insert ....	20037	31	3.5	Service Pack; W/43mm Silver Insert ....	20037	31	3.5
Service Pack; W/48mm Green Insert ...	20038	31	3.5	Service Pack; W/48mm Green Insert ...	20038	31	3.5
Service Pack; W/49mm Black Insert ....	20039	31	3.5	Service Pack; W/49mm Black Insert ....	20039	31	3.5
Service Pack; W/51mm Orange Insert .	20040	31	3.5	Service Pack; W/51mm Orange Insert .	20040	31	3.5
<b>X3; X5</b>				<b>760LI; M3</b>			
Sensor; Includes Transmitter Only .....	20083	35	4	Sensor; Includes Transmitter Only .....	20083	31	3.5
Service Pack; Does Not Include Valve .	20023	35	4	Service Pack; Does Not Include Valve .	20023	31	3.5
Service Pack; W/43mm Silver Insert ....	20037	35	4	Service Pack; W/43mm Silver Insert ....	20037	31	3.5
Service Pack; W/48mm Green Insert ...	20038	35	4	Service Pack; W/48mm Green Insert ...	20038	31	3.5
Service Pack; W/49mm Black Insert ....	20039	35	4	Service Pack; W/49mm Black Insert ....	20039	31	3.5
Service Pack; W/51mm Orange Insert .	20040	35	4	Service Pack; W/51mm Orange Insert .	20040	31	3.5
<b>Z4</b>				<b>X5</b>			
Sensor; Includes Transmitter Only .....	20083	31	3.5	Sensor; Includes Transmitter Only .....	20083	35	4
Service Pack; Does Not Include Valve .	20023	31	3.5	Service Pack; Does Not Include Valve .	20023	35	4
Service Pack; W/43mm Silver Insert ....	20037	31	3.5	Service Pack; W/43mm Silver Insert ....	20037	35	4
Service Pack; W/48mm Green Insert ...	20038	31	3.5	Service Pack; W/48mm Green Insert ...	20038	35	4
Service Pack; W/49mm Black Insert ....	20039	31	3.5	Service Pack; W/49mm Black Insert ....	20039	35	4
Service Pack; W/51mm Orange Insert .	20040	31	3.5	Service Pack; W/51mm Orange Insert .	20040	35	4
<b>2006</b>				<b>Z4</b>			
<b>323I</b>				Sensor; Includes Transmitter Only .....			
Sensor; Includes Transmitter Only; Jun. & Newer .....	20083	31	3.5	Sensor; Includes Transmitter Only .....	20083	31	3.5
Service Pack; Does Not Include Valve; Jun. & Newer .....	20023	31	3.5	Service Pack; Does Not Include Valve .	20023	31	3.5
Service Pack; W/43mm Silver Insert; Jun. & Newer .....	20037	31	3.5	Service Pack; W/43mm Silver Insert ....	20037	31	3.5
Service Pack; W/48mm Green Insert; Jun. & Newer .....	20038	31	3.5	Service Pack; W/48mm Green Insert ...	20038	31	3.5
Service Pack; W/49mm Black Insert; Jun. & Newer .....	20039	31	3.5	Service Pack; W/49mm Black Insert ....	20039	31	3.5
Service Pack; W/51mm Orange Insert; Jun. & Newer .....	20040	31	3.5	Service Pack; W/51mm Orange Insert .	20040	31	3.5
<b>325CI; 325I; 325XI; 330CI; 330I; 330XI</b>				<b>2004</b>			
Sensor; Includes Transmitter Only .....	20080	31	3.5	<b>320I; 325CI; 325I; 325XI; 330CI; 330I; 330XI; 525I; 530I; 545I; 645CI; 745I; 745LI; 760I</b>			
Service Pack; Does Not Include Valve .	20023	31	3.5	Sensor; Includes Transmitter Only .....	20080	31	3.5
Service Pack; W/43mm Silver Insert ....	20037	31	3.5	Service Pack; Does Not Include Valve .	20023	31	3.5
Service Pack; W/48mm Green Insert ...	20038	31	3.5	Service Pack; W/43mm Silver Insert ....	20037	31	3.5
Service Pack; W/49mm Black Insert ....	20039	31	3.5	Service Pack; W/48mm Green Insert ...	20038	31	3.5
Service Pack; W/51mm Orange Insert .	20040	31	3.5	Service Pack; W/49mm Black Insert ....	20039	31	3.5
<b>525I; 525XI; 530I; 530XI; 550I; 650I; 750I; 750LI; 760I; 760LI; M3; M5; M6</b>				<b>760LI; M3</b>			
Sensor; Includes Transmitter Only .....	20083	31	3.5	Sensor; Includes Transmitter Only .....	20083	31	3.5
Service Pack; Does Not Include Valve .	20023	31	3.5	Service Pack; Does Not Include Valve .	20023	31	3.5
Service Pack; W/43mm Silver Insert ....	20037	31	3.5	Service Pack; W/43mm Silver Insert ....	20037	31	3.5
Service Pack; W/48mm Green Insert ...	20038	31	3.5	Service Pack; W/48mm Green Insert ...	20038	31	3.5
Service Pack; W/49mm Black Insert ....	20039	31	3.5	Service Pack; W/49mm Black Insert ....	20039	31	3.5
Service Pack; W/51mm Orange Insert .	20040	31	3.5	Service Pack; W/51mm Orange Insert .	20040	31	3.5
<b>X3; X5</b>				<b>X5</b>			
Sensor; Includes Transmitter Only .....	20083	35	4	Sensor; Includes Transmitter Only .....	28082	35	4
Service Pack; Does Not Include Valve .	20023	35	4	Service Pack; Does Not Include Valve .	20023	35	4
Service Pack; W/43mm Silver Insert ....	20037	35	4	Service Pack; W/43mm Silver Insert ....	20037	35	4
Service Pack; W/48mm Green Insert ...	20038	35	4	Service Pack; W/48mm Green Insert ...	20038	35	4
Service Pack; W/49mm Black Insert ....	20039	35	4	Service Pack; W/49mm Black Insert ....	20039	35	4
Service Pack; W/51mm Orange Insert .	20040	35	4	Service Pack; W/51mm Orange Insert .	20040	35	4
<b>Z4</b>				<b>Z4</b>			
Sensor; Includes Transmitter Only .....	20083	31	3.5	Sensor; Includes Transmitter Only .....	20083	31	3.5
Service Pack; Does Not Include Valve .	20023	31	3.5	Service Pack; Does Not Include Valve .	20023	31	3.5
Service Pack; W/43mm Silver Insert ....	20037	31	3.5	Service Pack; W/43mm Silver Insert ....	20037	31	3.5
Service Pack; W/48mm Green Insert ...	20038	31	3.5	Service Pack; W/48mm Green Insert ...	20038	31	3.5
Service Pack; W/49mm Black Insert ....	20039	31	3.5	Service Pack; W/49mm Black Insert ....	20039	31	3.5
Service Pack; W/51mm Orange Insert .	20040	31	3.5	Service Pack; W/51mm Orange Insert .	20040	31	3.5
<b>2003</b>				<b>2003</b>			
<b>320I; 325CI; 325I; 325XI; 330CI; 330I; 330XI; 525I; 530I; 540I; 745I; 745LI; 760LI; M3</b>				<b>320I; 325CI; 325I; 325XI; 330CI; 330I; 330XI; 525I; 530I; 540I; 745I; 745LI; 760LI; M3</b>			
Sensor; Includes Transmitter Only .....	20080	31	3.5	Sensor; Includes Transmitter Only .....	20080	31	3.5
Service Pack; Does Not Include Valve .	20023	31	3.5	Service Pack; Does Not Include Valve .	20023	31	3.5

## Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
<b>► BMW - Continued</b>				<b>► BMW - Continued</b>			
<b>2003 - Continued</b>				<b>2001 - Continued</b>			
<b>320I; 325CI; 325I; 325XI; 330CI; 330I; 330XI; 525I; 530I; 540I; 745I; 745LI; 760LI; M3 - Continued</b>				<b>320I; 325CI; 325I; 325XI; 330CI; 330I; 330XI; 525I; 530I; 540I; 740I; 740IL; 750IL; M3 - Continued</b>			
Service Pack; W/43mm Silver Insert ....	20037	31	3.5	Service Pack; W/49mm Black Insert .....	20039	31	3.5
Service Pack; W/48mm Green Insert ...	20038	31	3.5	Service Pack; W/51mm Orange Insert .	20040	31	3.5
Service Pack; W/49mm Black Insert .....	20039	31	3.5				
Service Pack; W/51mm Orange Insert .	20040	31	3.5				
<b>M5</b>				<b>M5</b>			
Sensor; Includes Transmitter Only;				Sensor; Includes Transmitter Only;			
W/433 MHz Sensor .....	20080	31	3.5	W/433 MHz Sensor .....	20080	31	3.5
Service Pack; Does Not Include Valve .	20023	31	3.5	Service Pack; Does Not Include Valve .	20023	31	3.5
Service Pack; W/43mm Silver Insert ....	20037	31	3.5	Service Pack; W/43mm Silver Insert ....	20037	31	3.5
Service Pack; W/48mm Green Insert ...	20038	31	3.5	Service Pack; W/48mm Green Insert ...	20038	31	3.5
Service Pack; W/49mm Black Insert .....	20039	31	3.5	Service Pack; W/49mm Black Insert .....	20039	31	3.5
Service Pack; W/51mm Orange Insert .	20040	31	3.5	Service Pack; W/51mm Orange Insert .	20040	31	3.5
<b>X5</b>				<b>X5</b>			
Sensor; Includes Transmitter Only .....	28082	35	4	Sensor; Includes Transmitter Only .....	28082	35	4
Service Pack; Does Not Include Valve .	20023	35	4	Service Pack; Does Not Include Valve .	20023	35	4
Service Pack; W/43mm Silver Insert ....	20037	35	4	Service Pack; W/43mm Silver Insert ....	20037	35	4
Service Pack; W/48mm Green Insert ...	20038	35	4	Service Pack; W/48mm Green Insert ...	20038	35	4
Service Pack; W/49mm Black Insert .....	20039	35	4	Service Pack; W/49mm Black Insert .....	20039	35	4
Service Pack; W/51mm Orange Insert .	20040	35	4	Service Pack; W/51mm Orange Insert .	20040	35	4
<b>Z4</b>				<b>Z3; Z8</b>			
Sensor; Includes Transmitter Only .....	20083	31	3.5	Service Pack; Does Not Include Valve .	20023	31	3.5
Service Pack; Does Not Include Valve .	20023	31	3.5	Service Pack; W/43mm Silver Insert ....	20037	31	3.5
Service Pack; W/43mm Silver Insert ....	20037	31	3.5	Service Pack; W/48mm Green Insert ...	20038	31	3.5
Service Pack; W/48mm Green Insert ...	20038	31	3.5	Service Pack; W/49mm Black Insert .....	20039	31	3.5
Service Pack; W/49mm Black Insert .....	20039	31	3.5	Service Pack; W/51mm Orange Insert .	20040	31	3.5
Service Pack; W/51mm Orange Insert .	20040	31	3.5				
<b>Z8</b>				<b>2000</b>			
Sensor; Includes Transmitter Only;				<b>323CI; 323I; 328CI; 328I; 528I; 540I; 740I; 740IL; 750IL</b>			
W/433 MHz Sensor .....	20080	31	3.5	Service Pack; Does Not Include Valve .	20023	31	3.5
Service Pack; Does Not Include Valve .	20023	31	3.5	Service Pack; W/43mm Silver Insert ....	20037	31	3.5
Service Pack; W/43mm Silver Insert ....	20037	31	3.5	Service Pack; W/48mm Green Insert ...	20038	31	3.5
Service Pack; W/48mm Green Insert ...	20038	31	3.5	Service Pack; W/49mm Black Insert .....	20039	31	3.5
Service Pack; W/49mm Black Insert .....	20039	31	3.5	Service Pack; W/51mm Orange Insert .	20040	31	3.5
Service Pack; W/51mm Orange Insert .	20040	31	3.5				
<b>2002</b>				<b>M5</b>			
<b>320I; 325CI; 325I; 325XI; 330CI; 330I; 330XI; 525I; 530I; 540I; 745I; 745LI; M3; M5</b>				Sensor; Includes Transmitter Only;			
Sensor; Includes Transmitter Only;				W/433 MHz Sensor .....	20080	31	3.5
W/433 MHz Sensor .....	20080	31	3.5	Service Pack; Does Not Include Valve .	20023	31	3.5
Service Pack; Does Not Include Valve .	20023	31	3.5	Service Pack; W/43mm Silver Insert ....	20037	31	3.5
Service Pack; W/43mm Silver Insert ....	20037	31	3.5	Service Pack; W/48mm Green Insert ...	20038	31	3.5
Service Pack; W/48mm Green Insert ...	20038	31	3.5	Service Pack; W/49mm Black Insert .....	20039	31	3.5
Service Pack; W/49mm Black Insert .....	20039	31	3.5	Service Pack; W/51mm Orange Insert .	20040	31	3.5
Service Pack; W/51mm Orange Insert .	20040	31	3.5				
<b>X5</b>				<b>X5</b>			
Sensor; Includes Transmitter Only .....	28082	35	4	Sensor; Includes Transmitter Only .....	28082	35	4
Service Pack; Does Not Include Valve .	20023	35	4	Service Pack; Does Not Include Valve .	20023	35	4
Service Pack; W/43mm Silver Insert ....	20037	35	4	Service Pack; W/43mm Silver Insert ....	20037	35	4
Service Pack; W/48mm Green Insert ...	20038	35	4	Service Pack; W/48mm Green Insert ...	20038	35	4
Service Pack; W/49mm Black Insert .....	20039	35	4	Service Pack; W/49mm Black Insert .....	20039	35	4
Service Pack; W/51mm Orange Insert .	20040	35	4	Service Pack; W/51mm Orange Insert .	20040	35	4
<b>Z3; Z8</b>				<b>Z3; Z8</b>			
Service Pack; Does Not Include Valve .	20023	31	3.5	Service Pack; Does Not Include Valve .	20023	31	3.5
Service Pack; W/43mm Silver Insert ....	20037	31	3.5	Service Pack; W/43mm Silver Insert ....	20037	31	3.5
Service Pack; W/48mm Green Insert ...	20038	31	3.5	Service Pack; W/48mm Green Insert ...	20038	31	3.5
Service Pack; W/49mm Black Insert .....	20039	31	3.5	Service Pack; W/49mm Black Insert .....	20039	31	3.5
Service Pack; W/51mm Orange Insert .	20040	31	3.5	Service Pack; W/51mm Orange Insert .	20040	31	3.5
<b>2001</b>				<b>1999-1997</b>			
<b>320I; 325CI; 325I; 325XI; 330CI; 330I; 330XI; 525I; 530I; 540I; 740I; 740IL; 750IL; M3</b>				<b>528I; 540I; 740I; 740IL; 750IL</b>			
Service Pack; Does Not Include Valve .	20023	31	3.5	Service Pack; Does Not Include Valve .	20023	31	3.5
Service Pack; W/43mm Silver Insert ....	20037	31	3.5	Service Pack; W/43mm Silver Insert ....	20037	31	3.5
Service Pack; W/48mm Green Insert ...	20038	31	3.5	Service Pack; W/48mm Green Insert ...	20038	31	3.5
				Service Pack; W/49mm Black Insert .....	20039	31	3.5
				Service Pack; W/51mm Orange Insert .	20040	31	3.5
				<b>► Bugatti</b>			
				<b>2006</b>			
				<b>Veyron</b>			
				Service Pack; Does Not Include Valve .	20023	35	4

## Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
<b>► Bugatti - Continued</b>				<b>► Buick - Continued</b>			
<b>2006 - Continued</b>				<b>2010 - Continued</b>			
<b>Veyron - Continued</b>				<b>LaCrosse - Continued</b>			
Service Pack; W/43mm Silver Insert ....	20037	35	4	Service Pack .....	20008	11.5	1.3
Service Pack; W/48mm Green Insert ...	20038	35	4	<b>Lucerne</b>			
Service Pack; W/49mm Black Insert .....	20039	35	4	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Service Pack; W/51mm Orange Insert .	20040	35	4	EZ-sensor Service Pack; Almm. Valve	34000	62	7
<b>► Buick</b>				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
<b>2013-2012</b>				Sensor .....	20153	11.5	1.3
<b>Enclave; LaCrosse</b>				Service Pack .....	20008	11.5	1.3
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	<b>2009</b>			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>Allure; Enclave; LaCrosse; Lucerne</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Sensor .....	20153	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Service Pack .....	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
<b>Regal; Verano</b>				Sensor .....	20153	11.5	1.3
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Service Pack .....	20008	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>2008</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	<b>Allure; Enclave; LaCrosse</b>			
Sensor .....	28206	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Service Pack .....	20008	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
<b>2011</b>				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
<b>Enclave</b>				Sensor .....	20158	62	7
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Service Pack; W/Schrader Sensor .....	20004	62	7
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Service Pack; W/Siemens Sensor .....	20030	80	9
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	<b>Lucerne</b>			
Sensor .....	20153	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Service Pack .....	20008	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
<b>LaCrosse</b>				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Sensor .....	20153	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Service Pack .....	20008	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	<b>2007</b>			
Sensor .....	28206	11.5	1.3	<b>Allure; LaCrosse</b>			
Service Pack .....	20008	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
<b>Lucerne</b>				EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor .....	20158	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack; W/Schrader Sensor .....	20004	62	7
Sensor .....	20153	11.5	1.3	Service Pack; W/Siemens Sensor .....	20030	80	9
Service Pack .....	20008	11.5	1.3	<b>Lucerne</b>			
<b>Regal</b>				EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor .....	20153	11.5	1.3
Sensor .....	28206	11.5	1.3	Service Pack .....	20008	11.5	1.3
Service Pack .....	20008	11.5	1.3	<b>Rainier</b>			
<b>2010</b>				EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
<b>Allure</b>				EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor; OEM Part No. 25774006 .....	20116	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack .....	20004	62	7
Sensor .....	28206	11.5	1.3	<b>2006</b>			
Service Pack .....	20008	11.5	1.3	<b>Rainier</b>			
<b>Enclave</b>				Sensor; OEM Part No. 25774006 .....	20116	62	7
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Service Pack .....	20004	62	7
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>► Cadillac</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	<b>2013</b>			
Sensor .....	20153	11.5	1.3	<b>CTS</b>			
Service Pack .....	20008	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
<b>LaCrosse</b>				EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor; OEM Part No. 15268606; CTS			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	V; W/315 MHz Sensor .....	20158	62	7
Sensor .....	28206	11.5	1.3				

◇ Programming Tool Required.



**Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks**

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
<b>► Cadillac - Continued</b>				<b>► Cadillac - Continued</b>			
<b>2013 - Continued</b>				<b>2011-2010 - Continued</b>			
<b>CTS - Continued</b>				<b>SRX - Continued</b>			
Sensor; OEM Part No. 25920615; Exc. CTS V .....	20153	11.5	1.3	EZ-sensor Service Pack; Rubber Valve Sensor .....	20008	11.5	1.3
Service Pack; OEM Part No. 15268606; CTS V; W/315 MHz Sensor .....	20004	62	7	Service Pack .....	20008	11.5	1.3
Service Pack; OEM Part No. 25920615; Exc. CTS V .....	20008	11.5	1.3	<b>STS</b>			
<b>Escalade</b>				EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Almm. Valve .....	34000	62	7
EZ-sensor Service Pack; Almm. Valve .....	34000	62	7	EZ-sensor Service Pack; Rubber Valve Sensor .....	20008	11.5	1.3
EZ-sensor Service Pack; Rubber Valve .....	20008	11.5	1.3	Service Pack .....	20008	11.5	1.3
Sensor .....	20153	11.5	1.3	<b>2009</b>			
Service Pack .....	20008	11.5	1.3	<b>CTS</b>			
<b>SRX; XTS</b>				EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Almm. Valve .....	34000	62	7
EZ-sensor Service Pack; Almm. Valve .....	34000	62	7	EZ-sensor Service Pack; Rubber Valve Sensor; OEM Part No. 15268606; CTS V; W/315 MHz Sensor .....	20158	62	7
EZ-sensor Service Pack; Rubber Valve .....	20008	11.5	1.3	Sensor; OEM Part No. 25920615; Exc. CTS V .....	20153	11.5	1.3
Sensor .....	28206	11.5	1.3	Service Pack; OEM Part No. 15268606; CTS V; W/315 MHz Sensor .....	20004	62	7
Service Pack .....	20008	11.5	1.3	Service Pack; OEM Part No. 25920615; Exc. CTS V .....	20008	11.5	1.3
<b>2012</b>				<b>DTS; Escalade; SRX</b>			
<b>CTS</b>				EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Almm. Valve .....	34000	62	7
EZ-sensor Service Pack; Almm. Valve .....	34000	62	7	EZ-sensor Service Pack; Rubber Valve Sensor .....	20008	11.5	1.3
EZ-sensor Service Pack; Rubber Valve .....	20008	11.5	1.3	Service Pack .....	20008	11.5	1.3
Sensor; OEM Part No. 15268606; CTS V; W/315 MHz Sensor .....	20158	62	7	<b>STS</b>			
Sensor; OEM Part No. 25920615; Exc. CTS V .....	20153	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Service Pack; OEM Part No. 15268606; CTS V; W/315 MHz Sensor .....	20004	62	7	EZ-sensor Service Pack; Almm. Valve .....	34000	62	7
Service Pack; OEM Part No. 25920615; Exc. CTS V .....	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve Sensor; OEM Part No. 25920615; Exc. STS V .....	20153	11.5	1.3
<b>Escalade</b>				Service Pack; OEM Part No. 25920615; Exc. STS V .....	20008	11.5	1.3
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	<b>XLR</b>			
EZ-sensor Service Pack; Almm. Valve .....	34000	62	7	Sensor; OEM Part No. 25758220 .....	20076	62	7
EZ-sensor Service Pack; Rubber Valve .....	20008	11.5	1.3	Service Pack .....	20004	62	7
Sensor .....	20153	11.5	1.3	<b>2008</b>			
Service Pack .....	20008	11.5	1.3	<b>CTS; DTS; Escalade; SRX</b>			
<b>SRX</b>				EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Almm. Valve .....	34000	62	7
EZ-sensor Service Pack; Almm. Valve .....	34000	62	7	EZ-sensor Service Pack; Rubber Valve Sensor .....	20008	11.5	1.3
EZ-sensor Service Pack; Rubber Valve .....	20008	11.5	1.3	Service Pack .....	20008	11.5	1.3
Sensor .....	28206	11.5	1.3	<b>STS; XLR</b>			
Service Pack .....	20008	11.5	1.3	Sensor; OEM Part No. 25758220 .....	20076	62	7
<b>2011-2010</b>				Service Pack .....	20004	62	7
<b>CTS</b>				<b>2007</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	<b>CTS</b>			
EZ-sensor Service Pack; Almm. Valve .....	34000	62	7	Sensor; OEM Part No. 25774006 .....	20116	62	7
EZ-sensor Service Pack; Rubber Valve .....	20008	11.5	1.3	Service Pack .....	20004	62	7
Sensor; OEM Part No. 15268606; CTS V; W/315 MHz Sensor .....	20158	62	7	<b>DTS</b>			
Sensor; OEM Part No. 25920615; Exc. CTS V .....	20153	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Service Pack; OEM Part No. 15268606; CTS V; W/315 MHz Sensor .....	20004	62	7	EZ-sensor Service Pack; Almm. Valve .....	34000	62	7
Service Pack; OEM Part No. 25920615; Exc. CTS V .....	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve Sensor .....	20008	11.5	1.3
<b>DTS; Escalade</b>				Service Pack .....	20008	11.5	1.3
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	<b>Escalade</b>			
EZ-sensor Service Pack; Almm. Valve .....	34000	62	7	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Rubber Valve .....	20008	11.5	1.3	EZ-sensor Service Pack; Almm. Valve .....	34000	62	7
Sensor .....	20153	11.5	1.3	EZ-sensor Service Pack; Rubber Valve .....	20008	11.5	1.3
Service Pack .....	20008	11.5	1.3	Sensor .....	20153	11.5	1.3
<b>SRX</b>				Service Pack .....	20008	11.5	1.3
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	<b>2007</b>			
EZ-sensor Service Pack; Almm. Valve .....	34000	62	7	<b>CTS</b>			

◇ Programming Tool Required.



## Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
<b>► Cadillac - Continued</b>				<b>► Cadillac - Continued</b>			
<b>2007 - Continued</b>				<b>2004 - Continued</b>			
<b>Escalade - Continued</b>				<b>Escalade</b>			
Sensor; Clamp-In Style Only; TRW Sensor; W/Almm. Valve Stem .....	20158	62	7	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Sensor; Snap-In Style Only; Schrader Sensor; W/Rubber Valve Stem .....	20153	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Service Pack; Clamp-In Style Only; TRW Sensor; W/Almm. Valve Stem .....	20015	80	9	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Service Pack; Snap-In Style Only; Schrader Sensor; W/Rubber Valve Stem .....	20008	11.5	1.3	Sensor .....	20115	62	7
<b>SRX</b>				Service Pack .....	20004	62	7
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	<b>Seville</b>			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor .....	●20117	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack .....	20003	62	7
Sensor .....	20153	11.5	1.3	<b>SRX</b>			
Service Pack .....	20008	11.5	1.3	Sensor .....	20116	62	7
<b>STS; XLR</b>				Service Pack .....	20004	62	7
Sensor; OEM Part No. 25758220 .....	20076	62	7	<b>XLR</b>			
Service Pack .....	20004	62	7	Sensor; OEM Part No. 25758220 .....	20076	62	7
<b>2006</b>				Service Pack .....	20004	62	7
<b>CTS</b>				<b>2003-2001</b>			
Sensor; OEM Part No. 25774006 .....	20116	62	7	<b>Deville; Seville</b>			
Service Pack .....	20004	62	7	Sensor .....	●20117	62	7
<b>DTS</b>				Service Pack .....	20003	62	7
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	<b>► Chevrolet</b>			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>2013</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	<b>Avalanche</b>			
Sensor .....	20158	62	7	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Service Pack .....	20004	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
<b>Escalade</b>				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor .....	20107	62	7	Sensor .....	20153	11.5	1.3
Service Pack .....	20004	62	7	Service Pack .....	20008	11.5	1.3
<b>SRX</b>				<b>Camaro</b>			
Sensor; OEM Part No. 25774006 .....	20116	62	7	EZ-sensor - 315 MHz; Exc. ZL1 .....	◇33000	11.5	1.3
Service Pack .....	20004	62	7	EZ-sensor Service Pack; Almm. Valve; Exc. ZL1 .....	34000	62	7
<b>STS; XLR</b>				EZ-sensor Service Pack; Rubber Valve; Exc. ZL1 .....	20008	11.5	1.3
Sensor; OEM Part No. 25758220 .....	20076	62	7	Sensor; ZL1 .....	28423	11.5	1.3
Service Pack .....	20004	62	7	Sensor; Exc. ZL1 .....	28206	11.5	1.3
<b>2005</b>				Service Pack; ZL1 .....	20004	62	7
<b>CTS</b>				Service Pack; Exc. ZL1 .....	20008	11.5	1.3
Sensor .....	20116	62	7	<b>Caprice</b>			
Service Pack .....	20004	62	7	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
<b>Deville</b>				EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor .....	●20117	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Service Pack .....	20003	62	7	Sensor .....	20158	62	7
<b>Escalade</b>				Service Pack .....	20004	62	7
Sensor .....	20107	62	7	<b>Captiva</b>			
Service Pack .....	20004	62	7	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
<b>SRX</b>				EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor .....	20116	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Service Pack .....	20004	62	7	Sensor .....	20153	11.5	1.3
<b>STS; XLR</b>				Service Pack .....	20008	11.5	1.3
Sensor; OEM Part No. 25758220 .....	20076	62	7	<b>Corvette</b>			
Service Pack .....	20004	62	7	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
<b>2004</b>				EZ-sensor Service Pack; Almm. Valve	34000	62	7
<b>CTS</b>				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor .....	20116	62	7	Sensor .....	20158	62	7
Service Pack .....	20004	62	7	Service Pack .....	20004	62	7
<b>Deville</b>				<b>Cruze; Equinox</b>			
Sensor .....	●20117	62	7	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Service Pack .....	20003	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
<b>2004 - Continued</b>				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
<b>Express; Impala; Malibu</b>				Sensor .....	28206	11.5	1.3
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Service Pack .....	20008	11.5	1.3

◇ Programming Tool Required.  
● Magnet Required to Activate Sensor.

## Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
<b>► Chevrolet - Continued</b>				<b>► Chevrolet - Continued</b>			
<b>2013 - Continued</b>				<b>2012 - Continued</b>			
<b>Express; Impala; Malibu - Continued</b>				<b>Corvette</b>			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor .....	20153	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Service Pack .....	20008	11.5	1.3	Sensor .....	20158	62	7
<b>Silverado Series Pickup</b>				<b>Cruze; Equinox</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor; W/Single Rear Wheels .....	20153	11.5	1.3	Sensor .....	28206	11.5	1.3
Service Pack; W/Single Rear Wheels ...	20008	11.5	1.3	Service Pack .....	20008	11.5	1.3
<b>Sonic; Spark</b>				<b>Express; Impala; Malibu</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor .....	28206	11.5	1.3	Sensor .....	20153	11.5	1.3
Service Pack .....	20008	11.5	1.3	Service Pack .....	20008	11.5	1.3
<b>Suburban; Tahoe; Traverse</b>				<b>Orlando</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor .....	20153	11.5	1.3	Sensor .....	28206	11.5	1.3
Service Pack .....	20008	11.5	1.3	Service Pack .....	20008	11.5	1.3
<b>Volt</b>				<b>Silverado Series Pickup</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor .....	28206	11.5	1.3	Sensor; W/Single Rear Wheels .....	20153	11.5	1.3
Service Pack .....	20008	11.5	1.3	Service Pack; W/Single Rear Wheels ...	20008	11.5	1.3
<b>2012</b>				<b>Sonic</b>			
<b>Avalanche; Aveo</b>				EZ-sensor - 315 MHz .....			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor .....	20153	11.5	1.3	Sensor .....	28206	11.5	1.3
Service Pack .....	20008	11.5	1.3	Service Pack .....	20008	11.5	1.3
<b>Camaro</b>				<b>Suburban; Tahoe; Traverse</b>			
EZ-sensor - 315 MHz; Exc. ZL1 .....	◇33000	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve; Exc. ZL1 .....	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve; Exc. ZL1 .....	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor; ZL1 .....	28423	11.5	1.3	Sensor .....	20153	11.5	1.3
Sensor; Exc. ZL1 .....	28206	11.5	1.3	Service Pack .....	20008	11.5	1.3
Service Pack; ZL1 .....	20004	62	7	<b>Volt</b>			
Service Pack; Exc. ZL1 .....	20008	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
<b>Caprice</b>				EZ-sensor Service Pack; Almm. Valve			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor .....	28206	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack .....	20008	11.5	1.3
Sensor .....	20158	62	7	<b>2011</b>			
Service Pack .....	20004	62	7	<b>Avalanche; Aveo</b>			
<b>Captiva</b>				EZ-sensor - 315 MHz .....			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor .....	20153	11.5	1.3	Sensor .....	20153	11.5	1.3
Service Pack .....	20008	11.5	1.3	Service Pack .....	20008	11.5	1.3
<b>Colorado</b>				<b>Camaro</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor .....	20131	62	7	Sensor .....	28206	11.5	1.3
Service Pack .....	20006	62	7	Service Pack .....	20008	11.5	1.3
<b>Caprice</b>				EZ-sensor - 315 MHz .....			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7

◇ Programming Tool Required.

## Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
<b>► Chevrolet - Continued</b>				<b>► Chevrolet - Continued</b>			
<b>2011 - Continued</b>				<b>2010 - Continued</b>			
<b>Caprice - Continued</b>				<b>Colorado - Continued</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack .....	20006	62	7
Sensor .....	20158	62	7	<b>Corvette</b>			
Service Pack .....	20004	62	7	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
<b>Colorado</b>				EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor .....	20158	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack .....	20004	62	7
Sensor .....	20131	62	7	<b>Equinox</b>			
Service Pack .....	20006	62	7	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
<b>Corvette</b>				EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor .....	28206	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack .....	20008	11.5	1.3
Sensor .....	20158	62	7	<b>Express</b>			
Service Pack .....	20004	62	7	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
<b>Cruze; Equinox</b>				EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor .....	20153	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack .....	20008	11.5	1.3
Sensor .....	28206	11.5	1.3	<b>HHR</b>			
Service Pack .....	20008	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
<b>Express; HHR; Impala; Malibu</b>				EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor .....	28206	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack .....	20008	11.5	1.3
Sensor .....	20153	11.5	1.3	<b>Impala</b>			
Service Pack .....	20008	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
<b>Silverado Series Pickup</b>				EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor .....	20153	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack .....	20008	11.5	1.3
Sensor; W/Single Rear Wheels .....	20153	11.5	1.3	<b>Malibu</b>			
Service Pack; W/Single Rear Wheels ...	20008	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
<b>Suburban; Tahoe; Traverse</b>				EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor .....	28206	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack .....	20008	11.5	1.3
Sensor .....	20153	11.5	1.3	<b>Silverado Series Pickup</b>			
Service Pack .....	20008	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
<b>Volt</b>				EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor; W/Single Rear Wheels .....	20153	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack; W/Single Rear Wheels ...	20008	11.5	1.3
Sensor .....	28206	11.5	1.3	<b>Suburban; Tahoe; Traverse</b>			
Service Pack .....	20008	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
<b>2010</b>				EZ-sensor Service Pack; Almm. Valve	34000	62	7
<b>Avalanche; Aveo</b>				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Sensor .....	20153	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Service Pack .....	20008	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	<b>2009</b>			
Sensor .....	20153	11.5	1.3	<b>Avalanche; Aveo</b>			
Service Pack .....	20008	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
<b>Camaro; Cobalt</b>				EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor .....	20153	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack .....	20008	11.5	1.3
Sensor .....	28206	11.5	1.3	<b>Cobalt</b>			
Service Pack .....	20008	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
<b>Colorado</b>				EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor; Clamp-In Style Only; W/Almm. Valve Stem .....	20158	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor .....	20131	62	7				

◇ Programming Tool Required.

**Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks**

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
<b>► Chevrolet - Continued</b>				<b>► Chevrolet - Continued</b>			
<b>2009 - Continued</b>				<b>2009 - Continued</b>			
<b>Cobalt - Continued</b>				<b>Uplander</b>			
Sensor; Snap-In Style Only; W/Rubber Valve Stem .....	20153	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Service Pack; Clamp-In Style Only; W/Almm. Valve Stem .....	20004	80	9	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Service Pack; Snap-In Style Only; W/Rubber Valve Stem .....	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
<b>Colorado</b>				<b>2008</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	<b>Avalanche; Aveo</b>			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor .....	20131	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Service Pack .....	20006	62	7	Sensor .....	20153	11.5	1.3
<b>Corvette</b>				<b>Service Pack .....</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	20008 11.5 1.3			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>Cobalt</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz .....			
Sensor; OEM Part No. 25758220 .....	20076	62	7	◇33000 11.5 1.3			
Service Pack .....	20004	62	7	EZ-sensor Service Pack; Almm. Valve			
<b>Equinox; Express</b>				34000 62 7			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	20008 11.5 1.3			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor .....			
Sensor .....	20158	62	7	20158 62 7			
Service Pack; W/Schrader Sensor .....	20004	62	7	Sensor; Snap-In Style Only; W/Rubber Valve Stem .....			
Service Pack; W/Siemens Sensor .....	20030	80	9	20153 11.5 1.3			
<b>HHR</b>				Service Pack; Clamp-In Style Only; W/Almm. Valve Stem .....			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	20004 80 9			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Service Pack; Snap-In Style Only; W/Rubber Valve Stem .....			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	20008 11.5 1.3			
Sensor; Clamp-In Style Only; W/Almm. Valve Stem .....	20158	62	7	<b>Colorado</b>			
Sensor; Snap-In Style Only; W/Rubber Valve Stem .....	20153	11.5	1.3	EZ-sensor - 315 MHz .....			
Service Pack; Clamp-In Style Only; W/Almm. Valve Stem .....	20004	80	9	◇33000 11.5 1.3			
Service Pack; Snap-In Style Only; W/Rubber Valve Stem .....	20008	11.5	1.3	EZ-sensor Service Pack; Almm. Valve			
<b>Impala; Malibu</b>				34000 62 7			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	20008 11.5 1.3			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor .....			
Sensor .....	20153	11.5	1.3	20131 62 7			
Service Pack .....	20008	11.5	1.3	Service Pack .....			
<b>Silverado Series Pickup</b>				20006 62 7			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	<b>Corvette</b>			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor - 315 MHz .....			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	◇33000 11.5 1.3			
Sensor; W/Single Rear Wheels .....	20153	11.5	1.3	EZ-sensor Service Pack; Almm. Valve			
Service Pack; W/Single Rear Wheels ...	20008	11.5	1.3	34000 62 7			
<b>Suburban; Tahoe</b>				EZ-sensor Service Pack; Rubber Valve			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	20008 11.5 1.3			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor .....			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	20158 62 7			
Sensor .....	20153	11.5	1.3	Service Pack; W/Schrader Sensor .....			
Service Pack .....	20008	11.5	1.3	20004 62 7			
<b>Trailblazer</b>				Service Pack; W/Siemens Sensor .....			
Sensor; OEM Part No. 25774006 .....	20116	62	7	20030 80 9			
Service Pack .....	20004	62	7	<b>HHR</b>			
<b>Traverse</b>				EZ-sensor - 315 MHz .....			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	◇33000 11.5 1.3			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	34000 62 7			
Sensor .....	20153	11.5	1.3	EZ-sensor Service Pack; Rubber Valve			
Service Pack .....	20008	11.5	1.3	20008 11.5 1.3			
<b>Impala</b>				Sensor .....			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	20153 11.5 1.3			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Service Pack .....			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	20008 11.5 1.3			
Sensor .....	20153	11.5	1.3	<b>Malibu</b>			
Service Pack .....	20008	11.5	1.3	EZ-sensor - 315 MHz .....			
<b>Malibu</b>				◇33000 11.5 1.3			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Almm. Valve			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	34000 62 7			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve			
Sensor .....	20153	11.5	1.3	20008 11.5 1.3			
Service Pack .....	20008	11.5	1.3	Sensor .....			
<b>Malibu</b>				20153 11.5 1.3			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Service Pack .....			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	20008 11.5 1.3			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	<b>Impala</b>			

◇ Programming Tool Required.



## Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
<b>► Chevrolet - Continued</b>				<b>► Chevrolet - Continued</b>			
<b>2008 - Continued</b>				<b>2007 - Continued</b>			
<b>Malibu - Continued</b>				<b>Equinox - Continued</b>			
Sensor; Clamp-In Style Only; W/Almm. Valve Stem .....	20158	62	7	Sensor .....	20158	62	7
Sensor; Snap-In Style Only; W/Rubber Valve Stem .....	20153	11.5	1.3	Service Pack; W/Schrader Sensor .....	20004	62	7
Service Pack; Clamp-In Style Only; W/Almm. Valve Stem .....	20004	80	9	Service Pack; W/Siemens Sensor .....	20030	80	9
Service Pack; Snap-In Style Only; W/Rubber Valve Stem .....	20008	11.5	1.3	<b>Impala; Monte Carlo</b>			
<b>Silverado Series Pickup</b>				EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; Clamp-In Style Only; W/Almm. Valve Stem .....	20158	62	7
Sensor; W/Single Rear Wheels .....	20153	11.5	1.3	Sensor; Snap-In Style Only; W/Rubber Valve Stem .....	20153	11.5	1.3
Service Pack; W/Single Rear Wheels ...	20008	11.5	1.3	Service Pack; Clamp-In Style Only; W/Almm. Valve Stem .....	20004	62	7
<b>Suburban; Tahoe</b>				Service Pack; Snap-In Style Only; W/Rubber Valve Stem .....	20008	11.5	1.3
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	<b>Silverado Series Pickup</b>			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor .....	20153	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Service Pack .....	20008	11.5	1.3	Sensor; Classic .....	20107	62	7
<b>Trailblazer</b>				Sensor; Clamp-In Style Only; TRW Sensor; W/Almm. Valve Stem; Exc. Classic .....	20158	62	7
Sensor; OEM Part No. 25774006 .....	20116	62	7	Sensor; Snap-In Style Only; Schrader Sensor; W/Rubber Valve Stem; Exc. Classic .....	20153	11.5	1.3
Service Pack .....	20004	62	7	Service Pack; Classic .....	20004	62	7
<b>Uplander</b>				Service Pack; Clamp-In Style Only; TRW Sensor; W/Almm. Valve Stem; Exc. Classic .....	20015	80	9
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Service Pack; Snap-In Style Only; Schrader Sensor; W/Rubber Valve Stem; Exc. Classic .....	20008	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>Suburban; Tahoe</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Sensor .....	20158	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Service Pack .....	20004	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
<b>2007</b>				<b>2006</b>			
<b>Avalanche</b>				<b>Avalanche</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor; Clamp-In Style Only; TRW Sensor; W/Almm. Valve Stem .....	20158	62	7	Sensor .....	20107	62	7
Sensor; Snap-In Style Only; Schrader Sensor; W/Rubber Valve Stem .....	20153	11.5	1.3	Service Pack .....	20004	62	7
Service Pack; Clamp-In Style Only; TRW Sensor; W/Almm. Valve Stem .....	20015	80	9	<b>Corvette</b>			
Service Pack; Snap-In Style Only; Schrader Sensor; W/Rubber Valve Stem .....	20008	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
<b>Aveo</b>				EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor; OEM Part No. 25758220 .....	20076	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack .....	20004	62	7
Sensor; Hatchback .....	20153	11.5	1.3	<b>Impala; Monte Carlo</b>			
Service Pack .....	20008	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
<b>Colorado</b>				EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor .....	20107	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack .....	20004	62	7
Sensor .....	20131	62	7	<b>Corvette</b>			
Service Pack .....	20006	62	7	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
<b>Corvette</b>				EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor; OEM Part No. 25758220 .....	20076	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack .....	20004	62	7
Sensor; OEM Part No. 25758220 .....	20076	62	7	<b>Impala; Monte Carlo</b>			
Service Pack .....	20004	62	7	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
<b>Equinox</b>				EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor; W/Alloy Wheels .....	20158	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				

◇ Programming Tool Required.



## Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
<b>► Chevrolet - Continued</b>				<b>► Chevrolet - Continued</b>			
<b>2006 - Continued</b>				<b>2000-1997 - Continued</b>			
<b>Impala; Monte Carlo - Continued</b>				<b>Corvette - Continued</b>			
Service Pack; W/Alloy Wheels .....	20004	62	7	Service Pack .....	20012	62	7
<b>Silverado Series Pickup</b>				<b>► Chrysler</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	<b>2012</b>			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>200</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Sensor .....	20107	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Service Pack .....	20004	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
<b>SSR</b>				Sensor .....	20066	58	6.5
Sensor; OEM Part No. 25774006 .....	20116	62	7	or 28308	11.5	1.3	
Service Pack .....	20004	62	7	<b>Service Pack; W/Schrader Sensor; Includes Stem Only .....</b>			
<b>Suburban; Tahoe</b>				<b>20020</b> 58 6.5			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	<b>Service Pack; W/Schrader Sensor; Does Not Include Stem .....</b>			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>20013</b> 58 6.5			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	<b>300</b>			
Sensor .....	20107	62	7	Sensor; W/Rubber Stem Snap-in Sensor			
Service Pack .....	20004	62	7	Service Pack; W/Metal Stem Clamp-in Sensor; Includes Stem Only .....			
<b>Trailblazer</b>				<b>20020</b> 58 6.5			
Sensor; OEM Part No. 25774006 .....	20116	62	7	Service Pack; W/Metal Stem Clamp-in Sensor; Does Not Include Stem .....			
Service Pack .....	20004	62	7	<b>20016</b> 58 6.5			
<b>2005</b>				Service Pack; W/Rubber Stem Snap-in Sensor .....			
<b>Avalanche</b>				<b>20008</b> 11.5 1.3			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	<b>Town &amp; Country Van</b>			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor .....			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack .....			
Sensor .....	20107	62	7	<b>20398</b> 11.5 1.3			
Service Pack .....	20004	62	7	<b>20018</b> 11.5 1.3			
<b>Corvette</b>				<b>2011</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	<b>200</b>			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor - 315 MHz .....			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almm. Valve			
Sensor .....	20076	62	7	EZ-sensor Service Pack; Rubber Valve			
Service Pack .....	20004	62	7	Sensor .....			
<b>Silverado Series Pickup; Suburban; Tahoe</b>				or 28308			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Service Pack; W/Schrader Sensor; Does Not Include Stem .....			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Service Pack; W/Schrader Sensor; Includes Stem Only .....			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	<b>20013</b> 58 6.5			
Sensor .....	20107	62	7	<b>20020</b> 58 6.5			
Service Pack .....	20004	62	7	<b>300; Town &amp; Country Van</b>			
<b>2004</b>				Sensor .....			
<b>Avalanche</b>				Service Pack .....			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	<b>20398</b> 11.5 1.3			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>20008</b> 11.5 1.3			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	<b>2010</b>			
Sensor .....	20115	62	7	<b>300</b>			
Service Pack .....	20004	62	7	Sensor .....			
<b>Corvette</b>				Service Pack; Does Not Include Stem ..			
Sensor .....	●20117	62	7	Service Pack; Includes Stem Only .....			
Service Pack .....	20003	62	7	<b>20016</b> 58 6.5			
<b>Silverado Series Pickup; Suburban; Tahoe</b>				<b>20020</b> 58 6.5			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	<b>PT Cruiser</b>			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor - 315 MHz .....			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almm. Valve			
Sensor .....	20115	62	7	EZ-sensor Service Pack; Rubber Valve			
Service Pack .....	20004	62	7	Sensor .....			
<b>2003-2001</b>				or 28308			
<b>Corvette</b>				Service Pack; W/Schrader Sensor; Includes Stem Only .....			
Sensor .....	●20117	62	7	Service Pack; W/Schrader Sensor; Does Not Include Stem .....			
Service Pack .....	20003	62	7	Service Pack; W/Siemens Sensor .....			
<b>2000-1997</b>				<b>20030</b> 71 8			
<b>Corvette</b>				<b>Sebring</b>			
Sensor .....	●28006	62	7	EZ-sensor - 315 MHz .....			
				EZ-sensor Service Pack; Almm. Valve			
				EZ-sensor Service Pack; Rubber Valve			
				Sensor .....			
				or 28308			
				Service Pack; W/Schrader Sensor; Includes Stem Only .....			
				Service Pack; W/Schrader Sensor; Does Not Include Stem .....			
				<b>20013</b> 58 6.5			

◇ Programming Tool Required.  
● Magnet Required to Activate Sensor.

## Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
<b>► Chrysler - Continued</b>				<b>► Chrysler - Continued</b>			
<b>2009</b>				<b>2008 - Continued</b>			
<b>300</b>				<b>Town &amp; Country Van - Continued</b>			
Sensor .....	28291	58	6.5	Service Pack; W/Schrader Sensor; Does Not Include Stem .....	20013	58	6.5
Service Pack; Includes Stem Only .....	20020	58	6.5	Service Pack; W/Siemens Sensor .....	20030	71	8
Service Pack; Does Not Include Stem ..	20016	58	6.5				
<b>Aspen; PT Cruiser; Sebring</b>				<b>2007</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	<b>300</b>			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor .....	20066	58	6.5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
or 28308	11.5	1.3		Sensor .....	28434	11.5	1.3
Service Pack; W/Schrader Sensor; Includes Stem Only .....	20020	58	6.5	Service Pack; W/Schrader Sensor; Includes Stem Only .....	20020	58	6.5
Service Pack; W/Schrader Sensor; Does Not Include Stem .....	20013	58	6.5	Service Pack; W/Schrader Sensor; Does Not Include Stem .....	20013	58	6.5
Service Pack; W/Siemens Sensor .....	20030	71	8	Service Pack; W/Siemens Sensor .....	20030	71	8
<b>Town &amp; Country Van</b>				<b>Aspen</b>			
Sensor .....	28155	58	6.5	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
or 28434	11.5	1.3		EZ-sensor Service Pack; Almm. Valve	34000	62	7
Service Pack; W/Schrader Sensor; Includes Stem Only .....	20020	58	6.5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Service Pack; W/Schrader Sensor; Does Not Include Stem .....	20013	58	6.5	Sensor .....	20066	58	6.5
Service Pack; W/Siemens Sensor .....	20030	71	8	or 28308	11.5	1.3	
				Service Pack; W/Schrader Sensor; Includes Stem Only .....	20020	58	6.5
<b>2008</b>				Service Pack; W/Schrader Sensor; Does Not Include Stem .....			
<b>300</b>				20013			
EZ-sensor - 433 MHz .....	◇33100	11.5	1.3	Service Pack; W/Siemens Sensor .....			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	20030			
EZ-sensor Service Pack; W/Steel Wheels .....	20008	11.5	1.3				
Sensor .....	28155	58	6.5	<b>Crossfire</b>			
or 28434	11.5	1.3		Sensor .....			
Service Pack; W/Schrader Sensor; Includes Stem Only .....	20020	58	6.5	●20028			
Service Pack; W/Schrader Sensor; Does Not Include Stem .....	20013	58	6.5	Service Pack; W/Schrader Sensor .....			
Service Pack; W/Siemens Sensor .....	20030	71	8	20003			
				Service Pack; W/Siemens Sensor .....			
<b>Aspen</b>				20030			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	<b>Pacifica; Sebring; Town &amp; Country Van</b>			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor - 315 MHz .....			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	◇33000			
Sensor .....	20066	58	6.5	EZ-sensor Service Pack; Almm. Valve			
or 28308	11.5	1.3		34000			
Service Pack; W/Schrader Sensor; Includes Stem Only .....	20020	58	6.5	EZ-sensor Service Pack; Rubber Valve			
Service Pack; W/Schrader Sensor; Does Not Include Stem .....	20013	58	6.5	20008			
Service Pack; W/Siemens Sensor .....	20030	71	8	Sensor .....			
				20066			
<b>Crossfire</b>				or 28308			
Sensor .....	●20028	35	4	11.5			
Service Pack; W/Schrader Sensor .....	20003	35	4	1.3			
Service Pack; W/Siemens Sensor .....	20030	35	4				
				Service Pack; W/Schrader Sensor; Includes Stem Only .....			
<b>Pacifica; PT Cruiser; Sebring</b>				20020			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Service Pack; W/Schrader Sensor; Does Not Include Stem .....			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	20013			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	58			
Sensor .....	20066	58	6.5	6.5			
or 28308	11.5	1.3		Service Pack; W/Siemens Sensor .....			
Service Pack; W/Schrader Sensor; Includes Stem Only .....	20020	58	6.5	20030			
Service Pack; W/Schrader Sensor; Does Not Include Stem .....	20013	58	6.5	71			
Service Pack; W/Siemens Sensor .....	20030	71	8	8			
<b>Town &amp; Country Van</b>				<b>2006</b>			
Sensor .....	28155	58	6.5	<b>300</b>			
or 28434	11.5	1.3		EZ-sensor - 315 MHz .....			
Service Pack; W/Schrader Sensor; Includes Stem Only .....	20020	58	6.5	◇33000			
				11.5			
				EZ-sensor Service Pack; Almm. Valve			
				34000			
				EZ-sensor Service Pack; Rubber Valve			
				20008			
				11.5			
				Sensor .....			
				20066			
				58			
				6.5			
				or 28308			
				11.5			
				1.3			
				Service Pack; W/Schrader Sensor; Includes Stem Only .....			
				20020			
				58			
				6.5			
				Service Pack; W/Schrader Sensor; Does Not Include Stem .....			
				20013			
				58			
				6.5			
				Service Pack; W/Siemens Sensor .....			
				20030			
				71			
				8			
				<b>Crossfire</b>			
				Sensor .....			
				●20028			
				35			
				4			
				Service Pack; W/Schrader Sensor .....			
				20003			
				35			
				4			
				Service Pack; W/Siemens Sensor .....			
				20030			
				35			
				4			
				<b>Pacifica; Town &amp; Country Van</b>			
				EZ-sensor - 315 MHz .....			
				◇33000			
				11.5			
				1.3			
				EZ-sensor Service Pack; Almm. Valve			
				34000			
				62			
				7			
				EZ-sensor Service Pack; Rubber Valve			
				20008			
				11.5			
				1.3			
				Sensor .....			
				20066			
				58			
				6.5			
				or 28308			
				11.5			
				1.3			
				Service Pack; W/Schrader Sensor; Includes Stem Only .....			
				20020			
				58			
				6.5			

◇ Programming Tool Required.  
● Magnet Required to Activate Sensor.

## Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.			
<b>► Chrysler - Continued</b>				<b>► Chrysler - Continued</b>						
<b>2006 - Continued</b>				<b>2003 - Continued</b>						
<b>Pacifica; Town &amp; Country Van - Continued</b>				<b>Town &amp; Country Van; Voyager - Continued</b>						
Service Pack; W/Schrader Sensor; Does Not Include Stem .....	20013	58	6.5	EZ-sensor Service Pack; Rubber Valve Sensor .....	20008	11.5	1.3			
Service Pack; W/Siemens Sensor .....	20030	71	8	●20028	35	4				
<b>2005</b>				Service Pack .....				20003	35	4
<b>300</b>				<b>2002</b>						
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	<b>300M; Concorde; Intrepid; Prowler</b>						
EZ-sensor Service Pack; Almm. Valve .....	34000	62	7	EZ-sensor - 433 MHz .....	◇33100	11.5	1.3			
EZ-sensor Service Pack; Rubber Valve Sensor .....	20008	11.5	1.3	EZ-sensor Service Pack; Almm. Valve .....	34000	62	7			
or	28308	11.5	1.3	EZ-sensor Service Pack; Rubber Valve Sensor .....	20008	11.5	1.3			
Service Pack; W/Schrader Sensor; Includes Stem Only .....	20020	58	6.5	●20028	35	4				
Service Pack; W/Schrader Sensor; Does Not Include Stem .....	20013	58	6.5	Service Pack; W/Schrader Sensor .....	20003	35	4			
Service Pack; W/Siemens Sensor .....	20030	71	8	Service Pack; W/Siemens Sensor .....	20030	35	4			
<b>Crossfire</b>				<b>Town &amp; Country Van; Voyager</b>						
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor - 433 MHz .....	◇33100	11.5	1.3			
EZ-sensor - 433 MHz .....	◇33100	11.5	1.3	EZ-sensor Service Pack; Almm. Valve .....	34000	62	7			
EZ-sensor Service Pack; Almm. Valve .....	34000	62	7	EZ-sensor Service Pack; Rubber Valve Sensor .....	20008	11.5	1.3			
EZ-sensor Service Pack; Rubber Valve Sensor; OEM Part No. 5142340AA .....	20066	58	6.5	●20028	35	4				
or	28308	11.5	1.3	Service Pack .....	20003	35	4			
Sensor; OEM Part No. 52088990AC .....	●20028	35	4	<b>2001</b>						
Service Pack; OEM Part No. 5142340AA; Includes Stem Only .....	20020	58	6.5	<b>Prowler</b>						
Service Pack; OEM Part No. 5142340AA; Does Not Include Stem .....	20013	58	6.5	Sensor .....	28004	35	4			
Service Pack; OEM Part No. 52088990AC .....	20003	35	4	Service Pack; W/Black Sensor Body .....	20012	35	4			
<b>Pacifica; Town &amp; Country Van</b>				Service Pack; W/Red Sensor Body .....				20003	35	4
Sensor .....	20335	71	8	<b>► Dodge</b>						
Service Pack .....	20030	71	8	<b>2012</b>						
<b>2004</b>				<b>Avenger</b>						
<b>300M; Concorde; Crossfire; Intrepid</b>				EZ-sensor - 315 MHz .....				◇33000	11.5	1.3
EZ-sensor - 433 MHz .....	◇33100	11.5	1.3	EZ-sensor Service Pack; Almm. Valve .....	34000	62	7			
EZ-sensor Service Pack; Almm. Valve .....	34000	62	7	EZ-sensor Service Pack; Rubber Valve Sensor .....	20008	11.5	1.3			
EZ-sensor Service Pack; Rubber Valve Sensor .....	20008	11.5	1.3	or	20066	58	6.5			
Service Pack; W/Schrader Sensor .....	20003	35	4	Service Pack; W/Schrader Sensor; Includes Stem Only .....	28308	11.5	1.3			
Service Pack; W/Siemens Sensor .....	20030	35	4	Service Pack; W/Schrader Sensor; Does Not Include Stem .....	20013	58	6.5			
<b>Pacifica</b>				<b>Challenger</b>						
EZ-sensor - 433 MHz .....	◇33100	11.5	1.3	Sensor; W/Metal Stem Clamp-in Sensor .....	28291	58	6.5			
EZ-sensor Service Pack; Almm. Valve .....	34000	62	7	Sensor; W/Rubber Stem Snap-in Sensor .....	20398	11.5	1.3			
EZ-sensor Service Pack; Rubber Valve Sensor; OEM Part No. 04727392AD .....	20008	11.5	1.3	Service Pack; W/Metal Stem Clamp-in Sensor; Includes Stem Only .....	20020	58	6.5			
or	20335	71	8	Service Pack; W/Metal Stem Clamp-in Sensor; Does Not Include Stem .....	20016	58	6.5			
Sensor; OEM Part No. 52088990AC .....	●20028	35	4	Service Pack; W/Rubber Stem Snap-in Sensor .....	20008	11.5	1.3			
Service Pack; OEM Part No. 04727392AD .....	20030	71	8	<b>Charger; Durango; Grand Caravan; Journey; Ram 4500HD; Ram 5500HD; Ram Series Pickup</b>						
Service Pack; OEM Part No. 52088990AC .....	20003	35	4	Sensor .....	20398	11.5	1.3			
<b>Town &amp; Country Van</b>				Service Pack .....				20018	11.5	1.3
Sensor .....	20335	71	8	<b>2011</b>						
Service Pack .....	20030	71	8	<b>Avenger; Caliber</b>						
<b>2003</b>				EZ-sensor - 315 MHz .....				◇33000	11.5	1.3
<b>300M; Concorde; Intrepid</b>				EZ-sensor Service Pack; Almm. Valve .....				34000	62	7
EZ-sensor - 433 MHz .....	◇33100	11.5	1.3	EZ-sensor Service Pack; Rubber Valve Sensor .....	20008	11.5	1.3			
EZ-sensor Service Pack; Almm. Valve .....	34000	62	7	or	20066	58	6.5			
EZ-sensor Service Pack; Rubber Valve Sensor .....	20008	11.5	1.3	Service Pack; W/Schrader Sensor; Includes Stem Only .....	28308	11.5	1.3			
Service Pack; W/Schrader Sensor .....	20003	35	4	Service Pack; W/Schrader Sensor; Does Not Include Stem .....	20013	58	6.5			
Service Pack; W/Siemens Sensor .....	20030	35	4	<b>Challenger</b>						
<b>Town &amp; Country Van; Voyager</b>				Sensor; W/Metal Stem Clamp-in Sensor .....				28291	58	6.5
EZ-sensor - 433 MHz .....	◇33100	11.5	1.3	Sensor; W/Rubber Stem Snap-in Sensor .....	20398	11.5	1.3			
EZ-sensor Service Pack; Almm. Valve .....	34000	62	7	Service Pack; W/Metal Stem Clamp-in Sensor; Includes Stem Only .....	20020	58	6.5			

◇ Programming Tool Required.  
● Magnet Required to Activate Sensor.

## Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
<b>► Dodge - Continued</b>				<b>► Dodge - Continued</b>			
<b>2011 - Continued</b>				<b>2010 - Continued</b>			
<b>Challenger - Continued</b>				<b>Dakota - Continued</b>			
Service Pack; W/Metal Stem Clamp-in Sensor; Does Not Include Stem .....	20016	58	6.5	EZ-sensor Service Pack; Rubber Valve Sensor .....	20008 28154	11.5 58	1.3 6.5
Service Pack; W/Rubber Stem Snap-in Sensor .....	20008	11.5	1.3	or 28461	11.5	1.3	
<b>Charger</b>				Service Pack; Includes Stem Only .....	20020	58	6.5
Sensor; W/Rubber Stem Snap-in Sensor	20398	11.5	1.3	Service Pack; Does Not Include Stem ..	20013	58	6.5
Service Pack; W/Rubber Stem Snap-in Sensor .....	20008	11.5	1.3	<b>Grand Caravan; Journey</b>			
<b>Dakota</b>				Sensor .....	28155	58	6.5
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	or 28434	11.5	1.3	
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Service Pack; W/Schrader Sensor; Includes Stem Only .....	20020	58	6.5
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack; W/Schrader Sensor; Does Not Include Stem .....	20013	58	6.5
Sensor .....	20066	58	6.5	Service Pack; W/Siemens Sensor .....	20030	71	8
or 28308	11.5	1.3		<b>Nitro</b>			
Service Pack; Includes Stem Only .....	20020	58	6.5	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Service Pack; Does Not Include Stem ..	20013	58	6.5	EZ-sensor Service Pack; Almm. Valve	34000	62	7
<b>Durango; Grand Caravan; Journey</b>				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor .....	20398	11.5	1.3	Sensor .....	20066	58	6.5
Service Pack .....	20008	11.5	1.3	or 28308	11.5	1.3	
<b>Nitro</b>				Service Pack; Includes Stem Only .....	20020	58	6.5
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Service Pack; Does Not Include Stem ..	20013	58	6.5
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>Ram Series Pickup</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; 1500, 2500; W/Metal Stem			
Sensor .....	20066	58	6.5	Clamp-in Sensor .....	28155	58	6.5
or 28308	11.5	1.3		or 28434	11.5	1.3	
Service Pack; Includes Stem Only .....	20020	58	6.5	Sensor; W/Rubber Stem Snap-in Sensor	20398	11.5	1.3
Service Pack; Does Not Include Stem ..	20013	58	6.5	Service Pack; 1500, 2500; W/Metal Stem			
<b>Ram Series Pickup</b>				Clamp-in Sensor; Includes Stem Only	20020	58	6.5
Sensor; W/Rubber Stem Snap-in Sensor	20398	11.5	1.3	Service Pack; 1500, 2500; W/Metal Stem			
Service Pack; W/Rubber Stem Snap-in				Clamp-in Sensor; Does Not Include			
Sensor .....	20008	11.5	1.3	Stem .....	20013	58	6.5
<b>2010</b>				Service Pack; W/Rubber Stem Snap-in			
<b>Avenger</b>				Sensor .....	20008	11.5	1.3
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	<b>Sprinter</b>			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor .....	20066	58	6.5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
or 28308	11.5	1.3		Sensor .....	20089	53	6
Service Pack; W/Schrader Sensor; Includes Stem Only .....	20020	58	6.5	Service Pack; Includes Valve .....	20036	53	6
Service Pack; W/Schrader Sensor; Does Not Include Stem .....	20013	58	6.5	Service Pack; Does Not Include Valve .	20021	53	6
<b>Caliber</b>				<b>Viper</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor - 433 MHz .....	◇33100	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor .....	20066	58	6.5	Sensor .....	●20028	35	4
or 28308	11.5	1.3		Service Pack .....	20003	35	4
Service Pack; W/Schrader Sensor; Includes Stem Only .....	20020	58	6.5	<b>2009</b>			
Service Pack; W/Schrader Sensor; Does Not Include Stem .....	20013	58	6.5	<b>Avenger; Caliber</b>			
Service Pack; W/Siemens Sensor .....	20030	71	8	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
<b>Challenger; Charger</b>				EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor; W/Metal Stem Clamp-in Sensor	28291	58	6.5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor; W/Rubber Stem Snap-in Sensor	20398	11.5	1.3	Sensor .....	20066	58	6.5
Service Pack; W/Metal Stem Clamp-in Sensor; Includes Stem Only .....	20020	58	6.5	or 28308	11.5	1.3	
Service Pack; W/Metal Stem Clamp-in Sensor; Does Not Include Stem .....	20016	58	6.5	Service Pack; W/Schrader Sensor; Includes Stem Only .....	20020	58	6.5
Service Pack; W/Rubber Stem Snap-in Sensor .....	20008	11.5	1.3	Service Pack; W/Schrader Sensor; Does Not Include Stem .....	20013	58	6.5
<b>Dakota</b>				Service Pack; W/Siemens Sensor .....	20030	71	8
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	<b>Challenger; Charger</b>			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor .....	28291	58	6.5
				Service Pack; Includes Stem Only .....	20020	58	6.5
				Service Pack; Does Not Include Stem ..	20016	58	6.5
				<b>Dakota</b>			
				EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
				EZ-sensor Service Pack; Almm. Valve	34000	62	7

◇ Programming Tool Required.  
● Magnet Required to Activate Sensor.



## Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
<b>► Dodge - Continued</b>				<b>► Dodge - Continued</b>			
<b>2009 - Continued</b>				<b>2008 - Continued</b>			
<b>Dakota - Continued</b>				<b>Challenger - Continued</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack; Does Not Include Stem ..	20016	58	6.5
Sensor .....	28154	58	6.5	<b>Charger</b>			
or	28461	11.5	1.3	Sensor .....	28155	58	6.5
Service Pack; Includes Stem Only .....	20020	58	6.5	or	28434	11.5	1.3
Service Pack; Does Not Include Stem ..	20013	58	6.5	Service Pack; W/Schrader Sensor; Includes Stem Only .....	20020	58	6.5
<b>Durango</b>				Service Pack; W/Schrader Sensor; Does Not Include Stem .....	20013	58	6.5
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Service Pack; W/Siemens Sensor .....	20030	71	8
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>Dakota</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Sensor .....	20066	58	6.5	EZ-sensor Service Pack; Almm. Valve	34000	62	7
or	28308	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Service Pack; Includes Stem Only .....	20020	58	6.5	Sensor .....	28154	58	6.5
Service Pack; Does Not Include Stem ..	20013	58	6.5	or	28461	11.5	1.3
<b>Grand Caravan; Journey</b>				Service Pack; Includes Stem Only .....	20020	58	6.5
Sensor .....	28155	58	6.5	Service Pack; Does Not Include Stem ..	20013	58	6.5
or	28434	11.5	1.3	<b>Durango</b>			
Service Pack; W/Schrader Sensor; Includes Stem Only .....	20020	58	6.5	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Service Pack; W/Schrader Sensor; Does Not Include Stem .....	20013	58	6.5	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Service Pack; W/Siemens Sensor .....	20030	71	8	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
<b>Nitro</b>				Sensor .....	20066	58	6.5
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	or	28308	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Service Pack; W/Schrader Sensor; Includes Stem Only .....	20020	58	6.5
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack; W/Schrader Sensor; Does Not Include Stem .....	20013	58	6.5
Sensor .....	20066	58	6.5	Service Pack; W/Siemens Sensor .....	20030	71	8
or	28308	11.5	1.3	<b>Grand Caravan; Magnum</b>			
Service Pack; Includes Stem Only .....	20020	58	6.5	Sensor .....	28155	58	6.5
Service Pack; Does Not Include Stem ..	20013	58	6.5	or	28434	11.5	1.3
<b>Ram Series Pickup</b>				Service Pack; W/Schrader Sensor; Includes Stem Only .....	20020	58	6.5
Sensor; 1500, 2500 .....	28155	58	6.5	Service Pack; W/Schrader Sensor; Does Not Include Stem .....	20013	58	6.5
or	28434	11.5	1.3	Service Pack; W/Siemens Sensor .....	20030	71	8
Service Pack; 1500, 2500; Includes Stem Only .....	20020	58	6.5	<b>Nitro</b>			
Service Pack; 1500, 2500; Does Not Include Stem .....	20013	58	6.5	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
<b>Sprinter</b>				EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor .....	20066	58	6.5
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	or	28308	11.5	1.3
Sensor .....	20089	53	6	Service Pack; W/Schrader Sensor; Includes Stem Only .....	20020	58	6.5
Service Pack; Includes Valve .....	20036	53	6	Service Pack; W/Schrader Sensor; Does Not Include Stem .....	20013	58	6.5
Service Pack; Does Not Include Valve .	20021	53	6	Service Pack; W/Siemens Sensor .....	20030	71	8
<b>Viper</b>				<b>Ram Series Pickup</b>			
EZ-sensor - 433 MHz .....	◇33100	11.5	1.3	EZ-sensor - 315 MHz; 1500, 2500 .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; 1500, 2500; Almm. Valve .....	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; 1500, 2500; Rubber Valve .....	20008	11.5	1.3
Sensor .....	●20028	35	4	Sensor; 1500, 2500 .....	28154	58	6.5
Service Pack .....	20003	35	4	or	28461	11.5	1.3
<b>2008</b>				Service Pack; 1500, 2500; Includes Stem Only .....	20020	58	6.5
<b>Avenger; Caliber</b>				Service Pack; 1500, 2500; Does Not Include Stem .....	20013	58	6.5
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	<b>Sprinter</b>			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor .....	20066	58	6.5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
or	28308	11.5	1.3	Sensor .....	20089	53	6
Service Pack; W/Schrader Sensor; Includes Stem Only .....	20020	58	6.5	Service Pack; Includes Valve .....	20036	53	6
Service Pack; W/Schrader Sensor; Does Not Include Stem .....	20013	58	6.5	Service Pack; Does Not Include Valve .	20021	53	6
Service Pack; W/Siemens Sensor .....	20030	71	8				
<b>Challenger</b>							
Sensor .....	28291	58	6.5				
Service Pack; Includes Stem Only .....	20020	58	6.5				

◇ Programming Tool Required.  
● Magnet Required to Activate Sensor.



# Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
<b>► Dodge - Continued</b>				<b>► Dodge - Continued</b>			
<b>2008 - Continued</b>				<b>2004</b>			
<b>Viper</b>				<b>Caravan; Grand Caravan</b>			
EZ-sensor - 433 MHz .....	◇33100	11.5	1.3	Sensor .....	20335	71	8
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Service Pack .....	20030	71	8
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	<b>Intrepid</b>			
Sensor .....	●20028	35	4	Sensor .....	●20028	35	4
Service Pack .....	20003	35	4	Service Pack .....	20003	35	4
<b>2007</b>				<b>Viper</b>			
<b>Caliber; Caravan; Charger; Durango; Grand Caravan; Magnum; Nitro</b>				EZ-sensor - 433 MHz .....			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	◇33100	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor .....	●20028	35	4
Sensor .....	20066	58	6.5	Service Pack .....	20003	35	4
or 28308	11.5	1.3	<b>2003</b>				
Service Pack; W/Schrader Sensor; Includes Stem Only .....	20020	58	6.5	<b>Caravan; Grand Caravan; Intrepid; Viper</b>			
Service Pack; W/Schrader Sensor; Does Not Include Stem .....	20013	58	6.5	EZ-sensor - 433 MHz .....	◇33100	11.5	1.3
Service Pack; W/Siemens Sensor .....	20030	71	8	EZ-sensor Service Pack; Almm. Valve	34000	62	7
<b>Sprinter</b>				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Sensor .....	●20028	35	4
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Service Pack .....	20003	35	4
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	<b>2002</b>			
Sensor .....	20089	53	6	<b>Caravan; Grand Caravan; Intrepid</b>			
Service Pack; Includes Valve .....	20036	53	6	EZ-sensor - 433 MHz .....	◇33100	11.5	1.3
Service Pack; Does Not Include Valve	20021	53	6	EZ-sensor Service Pack; Almm. Valve	34000	62	7
<b>2006</b>				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
<b>Caravan; Charger; Grand Caravan; Magnum</b>				Sensor .....	●20028	35	4
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Service Pack .....	20003	35	4
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>► Ferrari</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	<b>2009-2006</b>			
Sensor .....	20066	58	6.5	<b>612 Scaglietti; F430</b>			
or 28308	11.5	1.3	Sensor; Includes Transmitter Only .....	20077	35	4	
Service Pack; W/Schrader Sensor; Includes Stem Only .....	20020	58	6.5	Service Pack; Does Not Include Valve	20023	35	4
Service Pack; W/Schrader Sensor; Does Not Include Stem .....	20013	58	6.5	Service Pack; W/43mm Silver Insert ...	20037	35	4
Service Pack; W/Siemens Sensor .....	20030	71	8	Service Pack; W/48mm Green Insert ...	20038	35	4
<b>Viper</b>				Service Pack; W/49mm Black Insert .....	20039	35	4
EZ-sensor - 433 MHz .....	◇33100	11.5	1.3	Service Pack; W/51mm Orange Insert .	20040	35	4
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>2005</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	<b>575M Maranello; 612 Scaglietti; F430</b>			
Sensor .....	●20028	35	4	Sensor; Includes Transmitter Only .....	20077	35	4
Service Pack .....	20003	35	4	Service Pack; Does Not Include Valve	20023	35	4
<b>2005</b>				Service Pack; W/43mm Silver Insert ...	20037	35	4
<b>Caravan; Grand Caravan</b>				Service Pack; W/48mm Green Insert ...	20038	35	4
Sensor .....	20335	71	8	Service Pack; W/49mm Black Insert .....	20039	35	4
Service Pack .....	20030	71	8	Service Pack; W/51mm Orange Insert .	20040	35	4
<b>Magnum</b>				<b>2004</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	<b>575M Maranello; 612 Scaglietti</b>			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor; Includes Transmitter Only .....	20077	35	4
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack; Does Not Include Valve	20023	35	4
Sensor .....	20066	58	6.5	Service Pack; W/43mm Silver Insert ...	20037	35	4
or 28308	11.5	1.3	Service Pack; W/48mm Green Insert ...	20038	35	4	
Service Pack; W/Schrader Sensor; Includes Stem Only .....	20020	58	6.5	Service Pack; W/49mm Black Insert .....	20039	35	4
Service Pack; W/Schrader Sensor; Does Not Include Stem .....	20013	58	6.5	Service Pack; W/51mm Orange Insert .	20040	35	4
Service Pack; W/Siemens Sensor .....	20030	71	8	<b>Enzo</b>			
<b>Viper</b>				Sensor; Includes Transmitter Only .....	20084	35	4
EZ-sensor - 433 MHz .....	◇33100	11.5	1.3	Service Pack; Does Not Include Valve	20023	35	4
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Service Pack; W/43mm Silver Insert ...	20037	35	4
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack; W/48mm Green Insert ...	20038	35	4
Sensor .....	●20028	35	4	Service Pack; W/49mm Black Insert .....	20039	35	4
Service Pack .....	20003	35	4	Service Pack; W/51mm Orange Insert .	20040	35	4
<b>2003</b>				<b>2003</b>			
<b>575M Maranello</b>				<b>575M Maranello</b>			
Sensor; Includes Transmitter Only .....	20077	35	4	Sensor; Includes Transmitter Only .....	20077	35	4

● Magnet Required to Activate Sensor.  
◇ Programming Tool Required.

## Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
<b>► Ferrari - Continued</b>				<b>► Ford - Continued</b>			
<b>2003 - Continued</b>				<b>2013 - Continued</b>			
<b>575M Maranello - Continued</b>				<b>Explorer; F Series Pickup; Fiesta; Flex - Continued</b>			
Service Pack; Does Not Include Valve .	20023	35	4	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Service Pack; W/43mm Silver Insert ....	20037	35	4	Sensor .....	20315	11.5	1.3
Service Pack; W/48mm Green Insert ...	20038	35	4	Service Pack .....	20018	11.5	1.3
Service Pack; W/49mm Black Insert .....	20039	35	4	<b>Focus</b>			
Service Pack; W/51mm Orange Insert .	20040	35	4	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
<b>Enzo</b>				EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor; Includes Transmitter Only .....	20084	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Service Pack; Does Not Include Valve .	20023	35	4	Sensor .....	20315	13	1.5
Service Pack; W/43mm Silver Insert ....	20037	35	4	Service Pack .....	20018	11.5	1.3
Service Pack; W/48mm Green Insert ...	20038	35	4	<b>Fusion; Mustang</b>			
Service Pack; W/49mm Black Insert .....	20039	35	4	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Service Pack; W/51mm Orange Insert .	20040	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
				EZ-sensor Service Pack; Almm. Valve	34000	62	7
				Sensor .....	20315	11.5	1.3
				Service Pack .....	20018	11.5	1.3
				<b>Police Interceptor Sedan</b>			
				EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
				EZ-sensor Service Pack; Almm. Valve	34000	62	7
				<b>Police Interceptor Utility</b>			
				EZ-sensor Service Pack; Almm. Valve	34000	62	7
				<b>Super Duty Pickup; Super Duty Van</b>			
				EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
				EZ-sensor Service Pack; Almm. Valve	34000	62	7
				<b>Taurus</b>			
				EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
				EZ-sensor Service Pack; Almm. Valve	34000	62	7
				Sensor .....	20315	11.5	1.3
				Service Pack .....	20018	11.5	1.3
				<b>Transit Connect</b>			
				EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
				EZ-sensor Service Pack; Almm. Valve	34000	62	7
				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
				Sensor .....	20315	13	1.5
				Service Pack .....	20018	11.5	1.3
				<b>2012</b>			
				<b>E Series Van; Edge; Escape; Expedition; Explorer; F Series Pickup; Fiesta; Flex</b>			
				EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
				EZ-sensor Service Pack; Almm. Valve	34000	62	7
				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
				Sensor .....	20315	11.5	1.3
				Service Pack .....	20018	11.5	1.3
				<b>Focus</b>			
				EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
				EZ-sensor Service Pack; Almm. Valve	34000	62	7
				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
				Sensor .....	20315	13	1.5
				Service Pack .....	20018	11.5	1.3
				<b>Fusion; Mustang; Super Duty Pickup; Taurus; Transit Connect</b>			
				EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
				EZ-sensor Service Pack; Almm. Valve	34000	62	7
				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
				Sensor .....	20315	11.5	1.3
				Service Pack .....	20018	11.5	1.3
				<b>2011</b>			
				<b>Crown Victoria</b>			
				EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
				EZ-sensor Service Pack; Almm. Valve	34000	62	7
				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
				Sensor .....	28385	27	3
				Sensor Clip .....	22100		

◇ Programming Tool Required.

## Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
<b>► Ford - Continued</b>				<b>► Ford - Continued</b>			
<b>2011 - Continued</b>				<b>2010 - Continued</b>			
<b>Crown Victoria - Continued</b>				<b>Edge - Continued</b>			
Sensor Cradle .....	22101			EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor Universal Band .....	22102			Sensor .....	28390	27	3
<b>E Series Van; Edge; Escape; Expedition; Explorer; F Series Pickup</b>				<b>Escape</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor .....	20315	11.5	1.3	Sensor .....	20315	11.5	1.3
<b>Fiesta; Flex; Focus; Fusion; Mustang</b>				<b>Expedition</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor .....	20315	11.5	1.3	Sensor .....	20315	11.5	1.3
Service Pack .....	20018	11.5	1.3	Service Pack .....	20018	11.5	1.3
<b>Ranger</b>				<b>Explorer; Explorer Sport Trac</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor .....	28385	27	3	Sensor .....	28385	27	3
Sensor Clip .....	22100			Sensor Clip .....	22100		
Sensor Cradle .....	22101			Sensor Cradle .....	22101		
Sensor Universal Band .....	22102			Sensor Universal Band .....	22102		
<b>Super Duty Pickup; Super Duty Van</b>				<b>F450 Super Duty; F550 Super Duty</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor .....	20315	11.5	1.3	Sensor .....	28395	27	3
<b>Taurus; Transit Connect</b>				<b>F Series Pickup</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor .....	20315	11.5	1.3	Sensor .....	20315	11.5	1.3
Service Pack .....	20018	11.5	1.3	Service Pack .....	20018	11.5	1.3
<b>2010</b>				<b>Flex</b>			
<b>Crown Victoria</b>				<b>EZ-sensor - 315 MHz .....</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor .....	28390	27	3
Sensor .....	28385	27	3	Sensor Clip .....	22100		
Sensor Clip .....	22100			Sensor Cradle .....	22101		
Sensor Cradle .....	22101			Sensor Universal Band .....	22102		
Sensor Universal Band .....	22102			<b>F Series Pickup</b>			
<b>E450 Super Duty</b>				<b>EZ-sensor - 315 MHz .....</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor .....	20315	11.5	1.3
Sensor .....	20315	11.5	1.3	Service Pack .....	20018	11.5	1.3
Service Pack .....	20018	11.5	1.3	<b>Focus</b>			
<b>E Series Van</b>				<b>EZ-sensor - 315 MHz .....</b>			
EZ-sensor - 315 MHz; W/Alloy Wheels	◇33000	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; W/Alloy Wheels; Almm. Valve .....	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; W/Alloy Wheels; Rubber Valve .....	20008	11.5	1.3	Sensor .....	20315	13	1.5
Sensor; W/Alloy Wheels .....	28395	27	3	Service Pack .....	20018	11.5	1.3
Sensor; W/Steel Wheels .....	20315	11.5	1.3	<b>Fusion</b>			
Service Pack; W/Steel Wheels .....	20018	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Sensor Clip; W/Alloy Wheels .....	22100			EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor Cradle; W/Alloy Wheels .....	22101			EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor Universal Band; W/Alloy Wheels	22102			Sensor .....	20315	11.5	1.3
<b>Edge</b>				<b>Service Pack .....</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	20018	11.5	1.3	
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>Grand Marquis</b>			
<b>Edge</b>				<b>EZ-sensor - 315 MHz .....</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Almm. Valve	34000	62	7				

◇ Programming Tool Required.





## Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
<b>► Ford - Continued</b>				<b>► Ford - Continued</b>			
<b>2009 - Continued</b>				<b>2008 - Continued</b>			
<b>Fusion; Grand Marquis; Mustang; Ranger - Continued</b>				<b>Expedition - Continued</b>			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor Cradle .....	22101		
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor Universal Band .....	22102		
Sensor .....	28385	27	3	<b>Explorer; Explorer Sport Trac</b>			
Sensor Clip .....	22100			EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Sensor Cradle .....	22101			EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor Universal Band .....	22102			EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
<b>Super Duty Pickup; Super Duty Van</b>				Sensor .....	28385	27	3
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Sensor Clip .....	22100		
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor Cradle .....	22101		
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor Universal Band .....	22102		
Sensor .....	28395	27	3	<b>F450 Super Duty</b>			
Sensor Clip .....	22100			EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Sensor Cradle .....	22101			EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor Universal Band .....	22102			EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
<b>Taurus; Taurus X</b>				Sensor .....	28395	27	3
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Sensor Clip .....	22100		
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor Cradle .....	22101		
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor Universal Band .....	22102		
Sensor .....	28390	27	3	<b>F Series Pickup</b>			
Sensor Clip .....	22100			EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Sensor Cradle .....	22101			EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor Universal Band .....	22102			EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
<b>2008</b>				Sensor; W/H.D. Payload Pkg. ....	28395	27	3
<b>Crown Victoria</b>				Sensor; W/O H.D. Payload Pkg. ....	28385	27	3
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Sensor Clip .....	22100		
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor Cradle .....	22101		
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor Universal Band .....	22102		
Sensor .....	28385	27	3	<b>Focus</b>			
Sensor Clip .....	22100			EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Sensor Cradle .....	22101			EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor Universal Band .....	22102			EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
<b>E450 Super Duty; E Series Van</b>				Sensor .....	28390	27	3
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Sensor Clip .....	22100		
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor Cradle .....	22101		
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor Universal Band .....	22102		
Sensor .....	28395	27	3	<b>Fusion; Grand Marquis; Mustang; Ranger</b>			
Sensor Clip .....	22100			EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Sensor Cradle .....	22101			EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor Universal Band .....	22102			EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
<b>Edge</b>				Sensor .....	28385	27	3
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Sensor Clip .....	22100		
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor Cradle .....	22101		
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor Universal Band .....	22102		
Sensor; W/Chrome Plated Almm. Wheels .....	28385	27	3	<b>Super Duty Pickup; Super Duty Van</b>			
Sensor; W/O Chrome Plated Almm. Wheels .....	28390	27	3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Sensor Clip .....	22100			EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor Cradle .....	22101			EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor Universal Band .....	22102			Sensor .....	28395	27	3
<b>Escape</b>				Sensor Clip .....	22100		
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Sensor Cradle .....	22101		
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor Universal Band .....	22102		
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	<b>Taurus; Taurus X</b>			
Sensor .....	28385	27	3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Sensor Clip .....	22100			EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor Cradle .....	22101			EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor Universal Band .....	22102			Sensor .....	28390	27	3
<b>Expedition</b>				Sensor Clip .....	22100		
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Sensor Cradle .....	22101		
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor Universal Band .....	22102		
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	<b>2007</b>			
Sensor .....	28390	27	3	<b>Crown Victoria; E Series Van</b>			
Sensor Clip .....	22100			EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
<b>2007</b>				EZ-sensor Service Pack; Almm. Valve	34000	62	7
<b>Crown Victoria; E Series Van</b>							
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3				
EZ-sensor Service Pack; Almm. Valve	34000	62	7				

◇ Programming Tool Required.



## Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
<b>► Ford - Continued</b>				<b>► Ford - Continued</b>			
<b>2007 - Continued</b>				<b>2006 - Continued</b>			
<b>Crown Victoria; E Series Van - Continued</b>				<b>Crown Victoria; Escape - Continued</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor Universal Band .....	22102		
Sensor .....	28385	27	3	<b>Expedition</b>			
Sensor Clip .....	22100			Sensor .....	●20135	44	5
Sensor Cradle .....	22101			Service Pack .....	20002	44	5
Sensor Universal Band .....	22102			<b>Explorer</b>			
<b>Edge</b>				EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor .....	28385	27	3
Sensor; W/Chrome Plated Almm.				Sensor Clip .....	22100		
Wheels .....	28385	27	3	Sensor Cradle .....	22101		
Sensor; W/O Chrome Plated Almm.				Sensor Universal Band .....	22102		
Wheels .....	28390	27	3	<b>Five Hundred</b>			
Sensor Clip .....	22100			EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Sensor Cradle .....	22101			EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor Universal Band .....	22102			EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
<b>Escape</b>				Sensor .....	28390	27	3
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Sensor Clip .....	22100		
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor Cradle .....	22101		
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor Universal Band .....	22102		
Sensor .....	28385	27	3	<b>Freestar; Grand Marquis</b>			
Sensor Clip .....	22100			EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Sensor Cradle .....	22101			EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor Universal Band .....	22102			EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
<b>Expedition</b>				Sensor .....	28385	27	3
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Sensor Clip .....	22100		
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor Cradle .....	22101		
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor Universal Band .....	22102		
Sensor .....	28390	27	3	<b>2005</b>			
Sensor Clip .....	22100			<b>Escape</b>			
Sensor Cradle .....	22101			EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Sensor Universal Band .....	22102			EZ-sensor Service Pack; Almm. Valve	34000	62	7
<b>Explorer; Explorer Sport Trac; F Series Pickup</b>				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Sensor; Oct. 3, 2005 & Newer .....	28385	27	3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor Clip .....	22100		
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor Cradle .....	22101		
Sensor .....	28385	27	3	Sensor Universal Band .....	22102		
Sensor Clip .....	22100			<b>Expedition</b>			
Sensor Cradle .....	22101			Sensor .....	●20135	44	5
Sensor Universal Band .....	22102			Service Pack .....	20002	44	5
<b>Five Hundred</b>				<b>Explorer</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor - 433 MHz .....	◇33100	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor .....	28390	27	3	Sensor .....	●20096	44	5
Sensor Clip .....	22100			Service Pack .....	20002	44	5
Sensor Cradle .....	22101			<b>Freestar</b>			
Sensor Universal Band .....	22102			Sensor; W/Almm. Valve Stem .....	●20135	44	5
<b>Focus; Freestar; Fusion; Grand Marquis; Mustang; Ranger</b>				Service Pack; W/Almm. Valve Stem ...	20002	44	5
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	<b>2004</b>			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>Expedition; Explorer</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 433 MHz .....	◇33100	11.5	1.3
Sensor .....	28385	27	3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor Clip .....	22100			EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor Cradle .....	22101			Sensor .....	●20096	44	5
Sensor Universal Band .....	22102			Service Pack .....	20002	44	5
<b>2006</b>				<b>Freestar</b>			
<b>Crown Victoria; Escape</b>				Sensor; W/Almm. Valve Stem .....	●20135	44	5
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Service Pack; W/Almm. Valve Stem ...	20002	44	5
EZ-sensor Service Pack; Almm. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor .....	28385	27	3				
Sensor Clip .....	22100						
Sensor Cradle .....	22101						

◇ Programming Tool Required.  
● Magnet Required to Activate Sensor.

## Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
<b>► Ford - Continued</b>				<b>► GMC - Continued</b>			
<b>2003</b>				<b>2012-2010 - Continued</b>			
<b>Escape</b>				<b>Acadia - Continued</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor .....	20153	11.5	1.3
<b>Expedition</b>				Service Pack .....	20008	11.5	1.3
EZ-sensor - 433 MHz .....	◇33100	11.5	1.3	<b>Canyon</b>			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor .....	●20096	44	5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Service Pack .....	20002	44	5	Sensor .....	20131	62	7
<b>Explorer</b>				Service Pack .....	20006	62	7
EZ-sensor - 433 MHz .....	◇33100	11.5	1.3	<b>Savana</b>			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor; Exc. Sport .....	●20096	44	5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Service Pack; Exc. Sport .....	20002	44	5	Sensor .....	20153	11.5	1.3
<b>2002</b>				Service Pack .....	20008	11.5	1.3
<b>Explorer</b>				<b>Sierra Series Pickup</b>			
EZ-sensor - 433 MHz .....	◇33100	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor; Exc. Sport .....	●20096	44	5	Sensor; W/Single Rear Wheels .....	20153	11.5	1.3
Service Pack; Exc. Sport .....	20002	44	5	Service Pack; W/Single Rear Wheels ...	20008	11.5	1.3
<b>► Freightliner</b>				<b>Terrain</b>			
<b>2008-2007</b>				EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
<b>Sprinter</b>				EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor .....	28206	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack .....	20008	11.5	1.3
Sensor .....	20089	53	6	<b>Yukon</b>			
Service Pack; Includes Valve .....	20036	53	6	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Service Pack; Does Not Include Valve .	20021	53	6	EZ-sensor Service Pack; Almm. Valve	34000	62	7
<b>► GMC</b>				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
<b>2013</b>				Sensor .....	20153	11.5	1.3
<b>Acadia; Savana</b>				Service Pack .....	20008	11.5	1.3
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	<b>2009</b>			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>Acadia</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Sensor .....	20153	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Service Pack .....	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
<b>Sierra Series Pickup</b>				Sensor .....	20153	11.5	1.3
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Service Pack .....	20008	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>Canyon</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Sensor; W/Single Rear Wheels .....	20153	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Service Pack; W/Single Rear Wheels ...	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
<b>Terrain</b>				Sensor .....	20131	62	7
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Service Pack .....	20006	62	7
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>Envo</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Sensor .....	28206	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Service Pack .....	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
<b>Yukon</b>				Sensor .....	20153	11.5	1.3
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Service Pack .....	20008	62	7
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>Savana</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Sensor .....	20153	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Service Pack .....	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
<b>2012-2010</b>				Sensor .....	20158	62	7
<b>Acadia</b>				Service Pack; W/Schrader Sensor .....	20004	62	7
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Service Pack; W/Siemens Sensor .....	20030	80	9
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>Sierra Series Pickup</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
<b>2008-2007</b>				EZ-sensor Service Pack; Almm. Valve	34000	62	7
<b>Sprinter</b>				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Sensor; W/Single Rear Wheels .....	20153	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>2009</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	<b>Acadia</b>			
Sensor .....	20089	53	6	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Service Pack; Includes Valve .....	20036	53	6	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Service Pack; Does Not Include Valve .	20021	53	6	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
<b>► GMC</b>				Sensor .....	20153	11.5	1.3
<b>2013</b>				Service Pack .....	20008	11.5	1.3
<b>Acadia; Savana</b>				<b>Canyon</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor .....	20153	11.5	1.3	Sensor .....	20131	62	7
Service Pack .....	20008	11.5	1.3	Service Pack .....	20006	62	7
<b>Sierra Series Pickup</b>				<b>Envo</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor; W/Single Rear Wheels .....	20153	11.5	1.3	Sensor .....	20153	11.5	1.3
Service Pack; W/Single Rear Wheels ...	20008	11.5	1.3	Service Pack .....	20008	62	7
<b>Terrain</b>				<b>Savana</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor .....	28206	11.5	1.3	Sensor .....	20158	62	7
Service Pack .....	20008	11.5	1.3	Service Pack; W/Schrader Sensor .....	20004	62	7
<b>Yukon</b>				Service Pack; W/Siemens Sensor .....	20030	80	9
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	<b>Sierra Series Pickup</b>			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor .....	20153	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Service Pack .....	20008	11.5	1.3	Sensor; W/Single Rear Wheels .....	20153	11.5	1.3
<b>2012-2010</b>				<b>2009</b>			
<b>Acadia</b>				<b>Acadia</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3

◇ Programming Tool Required.  
● Magnet Required to Activate Sensor.

## Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
<b>► GMC - Continued</b>				<b>► GMC - Continued</b>			
<b>2009 - Continued</b>				<b>2007 - Continued</b>			
<b>Sierra Series Pickup - Continued</b>				<b>Envoy - Continued</b>			
Service Pack; W/Single Rear Wheels ...	20008	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
<b>Yukon</b>				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Sensor .....	20116	62	7
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Service Pack .....	20004	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	<b>Sierra Series Pickup</b>			
Sensor .....	20153	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Service Pack .....	20008	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
<b>2008</b>				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
<b>Acadia</b>				Sensor; Clamp-In Style Only; TRW			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Sensor; W/Almm. Valve Stem; Exc.	20158	62	7
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Classic .....			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; Snap-In Style Only; Schrader			
Sensor .....	20158	62	7	Sensor; W/Rubber Valve Stem; Exc.	20153	11.5	1.3
Service Pack; W/Schrader Sensor .....	20004	62	7	Classic .....			
Service Pack; W/Siemens Sensor .....	20030	80	9	Sensor; Classic .....	20107	62	7
<b>Canyon</b>				Service Pack; Clamp-In Style Only; TRW			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Sensor; W/Almm. Valve Stem; Exc.	20015	80	9
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Classic .....			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack; Snap-In Style Only;			
Sensor .....	20131	62	7	Schrader Sensor; W/Rubber Valve			
Service Pack .....	20006	62	7	Stem; Exc. Classic .....	20008	11.5	1.3
<b>Envoy</b>				Service Pack; Classic .....	20004	62	7
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	<b>Yukon</b>			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor .....	20153	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Service Pack .....	20008	11.5	1.3	Sensor; Clamp-In Style Only; TRW			
<b>Savana</b>				Sensor; W/Almm. Valve Stem .....	20158	62	7
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Sensor; Snap-In Style Only; Schrader			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor; W/Rubber Valve Stem .....	20153	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack; Clamp-In Style Only; TRW			
Sensor .....	20158	62	7	Sensor; W/Almm. Valve Stem .....	20015	62	7
Service Pack; W/Schrader Sensor .....	20004	62	7	Service Pack; Snap-In Style Only;			
Service Pack; W/Siemens Sensor .....	20030	80	9	Schrader Sensor; W/Rubber Valve			
<b>Sierra Series Pickup</b>				Stem .....	20008	11.5	1.3
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	<b>2006</b>			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>Envoy</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Sensor; W/Single Rear Wheels .....	20153	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Service Pack; W/Single Rear Wheels ...	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
<b>Yukon</b>				Sensor .....	20116	62	7
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Service Pack .....	20004	62	7
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>Sierra Series Pickup; Yukon</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor .....	20107	62	7
Sensor .....	20153	11.5	1.3	Service Pack .....	20004	62	7
Service Pack .....	20008	11.5	1.3	<b>2005</b>			
<b>2007</b>				<b>Sierra Series Pickup; Yukon</b>			
<b>Acadia</b>				Sensor .....	20107	62	7
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Service Pack .....	20004	62	7
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>2004</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	<b>Sierra Series Pickup; Yukon</b>			
Sensor .....	20158	62	7	Sensor .....	20115	62	7
Service Pack; W/Schrader Sensor .....	20004	62	7	Service Pack .....	20004	62	7
Service Pack; W/Siemens Sensor .....	20030	80	9	<b>► Honda</b>			
<b>Canyon</b>				<b>2013</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	<b>CR-V; CR-Z; Fit; Odyssey</b>			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor .....	20131	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Service Pack .....	20006	62	7	Sensor .....	28720	35	4
<b>Envoy</b>				Service Pack .....	20019	35	4
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	<b>Pilot</b>			
				Sensor; W/Alloy Wheels .....	20098	35	4

◇ Programming Tool Required.

## Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
<b>► Honda - Continued</b>				<b>► Honda - Continued</b>			
<b>2013 - Continued</b>				<b>2011 - Continued</b>			
<b>Pilot - Continued</b>				<b>Pilot</b>			
Service Pack; W/Alloy Wheels .....	20032	35	4	Sensor; Exc. LX .....	20098	35	4
<b>2012</b>				Service Pack; Exc. LX .....	20032	35	4
<b>Accord</b>				<b>Ridgeline</b>			
Sensor .....	20099	35	4	Sensor; RT .....	28981	35	4
Service Pack .....	20032	35	4	Sensor; Exc. RT .....	28981	35	4
<b>Civic; CR-V; CR-Z</b>				Service Pack; RT; Includes Valve .....	20036	35	4
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Service Pack; Does Not Include Valve .	20021	35	4
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>2010</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	<b>Accord</b>			
Sensor .....	28720	35	4	EZ-sensor - 315 MHz; Exc. Crosstour ..	◇33000	11.5	1.3
Service Pack .....	20019	35	4	EZ-sensor Service Pack; Exc. Crosstour; Almm. Valve .....	34000	62	7
<b>Crosstour</b>				EZ-sensor Service Pack; Exc. Crosstour; Rubber Valve .....	20008	11.5	1.3
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Sensor; Exc. Crosstour .....	20099	35	4
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor; Crosstour .....	20100	35	4
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack; Exc. Crosstour .....	20032	35	4
Sensor .....	20100	71	8	<b>Civic</b>			
Service Pack .....	20032	35	4	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
<b>Fit; Insight; Odyssey</b>				EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor .....	28720	35	4
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack .....	20019	35	4
Sensor .....	28720	35	4	<b>CR-V</b>			
Service Pack .....	20019	35	4	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
<b>Pilot</b>				EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor; W/Alloy Wheels .....	20098	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Service Pack; W/Alloy Wheels .....	20032	35	4	Sensor .....	20099	35	4
<b>Ridgeline</b>				Service Pack .....	20032	35	4
Service Pack; RT; Includes Valve .....	20036	35	4	<b>Element; Fit; Insight</b>			
Service Pack; Does Not Include Valve .	20021	35	4	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Sensor .....	28981	35	4	EZ-sensor Service Pack; Almm. Valve	34000	62	7
<b>2011</b>				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
<b>Accord</b>				Sensor .....	28720	35	4
EZ-sensor - 315 MHz; Exc. Crosstour ..	◇33000	11.5	1.3	Service Pack .....	20019	35	4
EZ-sensor Service Pack; Exc. Crosstour; Almm. Valve .....	34000	62	7	<b>Odyssey</b>			
EZ-sensor Service Pack; Exc. Crosstour; Rubber Valve .....	20008	11.5	1.3	Sensor .....	28983	31-40	3.5-4.5
Sensor; Exc. Crosstour .....	20099	35	4	Service Pack; Includes Valve .....	20036	31-40	3.5-4.5
Sensor; Crosstour .....	20100	35	4	Service Pack; Does Not Include Valve .	20021	31-40	3.5-4.5
Service Pack; Exc. Crosstour .....	20032	35	4	<b>Pilot</b>			
<b>Civic</b>				Sensor; Exc. LX .....	20098	35	4
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Service Pack; Exc. LX .....	20032	35	4
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>Ridgeline</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; RT .....	28981	35	4
Sensor .....	28720	35	4	Sensor; Exc. RT .....	28981	35	4
Service Pack .....	20019	35	4	Service Pack; RT; Includes Valve .....	20036	35	4
<b>CR-V</b>				Service Pack; Does Not Include Valve .	20021	35	4
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	<b>2009</b>			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>Accord</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Sensor .....	20099	35	4	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Service Pack .....	20032	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
<b>CR-Z</b>				Sensor .....	20099	35	4
Sensor .....	28720	35	4	Service Pack .....	20032	35	4
Service Pack .....	20019	35	4	<b>Civic</b>			
<b>Element; Fit; Insight; Odyssey</b>				EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor .....	28720	35	4
Sensor .....	28720	35	4	Service Pack .....	20019	35	4
Service Pack .....	20019	35	4	<b>CR-V</b>			
<b>◇ Programming Tool Required.</b>				EZ-sensor - 315 MHz .....	◇33000	11.5	1.3

## Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
<b>▶ Honda - Continued</b>				<b>▶ Honda - Continued</b>			
<b>2009 - Continued</b>				<b>2008 - Continued</b>			
<b>CR-V - Continued</b>				<b>Ridgeline - Continued</b>			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Service Pack; RTL, RTS, RTX; Includes Valve	20036	35	4
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack; Does Not Include Valve	20021	35	4
Sensor	20099	35	4	<b>S2000</b>			
Service Pack	20032	35	4	EZ-sensor - 315 MHz	33000	11.5	1.3
<b>Element; Fit</b>				EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Service Pack	20032	35	4
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	<b>2007</b>			
Sensor	28720	35	4	<b>CR-V</b>			
Service Pack	20019	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3
<b>Odyssey</b>				EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor	28983	31-40	3.5-4.5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Service Pack; Includes Valve	20036	31-40	3.5-4.5	Sensor	20099	35	4
Service Pack; Does Not Include Valve	20021	31-40	3.5-4.5	Service Pack	20032	35	4
<b>Pilot</b>				<b>Element</b>			
Sensor; W/Alloy Wheels	20098	35	4	Service Pack; Includes Valve	20036	35	4
Service Pack; W/Alloy Wheels	20032	35	4	Service Pack; Does Not Include Valve	20021	35	4
<b>Ridgeline</b>				<b>Odyssey</b>			
Sensor	28981	35	4	Sensor; Touring	28981	35	4
Service Pack; Includes Valve	20036	35	4	Service Pack; Touring; Includes Valve	20036	35	4
Service Pack; Does Not Include Valve	20021	35	4	Service Pack; Touring; Does Not Include Valve	20021	35	4
<b>S2000</b>				<b>Pilot</b>			
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor	28981	35	4
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Service Pack; Includes Valve	20036	35	4
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack; Does Not Include Valve	20021	35	4
Service Pack	20032	35	4	<b>Ridgeline</b>			
<b>2008</b>				Sensor; RT	28982	35	4
<b>Accord</b>				Sensor; RTL, RTS, RTX	28981	35	4
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack; RT; Includes Valve	20035	35	4
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Service Pack; RTL, RTS, RTX; Includes Valve	20036	35	4
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack; Does Not Include Valve	20021	35	4
Sensor	20099	35	4	<b>2006</b>			
Service Pack	20032	35	4	<b>Odyssey</b>			
<b>Civic</b>				Sensor; Touring	28981	35	4
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack; Touring; Includes Valve	20036	35	4
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Service Pack; Touring; Does Not Include Valve	20021	35	4
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	<b>Pilot</b>			
Sensor	28720	35	4	Sensor	28981	35	4
Service Pack	20019	35	4	Service Pack; Includes Valve	20036	35	4
<b>CR-V</b>				Service Pack; Does Not Include Valve	20021	35	4
EZ-sensor - 315 MHz	◇33000	11.5	1.3	<b>Ridgeline</b>			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor; RT	28982	35	4
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; RTL, RTS	28981	35	4
Sensor	20099	35	4	Service Pack; RT; Includes Valve	20035	35	4
Service Pack	20032	35	4	Service Pack; RTL, RTS; Includes Valve	20036	35	4
<b>Element</b>				Service Pack; Does Not Include Valve	20021	35	4
Service Pack; Includes Valve	20036	35	4	<b>2005</b>			
Service Pack; Does Not Include Valve	20021	35	4	<b>Odyssey</b>			
<b>Fit</b>				Sensor; Touring	28981	35	4
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack; Touring; Includes Valve	20036	35	4
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Service Pack; Touring; Does Not Include Valve	20021	35	4
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	<b>Pilot</b>			
Sensor	20099	35	4	Sensor; EX	28981	35	4
Service Pack	20032	35	4	Sensor; LX; W/Long Stem Valve	28982	35	4
<b>Pilot</b>				Sensor; LX; W/Short Stem Valve	28981	35	4
Sensor	28981	35	4	Service Pack; EX; Includes Valve	20036	35	4
Service Pack; Includes Valve	20036	35	4				
Service Pack; Does Not Include Valve	20021	35	4				
<b>Ridgeline</b>							
Sensor; RT	28982	35	4				
Sensor; RTL, RTS, RTX	28981	35	4				
Service Pack; RT; Includes Valve	20035	35	4				
Service Pack; RTL, RTS; Includes Valve	20036	35	4				
Service Pack; Does Not Include Valve	20021	35	4				

◇ Programming Tool Required.



## Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
<b>► Honda - Continued</b>				<b>► Hyundai - Continued</b>			
<b>2005 - Continued</b>				<b>2013 - Continued</b>			
<b>Pilot - Continued</b>				<b>Tucson</b>			
Service Pack; LX; W/Long Stem Valve; Includes Valve .....	20035	35	4	Sensor .....	28849	31-40	3.5-4.5
Service Pack; LX; W/Short Stem Valve; Includes Valve .....	20036	35	4	Service Pack .....	20022	31-40	3.5-4.5
Service Pack; Does Not Include Valve .	20021	35	4	<b>Veloster</b>			
<b>► Hummer</b>				<b>2012</b>			
<b>2010-2009</b>				<b>Accent</b>			
<b>H2</b>				Sensor .....			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	20092	31-40	3.5-4.5	
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>Azera</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz .....			
Sensor .....	20153	11.5	1.3	◇33000			
Service Pack .....	20008	11.5	1.3	EZ-sensor Service Pack; Almm. Valve			
<b>H3; H3T</b>				34000			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	20008			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; Includes Transmitter Only .....			
Sensor .....	20131	62	7	20086			
Service Pack .....	20006	62	7	Service Pack; Includes Valve .....			
<b>2008</b>				20036			
<b>H2</b>				Service Pack; Does Not Include Valve .			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	20021			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>Elantra</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz .....			
Sensor .....	20153	11.5	1.3	◇33000			
Service Pack .....	20008	11.5	1.3	EZ-sensor Service Pack; Almm. Valve			
<b>H3</b>				34000			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	20008			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; W/Transmitter Only .....			
Sensor .....	20131	62	7	20086			
Service Pack .....	20006	62	7	Service Pack; Includes Valve .....			
<b>2007-2006</b>				20036			
<b>H3</b>				Service Pack; Does Not Include Valve .			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	20021			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>Equus</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor .....			
Sensor .....	20131	62	7	28849			
Service Pack .....	20006	62	7	Service Pack .....			
<b>► Hyundai</b>				20022			
<b>2013</b>				<b>Genesis</b>			
<b>Accent</b>				EZ-sensor - 315 MHz .....			
Sensor .....	20092	31-40	3.5-4.5	◇33000			
<b>Azera</b>				EZ-sensor Service Pack; Almm. Valve			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	34000			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	20008			
Sensor .....	20086	31-40	3.5-4.5	Sensor; Coupe .....			
Service Pack; Includes Valve .....	20036	31-40	3.5-4.5	20092			
Service Pack; Does Not Include Valve .	20021	31-40	3.5-4.5	Sensor; Sedan .....			
<b>Elantra</b>				28849			
Sensor; W/Transmitter Only .....	20086	31-40	3.5-4.5	Service Pack; Sedan .....			
Service Pack; Does Not Include Valve .	20021	31-40	3.5-4.5	20022			
Service Pack; Includes Valve .....	20036	31-40	3.5-4.5	<b>Santa Fe</b>			
<b>Sonata</b>				EZ-sensor - 315 MHz .....			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	◇33000			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	34000			
Sensor .....	20092	31-40	3.5-4.5	EZ-sensor Service Pack; Rubber Valve			
<b>► Hyundai</b>				20008			
<b>2011</b>				Sensor .....			
<b>Accent</b>				20092			
EZ-sensor - 315 MHz .....				◇33000			
EZ-sensor Service Pack; Almm. Valve				34000			
EZ-sensor Service Pack; Rubber Valve				20008			
Sensor .....				28849			
Service Pack .....				20022			
<b>Azera; Elantra</b>				EZ-sensor - 315 MHz .....			
EZ-sensor - 315 MHz .....				◇33000			
EZ-sensor Service Pack; Almm. Valve				34000			

◇ Programming Tool Required.

## Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
<b>► Hyundai - Continued</b>				<b>► Hyundai - Continued</b>			
<b>2011 - Continued</b>				<b>2010 - Continued</b>			
<b>Azera; Elantra - Continued</b>				<b>Tucson</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor .....	28849	31-40	3.5-4.5
Sensor; Includes Transmitter Only .....	20086	31-40	3.5-4.5	Service Pack .....	20022	31-40	3.5-4.5
Service Pack; Includes Valve .....	20036	31-40	3.5-4.5	<b>Veracruz</b>			
Service Pack; Does Not Include Valve .	20021	31-40	3.5-4.5	Sensor; Includes Transmitter Only .....	20086	31-40	3.5-4.5
<b>Equus</b>				Service Pack; Includes Valve .....	20036	31-40	3.5-4.5
Sensor .....	28849	31-40	3.5-4.5	Service Pack; Does Not Include Valve .	20021	31-40	3.5-4.5
Service Pack .....	20022	31-40	3.5-4.5	<b>2009</b>			
<b>Genesis</b>				<b>Accent</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor; Coupe .....	20092	31-40	3.5-4.5	Sensor .....	28849	31-40	3.5-4.5
Sensor; Sedan .....	28849	31-40	3.5-4.5	Service Pack .....	20022	31-40	3.5-4.5
Service Pack; Sedan .....	20022	31-40	3.5-4.5	<b>Azera; Elantra</b>			
<b>Santa Fe</b>				EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; Includes Transmitter Only .....	20086	31-40	3.5-4.5
<b>Sonata</b>				Service Pack; Includes Valve .....	20036	31-40	3.5-4.5
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Service Pack; Does Not Include Valve .	20021	31-40	3.5-4.5
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>Entourage</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; Includes Transmitter Only .....	20085	31-40	3.5-4.5
Sensor .....	20092	31-40	3.5-4.5	Service Pack; Includes Valve .....	20036	31-40	3.5-4.5
<b>Tucson</b>				Service Pack; Does Not Include Valve .	20021	31-40	3.5-4.5
Sensor .....	28849	31-40	3.5-4.5	<b>Genesis</b>			
Service Pack .....	20022	31-40	3.5-4.5	Service Pack .....	20022	31-40	3.5-4.5
<b>Veracruz</b>				<b>Santa Fe</b>			
Sensor; Includes Transmitter Only .....	20086	31-40	3.5-4.5	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Service Pack; Includes Valve .....	20036	31-40	3.5-4.5	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Service Pack; Does Not Include Valve .	20021	31-40	3.5-4.5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
<b>2010</b>				Sensor; Includes Transmitter Only .....	20086	31-40	3.5-4.5
<b>Accent</b>				Service Pack; Includes Valve .....	20036	31-40	3.5-4.5
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Service Pack; Does Not Include Valve .	20021	31-40	3.5-4.5
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>Sonata</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Sensor .....	28849	31-40	3.5-4.5	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Service Pack .....	20022	31-40	3.5-4.5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
<b>Azera; Elantra</b>				Sensor .....	28849	31-40	3.5-4.5
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Service Pack .....	20022	31-40	3.5-4.5
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>Tucson</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor .....	28983	31-40	3.5-4.5
Sensor; Includes Transmitter Only .....	20086	31-40	3.5-4.5	Service Pack; Includes Valve .....	20036	31-40	3.5-4.5
Service Pack; Includes Valve .....	20036	31-40	3.5-4.5	Service Pack; Does Not Include Valve .	20021	31-40	3.5-4.5
Service Pack; Does Not Include Valve .	20021	31-40	3.5-4.5	<b>Veracruz</b>			
<b>Genesis</b>				Sensor; Includes Transmitter Only .....	20086	31-40	3.5-4.5
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Service Pack; Includes Valve .....	20036	31-40	3.5-4.5
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Service Pack; Does Not Include Valve .	20021	31-40	3.5-4.5
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	<b>2008</b>			
Sensor; Coupe .....	20092	31-40	3.5-4.5	<b>Accent</b>			
<b>Santa Fe</b>				EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor .....	28849	31-40	3.5-4.5
Sensor; Includes Transmitter Only .....	20086	31-40	3.5-4.5	Service Pack .....	20022	31-40	3.5-4.5
Service Pack; Includes Valve .....	20036	31-40	3.5-4.5	<b>Azera; Elantra</b>			
Service Pack; Does Not Include Valve .	20021	31-40	3.5-4.5	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
<b>Sonata</b>				EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor; Includes Transmitter Only .....	20086	31-40	3.5-4.5
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack; Includes Valve .....	20036	31-40	3.5-4.5
Sensor .....	28849	31-40	3.5-4.5	Service Pack; Does Not Include Valve .	20021	31-40	3.5-4.5
Service Pack .....	20022	31-40	3.5-4.5				

◇ Programming Tool Required.

## Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
<b>► Hyundai - Continued</b>				<b>► Infiniti - Continued</b>			
<b>2008 - Continued</b>				<b>2010-2009 - Continued</b>			
<b>Entourage</b>				<b>EX35; FX35; FX50; G37 - Continued</b>			
Sensor; Includes Transmitter Only .....	20085	31-40	3.5-4.5	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Service Pack; Includes Valve .....	20036	31-40	3.5-4.5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Service Pack; Does Not Include Valve .	20021	31-40	3.5-4.5	Sensor .....	28210	66	7.5
<b>Santa Fe</b>				Service Pack .....			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3		20014	66	7.5
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>M35; M45</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Sensor; Includes Transmitter Only .....	20085	31-40	3.5-4.5	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Service Pack; Includes Valve .....	20036	31-40	3.5-4.5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Service Pack; Does Not Include Valve .	20021	31-40	3.5-4.5	Sensor .....	28204	66	7.5
<b>Sonata</b>				Service Pack .....			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3		20014	66	7.5
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>QX56</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Sensor .....	28983	31-40	3.5-4.5	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Service Pack; Includes Valve .....	20036	31-40	3.5-4.5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Service Pack; Does Not Include Valve .	20021	31-40	3.5-4.5	Sensor .....	28204	49	5.5
<b>Tiburon; Tucson</b>				Service Pack .....			
Sensor .....	28983	31-40	3.5-4.5		20014	49	5.5
Service Pack; Includes Valve .....	20036	31-40	3.5-4.5	<b>2008</b>			
Service Pack; Does Not Include Valve .	20021	31-40	3.5-4.5	<b>EX35</b>			
<b>Veracruz</b>				EZ-sensor - 315 MHz .....			
Sensor; Includes Transmitter Only .....	20085	31-40	3.5-4.5		◇33000	11.5	1.3
Service Pack; Includes Valve .....	20036	31-40	3.5-4.5	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Service Pack; Does Not Include Valve .	20021	31-40	3.5-4.5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
<b>2007</b>				Sensor .....			
<b>Azera</b>				Service Pack .....			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3		20014	66	7.5
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>FX35; FX45</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Sensor; Includes Transmitter Only .....	20086	31-40	3.5-4.5	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Service Pack; Includes Valve .....	20036	31-40	3.5-4.5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Service Pack; Does Not Include Valve .	20021	31-40	3.5-4.5	Sensor .....	28204	66	7.5
<b>Elantra</b>				Service Pack .....			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3		20014	66	7.5
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>G35; G37</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
<b>Entourage; Santa Fe</b>				EZ-sensor Service Pack; Almm. Valve			
Sensor; Includes Transmitter Only .....	20085	31-40	3.5-4.5		34000	62	7
Service Pack; Includes Valve .....	20036	31-40	3.5-4.5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Service Pack; Does Not Include Valve .	20021	31-40	3.5-4.5	Sensor .....	28210	66	7.5
<b>Sonata; Tiburon; Tucson</b>				Service Pack .....			
Sensor .....	28983	31-40	3.5-4.5		20014	66	7.5
Service Pack; Includes Valve .....	20036	31-40	3.5-4.5	<b>M35; M45</b>			
Service Pack; Does Not Include Valve .	20021	31-40	3.5-4.5	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
<b>Veracruz</b>				EZ-sensor Service Pack; Almm. Valve			
Sensor; Includes Transmitter Only .....	20085	31-40	3.5-4.5		34000	62	7
Service Pack; Includes Valve .....	20036	31-40	3.5-4.5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Service Pack; Does Not Include Valve .	20021	31-40	3.5-4.5	Sensor .....	28204	66	7.5
<b>2006</b>				Service Pack .....			
<b>Azera</b>							
Sensor; Includes Transmitter Only .....	20086	31-40	3.5-4.5		20014	66	7.5
Service Pack; Includes Valve .....	20036	31-40	3.5-4.5	<b>QX56</b>			
Service Pack; Does Not Include Valve .	20021	31-40	3.5-4.5	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
<b>Tucson</b>				EZ-sensor Service Pack; Almm. Valve			
Sensor .....	28983	31-40	3.5-4.5		34000	62	7
Service Pack; Includes Valve .....	20036	31-40	3.5-4.5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Service Pack; Does Not Include Valve .	20021	31-40	3.5-4.5	Sensor .....	28204	49	5.5
<b>► Infiniti</b>				Service Pack .....			
<b>2010-2009</b>							
<b>EX35; FX35; FX50; G37</b>				<b>2007</b>			
EZ-sensor - 315 MHz .....	33000	11.5	1.3	<b>FX35; FX45</b>			
				EZ-sensor - 315 MHz .....			
				◇33000			
				11.5			
				1.3			
				EZ-sensor Service Pack; Almm. Valve			
				34000			
				62			
				7			
				EZ-sensor Service Pack; Rubber Valve			
				20008			
				11.5			
				1.3			
				Sensor; Jul. & Newer .....			
				28204			
				66			
				7.5			
				Sensor; Jun. & Older .....			
				20064			
				66			
				7.5			
				Service Pack; Jul. & Newer .....			
				20014			
				66			
				7.5			
				Service Pack; Jun. & Older .....			
				20007			
				66			
				7.5			
				<b>G35</b>			
				EZ-sensor - 315 MHz .....			
				◇33000			
				11.5			
				1.3			
				EZ-sensor Service Pack; Almm. Valve			
				34000			
				62			
				7			
				EZ-sensor Service Pack; Rubber Valve			
				20008			
				11.5			
				1.3			
				Sensor; Coupe .....			
				28204			
				66			
				7.5			
				Sensor; Sedan .....			
				28210			
				66			
				7.5			
				Service Pack .....			
				20014			
				66			
				7.5			

Programming Tool Required. ◇

## Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
<b>► Infiniti - Continued</b>				<b>► Infiniti - Continued</b>			
<b>2007 - Continued</b>				<b>2005 - Continued</b>			
<b>M35; M45</b>				<b>Q45 - Continued</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor .....	20064	66	7.5
Sensor .....	20064	66	7.5	Service Pack .....	20007	66	7.5
Service Pack .....	20007	66	7.5				
<b>QX56</b>				<b>QX56</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor; Apr. 1 & Newer .....	28204	49	5.5	Sensor; W/Alloy Wheels .....	20161	49	5.5
Sensor; Mar. & Older .....	20161	49	5.5	Sensor; W/Steel Wheels .....	20069	49	5.5
Service Pack; Apr. 1 & Newer .....	20014	49	5.5	Service Pack; W/Alloy Wheels .....	20007	49	5.5
Service Pack; Mar. & Older .....	20007	49	5.5	Service Pack; W/Steel Wheels .....	20005	49	5.5
<b>2006</b>				<b>2004</b>			
<b>FX35; FX45</b>				<b>FX35; FX45</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor .....	20064	66	7.5	Sensor .....	20064	66	7.5
Service Pack .....	20007	66	7.5	Service Pack .....	20007	66	7.5
<b>G35</b>				<b>G35</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor .....	20064	61-72	6.8-8.2	Sensor .....	20064	61-72	6.8-8.2
Service Pack .....	20007	61-72	6.8-8.2	Service Pack .....	20007	61-72	6.8-8.2
<b>M35; M45</b>				<b>M45; Q45</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor .....	20064	66	7.5	Sensor .....	20064	66	7.5
Service Pack .....	20007	66	7.5	Service Pack .....	20007	66	7.5
<b>Q45</b>				<b>QX56</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor; Aug. & Newer .....	28204	66	7.5	Sensor .....	20069	49	5.5
Sensor; Jul. & Older .....	20064	66	7.5	Service Pack .....	20005	49	5.5
Service Pack; Aug. & Newer .....	20014	66	7.5				
Service Pack; Jul. & Older .....	20007	66	7.5				
<b>QX56</b>				<b>2003</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	<b>FX35; FX45</b>			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor; W/Alloy Wheels .....	20161	49	5.5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor; W/Steel Wheels .....	20069	49	5.5	Sensor .....	20064	66	7.5
Service Pack; W/Alloy Wheels .....	20007	49	5.5	Service Pack .....	20007	66	7.5
Service Pack; W/Steel Wheels .....	20005	49	5.5				
<b>2005</b>				<b>G35</b>			
<b>FX35; FX45</b>				EZ-sensor - 315 MHz .....			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor .....	20064	66	7.5	Sensor; Jun. & Newer .....	20064	61-72	6.8-8.2
Service Pack .....	20007	66	7.5	Service Pack; Jun. & Newer .....	20007	61-72	6.8-8.2
<b>G35</b>				<b>M45; Q45; QX4</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor .....	20064	61-72	6.8-8.2	Sensor .....	20064	66	7.5
Service Pack .....	20007	61-72	6.8-8.2	Service Pack .....	20007	66	7.5
<b>Q45</b>				<b>► Isuzu</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	<b>2008-2007</b>			
				<b>Ascender</b>			
				Sensor .....	20116	62	7
				Service Pack .....	20004	62	7

◇ Programming Tool Required.



## Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
<b>► Isuzu - Continued</b>				<b>► Jeep - Continued</b>			
<b>2008-2007 - Continued</b>				<b>2013 - Continued</b>			
<b>I-290; I-370</b>				<b>Compass - Continued</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor .....	28308	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack; Rubber Valve .....	20018	11.5	1.3
Sensor .....	20131	62	7	<b>Wrangler</b>			
Service Pack .....	20006	62	7	Sensor .....	20398	11.5	1.3
<b>2006</b>				Service Pack .....	20018	11.5	1.3
<b>Ascender</b>				<b>2012</b>			
Sensor .....	20116	62	7	<b>Compass</b>			
Service Pack .....	20004	62	7	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
<b>2004</b>				EZ-sensor Service Pack; Almm. Valve	34000	62	7
<b>Rodeo</b>				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor - 433 MHz .....	◇33100	11.5	1.3	Sensor .....	28308	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Service Pack; Rubber Valve .....	20018	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	<b>Grand Cherokee</b>			
Sensor .....	●20028	62	7	Sensor .....	20398	11.5	1.3
Service Pack .....	20003	62	7	Service Pack .....	20018	11.5	1.3
<b>► Jaguar</b>				<b>Liberty</b>			
<b>2012</b>				EZ-sensor - 315 MHz .....	33000	11.5	1.3
<b>XF; XJ; XK</b>				EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor; W/315 MHz Sensor .....	20090	71	8	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor; W/433 MHz Sensor .....	20091	71	8	Sensor .....	20066	58	6.5
Service Pack .....	20030	71	8	or 28308	11.5	1.3	
<b>2011-2010</b>				Service Pack; Rubber Valve .....	20018	11.5	1.3
<b>XF; XFR; XJ; XK; XKR</b>				Service Pack; Includes Stem Only .....	20020	58	6.5
Sensor; W/315 MHz Sensor .....	20090	71	8	Service Pack; Does Not Include Stem ..	20013	58	6.5
Sensor; W/433 MHz Sensor .....	20091	71	8	<b>Patriot</b>			
Service Pack .....	20030	71	8	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
<b>2009</b>				EZ-sensor Service Pack; Almm. Valve	34000	62	7
<b>Super V8; Vanden Plas; XF; XJ8; XJR; XK; XKR</b>				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor; W/315 MHz Sensor .....	20090	71	8	Sensor .....	20066	58	6.5
Sensor; W/433 MHz Sensor .....	20091	71	8	or 28308	11.5	1.3	
Service Pack .....	20030	71	8	Service Pack; Rubber Valve .....	20018	11.5	1.3
<b>2008</b>				Service Pack; W/Schrader Sensor; Includes Stem Only .....	20020	58	6.5
<b>S-Type; Super V8; Vanden Plas; X-Type; XJ8; XJR; XK; XKR</b>				Service Pack; W/Schrader Sensor; Does Not Include Stem .....	20013	58	6.5
Sensor; W/315 MHz Sensor .....	20090	71	8	<b>Wrangler</b>			
Sensor; W/433 MHz Sensor .....	20091	71	8	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Service Pack .....	20030	71	8	EZ-sensor Service Pack; Almm. Valve	34000	62	7
<b>2007</b>				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
<b>Super V8; Vanden Plas; XJ8; XJR; XK; XKR</b>				Sensor .....	20066	58	6.5
Sensor; W/315 MHz Sensor .....	20090	71	8	or 28308	11.5	1.3	
Sensor; W/433 MHz Sensor .....	20091	71	8	Service Pack .....	20018	11.5	1.3
Service Pack .....	20030	71	8	<b>2011</b>			
<b>2006-2005</b>				<b>Compass</b>			
<b>Super V8; Vanden Plas; XJ8; XJR</b>				EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Sensor; W/315 MHz Sensor .....	20090	71	8	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor; W/433 MHz Sensor .....	20091	71	8	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Service Pack .....	20030	71	8	Sensor .....	20066	58	6.5
<b>2004</b>				or 28308	11.5	1.3	
<b>Vanden Plas; XJ8; XJR</b>				Service Pack; Rubber Valve .....	20018	11.5	1.3
Sensor; W/315 MHz Sensor .....	20090	71	8	Service Pack; W/Schrader Sensor; Includes Stem Only .....	20020	58	6.5
Sensor; W/433 MHz Sensor .....	20091	71	8	Service Pack; W/Schrader Sensor; Does Not Include Stem .....	20013	58	6.5
Service Pack .....	20030	71	8	<b>Grand Cherokee</b>			
<b>► Jeep</b>				Sensor .....	20398	11.5	1.3
<b>2013</b>				Service Pack .....	20018	11.5	1.3
<b>Compass</b>				<b>Liberty</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor .....	20066	58	6.5	Sensor .....	20066	58	6.5
or 28308	11.5	1.3	<b>2011</b>				
Service Pack; Rubber Valve .....	20018	11.5	<b>Compass</b>				
Service Pack; W/Schrader Sensor; Includes Stem Only .....	20020	58	EZ-sensor - 315 MHz .....				
Service Pack; W/Schrader Sensor; Does Not Include Stem .....	20013	58	◇33000				
<b>Grand Cherokee</b>				11.5			
Sensor .....	20398	11.5	1.3				
Service Pack .....	20018	11.5	1.3				

◇ Programming Tool Required.  
● Magnet Required to Activate Sensor.



## Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
<b>► Jeep - Continued</b>				<b>► Jeep - Continued</b>			
<b>2011 - Continued</b>				<b>2010 - Continued</b>			
<b>Liberty - Continued</b>				<b>Wrangler</b>			
	or 28308	11.5	1.3	Sensor .....	28155	58	6.5
Service Pack; Rubber Valve .....	20018	11.5	1.3	or 28434	11.5	1.3	
Service Pack; Includes Stem Only .....	20020	58	6.5	Service Pack; Includes Stem Only .....	20020	58	6.5
Service Pack; Does Not Include Stem ..	20013	58	6.5	Service Pack; Does Not Include Stem ..	20013	58	6.5
<b>Patriot; Wrangler</b>				<b>2009</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	<b>Commander</b>			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor - 433 MHz .....	◇33100	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor .....	20066	58	6.5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
or 28308	11.5	1.3		Sensor .....	28155	58	6.5
Service Pack; W/Schrader Sensor;				or 28434	11.5	1.3	
Includes Stem Only .....	20020	58	6.5	Service Pack; Rubber Valve .....	20018	11.5	1.3
Service Pack; W/Schrader Sensor; Does				Service Pack; Includes Stem Only .....	20020	58	6.5
Not Include Stem .....	20013	58	6.5	Service Pack; Does Not Include Stem ..	20013	58	6.5
<b>2010</b>				<b>Compass</b>			
<b>Commander</b>				EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor - 433 MHz .....	◇33100	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor .....	20066	58	6.5
Sensor .....	28155	58	6.5	or 28308	11.5	1.3	
or 28434	11.5	1.3		Service Pack; Rubber Valve .....	20018	11.5	1.3
Service Pack; Rubber Valve .....	20018	11.5	1.3	Service Pack; W/Schrader Sensor;			
Service Pack; Includes Stem Only .....	20020	58	6.5	Includes Stem Only .....	20020	58	6.5
Service Pack; Does Not Include Stem ..	20013	58	6.5	Service Pack; W/Schrader Sensor; Does			
<b>Compass</b>				Not Include Stem .....	20013	58	6.5
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Service Pack; W/Siemens Sensor .....	20030	71	8
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>Grand Cherokee</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 433 MHz .....	◇33100	11.5	1.3
Sensor .....	20066	58	6.5	EZ-sensor Service Pack; Almm. Valve	34000	62	7
or 28308	11.5	1.3		EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Service Pack; Rubber Valve .....	20018	11.5	1.3	Sensor .....	28155	58	6.5
Service Pack; W/Schrader Sensor;				or 28434	11.5	1.3	
Includes Stem Only .....	20020	58	6.5	Service Pack; Rubber Valve .....	20018	11.5	1.3
Service Pack; W/Schrader Sensor; Does				Service Pack; Includes Stem Only .....	20020	58	6.5
Not Include Stem .....	20013	58	6.5	Service Pack; Does Not Include Stem ..	20013	58	6.5
Service Pack; W/Siemens Sensor .....	20030	71	8	<b>Liberty</b>			
<b>Grand Cherokee</b>				EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor - 433 MHz .....	◇33100	11.5	1.3	EZ-sensor - 433 MHz .....	◇33100	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor .....	28155	58	6.5	Sensor; Sport .....	20066	58	6.5
or 28434	11.5	1.3		or 28308	11.5	1.3	
Service Pack; Rubber Valve .....	20018	11.5	1.3	Sensor; Exc. Sport .....	28155	58	6.5
Service Pack; Includes Stem Only .....	20020	58	6.5	or 28434	11.5	1.3	
Service Pack; Does Not Include Stem ..	20013	58	6.5	Service Pack; Includes Stem Only .....	20020	58	6.5
<b>Liberty</b>				Service Pack; Does Not Include Stem ..	20013	58	6.5
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	<b>Patriot</b>			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor .....	20066	58	6.5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
or 28308	11.5	1.3		Sensor .....	20066	58	6.5
Service Pack; Rubber Valve .....	20018	11.5	1.3	or 28308	11.5	1.3	
Service Pack; Includes Stem Only .....	20020	58	6.5	Service Pack; W/Schrader Sensor;			
Service Pack; Does Not Include Stem ..	20013	58	6.5	Includes Stem Only .....	20020	58	6.5
<b>Patriot</b>				Service Pack; W/Schrader Sensor; Does			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Not Include Stem .....	20013	58	6.5
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Service Pack; W/Siemens Sensor .....	20030	71	8
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	<b>Wrangler</b>			
Sensor .....	20066	58	6.5	Sensor .....	28155	58	6.5
or 28308	11.5	1.3		or 28434	11.5	1.3	
Service Pack; W/Schrader Sensor;				Service Pack; Includes Stem Only .....	20020	58	6.5
Includes Stem Only .....	20020	58	6.5	Service Pack; Does Not Include Stem ..	20013	58	6.5
Service Pack; W/Schrader Sensor; Does							
Not Include Stem .....	20013	58	6.5				
Service Pack; W/Siemens Sensor .....	20030	71	8				

◇ Programming Tool Required.

## Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
<b>► Jeep - Continued</b>				<b>► Jeep - Continued</b>			
<b>2008</b>				<b>2006</b>			
<b>Commander</b>				<b>Commander; Grand Cherokee</b>			
EZ-sensor - 433 MHz .....	◇33100	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor .....	28155	58	6.5	Sensor .....	20066	58	6.5
or	28434	11.5	1.3	or	28308	11.5	1.3
Service Pack; Rubber Valve .....	20018	11.5	1.3	Service Pack; Rubber Valve .....	20018	11.5	1.3
Service Pack; Includes Stem Only .....	20020	58	6.5	Service Pack; W/Schrader Sensor; Includes Stem Only .....	20020	58	6.5
Service Pack; Does Not Include Stem ..	20013	58	6.5	Service Pack; W/Schrader Sensor; Does Not Include Stem .....	20013	58	6.5
<b>Compass</b>				<b>Liberty</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor .....	20066	58	6.5	Sensor .....	20066	58	6.5
or	28308	11.5	1.3	or	28308	11.5	1.3
Service Pack; Rubber Valve .....	20018	11.5	1.3	Service Pack; W/Schrader Sensor; Includes Stem Only .....	20020	58	6.5
Service Pack; W/Schrader Sensor; Includes Stem Only .....	20020	58	6.5	Service Pack; W/Schrader Sensor; Does Not Include Stem .....	20013	58	6.5
Service Pack; W/Schrader Sensor; Does Not Include Stem .....	20013	58	6.5	Service Pack; W/Schrader Sensor; Does Not Include Stem .....	20013	58	6.5
Service Pack; W/Siemens Sensor .....	20030	71	8	Service Pack; W/Siemens Sensor .....	20030	71	8
<b>Grand Cherokee</b>				<b>2005</b>			
EZ-sensor - 433 MHz .....	◇33100	11.5	1.3	<b>Grand Cherokee</b>			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor .....	28155	58	6.5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
or	28434	11.5	1.3	Sensor .....	20066	58	6.5
Service Pack; Rubber Valve .....	20018	11.5	1.3	or	28308	11.5	1.3
Service Pack; Includes Stem Only .....	20020	58	6.5	Service Pack; Rubber Valve .....	20018	11.5	1.3
Service Pack; Does Not Include Stem ..	20013	58	6.5	Service Pack; W/Schrader Sensor; Includes Stem Only .....	20020	58	6.5
<b>Liberty; Patriot; Wrangler</b>				<b>Liberty</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor .....	20066	58	6.5	Sensor .....	20066	58	6.5
or	28308	11.5	1.3	or	28308	11.5	1.3
Service Pack; W/Schrader Sensor; Includes Stem Only .....	20020	58	6.5	Service Pack; W/Schrader Sensor; Includes Stem Only .....	20020	58	6.5
Service Pack; W/Schrader Sensor; Does Not Include Stem .....	20013	58	6.5	Service Pack; W/Schrader Sensor; Does Not Include Stem .....	20013	58	6.5
Service Pack; W/Siemens Sensor .....	20030	71	8	Service Pack; W/Siemens Sensor .....	20030	71	8
<b>2007</b>				<b>2004-2002</b>			
<b>Commander; Compass; Grand Cherokee</b>				<b>Grand Cherokee; Liberty</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor - 433 MHz .....	◇33100	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor .....	20066	58	6.5	Sensor .....	●20028	64	7
or	28308	11.5	1.3	Service Pack .....	20003	64	7
Service Pack; Rubber Valve .....	20018	11.5	1.3	<b>► Kia</b>			
Service Pack; W/Schrader Sensor; Includes Stem Only .....	20020	58	6.5	<b>2013</b>			
Service Pack; W/Schrader Sensor; Does Not Include Stem .....	20013	58	6.5	<b>Forte; Optima</b>			
Service Pack; W/Siemens Sensor .....	20030	71	8	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
<b>Liberty; Patriot; Wrangler</b>				<b>2013</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	<b>Forte; Optima</b>			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor .....	20066	58	6.5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
or	28308	11.5	1.3	Sensor .....	20092	31-40	3.5-4.5
Service Pack; W/Schrader Sensor; Includes Stem Only .....	20020	58	6.5	<b>Rio</b>			
Service Pack; W/Schrader Sensor; Does Not Include Stem .....	20013	58	6.5	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Service Pack; W/Siemens Sensor .....	20030	71	8	EZ-sensor Service Pack; Almm. Valve	34000	62	7
<b>2007</b>				<b>2013</b>			
<b>Commander; Compass; Grand Cherokee</b>				<b>Forte; Optima</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor .....	20066	58	6.5	Sensor .....	20092	31-40	3.5-4.5
or	28308	11.5	1.3	<b>Rio</b>			
Service Pack; Rubber Valve .....	20018	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Service Pack; W/Schrader Sensor; Includes Stem Only .....	20020	58	6.5	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Service Pack; W/Schrader Sensor; Does Not Include Stem .....	20013	58	6.5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Service Pack; W/Siemens Sensor .....	20030	71	8	Sensor .....	20092	31-40	3.5-4.5

◇ Programming Tool Required.  
● Magnet Required to Activate Sensor.

## Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
<b>► Kia - Continued</b>				<b>► Kia - Continued</b>			
<b>2013 - Continued</b>				<b>2011 - Continued</b>			
<b>Rio - Continued</b>				<b>Rondo; Sedona - Continued</b>			
Sensor .....	20086	31-40	3.5-4.5	Service Pack; Includes Valve .....	20036	31-40	3.5-4.5
Service Pack; Includes Valve .....	20036	31-40	3.5-4.5	Service Pack; Does Not Include Valve .	20021	31-40	3.5-4.5
Service Pack; Does Not Include Valve .	20021	31-40	3.5-4.5	<b>Sorento; Soul</b>			
<b>Sorento</b>				EZ-sensor - 315 MHz .....			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor .....	20092	31-40	3.5-4.5
Sensor .....	20092	31-40	3.5-4.5	<b>Sportage</b>			
<b>2012</b>				EZ-sensor - 315 MHz .....			
<b>Forte; Optima</b>				EZ-sensor Service Pack; Almm. Valve			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor .....	28849	31-40	3.5-4.5
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack .....	20022	31-40	3.5-4.5
Sensor .....	20092	31-40	3.5-4.5	<b>2010</b>			
<b>Rio</b>				<b>Borrego</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor .....	20092	31-40	3.5-4.5	Sensor .....	28849	31-40	3.5-4.5
Service Pack; Includes Valve .....	20036	31-40	3.5-4.5	Service Pack .....	20022	31-40	3.5-4.5
Service Pack; Does Not Include Valve .	20021	31-40	3.5-4.5	<b>Forte</b>			
<b>Sedona</b>				EZ-sensor - 315 MHz .....			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor .....	20092	31-40	3.5-4.5
Sensor; Includes Transmitter Only .....	20086	31-40	3.5-4.5	<b>Magentis; Optima</b>			
Service Pack; Includes Valve .....	20036	31-40	3.5-4.5	Sensor; Includes Transmitter Only .....			
Service Pack; Does Not Include Valve .	20021	31-40	3.5-4.5	Service Pack; Includes Valve .....			
<b>Sorento; Soul</b>				Service Pack; Does Not Include Valve .			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	20021 31-40 3.5-4.5			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>Rio</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz .....			
Sensor .....	20092	31-40	3.5-4.5	EZ-sensor Service Pack; Almm. Valve			
<b>Sportage</b>				EZ-sensor Service Pack; Rubber Valve			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	20008 11.5 1.3			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor .....			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	28849 35-35.7 3.5-4.5			
Sensor .....	28849	31-40	3.5-4.5	Service Pack .....			
Service Pack .....	20022	31-40	3.5-4.5	20022 35-35.7 3.5-4.5			
<b>2011</b>				<b>Rondo; Sedona</b>			
<b>Borrego</b>				EZ-sensor - 315 MHz .....			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Almm. Valve			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	20008 11.5 1.3			
Sensor .....	28849	35-35.7	3.5-4.5	Sensor; Includes Transmitter Only .....			
Service Pack .....	20022	35-35.7	3.5-4.5	20086 31-40 3.5-4.5			
<b>Forte; Optima</b>				Service Pack; Includes Valve .....			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	20036 31-40 3.5-4.5			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Service Pack; Does Not Include Valve .			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	20021 31-40 3.5-4.5			
Sensor .....	20092	31-40	3.5-4.5	<b>Soul</b>			
<b>Rio</b>				EZ-sensor - 315 MHz .....			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Almm. Valve			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	20008 11.5 1.3			
Sensor .....	28849	35-35.7	3.5-4.5	Sensor .....			
Service Pack .....	20022	35-35.7	3.5-4.5	28849 35-35.7 3.5-4.5			
<b>Rondo; Sedona</b>				Service Pack .....			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	20022 31-40 3.5-4.5			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>2009</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	<b>Amanti</b>			
Sensor; Includes Transmitter Only .....	20086	31-40	3.5-4.5	Sensor .....			
<b>Sorento; Soul</b>				Service Pack; Includes Valve .....			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	20036 35-35.7 3.5-4.5			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Service Pack; Does Not Include Valve .			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	20021 35-35.7 3.5-4.5			
Sensor; Includes Transmitter Only .....	20086	31-40	3.5-4.5	<b>Borrego</b>			
<b>Rondo; Sedona</b>				EZ-sensor - 315 MHz .....			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Almm. Valve			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	20008 11.5 1.3			
Sensor; Includes Transmitter Only .....	20086	31-40	3.5-4.5	Sensor .....			
<b>Sorento; Soul</b>				28849 31-40 3.5-4.5			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Service Pack .....			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	20022 31-40 3.5-4.5			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	<b>2009</b>			
Sensor .....	20092	31-40	3.5-4.5	<b>Amanti</b>			
<b>Sportage</b>				Sensor .....			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Service Pack; Includes Valve .....			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	20036 35-35.7 3.5-4.5			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack; Does Not Include Valve .			
Sensor .....	28849	31-40	3.5-4.5	20021 35-35.7 3.5-4.5			
Service Pack .....	20022	31-40	3.5-4.5	<b>Borrego</b>			
<b>2009</b>				EZ-sensor - 315 MHz .....			
<b>Amanti</b>				EZ-sensor Service Pack; Almm. Valve			
Sensor .....				EZ-sensor Service Pack; Rubber Valve			
Service Pack; Includes Valve .....				20008 11.5 1.3			
Service Pack; Does Not Include Valve .				20021 35-35.7 3.5-4.5			
<b>Borrego</b>				<b>2009</b>			
EZ-sensor - 315 MHz .....				EZ-sensor - 315 MHz .....			
EZ-sensor Service Pack; Almm. Valve				EZ-sensor Service Pack; Almm. Valve			
EZ-sensor Service Pack; Rubber Valve				EZ-sensor Service Pack; Rubber Valve			
20008 11.5 1.3				20008 11.5 1.3			
20008 11.5 1.3				Sensor .....			
20086 31-40 3.5-4.5				28849 31-40 3.5-4.5			
20086 31-40 3.5-4.5				Service Pack .....			
20086 31-40 3.5-4.5				20022 31-40 3.5-4.5			

◇ Programming Tool Required.

## Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
<b>► Kia - Continued</b>				<b>► Kia - Continued</b>			
<b>2009 - Continued</b>				<b>2008 - Continued</b>			
<b>Borrego - Continued</b>				<b>Sorento</b>			
Sensor .....	28849	31-40	3.5-4.5	Sensor .....	28983	35-35.7	3.5-4.5
Service Pack .....	20022	31-40	3.5-4.5	Service Pack; Includes Valve .....	20036	35-35.7	3.5-4.5
<b>Magentis; Optima</b>				Service Pack; Does Not Include Valve .			
Sensor; Includes Transmitter Only .....	20086	31-40	3.5-4.5	20021	35-35.7	3.5-4.5	
Service Pack; Includes Valve .....	20036	31-40	3.5-4.5	<b>Spectra</b>			
Service Pack; Does Not Include Valve .	20021	31-40	3.5-4.5	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
<b>Rio</b>				EZ-sensor Service Pack; Almm. Valve			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	20008	11.5	1.3	
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor .....	28849	35-35.7	3.5-4.5
Sensor .....	28849	35-35.7	3.5-4.5	Service Pack .....	20022	35-35.7	3.5-4.5
Service Pack .....	20022	35-35.7	3.5-4.5	<b>Sportage</b>			
<b>Rondo; Sedona</b>				Sensor .....			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	28983	35-35.7	3.5-4.5	
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Service Pack; Includes Valve .....	20036	35-35.7	3.5-4.5
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack; Does Not Include Valve .	20021	35-35.7	3.5-4.5
Sensor; Includes Transmitter Only .....	20086	31-40	3.5-4.5	<b>2007</b>			
Service Pack; Includes Valve .....	20036	31-40	3.5-4.5	<b>Amanti</b>			
Service Pack; Does Not Include Valve .	20021	31-40	3.5-4.5	Sensor .....			
<b>Sorento</b>				28983			
Sensor .....	28983	35-35.7	3.5-4.5	Service Pack; Includes Valve .....			
Service Pack; Includes Valve .....	20036	35-35.7	3.5-4.5	20036			
Service Pack; Does Not Include Valve .	20021	35-35.7	3.5-4.5	Service Pack; Does Not Include Valve .			
<b>Spectra</b>				20021			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	<b>Optima</b>			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor; Includes Transmitter Only .....			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	20086			
Sensor .....	28849	35-35.7	3.5-4.5	Service Pack; Includes Valve .....			
Service Pack .....	20022	35-35.7	3.5-4.5	20036			
<b>Sportage</b>				Service Pack; Does Not Include Valve .			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	20021			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>Rio</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz .....			
Sensor .....	28849	31-40	3.5-4.5	◇33000			
Service Pack .....	20022	31-40	3.5-4.5	EZ-sensor Service Pack; Almm. Valve			
<b>2008</b>				34000			
<b>Amanti</b>				20008			
Sensor .....				11.5			
28983				1.3			
Service Pack; Includes Valve .....				EZ-sensor Service Pack; Rubber Valve			
20036				20008			
Service Pack; Does Not Include Valve .				Sensor .....			
20021				28849			
<b>Magentis; Optima</b>				Service Pack .....			
Sensor; Includes Transmitter Only .....				20022			
20086				35-35.7			
Service Pack; Includes Valve .....				3.5-4.5			
20036				3.5-4.5			
Service Pack; Does Not Include Valve .				3.5-4.5			
20021				3.5-4.5			
<b>Rio</b>				<b>Rondo</b>			
EZ-sensor - 315 MHz .....				EZ-sensor - 315 MHz .....			
◇33000				◇33000			
EZ-sensor Service Pack; Almm. Valve				EZ-sensor Service Pack; Almm. Valve			
34000				34000			
EZ-sensor Service Pack; Rubber Valve				EZ-sensor Service Pack; Rubber Valve			
20008				20008			
Sensor .....				Sensor; Includes Transmitter Only .....			
28849				20086			
Service Pack .....				Service Pack; Includes Valve .....			
20022				20036			
<b>Sedona</b>				Service Pack; Does Not Include Valve .			
Sensor; Includes Transmitter Only .....				20021			
20085				31-40			
Service Pack; Includes Valve .....				3.5-4.5			
20036				3.5-4.5			
Service Pack; Does Not Include Valve .				3.5-4.5			
20021				3.5-4.5			
<b>Sorento</b>				<b>Spectra</b>			
Sensor .....				EZ-sensor - 315 MHz .....			
28983				◇33000			
Service Pack; Includes Valve .....				EZ-sensor Service Pack; Almm. Valve			
20036				34000			
Service Pack; Does Not Include Valve .				EZ-sensor Service Pack; Rubber Valve			
20021				20008			
<b>Spectra</b>				Sensor .....			
EZ-sensor - 315 MHz .....				28849			
◇33000				35-35.7			
EZ-sensor Service Pack; Almm. Valve				Service Pack .....			
34000				20022			
EZ-sensor Service Pack; Rubber Valve				35-35.7			
20008				3.5-4.5			
Sensor .....				<b>Sportage</b>			
28849				Sensor .....			
Service Pack .....				28983			
20022				31-40			
<b>Sportage</b>				Service Pack; Includes Valve .....			
Sensor .....				20036			
28983				31-40			
Service Pack; Includes Valve .....				Service Pack; Does Not Include Valve .			
20036				20021			
Service Pack; Does Not Include Valve .				31-40			
20021				3.5-4.5			
<b>2006</b>				<b>Optima</b>			
<b>Optima</b>				EZ-sensor - 315 MHz .....			
EZ-sensor - 315 MHz .....				◇33000			
◇33000				11.5			
EZ-sensor Service Pack; Almm. Valve				EZ-sensor Service Pack; Almm. Valve			
34000				34000			
EZ-sensor Service Pack; Rubber Valve				EZ-sensor Service Pack; Rubber Valve			
20008				20008			
Sensor; Includes Transmitter Only .....				Sensor .....			
20086				28849			
Service Pack; Includes Valve .....				Service Pack .....			
20036				20022			
Service Pack; Does Not Include Valve .				35-35.7			
20021				3.5-4.5			

◇ Programming Tool Required.



## Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
<b>► Kia - Continued</b>				<b>► Land Rover - Continued</b>			
<b>2006 - Continued</b>				<b>2004-2002 - Continued</b>			
<b>Sedona</b>				<b>Range Rover - Continued</b>			
Sensor; Includes Transmitter Only .....	20085	31-40	3.5-4.5	Service Pack; Does Not Include Valve .	20023	58	6.5
Service Pack; Includes Valve .....	20036	31-40	3.5-4.5	Service Pack; W/43mm Silver Insert ....	20037	58	6.5
Service Pack; Does Not Include Valve .	20021	31-40	3.5-4.5	Service Pack; W/48mm Green Insert ...	20038	58	6.5
<b>Spectra</b>				Service Pack; W/49mm Black Insert .....	20039	58	6.5
Sensor .....	28849	35-35.7	3.5-4.5	Service Pack; W/51mm Orange Insert .	20040	58	6.5
Service Pack .....	20022	35-35.7	3.5-4.5	<b>► Lexus</b>			
<b>Sportage</b>				<b>2013</b>			
Sensor .....	28983	31-40	3.5-4.5	<b>ES350; GS350; GS450h; GX460; IS250; IS350; IS F; LFA; LS460; LS600h; LX570; RX350; RX450h</b>			
Service Pack; Includes Valve .....	20036	31-40	3.5-4.5	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Service Pack; Does Not Include Valve .	20021	31-40	3.5-4.5	EZ-sensor Service Pack; Almm. Valve	34000	62	7
<b>2005</b>				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
<b>Sportage</b>				Sensor .....	28370	35	4
Sensor; Jun. 15, 2005 & Newer .....	28983	31-40	3.5-4.5	Service Pack .....	20032	35	4
Service Pack; Jun. 15, 2005 & Newer; Includes Valve .....	20036	31-40	3.5-4.5	<b>2012</b>			
Service Pack; Jun. 15, 2005 & Newer; Does Not Include Valve .....	20021	31-40	3.5-4.5	<b>CT200h; ES350; GX460</b>			
<b>► Land Rover</b>				EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
<b>2013</b>				EZ-sensor Service Pack; Almm. Valve	34000	62	7
<b>Range Rover</b>				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor .....	20090	71	8	Sensor .....	28370	35	4
Service Pack .....	20030	71	8	Service Pack .....	20032	35	4
<b>2012</b>				<b>HS250h</b>			
<b>LR2; LR4; Range Rover</b>				EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Sensor .....	20090	71	8	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Service Pack .....	20030	71	8	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
<b>2011-2010</b>				Sensor .....	28345	35	4
<b>LR2</b>				Service Pack .....	20032	35	4
Sensor .....	20090	71	8	<b>IS250; IS350; IS F; LFA; LS460; LS600h; RX350; RX450h</b>			
Service Pack .....	20030	71	8	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
<b>LR4; Range Rover</b>				EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor; W/315 MHz Sensor .....	20090	71	8	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor; W/433 MHz Sensor .....	20091	71	8	Sensor .....	28370	35	4
Service Pack .....	20030	71	8	Service Pack .....	20032	35	4
<b>2009-2008</b>				<b>2011</b>			
<b>LR2</b>				<b>CT200h; ES350; GS350; GS450h; GS460; GX460</b>			
Sensor .....	20090	71	8	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Service Pack .....	20030	71	8	EZ-sensor Service Pack; Almm. Valve	34000	62	7
<b>LR3; Range Rover</b>				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor; W/315 MHz Sensor .....	20090	71	8	Sensor .....	28370	35	4
Sensor; W/433 MHz Sensor .....	20091	71	8	Service Pack .....	20032	35	4
Service Pack .....	20030	71	8	<b>HS250h</b>			
<b>2007-2006</b>				EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
<b>LR3; Range Rover</b>				EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor; W/315 MHz Sensor .....	20090	71	8	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor; W/433 MHz Sensor .....	20091	71	8	Sensor .....	28345	35	4
Service Pack .....	20030	71	8	Service Pack .....	20032	35	4
<b>2005</b>				<b>IS250; IS350; IS F; LFA; LS460; LS600h; LX570; RX350; RX450h</b>			
<b>LR3; Range Rover</b>				EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Sensor; Includes Transmitter Only .....	28082	58	6.5	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Service Pack; Does Not Include Valve .	20023	58	6.5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Service Pack; W/43mm Silver Insert ....	20037	58	6.5	Sensor .....	28370	35	4
Service Pack; W/48mm Green Insert ...	20038	58	6.5	Service Pack .....	20032	35	4
Service Pack; W/49mm Black Insert ....	20039	58	6.5	<b>2010</b>			
Service Pack; W/51mm Orange Insert .	20040	58	6.5	<b>ES350; GS350; GS450h; GS460; GX460</b>			
<b>2004-2002</b>				EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
<b>Range Rover</b>				EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor; Includes Transmitter Only .....	28082	58	6.5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
				Sensor .....	28370	35	4
				Service Pack .....	20032	35	4
				<b>HS250h</b>			
				EZ-sensor - 315 MHz .....	◇33000	11.5	1.3

◇ Programming Tool Required.

## Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
<b>► Lexus - Continued</b>				<b>► Lexus - Continued</b>			
<b>2010 - Continued</b>				<b>2007 - Continued</b>			
<b>HS250h - Continued</b>				<b>SC430</b>			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor - 315 MHz	◇33000	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor	28345	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Service Pack	20032	35	4	Sensor	28370	27	3
<b>IS250; IS350; IS F; LS460; LS600h; LX570</b>				<b>2006</b>			
EZ-sensor - 315 MHz	◇33000	11.5	1.3	<b>GS300</b>			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor - 315 MHz	◇33000	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor	28370	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Service Pack	20032	35	4	Sensor	28335	35	4
<b>RX350</b>				<b>GS430</b>			
EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor; Models made in Japan.	28370	35	4	Sensor; Jul. & Newer	28370	35	4
Service Pack	20032	35	4	Sensor; Jun. & Older	28335	35	4
<b>RX450h</b>				<b>Service Pack; Jul. &amp; Newer</b>			
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack; Jun. & Older	20031	35	4
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>GX470</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3
Sensor	28370	35	4	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Service Pack	20032	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
<b>SC430</b>				<b>ES350; GS350; GS450h; GS460; GX470; IS250; IS350; IS F; LS460; LS600h; LX570</b>			
EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor	28370	27	3	Sensor	28370	35	4
Service Pack	20032	27	3	Service Pack	20032	35	4
<b>2009-2008</b>				<b>RX350; RX400h</b>			
<b>ES350; GS350; GS450h; GS460; GX470; IS250; IS350; IS F; LS460; LS600h; LX570</b>				<b>SC430</b>			
EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor	28370	35	4	Sensor	28370	27	3
Service Pack	20032	35	4	Service Pack	20032	27	3
<b>RX350; RX400h</b>				<b>2007</b>			
EZ-sensor - 315 MHz	◇33000	11.5	1.3	<b>ES350; GS350; GS430; GS450h; GX470; IS250; IS350; LS460; LX470</b>			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor - 315 MHz	◇33000	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor; Models made in Japan.	28370	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Service Pack	20032	35	4	Sensor	28370	35	4
<b>SC430</b>				<b>Service Pack</b>			
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack	20032	35	4
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>2007</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	<b>ES350; GS350; GS430; GS450h; GX470; IS250; IS350; LS460; LX470</b>			
Sensor	28370	27	3	EZ-sensor - 315 MHz	◇33000	11.5	1.3
Service Pack	20032	27	3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
<b>2007</b>				<b>RX350; RX400h</b>			
<b>ES350; GS350; GS430; GS450h; GX470; IS250; IS350; LS460; LX470</b>				<b>SC430</b>			
EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor	28370	35	4	Sensor; Aug. & Newer	28370	27	3
Service Pack	20032	35	4	Sensor; Aug. & Newer	28370	27	3
<b>RX350; RX400h</b>				<b>Sensor; W/White I.D. Mark; Jul. &amp; Older</b>			
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor; W/White I.D. Mark; Jul. & Older	28310	27	3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor; W/Blue I.D. Mark; Jul. & Older	28315	27	3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; W/Red I.D. Mark; Jul. & Older	28320	27	3
Sensor; Models made in Japan.	28370	35	4	Sensor; W/Gold I.D. Mark; Jul. & Older	28325	27	3
Service Pack	20032	35	4	Service Pack; Aug. & Newer	20032	27	3

◇ Programming Tool Required.

## Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
<b>► Lexus - Continued</b>				<b>► Lincoln - Continued</b>			
<b>2005</b>				<b>2010 - Continued</b>			
<b>GS430</b>				<b>MKS; MKT; MKX - Continued</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Sensor Clip .....	22100		
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor Cradle .....	22101		
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor Universal Band .....	22102		
Sensor .....	28335	35	4	<b>MKZ</b>			
Service Pack .....	20031	35	4	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
<b>GX470</b>				EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor .....	20315	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack .....	20018	11.5	1.3
Sensor .....	28345	35	4	<b>Navigator</b>			
Service Pack .....	20031	35	4	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
<b>LX470</b>				EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor .....	28390	27	3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor Clip .....	22100		
Sensor .....	28365	35	4	Sensor Cradle .....	22101		
Service Pack .....	20031	35	4	Sensor Universal Band .....	22102		
<b>SC430</b>				<b>Town Car</b>			
Sensor; W/White I.D. Mark .....	28310	27	3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Sensor; W/Blue I.D. Mark .....	28315	27	3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor; W/Red I.D. Mark .....	28320	27	3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor; W/Gold I.D. Mark .....	28325	27	3	Sensor .....	28385	27	3
				Sensor Clip .....	22100		
				Sensor Cradle .....	22101		
				Sensor Universal Band .....	22102		
<b>2004</b>				<b>2009</b>			
<b>GX470</b>				<b>Mark LT</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor .....	20315	11.5	1.3
Sensor .....	28345	35	4	<b>MKS; MKX</b>			
Service Pack .....	20031	35	4	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
<b>SC430</b>				EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor; W/White I.D. Mark .....	28310	27	3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor; W/Blue I.D. Mark .....	28315	27	3	Sensor .....	28390	27	3
Sensor; W/Red I.D. Mark .....	28320	27	3	Sensor Clip .....	22100		
Sensor; W/Gold I.D. Mark .....	28325	27	3	Sensor Cradle .....	22101		
				Sensor Universal Band .....	22102		
<b>2003-2002</b>				<b>MKZ</b>			
<b>SC430</b>				EZ-sensor - 315 MHz .....			
Sensor; W/White I.D. Mark .....	28310	27	3	◇33000	11.5	1.3	
Sensor; W/Blue I.D. Mark .....	28315	27	3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor; W/Red I.D. Mark .....	28320	27	3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor; W/Gold I.D. Mark .....	28325	27	3	Sensor .....	28390	27	3
				Sensor Clip .....	22100		
				Sensor Cradle .....	22101		
				Sensor Universal Band .....	22102		
<b>► Lincoln</b>				<b>Navigator</b>			
<b>2013-2012</b>				EZ-sensor - 315 MHz .....			
<b>MKS; MKT; MKX; MKZ; Navigator</b>				◇33000			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor .....	20315	11.5	1.3
Sensor .....	20315	11.5	1.3	Service Pack .....	20018	11.5	1.3
Service Pack .....	20018	11.5	1.3	<b>2011</b>			
				<b>MKS; MKT; MKX; MKZ; Navigator; Town Car</b>			
				EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
				EZ-sensor Service Pack; Almm. Valve	34000	62	7
				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
				Sensor .....	20315	11.5	1.3
				Service Pack .....	20018	11.5	1.3
				<b>2010</b>			
				<b>MKS; MKT; MKX</b>			
				EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
				EZ-sensor Service Pack; Almm. Valve	34000	62	7
				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
				Sensor .....	28390	27	3

◇ Programming Tool Required.

## Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
<b>► Lincoln - Continued</b>				<b>► Lincoln - Continued</b>			
<b>2008-2007</b>				<b>2005 - Continued</b>			
<b>Mark LT</b>				<b>Navigator - Continued</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Service Pack .....	20002	44	5
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>2004-2003</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	<b>Aviator; Navigator</b>			
Sensor .....	28385	27	3	EZ-sensor - 433 MHz .....	◇33100	11.5	1.3
Sensor Clip .....	22100			EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor Cradle .....	22101			EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor Universal Band .....	22102			Sensor .....	●20096	44	5
<b>MKX</b>				Service Pack .....	20002	44	5
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	<b>► Maserati</b>			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>2006</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	<b>Coupe; Gransport; MC12; Quattroporte; Spyder</b>			
Sensor; W/Chrome Plated Almm. Wheels .....	28385	27	3	Service Pack; Does Not Include Valve .	20023		
Sensor; W/O Chrome Plated Almm. Wheels .....	28390	27	3	Service Pack; W/43mm Silver Insert ...	20037		
Sensor Clip .....	22100			Service Pack; W/48mm Green Insert ...	20038		
Sensor Cradle .....	22101			Service Pack; W/49mm Black Insert ....	20039		
Sensor Universal Band .....	22102			Service Pack; W/51mm Orange Insert .	20040		
<b>MKZ</b>				<b>2005-2004</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	<b>Coupe; Gransport; Quattroporte; Spyder</b>			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Service Pack; Does Not Include Valve .	20023		
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack; W/43mm Silver Insert ...	20037		
Sensor .....	28385	27	3	Service Pack; W/48mm Green Insert ...	20038		
Sensor Clip .....	22100			Service Pack; W/49mm Black Insert ....	20039		
Sensor Cradle .....	22101			Service Pack; W/51mm Orange Insert .	20040		
Sensor Universal Band .....	22102			<b>► Mazda</b>			
<b>Navigator</b>				<b>2013</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	6	Service Pack .....	20030	71 8
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>2012</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	<b>2; 3; 5; 6; CX-9; MX-5 Miata</b>			
Sensor .....	28390	27	3	Sensor .....	20093	71	8
Sensor Clip .....	22100			Service Pack .....	20030	71	8
Sensor Cradle .....	22101			<b>2011</b>			
Sensor Universal Band .....	22102			<b>2; 3; 6; CX-7; CX-9; MX-5 Miata; RX-8; Tribute</b>			
<b>Town Car</b>				Sensor .....	20093	71	8
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Service Pack .....	20030	71	8
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>2010</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	<b>3; 5; 6; CX-7; CX-9; MX-5 Miata; RX-8</b>			
Sensor .....	28385	27	3	Sensor .....	20093	71	8
Sensor Clip .....	22100			Service Pack .....	20030	71	8
Sensor Cradle .....	22101			<b>Tribute</b>			
Sensor Universal Band .....	22102			EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
<b>2006</b>				EZ-sensor Service Pack; Almm. Valve	34000	62	7
<b>Navigator</b>				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor .....	●20135	44	5	Sensor .....	20315	11.5	1.3
Service Pack .....	20002	44	5	Service Pack .....	20018	11.5	1.3
<b>Town Car</b>				<b>2009</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	<b>3; 5; 6</b>			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor .....	20093	71	8
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack .....	20030	71	8
Sensor .....	28385	27	3	<b>B2300 Pickup; B4000 Pickup</b>			
Sensor Clip .....	22100			EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Sensor Cradle .....	22101			EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor Universal Band .....	22102			EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
<b>2005</b>				Sensor .....	28385	27	3
<b>Aviator</b>				Sensor Clip .....	22100		
EZ-sensor - 433 MHz .....	◇33100	11.5	1.3	Sensor Cradle .....	22101		
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor Universal Band .....	22102		
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	<b>2009</b>			
Sensor .....	●20096	44	5	<b>3; 5; 6</b>			
Service Pack .....	20002	44	5	Sensor .....	20093	71	8
<b>Navigator</b>				Service Pack .....	20030	71	8
Sensor .....	●20135	44	5	<b>2009</b>			

◇ Programming Tool Required.  
● Magnet Required to Activate Sensor.



## Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
<b>► Mazda - Continued</b>				<b>► Mazda - Continued</b>			
<b>2009 - Continued</b>				<b>2005-2004 - Continued</b>			
<b>CX-7; CX-9; MX-5 Miata; RX-8</b>				<b>3; RX-8 - Continued</b>			
Sensor .....	20093	71	8	Service Pack .....	20030	71	8
Service Pack .....	20030	71	8	<b>► Mercedes-Benz</b>			
<b>Tribute</b>				<b>2013</b>			
EZ-sensor - 315 MHz .....	⇨33000	11.5	1.3	<b>C63; C250; C300; C350; CL63; CL65; CL550; CL600; CLS63; CLS550; E63; E350; E550; G550; GL63; GL450; GL550; GLK350; ML63; ML350; R350; S63; S65; S350; S400; S550; S600; SL63; SL550; SLK250; SLK350; SLS</b>			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor .....	28214	58	6.5
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack; W/Valve .....	20020	58	6.5
Sensor .....	20315	11.5	1.3	Service Pack; W/O Valve .....	20016	58	6.5
Service Pack .....	20018	11.5	1.3	<b>2012</b>			
<b>2008</b>				<b>C63; C250; C300; C350; CL63; CL65; CL550; CL600; CLS63; CLS550</b>			
<b>3; 5; 6</b>				<b>E63</b>			
Sensor .....	20093	71	8	Sensor .....	28214	58	6.5
Service Pack .....	20030	71	8	Service Pack; W/Valve .....	20020	58	6.5
<b>B2300 Pickup; B3000 Pickup; B4000 Pickup</b>				<b>E350</b>			
EZ-sensor - 315 MHz .....	⇨33000	11.5	1.3	Sensor .....	28214	58	6.5
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Service Pack; Includes Stem Only .....	20020	58	6.5
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack; Does Not Include Stem ..	20016	58	6.5
Sensor .....	28385	27	3	<b>E550</b>			
Sensor Clip .....	22100			Sensor .....	28214	58	6.5
Sensor Cradle .....	22101			Service Pack; W/Valve .....	20020	58	6.5
Sensor Universal Band .....	22102			Service Pack; W/O Valve .....	20016	58	6.5
<b>CX-7; CX-9; MX-5 Miata; RX-8</b>				<b>G550</b>			
Sensor .....	20093	71	8	Sensor .....	28214	58	6.5
Service Pack .....	20030	71	8	Service Pack; W/Valve .....	20020	31-40	3.5-4.5
<b>Tribute</b>				<b>Service Pack; W/O Valve .....</b>			
EZ-sensor - 315 MHz .....	⇨33000	11.5	1.3	<b>20016 31-40 3.5-4.5</b>			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>GL350; GL450; GL550</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor .....	28214	58	6.5
Sensor .....	28385	27	3	Service Pack; W/Valve .....	20020	58	6.5
Sensor Clip .....	22100			Service Pack; W/O Valve .....	20016	58	6.5
Sensor Cradle .....	22101			<b>GLK350</b>			
Sensor Universal Band .....	22102			Sensor .....	28214	58	6.5
<b>2007</b>				<b>Service Pack; Includes Stem Only .....</b>			
<b>3; 5</b>				<b>Service Pack; Does Not Include Stem ..</b>			
Sensor .....	20093	71	8	<b>20016 58 6.5</b>			
Service Pack .....	20030	71	8	<b>ML63</b>			
<b>B2300 Pickup; B3000 Pickup; B4000 Pickup</b>				<b>Sensor .....</b>			
EZ-sensor - 315 MHz .....	⇨33000	11.5	1.3	<b>Service Pack; W/Valve .....</b>			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>Service Pack; W/O Valve .....</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	<b>28214 58 6.5</b>			
Sensor .....	28385	27	3	<b>ML350; R350</b>			
Sensor Clip .....	22100			<b>Sensor .....</b>			
Sensor Cradle .....	22101			<b>Service Pack; Includes Stem Only .....</b>			
Sensor Universal Band .....	22102			<b>Service Pack; Does Not Include Stem ..</b>			
<b>CX-7; CX-9; MX-5 Miata; RX-8</b>				<b>20016 58 6.5</b>			
Sensor .....	20093	71	8	<b>S63; S65; S350; S400; S550; S600</b>			
Service Pack .....	20030	71	8	<b>Sensor .....</b>			
<b>2006</b>				<b>Service Pack; W/Valve .....</b>			
<b>3; 5; MX-5 Miata; RX-8</b>				<b>Service Pack; W/O Valve .....</b>			
Sensor .....	20093	71	8	<b>28214 58 6.5</b>			
Service Pack .....	20030	71	8	<b>20020 58 6.5</b>			
<b>Tribute</b>				<b>20016 58 6.5</b>			
EZ-sensor - 315 MHz .....	⇨33000	11.5	1.3	<b>SL63; SL550; SLK250; SLK350; SLS</b>			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>Sensor .....</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	<b>Service Pack; Includes Stem Only .....</b>			
Sensor .....	28385	27	3	<b>Service Pack; Does Not Include Stem ..</b>			
Sensor Clip .....	22100			<b>28214 58 6.5</b>			
Sensor Cradle .....	22101			<b>20020 58 6.5</b>			
Sensor Universal Band .....	22102			<b>20016 58 6.5</b>			
<b>2005-2004</b>				<b>2011</b>			
<b>3; RX-8</b>				<b>C63; C300; C350; CL63; CL65; CL550</b>			
Sensor .....	20093	71	8	<b>Sensor .....</b>			
				<b>Service Pack; Includes Stem Only .....</b>			
				<b>28214 58 6.5</b>			
				<b>20020 58 6.5</b>			

⇨ Programming Tool Required.

## Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
<b>► Mercedes-Benz - Continued</b>				<b>► Mercedes-Benz - Continued</b>			
<b>2011 - Continued</b>				<b>2009 - Continued</b>			
<b>C63; C300; C350; CL63; CL65; CL550 - Continued</b>				<b>CLS63; CLS550; E63; E320</b>			
Service Pack; Does Not Include Stem ..	20016	58	6.5	Sensor .....	20094	53	6
<b>CLS63; CLS550</b>				Service Pack; Includes Valve .....	20036	53	6
Sensor .....	20094	53	6	Service Pack; Does Not Include Valve .	20021	53	6
Service Pack; Includes Valve .....	20036	53	6	<b>E350; E550</b>			
Service Pack; Does Not Include Valve .	20021	53	6	Sensor; W/315 MHz Sensor .....	20094	53	6
<b>E63; E350; E550</b>				Sensor; W/433 MHz Sensor .....	20095	53	6
Sensor .....	28214	58	6.5	Service Pack; Includes Valve .....	20036	53	6
Service Pack; Includes Stem Only .....	20020	58	6.5	Service Pack; Does Not Include Valve .	20021	53	6
Service Pack; Does Not Include Stem ..	20016	58	6.5	<b>G55; G550</b>			
<b>G55; G550; GL350; GL450; GL550; GLK350; ML63; ML350; ML450; ML550; R350</b>				Sensor .....	28214	58	6.5
Sensor .....	28214	58	6.5	Service Pack; Includes Stem Only .....	20020	58	6.5
Service Pack; Mar. & Newer; Includes Stem Only .....	20020	58	6.5	Service Pack; Does Not Include Stem ..	20016	58	6.5
Service Pack; Mar. & Newer; Does Not Include Stem .....	20016	58	6.5	<b>GL320; GL450; GL550; ML63; ML320; ML350; ML550; R320; R350</b>			
<b>S63; S65; S400; S550; S600</b>				Sensor .....	20095	53	6
Sensor .....	28214	58	6.5	Service Pack; Includes Valve .....	20036	53	6
Service Pack; Includes Stem Only .....	20020	58	6.5	Service Pack; Does Not Include Valve .	20021	53	6
Service Pack; Does Not Include Stem ..	20016	58	6.5	<b>S63; S65; S550; S600; SL63; SL65; SL550; SL600</b>			
<b>SL63; SL65</b>				Sensor .....	20094	53	6
Sensor .....	20094	53	6	<b>SLK55; SLK300; SLK350</b>			
<b>SLK300; SLK350; SLS</b>				Sensor .....	28214	58	6.5
Sensor .....	28214	58	6.5	Service Pack; Includes Stem Only .....	20020	58	6.5
Service Pack; Includes Stem Only .....	20020	58	6.5	Service Pack; Does Not Include Stem ..	20016	58	6.5
Service Pack; Does Not Include Stem ..	20016	58	6.5	<b>SLR McLaren</b>			
<b>2010</b>				Sensor .....	20094	53	6
<b>C63; C300; C350; CL63; CL65; CL550; CL600</b>				Service Pack; Includes Valve .....	20036	53	6
Sensor .....	28214	58	6.5	Service Pack; Does Not Include Valve .	20021	53	6
Service Pack; Includes Stem Only .....	20020	58	6.5	<b>2008</b>			
Service Pack; Does Not Include Stem ..	20016	58	6.5	<b>C63; C300; C350</b>			
<b>CLS63; CLS550</b>				Sensor .....	28214	58	6.5
Sensor .....	20094	53	6	Service Pack; Includes Stem Only .....	20020	58	6.5
Service Pack; Includes Valve .....	20036	53	6	Service Pack; Does Not Include Stem ..	20016	58	6.5
Service Pack; Does Not Include Valve .	20021	53	6	<b>CL63; CL65; CL550; CL600</b>			
<b>E63; E350; E550; G55; G550; GL350; GL450; GL550; GLK350; ML63; ML350; ML450; ML550; R350</b>				Sensor .....	20094	53	6
Sensor .....	28214	58	6.5	Service Pack; Includes Valve .....	20036	53	6
Service Pack; Includes Stem Only .....	20020	58	6.5	Service Pack; Does Not Include Valve .	20021	53	6
Service Pack; Does Not Include Stem ..	20016	58	6.5	<b>CLK63; CLK350; CLK550</b>			
<b>S63; S65; S400; S550; S600</b>				Sensor .....	28214	58	6.5
Sensor .....	20094	53	6	Service Pack; Includes Stem Only .....	20020	58	6.5
Service Pack; Includes Valve .....	20036	53	6	Service Pack; Does Not Include Stem ..	20016	58	6.5
Service Pack; Does Not Include Valve .	20021	53	6	<b>CLS63; CLS550; E63; E320</b>			
<b>SLK55; SLK300; SLK350</b>				Sensor .....	20094	53	6
Sensor .....	28214	58	6.5	Service Pack; Includes Valve .....	20036	53	6
Service Pack; Includes Stem Only .....	20020	58	6.5	Service Pack; Does Not Include Valve .	20021	53	6
Service Pack; Does Not Include Stem ..	20016	58	6.5	<b>E350; E550</b>			
<b>2009</b>				Sensor; W/315 MHz Sensor .....	20094	53	6
<b>C63; C300; C350</b>				Sensor; W/433 MHz Sensor .....	20095	53	6
Sensor .....	28214	58	6.5	Service Pack; Includes Valve .....	20036	53	6
Service Pack; Includes Stem Only .....	20020	58	6.5	Service Pack; Does Not Include Valve .	20021	53	6
Service Pack; Does Not Include Stem ..	20016	58	6.5	<b>G55; G500</b>			
<b>CL63; CL65; CL550; CL600</b>				Sensor .....	28214	58	6.5
Sensor .....	20094	53	6	Service Pack; Includes Stem Only .....	20020	58	6.5
Service Pack; Includes Valve .....	20036	53	6	Service Pack; Does Not Include Stem ..	20016	58	6.5
Service Pack; Does Not Include Valve .	20021	53	6	<b>GL320; GL450; GL550; ML63; ML320; ML350; ML550; R320; R350</b>			
<b>CLK63; CLK350; CLK550</b>				Sensor .....	20095	53	6
Sensor .....	28214	58	6.5	Service Pack; Includes Valve .....	20036	53	6
Service Pack; Includes Stem Only .....	20020	58	6.5	Service Pack; Does Not Include Valve .	20021	53	6
Service Pack; Does Not Include Stem ..	20016	58	6.5				

## Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
<b>► Mercedes-Benz - Continued</b>				<b>► Mercedes-Benz - Continued</b>			
<b>2008 - Continued</b>				<b>2007 - Continued</b>			
<b>R550</b>				<b>SLK55; SLK280; SLK350</b>			
Service Pack; Does Not Include Valve .	20023	53	6	Sensor; May & Newer .....	28214	58	6.5
Service Pack; W/43mm Silver Insert ....	20037	53	6	Service Pack; May & Newer; Includes Stem Only .....	20020	58	6.5
Service Pack; W/48mm Green Insert ...	20038	53	6	Service Pack; May & Newer; Does Not Include Stem .....	20016	58	6.5
Service Pack; W/49mm Black Insert .....	20039	53	6	<b>SLR McLaren</b>			
Service Pack; W/51mm Orange Insert .	20040	53	6	Service Pack; Does Not Include Valve .	20023	53	6
<b>S63; S65; S550; S600; SL55; SL65; SL550; SL600</b>				Service Pack; W/43mm Silver Insert ....	20037	53	6
Sensor .....	20094	53	6	Service Pack; W/48mm Green Insert ...	20038	53	6
Service Pack; Includes Valve .....	20036	53	6	Service Pack; W/49mm Black Insert .....	20039	53	6
Service Pack; Does Not Include Valve .	20021	53	6	Service Pack; W/51mm Orange Insert .	20040	53	6
<b>SLK55; SLK280; SLK350</b>				<b>2006</b>			
Sensor .....	28214	58	6.5	<b>CL55; CL65; CL500; CL600</b>			
Service Pack; Includes Stem Only .....	20020	58	6.5	Service Pack; Does Not Include Valve .	20023	35	4
Service Pack; Does Not Include Stem ..	20016	58	6.5	Service Pack; W/43mm Silver Insert ....	20037	35	4
<b>SLR McLaren</b>				Service Pack; W/48mm Green Insert ...	20038	35	4
Sensor .....	20094	53	6	Service Pack; W/49mm Black Insert .....	20039	35	4
Service Pack; Includes Valve .....	20036	53	6	Service Pack; W/51mm Orange Insert .	20040	35	4
Service Pack; Does Not Include Valve .	20021	53	6	<b>CLK55; CLK350; CLK500</b>			
<b>2007</b>				Sensor .....	28214	58	6.5
<b>C280</b>				Service Pack; Includes Stem Only .....	20020	58	6.5
Sensor; Mar. & Newer .....	28214	58	6.5	Service Pack; Does Not Include Stem ..	20016	58	6.5
Service Pack; Mar. & Newer; Includes Stem Only .....	20020	58	6.5	<b>CLS55; CLS500; E55; E320</b>			
Service Pack; Mar. & Newer; Does Not Include Stem .....	20016	58	6.5	Sensor .....	20094	53	6
<b>C350</b>				Service Pack; Includes Valve .....	20036	53	6
Sensor; Jun. & Newer .....	28214	58	6.5	Service Pack; Does Not Include Valve .	20021	53	6
Service Pack; Jun. & Newer; Includes Stem Only .....	20020	58	6.5	<b>E350</b>			
Service Pack; Jun. & Newer; Does Not Include Stem .....	20016	58	6.5	Sensor; W/315 MHz Sensor .....	20094	53	6
<b>CL63; CL550; CL600</b>				Sensor; W/433 MHz Sensor .....	20095	53	6
Sensor .....	20094	53	6	Service Pack; Includes Valve .....	20036	53	6
Service Pack; Includes Valve .....	20036	53	6	Service Pack; Does Not Include Valve .	20021	53	6
Service Pack; Does Not Include Valve .	20021	53	6	<b>E500</b>			
<b>CLK63; CLK350; CLK550</b>				Sensor .....	20094	53	6
Sensor .....	28214	58	6.5	Service Pack; Includes Valve .....	20036	53	6
Service Pack; Includes Stem Only .....	20020	58	6.5	Service Pack; Does Not Include Valve .	20021	53	6
Service Pack; Does Not Include Stem ..	20016	58	6.5	<b>ML350; ML500; R350; R500</b>			
<b>CLS63; CLS550; E63; E320</b>				Sensor .....	20095	53	6
Sensor .....	20094	53	6	Service Pack; Includes Valve .....	20036	53	6
Service Pack; Includes Valve .....	20036	53	6	Service Pack; Does Not Include Valve .	20021	53	6
Service Pack; Does Not Include Valve .	20021	53	6	<b>S55; S65; S350; S430; S500; S600</b>			
<b>E350; E550</b>				Service Pack; Does Not Include Valve .	20023	35	4
Sensor; W/315 MHz Sensor .....	20094	53	6	Service Pack; W/43mm Silver Insert ....	20037	35	4
Sensor; W/433 MHz Sensor .....	20095	53	6	Service Pack; W/48mm Green Insert ...	20038	35	4
Service Pack; Includes Valve .....	20036	53	6	Service Pack; W/49mm Black Insert .....	20039	35	4
Service Pack; Does Not Include Valve .	20021	53	6	Service Pack; W/51mm Orange Insert .	20040	35	4
<b>G55; G500</b>				<b>SL55; SL65; SL500; SL600</b>			
Sensor; Mar. & Newer .....	28214	58	6.5	Sensor .....	20094	53	6
Service Pack; Mar. & Newer; Includes Stem Only .....	20020	58	6.5	Service Pack; Includes Valve .....	20036	53	6
Service Pack; Mar. & Newer; Does Not Include Stem .....	20016	58	6.5	Service Pack; Does Not Include Valve .	20021	53	6
<b>GL320; GL450; ML63; ML320; ML350; ML500; R63; R320; R350; R500</b>				<b>SLR McLaren</b>			
Sensor .....	20095	53	6	Service Pack; Does Not Include Valve .	20023	35	4
Service Pack; Includes Valve .....	20036	53	6	Service Pack; W/43mm Silver Insert ....	20037	35	4
Service Pack; Does Not Include Valve .	20021	53	6	Service Pack; W/48mm Green Insert ...	20038	35	4
<b>S63; S65; S550; S600; SL55; SL65; SL550; SL600</b>				Service Pack; W/49mm Black Insert .....	20039	35	4
Sensor .....	20094	53	6	Service Pack; W/51mm Orange Insert .	20040	35	4
Service Pack; Includes Valve .....	20036	53	6	<b>2005</b>			
Service Pack; Does Not Include Valve .	20021	53	6	<b>CL55; CL65; CL500; CL600; E55; E320; E500; S55; S430; S500; S600; SL55; SL65; SL500; SL600; SLR McLaren</b>			
<b>2008 - Continued</b>				Service Pack; Does Not Include Valve .	20023	35	4
Sensor .....	20094	53	6	Service Pack; W/43mm Silver Insert ....	20037	35	4
Service Pack; Includes Valve .....	20036	53	6	Service Pack; W/48mm Green Insert ...	20038	35	4
Service Pack; Does Not Include Valve .	20021	53	6	Service Pack; W/49mm Black Insert .....	20039	35	4

## Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
<b>► Mercedes-Benz - Continued</b>				<b>► Mercury - Continued</b>			
<b>2005 - Continued</b>				<b>2010</b>			
<b>CL55; CL65; CL500; CL600; E55; E320; E500; S55; S430; S500; S600; SL55; SL65; SL500; SL600; SLR McLaren - Continued</b>				<b>Grand Marquis</b>			
Service Pack; W/51mm Orange Insert .	20040	35	4	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
<b>2004</b>				EZ-sensor Service Pack; Almm. Valve	34000	62	7
<b>CL55; CL500; CL600; E55; E320; E500; S55; S430; S500; S600; SL55; SL500; SL600; SLR McLaren</b>				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Service Pack; Does Not Include Valve .	20023	35	4	Sensor .....	28385	27	3
Service Pack; W/43mm Silver Insert ....	20037	35	4	Sensor Clip .....	22100		
Service Pack; W/48mm Green Insert ...	20038	35	4	Sensor Cradle .....	22101		
Service Pack; W/49mm Black Insert .....	20039	35	4	Sensor Universal Band .....	22102		
Service Pack; W/51mm Orange Insert .	20040	35	4	<b>Mariner; Milan</b>			
<b>2003</b>				EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
<b>CL55; CL500; CL600; E55; E320; E500; S55; S430; S500; S600; SL55; SL500</b>				EZ-sensor Service Pack; Almm. Valve	34000	62	7
Service Pack; Does Not Include Valve .	20023	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Service Pack; W/43mm Silver Insert ....	20037	35	4	Sensor .....	20315	13	1.5
Service Pack; W/48mm Green Insert ...	20038	35	4	Service Pack .....	20018	11.5	1.3
Service Pack; W/49mm Black Insert .....	20039	35	4	<b>Mountaineer</b>			
Service Pack; W/51mm Orange Insert .	20040	35	4	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
<b>2002-2001</b>				EZ-sensor Service Pack; Almm. Valve	34000	62	7
<b>CL55; CL500; CL600; E55; E320; E430; S55; S430; S500; S600; SL500; SL600</b>				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Service Pack; Does Not Include Valve .	20023	35	4	Sensor .....	28385	27	3
Service Pack; W/43mm Silver Insert ....	20037	35	4	Sensor Clip .....	22100		
Service Pack; W/48mm Green Insert ...	20038	35	4	Sensor Cradle .....	22101		
Service Pack; W/49mm Black Insert .....	20039	35	4	Sensor Universal Band .....	22102		
Service Pack; W/51mm Orange Insert .	20040	35	4	<b>2009</b>			
<b>2000</b>				<b>Grand Marquis</b>			
<b>CL500; E55; S430; S500</b>				EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Service Pack; Does Not Include Valve .	20023	35	4	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Service Pack; W/43mm Silver Insert ....	20037	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Service Pack; W/48mm Green Insert ...	20038	35	4	Sensor .....	28385	27	3
Service Pack; W/49mm Black Insert .....	20039	35	4	Sensor Clip .....	22100		
Service Pack; W/51mm Orange Insert .	20040	35	4	Sensor Cradle .....	22101		
<b>1999</b>				Sensor Universal Band .....	22102		
<b>E55</b>				<b>Mariner</b>			
Service Pack; Does Not Include Valve;				EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Jul. & Newer .....	20023	35	4	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Service Pack; W/43mm Silver Insert; Jul.				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
& Newer .....	20037	35	4	Sensor .....	20315	13	1.5
Service Pack; W/48mm Green Insert; Jul.				Service Pack .....	20018	11.5	1.3
& Newer .....	20038	35	4	<b>Milan; Mountaineer</b>			
Service Pack; W/49mm Black Insert; Jul.				EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
& Newer .....	20039	35	4	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Service Pack; W/51mm Orange Insert;				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Jul. & Newer .....	20040	35	4	Sensor .....	28385	27	3
<b>► Mercury</b>				Sensor Clip .....	22100		
<b>2011</b>				Sensor Cradle .....	22101		
<b>Grand Marquis</b>				Sensor Universal Band .....	22102		
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	<b>Sable</b>			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor .....	20315	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor Clip .....	22100			Sensor .....	28385	27	3
Sensor Cradle .....	22101			Sensor Clip .....	22100		
Sensor Universal Band .....	22102			Sensor Cradle .....	22101		
<b>Mariner; Milan</b>				Sensor Universal Band .....	22102		
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	<b>2008</b>			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>Grand Marquis; Mariner; Milan; Mountaineer</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Sensor .....	20315	13	1.5	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Service Pack .....	20018	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
				Sensor .....	28385	27	3
				Sensor Clip .....	22100		
				Sensor Cradle .....	22101		
				Sensor Universal Band .....	22102		
				<b>Sable</b>			
				EZ-sensor - 315 MHz .....	◇33000	11.5	1.3

◇ Programming Tool Required.



## Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
<b>► Mercury - Continued</b>				<b>► Mercury - Continued</b>			
<b>2008 - Continued</b>				<b>2005 - Continued</b>			
<b>Sable - Continued</b>				<b>Mariner - Continued</b>			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor Cradle .....	22101		
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor Universal Band .....	22102		
Sensor .....	28390	27	3	<b>Monterey Van</b>			
Sensor Clip .....	22100			Sensor .....	●20135	44	5
Sensor Cradle .....	22101			Service Pack .....	20002	44	5
Sensor Universal Band .....	22102			<b>Mountaineer</b>			
<b>2007</b>				<b>2004</b>			
<b>Grand Marquis; Mariner; Milan</b>				<b>Monterey Van</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Sensor .....	●20135	44	5
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Service Pack .....	20002	44	5
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	<b>Mountaineer</b>			
Sensor .....	28385	27	3	EZ-sensor - 433 MHz .....	◇33100	11.5	1.3
Sensor Clip .....	22100			EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor Cradle .....	22101			EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor Universal Band .....	22102			Sensor .....	●20096	44	5
<b>Montego</b>				<b>Service Pack .....</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3		20002	44	5
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>2003-2002</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	<b>Mountaineer</b>			
Sensor .....	28390	27	3	EZ-sensor - 433 MHz .....	◇33100	11.5	1.3
Sensor Clip .....	22100			EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor Cradle .....	22101			EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor Universal Band .....	22102			Sensor .....	●20096	44	5
<b>Monterey Van; Mountaineer</b>				<b>Service Pack .....</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3		20002	44	5
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>2002</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	<b>Mountaineer</b>			
Sensor .....	28385	27	3	EZ-sensor - 433 MHz .....	◇33100	11.5	1.3
Sensor Clip .....	22100			EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor Cradle .....	22101			EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor Universal Band .....	22102			Sensor .....	●20096	44	5
<b>2006</b>				<b>Service Pack .....</b>			
					20002	44	5
<b>Grand Marquis; Mariner</b>				<b>► Mini</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	<b>2012</b>			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>Cooper</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; Includes Transmitter Only .....			
Sensor .....	28385	27	3	Service Pack; Does Not Include Valve .			
Sensor Clip .....	22100			Service Pack; W/43mm Silver Insert ....			
Sensor Cradle .....	22101			Service Pack; W/48mm Green Insert ...			
Sensor Universal Band .....	22102			Service Pack; W/49mm Black Insert .....			
<b>Montego</b>				Service Pack; W/51mm Orange Insert .			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	<b>2011</b>			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>Cooper</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; Includes Transmitter Only .....			
Sensor .....	28390	27	3	Service Pack; W/43mm Silver Insert ....			
Sensor Clip .....	22100			Service Pack; W/48mm Green Insert ...			
Sensor Cradle .....	22101			Service Pack; W/49mm Black Insert .....			
Sensor Universal Band .....	22102			Service Pack; W/51mm Orange Insert .			
<b>Monterey Van; Mountaineer</b>				<b>2010</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	<b>Cooper</b>			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor; Includes Transmitter Only .....			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack; Does Not Include Valve .			
Sensor .....	28385	27	3	Service Pack; W/43mm Silver Insert ....			
Sensor Clip .....	22100			Service Pack; W/48mm Green Insert ...			
Sensor Cradle .....	22101			Service Pack; W/49mm Black Insert .....			
Sensor Universal Band .....	22102			Service Pack; W/51mm Orange Insert .			
<b>2005</b>				<b>2009-2008</b>			
<b>Mariner</b>				<b>Cooper</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Sensor; Includes Transmitter Only .....			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Service Pack; Does Not Include Valve .			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack; W/43mm Silver Insert ....			
Sensor; Oct. 3, 2005 & Newer .....	28385	27	3	Service Pack; W/48mm Green Insert ...			
Sensor Clip .....	22100			Service Pack; W/49mm Black Insert .....			
				Service Pack; W/51mm Orange Insert .			

◇ Programming Tool Required.  
● Magnet Required to Activate Sensor.

## Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
<b>► Mitsubishi</b>				<b>► Mitsubishi - Continued</b>			
<b>2013</b>				<b>2011 - Continued</b>			
<b>Lancer</b>				<b>Outlander</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; W/Alloy Wheels .....	20398	11.5	1.3
Sensor; W/Alloy Wheels .....	20398	11.5	1.3	Sensor; W/Steel Wheels .....	28096	71	8
Sensor; W/Steel Wheels .....	28096	71	8	Service Pack; W/Alloy Wheels .....	20008	11.5	1.3
Service Pack; W/Alloy Wheels .....	20008	11.5	1.3	Service Pack; W/Steel Wheels .....	20030	71	8
Service Pack; W/Steel Wheels .....	20030	71	8	Service Pack; Rubber Valve .....	20008	11.5	1.3
<b>Outlander</b>				<b>2010</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	<b>Eclipse; Endeavor</b>			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Sensor; W/Alloy Wheels .....	20398	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor; W/Steel Wheels .....	28096	71	8	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Service Pack; W/Alloy Wheels .....	20008	11.5	1.3	Sensor .....	●20034	45-53	5-6
Service Pack; W/Steel Wheels .....	20030	71	8	Service Pack .....	20003	45-53	5-6
Service Pack; Rubber Valve .....	20008	11.5	1.3	<b>Galant</b>			
<b>2012</b>				<b>Lancer; Outlander</b>			
<b>Eclipse</b>				EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Sensor; W/Steel Wheels .....	28129	45-53	5-6	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Service Pack .....	20003	45-53	5-6	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
<b>Galant</b>				Sensor; W/Alloy Wheels .....	20034	49	5.5
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Sensor; W/Steel Wheels .....	28129	45-53	5-6
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>Lancer</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Sensor; W/Alloy Wheels .....	20034	49	5.5	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor; W/Steel Wheels .....	28129	45-53	5-6	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
<b>Lancer</b>				Sensor .....	28096	71	8
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Service Pack .....	20030	71	8
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>2009</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	<b>Eclipse</b>			
Sensor; W/Alloy Wheels .....	20398	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Sensor; W/Steel Wheels .....	28096	71	8	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Service Pack; W/Alloy Wheels .....	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Service Pack; W/Steel Wheels .....	20030	71	8	Sensor .....	●20034	45-53	5-6
<b>Outlander</b>				Service Pack .....	20003	45-53	5-6
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	<b>Galant</b>			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Sensor; W/Alloy Wheels .....	20398	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor; W/Steel Wheels .....	28096	71	8	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Service Pack; W/Alloy Wheels .....	20008	11.5	1.3	Sensor; W/Alloy Wheels .....	●20034	45-53	5-6
Service Pack; W/Steel Wheels .....	20030	71	8	Sensor; W/Steel Wheels .....	28129	45-53	5-6
<b>2011</b>				Service Pack; W/Alloy Wheels .....	20003	45-53	5-6
<b>Eclipse; Endeavor</b>				Service Pack; W/Steel Wheels .....	20010	45-53	5-6
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	<b>Lancer; Outlander</b>			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor .....	20034	49	5.5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Service Pack .....	20003	45-53	5-6	Sensor .....	28096	71	8
<b>Galant</b>				Service Pack .....	20030	71	8
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	<b>Raider</b>			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor; W/Alloy Wheels .....	20034	49	5.5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor; W/Steel Wheels .....	28129	45-53	5-6	Sensor .....	28154	58	6.5
Service Pack; W/Alloy Wheels .....	20003	45-53	5-6	or	28461	11.5	1.3
Service Pack; W/Steel Wheels .....	20010	45-53	5-6	Service Pack; Includes Stem Only .....	20020	58	6.5
<b>Lancer</b>				Service Pack; Does Not Include Stem ..	20013	58	6.5
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	<b>2008</b>			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>Eclipse; Endeavor</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Sensor; W/Alloy Wheels .....	20398	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor; W/Steel Wheels .....	28096	71	8	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Service Pack; W/Alloy Wheels .....	20008	11.5	1.3	Sensor .....	●20034	45-53	5-6
Service Pack; W/Steel Wheels .....	20030	71	8				

◇ Programming Tool Required.  
● Magnet Required to Activate Sensor.

## Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
<b>► Mitsubishi - Continued</b>				<b>► Mitsubishi - Continued</b>			
<b>2008 - Continued</b>				<b>2006 - Continued</b>			
<b>Eclipse; Endeavor - Continued</b>				<b>Endeavor</b>			
Service Pack .....	20003	45-53	5-6	EZ-sensor - 315 MHz; Sept. 1 & Newer	◇33000	11.5	1.3
<b>Galant</b>				EZ-sensor - 433 MHz; Aug. & Older .....	◇33100	11.5	1.3
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; Sept. 1 & Newer .....	●20034	45-53	5-6
Sensor; W/Alloy Wheels .....	●20034	45-53	5-6	Sensor; Aug. & Older .....	●20028	45-53	5-6
Sensor; W/Steel Wheels .....	28129	45-53	5-6	Service Pack .....	20003	45-53	5-6
Service Pack; W/Alloy Wheels .....	20003	45-53	5-6	<b>Galant</b>			
Service Pack; W/Steel Wheels .....	20010	45-53	5-6	EZ-sensor - 433 MHz .....	◇33100	11.5	1.3
<b>Lancer; Outlander</b>				EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor .....	●20028	45-53	5-6
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack .....	20003	45-53	5-6
Sensor .....	28096	71	8	<b>Montero</b>			
Service Pack .....	20030	71	8	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
<b>Raider</b>				EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor .....	●20034	45-53	5-6
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack .....	20003	45-53	5-6
Sensor .....	28154	58	6.5	<b>2005-2004</b>			
or	28461	11.5	1.3	<b>Endeavor; Galant</b>			
Service Pack; Includes Stem Only .....	20020	58	6.5	EZ-sensor - 433 MHz .....	◇33100	11.5	1.3
Service Pack; Does Not Include Stem ..	20013	58	6.5	EZ-sensor Service Pack; Almm. Valve	34000	62	7
<b>2007</b>				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
<b>Eclipse</b>				Sensor .....	●20028	45-53	5-6
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Service Pack .....	20003	45-53	5-6
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>Montero</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Sensor; W/Alloy Wheels .....	●20034	45-53	5-6	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor; W/Steel Wheels .....	28129	45-53	5-6	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Service Pack; W/Alloy Wheels .....	20003	45-53	5-6	Sensor .....	●20034	45-53	5-6
Service Pack; W/Steel Wheels .....	20010	45-53	5-6	Service Pack .....	20003	45-53	5-6
<b>Endeavor</b>				<b>2003</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	<b>Montero</b>			
EZ-sensor - 433 MHz .....	◇33100	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor .....	●20028	45-53	5-6	Sensor .....	●20034	45-53	5-6
Service Pack .....	20003	45-53	5-6	Service Pack .....	20003	45-53	5-6
<b>Galant</b>				<b>► Nissan</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	<b>2013</b>			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>Armada; Cube; Frontier; GT-R</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Sensor; W/Alloy Wheels .....	●20034	45-53	5-6	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor; W/Steel Wheels .....	28129	45-53	5-6	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Service Pack; W/Alloy Wheels .....	20003	45-53	5-6	Sensor .....	28204	49	5.5
Service Pack; W/Steel Wheels .....	20010	45-53	5-6	Service Pack .....	20014	71	8
<b>Outlander</b>				<b>NV</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Sensor .....	28342	68	7.7
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Service Pack .....	20014	71	8
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	<b>Sentra; Titan; Xterra</b>			
Sensor .....	28096	71	8	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Service Pack .....	20030	71	8	EZ-sensor Service Pack; Almm. Valve	34000	62	7
<b>2006</b>				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
<b>Eclipse</b>				Sensor .....	28204	49	5.5
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Service Pack .....	20014	71	8
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>2012</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	<b>Altima</b>			
Sensor; W/Alloy Wheels .....	●20034	45-53	5-6	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Sensor; W/Steel Wheels .....	28129	45-53	5-6	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Service Pack; W/Alloy Wheels .....	20003	45-53	5-6	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Service Pack; W/Steel Wheels .....	20010	45-53	5-6				

◇ Programming Tool Required.  
● Magnet Required to Activate Sensor.

## Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
<b>► Nissan - Continued</b>				<b>► Nissan - Continued</b>			
<b>2012 - Continued</b>				<b>2011 - Continued</b>			
<b>Altima - Continued</b>				<b>Juke - Continued</b>			
Sensor .....	28204	66	7.5	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Service Pack .....	20014	71	8	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
<b>Armada; Cube; Frontier; GT-R; Juke; Maxima; Murano</b>				Sensor .....	28204	49	5.5
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Service Pack .....	20014	49	5.5
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>Maxima</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Sensor .....	28204	49	5.5	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Service Pack .....	20014	71	8	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
<b>NV</b>				Sensor .....	28204	49	5.5
Sensor .....	28342	68	7.7	Service Pack .....	20014	71	8
Service Pack .....	20014	71	8	<b>Murano</b>			
<b>Pathfinder; Rogue</b>				EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor .....	28204	49	5.5
Sensor .....	28204	49	5.5	Service Pack .....	20014	49	5.5
Service Pack .....	20014	71	8	<b>NV</b>			
<b>Sentra</b>				Sensor .....	28342	68	7.7
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	<b>Pathfinder; Rogue</b>			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor .....	28204	66	7.5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Service Pack .....	20014	71	8	Sensor .....	28204	49	5.5
<b>Titan; Versa; Xterra</b>				Service Pack .....	20014	49	5.5
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	<b>Sentra</b>			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor .....	28204	49	5.5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Service Pack .....	20014	71	8	Sensor .....	28204	49	5.5
<b>2011</b>				Service Pack .....	20014	71	8
<b>Altima</b>				<b>Titan</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor .....	28204	49	5.5	Sensor .....	28204	49	5.5
Service Pack .....	20014	71	8	Service Pack .....	20014	49	5.5
<b>Armada</b>				<b>Versa</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor .....	28204	49	5.5	Sensor .....	28204	49	5.5
Service Pack .....	20014	49	5.5	Service Pack .....	20014	71	8
<b>Cube</b>				<b>Xterra</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor .....	28204	49	5.5	Sensor .....	28204	49	5.5
Service Pack .....	20014	71	8	Service Pack .....	20014	49	5.5
<b>Frontier</b>				<b>2010</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	<b>370Z</b>			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor .....	28204	49	5.5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Service Pack .....	20014	49	5.5	Sensor .....	28210	71	8
<b>GT-R</b>				Service Pack .....	20014	71	8
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	<b>Altima</b>			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor .....	28204	49	5.5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Service Pack .....	20014	71	8	Sensor .....	28204	71	8
<b>Juke</b>				Service Pack .....	20014	71	8
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3				

◇ Programming Tool Required.



## Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
<b>► Nissan - Continued</b>				<b>► Nissan - Continued</b>			
<b>2010 - Continued</b>				<b>2009 - Continued</b>			
<b>Armada; Frontier</b>				<b>Altima - Continued</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor .....	28204	71	8
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack .....	20014	71	8
Sensor .....	28204	49	5.5	<b>Armada</b>			
Service Pack .....	20014	49	5.5	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
<b>Maxima</b>				EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor .....	28204	49	5.5
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack .....	20014	49	5.5
Sensor .....	28204	68	7.7	<b>Cube</b>			
Service Pack .....	20014	68	7.7	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
<b>Murano</b>				EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor .....	28204	71	8
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack .....	20014	71	8
Sensor .....	28204	35	4	<b>Frontier</b>			
Service Pack .....	20014	49	5.5	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
<b>Pathfinder</b>				EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor .....	28204	49	5.5
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack .....	20014	49	5.5
Sensor .....	28204	49	5.5	<b>GT-R</b>			
Service Pack .....	20014	49	5.5	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
<b>Sentra</b>				EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor .....	28204	71	8
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack .....	20014	71	8
Sensor .....	28204	68	7.7	<b>Maxima; Murano</b>			
Service Pack .....	20014	68	7.7	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
<b>Titan</b>				EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor .....	28204	68	7.7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack .....	20014	68	7.7
Sensor .....	28204	49	5.5	<b>Pathfinder; Quest</b>			
Service Pack .....	20014	49	5.5	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
<b>Versa</b>				EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor .....	28204	49	5.5
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack .....	20014	49	5.5
Sensor .....	28204	71	8	<b>Rogue; Sentra</b>			
Service Pack .....	20014	71	8	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
<b>Xterra</b>				EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor .....	28204	68	7.7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack .....	20014	68	7.7
Sensor .....	28204	49	5.5	<b>Titan</b>			
Service Pack .....	20014	49	5.5	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
<b>2009</b>				EZ-sensor Service Pack; Almm. Valve	34000	62	7
<b>350Z</b>				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Sensor .....	28204	49	5.5
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Service Pack .....	20014	49	5.5
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	<b>Versa</b>			
Sensor .....	28204	71	8	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Service Pack .....	20014	71	8	EZ-sensor Service Pack; Almm. Valve	34000	62	7
<b>370Z</b>				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Sensor .....	28204	71	8
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Service Pack .....	20014	71	8
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	<b>Xterra</b>			
Sensor .....	28210	71	8	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Service Pack .....	20014	71	8	EZ-sensor Service Pack; Almm. Valve	34000	62	7
<b>Altima</b>				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Sensor .....	28204	49	5.5
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Service Pack .....	20014	49	5.5

◇ Programming Tool Required.

## Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
<b>► Nissan - Continued</b>				<b>► Nissan - Continued</b>			
<b>2008</b>				<b>2007</b>			
<b>350Z; Altima</b>				<b>350Z; Altima</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor .....	28204	71	8	Sensor .....	28204	71	8
Service Pack .....	20014	71	8	Service Pack .....	20014	71	8
<b>Armada</b>				<b>Armada</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor; LE .....	28204	49	5.5	Sensor .....	20161	49	5.5
Sensor; SE .....	20161	49	5.5	Service Pack .....	20007	49	5.5
Service Pack; LE .....	20014	49	5.5				
Service Pack; SE .....	20007	49	5.5				
<b>Frontier</b>				<b>Frontier</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor; W/Alloy Wheels .....	20161	49	5.5	Sensor; W/Alloy Wheels .....	20161	49	5.5
Sensor; W/Steel Wheels .....	28204	49	5.5	Sensor; W/Steel Wheels .....	20069	49	5.5
Service Pack; W/Alloy Wheels .....	20007	49	5.5	Service Pack; W/Alloy Wheels .....	20007	49	5.5
Service Pack; W/Steel Wheels .....	20014	49	5.5	Service Pack; W/Steel Wheels .....	20005	49	5.5
<b>Maxima</b>				<b>Maxima</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor; Apr. 1 & Newer .....	28204	68	7.7	Sensor; Apr. 1 & Newer .....	28204	68	7.7
Sensor; Mar. & Older .....	20161	49	5.5	Sensor; Mar. & Older .....	20161	49	5.5
Service Pack; Apr. 1 & Newer .....	20014	68	7.7	Service Pack; Apr. 1 & Newer .....	20014	68	7.7
Service Pack; Mar. & Older .....	20014	68	7.7	Service Pack; Mar. & Older .....	20007	49	5.5
<b>Pathfinder; Quest</b>				<b>Murano</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor .....	28204	49	5.5	Sensor .....	28204	71	8
Service Pack .....	20014	49	5.5	Service Pack .....	20014	71	8
<b>Rogue</b>				<b>Pathfinder</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor .....	28204	68	7.7	Sensor; OEM Part No. 40700JA01A ....	28167	49	5.5
Service Pack .....	20014	68	7.7	Sensor; OEM Part No. 40700JA01B ....	28204	49	5.5
<b>Sentra</b>				<b>Service Pack .....</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor .....	28204	71	8	Sensor .....	28204	49	5.5
Service Pack .....	20014	71	8	Service Pack .....	20014	49	5.5
<b>Titan</b>				<b>Quest</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor .....	28204	49	5.5	Sensor .....	28204	49	5.5
Service Pack .....	20014	49	5.5	Service Pack .....	20014	49	5.5
<b>Versa</b>				<b>Sentra</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor .....	28204	71	8	Sensor; W/Alloy Wheels .....	20161	78	8.8
Service Pack .....	20014	71	8	Sensor; W/Steel Wheels .....	28204	71	8
<b>Xterra</b>				<b>Service Pack; W/Alloy Wheels .....</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Service Pack; W/Alloy Wheels .....	20007	78	8.8
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Service Pack; W/Steel Wheels .....	20014	71	8
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor .....	28204	49	5.5	<b>Titan</b>			
Service Pack .....	20014	49	5.5	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
				EZ-sensor Service Pack; Almm. Valve	34000	62	7
				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
				Sensor; Apr. 1 & Newer .....	28204	49	5.5
				Sensor; Mar. & Older .....	20161	49	5.5
				Service Pack; Apr. 1 & Newer .....	20014	49	5.5
				Service Pack; Mar. & Older .....	20007	49	5.5
				<b>Versa</b>			
				EZ-sensor - 315 MHz .....	◇33000	11.5	1.3

◇ Programming Tool Required.

## Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
<b>► Nissan - Continued</b>				<b>► Nissan - Continued</b>			
<b>2007 - Continued</b>				<b>2006 - Continued</b>			
<b>Versa - Continued</b>				<b>Titan - Continued</b>			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor .....	20161	49	5.5
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack .....	20007	49	5.5
Sensor; OEM Part No. 40700JA01A ....	28167	71	8	<b>Xterra</b>			
Sensor; OEM Part No. 40700JA01B ....	28204	71	8	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Service Pack .....	20014	71	8	EZ-sensor Service Pack; Almm. Valve	34000	62	7
<b>Xterra</b>				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Sensor; Submodel X .....	20069	49	5.5
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor; Exc. Submodel X .....	20161	49	5.5
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack; Submodel X .....	20005	49	5.5
Sensor; OEM Part No. 40700JA01A ....	28167	49	5.5	Service Pack; Exc. Submodel X .....	20007	49	5.5
Sensor; OEM Part No. 40700JA01B ....	28204	49	5.5	<b>2005</b>			
Service Pack .....	20014	49	5.5	<b>350Z</b>			
<b>2006</b>				EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
<b>350Z</b>				EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor .....	20064	49	5.5
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack .....	20007	49	5.5
Sensor .....	20064	49	5.5	<b>Armada; Frontier</b>			
Service Pack .....	20007	49	5.5	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
<b>Altima</b>				EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor; W/Alloy Wheels .....	20161	49	5.5
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; W/Steel Wheels .....	20069	49	5.5
Sensor; Oct. 1 & Newer .....	28204	71	8	Service Pack; W/Alloy Wheels .....	20007	49	5.5
Service Pack; Oct. 1 & Newer .....	20014	71	8	Service Pack; W/Steel Wheels .....	20005	49	5.5
<b>Armada; Frontier</b>				<b>Murano</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor; W/Alloy Wheels .....	20161	49	5.5	Sensor .....	20064	66	7.5
Sensor; W/Steel Wheels .....	20069	49	5.5	Service Pack .....	20007	66	7.5
Service Pack; W/Alloy Wheels .....	20007	49	5.5	<b>Pathfinder</b>			
Service Pack; W/Steel Wheels .....	20005	49	5.5	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
<b>Maxima</b>				EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor .....	20161	49	5.5
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack .....	20007	49	5.5
Sensor; Jun. & Newer .....	20161	49	5.5	<b>Quest</b>			
Service Pack; Jun. & Newer .....	20007	49	5.5	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
<b>Murano</b>				EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor; W/Alloy Wheels .....	20161	78	8.8
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; W/Steel Wheels .....	20069	78	8.8
Sensor .....	20064	66	7.5	Service Pack; W/Alloy Wheels .....	20007	78	8.8
Service Pack .....	20007	66	7.5	Service Pack; W/Steel Wheels .....	20005	78	8.8
<b>Pathfinder</b>				<b>Titan</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor .....	20161	49	5.5	Sensor; Apr. 1 & Newer .....	20161	49	5.5
Service Pack .....	20007	49	5.5	Sensor; Mar. & Older .....	20069	49	5.5
<b>Quest</b>				Service Pack; Apr. 1 & Newer .....	20007	49	5.5
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Service Pack; Mar. & Older .....	20005	49	5.5
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>Xterra</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Sensor; W/Alloy Wheels .....	20161	78	8.8	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor; W/Steel Wheels .....	20069	78	8.8	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Service Pack; W/Alloy Wheels .....	20007	78	8.8	Sensor .....	20161	36-60	4.1-6.8
Service Pack; W/Steel Wheels .....	20005	78	8.8	Service Pack .....	20007	36-60	4.1-6.8
<b>Titan</b>				<b>2004</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	<b>350Z</b>			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7

◇ Programming Tool Required.

## Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
<b>► Nissan - Continued</b>				<b>► Nissan - Continued</b>			
<b>2004 - Continued</b>				<b>2003 - Continued</b>			
<b>350Z - Continued</b>				<b>Pathfinder</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Sensor .....	20064	49	5.5	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Service Pack .....	20007	49	5.5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
<b>Frontier</b>				Sensor .....	20064	49	5.5
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Service Pack .....	20007	49	5.5
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>Xterra</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Sensor .....	20064	36-60	4.1-6.8	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Service Pack .....	20007	36-60	4.1-6.8	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
<b>Murano</b>				Sensor .....	20064	36-60	4.1-6.8
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Service Pack .....	20007	36-60	4.1-6.8
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>► Plymouth</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	<b>2001-1999</b>			
Sensor .....	20064	66	7.5	<b>Prowler</b>			
Service Pack .....	20007	66	7.5	Sensor .....	28004	35	4
<b>Pathfinder</b>				Service Pack; W/Black Sensor Body ....	20012	35	4
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Service Pack; W/Red Sensor Body .....	20003	35	4
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>1997</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	<b>Prowler</b>			
Sensor; Armada .....	20069	49	5.5	Sensor .....	28004	35	4
Sensor; Exc. Armada; Aug. & Newer ....	20069	49	5.5	Service Pack; W/Black Sensor Body ....	20012	35	4
Sensor; Exc. Armada; Jul. & Older .....	20064	49	5.5	Service Pack; W/Red Sensor Body .....	20003	35	4
Service Pack; Armada .....	20005	49	5.5	<b>► Pontiac</b>			
Service Pack; Exc. Armada; Aug. & Newer .....	20005	49	5.5	<b>2010</b>			
Service Pack; Exc. Armada; Jul. & Older	20007	49	5.5	<b>G3; G5; G6; G8</b>			
<b>Quest</b>				EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor .....	20153	11.5	1.3
Sensor .....	20069	78	8.8	Service Pack .....	20008	11.5	1.3
Service Pack .....	20005	78	8.8	<b>Solstice</b>			
<b>Titan</b>				EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor .....	20158	62	7
Sensor .....	20069	49	5.5	Service Pack; W/Schrader Sensor .....	20004	62	7
Service Pack .....	20005	49	5.5	Service Pack; W/Siemens Sensor .....	20030	80	9
<b>Xterra</b>				<b>Vibe</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor .....	20064	36-60	4.1-6.8	Sensor .....	28360	35	4
Service Pack .....	20007	36-60	4.1-6.8	Service Pack .....	20032	35	4
<b>2003</b>				<b>2009</b>			
<b>350Z</b>				<b>G3; G3 Wave; G5; G6; G8</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor .....	20064	49	5.5	Sensor .....	20153	11.5	1.3
Service Pack .....	20007	49	5.5	Service Pack .....	20008	11.5	1.3
<b>Frontier</b>				<b>Montana; Solstice; Torrent</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor .....	20064	36-60	4.1-6.8	Sensor .....	20158	62	7
Service Pack .....	20007	36-60	4.1-6.8	Service Pack; W/Schrader Sensor .....	20004	62	7
<b>Murano</b>				Service Pack; W/Siemens Sensor .....	20030	80	9
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	<b>Vibe</b>			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor .....	20064	66	7.5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Service Pack .....	20007	66	7.5	Sensor .....	28360	35	4
				Service Pack .....	20032	35	4

◇ Programming Tool Required.



## Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
<b>► Pontiac - Continued</b>				<b>► Porsche</b>			
<b>2009 - Continued</b>				<b>2012</b>			
<b>Vibe - Continued</b>				<b>Cayenne</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; Includes Transmitter Only .....	20103	35	4
Sensor .....	28360	35	4	Service Pack; W/43mm Silver Insert ....	20037	35	4
Service Pack .....	20032	35	4	Service Pack; W/48mm Green Insert ...	20038	35	4
<b>Wave</b>				Service Pack; W/49mm Black Insert .....	20039	35	4
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Service Pack; W/51mm Orange Insert .	20040	35	4
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>2011</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	<b>911; Boxster</b>			
Sensor .....	20153	11.5	1.3	Sensor; Includes Transmitter Only .....	20077	35	4
Service Pack .....	20008	11.5	1.3	Service Pack; Does Not Include Valve .	20023	35	4
<b>2008</b>				Service Pack; W/43mm Silver Insert ....	20037	35	4
<b>G5; G6</b>				Service Pack; W/48mm Green Insert ...	20038	35	4
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Service Pack; W/49mm Black Insert .....	20039	35	4
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Service Pack; W/51mm Orange Insert .	20040	35	4
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	<b>Cayenne</b>			
Sensor .....	20158	62	7	Sensor; Includes Transmitter Only .....	20103	35	4
Service Pack; W/Schrader Sensor .....	20004	62	7	Service Pack; W/43mm Silver Insert ....	20037	35	4
Service Pack; W/Siemens Sensor .....	20030	80	9	Service Pack; W/48mm Green Insert ...	20038	35	4
<b>G8</b>				Service Pack; W/49mm Black Insert .....	20039	35	4
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Service Pack; W/51mm Orange Insert .	20040	35	4
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>Cayman</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; Includes Transmitter Only .....	20077	35	4
Sensor .....	20153	62	7	Service Pack; Does Not Include Valve .	20023	35	4
Service Pack .....	20008	62	7	Service Pack; W/43mm Silver Insert ....	20037	35	4
<b>Grand Prix</b>				Service Pack; W/48mm Green Insert ...	20038	35	4
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Service Pack; W/49mm Black Insert .....	20039	35	4
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Service Pack; W/51mm Orange Insert .	20040	35	4
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	<b>Panamera</b>			
Sensor; Clamp-In Style Only; W/Almm. Valve Stem .....	20158	62	7	Sensor; Includes Transmitter Only .....	28087	31-40	3.5-4.5
Sensor; Snap-In Style Only; W/Rubber Valve Stem .....	20153	11.5	1.3	Service Pack; W/43mm Silver Insert ....	20037	31-40	3.5-4.5
Service Pack; Clamp-In Style Only; W/Almm. Valve Stem .....	20004	62	7	Service Pack; W/48mm Green Insert ...	20038	31-40	3.5-4.5
Service Pack; Snap-In Style Only; W/Rubber Valve Stem .....	20008	11.5	1.3	Service Pack; W/49mm Black Insert .....	20039	31-40	3.5-4.5
<b>Montana; Solstice; Torrent</b>				Service Pack; W/51mm Orange Insert .	20040	31-40	3.5-4.5
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	<b>2010</b>			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>911; Boxster</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; Includes Transmitter Only .....	28087	31-40	3.5-4.5
Sensor .....	20158	62	7	Service Pack; Does Not Include Valve .	20023	31-40	3.5-4.5
Service Pack; W/Schrader Sensor .....	20004	62	7	Service Pack; W/43mm Silver Insert ....	20037	31-40	3.5-4.5
Service Pack; W/Siemens Sensor .....	20030	80	9	Service Pack; W/48mm Green Insert ...	20038	31-40	3.5-4.5
<b>Vibe</b>				Service Pack; W/49mm Black Insert .....	20039	31-40	3.5-4.5
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Service Pack; W/51mm Orange Insert .	20040	31-40	3.5-4.5
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>Cayenne</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack; Does Not Include Valve .	20023	31-40	3.5-4.5
Sensor .....	28360	35	4	Service Pack; W/43mm Silver Insert ....	20037	31-40	3.5-4.5
Service Pack .....	20032	35	4	Service Pack; W/48mm Green Insert ...	20038	31-40	3.5-4.5
<b>Wave</b>				Service Pack; W/49mm Black Insert .....	20039	31-40	3.5-4.5
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Service Pack; W/51mm Orange Insert .	20040	31-40	3.5-4.5
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>Cayman; Panamera</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; Includes Transmitter Only .....	28087	31-40	3.5-4.5
Sensor .....	20153	11.5	1.3	Service Pack; Does Not Include Valve .	20023	31-40	3.5-4.5
Service Pack .....	20008	11.5	1.3	Service Pack; W/43mm Silver Insert ....	20037	31-40	3.5-4.5
<b>2007</b>				Service Pack; W/48mm Green Insert ...	20038	31-40	3.5-4.5
<b>Grand Prix; Torrent</b>				Service Pack; W/49mm Black Insert .....	20039	31-40	3.5-4.5
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Service Pack; W/51mm Orange Insert .	20040	31-40	3.5-4.5
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>2009</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	<b>911; Boxster; Cayenne</b>			
Sensor .....	20158	62	7	Service Pack; Does Not Include Valve .	20023	31-40	3.5-4.5
Service Pack; W/Schrader Sensor .....	20004	62	7	Service Pack; W/43mm Silver Insert ....	20037	31-40	3.5-4.5
Service Pack; W/Siemens Sensor .....	20030	80	9	Service Pack; W/48mm Green Insert ...	20038	31-40	3.5-4.5
				Service Pack; W/49mm Black Insert .....	20039	31-40	3.5-4.5
				Service Pack; W/51mm Orange Insert .	20040	31-40	3.5-4.5
				<b>Cayman</b>			
				Sensor; Includes Transmitter Only .....	28087	31-40	3.5-4.5

◇ Programming Tool Required.

## Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
<b>► Porsche - Continued</b>				<b>► Saab - Continued</b>			
<b>2009 - Continued</b>				<b>2012-2011 - Continued</b>			
<b>Cayman - Continued</b>				<b>9-3 - Continued</b>			
Service Pack; Does Not Include Valve .	20023	31-40	3.5-4.5	Service Pack .....	20009	88	10
Service Pack; W/43mm Silver Insert ....	20037	31-40	3.5-4.5	<b>9-4X</b>			
Service Pack; W/48mm Green Insert ...	20038	31-40	3.5-4.5	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Service Pack; W/49mm Black Insert .....	20039	31-40	3.5-4.5	Sensor .....	28206	11.5	1.3
Service Pack; W/51mm Orange Insert .	20040	31-40	3.5-4.5	Service Pack .....	20008	11.5	1.3
<b>2008</b>				<b>9-5</b>			
<b>911; Boxster; Cayenne; Cayman</b>				Sensor .....			
Service Pack; Does Not Include Valve .	20023	31-40	3.5-4.5	Service Pack .....	20159	88	10
Service Pack; W/43mm Silver Insert ....	20037	31-40	3.5-4.5	Service Pack .....	20009	88	10
Service Pack; W/48mm Green Insert ...	20038	31-40	3.5-4.5	<b>2010</b>			
Service Pack; W/49mm Black Insert .....	20039	31-40	3.5-4.5	<b>9-3; 9-5</b>			
Service Pack; W/51mm Orange Insert .	20040	31-40	3.5-4.5	Sensor .....	20159	88	10
<b>2007</b>				Service Pack .....			
<b>911; Boxster; Cayman</b>				Service Pack .....			
Service Pack; Does Not Include Valve .	20023	31-40	3.5-4.5	<b>2009-2008</b>			
Service Pack; W/43mm Silver Insert ....	20037	31-40	3.5-4.5	<b>9-3; 9-5</b>			
Service Pack; W/48mm Green Insert ...	20038	31-40	3.5-4.5	Sensor .....	20159	88	10
Service Pack; W/49mm Black Insert .....	20039	31-40	3.5-4.5	Service Pack .....	20009	88	10
Service Pack; W/51mm Orange Insert .	20040	31-40	3.5-4.5	<b>9-7X</b>			
<b>2006</b>				Sensor .....			
<b>911; Boxster; Carrera GT; Cayenne; Cayman</b>				Service Pack .....			
Service Pack; Does Not Include Valve .	20023	31-40	3.5-4.5	<b>2007-2005</b>			
Service Pack; W/43mm Silver Insert ....	20037	31-40	3.5-4.5	<b>9-3; 9-5</b>			
Service Pack; W/48mm Green Insert ...	20038	31-40	3.5-4.5	Sensor .....	28078	62	7
Service Pack; W/49mm Black Insert .....	20039	31-40	3.5-4.5	Service Pack .....	20009	62	7
Service Pack; W/51mm Orange Insert .	20040	31-40	3.5-4.5	<b>9-7X</b>			
<b>2005</b>				Sensor .....			
<b>911; Boxster; Carrera GT; Cayenne</b>				Service Pack .....			
Service Pack; Does Not Include Valve .	20023	31-40	3.5-4.5	<b>2004-2003</b>			
Service Pack; W/43mm Silver Insert ....	20037	31-40	3.5-4.5	<b>9-3; 9-5</b>			
Service Pack; W/48mm Green Insert ...	20038	31-40	3.5-4.5	Sensor .....	28078	62	7
Service Pack; W/49mm Black Insert .....	20039	31-40	3.5-4.5	Service Pack .....	20009	62	7
Service Pack; W/51mm Orange Insert .	20040	31-40	3.5-4.5	<b>► Saturn</b>			
<b>2004</b>				<b>2010-2009</b>			
<b>Carrera GT; Cayenne</b>				<b>Astra</b>			
Service Pack; Does Not Include Valve .	20023	31-40	3.5-4.5	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Service Pack; W/43mm Silver Insert ....	20037	31-40	3.5-4.5	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Service Pack; W/48mm Green Insert ...	20038	31-40	3.5-4.5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Service Pack; W/49mm Black Insert .....	20039	31-40	3.5-4.5	Sensor .....	28206	11.5	1.3
Service Pack; W/51mm Orange Insert .	20040	31-40	3.5-4.5	Service Pack .....	20008	11.5	1.3
<b>2003</b>				<b>Aura; Outlook</b>			
<b>Cayenne</b>				EZ-sensor - 315 MHz .....			
Service Pack; Does Not Include Valve .	20023	31-40	3.5-4.5	EZ-sensor Service Pack; Almm. Valve	◇33000	11.5	1.3
Service Pack; W/43mm Silver Insert ....	20037	31-40	3.5-4.5	EZ-sensor Service Pack; Rubber Valve	34000	62	7
Service Pack; W/48mm Green Insert ...	20038	31-40	3.5-4.5	Sensor .....	20153	11.5	1.3
Service Pack; W/49mm Black Insert .....	20039	31-40	3.5-4.5	Service Pack .....	20008	11.5	1.3
Service Pack; W/51mm Orange Insert .	20040	31-40	3.5-4.5	<b>Sky</b>			
<b>2002</b>				EZ-sensor - 315 MHz .....			
<b>► Rolls-Royce</b>				EZ-sensor Service Pack; Almm. Valve			
<b>2010-2007</b>				EZ-sensor Service Pack; Rubber Valve			
<b>Phantom</b>				Sensor .....			
Service Pack; Does Not Include Valve .	20023	31-40	3.5-4.5	Service Pack; W/Schrader Sensor .....	20004	62	7
Service Pack; W/43mm Silver Insert ....	20037	31-40	3.5-4.5	Service Pack; W/Siemens Sensor .....	20030	80	9
Service Pack; W/48mm Green Insert ...	20038	31-40	3.5-4.5	<b>VUE</b>			
Service Pack; W/49mm Black Insert .....	20039	31-40	3.5-4.5	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Service Pack; W/51mm Orange Insert .	20040	31-40	3.5-4.5	EZ-sensor Service Pack; Almm. Valve	34000	62	7
<b>► Saab</b>				EZ-sensor Service Pack; Rubber Valve			
<b>2012-2011</b>				Sensor .....			
<b>9-3</b>				Service Pack .....			
Sensor .....	20159	88	10				

◇ Programming Tool Required.

Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
<b>► Saturn - Continued</b>				<b>► Scion - Continued</b>			
<b>2008</b>				<b>2007</b>			
<b>Astra</b>				<b>TC</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor .....	28078	80	9	Sensor .....	28365	35	4
Service Pack .....	20009	80	9	Service Pack .....	20032	35	4
<b>Aura</b>				<b>2006</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	<b>TC</b>			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor .....	20153	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Service Pack .....	20008	11.5	1.3	Sensor; May & Newer .....	28365	35	4
<b>Outlook</b>				<b>Service Pack; May &amp; Newer .....</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	20032 35 4			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>► Smart</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	<b>2013</b>			
Sensor .....	20158	62	7	<b>Fortwo</b>			
Service Pack; W/Schrader Sensor .....	20004	62	7	Sensor .....	28214	58	6.5
Service Pack; W/Siemens Sensor .....	20030	62	7	Service Pack; W/Valve .....	20020	58	6.5
<b>Sky</b>				Service Pack; W/O Valve .....	20016	58	6.5
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	<b>2012-2008</b>			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>Fortwo</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor .....	28214	53	6
Sensor .....	20158	62	7	Service Pack; Includes Stem Only .....	20020	53	6
Service Pack; W/Schrader Sensor .....	20004	62	7	Service Pack; Does Not Include Stem ..	20016	53	6
Service Pack; W/Siemens Sensor .....	20030	80	9	<b>► Subaru</b>			
<b>VUE</b>				<b>2013</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	<b>Forester; Impreza; Legacy; Outback</b>			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor .....	20153	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Service Pack .....	20008	11.5	1.3	Sensor .....	28203	11.5	1.3
<b>2007</b>				Service Pack .....	20008	11.5	1.3
<b>Aura; Outlook</b>				<b>XV Crosstrek</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack; Rubber Valve .....	20008	11.5	1.3
Sensor .....	20158	62	7	Sensor .....	28203	11.5	1.3
Service Pack; W/Schrader Sensor .....	20004	62	7	<b>2012</b>			
Service Pack; W/Siemens Sensor .....	20030	62	7	<b>Forester</b>			
<b>VUE</b>				EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor .....	28203	11.5	1.3
Sensor .....	20153	11.5	1.3	Service Pack .....	20008	11.5	1.3
Service Pack .....	20008	11.5	1.3	<b>Impreza</b>			
<b>► Scion</b>				EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
<b>2013-2011</b>				EZ-sensor Service Pack; Almm. Valve	34000	62	7
<b>iQ; TC; XB; XD</b>				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Sensor .....	28203	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Service Pack .....	20008	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack; Rubber Valve .....	20008	11.5	1.3
Sensor .....	28365	35	4	<b>Legacy; Outback; Tribeca</b>			
Service Pack .....	20032	35	4	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
<b>2010-2008</b>				EZ-sensor Service Pack; Almm. Valve	34000	62	7
<b>TC; XB; XD</b>				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Sensor .....	28203	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Service Pack .....	20008	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	<b>2011</b>			
Sensor .....	28365	35	4	<b>Forester; Impreza; Legacy; Outback</b>			
Service Pack .....	20032	35	4	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3

◇ Programming Tool Required.

## Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
<b>► Subaru - Continued</b>				<b>► Subaru - Continued</b>			
<b>2011 - Continued</b>				<b>2008 - Continued</b>			
<b>Forester; Impreza; Legacy; Outback - Continued</b>				<b>Tribeca</b>			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor .....	28203	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Service Pack .....	20008	11.5	1.3	Sensor; W/Metal Stem Clamp-in Sensor	20081	66	7.5
<b>Tribeca</b>				Sensor; W/Rubber Stem Snap-in Sensor	28203	11.5	1.3
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Service Pack; W/Metal Stem Clamp-in	20011	66	7.5
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor .....	20011	66	7.5
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack; W/Rubber Stem Snap-in	20008	11.5	1.3
Sensor; W/Metal Stem Clamp-in Sensor	20081	66	7.5	Sensor .....	20008	11.5	1.3
Sensor; W/Rubber Stem Snap-in Sensor	28203	11.5	1.3	Service Pack; Rubber Valve .....	20008	11.5	1.3
Service Pack; Rubber Valve .....	20008	11.5	1.3	<b>2007</b>			
<b>2010</b>				<b>B9 Tribeca; Legacy</b>			
<b>Forester; Impreza; Legacy; Outback</b>				EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor .....	20081	66	7.5
Sensor .....	28203	11.5	1.3	Service Pack .....	20011	66	7.5
Service Pack .....	20008	11.5	1.3	<b>2006</b>			
<b>Tribeca</b>				<b>B9 Tribeca; Legacy; Outback</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor; W/Metal Stem Clamp-in Sensor	20081	66	7.5	Sensor .....	20081	66	7.5
Sensor; W/Rubber Stem Snap-in Sensor	28203	11.5	1.3	Service Pack .....	20011	66	7.5
Service Pack .....	20008	11.5	1.3	<b>2005-2004</b>			
<b>2009</b>				<b>Legacy; Outback</b>			
<b>Forester; Impreza; Legacy; Outback</b>				EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor .....	20081	66	7.5
Sensor .....	28203	11.5	1.3	Service Pack .....	20011	66	7.5
Service Pack .....	20008	11.5	1.3	<b>► Suzuki</b>			
<b>Tribeca</b>				<b>2013</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	<b>Equator</b>			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor; W/Metal Stem Clamp-in Sensor	20081	66	7.5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor; W/Rubber Stem Snap-in Sensor	28203	11.5	1.3	Sensor .....	28204	49	5.5
Service Pack; W/Metal Stem Clamp-in	20011	66	7.5	Service Pack .....	20014	49	5.5
Sensor .....	20011	66	7.5	<b>Grand Vitara; SX4</b>			
Service Pack; Rubber Valve .....	20008	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
<b>2008</b>				EZ-sensor Service Pack; Almm. Valve	34000	62	7
<b>Forester; Impreza</b>				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Sensor .....	20087	80	9
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Service Pack .....	20009	80	9
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	<b>2012-2010</b>			
Sensor .....	28203	11.5	1.3	<b>Equator</b>			
Service Pack .....	20008	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
<b>Legacy</b>				EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor .....	28204	49	5.5
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack .....	20014	49	5.5
Sensor; W/16" Or 17" Wheels .....	20081	66	7.5	<b>Grand Vitara</b>			
Sensor; W/18" Wheels .....	28203	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Service Pack; W/16" Or 17" Wheels .....	20011	66	7.5	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Service Pack; W/18" Wheels .....	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
<b>Outback</b>				Sensor .....	20087	80	9
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Service Pack .....	20009	80	9
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>Kizashi</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Sensor .....	28203	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Service Pack .....	20008	11.5	1.3				

◇ Programming Tool Required.



## Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
<b>► Suzuki - Continued</b>				<b>► Suzuki - Continued</b>			
<b>2012-2010 - Continued</b>				<b>2008-2007 - Continued</b>			
<b>Kizashi - Continued</b>				<b>XL-7 - Continued</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor .....	20158	62	7
Sensor .....	20066	58	6.5	Service Pack; W/Schrader Sensor .....	20004	62	7
or	28308	11.5	1.3	Service Pack; W/Siemens Sensor .....	20030	62	7
Service Pack; W/Schrader Sensor; Includes Stem Only .....	20020	58	6.5	<b>2006-2005</b>			
Service Pack; W/Schrader Sensor; Does Not Include Stem .....	20013	58	6.5	<b>Verona</b>			
Service Pack; W/Siemens Sensor .....	20030	71	8	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
<b>SX4</b>				EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor .....	20082	80	9
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack .....	20009	80	9
Sensor .....	20087	80	9	<b>XL-7</b>			
Service Pack .....	20009	80	9	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
<b>2009</b>				EZ-sensor Service Pack; Almm. Valve	34000	62	7
<b>Equator</b>				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Sensor .....	28204	49	5.5
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Service Pack .....	20014	49	5.5
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	<b>► Toyota</b>			
Sensor .....	28204	49	5.5	<b>2013</b>			
Service Pack .....	20014	49	5.5	<b>4 Runner</b>			
<b>Grand Vitara; SX4</b>				EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor .....	28370	35	4
Sensor .....	20087	80	9	Service Pack .....	20032	35	4
Service Pack .....	20009	80	9	<b>Camry</b>			
<b>XL-7</b>				EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor .....	28360	35	4
Sensor .....	20158	62	7	Service Pack .....	20032	35	4
Service Pack; W/Schrader Sensor .....	20004	62	7	<b>Corolla</b>			
Service Pack; W/Siemens Sensor .....	20030	62	7	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
<b>2008-2007</b>				EZ-sensor Service Pack; Almm. Valve	34000	62	7
<b>Forenza</b>				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Sensor; Models made in Japan. ....	28365	35	4
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor; Models made in USA.; W/16" Or 17" Wheels .....	28360	35	4
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack .....	20032	35	4
Sensor .....	20153	11.5	1.3	<b>FJ Cruiser</b>			
Service Pack .....	20008	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
<b>Grand Vitara</b>				EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor .....	28365	35	4
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack .....	20032	35	4
Sensor .....	20087	80	9	<b>Highlander</b>			
Service Pack .....	20009	80	9	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
<b>Reno</b>				EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor .....	28360	35	4
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack .....	20032	35	4
Sensor .....	20153	11.5	1.3	<b>Land Cruiser</b>			
Service Pack .....	20008	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
<b>SX4</b>				EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor .....	28365	35	4
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack .....	20032	35	4
Sensor .....	20087	80	9	<b>Matrix</b>			
Service Pack .....	20009	80	9	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
<b>XL-7</b>				EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor; Models made in Japan.; OEM Part No. 4260733011 .....	28365	35	4
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				

◇ Programming Tool Required.

**Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks**

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
<b>► Toyota - Continued</b>				<b>► Toyota - Continued</b>			
<b>2013 - Continued</b>				<b>2012 - Continued</b>			
<b>Matrix - Continued</b>				<b>Highlander - Continued</b>			
Sensor; Models made in USA.; OEM Part No. 4260706011 .....	28360	35	4	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Service Pack .....	20032	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
<b>Prius</b>				Sensor .....	28360	35	4
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Service Pack .....	20032	35	4
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>Land Cruiser</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Sensor .....	28365	35	4	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Service Pack .....	20032	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
<b>Sequoia; Sienna</b>				Sensor .....	28365	35	4
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Service Pack .....	20032	35	4
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>Matrix</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Sensor .....	28670	35	4	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Service Pack .....	20022	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
<b>Tacoma</b>				Sensor; Models made in Japan.; OEM Part No. 4260733011 .....	28365	35	4
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Sensor; Models made in USA.; OEM Part No. 4260706011 .....	28360	35	4
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Service Pack .....	20032	35	4
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	<b>Prius</b>			
Sensor; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor .....	28360	35	4	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Sensor; W/Steel Wheels; W/40 Deg. Angled Valve Sensor .....	28380	35	4	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Service Pack .....	20032	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
<b>Venza; Yaris</b>				Sensor .....	28365	35	4
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Service Pack .....	20032	35	4
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>RAV4</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Sensor .....	28360	35	4	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Service Pack .....	20032	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
<b>2012</b>				Sensor .....	28370	35	4
<b>4 Runner</b>				Service Pack .....	20032	35	4
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	<b>Sequoia; Sienna</b>			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor .....	28370	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Service Pack .....	20032	35	4	Sensor .....	28670	35	4
<b>Avalon; Camry</b>				Service Pack .....	20022	35	4
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	<b>Tacoma</b>			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor .....	28360	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Service Pack .....	20032	35	4	Sensor; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor .....	28360	35	4
<b>Corolla</b>				Sensor; W/Steel Wheels; W/40 Deg. Angled Valve Sensor .....	28380	35	4
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Service Pack .....	20032	35	4
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>Tundra</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Sensor; Models made in Japan.; OEM Part No. 4260733011 .....	28365	35	4	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor; Models made in Japan.; OEM Part No. 4260733021 .....	28370	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor; Models made in USA.; W/15" Wheels .....	28365	35	4	Sensor .....	28670	35	4
Sensor; Models made in USA.; W/16" Or 17" Wheels .....	28360	35	4	Service Pack .....	20022	35	4
Service Pack .....	20032	35	4	<b>Venza</b>			
<b>FJ Cruiser</b>				EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor .....	28360	35	4
Sensor .....	28365	35	4	Service Pack .....	20032	35	4
Service Pack .....	20032	35	4	<b>Yaris</b>			
<b>Highlander</b>				EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
				Sensor .....	28365	35	4
				Service Pack .....	20032	35	4

◇ Programming Tool Required.

Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
<b>► Toyota - Continued</b>				<b>► Toyota - Continued</b>			
<b>2011</b>				<b>2011 - Continued</b>			
<b>4 Runner</b>				<b>Prius - Continued</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Service Pack .....	20032	35	4
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>RAV4</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Sensor .....	28370	35	4	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Service Pack .....	20032	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
				Sensor .....	28370	35	4
				Service Pack .....	20032	35	4
<b>Avalon</b>				<b>Sequoia; Sierra</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor .....	28360	35	4	Sensor .....	28670	35	4
Service Pack .....	20032	35	4	Service Pack .....	20022	35	4
<b>Camry</b>				<b>Tacoma</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor; Models made in Japan.; OEM Part No. 4260733011 .....	28365	35	4	Sensor; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor .....	28360	35	4
Sensor; Models made in USA.; OEM Part No. 4260706011 .....	28360	35	4	Sensor; W/Steel Wheels; W/40 Deg. Angled Valve Sensor .....	28380	35	4
Service Pack .....	20032	35	4	Service Pack .....	20032	35	4
<b>Corolla</b>				<b>Tundra</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor; Models made in Japan.; OEM Part No. 4260733011 .....	28365	35	4	Sensor .....	28670	35	4
Sensor; Models made in Japan.; OEM Part No. 4260733021 .....	28370	35	4	Service Pack .....	20022	35	4
Sensor; Models made in USA.; W/15" Wheels .....	28365	35	4				
Sensor; Models made in USA.; W/16" Or 17" Wheels .....	28360	35	4	<b>Venza</b>			
Service Pack .....	20032	35	4	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
				EZ-sensor Service Pack; Almm. Valve	34000	62	7
				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
				Sensor .....	28360	35	4
				Service Pack .....	20032	35	4
<b>FJ Cruiser</b>				<b>Yaris</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor .....	28365	35	4	Sensor .....	28365	35	4
Service Pack .....	20032	35	4	Service Pack .....	20032	35	4
<b>Highlander</b>				<b>2010</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	<b>4 Runner</b>			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor .....	28360	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Service Pack .....	20032	35	4	Sensor .....	28370	35	4
				Service Pack .....	20032	35	4
<b>Land Cruiser</b>				<b>Avalon</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor .....	28365	35	4	Sensor .....	28360	35	4
Service Pack .....	20032	35	4	Service Pack .....	20032	35	4
<b>Matrix</b>				<b>Camry</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor; Models made in Japan.; OEM Part No. 4260733011 .....	28365	35	4	Sensor; Models made in Japan.; OEM Part No. 4260733011 .....	28365	35	4
Sensor; Models made in USA.; OEM Part No. 4260706011 .....	28360	35	4	Sensor; Models made in USA.; OEM Part No. 4260706011 .....	28360	35	4
Service Pack .....	20032	35	4	Service Pack .....	20032	35	4
<b>Prius</b>							
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3				
EZ-sensor Service Pack; Almm. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor .....	28365	35	4				

◇ Programming Tool Required.

## Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
<b>► Toyota - Continued</b>				<b>► Toyota - Continued</b>			
<b>2010 - Continued</b>				<b>2010 - Continued</b>			
<b>Corolla</b>				<b>Venza - Continued</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Sensor .....	28360	35	4
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Service Pack .....	20032	35	4
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	<b>Yaris</b>			
Sensor; Models made in Japan.; OEM Part No. 4260733011 .....	28365	35	4	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Sensor; Models made in Japan.; OEM Part No. 4260733021 .....	28370	35	4	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor; Models made in USA.; W/15" Wheels .....	28365	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor; Models made in USA.; W/16" Or 17" Wheels .....	28360	35	4	Sensor .....	28365	35	4
Service Pack .....	20032	35	4	Service Pack .....	20032	35	4
<b>FJ Cruiser; Highlander; Land Cruiser</b>				<b>2009</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	<b>4 Runner</b>			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor .....	28365	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Service Pack .....	20032	35	4	Sensor; W/Valve Cap .....	28365	35	4
<b>Matrix</b>				Sensor; W/O Valve Cap .....	28370	35	4
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Service Pack .....	20032	35	4
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>Avalon</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Sensor; Models made in Japan.; OEM Part No. 4260733011 .....	28365	35	4	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor; Models made in USA.; OEM Part No. 4260706011 .....	28360	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Service Pack .....	20032	35	4	Sensor .....	28360	35	4
<b>Prius</b>				Service Pack .....	20032	35	4
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	<b>Camry</b>			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor .....	28365	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Service Pack .....	20032	35	4	Sensor; Models made in Japan.; OEM Part No. 4260733011 .....	28365	35	4
<b>RAV4</b>				Sensor; Models made in USA.; OEM Part No. 4260706011 .....	28360	35	4
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Service Pack .....	20032	35	4
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>Corolla</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Sensor .....	28370	35	4	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Service Pack .....	20032	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
<b>Sequoia; Sienna</b>				Sensor; Models made in Japan.; OEM Part No. 4260733011 .....	28365	35	4
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Sensor; Models made in Japan.; OEM Part No. 4260733021 .....	28370	35	4
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor; Models made in USA.; W/15" Wheels .....	28365	35	4
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; Models made in USA.; W/16" Or 17" Wheels .....	28360	35	4
Sensor .....	28670	35	4	Service Pack .....	20032	35	4
Service Pack .....	20022	35	4	<b>FJ Cruiser; Highlander; Land Cruiser</b>			
<b>Tacoma</b>				EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor .....	28365	35	4
Sensor; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor .....	28360	35	4	Service Pack .....	20032	35	4
Sensor; W/Steel Wheels; W/40 Deg. Angled Valve Sensor .....	28380	35	4	<b>Matrix</b>			
Service Pack .....	20032	35	4	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
<b>Tundra</b>				EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor; Models made in Japan.; OEM Part No. 4260733011 .....	28365	35	4
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; Models made in USA.; OEM Part No. 4260706011 .....	28360	35	4
Sensor; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor .....	28670	35	4	Service Pack .....	20032	35	4
Service Pack .....	20022	35	4	<b>Prius</b>			
<b>Venza</b>				EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor .....	28365	35	4
				Service Pack .....	20032	35	4

◇ Programming Tool Required.



## Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
<b>► Toyota - Continued</b>				<b>► Toyota - Continued</b>			
<b>2009 - Continued</b>				<b>2008 - Continued</b>			
<b>RAV4</b>				<b>FJ Cruiser; Highlander; Land Cruiser</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor .....	28370	35	4	Sensor .....	28365	35	4
Service Pack .....	20032	35	4	Service Pack .....	20032	35	4
<b>Sequoia; Sienna</b>				<b>Matrix</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor .....	28670	35	4	Sensor; Models made in Japan.; OEM Part No. 4260733011 .....	28365	35	4
Service Pack .....	20022	35	4	Sensor; Models made in USA.; OEM Part No. 4260706011 .....	28360	35	4
<b>Tacoma</b>				<b>Service Pack .....</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Service Pack .....	20032	35	4
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>Prius</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Sensor; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor .....	28360	35	4	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor; W/Steel Wheels; W/40 Deg. Angled Valve Sensor .....	28380	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Service Pack .....	20032	35	4	Sensor .....	28365	35	4
<b>Tundra</b>				<b>Service Pack .....</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Service Pack .....	20032	35	4
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>RAV4</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Sensor; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor .....	28670	35	4	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Service Pack .....	20022	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
<b>Venza</b>				<b>Sensor .....</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Sensor .....	28370	35	4
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Service Pack .....	20032	35	4
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	<b>Sequoia; Sienna</b>			
Sensor .....	28360	35	4	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Service Pack .....	20032	35	4	EZ-sensor Service Pack; Almm. Valve	34000	62	7
<b>Yaris</b>				<b>Service Pack .....</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor .....	28670	35	4
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack .....	20022	35	4
Sensor .....	28365	35	4	<b>Solara</b>			
Service Pack .....	20032	35	4	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
<b>2008</b>				<b>Service Pack .....</b>			
<b>4 Runner</b>				<b>Service Pack .....</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor; W/Valve Cap; OEM Part No. 4260733011 .....	28365	35	4	Sensor; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor .....	28360	35	4
Sensor; W/O Valve Cap; OEM Part No. 4260733021 .....	28370	35	4	Sensor; W/Steel Wheels; W/40 Deg. Angled Valve Sensor .....	28380	35	4
Service Pack .....	20032	35	4	Service Pack .....	20032	35	4
<b>Avalon</b>				<b>Tacoma</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor .....	28360	35	4	Sensor; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor .....	28670	35	4
Service Pack .....	20032	35	4	Service Pack .....	20022	35	4
<b>Camry; Corolla</b>				<b>Tundra</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor; Models made in Japan.; OEM Part No. 4260733011 .....	28365	35	4	Sensor; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor .....	28670	35	4
Sensor; Models made in USA.; OEM Part No. 4260706011 .....	28360	35	4	Service Pack .....	20022	35	4
Service Pack .....	20032	35	4	<b>Yaris</b>			
<b>2007</b>				<b>Service Pack .....</b>			
<b>4 Runner</b>				<b>Service Pack .....</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7

◇ Programming Tool Required.

## Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
<b>► Toyota - Continued</b>				<b>► Toyota - Continued</b>			
<b>2007 - Continued</b>				<b>2007 - Continued</b>			
<b>4 Runner - Continued</b>				<b>Sequoia - Continued</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; W/Alloy Wheels .....	28305	35	4
Sensor; W/Valve Cap .....	28365	35	4	Sensor; W/Steel Wheels; W/20 Deg. Angled Valve Sensor .....	28305	35	4
Sensor; W/O Valve Cap .....	28370	35	4	Sensor; W/Steel Wheels; W/40 Deg. Angled Valve Sensor .....	28300	35	4
Service Pack .....	20032	35	4	Service Pack .....	20031	35	4
<b>Avalon</b>				<b>Sienna</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor .....	28360	35	4	Sensor .....	28670	35	4
Service Pack .....	20032	35	4	Service Pack .....	20022	35	4
<b>Camry</b>				<b>Solara</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor; Models made in Japan.; OEM Part No. 4260733011 .....	28365	35	4	Sensor .....	28360	35	4
Sensor; Models made in USA.; OEM Part No. 4260706011 .....	28360	35	4	Service Pack .....	20032	35	4
Service Pack .....	20032	35	4	<b>Tacoma</b>			
<b>Corolla</b>				EZ-sensor - 315 MHz .....			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor .....	28360	35	4
Sensor; Models made in Japan.; OEM Part No. 4260733011; Jun. & Newer .	28365	35	4	Sensor; W/Steel Wheels; W/40 Deg. Angled Valve Sensor .....	28380	35	4
Sensor; Models made in USA.; OEM Part No. 4260706011; Jun. & Newer .....	28360	35	4	Service Pack .....	20032	35	4
Service Pack; Jun. & Newer .....	20032	35	4	<b>Tundra</b>			
<b>Highlander</b>				EZ-sensor - 315 MHz .....			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor .....	28670	35	4
Sensor; May & Newer .....	28365	35	4	Service Pack .....	20022	35	4
Service Pack; May & Newer .....	20032	35	4	<b>Yaris</b>			
<b>Land Cruiser</b>				EZ-sensor - 315 MHz .....			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; Aug. & Newer .....	28365	35	4
Sensor .....	28365	35	4	Service Pack; Aug. & Newer .....	20032	35	4
Service Pack .....	20032	35	4	<b>2006</b>			
<b>Matrix</b>				<b>4 Runner</b>			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor; Models made in Japan.; OEM Part No. 4260733011; Jun. & Newer .	28365	35	4	Sensor; OEM Part No. 4260733011 .....	28365	35	4
Sensor; Models made in USA.; OEM Part No. 4260706011; Jun. & Newer .....	28360	35	4	Sensor; OEM Part No. 4260733021 .....	28370	35	4
Service Pack; Jun. & Newer .....	20032	35	4	Sensor; OEM Part No. 4260730030 .....	28335	35	4
<b>Prius</b>				Sensor; OEM Part No. 4260735010 .....			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Service Pack; Jun. & Newer .....	20032	35	4
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Service Pack; May & Older .....	20031	35	4
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	<b>Avalon</b>			
Sensor .....	28365	35	4	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Service Pack .....	20032	35	4	EZ-sensor Service Pack; Almm. Valve	34000	62	7
<b>RAV4</b>				EZ-sensor Service Pack; Rubber Valve			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Sensor; Aug. & Newer .....	28360	35	4
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Service Pack; Aug. & Newer .....	20032	35	4
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	<b>Land Cruiser</b>			
Sensor .....	28370	35	4	EZ-sensor - 315 MHz .....	◇33000	11.5	1.3
Service Pack .....	20032	35	4	EZ-sensor Service Pack; Almm. Valve	34000	62	7
<b>Sequoia</b>				EZ-sensor Service Pack; Rubber Valve			
EZ-sensor - 315 MHz .....	◇33000	11.5	1.3	Sensor .....	28365	35	4
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Service Pack; Apr. 1 & Newer .....	20032	35	4
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack; Mar. & Older .....	20031	35	4

◇ Programming Tool Required.

## Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
<b>► Toyota - Continued</b>				<b>► Toyota - Continued</b>			
<b>2006 - Continued</b>				<b>2005 - Continued</b>			
<b>Prius; RAV4</b>				<b>Sequoia - Continued</b>			
EZ-sensor - 315 MHz .....	⇨33000	11.5	1.3	Sensor; W/Steel Wheels; W/40 Deg. Angled Valve Sensor .....	28300	35	4
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Service Pack .....	20031	35	4
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	<b>Tacoma</b>			
Sensor .....	28365	35	4	EZ-sensor - 315 MHz .....	⇨33000	11.5	1.3
Service Pack .....	20032	35	4	EZ-sensor Service Pack; Almm. Valve	34000	62	7
<b>Sequoia</b>				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor - 315 MHz .....	⇨33000	11.5	1.3	Sensor; W/20 Deg. Angled Valve Sensor; Dec. 1 & Newer .....	28355	35	4
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor; W/20 Deg. Angled Valve Sensor; Nov. 30 & Older .....	28305	35	4
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; W/40 Deg. Angled Valve Sensor; Dec. 1 & Newer .....	28380	35	4
Sensor; W/Alloy Wheels .....	28305	35	4	Sensor; W/40 Deg. Angled Valve Sensor; Nov. 30 & Older .....	28300	35	4
Sensor; W/Steel Wheels; W/20 Deg. Angled Valve Sensor .....	28305	35	4	Service Pack .....	20031	35	4
Sensor; W/Steel Wheels; W/40 Deg. Angled Valve Sensor .....	28300	35	4	<b>Tundra</b>			
Service Pack .....	20031	35	4	EZ-sensor - 315 MHz .....	⇨33000	11.5	1.3
<b>Solara</b>				EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor - 315 MHz .....	⇨33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor; W/20 Deg. Angled Valve Sensor	28305	35	4
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; W/40 Deg. Angled Valve Sensor	28300	35	4
Sensor; May & Newer .....	28360	35	4	Service Pack .....	20031	35	4
Service Pack; May & Newer .....	20032	35	4	<b>2004</b>			
<b>Tacoma</b>				<b>4 Runner</b>			
EZ-sensor - 315 MHz .....	⇨33000	11.5	1.3	EZ-sensor - 315 MHz .....	⇨33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor; Aug. & Newer	28360	35	4	Sensor .....	28345	35	4
Sensor; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor; Jul. & Older	28355	35	4	Service Pack .....	20031	35	4
Sensor; W/Steel Wheels; W/40 Deg. Angled Valve Sensor .....	28380	35	4	<b>Sequoia</b>			
Service Pack; Aug. & Newer .....	20032	35	4	EZ-sensor - 315 MHz .....	⇨33000	11.5	1.3
Service Pack; Jul. & Older .....	20031	35	4	EZ-sensor Service Pack; Almm. Valve	34000	62	7
<b>Tundra</b>				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor - 315 MHz .....	⇨33000	11.5	1.3	Sensor; W/Alloy Wheels .....	28305	35	4
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor; W/Steel Wheels; W/20 Deg. Angled Valve Sensor .....	28305	35	4
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; W/Steel Wheels; W/40 Deg. Angled Valve Sensor .....	28300	35	4
Sensor; W/20 Deg. Angled Valve Sensor; Nov. 1 & Newer .....	28670	35	4	Service Pack .....	20031	35	4
Sensor; W/20 Deg. Angled Valve Sensor; Oct. 31 & Older .....	28305	35	4	<b>2003</b>			
Sensor; W/40 Deg. Angled Valve Sensor; Oct. 31 & Older .....	28300	35	4	<b>4 Runner</b>			
Service Pack; Nov. 1 & Newer .....	20022	35	4	EZ-sensor - 315 MHz .....	⇨33000	11.5	1.3
Service Pack; Oct. 31 & Older .....	20031	35	4	EZ-sensor Service Pack; Almm. Valve	34000	62	7
<b>2005</b>				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
<b>4 Runner</b>				Sensor .....	28345	35	4
EZ-sensor - 315 MHz .....	⇨33000	11.5	1.3	Service Pack .....	20031	35	4
EZ-sensor Service Pack; Almm. Valve	34000	62	7	<b>► Volkswagen</b>			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	<b>2013</b>			
Sensor .....	28345	35	4	<b>Touareg</b>			
Service Pack .....	20031	35	4	Sensor; W/315 MHz Sensor; Includes Transmitter Only .....	20077	35	4
<b>Land Cruiser</b>				Service Pack; Does Not Include Valve; W/315 MHz Sensor .....	20023	35	4
EZ-sensor - 315 MHz .....	⇨33000	11.5	1.3	Service Pack; W/43mm Silver Insert; W/315 MHz Sensor .....	20037	35	4
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Service Pack; W/48mm Green Insert; W/315 MHz Sensor .....	20038	35	4
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack; W/49mm Black Insert; W/315 MHz Sensor .....	20039	35	4
Sensor; May & Newer .....	28365	35	4	Service Pack; W/51mm Orange Insert; W/315 MHz Sensor .....	20040	35	4
Service Pack; May & Newer .....	20031	35	4	Sensor; W/433 MHz Sensor; Includes Transmitter Only .....	20103	35	4
<b>Sequoia</b>							
EZ-sensor - 315 MHz .....	⇨33000	11.5	1.3				
EZ-sensor Service Pack; Almm. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor; W/Alloy Wheels .....	28305	35	4				
Sensor; W/Steel Wheels; W/20 Deg. Angled Valve Sensor .....	28305	35	4				

⇨ Programming Tool Required.

## Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
<b>► Volkswagen - Continued</b>				<b>► Volkswagen - Continued</b>			
<b>2012-2011</b>				<b>2008 - Continued</b>			
<b>CC; Eos; Tiguan</b>				<b>Touareg 2 - Continued</b>			
Sensor .....	20088	71	8	Service Pack; W/43mm Silver Insert ....	20037	35	4
Service Pack .....	20017	71	8	Service Pack; W/48mm Green Insert ...	20038	35	4
<b>Touareg 2</b>				Service Pack; W/49mm Black Insert .....	20039	35	4
Sensor; W/315 MHz Sensor; Includes Transmitter Only .....	20077	35	4	Service Pack; W/51mm Orange Insert .	20040	35	4
Service Pack; Does Not Include Valve; W/315 MHz Sensor .....	20023	35	4	<b>2007</b>			
Service Pack; W/43mm Silver Insert; W/315 MHz Sensor .....	20037	35	4	<b>Eos</b>			
Service Pack; W/48mm Green Insert; W/315 MHz Sensor .....	20038	35	4	Sensor .....	20088	71	8
Service Pack; W/49mm Black Insert; W/315 MHz Sensor .....	20039	35	4	Service Pack .....	20017	71	8
Service Pack; W/51mm Orange Insert; W/315 MHz Sensor .....	20040	35	4	<b>GTI</b>			
Sensor; W/433 MHz Sensor; Includes Transmitter Only .....	20103	35	4	Sensor; W/16" Or 17" Wheels .....	20088	71	8
<b>2010</b>				Service Pack; W/16" Or 17" Wheels .....	20017	71	8
<b>Beetle; CC; Eos; Golf; GTI; Jetta; Passat; Tiguan</b>				<b>Jetta</b>			
Sensor .....	20088	71	8	Sensor .....	20088	71	8
Service Pack .....	20017	71	8	Service Pack .....	20017	71	8
<b>Touareg 2</b>				<b>Passat</b>			
Sensor; Includes Transmitter Only .....	20103	35	4	Sensor; W/16" Or 17" Wheels .....	20088	71	8
Service Pack; Does Not Include Valve .	20023	35	4	Service Pack; W/16" Or 17" Wheels .....	20017	71	8
Service Pack; W/43mm Silver Insert ....	20037	35	4	<b>Rabbit</b>			
Service Pack; W/48mm Green Insert ...	20038	35	4	Sensor; W/15" Wheels .....	20088	71	8
Service Pack; W/49mm Black Insert .....	20039	35	4	Service Pack; W/15" Wheels .....	20017	71	8
Service Pack; W/51mm Orange Insert .	20040	35	4	<b>Touareg</b>			
<b>2009</b>				Service Pack; Does Not Include Valve .	20023	62	7
<b>Beetle; CC; Eos</b>				Service Pack; W/43mm Silver Insert ....	20037	62	7
Sensor .....	20088	71	8	Service Pack; W/48mm Green Insert ...	20038	62	7
Service Pack .....	20017	71	8	Service Pack; W/49mm Black Insert .....	20039	62	7
<b>GLI</b>				Service Pack; W/51mm Orange Insert .	20040	62	7
Service Pack .....	20017	71	8	<b>2006</b>			
<b>Golf; GTI; Jetta; Passat; Rabbit; Tiguan</b>				<b>Golf</b>			
Sensor .....	20088	71	8	Service Pack; GTI .....	20017	71	8
Service Pack .....	20017	71	8	<b>GTI</b>			
<b>Touareg 2</b>				Sensor; W/16" Or 17" Wheels .....	20088	71	8
Sensor; Includes Transmitter Only .....	20078	35	4	Service Pack; W/16" Or 17" Wheels .....	20017	71	8
Service Pack; Does Not Include Valve .	20023	35	4	<b>Jetta</b>			
Service Pack; W/43mm Silver Insert ....	20037	35	4	Sensor .....	20088	71	8
Service Pack; W/48mm Green Insert ...	20038	35	4	Service Pack .....	20017	71	8
Service Pack; W/49mm Black Insert .....	20039	35	4	<b>Passat</b>			
Service Pack; W/51mm Orange Insert .	20040	35	4	Sensor; W/16" Or 17" Wheels .....	20088	71	8
<b>2008</b>				Service Pack; W/16" Or 17" Wheels .....	20017	71	8
<b>Beetle; Eos</b>				<b>Phaeton</b>			
Sensor .....	20088	71	8	Sensor; Includes Transmitter Only; W/315 MHz Sensor .....	20077	35	4
Service Pack .....	20017	71	8	Sensor; Includes Transmitter Only; W/433 MHz Sensor .....	20078	35	4
<b>GLI</b>				Service Pack; Does Not Include Valve; W/315 MHz Sensor .....	20023	35	4
Service Pack .....	20017	71	8	Service Pack; W/43mm Silver Insert; W/315 MHz Sensor .....	20037	35	4
<b>Golf; GTI; Jetta</b>				Service Pack; W/48mm Green Insert; W/315 MHz Sensor .....	20038	35	4
Sensor .....	20088	71	8	Service Pack; W/49mm Black Insert; W/315 MHz Sensor .....	20039	35	4
Service Pack .....	20017	71	8	Service Pack; W/51mm Orange Insert; W/315 MHz Sensor .....	20040	35	4
<b>Passat</b>				<b>Rabbit</b>			
Sensor; W/16" Or 17" Wheels .....	20088	71	8	Sensor; W/15" Wheels .....	20088	71	8
Service Pack; W/16" Or 17" Wheels .....	20017	71	8	Service Pack; W/15" Wheels .....	20017	71	8
<b>R32; Rabbit</b>				<b>Touareg</b>			
Sensor .....	20088	71	8	Service Pack; Does Not Include Valve .	20023	62	7
Service Pack .....	20017	71	8	Service Pack; W/43mm Silver Insert ....	20037	62	7
<b>Touareg 2</b>				Service Pack; W/48mm Green Insert ...	20038	62	7
Sensor; Includes Transmitter Only .....	20078	35	4	Service Pack; W/49mm Black Insert .....	20039	62	7
Service Pack; Does Not Include Valve .	20023	35	4	Service Pack; W/51mm Orange Insert .	20040	62	7



**Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks**

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
<b>► Volkswagen - Continued</b>				<b>► Volvo - Continued</b>			
<b>2005-2004</b>				<b>2007</b>			
<b>Phaeton</b>				<b>C30</b>			
Sensor; Includes Transmitter Only; W/315 MHz Sensor .....	20077	35	4	Sensor .....	20097	71	8
Sensor; Includes Transmitter Only; W/433 MHz Sensor .....	20078	35	4	Service Pack .....	20003	71	8
Service Pack; Does Not Include Valve; W/315 MHz Sensor .....	20023	35	4	<b>S60</b>			
Service Pack; W/43mm Silver Insert; W/315 MHz Sensor .....	20037	35	4	Sensor .....	20156	44	5
Service Pack; W/48mm Green Insert; W/315 MHz Sensor .....	20038	35	4	Service Pack .....	20010	44	5
Service Pack; W/49mm Black Insert; W/315 MHz Sensor .....	20039	35	4	<b>S80</b>			
Service Pack; W/51mm Orange Insert; W/315 MHz Sensor .....	20040	35	4	Sensor .....	20097	71	8
<b>Touareg</b>				Service Pack .....	20003	71	8
Service Pack; Does Not Include Valve .	20023	62	7	<b>V70; XC70; XC90</b>			
Service Pack; W/43mm Silver Insert ....	20037	62	7	Sensor; W/315 MHz Sensor .....	20156	44	5
Service Pack; W/48mm Green Insert ...	20038	62	7	Service Pack; W/315 MHz Sensor .....	20010	44	5
Service Pack; W/49mm Black Insert .....	20039	62	7	<b>2006</b>			
Service Pack; W/51mm Orange Insert .	20040	62	7	<b>S60; S80</b>			
<b>► Volvo</b>				Sensor .....	20156	44	5
<b>2013-2012</b>				Service Pack .....	20010	44	5
<b>C30; C70; S60; S80; XC60; XC70</b>				<b>V70; XC70; XC90</b>			
Sensor .....	20097	71	8	Sensor; W/315 MHz Sensor .....	20156	44	5
Service Pack .....	20003	71	8	Service Pack; W/315 MHz Sensor .....	20010	44	5
<b>XC90</b>				<b>2005</b>			
Sensor .....	28362	11.5	1.3	<b>S60</b>			
Service Pack .....	20008	11.5	1.3	Sensor; W/315 MHz Sensor .....	20156	44	5
<b>2011</b>				Service Pack; W/315 MHz Sensor .....	20010	44	5
<b>C30; C70; S40; S60; S80; V50; XC60; XC70; XC90</b>				<b>S80</b>			
Sensor .....	20097	71	8	Sensor .....	20156	44	5
Service Pack .....	20003	71	8	Service Pack .....	20010	44	5
<b>2010</b>				<b>V70; XC70; XC90</b>			
<b>C30; C70; S40; S80; V50; V70; XC60; XC70; XC90</b>				Sensor; W/315 MHz Sensor .....	20156	44	5
Sensor .....	20097	71	8	Service Pack; W/315 MHz Sensor .....	20010	44	5
Service Pack .....	20003	71	8	<b>2004</b>			
<b>2009</b>				<b>S60</b>			
<b>C30; C70; S40</b>				Sensor; W/315 MHz Sensor .....	20156	44	5
Sensor .....	20097	71	8	Service Pack; W/315 MHz Sensor .....	20010	44	5
Service Pack .....	20003	71	8	<b>S80</b>			
<b>S60</b>				Sensor .....	20156	44	5
Sensor .....	20156	44	5	Service Pack .....	20010	44	5
Service Pack .....	20010	44	5	<b>V70; XC70</b>			
<b>S80; V50; V70; XC70</b>				Sensor; W/315 MHz Sensor .....	20156	44	5
Sensor .....	20097	71	8	Service Pack; W/315 MHz Sensor .....	20010	44	5
Service Pack .....	20003	71	8	<b>XC90</b>			
<b>XC90</b>				Sensor .....	20156	44	5
Sensor; W/315 MHz Sensor .....	20156	44	5	Service Pack .....	20010	44	5
Service Pack; W/315 MHz Sensor .....	20010	44	5	<b>2008</b>			
<b>2008</b>				<b>C30; C70; S40</b>			
<b>C30; C70; S40</b>				Sensor .....	20097	71	8
Sensor .....	20097	71	8	Service Pack .....	20003	71	8
Service Pack .....	20003	71	8	<b>S60</b>			
<b>S60</b>				Sensor .....	20156	44	5
Sensor .....	20156	44	5	Service Pack .....	20010	44	5
Service Pack .....	20010	44	5	<b>S80; V50; V70; XC70; XC90</b>			
<b>S80; V50; V70; XC70; XC90</b>				Sensor .....	20097	71	8
Sensor .....	20097	71	8	Service Pack .....	20003	71	8
Service Pack .....	20003	71	8				

# Manufacturers' Part Numbers

OEM Sensor No.	Schrader Sensor No.	OEM Sensor No.	Schrader Sensor No.	OEM Sensor No.	Schrader Sensor No.
0009054100	28214	25758220	20076	4250B975	28096
0009057200	28214	25773946	20117	4260702010	28365
0025406817	20094	25774006	20116	4260704010	28380
0025406917	20095	25799331	20153	4260706011	28360
0025407917	20094	25920615	20153	4260708010	28670
0025407917	20094	28103AG00A	20081	426070C010	28300
0025408017	20095	28103AG01A	28203	426070C020	28305
0025408617	28214	28103AG01B	28203	426070C030	28670
0025409017	28214	28103AG01C	28203	426070C050	28670
0025409417	20094	28103SA001	28203	426070E011	28370
0035400217	28214	28103SA002	28203	4260724010	28310
0045421518	28214	307489910	20156	4260724020	28315
06421S3VA02	28981	31200923	28362	4260724030	28320
06421S3VA03	28981	312009230	20156	4260724040	28325
06421S3VA04	28981	312802970	20097	4260730030	28335
06421S9VA01	28982	31302096	20097	4260730070	28370
06421S9VA03	28982	313020960	20097	4260733011	28365
10394110	20158	36106790054	28081	4260733021	28370
10438853	28006	36118378682	20080	4260735010	28345
12768826	28206	36146752128	28082	4260775010	28345
13172567	28078	36236781847	20083	42607AD020	28355
13227143	20159	40700-1AA0B	28204	42753SHJA53	28981
15114379	20107	40700-1AA0D	28204	42753SHJA54	28981
15122618	20131	407001PAOA	28342	42753SHJA82	28983
15136883	20115	40700-CD001	20064	42753SNAA83	28720
15254101	20153	40700-CK001	20161	42753SNAA84	28720
15268606	20158	40700-CK002	20069	42753STKA01	20098
15825475	20158	40700-JA00C	28204	42753STKA02	20098
15921013	20158	40700-JA01A	28167	42753STKA03	20098
15922396	20153	40700-JA01B	28204	42753STKA04	20098
1K0907253D	20088	40700-JA01C	28204	42753SWA306	20099
20922900	28206	40700-JA02B	28204	42753SWA316	20099
20923680	20153	40700-JK00B	28210	42753TK4A01	20720
20964159	28423	40700-JK00C	28210	42753TL2A51	20098
224549	20077	42508875	28129	42753TL2A52	20098
224551	20084	4250A030	28129	42753TP6A82	20100
22853741	20153	4250A225	28096	4313054J20	20087
22854866	28206	4250B668	20398	4313054J21	20087
228553741	20153	4250B875	28129	4313054J22	20087
24437708	28078	4250B877	20034	4313057L00	20066 / 28308

# Manufacturers' Part Numbers

OEM Sensor No.	Schrader Sensor No.	OEM Sensor No.	Schrader Sensor No.	OEM Sensor No.	Schrader Sensor No.
4313078J10	20158	56029359AB	28434	86517000	20156
4313085Z00	20153	56029398AA	20398	88974915	28360
4313086Z20	20082	56029398AB	20398	8973271890	20028
4321182Z10	28204	56029400AB	28291	8C2Z1A189A	28395
4815132	28004	56029400AC	28291	95536105300	20077
4815132AB	28004	56029400AD	28291	95836166100	20103
4D0907275	20077	56029465AB	20066 / 28308	99760602120	28087
4D0907275C	20077	56029465AB	28308	9L3Z1A189A	20315
4D0907275D	20079	56029465AC	20066 / 28308	A0009057200	28214
4F0907275B	20078	56029465AC	28308	C2C25519	20090
4F0907275D	20103	56029479AA	20066 / 28308	C2C40476	20090
4F0907275H	20077	56029479AA	28308	C2C40725	20091
4L2Z 1A150 BA	20096	56029481AB	28155 / 28343	C2S40710	20091
5096808AA	20028	56053030AB	20066 / 28308	C2Z15016	20091
5127335AB	20335	56053030AB	28308	C2Z15017	20090
5142340AA	20066 / 28308	56053036AA	20066 / 28308	CM5T1A180AA	20315
5142340AA	28308	56053036AA	28308	DE8T1A180AA	20315
52088990AC	20028	5L1Z 1A150 AA	20135	DR3V1A180AA	20315
52088990AD	20028	68001696AA	20066 / 28308	GN3A37140B	20093
529331FA00	28983	68001696AA	28308	GS1D37140	20093
529332F000	28849	68001696AA	28434	LR010532	20091
529332F001	28849	68001696AB	20066 / 28308	LR010533	20090
529332G200	20086	68001696AB	28308	LR018860	20090
529332G201	20086	68001698AA	28155 / 28343	LR018861	20091
529332M000	20092	68001698AB	28155 / 28343	LR021936	20090
529332M001	20092	68001698AB	28434	LR031713	20090
529332V000	28505	68006771AA	20089	LR0500461	20090
529333X200	20086	68038945AA	20089	MN103033	20028
529334D200	20085	68078768AA	28155 / 28343	MN103081	20034
56029319AA	28154 / 28461	68078861AA	20066 / 28308	RQH500471	20091
56029319AA	28461	68078861AA	28308	XR855949	20091
56029319AB	28154 / 28461	6F2Z1A189A	28385	XR855950	20090
56029319AB	28461	7L1Z1A189A	28390	YBD000060	28082
56029359AA	28155 / 28343	7P0907275	20103	YBD000061	28082
56029359AA	28434	7P0907275A	20077	ZZC137140	28385
56029359AB	28155 / 28343	8257740060	20116	ZZDA37140	20315

# Numerical Listing Sensors/Transmitters

## 20028 (433 MHz)



Chrysler; 300M; 2004-2002  
 Chrysler; Concorde; 2004-2002  
 Chrysler; Crossfire; 2008-2006  
 Chrysler; Crossfire; 2005; OEM Part No. 52088990AC  
 Chrysler; Crossfire; 2004  
 Chrysler; Intrepid; 2004-2002  
 Chrysler; Pacifica; 2004; OEM Part No. 52088990AC  
 Chrysler; Prowler; 2002  
 Chrysler; Town & Country Van; 2003-2002  
 Chrysler; Voyager; 2003-2002  
 Dodge; Caravan; 2003-2002  
 Dodge; Grand Caravan; 2003-2002  
 Dodge; Intrepid; 2004-2002  
 Dodge; Viper; 2010-2008  
 Dodge; Viper; 2006-2003  
 Isuzu; Rodeo; 2004  
 Jeep; Grand Cherokee; 2004-2002  
 Jeep; Liberty; 2004-2002  
 Mitsubishi; Endeavor; 2007  
 Mitsubishi; Endeavor; 2006; Aug. & Older  
 Mitsubishi; Endeavor; 2005-2004  
 Mitsubishi; Galant; 2006-2004

## 20034 (315 MHz)



Mitsubishi; Eclipse; 2011-2008  
 Mitsubishi; Eclipse; 2007-2006; W/Alloy Wheels  
 Mitsubishi; Endeavor; 2011-2010  
 Mitsubishi; Endeavor; 2008  
 Mitsubishi; Endeavor; 2006; Sept. 1 & Newer  
 Mitsubishi; Galant; 2012-2007; W/Alloy Wheels  
 Mitsubishi; Montero; 2006-2003

## 20064 (315 MHz)



Infiniti; FX35; 2007; Jun. & Older  
 Infiniti; FX35; 2006-2003  
 Infiniti; FX45; 2007; Jun. & Older  
 Infiniti; FX45; 2006-2003  
 Infiniti; G35; 2006-2004  
 Infiniti; G35; 2003; Jun. & Newer  
 Infiniti; M35; 2007-2006  
 Infiniti; M45; 2007-2006  
 Infiniti; M45; 2004-2003  
 Infiniti; Q45; 2006; Jul. & Older  
 Infiniti; Q45; 2005-2003  
 Infiniti; QX4; 2003

## 20064 (315 MHz) - Continued

Nissan; 350Z; 2006-2003  
 Nissan; Frontier; 2004-2003  
 Nissan; Murano; 2006-2003  
 Nissan; Pathfinder; 2004; Exc. Armada; Jul. & Older  
 Nissan; Pathfinder; 2003  
 Nissan; Xterra; 2004-2003

## 20066 (315 MHz)



Chrysler; 200; 2012-2011  
 Chrysler; 300; 2006-2005  
 Chrysler; Aspen; 2009-2007  
 Chrysler; Crossfire; 2005; OEM Part No. 5142340AA  
 Chrysler; Pacifica; 2008-2006  
 Chrysler; PT Cruiser; 2010-2008  
 Chrysler; Sebring; 2010-2007  
 Chrysler; Town & Country Van; 2007-2006  
 Dodge; Avenger; 2012-2008  
 Dodge; Caliber; 2011-2007  
 Dodge; Caravan; 2007-2006  
 Dodge; Charger; 2007-2006  
 Dodge; Dakota; 2011  
 Dodge; Durango; 2009-2007  
 Dodge; Grand Caravan; 2007-2006  
 Dodge; Magnum; 2007-2005  
 Dodge; Nitro; 2011-2007  
 Jeep; Commander; 2007-2006  
 Jeep; Compass; 2011-2007  
 Jeep; Grand Cherokee; 2007-2005  
 Jeep; Liberty; 2012-2010  
 Jeep; Liberty; 2009; Sport  
 Jeep; Liberty; 2008-2005  
 Jeep; Patriot; 2012-2007  
 Jeep; Wrangler; 2012-2011  
 Jeep; Wrangler; 2008-2007  
 Suzuki; Kizashi; 2012-2010

## 20069 (315 MHz)



Infiniti; QX56; 2006-2005; W/Steel Wheels  
 Infiniti; QX56; 2004  
 Nissan; Armada; 2006-2005; W/Steel Wheels  
 Nissan; Frontier; 2007-2005; W/Steel Wheels  
 Nissan; Pathfinder; 2004; Armada  
 Nissan; Pathfinder; 2004; Exc. Armada; Aug. & Newer  
 Nissan; Quest; 2006-2005; W/Steel Wheels  
 Nissan; Quest; 2004  
 Nissan; Titan; 2005; Mar. & Older  
 Nissan; Titan; 2004  
 Nissan; Xterra; 2006; Submodel X



# Numerical Listing Sensors/Transmitters

## 20076 (315 MHz)



Cadillac; STS; 2008-2005; OEM Part No. 25758220  
 Cadillac; XLR; 2009-2004; OEM Part No. 25758220  
 Chevrolet; Corvette; 2009-2006; OEM Part No. 25758220  
 Chevrolet; Corvette; 2005

## 20077 (433 MHz)



Audi; A6; 2011  
 Audi; A8; 2010-2004  
 Audi; A8; 2003; Chassis No. 4E3000001 & After  
 Audi; Q7; 2011  
 Audi; S6; 2011  
 Audi; S8; 2009-2007  
 Audi; S8; 2003; Chassis No. 4E3000001 & After  
 Bentley; Continental; 2005-2003  
 Ferrari; 550 Maranello; 2002-2001  
 Ferrari; 575M Maranello; 2005-2002  
 Ferrari; 612 Scaglietti; 2009-2004  
 Ferrari; F430; 2009-2005  
 Porsche; 911; 2011  
 Porsche; Boxster; 2011  
 Porsche; Cayman; 2011  
 Volkswagen; Phaeton; 2006-2004; W/315 MHz Sensor  
 Volkswagen; Touareg; 2013; W/315 MHz Sensor  
 Volkswagen; Touareg 2; 2012-2011; W/315 MHz Sensor

## 20078 (433 MHz)



Audi; A4; 2008-2002  
 Audi; A6; 2009; Exc. Quattro  
 Audi; A6; 2008-2005  
 Audi; Q7; 2009-2007  
 Audi; R8; 2009-2008  
 Audi; RS4; 2008-2007  
 Audi; S4; 2009-2004  
 Audi; S6; 2009-2007  
 Bentley; Continental; 2010-2006  
 Volkswagen; Phaeton; 2006-2004; W/433 MHz Sensor  
 Volkswagen; Touareg 2; 2009-2008

## 20079 (315 MHz)



Audi; A8; 2003; Chassis No. 4D3004999 & Before  
 Audi; A8; 2002-2001  
 Audi; Allroad Quattro; 2005-2001  
 Audi; S8; 2003; Chassis No. 4D3004999 & Before  
 Audi; S8; 2002-2001

## 20080 (433 MHz)



BMW; 320i; 2005-2003  
 BMW; 320i; 2002; W/433 MHz Sensor  
 BMW; 325Ci; 2006-2003  
 BMW; 325Ci; 2002; W/433 MHz Sensor  
 BMW; 325i; 2006-2003  
 BMW; 325i; 2002; W/433 MHz Sensor  
 BMW; 325Xi; 2006-2003  
 BMW; 325Xi; 2002; W/433 MHz Sensor  
 BMW; 330Ci; 2006-2003  
 BMW; 330Ci; 2002; W/433 MHz Sensor  
 BMW; 330i; 2006-2003  
 BMW; 330i; 2002; W/433 MHz Sensor  
 BMW; 330Xi; 2006-2003  
 BMW; 330Xi; 2002; W/433 MHz Sensor  
 BMW; 525i; 2005-2003  
 BMW; 525i; 2002; W/433 MHz Sensor  
 BMW; 530i; 2005-2003  
 BMW; 530i; 2002; W/433 MHz Sensor  
 BMW; 540i; 2003  
 BMW; 540i; 2002; W/433 MHz Sensor  
 BMW; 545i; 2005-2004  
 BMW; 645Ci; 2005-2004  
 BMW; 745i; 2005-2003  
 BMW; 745i; 2002; W/433 MHz Sensor  
 BMW; 745Li; 2005-2003  
 BMW; 745Li; 2002; W/433 MHz Sensor  
 BMW; 760i; 2005-2004  
 BMW; 760Li; 2003  
 BMW; Alpina B7; 2011  
 BMW; M3; 2003  
 BMW; M3; 2002; W/433 MHz Sensor  
 BMW; M5; 2003-2000; W/433 MHz Sensor  
 BMW; Z8; 2003; W/433 MHz Sensor

# Numerical Listing Sensors/Transmitters

## 20081 (315 MHz)



Subaru; B9 Tribeca; 2007-2006  
Subaru; Legacy; 2008; W/16" Or 17" Wheels  
Subaru; Legacy; 2007-2004  
Subaru; Outback; 2006-2004  
Subaru; Tribeca; 2011-2008; W/Metal Stem Clamp-in Sensor

## 20082 (315 MHz)



Suzuki; Verona; 2006-2005

## 20083 (315 MHz)



BMW; 128i; 2011-2008  
BMW; 135i; 2010-2008  
BMW; 323i; 2010-2007  
BMW; 323i; 2006; Jun. & Newer  
BMW; 328i; 2009-2007  
BMW; 328Xi; 2008-2007  
BMW; 335D; 2009  
BMW; 335i; 2009-2007  
BMW; 335Xi; 2008-2007  
BMW; 525i; 2007-2006  
BMW; 525Xi; 2007-2006  
BMW; 528i; 2011-2008  
BMW; 528Xi; 2009-2008  
BMW; 530i; 2007-2006  
BMW; 530Xi; 2007-2006  
BMW; 535i; 2011-2008  
BMW; 535Xi; 2010  
BMW; 535Xi; 2008  
BMW; 550i; 2011-2006  
BMW; 650i; 2010-2006  
BMW; 740i; 2011  
BMW; 740Li; 2011  
BMW; 750i; 2011-2006  
BMW; 750Li; 2011-2006  
BMW; 760i; 2006  
BMW; 760Li; 2011-2010  
BMW; 760Li; 2008-2004  
BMW; Alpina B7; 2008-2007  
BMW; M3; 2009-2008  
BMW; M3; 2006-2004  
BMW; M5; 2010-2006  
BMW; M6; 2010-2006  
BMW; X3; 2011-2006  
BMW; X5; 2011-2005

## 20083 (315 MHz) - Continued

BMW; X6; 2011-2008  
BMW; Z4; 2011-2003  
Mini; Cooper; 2009-2008

## 20084 (433 MHz)



Ferrari; Enzo; 2004-2003

## 20085 (315 MHz)



Hyundai; Entourage; 2009-2007  
Hyundai; Santa Fe; 2008-2007  
Hyundai; Veracruz; 2008-2007  
Kia; Sedona; 2008-2006

## 20086 (315 MHz)



Hyundai; Azera; 2013  
Hyundai; Azera; 2012-2006  
Hyundai; Elantra; 2013-2012; W/Transmitter Only  
Hyundai; Elantra; 2011-2008  
Hyundai; Santa Fe; 2010-2009  
Hyundai; Veracruz; 2012-2009  
Kia; Magentis; 2010-2008  
Kia; Optima; 2010-2006  
Kia; Rio; 2013  
Kia; Rondo; 2011-2007  
Kia; Sedona; 2012-2009

## 20087 (315 MHz)



Suzuki; Grand Vitara; 2013-2007  
Suzuki; SX4; 2013-2007  
Suzuki; XL-7; 2006-2005

# Numerical Listing Sensors/Transmitters

## 20088 (315 MHz)



Audi; A3; 2012-2008  
 Audi; A4; 2012-2009  
 Audi; A5; 2012-2008  
 Audi; Q5; 2012-2009  
 Audi; S4; 2011-2010  
 Audi; S5; 2012-2008  
 Audi; TT; 2011-2008  
 Volkswagen; Beetle; 2010-2008  
 Volkswagen; CC; 2012-2009  
 Volkswagen; Eos; 2012-2007  
 Volkswagen; Golf; 2010-2008  
 Volkswagen; GTI; 2010-2008  
 Volkswagen; GTI; 2007-2006; W/16" Or 17" Wheels  
 Volkswagen; Jetta; 2010-2006  
 Volkswagen; Passat; 2010-2009  
 Volkswagen; Passat; 2008-2006; W/16" Or 17" Wheels  
 Volkswagen; R32; 2008  
 Volkswagen; Rabbit; 2009-2008  
 Volkswagen; Rabbit; 2007-2006; W/15" Wheels  
 Volkswagen; Tiguan; 2012-2009

## 20089 (315 MHz)



Dodge; Sprinter; 2010-2007  
 Freightliner; Sprinter; 2008-2007

## 20090 (315 MHz)



Jaguar; S-Type; 2008; W/315 MHz Sensor  
 Jaguar; Super V8; 2009-2005; W/315 MHz Sensor  
 Jaguar; Vanden Plas; 2009-2004; W/315 MHz Sensor  
 Jaguar; X-Type; 2008; W/315 MHz Sensor  
 Jaguar; XF; 2012-2009; W/315 MHz Sensor  
 Jaguar; XFR; 2011-2010; W/315 MHz Sensor  
 Jaguar; XJ; 2012-2010; W/315 MHz Sensor  
 Jaguar; XJ8; 2009-2004; W/315 MHz Sensor  
 Jaguar; XJR; 2009-2004; W/315 MHz Sensor  
 Jaguar; XK; 2012-2007; W/315 MHz Sensor  
 Jaguar; XKR; 2011-2007; W/315 MHz Sensor  
 Land Rover; LR2; 2012-2008  
 Land Rover; LR3; 2009-2006; W/315 MHz Sensor  
 Land Rover; LR4; 2012  
 Land Rover; LR4; 2011-2010; W/315 MHz Sensor

## 20090 (315 MHz) - Continued

Land Rover; Range Rover; 2013-2012  
 Land Rover; Range Rover; 2011-2006; W/315 MHz Sensor  
 20091  
 Jaguar; S-Type; 2008; W/433 MHz Sensor  
 Jaguar; Super V8; 2009-2005; W/433 MHz Sensor  
 Jaguar; Vanden Plas; 2009-2004; W/433 MHz Sensor  
 Jaguar; X-Type; 2008; W/433 MHz Sensor  
 Jaguar; XF; 2012-2009; W/433 MHz Sensor  
 Jaguar; XFR; 2011-2010; W/433 MHz Sensor  
 Jaguar; XJ; 2012-2010; W/433 MHz Sensor  
 Jaguar; XJ8; 2009-2004; W/433 MHz Sensor  
 Jaguar; XJR; 2009-2004; W/433 MHz Sensor  
 Jaguar; XK; 2012-2007; W/433 MHz Sensor  
 Jaguar; XKR; 2011-2007; W/433 MHz Sensor  
 Land Rover; LR3; 2009-2006; W/433 MHz Sensor  
 Land Rover; LR4; 2011-2010; W/433 MHz Sensor  
 Land Rover; Range Rover; 2011-2006; W/433 MHz Sensor

## 20092 (315 MHz)



Hyundai; Accent; 2013-2012  
 Hyundai; Genesis; 2012-2010; Coupe  
 Hyundai; Sonata; 2013-2011  
 Kia; Forte; 2013-2010  
 Kia; Optima; 2013-2011  
 Kia; Rio; 2012  
 Kia; Sorento; 2013-2011  
 Kia; Soul; 2012-2010

## 20093 (315 MHz)



Mazda; 2; 2012-2011  
 Mazda; 3; 2012-2004  
 Mazda; 5; 2012  
 Mazda; 5; 2010-2006  
 Mazda; 6; 2012-2008  
 Mazda; CX-7; 2011-2007  
 Mazda; CX-9; 2012-2007  
 Mazda; MX-5 Miata; 2012-2006  
 Mazda; RX-8; 2011-2004  
 Mazda; Tribute; 2011

# Numerical Listing Sensors/Transmitters

## 20094 (433 MHz)



Mercedes-Benz; CL63; 2009-2007  
 Mercedes-Benz; CL65; 2009-2008  
 Mercedes-Benz; CL550; 2009-2007  
 Mercedes-Benz; CL600; 2009-2007  
 Mercedes-Benz; CLS55; 2006  
 Mercedes-Benz; CLS63; 2011-2007  
 Mercedes-Benz; CLS500; 2006  
 Mercedes-Benz; CLS550; 2011-2007  
 Mercedes-Benz; E55; 2006  
 Mercedes-Benz; E63; 2009-2007  
 Mercedes-Benz; E320; 2009-2006  
 Mercedes-Benz; E350; 2009-2006; W/315 MHz Sensor  
 Mercedes-Benz; E500; 2006  
 Mercedes-Benz; E550; 2009-2007; W/315 MHz Sensor  
 Mercedes-Benz; S63; 2010-2007  
 Mercedes-Benz; S65; 2010-2007  
 Mercedes-Benz; S400; 2010  
 Mercedes-Benz; S550; 2010-2007  
 Mercedes-Benz; S600; 2010-2007  
 Mercedes-Benz; SL55; 2008-2006  
 Mercedes-Benz; SL63; 2011  
 Mercedes-Benz; SL63; 2009  
 Mercedes-Benz; SL65; 2011  
 Mercedes-Benz; SL65; 2009-2006  
 Mercedes-Benz; SL500; 2006  
 Mercedes-Benz; SL550; 2009-2007  
 Mercedes-Benz; SL600; 2009-2006  
 Mercedes-Benz; SLR McLaren; 2009-2008

## 20095 (433 MHz)



Mercedes-Benz; E350; 2009-2006; W/433 MHz Sensor  
 Mercedes-Benz; E550; 2009-2007; W/433 MHz Sensor  
 Mercedes-Benz; GL320; 2009-2007  
 Mercedes-Benz; GL450; 2009-2007  
 Mercedes-Benz; GL550; 2009-2008  
 Mercedes-Benz; ML63; 2009-2007  
 Mercedes-Benz; ML320; 2009-2007  
 Mercedes-Benz; ML350; 2009-2006  
 Mercedes-Benz; ML500; 2007-2006  
 Mercedes-Benz; ML550; 2009-2008  
 Mercedes-Benz; R63; 2007  
 Mercedes-Benz; R320; 2009-2007  
 Mercedes-Benz; R350; 2009-2006  
 Mercedes-Benz; R500; 2007-2006

## 20096 (433 MHz)



Ford; Expedition; 2004-2003  
 Ford; Explorer; 2005-2004  
 Ford; Explorer; 2003-2002; Exc. Sport  
 Lincoln; Aviator; 2005-2003  
 Lincoln; Navigator; 2004-2003  
 Mercury; Mountaineer; 2005-2002

## 20097 (433 MHz)



Volvo; C30; 2013-2007  
 Volvo; C70; 2013-2008  
 Volvo; S40; 2011-2008  
 Volvo; S60; 2013-2011  
 Volvo; S80; 2013-2007  
 Volvo; V50; 2011-2008  
 Volvo; V70; 2010-2008  
 Volvo; XC60; 2013-2010  
 Volvo; XC70; 2013-2008  
 Volvo; XC90; 2011-2010  
 Volvo; XC90; 2008

## 20098 (315 MHz)



Acura; MDX; 2013-2007  
 Acura; RDX; 2013-2007  
 Acura; TSX; 2012-2007  
 Honda; Pilot; 2013-2012; W/Alloy Wheels  
 Honda; Pilot; 2011-2010; Exc. LX  
 Honda; Pilot; 2009; W/Alloy Wheels

## 20099 (315 MHz)



Honda; Accord; 2012  
 Honda; Accord; 2011-2010; Exc. Crosstour  
 Honda; Accord; 2009-2008  
 Honda; CR-V; 2011-2007  
 Honda; Fit; 2008

# Numerical Listing Sensors/Transmitters

## 20100 (315 MHz)



Honda; Accord; 2011-2010; Crosstour  
Honda; Crosstour; 2012

## 20103 (433 MHz)



Audi; A6; 2010  
Audi; A6; 2009; Quattro  
Audi; Q7; 2012  
Audi; Q7; 2010  
Audi; R8; 2012  
Audi; R8; 2011  
Audi; R8; 2010  
Audi; S6; 2010  
Porsche; Cayenne; 2012-2011  
Volkswagen; Touareg; 2013; W/433 MHz Sensor  
Volkswagen; Touareg 2; 2012-2011; W/433 MHz Sensor  
Volkswagen; Touareg 2; 2010

## 20107 (315 MHz)



Cadillac; Escalade; 2006-2005  
Chevrolet; Avalanche; 2006-2005  
Chevrolet; Silverado Series Pickup; 2007; Classic  
Chevrolet; Silverado Series Pickup; 2006-2005  
Chevrolet; Suburban; 2006-2005  
Chevrolet; Tahoe; 2006-2005  
GMC; Sierra Series Pickup; 2007; Classic  
GMC; Sierra Series Pickup; 2006-2005  
GMC; Yukon; 2006-2005

## 20115 (315 MHz)



Cadillac; Escalade; 2004  
Chevrolet; Avalanche; 2004  
Chevrolet; Silverado Series Pickup; 2004  
Chevrolet; Suburban; 2004  
Chevrolet; Tahoe; 2004  
GMC; Sierra Series Pickup; 2004  
GMC; Yukon; 2004

## 20116 (315 MHz)



Buick; Rainier; 2007-2006; OEM Part No. 25774006  
Cadillac; CTS; 2007-2006; OEM Part No. 25774006  
Cadillac; CTS; 2005-2004  
Cadillac; SRX; 2006; OEM Part No. 25774006  
Cadillac; SRX; 2005-2004  
Chevrolet; SSR; 2006; OEM Part No. 25774006  
Chevrolet; Trailblazer; 2009-2006; OEM Part No. 25774006  
GMC; Envoy; 2007-2006  
Isuzu; Ascender; 2008-2006  
Saab; 9-7X; 2009-2005

## 20117 (315 MHz)



Cadillac; Deville; 2005-2001  
Cadillac; Seville; 2004-2001  
Chevrolet; Corvette; 2004-2001

## 20131 (315 MHz)



Chevrolet; Colorado; 2012-2007  
GMC; Canyon; 2012-2007  
Hummer; H3; 2010-2006  
Hummer; H3T; 2010-2009  
Isuzu; I-290; 2008-2007  
Isuzu; I-370; 2008-2007

## 20135 (315 MHz)



Ford; Expedition; 2006-2005  
Ford; Freestar; 2005-2004; W/Almm. Valve Stem  
Lincoln; Navigator; 2006-2005  
Mercury; Monterey Van; 2005-2004



# Numerical Listing Sensors/Transmitters

## 20153 (315 MHz)



Buick; Allure; 2009  
 Buick; Enclave; 2013-2009  
 Buick; LaCrosse; 2013-2012  
 Buick; LaCrosse; 2009  
 Buick; Lucerne; 2011-2007  
 Cadillac; CTS; 2013-2009; OEM Part No. 25920615; Exc. CTS V  
 Cadillac; CTS; 2008  
 Cadillac; DTS; 2011-2007  
 Cadillac; Escalade; 2013-2008  
 Cadillac; Escalade; 2007; Snap-In Style Only; Schrader Sensor;  
 W/Rubber Valve Stem  
 Cadillac; SRX; 2009-2007  
 Cadillac; STS; 2011-2010  
 Cadillac; STS; 2009; OEM Part No. 25920615; Exc. STS V  
 Chevrolet; Avalanche; 2013-2008  
 Chevrolet; Avalanche; 2007; Snap-In Style Only; Schrader Sensor;  
 W/Rubber Valve Stem  
 Chevrolet; Aveo; 2012-2008  
 Chevrolet; Aveo; 2007; Hatchback  
 Chevrolet; Captiva; 2013-2012  
 Chevrolet; Cobalt; 2009-2008; Snap-In Style Only; W/Rubber Valve Stem  
 Chevrolet; Express; 2013-2010  
 Chevrolet; HHR; 2011  
 Chevrolet; HHR; 2009-2008; Snap-In Style Only; W/Rubber Valve Stem  
 Chevrolet; Impala; 2013-2008  
 Chevrolet; Impala; 2007; Snap-In Style Only; W/Rubber Valve Stem  
 Chevrolet; Malibu; 2013-2011  
 Chevrolet; Malibu; 2009  
 Chevrolet; Malibu; 2008; Snap-In Style Only; W/Rubber Valve Stem  
 Chevrolet; Monte Carlo; 2007; Snap-In Style Only; W/Rubber Valve Stem  
 Chevrolet; Silverado Series Pickup; 2013-2008; W/Single Rear Wheels  
 Chevrolet; Silverado Series Pickup; 2007; Snap-In Style Only;  
 Schrader Sensor; W/Rubber Valve Stem; Exc. Classic  
 Chevrolet; Suburban; 2013-2008  
 Chevrolet; Suburban; 2007; Snap-In Style Only; Schrader Sensor;  
 W/Rubber Valve Stem  
 Chevrolet; Tahoe; 2013-2008  
 Chevrolet; Tahoe; 2007; Snap-In Style Only; Schrader Sensor;  
 W/Rubber Valve Stem  
 Chevrolet; Traverse; 2013-2009  
 GMC; Acadia; 2013-2009  
 GMC; Envoy; 2009-2008  
 GMC; Savana; 2013-2010  
 GMC; Sierra Series Pickup; 2013-2008; W/Single Rear Wheels  
 GMC; Sierra Series Pickup; 2007; Snap-In Style Only; Schrader Sensor;  
 W/Rubber Valve Stem; Exc. Classic  
 GMC; Yukon; 2013-2008  
 GMC; Yukon; 2007; Snap-In Style Only; Schrader Sensor;  
 W/Rubber Valve Stem  
 Hummer; H2; 2010-2008  
 Pontiac; G3; 2010-2009  
 Pontiac; G3 Wave; 2009  
 Pontiac; G5; 2010-2009  
 Pontiac; G6; 2010-2009  
 Pontiac; G8; 2010-2008  
 Pontiac; Grand Prix; 2008; Snap-In Style Only; W/Rubber Valve Stem  
 Pontiac; Wave; 2009-2008  
 Saturn; Aura; 2010-2008  
 Saturn; Outlook; 2010-2009

## 20153 (315 MHz) - Continued

Saturn; VUE; 2010-2007  
 Suzuki; Forenza; 2008-2007  
 Suzuki; Reno; 2008-2007

## 20156 (315 MHz)



Volvo; S60; 2009-2006  
 Volvo; S60; 2005-2004; W/315 MHz Sensor  
 Volvo; S80; 2006-2004  
 Volvo; V70; 2007-2004; W/315 MHz Sensor  
 Volvo; XC70; 2007-2004; W/315 MHz Sensor  
 Volvo; XC90; 2009; W/315 MHz Sensor  
 Volvo; XC90; 2007-2005; W/315 MHz Sensor  
 Volvo; XC90; 2004

## 20158 (315 MHz)



Buick; Allure; 2008-2007  
 Buick; Enclave; 2008  
 Buick; LaCrosse; 2008-2007  
 Cadillac; CTS; 2013-2009; OEM Part No. 15268606; CTS V;  
 W/315 MHz Sensor  
 Cadillac; DTS; 2006  
 Cadillac; Escalade; 2007; Clamp-In Style Only; TRW Sensor;  
 W/Almm. Valve Stem  
 Chevrolet; Avalanche; 2007; Clamp-In Style Only; TRW Sensor;  
 W/Almm. Valve Stem  
 Chevrolet; Caprice; 2013-2011  
 Chevrolet; Cobalt; 2009-2008; Clamp-In Style Only; W/Almm. Valve Stem  
 Chevrolet; Corvette; 2013-2010  
 Chevrolet; Equinox; 2009-2007  
 Chevrolet; Express; 2009-2008  
 Chevrolet; HHR; 2009-2008; Clamp-In Style Only; W/Almm. Valve Stem  
 Chevrolet; Impala; 2007; Clamp-In Style Only; W/Almm. Valve Stem  
 Chevrolet; Impala; 2006; W/Alloy Wheels  
 Chevrolet; Malibu; 2008; Clamp-In Style Only; W/Almm. Valve Stem  
 Chevrolet; Monte Carlo; 2007; Clamp-In Style Only; W/Almm. Valve Stem  
 Chevrolet; Monte Carlo; 2006; W/Alloy Wheels  
 Chevrolet; Silverado Series Pickup; 2007; Clamp-In Style Only;  
 TRW Sensor; W/Almm. Valve Stem; Exc. Classic  
 Chevrolet; Suburban; 2007; Clamp-In Style Only; TRW Sensor;  
 W/Almm. Valve Stem  
 Chevrolet; Tahoe; 2007; Clamp-In Style Only; TRW Sensor;  
 W/Almm. Valve Stem  
 Chevrolet; Uplander; 2009-2008  
 GMC; Acadia; 2008-2007  
 GMC; Savana; 2009-2008  
 GMC; Sierra Series Pickup; 2007; Clamp-In Style Only; TRW Sensor;  
 W/Almm. Valve Stem; Exc. Classic  
 GMC; Yukon; 2007; Clamp-In Style Only; TRW Sensor;  
 W/Almm. Valve Stem  
 Pontiac; G5; 2008

# Numerical Listing Sensors/Transmitters

## 20158 (315 MHz) - Continued

Pontiac; G6; 2008  
 Pontiac; Grand Prix; 2008; Clamp-In Style Only; W/Almm. Valve Stem  
 Pontiac; Grand Prix; 2007  
 Pontiac; Montana; 2009-2008  
 Pontiac; Solstice; 2010-2008  
 Pontiac; Torrent; 2009-2007  
 Saturn; Aura; 2007  
 Saturn; Outlook; 2008-2007  
 Saturn; Sky; 2010-2008  
 Suzuki; XL-7; 2009-2007

## 20159 (433 MHz)



Saab; 9-3; 2012-2008  
 Saab; 9-5; 2012-2008

## 20161 (315 MHz)



Infiniti; QX56; 2007; Mar. & Older  
 Infiniti; QX56; 2006-2005; W/Alloy Wheels  
 Nissan; Armada; 2008; SE  
 Nissan; Armada; 2007  
 Nissan; Armada; 2006-2005; W/Alloy Wheels  
 Nissan; Frontier; 2008-2005; W/Alloy Wheels  
 Nissan; Maxima; 2007; Mar. & Older  
 Nissan; Maxima; 2006; Jun. & Newer  
 Nissan; Pathfinder; 2006-2005  
 Nissan; Quest; 2006-2005; W/Alloy Wheels  
 Nissan; Sentra; 2007; W/Alloy Wheels  
 Nissan; Titan; 2007; Mar. & Older  
 Nissan; Titan; 2006  
 Nissan; Titan; 2005; Apr. 1 & Newer  
 Nissan; Xterra; 2006; Exc. Submodel X  
 Nissan; Xterra; 2005

## 20315 (315 MHz)



Ford; C-MAX; 2013  
 Ford; E450 Super Duty; 2010  
 Ford; E Series Van; 2013-2011  
 Ford; E Series Van; 2010; W/Steel Wheels  
 Ford; Edge; 2013-2011  
 Ford; Escape; 2013-2009  
 Ford; Expedition; 2013-2011  
 Ford; Explorer; 2013-2011

## 20315 (315 MHz) - Continued

Ford; F Series Pickup; 2013-2009  
 Ford; Fiesta; 2013-2011  
 Ford; Flex; 2013-2011  
 Ford; Focus; 2013-2010  
 Ford; Fusion; 2013-2010  
 Ford; Mustang; 2013-2010  
 Ford; Super Duty Pickup; 2012-2011  
 Ford; Super Duty Van; 2011  
 Ford; Super Duty Van; 2010; W/Steel Wheels  
 Ford; Taurus; 2013-2011  
 Ford; Taurus; 2010; May & Newer  
 Ford; Transit Connect; 2013-2010  
 Lincoln; Mark LT; 2009  
 Lincoln; MKS; 2013-2011  
 Lincoln; MKT; 2013-2011  
 Lincoln; MKX; 2013-2011  
 Lincoln; MKZ; 2013-2010  
 Lincoln; Navigator; 2013-2011  
 Lincoln; Town Car; 2011  
 Mazda; Tribute; 2010-2009  
 Mercury; Grand Marquis; 2011  
 Mercury; Mariner; 2011-2009  
 Mercury; Milan; 2011-2010

## 20335 (315 MHz)



Chrysler; Pacifica; 2005  
 Chrysler; Pacifica; 2004; OEM Part No. 04727392AD  
 Chrysler; Town & Country Van; 2005-2004  
 Dodge; Caravan; 2005-2004  
 Dodge; Grand Caravan; 2005-2004

## 20398 (433 MHz)



Chrysler; 300; 2012; W/Rubber Stem Snap-in Sensor  
 Chrysler; 300; 2011  
 Chrysler; Town & Country Van; 2012-2011  
 Dodge; Challenger; 2012-2010; W/Rubber Stem Snap-in Sensor  
 Dodge; Charger; 2012  
 Dodge; Charger; 2011-2010; W/Rubber Stem Snap-in Sensor  
 Dodge; Durango; 2012-2011  
 Dodge; Grand Caravan; 2012-2011  
 Dodge; Journey; 2012-2011  
 Dodge; Ram 4500HD; 2012  
 Dodge; Ram 5500HD; 2012  
 Dodge; Ram Series Pickup; 2012  
 Dodge; Ram Series Pickup; 2011-2010; W/Rubber Stem Snap-in Sensor  
 Fiat; 500; 2013-2012  
 Jeep; Grand Cherokee; 2012-2011  
 Jeep; Wrangler; 2013

# Numerical Listing Sensors/Transmitters

## 20398 (433 MHz) - Continued

Mitsubishi; Lancer; 2013-2011; W/Alloy Wheels  
Mitsubishi; Outlander; 2013-2011; W/Alloy Wheels

## 20720 (433 MHz)



Acura; TL; 2012-2009

## 28004 (315 MHz)



Chrysler; Prowler; 2001  
Plymouth; Prowler; 2001-1999  
Plymouth; Prowler; 1997

## 28006 (315 MHz)



Chevrolet; Corvette; 2000-1997

## 28078 (433 MHz)



Saab; 9-3; 2007-2003  
Saab; 9-5; 2007-2003  
Saturn; Astra; 2008

## 28081 (433 MHz)



BMW; 128i; 2012  
BMW; 135i; 2013-2012  
BMW; 135iS; 2013  
BMW; 328i; 2013-2010  
BMW; 335D; 2012-2010

## 28081 (433 MHz) - Continued

BMW; 335i; 2013-2010  
BMW; 335iS; 2013-2012  
BMW; 335Xi; 2010  
BMW; 528i; 2013-2012  
BMW; 535i; 2013-2012  
BMW; 550i; 2013-2012  
BMW; 640i; 2013-2012  
BMW; 650i; 2013-2012  
BMW; 740i; 2013-2012  
BMW; 740Li; 2013-2012  
BMW; 750i; 2013-2012  
BMW; 750Li; 2013-2012  
BMW; ActiveE; 2012  
BMW; M1; 2012  
BMW; M3; 2013-2010  
BMW; M5; 2013  
BMW; M6; 2013  
BMW; X1; 2013-2012  
BMW; X3; 2013-2012  
BMW; X5; 2013-2012  
BMW; X6; 2013-2012  
BMW; Z4; 2013-2012  
Mini; Cooper; 2012-2010

## 28082 (433 MHz)



BMW; X5; 2004-2000  
Land Rover; LR3; 2005  
Land Rover; Range Rover; 2005-2002

## 28087 (433 MHz)



Porsche; 911; 2010  
Porsche; Boxster; 2010  
Porsche; Cayman; 2010-2009  
Porsche; Panamera; 2011-2010

## 28096 (315 MHz)



Mitsubishi; Lancer; 2013-2011; W/Steel Wheels  
Mitsubishi; Lancer; 2010-2008  
Mitsubishi; Outlander; 2013-2011; W/Steel Wheels  
Mitsubishi; Outlander; 2010-2007

# Numerical Listing Sensors/Transmitters

## 28129 (315 MHz)



Mitsubishi; Eclipse; 2012; W/Steel Wheels  
Mitsubishi; Eclipse; 2007-2006; W/Steel Wheels  
Mitsubishi; Galant; 2012-2007; W/Steel Wheels

## 28154 (315 MHz)



Dodge; Dakota; 2010-2008  
Dodge; Ram Series Pickup; 2008; 1500, 2500  
Mitsubishi; Raider; 2009-2008

## 28155 (433 MHz)



Chrysler; 300; 2008  
Chrysler; Town & Country Van; 2009-2008  
Dodge; Charger; 2008  
Dodge; Grand Caravan; 2010-2008  
Dodge; Journey; 2010-2009  
Dodge; Magnum; 2008  
Dodge; Ram Series Pickup; 2010; 1500, 2500;  
W/Metal Stem Clamp-in Sensor  
Dodge; Ram Series Pickup; 2009; 1500, 2500  
Jeep; Commander; 2010-2008  
Jeep; Grand Cherokee; 2010-2008  
Jeep; Liberty; 2009; Exc. Sport  
Jeep; Wrangler; 2010-2009

## 28167 (315 MHz)



Nissan; Pathfinder; 2007; OEM Part No. 40700JA01A  
Nissan; Versa; 2007; OEM Part No. 40700JA01A  
Nissan; Xterra; 2007; OEM Part No. 40700JA01A

## 28203 (315 MHz)



Subaru; Forester; 2013-2008  
Subaru; Impreza; 2013-2008  
Subaru; Legacy; 2013-2009  
Subaru; Legacy; 2008; W/18" Wheels  
Subaru; Outback; 2013-2008  
Subaru; Tribeca; 2012  
Subaru; Tribeca; 2011-2008; W/Rubber Stem Snap-in Sensor  
Subaru; XV Crosstrek; 2013

## 28204 (315 MHz)



Infiniti; FX35; 2008  
Infiniti; FX35; 2007; Jul. & Newer  
Infiniti; FX45; 2008  
Infiniti; FX45; 2007; Jul. & Newer  
Infiniti; G35; 2007; Coupe  
Infiniti; M35; 2010-2008  
Infiniti; M45; 2010-2008  
Infiniti; Q45; 2006; Aug. & Newer  
Infiniti; QX56; 2010-2008  
Infiniti; QX56; 2007; Apr. 1 & Newer  
Nissan; 350Z; 2009-2007  
Nissan; Altima; 2012-2007  
Nissan; Altima; 2006; Oct. 1 & Newer  
Nissan; Armada; 2013-2009  
Nissan; Armada; 2008; LE  
Nissan; Cube; 2013-2011  
Nissan; Cube; 2009  
Nissan; Frontier; 2013-2009  
Nissan; Frontier; 2008; W/Steel Wheels  
Nissan; GT-R; 2013-2011  
Nissan; GT-R; 2009  
Nissan; Juke; 2012-2011  
Nissan; Maxima; 2012-2008  
Nissan; Maxima; 2007; Apr. 1 & Newer  
Nissan; Murano; 2012-2009  
Nissan; Murano; 2007  
Nissan; Pathfinder; 2012-2008  
Nissan; Pathfinder; 2007; OEM Part No. 40700JA01B  
Nissan; Quest; 2009-2007  
Nissan; Rogue; 2012-2011  
Nissan; Rogue; 2009-2008  
Nissan; Sentra; 2013-2008  
Nissan; Sentra; 2007; W/Steel Wheels  
Nissan; Titan; 2013-2008  
Nissan; Titan; 2007; Apr. 1 & Newer  
Nissan; Versa; 2012-2008  
Nissan; Versa; 2007; OEM Part No. 40700JA01B  
Nissan; Xterra; 2013-2008  
Nissan; Xterra; 2007; OEM Part No. 40700JA01B  
Suzuki; Equator; 2013-2009

# Numerical Listing Sensors/Transmitters

## 28206 (314.9 MHz)



Buick; Allure; 2010  
 Buick; LaCrosse; 2011-2010  
 Buick; Regal; 2013-2011  
 Buick; Verano; 2013-2012  
 Cadillac; SRX; 2013-2010  
 Cadillac; XTS; 2013  
 Chevrolet; Camaro; 2013-2012; Exc. ZL1  
 Chevrolet; Camaro; 2011-2010  
 Chevrolet; Cobalt; 2010  
 Chevrolet; Cruze; 2013-2011  
 Chevrolet; Equinox; 2013-2010  
 Chevrolet; HHR; 2010  
 Chevrolet; Malibu; 2010  
 Chevrolet; Orlando; 2012  
 Chevrolet; Sonic; 2013-2012  
 Chevrolet; Spark; 2013  
 Chevrolet; Volt; 2013-2011  
 GMC; Terrain; 2013-2010  
 Saab; 9-4X; 2012-2011  
 Saturn; Astra; 2010-2009

## 28210 (315 MHz)



Infiniti; EX35; 2010-2008  
 Infiniti; FX35; 2010-2009  
 Infiniti; FX50; 2010-2009  
 Infiniti; G35; 2008  
 Infiniti; G35; 2007; Sedan  
 Infiniti; G37; 2010-2008  
 Nissan; 370Z; 2010-2009

## 28214 (433 MHz)



Mercedes-Benz; C63; 2013-2008  
 Mercedes-Benz; C250; 2013-2012  
 Mercedes-Benz; C280; 2007; Mar. & Newer  
 Mercedes-Benz; C300; 2013-2008  
 Mercedes-Benz; C350; 2013-2008  
 Mercedes-Benz; C350; 2007; Jun. & Newer  
 Mercedes-Benz; CL63; 2013-2010  
 Mercedes-Benz; CL65; 2013-2010  
 Mercedes-Benz; CL550; 2013-2010  
 Mercedes-Benz; CL600; 2013-2012  
 Mercedes-Benz; CL600; 2010

## 28214 (433 MHz) - Continued

Mercedes-Benz; CLK55; 2006  
 Mercedes-Benz; CLK63; 2009-2007  
 Mercedes-Benz; CLK350; 2009-2006  
 Mercedes-Benz; CLK500; 2006  
 Mercedes-Benz; CLK550; 2009-2007  
 Mercedes-Benz; CLS63; 2013-2012  
 Mercedes-Benz; CLS550; 2013-2012  
 Mercedes-Benz; E63; 2013-2010  
 Mercedes-Benz; E350; 2013-2010  
 Mercedes-Benz; E550; 2013-2010  
 Mercedes-Benz; G55; 2011-2008  
 Mercedes-Benz; G55; 2007; Mar. & Newer  
 Mercedes-Benz; G500; 2008  
 Mercedes-Benz; G500; 2007; Mar. & Newer  
 Mercedes-Benz; G550; 2013-2009  
 Mercedes-Benz; GL63; 2013  
 Mercedes-Benz; GL350; 2012-2010  
 Mercedes-Benz; GL450; 2013-2010  
 Mercedes-Benz; GL550; 2013-2010  
 Mercedes-Benz; GLK350; 2013-2010  
 Mercedes-Benz; ML63; 2013-2010  
 Mercedes-Benz; ML350; 2013-2010  
 Mercedes-Benz; ML450; 2011-2010  
 Mercedes-Benz; ML550; 2011-2010  
 Mercedes-Benz; R350; 2013-2010  
 Mercedes-Benz; S63; 2013-2011  
 Mercedes-Benz; S65; 2013-2011  
 Mercedes-Benz; S350; 2013-2012  
 Mercedes-Benz; S400; 2013-2011  
 Mercedes-Benz; S550; 2013-2011  
 Mercedes-Benz; S600; 2013-2011  
 Mercedes-Benz; SL63; 2013-2012  
 Mercedes-Benz; SL550; 2013-2012  
 Mercedes-Benz; SLK55; 2010-2008  
 Mercedes-Benz; SLK55; 2007; May & Newer  
 Mercedes-Benz; SLK250; 2013-2012  
 Mercedes-Benz; SLK280; 2008  
 Mercedes-Benz; SLK280; 2007; May & Newer  
 Mercedes-Benz; SLK300; 2011-2009  
 Mercedes-Benz; SLK350; 2013-2008  
 Mercedes-Benz; SLK350; 2007; May & Newer  
 Mercedes-Benz; SLS; 2013-2011  
 Smart; Fortwo; 2013-2008

## 28291 (433 MHz)



Chrysler; 300; 2010-2009  
 Dodge; Challenger; 2012-2010; W/Metal Stem Clamp-in Sensor  
 Dodge; Challenger; 2009-2008  
 Dodge; Charger; 2010; W/Metal Stem Clamp-in Sensor  
 Dodge; Charger; 2009



# Numerical Listing Sensors/Transmitters

## 28300 (315 MHz)



Toyota; Sequoia; 2007-2004; W/Steel Wheels;  
W/40 Deg. Angled Valve Sensor  
Toyota; Tacoma; 2005; W/40 Deg. Angled Valve Sensor; Nov. 30 & Older  
Toyota; Tundra; 2006; W/40 Deg. Angled Valve Sensor; Oct. 31 & Older  
Toyota; Tundra; 2005; W/40 Deg. Angled Valve Sensor

## 28305 (315 MHz)



Toyota; Sequoia; 2007-2004; W/Alloy Wheels  
Toyota; Sequoia; 2007-2004; W/Steel Wheels;  
W/20 Deg. Angled Valve Sensor  
Toyota; Tacoma; 2005; W/20 Deg. Angled Valve Sensor; Nov. 30 & Older  
Toyota; Tundra; 2006; W/20 Deg. Angled Valve Sensor; Oct. 31 & Older  
Toyota; Tundra; 2005; W/20 Deg. Angled Valve Sensor

## 28308 (315 MHz)



Chrysler; 200; 2012-2011  
Chrysler; 300; 2006-2005  
Chrysler; Aspen; 2009-2007  
Chrysler; Crossfire; 2005; OEM Part No. 5142340AA  
Chrysler; Pacifica; 2008-2006  
Chrysler; PT Cruiser; 2010-2008  
Chrysler; Sebring; 2010-2007  
Chrysler; Town & Country Van; 2007-2006  
Dodge; Avenger; 2012-2008  
Dodge; Caliber; 2011-2007  
Dodge; Caravan; 2007-2006  
Dodge; Charger; 2007-2006  
Dodge; Dakota; 2011  
Dodge; Durango; 2009-2007  
Dodge; Grand Caravan; 2007-2006  
Dodge; Magnum; 2007-2005  
Dodge; Nitro; 2011-2007  
Jeep; Commander; 2007-2006  
Jeep; Compass; 2013-2007  
Jeep; Grand Cherokee; 2007-2005  
Jeep; Liberty; 2012-2010  
Jeep; Liberty; 2009; Sport  
Jeep; Liberty; 2008-2005  
Jeep; Patriot; 2012-2007  
Jeep; Wrangler; 2012-2011  
Jeep; Wrangler; 2008-2007  
Suzuki; Kizashi; 2012-2010

## 28310 (315 MHz)



Lexus; SC430; 2006; W/White I.D. Mark; Jul. & Older  
Lexus; SC430; 2005-2002; W/White I.D. Mark

## 28315 (315 MHz)



Lexus; SC430; 2006; W/Blue I.D. Mark; Jul. & Older  
Lexus; SC430; 2005-2002; W/Blue I.D. Mark

## 28320 (315 MHz)



Lexus; SC430; 2006; W/Red I.D. Mark; Jul. & Older  
Lexus; SC430; 2005-2002; W/Red I.D. Mark

## 28325 (315 MHz)



Lexus; SC430; 2006; W/Gold I.D. Mark; Jul. & Older  
Lexus; SC430; 2005-2002; W/Gold I.D. Mark

## 28335 (315 MHz)



Lexus; GS300; 2006  
Lexus; GS430; 2006; Jun. & Older  
Lexus; GS430; 2005  
Lexus; GX470; 2006; Feb. & Newer; W/O Valve Cap  
Lexus; IS250; 2006; Mar. & Older  
Lexus; IS350; 2006; Mar. & Older  
Toyota; 4 Runner; 2006; OEM Part No. 4260730030

# Numerical Listing Sensors/Transmitters

## 28342 (315 MHz)



Nissan; NV; 2013-2011

## 28345 (315 MHz)



Lexus; GX470; 2006; Jan. 31 & Older  
Lexus; GX470; 2005-2004  
Lexus; HS250h; 2012-2010  
Toyota; 4 Runner; 2006; OEM Part No. 4260735010  
Toyota; 4 Runner; 2005-2003

## 28355 (315 MHz)



Toyota; Tacoma; 2006; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor; Jul. & Older  
Toyota; Tacoma; 2005; W/20 Deg. Angled Valve Sensor; Dec. 1 & Newer

## 28360 (315 MHz)



Pontiac; Vibe; 2010-2008  
Toyota; Avalon; 2012-2007  
Toyota; Avalon; 2006; Aug. & Newer  
Toyota; Camry; 2013-2012  
Toyota; Camry; 2011-2007; Models made in USA.;  
OEM Part No. 4260706011  
Toyota; Corolla; 2013-2009; Models made in USA.; W/16" Or 17" Wheels  
Toyota; Corolla; 2008; Models made in USA.; OEM Part No. 4260706011  
Toyota; Corolla; 2007; Models made in USA.; OEM Part No. 4260706011;  
Jun. & Newer  
Toyota; Highlander; 2013-2011  
Toyota; Matrix; 2013-2008; Models made in USA.;  
OEM Part No. 4260706011  
Toyota; Matrix; 2007; Models made in USA.; OEM Part No. 4260706011;  
Jun. & Newer  
Toyota; Solara; 2008-2007  
Toyota; Solara; 2006; May & Newer  
Toyota; Tacoma; 2013-2007; W/Alloy Wheels;  
W/20 Deg. Angled Valve Sensor

## 28360 (315 MHz) - Continued

Toyota; Tacoma; 2006; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor;  
Aug. & Newer  
Toyota; Venza; 2013-2009  
Toyota; Yaris; 2013

## 28362 (315 MHz)



Volvo; XC90; 2013-2012

## 28365 (315 MHz)



Lexus; GX470; 2006; Feb. & Newer; W/Valve Cap  
Lexus; LX470; 2006; Jul. & Older  
Lexus; LX470; 2005  
Scion; iQ; 2013-2011  
Scion; TC; 2013-2007  
Scion; TC; 2006; May & Newer  
Scion; XB; 2013-2008  
Scion; XD; 2013-2008  
Toyota; 4 Runner; 2009; W/Valve Cap  
Toyota; 4 Runner; 2008; W/Valve Cap; OEM Part No. 4260733011  
Toyota; 4 Runner; 2007; W/Valve Cap  
Toyota; 4 Runner; 2006; OEM Part No. 4260733011  
Toyota; Camry; 2011-2007; Models made in Japan.;  
OEM Part No. 4260733011  
Toyota; Corolla; 2013; Models made in Japan.  
Toyota; Corolla; 2012-2008; Models made in Japan.;  
OEM Part No. 4260733011  
Toyota; Corolla; 2012-2009; Models made in USA.; W/15" Wheels  
Toyota; Corolla; 2007; Models made in Japan.; OEM Part No. 4260733011;  
Jun. & Newer  
Toyota; FJ Cruiser; 2013-2008  
Toyota; Highlander; 2010-2008  
Toyota; Highlander; 2007; May & Newer  
Toyota; Land Cruiser; 2013-2006  
Toyota; Land Cruiser; 2005; May & Newer  
Toyota; Matrix; 2013-2008; Models made in Japan.;  
OEM Part No. 4260733011  
Toyota; Matrix; 2007; Models made in Japan.; OEM Part No. 4260733011;  
Jun. & Newer  
Toyota; Prius; 2013-2006  
Toyota; RAV4; 2006  
Toyota; Yaris; 2012-2008  
Toyota; Yaris; 2007; Aug. & Newer

# Numerical Listing Sensors/Transmitters

## 28370 (315 MHz)



Lexus; CT200h; 2012-2011  
 Lexus; ES350; 2013-2007  
 Lexus; GS350; 2013  
 Lexus; GS350; 2011-2007  
 Lexus; GS430; 2007  
 Lexus; GS430; 2006; Jul. & Newer  
 Lexus; GS450h; 2013  
 Lexus; GS450h; 2011-2007  
 Lexus; GS460; 2011-2008  
 Lexus; GX460; 2013-2010  
 Lexus; GX470; 2009-2007  
 Lexus; IS250; 2013-2007  
 Lexus; IS250; 2006; Apr. 1 & Newer  
 Lexus; IS350; 2013-2007  
 Lexus; IS350; 2006; Apr. 1 & Newer  
 Lexus; IS F; 2013-2008  
 Lexus; LFA; 2013-2011  
 Lexus; LS460; 2013-2007  
 Lexus; LS600h; 2013-2008  
 Lexus; LX470; 2007  
 Lexus; LX470; 2006; Aug. & Newer  
 Lexus; LX570; 2013  
 Lexus; LX570; 2011-2008  
 Lexus; RX330; 2006; Models made in Japan.; Feb. & Newer  
 Lexus; RX350; 2013-2011  
 Lexus; RX350; 2010-2007; Models made in Japan.  
 Lexus; RX400h; 2009-2007; Models made in Japan.  
 Lexus; RX450h; 2013-2010  
 Lexus; SC430; 2010-2007  
 Lexus; SC430; 2006; Aug. & Newer  
 Toyota; 4 Runner; 2013-2010  
 Toyota; 4 Runner; 2009; W/O Valve Cap  
 Toyota; 4 Runner; 2008; W/O Valve Cap; OEM Part No. 4260733021  
 Toyota; 4 Runner; 2007; W/O Valve Cap  
 Toyota; 4 Runner; 2006; OEM Part No. 4260733021  
 Toyota; Corolla; 2012-2009; Models made in Japan.;  
 OEM Part No. 4260733021  
 Toyota; RAV4; 2012-2007

## 28380 (315 MHz)



Toyota; Tacoma; 2013-2006; W/Steel Wheels;  
 W/40 Deg. Angled Valve Sensor  
 Toyota; Tacoma; 2005; W/40 Deg. Angled Valve Sensor; Dec. 1 & Newer

## 28385 (315 MHz)



Ford; Crown Victoria; 2011-2006  
 Ford; E Series Van; 2007  
 Ford; Edge; 2008-2007; W/Chrome Plated Almm. Wheels  
 Ford; Escape; 2008-2006  
 Ford; Escape; 2005; Oct. 3, 2005 & Newer  
 Ford; Explorer; 2010-2006  
 Ford; Explorer Sport Trac; 2010-2007  
 Ford; F Series Pickup; 2008; W/O H.D. Payload Pkg.  
 Ford; F Series Pickup; 2007  
 Ford; Focus; 2007  
 Ford; Freestar; 2007-2006  
 Ford; Fusion; 2009-2007  
 Ford; Grand Marquis; 2010-2006  
 Ford; Mustang; 2009-2007  
 Ford; Ranger; 2011-2007  
 Lincoln; Mark LT; 2008-2007  
 Lincoln; MKX; 2008-2007; W/Chrome Plated Almm. Wheels  
 Lincoln; MKZ; 2009-2007  
 Lincoln; Town Car; 2010-2006  
 Mazda; B2300 Pickup; 2009-2007  
 Mazda; B3000 Pickup; 2008-2007  
 Mazda; B4000 Pickup; 2009-2007  
 Mazda; Tribute; 2008  
 Mazda; Tribute; 2006  
 Mercury; Grand Marquis; 2010-2006  
 Mercury; Mariner; 2008-2006  
 Mercury; Mariner; 2005; Oct. 3, 2005 & Newer  
 Mercury; Milan; 2009-2007  
 Mercury; Monterey Van; 2007-2006  
 Mercury; Mountaineer; 2010-2006

## 28390 (315 MHz)



Ford; Edge; 2010-2009  
 Ford; Edge; 2008-2007; W/O Chrome Plated Almm. Wheels  
 Ford; Expedition; 2010-2007  
 Ford; Five Hundred; 2007-2006  
 Ford; Flex; 2010-2009  
 Ford; Focus; 2009-2008  
 Ford; Taurus; 2010; Apr. & Older  
 Ford; Taurus; 2009-2008  
 Ford; Taurus X; 2009-2008  
 Lincoln; MKS; 2010-2009  
 Lincoln; MKT; 2010  
 Lincoln; MKX; 2010-2009  
 Lincoln; MKX; 2008-2007; W/O Chrome Plated Almm. Wheels  
 Lincoln; Navigator; 2010-2007  
 Mercury; Montego; 2007-2006  
 Mercury; Sable; 2009-2008

# Numerical Listing Sensors/Transmitters

## 28395 (315 MHz)



Ford; E450 Super Duty; 2009-2008  
 Ford; E Series Van; 2010; W/Alloy Wheels  
 Ford; E Series Van; 2009-2008  
 Ford; F450 Super Duty; 2010-2008  
 Ford; F550 Super Duty; 2010  
 Ford; F Series Pickup; 2008; W/H.D. Payload Pkg.  
 Ford; Super Duty Pickup; 2010-2008  
 Ford; Super Duty Van; 2010; W/Alloy Wheels  
 Ford; Super Duty Van; 2009-2008

## 28423 (314.9 MHz)



Chevrolet; Camaro; 2013-2012; ZL1

## 28434 (433 MHz)



Chrysler; 300; 2008-2007  
 Chrysler; Town & Country Van; 2009-2008  
 Dodge; Charger; 2008  
 Dodge; Grand Caravan; 2010-2008  
 Dodge; Journey; 2010-2009  
 Dodge; Magnum; 2008  
 Dodge; Ram Series Pickup; 2010; 1500, 2500;  
 W/Metal Stem Clamp-in Sensor  
 Dodge; Ram Series Pickup; 2009; 1500, 2500  
 Jeep; Commander; 2010-2008  
 Jeep; Grand Cherokee; 2010-2008  
 Jeep; Liberty; 2009; Exc. Sport  
 Jeep; Wrangler; 2010-2009

## 28461 (315 MHz)



Dodge; Dakota; 2010-2008  
 Dodge; Ram Series Pickup; 2008; 1500, 2500  
 Mitsubishi; Raider; 2009-2008

## 28505 (315 MHz)



Hyundai; Veloster; 2013-2012

## 28670 (315 MHz)



Toyota; Sequoia; 2013-2008  
 Toyota; Sienna; 2013-2007  
 Toyota; Tundra; 2012-2011  
 Toyota; Tundra; 2010-2007; W/Alloy Wheels;  
 W/20 Deg. Angled Valve Sensor  
 Toyota; Tundra; 2006; W/20 Deg. Angled Valve Sensor; Nov. 1 & Newer

## 28720 (315 MHz)



Acura; CSX; 2011-2008  
 Honda; Civic; 2012-2008  
 Honda; CR-V; 2013-2012  
 Honda; CR-Z; 2013-2011  
 Honda; Element; 2011-2009  
 Honda; Fit; 2013-2009  
 Honda; Insight; 2012-2010  
 Honda; Odyssey; 2013-2011

## 28849 (315 MHz)



Hyundai; Accent; 2011-2008  
 Hyundai; Equus; 2012-2011  
 Hyundai; Genesis; 2012-2011; Sedan  
 Hyundai; Sonata; 2010-2009  
 Hyundai; Tucson; 2013-2010  
 Kia; Borrego; 2011-2009  
 Kia; Rio; 2011-2007  
 Kia; Spectra; 2009-2006  
 Kia; Sportage; 2012-2009

# Numerical Listing Sensors/Transmitters

## 28981 (315 MHz)



Acura; MDX; 2006-2004  
Acura; RL; 2011-2005  
Acura; TL; 2008-2005  
Honda; Odyssey; 2007-2005; Touring  
Honda; Pilot; 2008-2006  
Honda; Pilot; 2005; EX  
Honda; Pilot; 2005; LX; W/Short Stem Valve  
Honda; Ridgeline; 2012  
Honda; Ridgeline; 2011-2010; Exc. RT  
Honda; Ridgeline; 2011-2010; RT  
Honda; Ridgeline; 2009  
Honda; Ridgeline; 2008-2007; RTL, RTS, RTX  
Honda; Ridgeline; 2006; RTL, RTS

## 28982 (315 MHz)



Honda; Pilot; 2005; LX; W/Long Stem Valve  
Honda; Ridgeline; 2008-2006; RT

## 28983 (315 MHz)



Honda; Odyssey; 2010-2009  
Hyundai; Sonata; 2008-2007  
Hyundai; Tiburon; 2008-2007  
Hyundai; Tucson; 2009-2006  
Kia; Amanti; 2009-2007  
Kia; Sorento; 2009-2007  
Kia; Sportage; 2008-2006  
Kia; Sportage; 2005; Jun. 15, 2005 & Newer



# Numerical Listing

## Service Packs

### 2002



Ford; Expedition; 2006-2003  
 Ford; Explorer; 2005-2004  
 Ford; Explorer; 2003-2002; Exc. Sport  
 Ford; Freestar; 2005-2004; W/Almm. Valve Stem  
 Lincoln; Aviator; 2005-2003  
 Lincoln; Navigator; 2006-2003  
 Mercury; Monterey Van; 2005-2004  
 Mercury; Mountaineer; 2005-2002

### 2003



Cadillac; Deville; 2005-2001  
 Cadillac; Seville; 2004-2001  
 Chevrolet; Corvette; 2004-2001  
 Chrysler; 300M; 2004-2002; W/Schrader Sensor  
 Chrysler; Concorde; 2004-2002; W/Schrader Sensor  
 Chrysler; Crossfire; 2008-2006; W/Schrader Sensor  
 Chrysler; Crossfire; 2005; OEM Part No. 52088990AC  
 Chrysler; Crossfire; 2004; W/Schrader Sensor  
 Chrysler; Intrepid; 2004-2002; W/Schrader Sensor  
 Chrysler; Pacifica; 2004; OEM Part No. 52088990AC  
 Chrysler; Prowler; 2002; W/Schrader Sensor  
 Chrysler; Prowler; 2001; W/Red Sensor Body  
 Chrysler; Town & Country Van; 2003-2002  
 Chrysler; Voyager; 2003-2002  
 Dodge; Caravan; 2003-2002  
 Dodge; Grand Caravan; 2003-2002  
 Dodge; Intrepid; 2004-2002  
 Dodge; Viper; 2010-2008  
 Dodge; Viper; 2006-2003  
 Isuzu; Rodeo; 2004  
 Jeep; Grand Cherokee; 2004-2002  
 Jeep; Liberty; 2004-2002  
 Mitsubishi; Eclipse; 2012-2008  
 Mitsubishi; Eclipse; 2007-2006; W/Alloy Wheels  
 Mitsubishi; Endeavor; 2011-2010  
 Mitsubishi; Endeavor; 2008-2004  
 Mitsubishi; Galant; 2011-2007; W/Alloy Wheels  
 Mitsubishi; Galant; 2006-2004  
 Mitsubishi; Montero; 2006-2003  
 Plymouth; Prowler; 2001-1999; W/Red Sensor Body  
 Plymouth; Prowler; 1997; W/Red Sensor Body  
 Volvo; C30; 2013-2007  
 Volvo; C70; 2013-2008  
 Volvo; S40; 2011-2008  
 Volvo; S60; 2013-2011  
 Volvo; S80; 2013-2007  
 Volvo; V50; 2011-2008  
 Volvo; V70; 2010-2008  
 Volvo; XC60; 2013-2010  
 Volvo; XC70; 2013-2008  
 Volvo; XC90; 2011-2010

Volvo; XC90; 2008

### 2004



Buick; Allure; 2008-2007; W/Schrader Sensor  
 Buick; Enclave; 2008; W/Schrader Sensor  
 Buick; LaCrosse; 2008-2007; W/Schrader Sensor  
 Buick; Rainier; 2007-2006  
 Cadillac; CTS; 2013-2009; OEM Part No. 15268606;  
 CTS V; W/315 MHz Sensor  
 Cadillac; CTS; 2007-2004  
 Cadillac; DTS; 2006  
 Cadillac; Escalade; 2006-2004  
 Cadillac; SRX; 2006-2004  
 Cadillac; STS; 2008-2005  
 Cadillac; XLR; 2009-2004  
 Chevrolet; Avalanche; 2006-2004  
 Chevrolet; Camaro; 2013-2012; ZL1  
 Chevrolet; Caprice; 2013-2011  
 Chevrolet; Cobalt; 2009-2008; Clamp-In Style Only; W/Almm. Valve Stem  
 Chevrolet; Corvette; 2013-2005  
 Chevrolet; Equinox; 2009-2007; W/Schrader Sensor  
 Chevrolet; Express; 2009-2008; W/Schrader Sensor  
 Chevrolet; HHR; 2009-2008; Clamp-In Style Only; W/Almm. Valve Stem  
 Chevrolet; Impala; 2007; Clamp-In Style Only; W/Almm. Valve Stem  
 Chevrolet; Impala; 2006; W/Alloy Wheels  
 Chevrolet; Malibu; 2008; Clamp-In Style Only; W/Almm. Valve Stem  
 Chevrolet; Monte Carlo; 2007; Clamp-In Style Only; W/Almm. Valve Stem  
 Chevrolet; Monte Carlo; 2006; W/Alloy Wheels  
 Chevrolet; Silverado Series Pickup; 2007; Classic  
 Chevrolet; Silverado Series Pickup; 2006-2004  
 Chevrolet; SSR; 2006  
 Chevrolet; Suburban; 2006-2004  
 Chevrolet; Tahoe; 2006-2004  
 Chevrolet; Trailblazer; 2009-2006  
 Chevrolet; Uplander; 2009-2008  
 GMC; Acadia; 2008-2007; W/Schrader Sensor  
 GMC; Envoy; 2007-2006  
 GMC; Savana; 2009-2008; W/Schrader Sensor  
 GMC; Sierra Series Pickup; 2007; Classic  
 GMC; Sierra Series Pickup; 2006-2004  
 GMC; Yukon; 2006-2004  
 Isuzu; Ascender; 2008-2006  
 Pontiac; G5; 2008; W/Schrader Sensor  
 Pontiac; G6; 2008; W/Schrader Sensor  
 Pontiac; Grand Prix; 2008; Clamp-In Style Only; W/Almm. Valve Stem  
 Pontiac; Grand Prix; 2007; W/Schrader Sensor  
 Pontiac; Montana; 2009-2008; W/Schrader Sensor  
 Pontiac; Solstice; 2010-2008; W/Schrader Sensor  
 Pontiac; Torrent; 2009-2007; W/Schrader Sensor  
 Saab; 9-7X; 2009-2005  
 Saturn; Aura; 2007; W/Schrader Sensor  
 Saturn; Outlook; 2008-2007; W/Schrader Sensor  
 Saturn; Sky; 2010-2008; W/Schrader Sensor  
 Suzuki; XL-7; 2009-2007; W/Schrader Sensor

# Numerical Listing

## Service Packs

### 2005



Infiniti; QX56; 2006-2005; W/Steel Wheels  
 Infiniti; QX56; 2004  
 Nissan; Armada; 2006-2005; W/Steel Wheels  
 Nissan; Frontier; 2007-2005; W/Steel Wheels  
 Nissan; Pathfinder; 2004; Armada  
 Nissan; Pathfinder; 2004; Exc. Armada; Aug. & Newer  
 Nissan; Quest; 2006-2005; W/Steel Wheels  
 Nissan; Quest; 2004  
 Nissan; Titan; 2005; Mar. & Older  
 Nissan; Titan; 2004  
 Nissan; Xterra; 2006; Submodel X

### 2006



Chevrolet; Colorado; 2012-2007  
 GMC; Canyon; 2012-2007  
 Hummer; H3; 2010-2006  
 Hummer; H3T; 2010-2009  
 Isuzu; I-290; 2008-2007  
 Isuzu; I-370; 2008-2007

### 2007



Infiniti; FX35; 2007; Jun. & Older  
 Infiniti; FX35; 2006-2003  
 Infiniti; FX45; 2007; Jun. & Older  
 Infiniti; FX45; 2006-2003  
 Infiniti; G35; 2006-2004  
 Infiniti; G35; 2003; Jun. & Newer  
 Infiniti; M35; 2007-2006  
 Infiniti; M45; 2007-2006  
 Infiniti; M45; 2004-2003  
 Infiniti; Q45; 2006; Jul. & Older  
 Infiniti; Q45; 2005-2003  
 Infiniti; QX4; 2003  
 Infiniti; QX56; 2007; Mar. & Older  
 Infiniti; QX56; 2006-2005; W/Alloy Wheels  
 Nissan; 350Z; 2006-2003  
 Nissan; Armada; 2008; SE  
 Nissan; Armada; 2007  
 Nissan; Armada; 2006-2005; W/Alloy Wheels  
 Nissan; Frontier; 2008-2005; W/Alloy Wheels  
 Nissan; Frontier; 2004-2003  
 Nissan; Maxima; 2007; Mar. & Older  
 Nissan; Maxima; 2006; Jun. & Newer

### 2007 - Continued

Nissan; Murano; 2006-2003  
 Nissan; Pathfinder; 2006-2005  
 Nissan; Pathfinder; 2004; Exc. Armada; Jul. & Older  
 Nissan; Pathfinder; 2003  
 Nissan; Quest; 2006-2005; W/Alloy Wheels  
 Nissan; Sentra; 2007; W/Alloy Wheels  
 Nissan; Titan; 2007; Mar. & Older  
 Nissan; Titan; 2006  
 Nissan; Titan; 2005; Apr. 1 & Newer  
 Nissan; Xterra; 2006; Exc. Submodel X  
 Nissan; Xterra; 2005-2003

### 2008



Buick; Allure; 2010-2009  
 Buick; Enclave; 2013-2009  
 Buick; LaCrosse; 2013-2009  
 Buick; Lucerne; 2011-2007  
 Buick; Regal; 2013-2011  
 Buick; Verano; 2013-2012  
 Cadillac; CTS; 2013-2009; OEM Part No. 25920615; Exc. CTS V  
 Cadillac; CTS; 2008  
 Cadillac; DTS; 2011-2007  
 Cadillac; Escalade; 2013-2008  
 Cadillac; Escalade; 2007; Snap-In Style Only; Schrader Sensor;  
 W/Rubber Valve Stem  
 Cadillac; SRX; 2013-2007  
 Cadillac; STS; 2011-2010  
 Cadillac; STS; 2009; OEM Part No. 25920615; Exc. STS V  
 Cadillac; XTS; 2013  
 Chevrolet; Avalanche; 2013-2008  
 Chevrolet; Avalanche; 2007; Snap-In Style Only; Schrader Sensor;  
 W/Rubber Valve Stem  
 Chevrolet; Aveo; 2012-2007  
 Chevrolet; Camaro; 2013-2012; Exc. ZL1  
 Chevrolet; Camaro; 2013-2012; Rubber Valve; Exc. ZL1  
 Chevrolet; Camaro; 2011-2010  
 Chevrolet; Captiva; 2013-2012  
 Chevrolet; Cobalt; 2010  
 Chevrolet; Cobalt; 2009-2008; Snap-In Style Only; W/Rubber Valve Stem  
 Chevrolet; Cruze; 2013-2011  
 Chevrolet; Equinox; 2013-2010  
 Chevrolet; Express; 2013-2010  
 Chevrolet; HHR; 2011-2010  
 Chevrolet; HHR; 2009-2008; Snap-In Style Only; W/Rubber Valve Stem  
 Chevrolet; Impala; 2013-2008  
 Chevrolet; Impala; 2007; Snap-In Style Only; W/Rubber Valve Stem  
 Chevrolet; Malibu; 2013-2009  
 Chevrolet; Malibu; 2008; Snap-In Style Only; W/Rubber Valve Stem  
 Chevrolet; Monte Carlo; 2007; Snap-In Style Only; W/Rubber Valve Stem  
 Chevrolet; Orlando; 2012  
 Chevrolet; Silverado Series Pickup; 2013-2008; W/Single Rear Wheels  
 Chevrolet; Silverado Series Pickup; 2007; Snap-In Style Only;  
 Schrader Sensor; W/Rubber Valve Stem; Exc. Classic  
 Chevrolet; Sonic; 2013-2012  
 Chevrolet; Spark; 2013  
 Chevrolet; Suburban; 2013-2008  
 Chevrolet; Suburban; 2007; Snap-In Style Only; Schrader Sensor;  
 W/Rubber Valve Stem  
 Chevrolet; Tahoe; 2013-2008

# Numerical Listing Service Packs

## 2008 - Continued

Chevrolet; Tahoe; 2007; Snap-In Style Only; Schrader Sensor;  
W/Rubber Valve Stem  
Chevrolet; Traverse; 2013-2009  
Chevrolet; Volt; 2013-2011  
Chrysler; 300; 2012; W/Rubber Stem Snap-in Sensor  
Chrysler; 300; 2011  
Chrysler; 300; 2008; W/Steel Wheels  
Chrysler; Town & Country Van; 2011  
Dodge; Challenger; 2012-2010; W/Rubber Stem Snap-in Sensor  
Dodge; Charger; 2011-2010; W/Rubber Stem Snap-in Sensor  
Dodge; Durango; 2011  
Dodge; Grand Caravan; 2011  
Dodge; Journey; 2011  
Dodge; Ram Series Pickup; 2011-2010; W/Rubber Stem Snap-in Sensor  
Dodge; Ram Series Pickup; 2008; 1500, 2500; Rubber Valve  
Ford; E Series Van; 2010; W/Alloy Wheels; Rubber Valve  
Ford; Super Duty Van; 2010; W/Alloy Wheels; Rubber Valve  
Ford; Taurus; 2010; Apr. & Older; Rubber Valve  
GMC; Acadia; 2013-2009  
GMC; Envoy; 2009-2008  
GMC; Savana; 2013-2010  
GMC; Sierra Series Pickup; 2013-2008; W/Single Rear Wheels  
GMC; Sierra Series Pickup; 2007; Snap-In Style Only; Schrader Sensor;  
W/Rubber Valve Stem; Exc. Classic  
GMC; Terrain; 2013-2010  
GMC; Yukon; 2013-2008  
GMC; Yukon; 2007; Snap-In Style Only; Schrader Sensor;  
W/Rubber Valve Stem  
Honda; Accord; 2011-2010; Exc. Crosstour; Rubber Valve  
Hummer; H2; 2010-2008  
Hyundai; Veloster; 2013-2012  
Mitsubishi; Lancer; 2013-2011; W/Alloy Wheels  
Mitsubishi; Outlander; 2013-2011; W/Alloy Wheels  
Pontiac; G3; 2010-2009  
Pontiac; G3 Wave; 2009  
Pontiac; G5; 2010-2009  
Pontiac; G6; 2010-2009  
Pontiac; G8; 2010-2008  
Pontiac; Grand Prix; 2008; Snap-In Style Only; W/Rubber Valve Stem  
Pontiac; Wave; 2009-2008  
Saab; 9-4X; 2012-2011  
Saturn; Astra; 2010-2009  
Saturn; Aura; 2010-2008  
Saturn; Outlook; 2010-2009  
Saturn; VUE; 2010-2007  
Subaru; Forester; 2013-2008  
Subaru; Impreza; 2013-2008  
Subaru; Legacy; 2013-2009  
Subaru; Legacy; 2008; W/18" Wheels  
Subaru; Outback; 2013-2008  
Subaru; Tribeca; 2012  
Subaru; Tribeca; 2010  
Subaru; Tribeca; 2008; W/Rubber Stem Snap-in Sensor  
Suzuki; Forenza; 2008-2007  
Suzuki; Reno; 2008-2007  
Volvo; XC90; 2013-2012

## 2009



Saab; 9-3; 2012-2003  
Saab; 9-5; 2012-2003  
Saturn; Astra; 2008  
Suzuki; Grand Vitara; 2013-2007  
Suzuki; SX4; 2013-2007  
Suzuki; Verona; 2006-2005  
Suzuki; XL-7; 2006-2005

## 2010



Mitsubishi; Eclipse; 2007-2006; W/Steel Wheels  
Mitsubishi; Galant; 2011-2007; W/Steel Wheels  
Volvo; S60; 2009-2006  
Volvo; S60; 2005-2004; W/315 MHz Sensor  
Volvo; S80; 2006-2004  
Volvo; V70; 2007-2004; W/315 MHz Sensor  
Volvo; XC70; 2007-2004; W/315 MHz Sensor  
Volvo; XC90; 2009; W/315 MHz Sensor  
Volvo; XC90; 2007-2005; W/315 MHz Sensor  
Volvo; XC90; 2004

## 2011



Subaru; B9 Tribeca; 2007-2006  
Subaru; Legacy; 2008; W/16" Or 17" Wheels  
Subaru; Legacy; 2007-2004  
Subaru; Outback; 2006-2004  
Subaru; Tribeca; 2009-2008; W/Metal Stem Clamp-in Sensor

## 2012



Chevrolet; Corvette; 2000-1997  
Chrysler; Prowler; 2001; W/Black Sensor Body  
Plymouth; Prowler; 2001-1999; W/Black Sensor Body  
Plymouth; Prowler; 1997; W/Black Sensor Body

# Numerical Listing Service Packs

## 2013



Chrysler; 200; 2012-2011; W/Schrader Sensor  
 Chrysler; 300; 2008-2005; W/Schrader Sensor  
 Chrysler; Aspen; 2009-2007; W/Schrader Sensor  
 Chrysler; Crossfire; 2005; OEM Part No. 5142340AA  
 Chrysler; Pacifica; 2008-2006; W/Schrader Sensor  
 Chrysler; PT Cruiser; 2010-2008; W/Schrader Sensor  
 Chrysler; Sebring; 2010-2007; W/Schrader Sensor  
 Chrysler; Town & Country Van; 2009-2006; W/Schrader Sensor  
 Dodge; Avenger; 2012-2008; W/Schrader Sensor  
 Dodge; Caliber; 2011-2007; W/Schrader Sensor  
 Dodge; Caravan; 2007-2006; W/Schrader Sensor  
 Dodge; Charger; 2008-2006; W/Schrader Sensor  
 Dodge; Dakota; 2011-2008  
 Dodge; Durango; 2009  
 Dodge; Durango; 2008-2007; W/Schrader Sensor  
 Dodge; Grand Caravan; 2010-2006; W/Schrader Sensor  
 Dodge; Journey; 2010-2009; W/Schrader Sensor  
 Dodge; Magnum; 2008-2005; W/Schrader Sensor  
 Dodge; Nitro; 2011-2009  
 Dodge; Nitro; 2008-2007; W/Schrader Sensor  
 Dodge; Ram Series Pickup; 2010; 2500; W/Metal Stem Clamp-in Sensor  
 Dodge; Ram Series Pickup; 2009-2008; 2500  
 Jeep; Commander; 2010-2008  
 Jeep; Commander; 2007-2006; W/Schrader Sensor  
 Jeep; Compass; 2011-2007; W/Schrader Sensor  
 Jeep; Grand Cherokee; 2010-2008  
 Jeep; Grand Cherokee; 2007-2005; W/Schrader Sensor  
 Jeep; Liberty; 2012-2009  
 Jeep; Liberty; 2008-2005; W/Schrader Sensor  
 Jeep; Patriot; 2012-2007; W/Schrader Sensor  
 Jeep; Wrangler; 2011; W/Schrader Sensor  
 Jeep; Wrangler; 2010-2009  
 Jeep; Wrangler; 2008-2007; W/Schrader Sensor  
 Mitsubishi; Raider; 2009-2008  
 Suzuki; Kizashi; 2012-2010; W/Schrader Sensor

## 2014



Infiniti; EX35; 2010-2008  
 Infiniti; FX35; 2010-2008  
 Infiniti; FX35; 2007; Jul. & Newer  
 Infiniti; FX45; 2008  
 Infiniti; FX45; 2007; Jul. & Newer  
 Infiniti; FX50; 2010-2009  
 Infiniti; G35; 2008-2007  
 Infiniti; G37; 2010-2008  
 Infiniti; M35; 2010-2008  
 Infiniti; M45; 2010-2008  
 Infiniti; Q45; 2006; Aug. & Newer  
 Infiniti; QX56; 2010-2008  
 Infiniti; QX56; 2007; Apr. 1 & Newer

## 2014 - Continued

Nissan; 350Z; 2009-2007  
 Nissan; 370Z; 2010-2009  
 Nissan; Altima; 2012-2007  
 Nissan; Altima; 2006; Oct. 1 & Newer  
 Nissan; Armada; 2013-2009  
 Nissan; Armada; 2008; LE  
 Nissan; Cube; 2013-2011  
 Nissan; Cube; 2009  
 Nissan; Frontier; 2013-2009  
 Nissan; Frontier; 2008; W/Steel Wheels  
 Nissan; GT-R; 2013-2011  
 Nissan; GT-R; 2009  
 Nissan; Juke; 2012-2011  
 Nissan; Maxima; 2012-2008  
 Nissan; Maxima; 2007; Apr. 1 & Newer  
 Nissan; Murano; 2012-2009  
 Nissan; Murano; 2007  
 Nissan; NV; 2013-2012  
 Nissan; Pathfinder; 2012-2007  
 Nissan; Quest; 2009-2007  
 Nissan; Rogue; 2012-2011  
 Nissan; Rogue; 2009-2008  
 Nissan; Sentra; 2013-2008  
 Nissan; Sentra; 2007; W/Steel Wheels  
 Nissan; Titan; 2013-2008  
 Nissan; Titan; 2007; Apr. 1 & Newer  
 Nissan; Versa; 2012-2007  
 Nissan; Xterra; 2013-2007  
 Suzuki; Equator; 2013-2009

## 2015



Cadillac; Escalade; 2007; Clamp-In Style Only; TRW Sensor;  
 W/Almnm. Valve Stem  
 Chevrolet; Avalanche; 2007; Clamp-In Style Only; TRW Sensor;  
 W/Almnm. Valve Stem  
 Chevrolet; Silverado Series Pickup; 2007; Clamp-In Style Only;  
 TRW Sensor; W/Almnm. Valve Stem; Exc. Classic  
 Chevrolet; Suburban; 2007; Clamp-In Style Only; TRW Sensor;  
 W/Almnm. Valve Stem  
 Chevrolet; Tahoe; 2007; Clamp-In Style Only; TRW Sensor;  
 W/Almnm. Valve Stem  
 GMC; Sierra Series Pickup; 2007; Clamp-In Style Only; TRW Sensor;  
 W/Almnm. Valve Stem; Exc. Classic  
 GMC; Yukon; 2007; Clamp-In Style Only; TRW Sensor;  
 W/Almnm. Valve Stem

## 2016



Chrysler; 300; 2012; W/Metal Stem Clamp-in Sensor  
 Chrysler; 300; 2010-2009  
 Dodge; Challenger; 2012-2010; W/Metal Stem Clamp-in Sensor

# Numerical Listing

## Service Packs

### 2016 - Continued

Dodge; Challenger; 2009-2008  
 Dodge; Charger; 2010; W/Metal Stem Clamp-in Sensor  
 Dodge; Charger; 2009  
 Mercedes-Benz; C63; 2013; W/O Valve  
 Mercedes-Benz; C63; 2012-2008  
 Mercedes-Benz; C250; 2013; W/O Valve  
 Mercedes-Benz; C250; 2012  
 Mercedes-Benz; C280; 2007; Mar. & Newer  
 Mercedes-Benz; C300; 2013; W/O Valve  
 Mercedes-Benz; C300; 2012-2008  
 Mercedes-Benz; C350; 2013; W/O Valve  
 Mercedes-Benz; C350; 2012-2008  
 Mercedes-Benz; C350; 2007; Jun. & Newer  
 Mercedes-Benz; CL63; 2013; W/O Valve  
 Mercedes-Benz; CL63; 2012-2010  
 Mercedes-Benz; CL65; 2013; W/O Valve  
 Mercedes-Benz; CL65; 2012-2010  
 Mercedes-Benz; CL550; 2013; W/O Valve  
 Mercedes-Benz; CL550; 2012-2010  
 Mercedes-Benz; CL600; 2013; W/O Valve  
 Mercedes-Benz; CL600; 2012  
 Mercedes-Benz; CL600; 2010  
 Mercedes-Benz; CLK55; 2006  
 Mercedes-Benz; CLK63; 2009-2007  
 Mercedes-Benz; CLK350; 2009-2006  
 Mercedes-Benz; CLK500; 2006  
 Mercedes-Benz; CLK550; 2009-2007  
 Mercedes-Benz; CLS63; 2013; W/O Valve  
 Mercedes-Benz; CLS63; 2012  
 Mercedes-Benz; CLS550; 2013; W/O Valve  
 Mercedes-Benz; CLS550; 2012  
 Mercedes-Benz; E63; 2013-2012; W/O Valve  
 Mercedes-Benz; E63; 2011-2010  
 Mercedes-Benz; E350; 2013; W/O Valve  
 Mercedes-Benz; E350; 2012-2010  
 Mercedes-Benz; E550; 2013-2012; W/O Valve  
 Mercedes-Benz; E550; 2011-2010  
 Mercedes-Benz; G55; 2011; Mar. & Newer  
 Mercedes-Benz; G55; 2010-2008  
 Mercedes-Benz; G55; 2007; Mar. & Newer  
 Mercedes-Benz; G500; 2008  
 Mercedes-Benz; G500; 2007; Mar. & Newer  
 Mercedes-Benz; G550; 2013-2012; W/O Valve  
 Mercedes-Benz; G550; 2011; Mar. & Newer  
 Mercedes-Benz; G550; 2010-2009  
 Mercedes-Benz; GL63; 2013; W/O Valve  
 Mercedes-Benz; GL350; 2012; W/O Valve  
 Mercedes-Benz; GL350; 2011; Mar. & Newer  
 Mercedes-Benz; GL350; 2010  
 Mercedes-Benz; GL450; 2013-2012; W/O Valve  
 Mercedes-Benz; GL450; 2011; Mar. & Newer  
 Mercedes-Benz; GL450; 2010  
 Mercedes-Benz; GL550; 2013-2012; W/O Valve  
 Mercedes-Benz; GL550; 2011; Mar. & Newer  
 Mercedes-Benz; GL550; 2010  
 Mercedes-Benz; GLK350; 2013; W/O Valve  
 Mercedes-Benz; GLK350; 2012  
 Mercedes-Benz; GLK350; 2011; Mar. & Newer  
 Mercedes-Benz; GLK350; 2010  
 Mercedes-Benz; ML63; 2013-2012; W/O Valve  
 Mercedes-Benz; ML63; 2011; Mar. & Newer  
 Mercedes-Benz; ML63; 2010  
 Mercedes-Benz; ML350; 2013; W/O Valve  
 Mercedes-Benz; ML350; 2012  
 Mercedes-Benz; ML350; 2011; Mar. & Newer

### 2016 - Continued

Mercedes-Benz; ML350; 2010  
 Mercedes-Benz; ML450; 2011; Mar. & Newer  
 Mercedes-Benz; ML450; 2010  
 Mercedes-Benz; ML550; 2011; Mar. & Newer  
 Mercedes-Benz; ML550; 2010  
 Mercedes-Benz; R350; 2013; W/O Valve  
 Mercedes-Benz; R350; 2012  
 Mercedes-Benz; R350; 2011; Mar. & Newer  
 Mercedes-Benz; R350; 2010  
 Mercedes-Benz; S63; 2013-2012; W/O Valve  
 Mercedes-Benz; S63; 2011  
 Mercedes-Benz; S65; 2013-2012; W/O Valve  
 Mercedes-Benz; S65; 2011  
 Mercedes-Benz; S350; 2013-2012; W/O Valve  
 Mercedes-Benz; S400; 2013-2012; W/O Valve  
 Mercedes-Benz; S400; 2011  
 Mercedes-Benz; S550; 2013-2012; W/O Valve  
 Mercedes-Benz; S550; 2011  
 Mercedes-Benz; S600; 2013-2012; W/O Valve  
 Mercedes-Benz; S600; 2011  
 Mercedes-Benz; SL63; 2013; W/O Valve  
 Mercedes-Benz; SL63; 2012  
 Mercedes-Benz; SL550; 2013; W/O Valve  
 Mercedes-Benz; SL550; 2012  
 Mercedes-Benz; SLK55; 2010-2008  
 Mercedes-Benz; SLK55; 2007; May & Newer  
 Mercedes-Benz; SLK250; 2013; W/O Valve  
 Mercedes-Benz; SLK250; 2012  
 Mercedes-Benz; SLK280; 2008  
 Mercedes-Benz; SLK280; 2007; May & Newer  
 Mercedes-Benz; SLK300; 2011-2009  
 Mercedes-Benz; SLK350; 2013; W/O Valve  
 Mercedes-Benz; SLK350; 2012-2008  
 Mercedes-Benz; SLK350; 2007; May & Newer  
 Mercedes-Benz; SLS; 2013; W/O Valve  
 Mercedes-Benz; SLS; 2012-2011  
 Smart; Fortwo; 2013; W/O Valve  
 Smart; Fortwo; 2012-2008

### 2017



Audi; A3; 2012-2008  
 Audi; A4; 2012-2009  
 Audi; A5; 2012-2008  
 Audi; Q5; 2012-2009  
 Audi; S4; 2011-2010  
 Audi; S5; 2012-2008  
 Audi; TT; 2011-2008  
 Volkswagen; Beetle; 2010-2008  
 Volkswagen; CC; 2012-2009  
 Volkswagen; Eos; 2012-2007  
 Volkswagen; GLI; 2009-2008  
 Volkswagen; Golf; 2010-2008  
 Volkswagen; Golf; 2006; GTI  
 Volkswagen; GTI; 2010-2008  
 Volkswagen; GTI; 2007-2006; W/16" Or 17" Wheels  
 Volkswagen; Jetta; 2010-2006  
 Volkswagen; Passat; 2010-2009



# Numerical Listing Service Packs

## 2017 - Continued

Volkswagen; Passat; 2008-2006; W/16" Or 17" Wheels  
 Volkswagen; R32; 2008  
 Volkswagen; Rabbit; 2009-2008  
 Volkswagen; Rabbit; 2007-2006; W/15" Wheels  
 Volkswagen; Tiguan; 2012-2009

## 20018



Chrysler; Town & Country Van; 2012  
 Dodge; Charger; 2012  
 Dodge; Durango; 2012  
 Dodge; Grand Caravan; 2012  
 Dodge; Journey; 2012  
 Dodge; Ram 4500HD; 2012  
 Dodge; Ram 5500HD; 2012  
 Dodge; Ram Series Pickup; 2012  
 Fiat; 500; 2013-2012  
 Ford; C-MAX; 2013  
 Ford; E450 Super Duty; 2010  
 Ford; E Series Van; 2013-2012  
 Ford; E Series Van; 2010; W/Steel Wheels  
 Ford; Edge; 2013-2012  
 Ford; Escape; 2013-2012  
 Ford; Escape; 2010-2009  
 Ford; Expedition; 2013-2012  
 Ford; Explorer; 2013-2012  
 Ford; F Series Pickup; 2013-2012  
 Ford; F Series Pickup; 2010-2009  
 Ford; Fiesta; 2013-2011  
 Ford; Flex; 2013-2011  
 Ford; Focus; 2013-2010  
 Ford; Fusion; 2013-2010  
 Ford; Mustang; 2013-2010  
 Ford; Super Duty Pickup; 2012  
 Ford; Super Duty Van; 2010; W/Steel Wheels  
 Ford; Taurus; 2013-2011  
 Ford; Taurus; 2010; May & Newer  
 Ford; Transit Connect; 2013-2010  
 Jeep; Commander; 2010-2006; Rubber Valve  
 Jeep; Compass; 2013-2007; Rubber Valve  
 Jeep; Grand Cherokee; 2012-2011  
 Jeep; Grand Cherokee; 2010-2005; Rubber Valve  
 Jeep; Liberty; 2012-2010; Rubber Valve  
 Jeep; Patriot; 2012; Rubber Valve  
 Jeep; Wrangler; 2013-2012  
 Lincoln; MKS; 2013-2011  
 Lincoln; MKT; 2013-2011  
 Lincoln; MKX; 2013-2011  
 Lincoln; MKZ; 2013-2010  
 Lincoln; Navigator; 2013-2011  
 Lincoln; Town Car; 2011  
 Mazda; Tribute; 2010-2009  
 Mercury; Mariner; 2011-2009  
 Mercury; Milan; 2011-2010

## 20019



Acura; CSX; 2011-2008  
 Acura; TL; 2012-2009  
 Honda; Civic; 2012-2008  
 Honda; CR-V; 2013-2012  
 Honda; CR-Z; 2013-2011  
 Honda; Element; 2011-2009  
 Honda; Fit; 2013-2009  
 Honda; Insight; 2012-2010  
 Honda; Odyssey; 2013-2011

## 20020



Chrysler; 200; 2012-2011; W/Schrader Sensor  
 Chrysler; 300; 2012; W/Metal Stem Clamp-in Sensor  
 Chrysler; 300; 2010-2009  
 Chrysler; 300; 2008-2005; W/Schrader Sensor  
 Chrysler; Aspen; 2009-2007; W/Schrader Sensor  
 Chrysler; Crossfire; 2005; OEM Part No. 5142340AA  
 Chrysler; Pacifica; 2008-2006; W/Schrader Sensor  
 Chrysler; PT Cruiser; 2010-2008; W/Schrader Sensor  
 Chrysler; Sebring; 2010-2007; W/Schrader Sensor  
 Chrysler; Town & Country Van; 2009-2006; W/Schrader Sensor  
 Dodge; Avenger; 2012-2008; W/Schrader Sensor  
 Dodge; Caliber; 2011-2007; W/Schrader Sensor  
 Dodge; Caravan; 2007-2006; W/Schrader Sensor  
 Dodge; Challenger; 2012-2010; W/Metal Stem Clamp-in Sensor  
 Dodge; Challenger; 2009-2008  
 Dodge; Charger; 2010; W/Metal Stem Clamp-in Sensor  
 Dodge; Charger; 2009  
 Dodge; Charger; 2008-2006; W/Schrader Sensor  
 Dodge; Dakota; 2011-2008  
 Dodge; Durango; 2009  
 Dodge; Durango; 2008-2007; W/Schrader Sensor  
 Dodge; Grand Caravan; 2010-2006; W/Schrader Sensor  
 Dodge; Journey; 2010-2009; W/Schrader Sensor  
 Dodge; Magnum; 2008-2005; W/Schrader Sensor  
 Dodge; Nitro; 2011-2009  
 Dodge; Nitro; 2008-2007; W/Schrader Sensor  
 Dodge; Ram Series Pickup; 2010; 2500; W/Metal Stem Clamp-in Sensor  
 Dodge; Ram Series Pickup; 2009-2008; 2500  
 Jeep; Commander; 2010-2008  
 Jeep; Commander; 2007-2006; W/Schrader Sensor  
 Jeep; Compass; 2011-2007; W/Schrader Sensor  
 Jeep; Grand Cherokee; 2010-2008  
 Jeep; Grand Cherokee; 2007-2005; W/Schrader Sensor  
 Jeep; Liberty; 2012-2009  
 Jeep; Liberty; 2008-2005; W/Schrader Sensor  
 Jeep; Patriot; 2012-2007; W/Schrader Sensor  
 Jeep; Wrangler; 2011; W/Schrader Sensor  
 Jeep; Wrangler; 2010-2009  
 Jeep; Wrangler; 2008-2007; W/Schrader Sensor  
 Mercedes-Benz; C63; 2013; W/Valve  
 Mercedes-Benz; C63; 2012-2008  
 Mercedes-Benz; C250; 2013; W/Valve  
 Mercedes-Benz; C250; 2012

# Numerical Listing Service Packs

## 2020 - Continued

Mercedes-Benz; C280; 2007; Mar. & Newer  
 Mercedes-Benz; C300; 2013; W/Valve  
 Mercedes-Benz; C300; 2012-2008  
 Mercedes-Benz; C350; 2013; W/Valve  
 Mercedes-Benz; C350; 2012-2008  
 Mercedes-Benz; C350; 2007; Jun. & Newer  
 Mercedes-Benz; CL63; 2013; W/Valve  
 Mercedes-Benz; CL63; 2012-2010  
 Mercedes-Benz; CL65; 2013; W/Valve  
 Mercedes-Benz; CL65; 2012-2010  
 Mercedes-Benz; CL550; 2013; W/Valve  
 Mercedes-Benz; CL550; 2012-2010  
 Mercedes-Benz; CL600; 2013; W/Valve  
 Mercedes-Benz; CL600; 2012  
 Mercedes-Benz; CL600; 2010  
 Mercedes-Benz; CLK55; 2006  
 Mercedes-Benz; CLK63; 2009-2007  
 Mercedes-Benz; CLK350; 2009-2006  
 Mercedes-Benz; CLK500; 2006  
 Mercedes-Benz; CLK550; 2009-2007  
 Mercedes-Benz; CLS63; 2013; W/Valve  
 Mercedes-Benz; CLS63; 2012  
 Mercedes-Benz; CLS550; 2013; W/Valve  
 Mercedes-Benz; CLS550; 2012  
 Mercedes-Benz; E63; 2013-2012; W/Valve  
 Mercedes-Benz; E63; 2011-2010  
 Mercedes-Benz; E350; 2013; W/Valve  
 Mercedes-Benz; E350; 2012-2010  
 Mercedes-Benz; E550; 2013-2012; W/Valve  
 Mercedes-Benz; E550; 2011-2010  
 Mercedes-Benz; G55; 2011; Mar. & Newer  
 Mercedes-Benz; G55; 2010-2008  
 Mercedes-Benz; G55; 2007; Mar. & Newer  
 Mercedes-Benz; G500; 2008  
 Mercedes-Benz; G500; 2007; Mar. & Newer  
 Mercedes-Benz; G550; 2013-2012; W/Valve  
 Mercedes-Benz; G550; 2011; Mar. & Newer  
 Mercedes-Benz; G550; 2010-2009  
 Mercedes-Benz; GL63; 2013; W/Valve  
 Mercedes-Benz; GL350; 2012; W/Valve  
 Mercedes-Benz; GL350; 2011; Mar. & Newer  
 Mercedes-Benz; GL350; 2010  
 Mercedes-Benz; GL450; 2013-2012; W/Valve  
 Mercedes-Benz; GL450; 2011; Mar. & Newer  
 Mercedes-Benz; GL450; 2010  
 Mercedes-Benz; GL550; 2013-2012; W/Valve  
 Mercedes-Benz; GL550; 2011; Mar. & Newer  
 Mercedes-Benz; GL550; 2010  
 Mercedes-Benz; GLK350; 2013; W/Valve  
 Mercedes-Benz; GLK350; 2012  
 Mercedes-Benz; GLK350; 2011; Mar. & Newer  
 Mercedes-Benz; GLK350; 2010  
 Mercedes-Benz; ML63; 2013-2012; W/Valve  
 Mercedes-Benz; ML63; 2011; Mar. & Newer  
 Mercedes-Benz; ML63; 2010  
 Mercedes-Benz; ML350; 2013; W/Valve  
 Mercedes-Benz; ML350; 2012  
 Mercedes-Benz; ML350; 2011; Mar. & Newer  
 Mercedes-Benz; ML350; 2010  
 Mercedes-Benz; ML450; 2011; Mar. & Newer  
 Mercedes-Benz; ML450; 2010  
 Mercedes-Benz; ML550; 2011; Mar. & Newer  
 Mercedes-Benz; ML550; 2010  
 Mercedes-Benz; R350; 2013; W/Valve  
 Mercedes-Benz; R350; 2012

## 2020 - Continued

Mercedes-Benz; R350; 2011; Mar. & Newer  
 Mercedes-Benz; R350; 2010  
 Mercedes-Benz; S63; 2013-2012; W/Valve  
 Mercedes-Benz; S63; 2011  
 Mercedes-Benz; S65; 2013-2012; W/Valve  
 Mercedes-Benz; S65; 2011  
 Mercedes-Benz; S350; 2013-2012; W/Valve  
 Mercedes-Benz; S400; 2013-2012; W/Valve  
 Mercedes-Benz; S400; 2011  
 Mercedes-Benz; S550; 2013-2012; W/Valve  
 Mercedes-Benz; S550; 2011  
 Mercedes-Benz; S600; 2013-2012; W/Valve  
 Mercedes-Benz; S600; 2011  
 Mercedes-Benz; SL63; 2013; W/Valve  
 Mercedes-Benz; SL63; 2012  
 Mercedes-Benz; SL550; 2013; W/Valve  
 Mercedes-Benz; SL550; 2012  
 Mercedes-Benz; SLK55; 2010-2008  
 Mercedes-Benz; SLK55; 2007; May & Newer  
 Mercedes-Benz; SLK250; 2013; W/Valve  
 Mercedes-Benz; SLK250; 2012  
 Mercedes-Benz; SLK280; 2008  
 Mercedes-Benz; SLK280; 2007; May & Newer  
 Mercedes-Benz; SLK300; 2011-2009  
 Mercedes-Benz; SLK350; 2013; W/Valve  
 Mercedes-Benz; SLK350; 2012-2008  
 Mercedes-Benz; SLK350; 2007; May & Newer  
 Mercedes-Benz; SLS; 2013; W/Valve  
 Mercedes-Benz; SLS; 2012-2011  
 Mitsubishi; Raider; 2009-2008  
 Smart; Fortwo; 2013; W/Valve  
 Smart; Fortwo; 2012-2008  
 Suzuki; Kizashi; 2012-2010; W/Schrader Sensor

## 2021



Acura; MDX; 2006-2004


Acura; RL; 2011-2005  
 Acura; TL; 2008-2005  
 Dodge; Sprinter; 2010-2007  
 Freightliner; Sprinter; 2008-2007  
 Honda; Element; 2008-2007  
 Honda; Odyssey; 2010-2009  
 Honda; Odyssey; 2007-2005; Touring  
 Honda; Pilot; 2008-2005  
 Honda; Ridgeline; 2012-2006  
 Hyundai; Azera; 2013-2006  
 Hyundai; Elantra; 2013-2008  
 Hyundai; Entourage; 2009-2007  
 Hyundai; Santa Fe; 2010-2007  
 Hyundai; Sonata; 2008-2007  
 Hyundai; Tiburon; 2008-2007  
 Hyundai; Tucson; 2009-2006  
 Hyundai; Veracruz; 2012-2007  
 Kia; Amanti; 2009-2007  
 Kia; Magentis; 2010-2008  
 Kia; Optima; 2010-2006  
 Kia; Rio; 2013-2012  
 Kia; Rondo; 2011-2007  
 Kia; Sedona; 2012-2006

# Numerical Listing Service Packs

## 20021 - Continued

Kia; Sorento; 2009-2007  
 Kia; Sportage; 2008-2006  
 Kia; Sportage; 2005; Jun. 15, 2005 & Newer  
 Mercedes-Benz; CL63; 2009-2007  
 Mercedes-Benz; CL65; 2009-2008  
 Mercedes-Benz; CL550; 2009-2007  
 Mercedes-Benz; CL600; 2009-2007  
 Mercedes-Benz; CLS55; 2006  
 Mercedes-Benz; CLS63; 2011-2007  
 Mercedes-Benz; CLS500; 2006  
 Mercedes-Benz; CLS550; 2011-2007  
 Mercedes-Benz; E55; 2006  
 Mercedes-Benz; E63; 2009-2007  
 Mercedes-Benz; E320; 2009-2006  
 Mercedes-Benz; E350; 2009-2006  
 Mercedes-Benz; E500; 2006  
 Mercedes-Benz; E550; 2009-2007  
 Mercedes-Benz; GL320; 2009-2007  
 Mercedes-Benz; GL450; 2009-2007  
 Mercedes-Benz; GL550; 2009-2008  
 Mercedes-Benz; ML63; 2009-2007  
 Mercedes-Benz; ML320; 2009-2007  
 Mercedes-Benz; ML350; 2009-2006  
 Mercedes-Benz; ML500; 2007-2006  
 Mercedes-Benz; ML550; 2009-2008  
 Mercedes-Benz; R63; 2007  
 Mercedes-Benz; R320; 2009-2007  
 Mercedes-Benz; R350; 2009-2006  
 Mercedes-Benz; R500; 2007-2006  
 Mercedes-Benz; S63; 2010-2007  
 Mercedes-Benz; S65; 2010-2007  
 Mercedes-Benz; S400; 2010  
 Mercedes-Benz; S550; 2010-2007  
 Mercedes-Benz; S600; 2010-2007  
 Mercedes-Benz; SL55; 2008-2006  
 Mercedes-Benz; SL63; 2009  
 Mercedes-Benz; SL65; 2009-2006  
 Mercedes-Benz; SL500; 2006  
 Mercedes-Benz; SL550; 2009-2007  
 Mercedes-Benz; SL600; 2009-2006  
 Mercedes-Benz; SLR McLaren; 2009-2008

## 20022



Hyundai; Accent; 2011-2008  
 Hyundai; Equus; 2012-2011  
 Hyundai; Genesis; 2012-2011; Sedan  
 Hyundai; Genesis; 2009  
 Hyundai; Sonata; 2010-2009  
 Hyundai; Tucson; 2013-2010  
 Kia; Borrego; 2011-2009  
 Kia; Rio; 2011-2007  
 Kia; Spectra; 2009-2006  
 Kia; Sportage; 2012-2009  
 Toyota; Sequoia; 2013-2008  
 Toyota; Sienna; 2013-2007  
 Toyota; Tundra; 2012-2007  
 Toyota; Tundra; 2006; Nov. 1 & Newer

## 20023



Audi; A4; 2008-2002  
 Audi; A6; 2011-2005  
 Audi; A8; 2010-2001  
 Audi; Allroad Quattro; 2005-2001  
 Audi; Q7; 2012-2007  
 Audi; R8; 2012-2008  
 Audi; RS4; 2008-2007  
 Audi; S4; 2009-2004  
 Audi; S6; 2011-2007  
 Audi; S8; 2009-2007  
 Audi; S8; 2003-2001  
 Bentley; Continental; 2010-2003  
 BMW; 128i; 2012-2008  
 BMW; 135i; 2013-2012  
 BMW; 135i; 2010-2008  
 BMW; 135iS; 2013  
 BMW; 320i; 2005-2001  
 BMW; 323Ci; 2000  
 BMW; 323i; 2010-2007  
 BMW; 323i; 2006; Jun. & Newer  
 BMW; 323i; 2000  
 BMW; 325Ci; 2006-2001  
 BMW; 325i; 2006-2001  
 BMW; 325Xi; 2006-2001  
 BMW; 328Ci; 2000  
 BMW; 328i; 2013-2007  
 BMW; 328i; 2000  
 BMW; 328Xi; 2008-2007  
 BMW; 330Ci; 2006-2001  
 BMW; 330i; 2006-2001  
 BMW; 330Xi; 2006-2001  
 BMW; 335D; 2012-2009  
 BMW; 335i; 2013-2007  
 BMW; 335iS; 2013-2012  
 BMW; 335Xi; 2010  
 BMW; 335Xi; 2008-2007  
 BMW; 525i; 2007-2001  
 BMW; 525Xi; 2007-2006  
 BMW; 528i; 2013-2008  
 BMW; 528i; 2000-1997  
 BMW; 528Xi; 2009-2008  
 BMW; 530i; 2007-2001  
 BMW; 530Xi; 2007-2006  
 BMW; 535i; 2013-2008  
 BMW; 535Xi; 2010  
 BMW; 535Xi; 2008  
 BMW; 540i; 2003-1997  
 BMW; 545i; 2005-2004  
 BMW; 550i; 2013-2006  
 BMW; 640i; 2013-2012  
 BMW; 645Ci; 2005-2004  
 BMW; 650i; 2013-2012  
 BMW; 650i; 2010-2006  
 BMW; 740i; 2013-2011  
 BMW; 740i; 2001-1997  
 BMW; 740iL; 2001-1997  
 BMW; 740Li; 2013-2011  
 BMW; 745i; 2005-2002

# Numerical Listing

## Service Packs

### 20023 - Continued

BMW; 745Li; 2005-2002  
 BMW; 750i; 2013-2006  
 BMW; 750iL; 2001-1997  
 BMW; 750Li; 2013-2006  
 BMW; 760i; 2006-2004  
 BMW; 760Li; 2011-2010  
 BMW; 760Li; 2008-2003  
 BMW; Alpina B7; 2011  
 BMW; Alpina B7; 2008-2007  
 BMW; M1; 2012  
 BMW; M3; 2013-2008  
 BMW; M3; 2006-2001  
 BMW; M5; 2013  
 BMW; M5; 2010-2006  
 BMW; M5; 2003-2000  
 BMW; M6; 2013  
 BMW; M6; 2010-2006  
 BMW; X1; 2013-2012  
 BMW; X3; 2013-2006  
 BMW; X5; 2013-2000  
 BMW; X6; 2013-2008  
 BMW; Z3; 2002-2000  
 BMW; Z4; 2013-2003  
 BMW; Z8; 2003-2000  
 Bugatti; Veyron; 2006  
 Ferrari; 550 Maranello; 2002-2001  
 Ferrari; 575M Maranello; 2005-2002  
 Ferrari; 612 Scaglietti; 2009-2004  
 Ferrari; Enzo; 2004-2003  
 Ferrari; F430; 2009-2005  
 Land Rover; LR3; 2005  
 Land Rover; Range Rover; 2005-2002  
 Maserati; Coupe; 2006-2004  
 Maserati; Gransport; 2006-2004  
 Maserati; MC12; 2006  
 Maserati; Quattroporte; 2006-2004  
 Maserati; Spyder; 2006-2004  
 Mercedes-Benz; CL55; 2006-2001  
 Mercedes-Benz; CL65; 2006-2005  
 Mercedes-Benz; CL500; 2006-2000  
 Mercedes-Benz; CL600; 2006-2001  
 Mercedes-Benz; E55; 2005-2000  
 Mercedes-Benz; E55; 1999; Jul. & Newer  
 Mercedes-Benz; E320; 2005-2001  
 Mercedes-Benz; E430; 2002-2001  
 Mercedes-Benz; E500; 2005-2003  
 Mercedes-Benz; R550; 2008  
 Mercedes-Benz; S55; 2006-2001  
 Mercedes-Benz; S65; 2006  
 Mercedes-Benz; S350; 2006  
 Mercedes-Benz; S430; 2006-2000  
 Mercedes-Benz; S500; 2006-2000  
 Mercedes-Benz; S600; 2006-2001  
 Mercedes-Benz; SL55; 2005-2003  
 Mercedes-Benz; SL65; 2005  
 Mercedes-Benz; SL500; 2005-2001  
 Mercedes-Benz; SL600; 2005-2004  
 Mercedes-Benz; SL600; 2002-2001  
 Mercedes-Benz; SLR McLaren; 2007-2004  
 Mini; Cooper; 2012  
 Mini; Cooper; 2010-2008  
 Porsche; 911; 2011-2005  
 Porsche; Boxster; 2011-2005  
 Porsche; Carrera GT; 2006-2004  
 Porsche; Cayenne; 2010-2008

### 20023 - Continued

Porsche; Cayenne; 2006-2003  
 Porsche; Cayman; 2011-2006  
 Porsche; Panamera; 2010  
 Rolls-Royce; Phantom; 2010-2007  
 Volkswagen; Phaeton; 2006-2004; W/315 MHz Sensor  
 Volkswagen; Touareg; 2013; W/315 MHz Sensor  
 Volkswagen; Touareg; 2007-2004  
 Volkswagen; Touareg 2; 2012-2011; W/315 MHz Sensor  
 Volkswagen; Touareg 2; 2010-2008

### 20030



Buick; Allure; 2008-2007; W/Siemens Sensor  
 Buick; Enclave; 2008; W/Siemens Sensor  
 Buick; LaCrosse; 2008-2007; W/Siemens Sensor  
 Chevrolet; Equinox; 2009-2007; W/Siemens Sensor  
 Chevrolet; Express; 2009-2008; W/Siemens Sensor  
 Chrysler; 300; 2008-2005; W/Siemens Sensor  
 Chrysler; 300M; 2004-2002; W/Siemens Sensor  
 Chrysler; Aspen; 2009-2007; W/Siemens Sensor  
 Chrysler; Concorde; 2004-2002; W/Siemens Sensor  
 Chrysler; Crossfire; 2008-2006; W/Siemens Sensor  
 Chrysler; Crossfire; 2004; W/Siemens Sensor  
 Chrysler; Intrepid; 2004-2002; W/Siemens Sensor  
 Chrysler; Pacifica; 2008-2006; W/Siemens Sensor  
 Chrysler; Pacifica; 2005  
 Chrysler; Pacifica; 2004; OEM Part No. 04727392AD  
 Chrysler; Prowler; 2002; W/Siemens Sensor  
 Chrysler; PT Cruiser; 2010-2008; W/Siemens Sensor  
 Chrysler; Sebring; 2009-2007; W/Siemens Sensor  
 Chrysler; Town & Country Van; 2009-2006; W/Siemens Sensor  
 Chrysler; Town & Country Van; 2005-2004  
 Dodge; Avenger; 2009-2008; W/Siemens Sensor  
 Dodge; Caliber; 2010-2007; W/Siemens Sensor  
 Dodge; Caravan; 2007-2006; W/Siemens Sensor  
 Dodge; Caravan; 2005-2004  
 Dodge; Charger; 2008-2006; W/Siemens Sensor  
 Dodge; Durango; 2008-2007; W/Siemens Sensor  
 Dodge; Grand Caravan; 2010-2006; W/Siemens Sensor  
 Dodge; Grand Caravan; 2005-2004  
 Dodge; Journey; 2010-2009; W/Siemens Sensor  
 Dodge; Magnum; 2008-2005; W/Siemens Sensor  
 Dodge; Nitro; 2008-2007; W/Siemens Sensor  
 GMC; Acadia; 2008-2007; W/Siemens Sensor  
 GMC; Savana; 2009-2008; W/Siemens Sensor  
 Jaguar; S-Type; 2008  
 Jaguar; Super V8; 2009-2005  
 Jaguar; Vanden Plas; 2009-2004  
 Jaguar; X-Type; 2008  
 Jaguar; XF; 2012-2009  
 Jaguar; XFR; 2011-2010  
 Jaguar; XJ; 2012-2010  
 Jaguar; XJ8; 2009-2004  
 Jaguar; XJR; 2009-2004  
 Jaguar; XK; 2012-2007  
 Jaguar; XKR; 2011-2007  
 Jeep; Commander; 2007-2006; W/Siemens Sensor  
 Jeep; Compass; 2010-2007; W/Siemens Sensor

# Numerical Listing Service Packs

## 20030 - Continued

Jeep; Grand Cherokee; 2007-2005; W/Siemens Sensor  
 Jeep; Liberty; 2008-2005; W/Siemens Sensor  
 Jeep; Patriot; 2010-2007; W/Siemens Sensor  
 Jeep; Wrangler; 2008-2007; W/Siemens Sensor  
 Land Rover; LR2; 2012-2008  
 Land Rover; LR3; 2009-2006  
 Land Rover; LR4; 2012-2010  
 Land Rover; Range Rover; 2013-2006  
 Mazda; 2; 2012-2011  
 Mazda; 3; 2012-2004  
 Mazda; 5; 2012  
 Mazda; 5; 2010-2006  
 Mazda; 6; 2013-2008  
 Mazda; CX-7; 2011-2007  
 Mazda; CX-9; 2012-2007  
 Mazda; MX-5 Miata; 2012-2006  
 Mazda; RX-8; 2011-2004  
 Mazda; Tribute; 2011  
 Mitsubishi; Lancer; 2013-2011; W/Steel Wheels  
 Mitsubishi; Lancer; 2010-2008  
 Mitsubishi; Outlander; 2013-2011; W/Steel Wheels  
 Mitsubishi; Outlander; 2010-2007  
 Pontiac; G5; 2008; W/Siemens Sensor  
 Pontiac; G6; 2008; W/Siemens Sensor  
 Pontiac; Grand Prix; 2007; W/Siemens Sensor  
 Pontiac; Montana; 2009-2008; W/Siemens Sensor  
 Pontiac; Solstice; 2010-2008; W/Siemens Sensor  
 Pontiac; Torrent; 2009-2007; W/Siemens Sensor  
 Saturn; Aura; 2007; W/Siemens Sensor  
 Saturn; Outlook; 2008-2007; W/Siemens Sensor  
 Saturn; Sky; 2010-2008; W/Siemens Sensor  
 Suzuki; Kizashi; 2012-2010; W/Siemens Sensor  
 Suzuki; XL-7; 2009-2007; W/Siemens Sensor

## 20031



Lexus; GS300; 2006  
 Lexus; GS430; 2006; Jun. & Older  
 Lexus; GS430; 2005  
 Lexus; GX470; 2006; Jan. 31 & Older  
 Lexus; GX470; 2005-2004  
 Lexus; IS250; 2006; Mar. & Older  
 Lexus; IS350; 2006; Mar. & Older  
 Lexus; LX470; 2006; Jul. & Older  
 Lexus; LX470; 2005  
 Lexus; RX330; 2006; Jan. 31 & Older  
 Toyota; 4 Runner; 2006; May & Older  
 Toyota; 4 Runner; 2005-2003  
 Toyota; Land Cruiser; 2006; Mar. & Older  
 Toyota; Land Cruiser; 2005; May & Newer  
 Toyota; Sequoia; 2007-2004  
 Toyota; Tacoma; 2006; Jul. & Older  
 Toyota; Tacoma; 2005  
 Toyota; Tundra; 2006; Oct. 31 & Older  
 Toyota; Tundra; 2005

## 20032



Honda; Accord; 2012  
 Honda; Accord; 2011-2010; Exc. Crosstour  
 Honda; Accord; 2009-2008  
 Honda; CR-V; 2011-2007  
 Honda; Crosstour; 2012  
 Honda; Fit; 2008  
 Honda; Pilot; 2013-2012; W/Alloy Wheels  
 Honda; Pilot; 2011-2010; Exc. LX  
 Honda; Pilot; 2009; W/Alloy Wheels  
 Honda; S2000; 2009-2008  
 Lexus; CT200h; 2012-2011  
 Lexus; ES350; 2013-2007  
 Lexus; GS350; 2013  
 Lexus; GS350; 2011-2007  
 Lexus; GS430; 2007  
 Lexus; GS430; 2006; Jul. & Newer  
 Lexus; GS450h; 2013  
 Lexus; GS450h; 2011-2007  
 Lexus; GS460; 2011-2008  
 Lexus; GX460; 2013-2010  
 Lexus; GX470; 2009-2007  
 Lexus; GX470; 2006; Feb. & Newer  
 Lexus; HS250h; 2012-2010  
 Lexus; IS250; 2013-2007  
 Lexus; IS250; 2006; Apr. 1 & Newer  
 Lexus; IS350; 2013-2007  
 Lexus; IS350; 2006; Apr. 1 & Newer  
 Lexus; IS F; 2013-2008  
 Lexus; LFA; 2013-2011  
 Lexus; LS460; 2013-2007  
 Lexus; LS600h; 2013-2008  
 Lexus; LX470; 2007  
 Lexus; LX470; 2006; Aug. & Newer  
 Lexus; LX570; 2013  
 Lexus; LX570; 2011-2008  
 Lexus; RX330; 2006; Feb. & Newer  
 Lexus; RX350; 2013-2007  
 Lexus; RX400h; 2009-2007  
 Lexus; RX450h; 2013-2010  
 Lexus; SC430; 2010-2007  
 Lexus; SC430; 2006; Aug. & Newer  
 Pontiac; Vibe; 2010-2008  
 Scion; iQ; 2013-2011  
 Scion; TC; 2013-2007  
 Scion; TC; 2006; May & Newer  
 Scion; XB; 2013-2008  
 Scion; XD; 2013-2008  
 Toyota; 4 Runner; 2013-2007  
 Toyota; 4 Runner; 2006; Jun. & Newer  
 Toyota; Avalon; 2012-2007  
 Toyota; Avalon; 2006; Aug. & Newer  
 Toyota; Camry; 2013-2007  
 Toyota; Corolla; 2013-2008  
 Toyota; Corolla; 2007; Jun. & Newer  
 Toyota; FJ Cruiser; 2013-2008  
 Toyota; Highlander; 2013-2008  
 Toyota; Highlander; 2007; May & Newer  
 Toyota; Land Cruiser; 2013-2007



# Numerical Listing Service Packs

## 20032 - Continued

Toyota; Land Cruiser; 2006; Apr. 1 & Newer  
 Toyota; Matrix; 2013-2008  
 Toyota; Matrix; 2007; Jun. & Newer  
 Toyota; Prius; 2013-2006  
 Toyota; RAV4; 2012-2006  
 Toyota; Solara; 2008-2007  
 Toyota; Solara; 2006; May & Newer  
 Toyota; Tacoma; 2013-2007  
 Toyota; Tacoma; 2006; Aug. & Newer  
 Toyota; Venza; 2013-2009  
 Toyota; Yaris; 2013-2008  
 Toyota; Yaris; 2007; Aug. & Newer

## 20035



Honda; Pilot; 2005; LX; W/Long Stem Valve  
 Honda; Ridgeline; 2008-2006; RT

## 20036



Acura; MDX; 2006-2004  
 Acura; RL; 2011-2005  
 Acura; TL; 2008-2005  
 Dodge; Sprinter; 2010-2007  
 Freightliner; Sprinter; 2008-2007  
 Honda; Element; 2008-2007  
 Honda; Odyssey; 2010-2009  
 Honda; Odyssey; 2007-2005; Touring  
 Honda; Pilot; 2008-2006  
 Honda; Pilot; 2005; EX  
 Honda; Pilot; 2005; LX; W/Short Stem Valve  
 Honda; Ridgeline; 2012-2010; RT  
 Honda; Ridgeline; 2009  
 Honda; Ridgeline; 2008-2007; RTL, RTS, RTX  
 Honda; Ridgeline; 2006; RTL, RTS  
 Hyundai; Azera; 2013-2006  
 Hyundai; Elantra; 2013-2008  
 Hyundai; Entourage; 2009-2007  
 Hyundai; Santa Fe; 2010-2007  
 Hyundai; Sonata; 2008-2007  
 Hyundai; Tiburon; 2008-2007  
 Hyundai; Tucson; 2009-2006  
 Hyundai; Veracruz; 2012-2007  
 Kia; Amanti; 2009-2007  
 Kia; Magentis; 2010-2008  
 Kia; Optima; 2010-2006  
 Kia; Rio; 2013-2012  
 Kia; Rondo; 2011-2007  
 Kia; Sedona; 2012-2006  
 Kia; Sorento; 2009-2007  
 Kia; Sportage; 2008-2006  
 Kia; Sportage; 2005; Jun. 15, 2005 & Newer

Mercedes-Benz; CL63; 2009-2007  
 Mercedes-Benz; CL65; 2009-2008  
 Mercedes-Benz; CL550; 2009-2007  
 Mercedes-Benz; CL600; 2009-2007  
 Mercedes-Benz; CLS55; 2006  
 Mercedes-Benz; CLS63; 2011-2007  
 Mercedes-Benz; CLS500; 2006  
 Mercedes-Benz; CLS550; 2011-2007  
 Mercedes-Benz; E55; 2006  
 Mercedes-Benz; E63; 2009-2007  
 Mercedes-Benz; E320; 2009-2006  
 Mercedes-Benz; E350; 2009-2006  
 Mercedes-Benz; E500; 2006  
 Mercedes-Benz; E550; 2009-2007  
 Mercedes-Benz; GL320; 2009-2007  
 Mercedes-Benz; GL450; 2009-2007  
 Mercedes-Benz; GL550; 2009-2008  
 Mercedes-Benz; ML63; 2009-2007  
 Mercedes-Benz; ML320; 2009-2007  
 Mercedes-Benz; ML350; 2009-2006  
 Mercedes-Benz; ML500; 2007-2006  
 Mercedes-Benz; ML550; 2009-2008  
 Mercedes-Benz; R63; 2007  
 Mercedes-Benz; R320; 2009-2007  
 Mercedes-Benz; R350; 2009-2006  
 Mercedes-Benz; R500; 2007-2006  
 Mercedes-Benz; S63; 2010-2007  
 Mercedes-Benz; S65; 2010-2007  
 Mercedes-Benz; S400; 2010  
 Mercedes-Benz; S550; 2010-2007  
 Mercedes-Benz; S600; 2010-2007  
 Mercedes-Benz; SL55; 2008-2006  
 Mercedes-Benz; SL63; 2009  
 Mercedes-Benz; SL65; 2009-2006  
 Mercedes-Benz; SL500; 2006  
 Mercedes-Benz; SL550; 2009-2007  
 Mercedes-Benz; SL600; 2009-2006  
 Mercedes-Benz; SLR McLaren; 2009-2008

## 20037 (W/43mm Silver Insert)



Audi; A4; 2008-2002  
 Audi; A6; 2011-2005  
 Audi; A8; 2010-2001  
 Audi; Allroad Quattro; 2005-2001  
 Audi; Q7; 2012-2007  
 Audi; R8; 2012-2008  
 Audi; RS4; 2008-2007  
 Audi; S4; 2009-2004  
 Audi; S6; 2011-2007  
 Audi; S8; 2009-2007  
 Audi; S8; 2003-2001  
 Bentley; Continental; 2010-2003  
 BMW; 128i; 2012-2008  
 BMW; 135i; 2013-2012  
 BMW; 135i; 2010-2008  
 BMW; 135IS; 2013  
 BMW; 320i; 2005-2001  
 BMW; 323Ci; 2000

# Numerical Listing

## Service Packs

### 20037 - Continued

BMW; 323i; 2010-2007  
 BMW; 323i; 2006; Jun. & Newer  
 BMW; 323i; 2000  
 BMW; 325Ci; 2006-2001  
 BMW; 325i; 2006-2001  
 BMW; 325Xi; 2006-2001  
 BMW; 328Ci; 2000  
 BMW; 328i; 2013-2007  
 BMW; 328i; 2000  
 BMW; 328Xi; 2008-2007  
 BMW; 330Ci; 2006-2001  
 BMW; 330i; 2006-2001  
 BMW; 330Xi; 2006-2001  
 BMW; 335D; 2012-2009  
 BMW; 335i; 2013-2007  
 BMW; 335iS; 2013-2012  
 BMW; 335Xi; 2010  
 BMW; 335Xi; 2008-2007  
 BMW; 525i; 2007-2001  
 BMW; 525Xi; 2007-2006  
 BMW; 528i; 2013-2008  
 BMW; 528i; 2000-1997  
 BMW; 528Xi; 2009-2008  
 BMW; 530i; 2007-2001  
 BMW; 530Xi; 2007-2006  
 BMW; 535i; 2013-2008  
 BMW; 535Xi; 2010  
 BMW; 535Xi; 2008  
 BMW; 540i; 2003-1997  
 BMW; 545i; 2005-2004  
 BMW; 550i; 2013-2006  
 BMW; 640i; 2013-2012  
 BMW; 645Ci; 2005-2004  
 BMW; 650i; 2013-2012  
 BMW; 650i; 2010-2006  
 BMW; 740i; 2013-2011  
 BMW; 740i; 2001-1997  
 BMW; 740iL; 2001-1997  
 BMW; 740Li; 2013-2011  
 BMW; 745i; 2005-2002  
 BMW; 745Li; 2005-2002  
 BMW; 750i; 2013-2006  
 BMW; 750iL; 2001-1997  
 BMW; 750Li; 2013-2006  
 BMW; 760i; 2006-2004  
 BMW; 760Li; 2011-2010  
 BMW; 760Li; 2008-2003  
 BMW; Alpina B7; 2011  
 BMW; Alpina B7; 2008-2007  
 BMW; M1; 2012  
 BMW; M3; 2013-2008  
 BMW; M3; 2006-2001  
 BMW; M5; 2013  
 BMW; M5; 2010-2006  
 BMW; M5; 2003-2000  
 BMW; M6; 2013  
 BMW; M6; 2010-2006  
 BMW; X1; 2013-2012  
 BMW; X3; 2013-2006  
 BMW; X5; 2013-2000  
 BMW; X6; 2013-2008  
 BMW; Z3; 2002-2000  
 BMW; Z4; 2013-2003  
 BMW; Z8; 2003-2000  
 Bugatti; Veyron; 2006

### 20037 - Continued

Ferrari; 550 Maranello; 2002-2001  
 Ferrari; 575M Maranello; 2005-2002  
 Ferrari; 612 Scaglietti; 2009-2004  
 Ferrari; Enzo; 2004-2003  
 Ferrari; F430; 2009-2005  
 Land Rover; LR3; 2005  
 Land Rover; Range Rover; 2005-2002  
 Maserati; Coupe; 2006-2004  
 Maserati; Gransport; 2006-2004  
 Maserati; MC12; 2006  
 Maserati; Quattroporte; 2006-2004  
 Maserati; Spyder; 2006-2004  
 Mercedes-Benz; CL55; 2006-2001  
 Mercedes-Benz; CL65; 2006-2005  
 Mercedes-Benz; CL500; 2006-2000  
 Mercedes-Benz; CL600; 2006-2001  
 Mercedes-Benz; E55; 2005-2000  
 Mercedes-Benz; E55; 1999; Jul. & Newer  
 Mercedes-Benz; E320; 2005-2001  
 Mercedes-Benz; E430; 2002-2001  
 Mercedes-Benz; E500; 2005-2003  
 Mercedes-Benz; R550; 2008  
 Mercedes-Benz; S55; 2006-2001  
 Mercedes-Benz; S65; 2006  
 Mercedes-Benz; S350; 2006  
 Mercedes-Benz; S430; 2006-2000  
 Mercedes-Benz; S500; 2006-2000  
 Mercedes-Benz; S600; 2006-2001  
 Mercedes-Benz; SL55; 2005-2003  
 Mercedes-Benz; SL65; 2005  
 Mercedes-Benz; SL500; 2005-2001  
 Mercedes-Benz; SL600; 2005-2004  
 Mercedes-Benz; SL600; 2002-2001  
 Mercedes-Benz; SLR McLaren; 2007-2004  
 Mini; Cooper; 2012-2008  
 Porsche; 911; 2011-2005  
 Porsche; Boxster; 2011-2005  
 Porsche; Carrera GT; 2006-2004  
 Porsche; Cayenne; 2012-2008  
 Porsche; Cayenne; 2006-2003  
 Porsche; Cayman; 2011-2006  
 Porsche; Panamera; 2011-2010  
 Rolls-Royce; Phantom; 2010-2007  
 Volkswagen; Phaeton; 2006-2004; W/315 MHz Sensor  
 Volkswagen; Touareg; 2013; W/315 MHz Sensor  
 Volkswagen; Touareg; 2007-2004  
 Volkswagen; Touareg 2; 2012-2011; W/315 MHz Sensor  
 Volkswagen; Touareg 2; 2010-2008

### 20038 (W/48mm Green Insert)



Audi; A4; 2008-2002  
 Audi; A6; 2011-2005  
 Audi; A8; 2010-2001  
 Audi; Allroad Quattro; 2005-2001  
 Audi; Q7; 2012-2007  
 Audi; R8; 2012-2008

# Numerical Listing

## Service Packs

### 20038 - Continued

Audi; RS4; 2008-2007  
 Audi; S4; 2009-2004  
 Audi; S6; 2011-2007  
 Audi; S8; 2009-2007  
 Audi; S8; 2003-2001  
 Bentley; Continental; 2010-2003  
 BMW; 128i; 2012-2008  
 BMW; 135i; 2013-2012  
 BMW; 135i; 2010-2008  
 BMW; 135iS; 2013  
 BMW; 320i; 2005-2001  
 BMW; 323Ci; 2000  
 BMW; 323i; 2010-2007  
 BMW; 323i; 2006; Jun. & Newer  
 BMW; 323i; 2000  
 BMW; 325Ci; 2006-2001  
 BMW; 325i; 2006-2001  
 BMW; 325Xi; 2006-2001  
 BMW; 328Ci; 2000  
 BMW; 328i; 2013-2007  
 BMW; 328i; 2000  
 BMW; 328Xi; 2008-2007  
 BMW; 330Ci; 2006-2001  
 BMW; 330i; 2006-2001  
 BMW; 330Xi; 2006-2001  
 BMW; 335D; 2012-2009  
 BMW; 335i; 2013-2007  
 BMW; 335iS; 2013-2012  
 BMW; 335Xi; 2010  
 BMW; 335Xi; 2008-2007  
 BMW; 525i; 2007-2001  
 BMW; 525Xi; 2007-2006  
 BMW; 528i; 2013-2008  
 BMW; 528i; 2000-1997  
 BMW; 528Xi; 2009-2008  
 BMW; 530i; 2007-2001  
 BMW; 530Xi; 2007-2006  
 BMW; 535i; 2013-2008  
 BMW; 535Xi; 2010  
 BMW; 535Xi; 2008  
 BMW; 540i; 2003-1997  
 BMW; 545i; 2005-2004  
 BMW; 550i; 2013-2006  
 BMW; 640i; 2013-2012  
 BMW; 645Ci; 2005-2004  
 BMW; 650i; 2013-2012  
 BMW; 650i; 2010-2006  
 BMW; 740i; 2013-2011  
 BMW; 740i; 2001-1997  
 BMW; 740iL; 2001-1997  
 BMW; 740Li; 2013-2011  
 BMW; 745i; 2005-2002  
 BMW; 745Li; 2005-2002  
 BMW; 750i; 2013-2006  
 BMW; 750iL; 2001-1997  
 BMW; 750Li; 2013-2006  
 BMW; 760i; 2006-2004  
 BMW; 760Li; 2011-2010  
 BMW; 760Li; 2008-2003  
 BMW; Alpina B7; 2011  
 BMW; Alpina B7; 2008-2007  
 BMW; M1; 2012  
 BMW; M3; 2013-2008  
 BMW; M3; 2006-2001  
 BMW; M5; 2013

### 20038 - Continued

BMW; M5; 2010-2006  
 BMW; M5; 2003-2000  
 BMW; M6; 2013  
 BMW; M6; 2010-2006  
 BMW; X1; 2013-2012  
 BMW; X3; 2013-2006  
 BMW; X5; 2013-2000  
 BMW; X6; 2013-2008  
 BMW; Z3; 2002-2000  
 BMW; Z4; 2013-2003  
 BMW; Z8; 2003-2000  
 Bugatti; Veyron; 2006  
 Ferrari; 550 Maranello; 2002-2001  
 Ferrari; 575M Maranello; 2005-2002  
 Ferrari; 612 Scaglietti; 2009-2004  
 Ferrari; Enzo; 2004-2003  
 Ferrari; F430; 2009-2005  
 Land Rover; LR3; 2005  
 Land Rover; Range Rover; 2005-2002  
 Maserati; Coupe; 2006-2004  
 Maserati; Gransport; 2006-2004  
 Maserati; MC12; 2006  
 Maserati; Quattroporte; 2006-2004  
 Maserati; Spyder; 2006-2004  
 Mercedes-Benz; CL55; 2006-2001  
 Mercedes-Benz; CL65; 2006-2005  
 Mercedes-Benz; CL500; 2006-2000  
 Mercedes-Benz; CL600; 2006-2001  
 Mercedes-Benz; E55; 2005-2000  
 Mercedes-Benz; E55; 1999; Jul. & Newer  
 Mercedes-Benz; E320; 2005-2001  
 Mercedes-Benz; E430; 2002-2001  
 Mercedes-Benz; E500; 2005-2003  
 Mercedes-Benz; R550; 2008  
 Mercedes-Benz; S55; 2006-2001  
 Mercedes-Benz; S65; 2006  
 Mercedes-Benz; S350; 2006  
 Mercedes-Benz; S430; 2006-2000  
 Mercedes-Benz; S500; 2006-2000  
 Mercedes-Benz; S600; 2006-2001  
 Mercedes-Benz; SL55; 2005-2003  
 Mercedes-Benz; SL65; 2005  
 Mercedes-Benz; SL500; 2005-2001  
 Mercedes-Benz; SL600; 2005-2004  
 Mercedes-Benz; SL600; 2002-2001  
 Mercedes-Benz; SLR McLaren; 2007-2004  
 Mini; Cooper; 2012-2008  
 Porsche; 911; 2011-2005  
 Porsche; Boxster; 2011-2005  
 Porsche; Carrera GT; 2006-2004  
 Porsche; Cayenne; 2012-2008  
 Porsche; Cayenne; 2006-2003  
 Porsche; Cayman; 2011-2006  
 Porsche; Panamera; 2011-2010  
 Rolls-Royce; Phantom; 2010-2007  
 Volkswagen; Phaeton; 2006-2004; W/315 MHz Sensor  
 Volkswagen; Touareg; 2013; W/315 MHz Sensor  
 Volkswagen; Touareg; 2007-2004  
 Volkswagen; Touareg 2; 2012-2011; W/315 MHz Sensor  
 Volkswagen; Touareg 2; 2010-2008

# Numerical Listing Service Packs

## 20039 (W/49mm Black Insert)



Audi; A4; 2008-2002  
 Audi; A6; 2011-2005  
 Audi; A8; 2010-2001  
 Audi; Allroad Quattro; 2005-2001  
 Audi; Q7; 2012-2007  
 Audi; R8; 2012-2008  
 Audi; RS4; 2008-2007  
 Audi; S4; 2009-2004  
 Audi; S6; 2011-2007  
 Audi; S8; 2009-2007  
 Audi; S8; 2003-2001  
 Bentley; Continental; 2010-2003  
 BMW; 128i; 2012-2008  
 BMW; 135i; 2013-2012  
 BMW; 135i; 2010-2008  
 BMW; 135iS; 2013  
 BMW; 320i; 2005-2001  
 BMW; 323Ci; 2000  
 BMW; 323i; 2010-2007  
 BMW; 323i; 2006; Jun. & Newer  
 BMW; 323i; 2000  
 BMW; 325Ci; 2006-2001  
 BMW; 325i; 2006-2001  
 BMW; 325Xi; 2006-2001  
 BMW; 328Ci; 2000  
 BMW; 328i; 2013-2007  
 BMW; 328i; 2000  
 BMW; 328Xi; 2008-2007  
 BMW; 330Ci; 2006-2001  
 BMW; 330i; 2006-2001  
 BMW; 330Xi; 2006-2001  
 BMW; 335D; 2012-2009  
 BMW; 335i; 2013-2007  
 BMW; 335iS; 2013-2012  
 BMW; 335Xi; 2010  
 BMW; 335Xi; 2008-2007  
 BMW; 525i; 2007-2001  
 BMW; 525Xi; 2007-2006  
 BMW; 528i; 2013-2008  
 BMW; 528i; 2000-1997  
 BMW; 528Xi; 2009-2008  
 BMW; 530i; 2007-2001  
 BMW; 530Xi; 2007-2006  
 BMW; 535i; 2013-2008  
 BMW; 535Xi; 2010  
 BMW; 535Xi; 2008  
 BMW; 540i; 2003-1997  
 BMW; 545i; 2005-2004  
 BMW; 550i; 2013-2006  
 BMW; 640i; 2013-2012  
 BMW; 645Ci; 2005-2004  
 BMW; 650i; 2013-2012  
 BMW; 650i; 2010-2006  
 BMW; 740i; 2013-2011  
 BMW; 740i; 2001-1997  
 BMW; 740iL; 2001-1997

## 20039 - Continued

BMW; 740Li; 2013-2011  
 BMW; 745i; 2005-2002  
 BMW; 745Li; 2005-2002  
 BMW; 750i; 2013-2006  
 BMW; 750iL; 2001-1997  
 BMW; 750Li; 2013-2006  
 BMW; 760i; 2006-2004  
 BMW; 760Li; 2011-2010  
 BMW; 760Li; 2008-2003  
 BMW; Alpina B7; 2011  
 BMW; Alpina B7; 2008-2007  
 BMW; M1; 2012  
 BMW; M3; 2013-2008  
 BMW; M3; 2006-2001  
 BMW; M5; 2013  
 BMW; M5; 2010-2006  
 BMW; M5; 2003-2000  
 BMW; M6; 2013  
 BMW; M6; 2010-2006  
 BMW; X1; 2013-2012  
 BMW; X3; 2013-2006  
 BMW; X5; 2013-2000  
 BMW; X6; 2013-2008  
 BMW; Z3; 2002-2000  
 BMW; Z4; 2013-2003  
 BMW; Z8; 2003-2000  
 Bugatti; Veyron; 2006  
 Ferrari; 550 Maranello; 2002-2001  
 Ferrari; 575M Maranello; 2005-2002  
 Ferrari; 612 Scaglietti; 2009-2004  
 Ferrari; Enzo; 2004-2003  
 Ferrari; F430; 2009-2005  
 Land Rover; LR3; 2005  
 Land Rover; Range Rover; 2005-2002  
 Maserati; Coupe; 2006-2004  
 Maserati; Gransport; 2006-2004  
 Maserati; MC12; 2006  
 Maserati; Quattroporte; 2006-2004  
 Maserati; Spyder; 2006-2004  
 Mercedes-Benz; CL55; 2006-2001  
 Mercedes-Benz; CL65; 2006-2005  
 Mercedes-Benz; CL500; 2006-2000  
 Mercedes-Benz; CL600; 2006-2001  
 Mercedes-Benz; E55; 2005-2000  
 Mercedes-Benz; E55; 1999; Jul. & Newer  
 Mercedes-Benz; E320; 2005-2001  
 Mercedes-Benz; E430; 2002-2001  
 Mercedes-Benz; E500; 2005-2003  
 Mercedes-Benz; R550; 2008  
 Mercedes-Benz; S55; 2006-2001  
 Mercedes-Benz; S65; 2006  
 Mercedes-Benz; S350; 2006  
 Mercedes-Benz; S430; 2006-2000  
 Mercedes-Benz; S500; 2006-2000  
 Mercedes-Benz; S600; 2006-2001  
 Mercedes-Benz; SL55; 2005-2003  
 Mercedes-Benz; SL65; 2005  
 Mercedes-Benz; SL500; 2005-2001  
 Mercedes-Benz; SL600; 2005-2004  
 Mercedes-Benz; SL600; 2002-2001  
 Mercedes-Benz; SLR McLaren; 2007-2004  
 Mini; Cooper; 2012-2008  
 Porsche; 911; 2011-2005  
 Porsche; Boxster; 2011-2005  
 Porsche; Carrera GT; 2006-2004

# Numerical Listing Service Packs

## 20039 - Continued

Porsche; Cayenne; 2012-2008  
 Porsche; Cayenne; 2006-2003  
 Porsche; Cayman; 2011-2006  
 Porsche; Panamera; 2011-2010  
 Rolls-Royce; Phantom; 2010-2007  
 Volkswagen; Phaeton; 2006-2004; W/315 MHz Sensor  
 Volkswagen; Touareg; 2013; W/315 MHz Sensor  
 Volkswagen; Touareg; 2007-2004  
 Volkswagen; Touareg 2; 2012-2011; W/315 MHz Sensor  
 Volkswagen; Touareg 2; 2010-2008

## 20040 (W/51mm Orange Insert)



Audi; A4; 2008-2002  
 Audi; A6; 2011-2005  
 Audi; A8; 2010-2001  
 Audi; Allroad Quattro; 2005-2001  
 Audi; Q7; 2012-2007  
 Audi; R8; 2012-2008  
 Audi; RS4; 2008-2007  
 Audi; S4; 2009-2004  
 Audi; S6; 2011-2007  
 Audi; S8; 2009-2007  
 Audi; S8; 2003-2001  
 Bentley; Continental; 2010-2003  
 BMW; 128i; 2012-2008  
 BMW; 135i; 2013-2012  
 BMW; 135i; 2010-2008  
 BMW; 135iS; 2013  
 BMW; 320i; 2005-2001  
 BMW; 323Ci; 2000  
 BMW; 323i; 2010-2007  
 BMW; 323i; 2006; Jun. & Newer  
 BMW; 323i; 2000  
 BMW; 325Ci; 2006-2001  
 BMW; 325i; 2006-2001  
 BMW; 325Xi; 2006-2001  
 BMW; 328Ci; 2000  
 BMW; 328i; 2013-2007  
 BMW; 328i; 2000  
 BMW; 328Xi; 2008-2007  
 BMW; 330Ci; 2006-2001  
 BMW; 330i; 2006-2001  
 BMW; 330Xi; 2006-2001  
 BMW; 335D; 2012-2009  
 BMW; 335i; 2013-2007  
 BMW; 335iS; 2013-2012  
 BMW; 335Xi; 2010  
 BMW; 335Xi; 2008-2007  
 BMW; 525i; 2007-2001  
 BMW; 525Xi; 2007-2006  
 BMW; 528i; 2013-2008  
 BMW; 528i; 2000-1997  
 BMW; 528Xi; 2009-2008  
 BMW; 530i; 2007-2001  
 BMW; 530Xi; 2007-2006  
 BMW; 535i; 2013-2008  
 BMW; 535Xi; 2010

## 20040 - Continued

BMW; 535Xi; 2008  
 BMW; 540i; 2003-1997  
 BMW; 545i; 2005-2004  
 BMW; 550i; 2013-2006  
 BMW; 640i; 2013-2012  
 BMW; 645Ci; 2005-2004  
 BMW; 650i; 2013-2012  
 BMW; 650i; 2010-2006  
 BMW; 740i; 2013-2011  
 BMW; 740i; 2001-1997  
 BMW; 740iL; 2001-1997  
 BMW; 740Li; 2013-2011  
 BMW; 745i; 2005-2002  
 BMW; 745Li; 2005-2002  
 BMW; 750i; 2013-2006  
 BMW; 750iL; 2001-1997  
 BMW; 750Li; 2013-2006  
 BMW; 760i; 2006-2004  
 BMW; 760Li; 2011-2010  
 BMW; 760Li; 2008-2003  
 BMW; Alpina B7; 2011  
 BMW; Alpina B7; 2008-2007  
 BMW; M1; 2012  
 BMW; M3; 2013-2008  
 BMW; M3; 2006-2001  
 BMW; M5; 2013  
 BMW; M5; 2010-2006  
 BMW; M5; 2003-2000  
 BMW; M6; 2013  
 BMW; M6; 2010-2006  
 BMW; X1; 2013-2012  
 BMW; X3; 2013-2006  
 BMW; X5; 2013-2000  
 BMW; X6; 2013-2008  
 BMW; Z3; 2002-2000  
 BMW; Z4; 2013-2003  
 BMW; Z8; 2003-2000  
 Bugatti; Veyron; 2006  
 Ferrari; 550 Maranello; 2002-2001  
 Ferrari; 575M Maranello; 2005-2002  
 Ferrari; 612 Scaglietti; 2009-2004  
 Ferrari; Enzo; 2004-2003  
 Ferrari; F430; 2009-2005  
 Land Rover; LR3; 2005  
 Land Rover; Range Rover; 2005-2002  
 Maserati; Coupe; 2006-2004  
 Maserati; Gransport; 2006-2004  
 Maserati; MC12; 2006  
 Maserati; Quattroporte; 2006-2004  
 Maserati; Spyder; 2006-2004  
 Mercedes-Benz; CL55; 2006-2001  
 Mercedes-Benz; CL65; 2006-2005  
 Mercedes-Benz; CL500; 2006-2000  
 Mercedes-Benz; CL600; 2006-2001  
 Mercedes-Benz; E55; 2005-2000  
 Mercedes-Benz; E55; 1999; Jul. & Newer  
 Mercedes-Benz; E320; 2005-2001  
 Mercedes-Benz; E430; 2002-2001  
 Mercedes-Benz; E500; 2005-2003  
 Mercedes-Benz; R550; 2008  
 Mercedes-Benz; S55; 2006-2001  
 Mercedes-Benz; S65; 2006  
 Mercedes-Benz; S350; 2006  
 Mercedes-Benz; S430; 2006-2000  
 Mercedes-Benz; S500; 2006-2000



# Numerical Listing Service Packs

## 20040 - Continued

Mercedes-Benz; S600; 2006-2001  
Mercedes-Benz; SL55; 2005-2003  
Mercedes-Benz; SL65; 2005  
Mercedes-Benz; SL500; 2005-2001  
Mercedes-Benz; SL600; 2005-2004  
Mercedes-Benz; SL600; 2002-2001  
Mercedes-Benz; SLR McLaren; 2007-2004  
Mini; Cooper; 2012-2008  
Porsche; 911; 2011-2005  
Porsche; Boxster; 2011-2005  
Porsche; Carrera GT; 2006-2004  
Porsche; Cayenne; 2012-2008  
Porsche; Cayenne; 2006-2003  
Porsche; Cayman; 2011-2006  
Porsche; Panamera; 2011-2010  
Rolls-Royce; Phantom; 2010-2007  
Volkswagen; Phaeton; 2006-2004; W/315 MHz Sensor  
Volkswagen; Touareg; 2013; W/315 MHz Sensor  
Volkswagen; Touareg; 2007-2004  
Volkswagen; Touareg 2; 2012-2011; W/315 MHz Sensor  
Volkswagen; Touareg 2; 2010-2008

# Notes

---

# Notes

---

# Notes

---

# Notes

---



# NHTSA TREAD Act

The Transportation Recall Enhancement, Accountability and Documentation (TREAD) Act was passed in the fall of 2000. The TREAD Act mandated that every new car manufactured for sale in the U.S. after September 1, 2007 must be equipped with sensors that monitor the pressure in all four tires. Sensors installed in the vehicle's wheels send a signal via RF to the vehicle's computer. The computer then processes the sensor data to alert the driver if pressure drops 25% below the specified cold placard pressure for the tire.

## DID YOU KNOW

- 40% tire under-inflation increases braking distance by 10%.
- If every vehicle in the United States had properly inflated tires, we'd realize a savings of 4 million gallons of gasoline per day, everyday.
- An estimated 23,000 accidents and 535 fatal accidents annually involve blowouts or flat tires.
- 20% tire under-inflation reduces tire life by 20% and reduces fuel economy by 2% to 3%.
- Approximately 27% of passenger cars and 33% of light trucks on U.S. roadways are driven with one or more tires substantially under-inflated.



**SCHRADER-USA**

205 FRAZIER ROAD  
ALTAVISTA, VA 24517

CUSTOMER SUPPORT LINE // 1.800.288.1804 ▶▶ [SCHRADERINTERNATIONAL.COM](http://SCHRADERINTERNATIONAL.COM)