

DILL TPMS APPLICATIONS CHART ©

OE	Model	Model Year	Multi-App Sensor	Multi-App Kit	Dill Sensor	Dill Kit	OE Sensor Part #	Valve Stem Replacement	Relearn	FCC ID #
Acura	CSX	08-09	7002	7020K	1212	2045K	42753-SNA-A83	NO	A0201	GQ4-36T
Acura	ILX	13	7002	7020K	5513	7000K	42753-TX6-A81	VS70		KR5S180052015B
Acura	MDX	04-06			1057	2000K	06421-S3V-A04	1096	A0201	T7B-2T
Acura	MDX	07-13			1209	1100K	42753-STK-A04	NO	A0201	PAXPMV107G
Acura	MDX	13		7020K	5512	7000K	42753-TX4-A51	VS70		KR5S180052015B
Acura	RDX	07-12			1209	1100K	42753-STK-A04	NO	A0201	PAXPMV107G
Acura	RDX	13		7020K	5512	7000K	42753-TX4-A51	VS70		KR5S180052015B
Acura	RL	05-08			1057	2000K	06421-S3V-A04	1096	A0201	T7B-2T
Acura	RL	09-12			1057	2045K or 2000K	42753-SHJ-A53	NO OR 1096	A0201	GQ4-35T OR T7B-2T
Acura	TL	05-08			1057	2000K	06421-S3V-A04	1096	A0201	T7B-2T
Acura	TL(Hi-Line)	09-13			1214	2045K	42753-TK4-A01	NO	A0201	GQ4-37T
Acura	TSX	07-13			1209	1100K	42753-TL2-A52	NO	A0201	PAXPMV107G
Acura	ZDX(Hi-Line)	10-13			1214	2045K	42753-TK4-A01	NO	A0201	GQ4-37T
Audi	Allroad(315 Mhz)	01-05			9004	1090K	4D0 907 275A	1092	E0101	OYGTSSRE3B
Audi	A6 Allroad(433 Mhz)	01-06			9001	1090K	4D0 907 275C	1092	E0101	OYGTSSRE4B
Audi	A6 Allroad(433 Mhz)	07-09			9007	1090K	4F0 907 275B	1092	E0101	OYG TSSRE4TB
Audi	A6 Allroad(433 Mhz)-- Post June 2009	10			9011	1090K	4F0 907 275D	1092	E0101	OYG TSSRE4TC
Audi	A3(315 Mhz)	06-12			1053	1030K	1K0907253D	NO	E0101	KR5S120123
Audi	A4(433 Mhz)	05-08			9007	1090K	4F0 907 275B	1092	E0101	OYG TSSRE4TB
Audi	A4 (315 Mhz)	09-12			1053	1030K	1K0907253D	NO	E0101	KR5S120123
Audi	A5(315 Mhz)	08-12			1053	1030K	1K0907253D	NO	E0101	KR5S120123
Audi	A6(315 Mhz)	02-04			9004	1090K	4D0 907 275A	1092	E0101	OYGTSSRE3B
Audi	A6(433 Mhz)	05-09			9007	1090K	4F0 907 275B	1092	E0101	OYG TSSRE4TB
Audi	A6(433 Mhz)-- Post June 2009	10-12			9011	1090K	4F0 907 275D	1092	E0101	OYG TSSRE4TC
Audi	A8(315 Mhz)	00-07			9004	1090K	4D0 907 275A	1092	E0101	OYGTSSRE3B
Audi	A8(433 Mhz)	00-12			9001	1090K	4D0 907 275C	1092	E0101	OYGTSSRE4B
Audi	Q5(315 Mhz)	09-12			1053	1030K	1K0907253D	NO	E0101	KR5S120123
Audi	Q7(433 Mhz)	06-09			9007	1090K	4F0 907 275B	1092	E0101	OYG TSSRE4TB
Audi	Q7(433 Mhz)-- Post June 2009	10-12			9011	1090K	4F0 907 275D	1092	E0101	OYG TSSRE4TC
Audi	R8(433 Mhz)	08-09			9007	1090K	4F0 907 275B	1092	E0101	OYG TSSRE4TB
Audi	R8(433 Mhz)-- Post June 2009	10-12			9011	1090K	4F0 907 275D	1092	E0101	OYG TSSRE4TC
Audi	RS4(433 Mhz)	07-08			9007	1090K	4F0 907 275B	1092	E0101	OYG TSSRE4TB
Audi	RS6(315 Mhz)	01-05			9004	1090K	4D0 907 275A	1092	E0101	OYGTSSRE3B
Audi	RS6(433 Mhz)	01-04			9001	1090K	4D0 907 275C	1092	E0101	OYGTSSRE4B
Audi	S4(433 Mhz)	05-07			9007	1090K	4F0 907 275B	1092	E0101	OYG TSSRE4TB
Audi	S4(315 Mhz)	10-12			1053	1030K	1K0907253D	NO	E0101	KR5S120123
Audi	S5(315 Mhz)	08-12			1053	1030K	1K0907253D	NO	E0101	KR5S120123
Audi	S6(433 Mhz)	05-09			9007	1090K	4F0 907 275B	1092	E0101	OYG TSSRE4TB
Audi	S6(433 Mhz)-- Post June 2009	10-12			9011	1090K	4F0 907 275D	1092	E0101	OYG TSSRE4TC
Audi	S8(315 Mhz)	00-08			9004	1090K	4D0 907 275A	1092	E0101	OYGTSSRE3B
Audi	S8(433 Mhz)	00-09			9001	1090K	4D0 907 275C	1092	E0101	OYGTSSRE4B
Audi	TT(315 Mhz)	08-12			1053	1030K	1K0907253D	NO	E0101	KR5S120123
Bentley	Continental GT--433 Mhz	03-05			9001	1090K	4D0 907 275C	1092-1095		OYGTSSRE4B
Bentley	Continental GT--433 Mhz (Post May)	05-12			9007	1090K	4F0 907 275B	1092-1095		OYG TSSRE4TB
Bentley	Azure--433 Mhz	07-12			9007	1090K	4F0 907 275B	1092-1095		OYG TSSRE4TB
Bentley	Mulsanne--433 Mhz	11-12			9007	1090K	4F0 907 275B	1092-1095		OYG TSSRE4TB
Bentley	Flying Spur--433 Mhz	06-12			9007	1090K	4F0 907 275B	1092-1095		OYG TSSRE4TB
BMW	1 Series(433 Mhz)	07-10			1027	1090K	36 23 6 781 847	1092-1095	E0201	OYGTSSRE4TC
BMW	1 Series(433 Mhz)	11-13			9012	2000K	36 10 6 790 054	1096	E0201	OYGTSSRE4D
BMW	3 Series(315 Mhz)	00-02			9004	1090K	36 11 8 378 681	1092-1095	E0201	OYGTSSRE3B
BMW	3 Series(433 Mhz)	00-04			9002	1090K	36 11 8 378 682	1092-1095	E0201	OYG TSSRE4B
BMW	3 Series(433 Mhz)	07-10			1027	1090K	36 23 6 781 847	1092-1095	E0201	OYGTSSRE4TC
BMW	3 Series(433 Mhz)-- Post September 2009	11-12			9012	2000K	36 10 6 790 054	1096	E0201	OYGTSSRE4D
BMW	3 Series	13			9017	2000K	36 10 6 798 872	1096	E201	OYGTSSRE4DB
BMW	5 Series(315 Mhz)	00-02			9004	1090K	36 11 8 378 681	1092-1095	E0201	OYGTSSRE3B
BMW	5 Series(433 Mhz)	02-05			9002	1090K	36 11 8 378 682	1092-1095	E0201	OYG TSSRE4B
BMW	5 Series(433 Mhz)	06-10			1027	1090K	36 23 6 781 847	1092-1095	E0201	OYGTSSRE4TC
BMW	5 Series(433 Mhz)	11-13			9012	2000K	36 10 6 790 054	1096	E0201	OYGTSSRE4D
BMW	6 Series(433 Mhz)	06-10			1027	1090K	36 23 6 781 847	1092-1095	E0201	OYGTSSRE4TC
BMW	6 Series(433 Mhz)	11-13			9012	2000K	36 10 6 790 054	1096	E0201	OYGTSSRE4D

DILL TPMS APPLICATIONS CHART ©

OE	Model	Model Year	Multi-App Sensor	Multi-App Kit	Dill Sensor	Dill Kit	OE Sensor Part #	Valve Stem Replacement	Relearn	FCC ID #
BMW	7 Series(315 Mhz)	00-01			9004	1090K	36 11 8 378 681	1092-1095	E0201	OYGTSSRE3B
BMW	7 Series(433 Mhz)	02-05			9002	1090K	36 11 8 378 682	1092-1095	E0201	OYG TSSRE4B
BMW	7 Series(433 Mhz)	06-10			1027	1090K	36 23 6 781 847	1092-1095	E0201	OYGTSSRE4C
BMW	7 Series(433 Mhz)	11-13			9012	2000K	36 10 6 790 054	1096	E0201	OYGTSSRE4D
BMW	M Series(433 Mhz)	06-10			1027	1090K	36 23 6 781 847	1092-1095	E0202	OYGTSSRE4TC
BMW	M Series(433 Mhz)	11-13			9012	2000K	36 10 6 790 054	1096	E0202	OYGTSSRE4D
BMW	X1	12-13			9012	2000K	36 10 6 790 054	1096	E0202	OYGTSSRE4D
BMW	X3(433 Mhz)	06-10			1027	1090K	36 23 6 781 847	1092-1095	E0202	OYGTSSRE4TC
BMW	X3(433 Mhz)	11-13			9012	2000K	36 10 6 790 054	1096	E0202	OYGTSSRE4D
BMW	X5(433 Mhz)	01-04			9003	1090K	36 14 6 752 128	1092-1095	E0202	OYG TSSRE4PB
BMW	X5(433 Mhz)	05-10			1027	1090K	36 23 6 781 847	1092-1095	E0202	OYGTSSRE4TC
BMW	X5(433 Mhz)	11-13			9012	2000K	36 10 6 790 054	1096	E0202	OYGTSSRE4D
BMW	X6(433 Mhz)	08-10			1027	1090K	36 23 6 781 847	1092-1095	E0202	OYGTSSRE4TC
BMW	X6(433 Mhz)	11-13			9012	2000K	36 10 6 790 054	1096	E0202	OYGTSSRE4D
BMW	Z Series(433 Mhz)	06-10			1027	1090K	36 23 6 781 847	1092-1095	E0202	OYGTSSRE4TC
BMW	Z Series(433 Mhz)	11-13			9012	2000K	36 10 6 790 054	1096	E0202	OYGTSSRE4D
BMW	Alpina(433 Mhz)	07-08			9002	1090K	36 11 8 378 682	1092-1095	E0201	OYG TSSRE4B
**1091-1099-1099L are valve options on some special wheel packages.										
Bugatti	Veyron	05-06			NA	1090K	NA	1092-1095		UNKNOWN
Buick	Allure	07-08	7001	7020K	9158	1050K	15921013	NO	D0305	MRXGMX272RS
Buick	Allure	09	7001-R	VS80	9153	VS950	12768826	VS950	D0305	MRXG53MA4S
Buick	Enclave	08	7001	7020K	9158	1050K	15921013	NO	D0305	MRXGMX272RS
Buick	Enclave	09-12	7001-R	VS80	9153	VS950	20923680	VS950	D0305	MRXG53MA4S
Buick	Encore	13	7001-R	VS80	9153	VS950	20922900	VS950	D0305	MRXG53MA4S
Buick	LaCrosse	07-08	7001	7020K	9158	1050K	15921013	NO	D0305	MRXGMX272RS
Buick	LaCrosse	09-13	7001-R	VS80	9153	VS950	20922900	VS950	D0305	MRXG53MA4S
Buick	Lesabre	07	7001-R	VS80	9153	VS950	25799331	VS950	D0322	MRXG53MA4S
Buick	Lucerne	07-11	7001-R	VS80	9153	VS950	25920615	VS950	D0305	MRXG53MA4S
Buick	Rainier	06-07	7001	7020K	9116	1070K	25774006	NO	D0321	MRXGMT51MAN
Buick	Rainier	07	7001-R	VS80	9153	VS950	25799331	VS950	D0321	MRXG53MA4S
Buick	Regal	11-13	7001-R	VS80	9153	VS950	20922900	VS950	D0305	MRXG53MA4S
Buick	Verano	12	7001-R	VS80	9153	VS950	20925924	VS950	D0305	MRXG53MA4S
Cadillac	ATS	13	7001-R	VS80	NEW	VS90	22959744	VS90		UNKNOWN
Cadillac	ATS--Sport	13		7020K	NEW	7020K	22959748	VS70		UNKNOWN
Cadillac	CTS	04-07	7001	7020K	9116	1070K	25774006	NO	D0305	MRXGMT51MAN
Cadillac	CTS	08-13	7001	7001-R	9153	VS950	20923680	VS950	D0319	MRXG53MA4S
Cadillac	CTS-V	09-12	7001	7020K	9158	1050K	15268606	NO	D0319	MRXGMX272RS
Cadillac	Deville	01-05			9117	1080K	25773946	NO	D0305	MRXGMG2RCAM
Cadillac	DTS	06	7001	7020K	9158	1070K	15268606	NO	D0305	MRXGMX272RS
Cadillac	DTS	07-11	7001-R	VS80	9153	VS950	25920615	VS950	D0305	MRXG53MA4S
Cadillac	Escalade-ESV-EXT	04			9115	1070K	15136883	NO	D0321	MRXGMT102PWM
Cadillac	Escalade-ESV-EXT	05-06			9107	1070K	15114379	NO	D0321	MRXGMG2R3PM
Cadillac	Escalade-ESV-EXT	07	7001	7020K	NA	2020K	15825475	NO	D0321	GQ428T
Cadillac	Escalade-ESV-EXT	07	7001	7020K	9158	1070K	TRW Sensor Replacement	NO	D0321	MRXGMX272RS
Cadillac	Escalade-ESV-EXT	07-13	7001-R	VS80	9153	VS950	20923680	VS950	D0305	MRXG53MA4S
Cadillac	Seville	01-04			9117	1080K	25773946	NO	D0305	MRXGMG2RCAM
Cadillac	SRX	04-06	7001	7020K	9116	1070K	25774006	NO	D0305	MRXGMT51MAN
Cadillac	SRX	07-13	7001-R	VS80	9153	VS950	12768826	VS950	D0305	MRXG53MA4S
Cadillac	STS	05-09	7001	7020K	9076	1070K	25758220	NO	D0319	MRXGMX295FM
Cadillac	STS	09	7001	7020K	9158	1070K	15268606	NO	D0319	MRXGMX272RS
Cadillac	STS	09-11	7001-R	VS80	9153	VS950	25920615	VS950	D0305	MRXG53MA4S
Cadillac	XLR	04-09	7001	7020K	9076	1070K	25758220	NO	D0305	MRXGMX295FM
Cadillac	XTS	13	7001-R	VS80	9153	VS950	20922900	VS950	D0305	MRXG53MA4S
**The 1050K is to be used on the Siemens sensors and the 1070K is to be used on the Schrader sensors.										
Chevrolet	Avalanche	04			9115	1070K	15136883	NO	D0321	MRXGMT102PWM
Chevrolet	Avalanche	05-06			9107	1070K	15114379	NO	D0321	MRXGMG2R3PM
Chevrolet	Avalanche	07	7001	7020K	NA	2020K	15825475	NO	D0321	GQ428T
Chevrolet	Avalanche	07	7001	7020K	9158	1070K	TRW Sensor Replacement	NO	D0321	MRXGMX272RS
Chevrolet	Avalanche	07-13	7001-R	VS80	9153	VS950	20923680	VS950	D0305	MRXG53MA4S
Chevrolet	Aveo	07-11			9153	VS950	25920615	VS950	D0303	MRXG53MA4S
Chevrolet	Camaro	10-13	7001-R	VS80	9153	VS950	12768826	VS950	D0301	MRXG53MA4S
Chevrolet	Camaro-Sport	12-13	7001	7020K	9158	1070K	20964159	NO		MRXC53MA4S
Chevrolet	Caprice	11-12	7001	7020K	9158	1050K	15268606	NO	D0319	MRXGMX272RS
Chevrolet	Captiva	12-13	7001-R	VS80	9153	VS950	20923680	VS950	D0305	MRXG53MA4S

DILL TPMS APPLICATIONS CHART ©

OE	Model	Model Year	Multi-App Sensor	Multi-App Kit	Dill Sensor	Dill Kit	OE Sensor Part #	Valve Stem Replacement	Relearn	FCC ID #
Chevrolet	Cobalt	08-10	7001	7020K	9158	1050K	15268606	NO	D0319	MRXGMX272RS
Chevrolet	Cobalt	08-10	7001-R	VS80	9153	VS950	12768826	VS950	D0319	MRXG53MA4S
Chevrolet	Colorado	07-12			9131	1110K	15122618	NO	D0321	MRXGMT102PWM
Chevrolet	Corvette	97-00			8006	1077K	10438853	NO	D0314	MRXGMG2R3FM
Chevrolet	Corvette-C5-Z6	01-04			9117	1080K	25773946	NO	D0313	MRXGMG2RCAM
Chevrolet	Corvette-C6	05-09	7001	7020K	9076	1070K	25758220	NO	D0305	MRXGMX295FM
Chevrolet	Corvette	10-11	7001	7020K	9158	1070K	15268606	NO	D0305	MRXGMX272RS
Chevrolet	Corvette	12-13	7001-R	VS80	9153	VS950	20925924	VS950	D0305	MRXG53MA4S
Chevrolet	Cruze	11-13	7001-R	VS80	9153	VS950	20922900	VS950	D0305	MRXG53MA4S
Chevrolet	Equinox	07-09	7001	7020K	9158	1050K	15921013	NO	D0319	MRXGMX272RS
Chevrolet	Equinox	10-13	7001-R	VS80	9153	VS950	20922900	VS950	D0301	MRXG53MA4S
Chevrolet	Express Series	08-09	7001	7020K	9158	1050K	15921013	NO	D0305	MRXGMX272RS
Chevrolet	Express Series(1500)	10-13	7001-R	VS80	9153	VS950	20923680	VS950	D0305	MRXG53MA4S
Chevrolet	Express Series(2500/3500)	10-13			9153	VS950	20923680	VS950	D0305	MRXG53MA4S
Chevrolet	G Series	08	7001	7020K	9158	1050K	15921013	NO	D0305	MRXGMX272RS
Chevrolet	HHR	08-09	7001	7020K	9158	1070K	15268606	NO	D0319	MRXGMX272RS
Chevrolet	HHR	08-11	7001-R	VS80	9153	VS950	25920615	VS950	D0319	MRXG53MA4S
Chevrolet	Impala	06-07	7001	7020K	9158	1070K	15268606	NO	D0305	MRXGMX272RS
Chevrolet	Impala	07-14	7001-R	VS80	9153	VS950	20923680	VS950	D0305	MRXG53MA4S
Chevrolet	Malibu(< 10/14/07)	08	7001	7020K	9158	1050K	15921013	NO	D0319	MRXGMX272RS
Chevrolet	Malibu	08-13	7001-R	VS80	9153	VS950	20923680	VS950	D0319	MRXG53MA4S
Chevrolet	Monte Carlo	06-07	7001	7020K	9158	1070K	15268606	NO	D0305	MRXGMX272RS
Chevrolet	Monte Carlo	07	7001-R	VS80	9153	VS950	25920615	VS950	D0305	MRXG53MA4S
Chevrolet	Orlando	12	7001-R	VS80	9153	VS950	25920615	VS950	D0305	MRXG53MA4S
Chevrolet	Silverado	04			9115	1070K	15136883	NO	D0321	MRXGMT102PWM
Chevrolet	Silverado	05-06			9107	1070K	15114379	NO	D0321	MRXGMG2R3PM
Chevrolet	Silverado	07	7001	7020K	NA	2020K	15825475	NO	D0321	GQ428T
Chevrolet	Silverado	07	7001	7020K	9158	1070K	TRW Sensor Replacement	NO	D0321	MRXGMX272RS
Chevrolet	Silverado(1500)	07-13	7001-R	VS80	9153	VS950	20923680	VS950	D0305	MRXG53MA4S
Chevrolet	Silverado(2500/3500)	07-13			9153	VS950	20923680	VS950	D0305	MRXG53MA4S
Chevrolet	Sonic	12-13	7001-R	VS80	9153	VS950	20922900	VS950	D0301	MRXG53MA4S
Chevrolet	Spark	13	7001-R	VS80	9153	VS950	12768826	VS950		MRXG53MA4S
Chevrolet	SSR	06-07	7001	7020K	9116	1070K	25774006	NO	D0321	MRXGMT51MAN
Chevrolet	Suburban	04			9115	1070K	15136883	NO	D0321	MRXGMT102PWM
Chevrolet	Suburban	05-06			9107	1070K	15114379	NO	D0321	MRXGMG2R3PM
Chevrolet	Suburban	07	7001	7020K	NA	2020K	15825475	NO	D0321	GQ428T
Chevrolet	Suburban	07	7001	7020K	9158	1070K	TRW Sensor Replacement	NO	D0321	MRXGMX272RS
Chevrolet	Suburban(1500)	07-13	7001-R	VS80	9153	VS950	20923680	VS950	D0305	MRXG53MA4S
Chevrolet	Suburban(2500)	07-13			9153	VS950	20923680	VS950	D0305	MRXG53MA4S
Chevrolet	Tahoe	04			9115	1070K	15136883	NO	D0321	MRXGMT102PWM
Chevrolet	Tahoe	05-06			9107	1070K	15114379	NO	D0321	MRXGMG2R3PM
Chevrolet	Tahoe	07	7001	7020K	NA	2020K	15825475	NO	D0321	GQ428T
Chevrolet	Tahoe	07	7001	7020K	9158	1070K	TRW Sensor Replacement	NO	D0321	MRXGMX272RS
Chevrolet	Tahoe	07-13	7001-R	VS80	9153	VS950	20923680	VS950	D0305	MRXG53MA4S
Chevrolet	Trailblazer	06-09	7001	7020K	9116	1070K	25774006	NO	D0321	MRXGMT51MAN
Chevrolet	Traverse	09-13	7001-R	VS80	9153	VS950	20923680	VS950	D0305	MRXG53MA4S
Chevrolet	Uplander	08-09	7001	7020K	9158	1070K	15268606	NO	D0319	MRXGMX272RS
Chevrolet	Volt	10-13	7001-R	VS80	9153	VS950	20922900	VS950	D0301	MRXG53MA4S
**The 1050K is to be used on the Siemens sensors and the 1070K is to be used on the Schrader sensors.										
Chrysler	200	11-13	7001	7020K	1051	7000K	68078861AA	VS70	D0203	KR5S180052015B
Chrysler	300M(433 Mhz)	02-04	7004	7020K	9028	1080K	52088990AC	NO	D0204	MRXTG224AM02
Chrysler	300(315 Mhz)	05-07	7001	7020K	1051	1050K	68111696AA	NO	D0203	KR5S180052015B
Chrysler	300(433 Mhz)	08-10	7004	7020K	1043	1050K	68001698AB	NO	D0203	KR5S180052020A
Chrysler	300(433 Mhz)	09-10			9214	2030K	56029400AD	9066K	D0203	MRXMERCXTX1
Chrysler	300(433 Mhz)	11-13			9398	VS950	56029398AB	VS950	D0203	MRXC4W4MA4
Chrysler	Aspen	07-09	7001	7020K	1051 **	1050K or 2030K	56029465AB	9066K	D0203	KR5S180052015B OR MRXDCA315TX1

DILL TPMS APPLICATIONS CHART ©

OE	Model	Model Year	Multi-App Sensor	Multi-App Kit	Dill Sensor	Dill Kit	OE Sensor Part #	Valve Stem Replacement	Relearn	FCC ID #
Chrysler	Concorde(433 Mhz)	02-04	7004	7020K	9028	1080K	52088990AC	NO	D0204	MRXTG224AM02
Chrysler	Crossfire(433 Mhz)	04-08	7004	7020K	9028	1080K	52088990AC	NO		MRXTG224AM02
Chrysler	Crossfire	05	7001	7020K	1051 **	1050K or 2030K	56053030AB	9066K		KR5S180052015B OR MRXDCA315TX1
Chrysler	Pacifica(433 Mhz)	04	7004	7020K	9028	1080K	52088990AC	NO	D0203	MRXTG224AM02
Chrysler	Pacifica	04-05	7001	7020K	1052	1050K	04727392AB	NO	D0203	KR5S120123
Chrysler	Pacifica	06-08	7001	7020K	1051	1050K	68001696AB	NO	D0203	KR5S180052015B
Chrysler	Prowler	01			8004	1080K	4815132AB	NO	D0201	MRXPRAMTX
Chrysler	Prowler(433 Mhz)	02	7004	7020K	9028	1080K	52088990AC	NO	D0201	MRXTG224AM02
Chrysler	PT Cruiser	08-10	7001	7020K	1051	1050K	68001696AB	NO	D0203	KR5S180052015B
Chrysler	Sebring(315 Mhz)	07-10	7001	7020K	1051	1050K	68001696AB	NO	D0203	KR5S180052015B
Chrysler	Sebring(315 Mhz)	10	7001	7020K	1051	7000K	68078861AA	VS70	D0203	KR5S180052015B
Chrysler	Town & Country(433 Mhz)	02-03	7004	7020K	9028	1080K	52088990AC	NO	D0204	MRXTG224AM02
Chrysler	Town & Country	04-05	7001	7020K	1052	1050K	04727392AB	NO	D0203	KR5S120123
Chrysler	Town & Country	06-07	7001	7020K	1051	1050K	56053030AB	NO	D0203	KR5S180052015B
Chrysler	Town & Country (433 Mhz)	08-10	7004	7020K	1043	1050K	68001698AB	NO	D0203	KR5S180052020A
Chrysler	Town & Country (433 Mhz)	10	7004	7020K	1043	7000K	68078768AA	VS70	D0203	KR5S180052020A
Chrysler	Town & Country (433 Mhz)	11-13			9398	VS950	56029398AB	VS950	D0203	MRXC4W4MA4
Chrysler	Voyager(433 Mhz)	02-03	7004	7020K	9028	1080K	52088990AC	NO	D0204	MRXTG224AM02
**The 1050K is to be used on the Siemens sensors and the 2030K is to be used on the Schrader sensors.										
Dodge	Avenger	08-10	7001	7020K	1051	1050	68001696AB	NO	D0203	KR5S180052015B
Dodge	Avenger	10-13	7001	7020K	1051	7000K	68078861AA	VS70	D0203	KR5S180052015B
Dodge	Caliber	07-10	7001	7020K	1051	1050K	68001696AB	NO	D0203	KR5S180052015B
Dodge	Caliber	11-12	7001	7020K	1051	7000K	68078861AA	VS70	D0203	KR5S180052015B
Dodge	Caliber--export	12	7004	7020K	1043	7000K	68078768AA	VS70	D0203	KR5S180052020A
Dodge	Caravan(433 Mhz)	02-03	7004	7020K	9028	1080K	52088990AC	NO	D0204	MRXTG224AM02
Dodge	Caravan	04-05	7001	7020K	1052	1050K	04727392AB	NO	D0203	KR5S120123
Dodge	Caravan	06-07	7001	7020K	1051	1050K	56053030AB	NO	D0203	KR5S180052015B
Dodge	Challenger	08	7004	7020K	1043	1050K	68078768AA	NO	D0203	KR5S180052020A
Dodge	Challenger--SRT (433 Mhz)	08-13			9214	2030K	56029400AE	9066K	D0203	MRXMERTX1
Dodge	Challenger(433 Mhz)	10-13			9398	VS950	56029398AB	VS950	D0203	MRXC4W4MA4
Dodge	Charger	06-07	7001	7020K	1051	1050K	68001696AB	NO	D0203	KR5S180052015B
Dodge	Charger(433 Mhz)	08	7004	7020K	1043	1050K	68001698AB	NO	D0203	KR5S180052020A
Dodge	Charger(433 Mhz)--SRT	09-13			9214	2030K	56029400AE	9066K	D0203	MRXMERTX1
Dodge	Charger(433 Mhz)	10-13			9398	VS950	56029398AB	VS950	D0203	MRXC4W4MA4
Dodge	Dakota	08-10	7001	7020K	9154	2030K	56029319AC	9066K	D0203	MRXC4N3MF9
Dodge	Dakota	11	7001-R	VS80	9308	VS950	56029479AA	VS950	D0203	MRXC4N3MF9
Dodge	Dart--433 Mhz	13			5775	VS90	68193586AA	VS90		KR55WY9012
Dodge	Durango	07-09	7001	7020K	1051 **	1050K or 2030K	56029465AB	9066K	D0203	KR5S180052015B OR MRXDCA315TX1
Dodge	Durango(433 Mhz)	11-13			9398	VS950	56029398AB	VS950	D0203	MRXC4W4MA4
Dodge	Grand Caravan(433 Mhz)	02-03	7004	7020K	9028	1080K	52088990AC	NO	D0204	MRXTG224AM02
Dodge	Grand Caravan	04-05	7001	7020K	1052	1050K	04727392AB	NO	D0203	KR5S120123
Dodge	Grand Caravan	06-07	7001	7020K	1051	1050K	56053030AB	NO	D0203	KR5S180052015B
Dodge	Grand Caravan (433 Mhz)	08-10	7004	7020K	1043	1050K	68001698AB	NO	D0203	KR5S180052020A
Dodge	Grand Caravan (433 Mhz)	10	7004	7020K	1043	7000K	68078768AA	VS70	D0203	KR5S180052020A
Dodge	Grand Caravan(433 Mhz)	11-13			9398	VS950	56029398AB	VS950	D0203	MRXC4W4MA4
Dodge	Intrepid(433 Mhz)	02-04	7004	7020K	9028	1080K	52088990AC	NO	D0204	MRXTG224AM02
Dodge	Journey(433 Mhz)	09-10	7004	7020K	1043	1050K	68001698AB	NO	D0203	KR5S180052020A
Dodge	Journey(433 Mhz)	10-13			9398	VS950	56029398AA	VS950	D0203	MRXC4W4MA4
Dodge	Magnum	05-07	7001	7020K	1051	1050K	68001696AB	NO	D0203	KR5S180052015B
Dodge	Magnum(433 Mhz)	08	7004	7020K	1043	1050K	68001698AB	NO	D0203	KR5S180052020A

DILL TPMS APPLICATIONS CHART ©

OE	Model	Model Year	Multi-App Sensor	Multi-App Kit	Dill Sensor	Dill Kit	OE Sensor Part #	Valve Stem Replacement	Relearn	FCC ID #
Dodge	Nitro	07-11	7001	7020K	1051 **	1050K or 2030K	56029465AB	9066K	D0203	KR5S180052015B OR MRXDCA315TX1
Dodge	Nitro(Alloy)	10-11	7001-R	VS80	9308	VS950	56029479AA	VS950	D0203	MRXC4N3MF9
Dodge	Ram(HP-315 Mhz) 1500/2500	08			9154	2030K	56029319AC (Check VIN)	9066K	D0203	MRXC4N3MF9
Dodge	Ram(433 Mhz) 1500/2500/3500	09-10	7004	7020K	1043	1050K	56029359AC	NO	D0203	KR5S180052020A
Dodge	Ram(433 Mhz) 1500/2500/3500	10-13			9398	VS950	56029398AB	VS950	D0203	MRXC4W4MA4
Dodge	Sprinter	07-12			1042	1098K	68038945AA	1098K	D0203	KR5S122228001
Dodge	Stratus	07	7001	7020K	1051	1050K	56053030AB	NO	D0203	KR5S180052015B
Dodge	Viper(433 Mhz)	03-10	7004	7020K	9028	1080K	52088990AD	NO		MRXTG224AM02
**The 1050K is to be used on the Siemens sensors and the 2030K is to be used on the Schrader sensors.										
Ferrari	430(433 Mhz)	06-07			9001	1090K	22 45 49	1092		OYGTSSRE4B
Ferrari	430(433 Mhz)	08-12			9007	1090K	23 92 98	1092		OYG TSSRE4TB
Ferrari	458(433 Mhz)	10-12			9008	1090K	22 88 87	1092		OYG TSSRE4TC
Ferrari	550(433 Mhz)	02-12			9001	1090K	22 45 49	1092		OYGTSSRE4B
Ferrari	575(433 Mhz)	02-06			9001	1090K	22 45 49	1092		OYGTSSRE4B
Ferrari	575(315 Mhz)	02-05			9004	1090K	22 45 48	1092		OYGTSSRE3B
Ferrari	599	04-12			9001	1090K	22 45 49	1092		OYGTSSRE4B
Ferrari	612(433 Mhz)	04-12			9001	1090K	22 45 49	1092		OYGTSSRE4B
Ferrari	California(433 Mhz)	09-12			9008	1090K	22 88 87	1092		OYG TSSRE4TC
Ferrari	Enzo(433 Mhz)	03-04			9005	1090K	22 45 51	1092		OYGTSSRE4PB
Ferrari	FXX(433 Mhz)	05-06			9005	1090K	22 45 51	1092		OYGTSSRE4PB
Ferrari	Spider(433 Mhz)	02-09			9001	1090K	22 45 49	1092		OYGTSSRE4B
Fiat	500(433 Mhz)	11-12			9398	VS950	56029398AB	VS950		MRXC4W4MA4
Ford	Crown Victoria	06-11	7001-R	VS80	1048	NA	6F2Z-1A189A	NO	D0105	KR5SWY7635
Ford	C-Max	12-13	7001-R	VS80	9315	VS950	CM5T-1A150-AA	VS950	D0105	MRXFE3MAF4
Ford	E Series	07-09			1048-HP	NA	8C2Z-1A189A	NO	D0101	KOBFTD06A
Ford	E Series(HP)	10-13			9315	VS950	CM5T-1A150-AA	VS950	D0101	MRXFE3MAF4
Ford	Edge	07-10	7001-R	VS80	1048	NA	7L1Z-1A189A	NO	D0105	KR5SWY7635
Ford	Edge	11-13	7001-R	VS80	9315	VS950	CM5T-1A150-AA	VS950	D0105	MRXFE3MAF4
Ford	Escape	06-08	7001-R	VS80	1048	NA	6F2Z-1A189A	NO	D0105	KR5SWY7635
Ford	Escape	09-13	7001-R	VS80	9315	VS950	CM5T-1A150-AA	VS950	D0105	MRXFE3MAF4
Ford	Expedition(433 Mhz)	03-04	*7004	7020K	9096	1060K	4L2T1A150BA	NO	D0104	MRXTG224AM02
Ford	Expedition(315 Mhz)	05-06	7001	7020K	9135	1060K	5L1ZA150AB	NO	D0104	MRXTG224AM01
Ford	Expedition	07-10	7001-R	VS80	1048	NA	7L1Z-1A189A	NO	D0105	KR5SWY7635
Ford	Expedition	11-13	7001-R	VS80	9315	VS950	CM5T-1A150-AA	VS950	D0105	MRXFE3MAF4
Ford	Explorer(433 Mhz)	02-05	*7004	7020K	9096	1060K	4L2T1A150BA	NO	D0104	MRXTG224AM02
Ford	Explorer	06-10	7001-R	VS80	1048	NA	6F2Z-1A189A	NO	D0105	KR5SWY7635
Ford	Explorer	11-13	7001-R	VS80	9315	VS950	CM5T-1A150-AA	VS950	D0105	MRXFE3MAF4
Ford	Explorer Sport Trac	07-10	7001-R	VS80	1048	NA	6F2Z-1A189A	NO	D0105	KR5SWY7635
Ford	F 150	07-08	7001-R	VS80	1048	NA	6F2Z-1A189A	NO	D0105	KR5SWY7635
Ford	F 150	09-13	7001-R	VS80	9315	VS950	CM5T-1A150-AA	VS950	D0105	MRXFE3MAF4
Ford	Fiesta	11-13	7001-R	VS80	9315	VS950	CM5T-1A150-AA	VS950	D0105	MRXFE3MAF4
Ford	500	08-09	7001-R	VS80	1048	NA	6F2Z-1A189A	NO	D0105	KR5SWY7635
Ford	Flex	09-10	7001-R	VS80	1048	NA	7L1Z-1A189A	NO	D0105	KR5SWY7635
Ford	Flex	11-13	7001-R	VS80	9315	VS950	CM5T-1A150-AA	VS950	D0105	MRXFE3MAF4
Ford	Focus	07-09	7001-R	VS80	1048	NA	6F2Z-1A189A/ 7L1Z-1A189A	NO	D0105	KR5SWY7635
Ford	Focus	10-13	7001-R	VS80	9315	VS950	CM5T-1A150-AA	VS950	D0105	MRXFE3MAF4
Ford	Freestar(315 Mhz)	04-05	7001	7020K	9135	1060K	5L1ZA150AB	NO	D0104	MRXTG224AM01
Ford	Freestar	06-07	7001-R	VS80	1048	NA	6F2Z-1A189A	NO	D0105	KR5SWY7635
Ford	Fusion	07-09	7001-R	VS80	1048	NA	6F2Z-1A189A	NO	D0105	KR5SWY7635
Ford	Fusion	10-13	7001-R	VS80	9315	VS950	CM5T-1A150-AA	VS950	D0105	MRXFE3MAF4
Ford	Mustang	07-09	7001-R	VS80	1048	NA	6F2Z-1A189A	NO	D0105	KR5SWY7635
Ford	Mustang	10-13	7001-R	VS80	9315	VS950	CM5T-1A150-AA	VS950	D0105	MRXFE3MAF4
Ford	Ranger	07-11	7001-R	VS80	1048	NA	6F2Z-1A189A	NO	D0105	KR5SWY7635
Ford	Ranger	12	7001-R	VS80	9315	VS950	CM5T-1A150-AA	VS950	D0105	MRXFE3MAF4
Ford	Shelby GT(>April 2012)	13	7001	VS80	9315	VS925C	DR3Z-1A189A	VS925C		UNKNOWN
Ford	Super Duty (250/350/450) Pre-June 2009	07-10			1048-HP	NA	8C2Z-1A189A	NO	D0101	KOBFTD06A
Ford	Super Duty (250/350/450) Post-June 2009	10-13			9315	VS950	CM5T-1A150-AA	VS950	D0101	MRXFE3MAF4
Ford	Taurus(Pre-May 2010)	08-10	7001-R	VS80	1048	NA	7L1Z-1A189A	NO	D0105	KR5SWY7635
Ford	Taurus(Post-May 2010)	11-13	7001-R	VS80	9315	VS950	CM5T-1A150-AA	VS950	D0105	MRXFE3MAF4

DILL TPMS APPLICATIONS CHART ©

OE	Model	Model Year	Multi-App Sensor	Multi-App Kit	Dill Sensor	Dill Kit	OE Sensor Part #	Valve Stem Replacement	Relearn	FCC ID #
Ford	Taurus X	08-09	7001-R	VS80	1048	NA	7L1Z-1A189A	NO	D0105	KR5SWY7635
Ford	Transit	10-13	7001-R	VS80	9315	VS950	CM5T-1A150-AA	VS950	D0105	MRXFE3MAF4
*Redi-Sensor relearn must be performed with scan tool and not magnet.										
GMC	Acadia	07-08	7001	7020K	9158	1050K	15921013	NO	D0305	MRXGMX272RS
GMC	Acadia	09-13	7001-R	VS80	9153	VS950	20923680	VS950	D0319	MRXG53MA4S
GMC	Canyon	07-12			9131	1110K	15122618	NO	D0321	MRXGMT102PWM
GMC	Envoy	05-07	7001	7020K	9116	1070K	25774006	NO	D0321	MRXGMT51MAN
GMC	Envoy	07-09	7001-R	VS80	9153	VS950	25920615	VS950	D0321	MRXG53MA4S
GMC	Savana	08-09	7001	7020K	9158	1050K	15921013	NO	D0319	MRXGMX272RS
GMC	Savana(1500)	10-13	7001-R	VS80	9153	VS950	20923680	VS950	D0319	MRXG53MA4S
GMC	Savana(2500/3500)	10-13			9153	VS950	20923680	VS950	D0319	MRXG53MA4S
GMC	Sierra	04			9115	1070K	15136883	NO	D0321	MRXGMT102PWM
GMC	Sierra	05-06			9107	1070K	15114379	NO	D0321	MRXGMG2R3PM
GMC	Sierra	07	7001	7020K	NA	2020K	15825475	NO	D0321	GQ428T
GMC	Sierra	07	7001	7020K	9158	1070K	TRW Sensor Replacement	NO	D0321	MRXGMX272RS
GMC	Sierra(1500)	07-13	7001-R	VS80	9153	VS950	20923680	VS950	D0321	MRXG53MA4S
GMC	Sierra(2500/3500)	07-13			9153	VS950	20923680	VS950	D0321	MRXG53MA4S
GMC	Terrain	10-13	7001-R	VS80	9153	VS950	20923680	VS950	D0305	MRXG53MA4S
GMC	Yukon	04			9115	1070K	15136883	NO	D0321	MRXGMT102PWM
GMC	Yukon	05-06			9107	1070K	15114379	NO	D0321	MRXGMG2R3PM
GMC	Yukon	07	7001	7020K	NA	2020K	15825475	NO	D0321	GQ428T
GMC	Yukon	07	7001	7020K	9158	1070K	TRW Sensor Replacement	NO	D0321	MRXGMX272RS
GMC	Yukon(1500)	07-13	7001-R	VS80	9153	VS950	20923680	VS950	D0305	MRXG53MA4S
GMC	Yukon(2500)	07-13			9153	VS950	20923680	VS950	D0305	MRXG53MA4S
Honda	Accord	08-12	7002	7020K	1208	1100K	42753-SWA-315/316	NO	A0201	PAXPMV107M
Honda	Civic	08-11	7002	7020K	1212	2045K	42753-TR3-A81	NO	A0201	GQ4-36T
Honda	Civic	12-13	7002	7020K	1212	2045K	42753-TR3-A81	NO	A0201	GQ4-36T
Honda	CR-V	07-11	7002	7020K	1208	1100K	42753-SWA-315/316	NO	A0201	PAXPMV107M
Honda	CR-V	12-13	7002	7020K	5511	7020K	42753-TP6-A82	VS70	A0201	KR5S180052015B
Honda	CR-Z	11-12	7002	7020K	1212	2045K	42753-TR3-A81	NO	A0201	GQ4-36T
Honda	Crosstour	10-13	7002	7020K	5511	7020K	42753-TP6-A82	VS70	A0201	KR5S180052015B
Honda	Element	06-07	7002	7020K	1058	2000K	06421-SCV-A01	1096	A0201	T7B-2T
Honda	Element	08	7002	7020K	1058	2045K or 2000K	42753-SHJ-A82	NO or 1096	A0201	GQ4-34T OR T7B-2T
Honda	Element	09-11	7002	7020K	1212	2045K	42753-TR3-A81	NO	A0201	GQ4-36T
Honda	Fit	08	7002	7020K	1208	1100K	42753-SWA-315/316	NO	A0201	PAXPMV107M
Honda	Fit	09-13	7002	7020K	1212	2045K	42753-TR3-A81	NO	A0201	GQ4-36T
Honda	Insight	10-13	7002	7020K	1212	2045K	42753-TR3-A81	NO	A0201	GQ4-36T
Honda	Odyssey EX, EX-L, LX	06-07	7002	7020K	1058	2000K	06421-SCV-A00		A0201	T7B-2T
Honda	Odyssey EX, EX-L, LX	08-10	7002	7020K	1058	2045K or 2000K	42753-SHJ-A82	NO or 1096	A0201	GQ4-34T OR T7B-2T
Honda	Odyssey EX, EX-L, LX	11-13	7002	7020K	1212	2045K	42753-TR3-A81	NO	A0201	GQ4-36T
Honda	Odyssey Touring	05-07			1057	2000K	06421-S3V-A04	1096	A0201	T7B-2T
Honda	Odyssey Touring	08-10			1057	2045K or 2000K	42753-SHJ-A53	NO or 1096	A0201	GQ4-35T OR T7B-2T
Honda	Odyssey Touring	11-12	7002	7020K	1212	2045K	42753-TR3-A81	NO	A0201	GQ4-36T
Honda	Pilot(Steel)-2.25"	05			1059	2000K	06421-S9V-A02	1097	A0201	T7B-2T
Honda	Pilot-1.75"	05-08			1057	2000K	06421-S3V-A04	1096	A0201	T7B-2T
Honda	Pilot	09-13			1209	1100K	42753-STK-A04	NO	A0201	PAXPMV107G
Honda	Pilot(Steel)	09-12			1219	1100K	42753-SZA-A12	NO	A0201	PAXPMV108G
Honda	Ridgeline(RT)-2.25"	06-08			1059	2000K	06421-S9V-A02	1097	A0201	T7B-2T
Honda	Ridgeline-1.75"	06-08			1057	2000K	06421-S3V-A04	1096	A0201	T7B-2T
Honda	Ridgeline(Alloy)	09-13			1057	2045K or 2000K	42753-SHJ-A53	NO or 1096	A0201	GQ4-35T OR T7B-2T
Honda	S2000	08-09	7002	7020K	1208	1100K	42753-S2A-315	NO	A0201	PAXPMV107M
Hummer	H2	08-09	7001-R	VS80	9153	VS950	25920615	VS950	D0305	MRXG53MA4S
Hummer	H3	06-10			9131	1110K	15122618	NO	D0321	MRXGMT102PWM
Hummer	H3T	09-10			9131	1110K	15122618	NO	D0321	MRXGMT102PWM
Hyundai	Accent(Lo-Line)	08-11	7002 or 1206-A	7020K or 1100K	1029**	2040K	52933-2F000	NO	A0301	T7B-1T
Hyundai	Accent	12-13	7001	7020K	5507	7020K	52933-2M000	VS70	A0301	KR5S180052015B
Hyundai	Azera	07-12	7002	7020K	1068	2000K	52933-2G200	1096	A0301	KOBHT05TPM
Hyundai	Azera	13			9505	VS950	52933-2V000	VS950	A0301	MRXFS5MAF4
Hyundai	Elantra	07-10	7002	7020K	1068	2000K	52933-2G200	1096	A0301	KOBHT05TPM
Hyundai	Elantra(Post Nov)	11-13	7002	7020K	NEW	VS965	52933-3X200	VS965	A0301	GQ4-44T

DILL TPMS APPLICATIONS CHART ©

OE	Model	Model Year	Multi-App Sensor	Multi-App Kit	Dill Sensor	Dill Kit	OE Sensor Part #	Valve Stem Replacement	Relearn	FCC ID #
Hyundai	Elantra(Touring)	09-12	7001	7020K	5507	1050K or 7020K	52933-A5000	VS70	A0301	KR5S180052015B
Hyundai	Elantra GT	13	7001	7020K	5507	7020K	52933-A5000	VS70	A0301	KR5S180052015B
Hyundai	Entourage	07-09			1028	2000K	52933-4D200	1096	A0301	KOBHT05ATPM
Hyundai	Equus(Hi-Line)	11-13			1029	2040K	52933-2F000	NO	A0301	T7B-1T
Hyundai	Genesis(Hi-line)	09-13			1029	2040K	52933-2F000	NO	A0301	T7B-1T
Hyundai	Genesis Coupe	10-13	7001	7020K	5507	7020K	52933-A5000	VS70	A0301	KR5S180052015B
Hyundai	Santa Fe (Thru July 2007)	07-08			1028	2000K	52933-4D200	1096	A0301	KOBHT05ATPM
Hyundai	Santa Fe (Thru Sept 2009)	08-10	7002	7020K	1068	2000K	52933-2G200	1096	A0301	KOBHT05TPM
Hyundai	Santa Fe(Oct 2009)	10-12	7002	7020K	NEW	VS1010	52933-0W100	VS1010	A0301	UNKNOWN
Hyundai	Santa Fe(Oct 2009)	10-12	7002	7020K	1068	2000K	Sensor Replacement Only	1096	A0301	KOBHT05TPM
Hyundai	Santa Fe--Turbo	13	7001	7020K	5507	7020K	52933-A5000	VS70	A0301	KR5S180052015B
Hyundai	Sonata	07-08			1058	2000K	52933-3E000	1096	A0301	T7B-2T
Hyundai	Sonata(Lo-Line) --Late '08 Builds	08-10	7002 or 1206-A	7020K or 1100K	1029**	2040K	52933-2F000	NO	A0301	T7B-1T
Hyundai	Sonata	11-13	7001	7020K	5507	7020K	52933-2M000	VS70	A0301	KR5S180052015B
Hyundai	Tiburon	07-08	7002	7020K	1058	2000K	52933-3E000	1096	A0301	T7B-2T
Hyundai	Tucson	07-10	7002	7020K	1058	2000K	52933-3E000	1096	A0301	T7B-2T
Hyundai	Tucson	10-13	7002 or 1206-A	7020K or 1100K	1029	2040K	52933-2F000	NO	A0301	T7B-1T
Hyundai	Veloster	12-13			9505	VS950	52933-2V000	VS950	A0301	MRXFS5MAF4
Hyundai	Veracruz	07-08			1028	2000K	52933-4D200	1096	A0301	KOBHT05ATPM
Hyundai	Veracruz	08-12	7002	7020K	1068	2000K	52933-2G200	1096	A0301	KOBHT05TPM
** Note: Use "TRW LoLine Fxd Dly" function on BarTec 400 or 400P to program the sensors.										
Infiniti	EX35	08-10	**7001	7020K	9204	1100K	40700-JK00C	NO	A0801	KOBHT05ATPM
Infiniti	EX35	11-12			1216	1100K	40700-1LA0C	NO	A0801	PAXPMV107S
Infiniti	EX37	13			1216	1100K	40700-1LA0C	NO	A0801	PAXPMV107S
Infiniti	FX35(Pre-June)	03-08	**7001	7020K	9064	1080K	40700-CD001	NO	A0801	MRXSUZ3MA4
Infiniti	FX35(Post-June)	09-10	**7001	7020K	9204	1100K	40700-JK00C	NO	A0801	KOBHT05ATPM
Infiniti	FX35	11-12			1216	1100K	40700-1LA0C	NO	A0801	PAXPMV107S
Infiniti	FX37	13			1216	1100K	40700-1LA0C	NO	A0801	PAXPMV107S
Infiniti	FX45(Pre-June)	03-07	**7001	7020K	9064	1080K	40700-CD001	NO	A0801	MRXSUZ3MA4
Infiniti	FX45(Post-June)	07-08	**7001	7020K	9204	2030K	40700-JK00C	NO	A0801	KOBHT05ATPM
Infiniti	FX50	09-10	**7001	7020K	9204	1100K	40700-JK00C	NO	A0801	KOBHT05ATPM
Infiniti	FX50	11-13			1216	1100K	40700-1LA0C	NO	A0801	PAXPMV107S
Infiniti	G25	11-12			1216	1100K	40700-1LA0C	NO	A0801	PAXPMV107S
Infiniti	G35	03-06	**7001	7020K	9064	1080K	40700-CD001	NO	A0801	MRXSUZ3MA4
Infiniti	G35(Sedan)	07-08	**7001	7020K	9204	1100K	40700-JK00C	NO	A0801	KOBHT05ATPM
Infiniti	G35(Coupe)	08	**7001	7020K	9204	2030K	40700-1AA0C	NO	A0801	KOBHT05ATPM
Infiniti	G37	08-10	**7001	7020K	9204	1100K	40700-JK00C	NO	A0801	KOBHT05ATPM
Infiniti	G37	11-13			1216	1100K	40700-1LA0C	NO	A0801	PAXPMV107S
Infiniti	JX35--433 Mhz	13		7020K	5556	7000K	40700-3JA0A	VS70	A0801	KR5S18052020A
Infiniti	M35	06-07	**7001	7020K	9064	1080K	40700-CD001	NO	A0801	MRXSUZ3MA4
Infiniti	M35	08-10	**7001	7020K	9204	2030K	40700-1AA0C	NO	A0801	KOBHT05ATPM
Infiniti	M37	11-13			1216	1100K	40700-1LA0C	NO	A0801	PAXPMV107S
Infiniti	M45	03-07	**7001	7020K	9064	1080K	40700-CD001	NO	A0801	MRXSUZ3MA4
Infiniti	M45	08-10	**7001	7020K	9204	2030K	40700-1AA0C	NO	A0801	KOBHT05ATPM
Infiniti	M56	11-12			1216	1100K	40700-1LA0C	NO	A0801	PAXPMV107S
Infiniti	Q45(pre-July)	03-06	**7001	7020K	9064	1080K	40700-CD001	NO	A0801	MRXSUZ3MA4
Infiniti	Q45(Post-Aug)	06	**7001	7020K	9204	2030K	40700-JA01B	NO	A0801	KOBHT05ATPM
Infiniti	QX4	03	**7001	7020K	9064	1080K	40700-CD001	NO	A0801	MRXSUZ3MA4
Infiniti	QX56(Steel)	05-06	**7001	7020K	9069	1130K	40700-CK002	NO	A0801	MRXNG33MA4S
Infiniti	QX56(Alloy)	04-07	**7001	7020K	9161	1080K	40700-CK001	NO	A0801	MRXNG33MA4S
Infiniti	QX56(Post-April)	07-10	**7001	7020K	9204	2030K	40700-JK00C	NO	A0801	KOBHT05ATPM
Infiniti	QX56	11-13			1216	1100K	40700-1LA0C	NO	A0801	PAXPMV107S
**Utilize the ATEQ VT-55 or Bartec OBD-enabled tools(Rev 45) for the vehicle relearn.										
ITEC	Trucks(433 Mhz)	---			9010	VS9013 or VS9980	---	VS9013 or VS9980	---	OYGTSSRE4NB
Isuzu	Ascender	06-08	7001	7020K	9116	1070K	25774006	NO	A0401	MRXGMT51MAN
Isuzu	I-290	07-08			9131	1110K	15122618	NO	A0401	MRXGMT102PWM
Isuzu	I-370	07-08			9131	1110K	15122618	NO	A0401	MRXGMT102PWM

DILL TPMS APPLICATIONS CHART ©

OE	Model	Model Year	Multi-App Sensor	Multi-App Kit	Dill Sensor	Dill Kit	OE Sensor Part #	Valve Stem Replacement	Relearn	FCC ID #
Isuzu	Rodeo(433 Mhz)	04	7004	7020K	9028	1080K	52088990AC	NO	A0401	MRXTG224AM02
Jaguar	S(315 Mhz)	05-08		7020K	1055	1050K	C2Z15017	NO	E0401	KR5S120123
Jaguar	S(433 Mhz)	05-08		7020K	1046	1050K	C2Z15016	NO	E0401	NONE
Jaguar	XF(315 Mhz)	09-10		7020K	1055	1050K	C2Z15017	NO	E0401	KR5S120123
Jaguar	XF(315 Mhz)	10-13		7020K	1055	7020K	C2Z15017	VS70	E0401	KR5S120123
Jaguar	XF(433 Mhz)	09-10		7020K	1046	1050K	C2Z15016	NO	E0401	NONE
Jaguar	XF(433 Mhz)	10-12		7020K	1046	7020K	C2Z15016	NO	E0401	NONE
Jaguar	XJ(315 Mhz)	04-10		7020K	1055	1050K	C2Z15017	NO	E0401	KR5S120123
Jaguar	XJ(315 Mhz)	10-11		7020K	1055	7020K	C2Z15017	VS70	E0401	KR5S120123
Jaguar	XJ(315 Mhz)	12-13		7020K	1045	1050K	C2D21601	NO	E0401	KR5S180052015B
Jaguar	XJ(433 Mhz)	04-10		7020K	1046	1050K	C2Z15016	NO	E0401	NONE
Jaguar	XJ(433 Mhz)	10-12		7020K	1046	7020K	C2Z15016	NO	E0401	NONE
Jaguar	XK(315 Mhz)	05-10		7020K	1055	7020K	C2Z15017	NO	E0401	KR5S120123
Jaguar	XK(315 Mhz)	10-13		7020K	1055	7020K	C2D221601	VS70	E0401	KR5S120123
Jaguar	XK(433 Mhz)	07-10		7020K	1046	1050K	C2Z15016	NO	E0401	NONE
Jaguar	XK(433 Mhz)	10-12		7020K	1046	7020K	C2Z15016	NO	E0401	NONE
Jeep	Commander	06	7001	7020K	1051	1050K	56029465AB	NO	D0203	KR5S180052015B
Jeep	Commander	07	7001	7020K	1051	1050K or 2030K	56029465AB	9066K	D0203	KR5S180052015B OR MRXDCA315TX1
Jeep	Commander (433 Mhz)	08-10	7004	7020K	1043 **	1050K or 2030K	56029359AB	9066K	D0203	KR5S180052020 OR MRXDCA433TX1
Jeep	Compass	07-09	7001	7020K	1051	1050K	68001696AB	NO	D0203	KR5S180052015B
Jeep	Compass	10-13	7001	7020K	1051	7000K or 2030K	68078861AA	9066K	D0203	KR5S180052015B OR MRXDCA315TX1
Jeep	Grand Cherokee(433 Mhz)	02-04	7004	7020K	9028	1080K	52088990AC	NO	D0202	MRXTG224AM02
Jeep	Grand Cherokee	05-06	7001	7020K	1051	1050K	68001696AB	NO	D0203	KR5S180052015B
Jeep	Grand Cherokee	07	7001	7020K	1051	1050K or 2030K	56029465AB	9066K	D0203	KR5S180052015B OR MRXDCA315TX1
Jeep	Grand Cherokee (433 Mhz)	08-10	7004	7020K	1043 **	1050K or 2030K	56029359AB	9066K	D0203	KR5S180052020 OR MRXDCA433TX1
Jeep	Grand Cherokee(433 Mhz)	11-13			9398	VS950	56029398AA	VS950	D0203	MRXC4W4MA4
Jeep	Grand Cherokee-SRT (433 Mhz)	12			9214	2030K	56029400AE	9066K	D0203	MRXMERCXTX1
Jeep	Liberty(433 Mhz)	04	7004	7020K	9028	1080K	52088990AC	NO	D0203	MRXTG224AM02
Jeep	Liberty	05-08	7001	7020K	1051	1050K	56029465AB	NO	D0203	KR5S180052015B
Jeep	Liberty	07-09	7001	7020K	1051 **	1050K or 2030K	56029465AB	9066K	D0203	KR5S180052015B OR MRXDCA315TX1
Jeep	Liberty(433 Mhz)--Non Sport	09	7004	7020K	1043 **	1050K or 2030K	56029359AB	9066K	D0203	KR5S180052020 OR MRXDCA433TX1
Jeep	Liberty	10	7001	7020K	1051 **	1050K or 2030K	56029465AB	9066K	D0203	KR5S180052015B OR MRXDCA315TX1
Jeep	Liberty	10-11	7001-R	VS80	9308	VS950	56029479AA	VS950	D0203	MRXC4N3MF9
Jeep	Liberty(433 Mhz)	12			9481	VS950	56029481AB	VS950	D0203	MRXC4N4MF9
Jeep	Patriot	07-10	7001	7020K	1051	1050K	68001696AB	NO	D0203	KR5S180052015B
Jeep	Patriot	10-13	7001	7020K	1051 **	1050K or 2030K	56029465AB	9066K	D0203	KR5S180052015B OR MRXDCA315TX1
Jeep	Wrangler(Alloy)	07-08	7001	7020K	1051 **	1050K or 2030K	56029465AB	9066K	D0203	KR5S180052015B OR MRXDCA315TX1
Jeep	Wrangler	09-10	7004	7020K	1043 **	1050K or 2030K	56029359AB	9066K	D0203	KR5S180052020 OR MRXDCA433TX1
Jeep	Wrangler	10-11	7001-R	VS80	9308	VS950	56029479AA	VS950	D0203	MRXC4N3MF9
Jeep	Wrangler(433 Mhz)	12-13			9398	VS950	56029398AA	VS950	D0203	MRXC4W4MA4
Jeep	Wrangler Export(433 Mhz)	11-12			9481	VS950	56029481AB	VS950	D0203	MRXC4N4MF9

****The 1050K is to be used on the Siemens sensors and the 2030K is to be used on the Schrader sensors.**

DILL TPMS APPLICATIONS CHART ©

OE	Model	Model Year	Multi-App Sensor	Multi-App Kit	Dill Sensor	Dill Kit	OE Sensor Part #	Valve Stem Replacement	Relearn	FCC ID #
KIA	Amanti	07-09	7002	7020K	1058	2000K	52933-3E000	1096	A0201	T7B-2T
KIA	Borrego(Lo-Line)	09	7002 or 1206-A	7020K or 1100K	1029**	2040K	52933-2F000	NO	A0201	T7B-1T
KIA	Forte	10-13	7001	7020K	5507	7020K	52933-2M000	VS70	A0201	KR5S180052015B
KIA	Magentis	08-10	7002	7020K	1068	2000K	52933-2G200	1096	A0201	KOBHT05TPM
KIA	Mohave	09	7002 or 1206-A	7020K or 1100K	1029**	2040K	52933-2F000	NO	A0201	T7B-1T
KIA	Optima(Lo-Line)	06-10	7002	7020K	1068	2000K	52933-2G200	1096	A0201	KOBHT05TPM
KIA	Optima	11-13	7001	7020K	5507	7020K	52933-2M000	VS70	A0201	KR5S180052015B
KIA	Rio-5(Lo-Line)	08-11	7002 or 1206-A	7020K or 1100K	1029**	2040K	52933-2F000	NO	A0201	T7B-1T
KIA	Rio 5(Lo-Line)	12-13	7002	7020K	NEW	VS965	52933-3X200	VS965	A0201	GQ4-44T
KIA	Rondo(Lo-Line)	07-09	7002	7020K	1068	2000K	52933-2G200	1096	A0201	KOBHT05TPM
KIA	Sedona(Hi-Line)	06-08			1028	2000K	52933-4D200	1096	A0201	KOBHT05ATPM
KIA	Sedona(Lo-Line)	09-12	7002	7020K	1068	2000K	52933-2G200	1096	A0201	KOBHT05TPM
KIA	Sorento	05-09	7002	7020K	1058	2000K	52933-3E000	1096	A0201	T7B-2T
KIA	Sorento	11-13	7001	7020K	5507	7020K	52933-2M000	VS70	A0201	KR5S180052015B
KIA	Soul	10-13	7001	7020K	5507	7020K	52933-2M000	VS70	A0201	KR5S180052015B
KIA	Spectra-5(Lo-Line)	07-09	7002 or 1206-A	7020K or 1100K	1029**	2040K	52933-2F000	NO	A0201	T7B-1T
KIA	Sportage	06-08	7002	7020K	1058	2000K	52933-3E000	1096	A0201	T7B-2T
KIA	Sportage(Lo-Line)	09-13	7002 or 1206-A	7020K or 1100K	1029**	2040K	52933-2F000	NO	A0201	T7B-1T
KIA	Tuscany	07-08	7002	7020K	1058	2000K	Enhanced/Basic	1096	A0201	T7B-2T
** Note: Use "TRW LoLine Fxd Dly" function on BarTec 400 or 400P to program the sensors.										
Land Rover	LR2(315 Mhz)	08-10			1045	1050K	LR032833	NO	E0401	KR5S180052015B
Land Rover	LR2(315 Mhz)	11-13			1045	7020K	LR032833	VS70	E0401	KR5S180052015B
Land Rover	LR2(433 Mhz)	10-11			1046	7020K	LR018861	VS70	E0401	NONE
Land Rover	LR3(433 Mhz)	02-05			9003	1090K	YDB 0000 60	1092-1095	E0401	OYG TSSRE4PB
Land Rover	LR3(315 Mhz)	06-09			1055	1050K	LR018860	NO	E0401	KR5S120123
Land Rover	LR3(433 Mhz)	06-09			1046	1050K	LR018861	NO	E0401	NONE
Land Rover	LR4(315 Mhz)	10-13			1045	7020K	LR032833	VS70	E0401	KR5S180052015B
Land Rover	LR4(433 Mhz)	10-11			1046	7020K	LR018861	VS70	E0401	NONE
Land Rover	Evoque(315 Mhz)	11-12			1045	7020K	LR032833	NO	E0401	KR5S180052015B
Land Rover	Range Rover (315 Mhz)	06-09			1055	1050K	LR018860	NO	E0401	KR5S120123
Land Rover	Range Rover (315 Mhz)	10-12			1045	7020K	LR032833	VS70	E0401	KR5S180052015B
Land Rover	Range Rover (433 Mhz)	06-09			1046	1050K	LR018861	NO	E0401	NONE
Land Rover	Range Rover (433 Mhz)	10-11			1046	7020K	LR018861	VS70	E0401	NONE
Land Rover	Range Rover Sport(315 Mhz)	06-09			1055	1050K	LR021936	NO	E0401	KR5S120123
Land Rover	Range Rover Sport(315 Mhz)	10-12			1045	7020K	LR032833	VS70	E0401	KR5S180052015B
Land Rover	Range Rover Sport(433 Mhz)	06-09			1046	1050K	LR018861	NO	E0401	NONE
Land Rover	Range Rover Sport(433 Mhz)	10-11			1046	7020K	LR018861	VS70	E0401	NONE
Lexus	CT	11-13	7002 or 1204-A	7020K	1204	1100K	42607-33021	NO	A1101	PAXPMV107J
Lexus	ES	07-12	7002 or 1204-A	7020K	1204	1100K	42607-33021	NO	A1101	PAXPMV107J
Lexus	ES	13			1218	1100K	42607-30060	NO	A1101	PAXPMVC010
Lexus	GS	05-11	7002 or 1204-A	7020K	1204	1100K	42607-33021	NO	A1101	PAXPMV107J

DILL TPMS APPLICATIONS CHART ©

OE	Model	Model Year	Multi-App Sensor	Multi-App Kit	Dill Sensor	Dill Kit	OE Sensor Part #	Valve Stem Replacement	Relearn	FCC ID #
Lexus	GS	13			1218	1100K	42607-30060	NO	A1101	PAXPMVC010
Lexus	GX470	04-06	7002 or 1204-A	7020K	1204	1110K	42607-35010	NO	A1101	PAXPMV107J
Lexus	GX	06-13	7002 or 1204-A	7020K	1204	1100K	42607-33021	NO	A1101	PAXPMV107J
Lexus	HS Series	10-12	7002 or 1204-A	7020K	1204	1100K	42607-75010	NO	A1101	PAXPMV107J
Lexus	IS Series	06-13	7002 or 1204-A	7020K	1204	1100K	42607-33021	NO	A1101	PAXPMV107J
Lexus	LFA	13	7002 or 1204-A	7020K	1204	1100K	42607-33021	NO	A1101	PAXPMV107J
Lexus	LS	07-13	7002 or 1204-A	7020K	1204	1100K	42607-33021	NO	A1101	PAXPMV107J
Lexus	LX	05-13	7002 or 1204-A	7020K	1204	1100K	42607-33021	NO	A1201	PAXPMV107J
Lexus	RX	06-13	7002 or 1204-A	7020K	1204	1100K	42607-33021	NO	A1201	PAXPMV107J
Lexus	SC430	02-06			1217-WH 1217-BL 1217-RD 1217-YL	1120K	42607-24010 42607-24020 42607-24030 42607-24040	NO		PAXPMV1001
Lexus	SC	07-10	7002 or 1204-A	7020K	1204	1100K	42607-33021	NO	A1101	PAXPMV107J
Lincoln	Aviator(433 Mhz)	03-05	*7004	7020K	9096	1060K	4L2T1A150-BA	NO	D0104	MRXTG224AM02
Lincoln	Mark LT	07-08	7001	7020K	1048	NA	6F2Z-1A189A	NO	D0105	KR5SWY7635
Lincoln	MKS	09-10	7001	7020K	1048	NA	7L1Z-1A189A	NO	D0105	KR5SWY7635
Lincoln	MKS	11-13	7001-R	VS80	9315	VS950	9L3Z-1A189A	VS950	D0105	MRXFE3MAF4
Lincoln	MKT	10	7001	7020K	1048	NA	7L1Z-1A189A	NO	D0105	KR5SWY7635
Lincoln	MKT	11-13	7001-R	VS80	9315	VS950	9L3Z-1A189A	VS950	D0105	MRXFE3MAF4
Lincoln	MKX	07-10	7001	7020K	1048	NA	7L1Z-1A189A	NO	D0105	KR5SWY7635
Lincoln	MKX	11-13	7001-R	VS80	9315	VS950	9L3Z-1A189A	VS950	D0105	MRXFE3MAF4
Lincoln	MKZ	07-09	7001	7020K	1048	NA	6F2Z-1A189A	NO	D0105	KR5SWY7635
Lincoln	MKZ	10-13	7001-R	VS80	9315	VS950	9L3Z-1A189A	VS950	D0105	MRXFE3MAF4
Lincoln	Navigator(433 Mhz)	03-04	*7004	7020K	9096	1060K	4L2T1A150-BA	NO	D0104	MRXTG224AM02
Lincoln	Navigator(315 Mhz)	05-06	7001	7020K	9135	1060K	5L1Z1A150-AB	NO	D0104	MRXTG224AM01
Lincoln	Navigator	07-10	7001	7020K	1048	NA	7L1Z-1A189A	NO	D0105	KR5SWY7635
Lincoln	Navigator	11-13	7001-R	VS80	9315	VS950	9L3Z-1A189A	VS950	D0105	MRXFE3MAF4
Lincoln	Town Car	06-11	7001	7020K	1048	NA	6F2Z-1A189A	NO	D0105	KR5SWY7635
*Redi-Sensor relearn must be performed with scan tool and not magnet.										
Maserati	Quattroporte-- Thru December	04-09			9001	1090K	22 45 49	1092		OYGTSSRE4B
Maserati	Quattroporte-- Post January	10-12			9011	1090K	24 88 87	1092		OYG TSSRE4TC
Maserati	Coupe-- Thru June	09			9001	1090K	22 45 49	1092		OYGTSSRE4B
Maserati	Coupe-- Post July	09-12			9011	1090K	24 88 87	1092		OYG TSSRE4TC
Mazda	B Series	07-09	7001	7020K	1048	NA	6F2Z-1A189A	NO	A0602	KR5SWY7635
Mazda	2	11-13	7001	7020K	1056	7020K	BBM2-37-140B	VS70	A0601	KR5S180052015B
Mazda	3	04	7001	7020K	1056	NA	FE01-37-140A/ GN3A-37-140B	NO	A0601	KR5S180052015B
Mazda	3	05-09	7001	7020K	1056	1050K	BBM2-37-140B	NO	A0601	KR5S180052015B
Mazda	3	10-13	7001	7020K	1056	7020K	BBM2-37-140B	VS70	A0601	KR5S180052015B
Mazda	5	06-09	7001	7020K	1056	1050K	BBM2-37-140B	NO	A0601	KR5S180052015B
Mazda	5	10-12	7001	7020K	1056	7020K	BBM2-37-140B	VS70	A0601	KR5S180052015B

DILL TPMS APPLICATIONS CHART ©

OE	Model	Model Year	Multi-App Sensor	Multi-App Kit	Dill Sensor	Dill Kit	OE Sensor Part #	Valve Stem Replacement	Relearn	FCC ID #
Mazda	6	05-10	7001	7020K	1056	1050K	BBM2-37-140B	NO	A0601	KR5S180052015B
Mazda	6	10-13	7001	7020K	1056	7020K	BBM2-37-140B	VS70	A0601	KR5S180052015B
Mazda	CX-7	07-09	7001	7020K	1056	1050K	BBM2-37-140B	NO	A0601	KR5S180052015B
Mazda	CX-7	10-12	7001	7020K	1056	7020K	BBM2-37-140B	VS70	A0601	KR5S180052015B
Mazda	CX-9	07-09	7001	7020K	1056	1050K	BBM2-37-140B	NO	A0601	KR5S180052015B
Mazda	CX-9	10-12	7001	7020K	1056	7020K	BBM2-37-140B	VS70	A0601	KR5S180052015B
Mazda	MX-5 Miata	06-09	7001	7020K	1056	1050K	BBM2-37-140B	NO	A0601	KR5S180052015B
Mazda	MX-5 Miata	10-13	7001	7020K	1056	7020K	BBM2-37-140B	VS70	A0601	KR5S180052015B
Mazda	RX-8	04	7001	7020K	1056	NA	FE01-37-140A/ GN3A-37-140B	NO	A0601	KR5S180052015B
Mazda	RX-8	05-09	7001	7020K	1056	1050K	BBM2-37-140B	NO	A0601	KR5S180052015B
Mazda	RX-8	10-11	7001	7020K	1056	7020K	BBM2-37-140B	VS70	A0601	KR5S180052015B
Mazda	Speed 3	10-12	7001	7020K	1056	7020K	BBM2-37-140B	VS70	A0601	KR5S180052015B
Mazda	Speed 6	07-08	7001	7020K	1056	1050K	BBM2-37-140B	NO	A0601	KR5S180052015B
Mazda	Tribute	06-08	7001	7020K	1048	NA	6F2Z-1A189A	NO	A0602	KR5SWY7635
Mazda	Tribute	09-11	7001-R	VS80	9315	VS950	9L3Z-1A189A	VS950	A0602	MRXFE3MAF4
M-Benz	C Class(433 Mhz)	07-13			9214	2030K	000 905 4100	9066K	E0703	MRXMERCCTX1
M-Benz	CL Class(315 Mhz)	00-06			9004	1090K	000 822 34 06	1094	E0703	OYGTSSRE3B
M-Benz	CL Class(433 Mhz)	00-06			9001	1090K	000 822 3306	1094	E0703	OYGTSSRE4B
M-Benz	CL Class(433 Mhz)	09-13			9214	2030K	000 905 4100	9066K	E0703	MRXMERCCTX1
M-Benz	CL 63-65-550-600 (315 Mhz)	07-11			1054	1040K	002 540 7917	1040K	E0703	KR5S122228001
M-Benz	CL 63-65-550-600 (433 Mhz)	07-11			1049	1040K	002 540 8017	1040K	E0703	KR5S122228002
M-Benz	CLKClass(315 Mhz)	06-07			9004	1090K	000 822 34 06	1094	E0701	OYGTSSRE3B
M-Benz	CLK Class(433 Mhz)	08-09			9214	2030K	000 905 4100	9066K	E0703	MRXMERCCTX1
M-Benz	CLS 55-63-500-550 (315 Mhz)	06-11			1054	1040K	002 540 7917	1040K	E0703	KR5S122228001
M-Benz	CLS 55-63-500-550 (433 Mhz)	06-09			1049	1040K	002 540 8017	1040K	E0703	KR5S122228002
M-Benz	CLS Class(433 Mhz)	08-13			9214	2030K	000 905 4100	9066K	E0703	MRXMERCCTX1
M-Benz	CLS Class(433 Mhz)	11			1049	1040K	002 540 8017	1040K	E0703	KR5S122228002
M-Benz	E Class(315 Mhz)	00-05			9004	1090K	000 822 34 06	1094	E0703	OYGTSSRE3B
M-Benz	E Class(433 Mhz)	00-05			9001	1090K	000 822 33 06	1094	E0703	OYGTSSRE4B
M-Benz	E Class(315 Mhz)	06-10			1054	1040K	002 540 7917	1040K	E0703	KR5S122228001
M-Benz	E Class(433 Mhz)	06-10			1049	1040K	002 540 8017	1040K	E0703	KR5S122228002
M-Benz	E Class(433 Mhz)	10-13			9214	2030K	000 905 4100	9066K	E0703	MRXMERCCTX1
M-Benz	G Class(433 Mhz)	07-13			9214	2030K	000 905 4100	9066K	E0703	MRXMERCCTX1
M-Benz	GL Class(315 Mhz)	07-09			1054	1040K	002 540 7917	1040K	E0703	KR5S122228001
M-Benz	GL Class(433 Mhz)	07-09			1049	1040K	002 540 8017	1040K	E0703	KR5S122228002
M-Benz	GL(433 Mhz)	10-13			9214	2030K	000 905 4100	9066K	E0703	MRXMERCCTX1
M-Benz	GLK(433 Mhz)	10-13			9214	2030K	000 905 4100	9066K	E0703	MRXMERCCTX1
M-Benz	ML Class(315 Mhz)	06-10			1054	1040K	002 540 7917	1040K	E0703	KR5S122228001
M-Benz	ML Class(433 Mhz)	06-10			1049	1040K	002 540 8017	1040K	E0703	KR5S122228002
M-Benz	ML Class(433 Mhz)	10-13			9214	2030K	000 905 4100	9066K	E0703	MRXMERCCTX1
M-Benz	R Class(315 Mhz)	06-09			1054	1040K	002 540 7917	1040K	E0703	KR5S122228001
M-Benz	R Class(433 Mhz)	06-09			1049	1040K	002 540 8017	1040K	E0703	KR5S122228002
M-Benz	R Class(433 Mhz)	10			9214	2030K	000 905 4100	9066K	E0703	MRXMERCCTX1
M-Benz	R Class(433 Mhz)	11			1049	1040K	002 540 8017	1040K	E0703	KR5S122228002
M-Benz	R Class(433 Mhz)	12			9214	2030K	000 905 4100	9066K	E0703	MRXMERCCTX1
M-Benz	S Class(315 Mhz)	00-06			9004	1090K	000 822 34 06	1094	E0703	OYGTSSRE3B
M-Benz	S Class(433 Mhz)	00-06			9001	1090K	000 822 33 06	1094	E0703	OYGTSSRE4B
M-Benz	S Class(315 Mhz)	07-11			1054	1040K	002 540 7917	1040K	E0703	KR5S122228001

DILL TPMS APPLICATIONS CHART ©

OE	Model	Model Year	Multi-App Sensor	Multi-App Kit	Dill Sensor	Dill Kit	OE Sensor Part #	Valve Stem Replacement	Relearn	FCC ID #
M-Benz	S Class(433 Mhz)	07-10			1049	1040K	002 540 8017	1040K	E0703	KR5S122228002
M-Benz	S(433 Mhz)	10-13			9214	2030K	000 905 4100	9066K	E0703	MRXMERCX1
M-Benz	SL Class(315 Mhz)	00-05			9004	1090K	000 822 34 06	1094	E0703	OYGTSSRE3B
M-Benz	SL Class(433 Mhz)	00-05			9001	1090K	000 822 33 06	1094	E0703	OYGTSSRE4B
M-Benz	SL Class(315 Mhz)	06-12			1054	1040K	002 540 7917	1040K	E0703	KR5S122228001
M-Benz	SL Class(433 Mhz)	06-09			1049	1040K	002 540 8017	1040K	E0703	KR5S122228002
M-Benz	SL Class(433 Mhz)	13			9214	2030K	000 905 4100	9066K	E0703	MRXMERCX1
M-Benz	SLK Class(433 Mhz)	08-13			9214	2030K	000 905 4100	9066K	E0703	MRXMERCX1
M-Benz	SLR Class(315 Mhz)	04-06			9004	1090K	000 822 34 06	1094	E0703	OYGTSSRE3B
M-Benz	SLR Class(433 Mhz)	00-06			9001	1090K	000 822 33 06	1094	E0703	OYGTSSRE4B
M-Benz	SLR Class(315 Mhz)	08-09			1054	1040K	002 540 7917	1040K	E0703	KR5S122228001
M-Benz	SLR Class(433 Mhz)	08-09			1049	1040K	002 540 8017	1040K	E0703	KR5S122228002
M-Benz	SLS(433 mhz)	11-13			9214	2030K	000 905 4100	9066K	E0703	MRXMERCX1
Mercury	Grand Marquis	07-10	7001	7020K	1048	NA	6F2Z-1A189A	NO	D0105	KR5SWY7635
Mercury	Mariner	06-08	7001	7020K	1048	NA	6F2Z-1A189A	NO	D0105	KR5SWY7635
Mercury	Mariner	09-11	7001-R	VS80	9315	VS950	9L3Z-1A189-A	VS950	D0105	MRXFE3MAF4
Mercury	Milan	08-09	7001	7020K	1048	NA	6F2Z-1A189A	NO	D0105	KR5SWY7635
Mercury	Milan	10-11	7001-R	VS80	9315	VS950	9L3Z-1A189-A	VS950	D0105	MRXFE3MAF4
Mercury	Montego	06-07	7001	7020K	1048	NA	6F2Z-1A189A	NO	D0105	KR5SWY7635
Mercury	Monterey(315 Mhz)	04-05	7001	7020K	9135	1060K	5L1Z1A150-AB	NO	D0104	MRXTG224AM01
Mercury	Monterey	06-07	7001	7020K	1048	NA	6F2Z-1A189A	NO	D0105	KR5SWY7635
Mercury	Mountaineer(433 Mhz)	02-05	*7004	7020K	9096	1060K	4L2T1A150-BA	NO	D0104	MRXTG224AM02
Mercury	Mountaineer	06-10	7001	7020K	1048	NA	6F2Z-1A189A	NO	D0105	KR5SWY7635
Mercury	Sable	08-09	7001	7020K	1048	NA	7L1Z-1A189A	NO	D0105	KR5SWY7635
*Redi-Sensor relearn must be performed with scan tool and not magnet.										
Mini	All(433 Mhz)	07-10			1027	1090K	36 23 6 781 847	1094	E0802	OYGTSSRE4TC
Mini	All(433 Mhz) (September 2009)	11-13			9012	2000K	36 10 6 856 227	1096	E0802	OYGTSSRE4D
Mitsubishi	Eclipse(Alloy)	06-12	7001	7020K	9034	1080K	425 0B 877	NO	A0701	MRX2T315AMA
Mitsubishi	Eclipse(Steel)	06-07	7001	7020K	9069	1130K	4250A030	NO	A0701	MRXNG33MA4S
Mitsubishi	Endeavor(433 Mhz)	04-06	7004	7020K	9028	1080K	52088990AC	NO	A0701	MRXTG224AM02
Mitsubishi	Endeavor(Sept +)	06-12	7001	7020K	9034	1080K	425 0B 877	NO	A0701	MRX2T315AMA
Mitsubishi	Galant(433 Mhz)	04-06	7004	7020K	9028	1080K	MN103033	NO	A0701	MRXTG224AM02
Mitsubishi	Galant	07-12	7001	7020K	9034	1080K	425 0B 877	NO	A0701	MRX2T315AMA
Mitsubishi	Galant(Steel)	07-12	7001	7020K	9069	1130K	425 0B 875	NO	A0701	MRXNG33MA4S
Mitsubishi	Lancer	08-10			1051	1050K	425 0B 668/975	NO	A0701	KR5S180052015B
Mitsubishi	Lancer	10-13			1051	7020K	425 0B 668/975	VS70	A0701	KR5S180052015B
Mitsubishi	Montero	03-05	7001	7020K	9034	1080K	MN103081	NO	A0701	MRX2T315AMA
Mitsubishi	Outlander	07-10			1051	1050K	425 0B 668/975	NO	A0701	KR5S180052015B
Mitsubishi	Outlander	10-13			1051	7020K	425 0B 668/975	VS70	A0701	KR5S180052015B
Mitsubishi	Raider	08-09	7001	7020K	9154	2030K	56029319AB	9066K	A0701	MRXC4N3MF9
Nissan	350Z	04-06	**7001	7020K	9064	1080K	40700-CD001	NO	A0801	MRXSUZ3MA4
Nissan	350Z	07-09	**7001	7020K	9204	2030K	40700-1AA0D	NO	A0801	KOBHT05ATPM
Nissan	370Z	09-10	**7001	7020K	9204	1100K	40700-JK00C	NO	A0801	KOBHT05ATPM
Nissan	370Z	11-13			1216	1100K	40700-1LA0D	NO	A0801	PAXPMV107S
Nissan	Altima	06-12	**7001	7020K	9204	2030K	40700-1AA0D	NO	A0801	KOBHT05ATPM
Nissan	Altima--433 Mhz	13			5556	7000K	40700-3JA0A	VS70	A801	KR5S18052020A
Nissan	Armada(Alloy)--SE	05-08	**7001	7020K	9161	1080K	40700-CK001	NO	A0801	MRXNG33MA4S
Nissan	Armada(Steel)	05-06	**7001	7020K	9069	1130K	40700-CK002	NO	A0801	MRXNG33MA4S
Nissan	Armada-LE	09-13	**7001	7020K	9204	2030K	40700-1AA0D	NO	A0801	KOBHT05ATPM
Nissan	Cube -- All Models	09-11	**7001	7020K	9204	2030K	40700-1AA0D	NO	A0801	KOBHT05ATPM
Nissan	Cube -- Base & S Models	12	**7001	7020K	9204	2030K	40700-1AA0D	NO	A0801	KOBHT05ATPM
Nissan	Cube - (>3/12)-- S Model	12-13	**7001	7020K	9204	1100K	40700-JK00C	NO	A0801	KOBHT05ATPM
Nissan	Cube -- S Model	12-13			1216	1100K	40700-1LA0D	NO	A0801	PAXPMV107S
Nissan	Cube -- SL & Krom Models	11-13	**7001	7020K	NEW	7000K	40700-3AN0A	VS70	A0801	KR5S18052033
Nissan	Frontier	03-04	**7001	7020K	9064	1080K	40700-CD001	NO	A0801	MRXSUZ3MA4

DILL TPMS APPLICATIONS CHART ©

OE	Model	Model Year	Multi-App Sensor	Multi-App Kit	Dill Sensor	Dill Kit	OE Sensor Part #	Valve Stem Replacement	Relearn	FCC ID #
Nissan	Frontier(Alloy)	05-08	**7001	7020K	9161	1080K	40700-CK001	NO	A0801	MRXNG33MA4S
Nissan	Frontier(Steel)	05-07	**7001	7020K	9069	1130K	40700-CK002	NO	A0801	MRXNG33MA4S
Nissan	Frontier(Steel)	09-12	**7001	7020K	9204	2030K	40700-1AA0D	NO	A0801	KOBHT05ATPM
Nissan	Frontier	13	**7001	7020K	NEW	7000K	40700-3AN0A	VS70	A0801	KR5S18052033
Nissan	GT-R	09-13	**7001	7020K	9204	2030K	40700-1AA0D	NO	A0801	KOBHT05ATPM
Nissan	Juke -- S Model	11	**7001	7020K	9204	2030K	40700-1AA0D	NO	A0801	KOBHT05ATPM
Nissan	Juke -- SL & SV Models	12	**7001	7020K	9204	2030K	40700-1AA0D	NO	A0801	KOBHT05ATPM
Nissan	Juke -- (3/12)-- SL & SV Models	12-13	**7001	7020K	9204	1100K	40700-JK00C	NO	A0801	KOBHT05ATPM
Nissan	Juke -- SL & SV Models	11			1216	1100K	40700-1LA0D	NO	A0801	PAXPMV107S
Nissan	Juke -- All Models	12-13			1216	1100K	40700-1LA0D	NO	A0801	PAXPMV107S
Nissan	Leaf	11-13			1216	1100K	40700-1LA0D	NO	A0801	PAXPMV107S
Nissan	Maxima(Alloy)	06-07	**7001	7020K	9161	1080K	40700-CK001	NO	A0801	MRXNG33MA4S
Nissan	Maxima(Post-April)	07-11	**7001	7020K	9204	2030K	40700-1AA0D	NO	A0801	KOBHT05ATPM
Nissan	Maxima	12	**7001	7020K	9204	2030K	40700-1AA0D	NO	A0801	KOBHT05ATPM
Nissan	Maxima(>12/11)	12-13	**7001	7020K	NEW	7000K	4070-3AN0A	VS70		UNKNOWN
Nissan	Murano	03-06	**7001	7020K	9064	1080K	40700-CD001	NO	A0801	MRXSUZ3MA4
Nissan	Murano	07-12	**7001	7020K	9204	2030K	40700-1AA0D	NO	A0801	KOBHT05ATPM
Nissan	Murano(>11/11)	13	**7001	7020K	9204	1100K	40700-JK00C	NO	A0801	KOBHT05ATPM
Nissan	NV 1500/2500HD/3500HD	12			NEW	2030K	40700-1PA0A			UNKNOWN
Nissan	Pathfinder	03-04	**7001	7020K	9064	1080K	40700-CD001	NO	A0801	MRXSUZ3MA4
Nissan	Pathfinder(Steel)	04	**7001	7020K	9069	1130K	40700-CK002	NO	A0801	MRXNG33MA4S
Nissan	Pathfinder	05-06	**7001	7020K	9161	1080K	40700-CK001	NO	A0801	MRXNG33MA4S
Nissan	Pathfinder	07-12	**7001	7020K	9204	2030K	40700-1AA0D	NO	A0801	KOBHT05ATPM
Nissan	Pathfinder	13		7020K	5556	7000K	4070-3JAOA	VS70		KR5S18052020A
Nissan	Quest(Steel)	04-07	**7001	7020K	9069	1130K	40700-CK002	NO	A0801	MRXNG33MA4S
Nissan	Quest(Alloy)	05-06	**7001	7020K	9161	1080K	40700-CK001	NO	A0801	MRXNG33MA4S
Nissan	Quest	07-09	**7001	7020K	9204	2030K	40700-1AA0D	NO	A0801	KOBHT05ATPM
Nissan	Quest	11-13			1216	1100K	40700-1LA0D	NO	A0801	PAXPMV107S
Nissan	Rogue	08-12	**7001	7020K	9204	2030K	40700-1AA0D	NO	A0801	KOBHT05ATPM
Nissan	Rogue(>11/11)	12-13	**7001	7020K	9204	1100K	40700-JK00C	NO	A0801	KOBHT05ATPM
Nissan	Sentra(Alloy)	07-08	**7001	7020K	9161	1080K	40700-CK001	NO	A0801	MRXNG33MA4S
Nissan	Sentra(Steel)	07-12	**7001	7020K	9204	2030K	40700-1AA0D	NO	A0801	KOBHT05ATPM
Nissan	Sentra(>1/12)	12-13	**7001	7020K	9204	1100K	40700-JK00C	NO	A0801	KOBHT05ATPM
Nissan	Titan(Alloy)	05-07	**7001	7020K	9161	1080K	40700-CK001	NO	A0801	MRXNG33MA4S
Nissan	Titan(Steel)	04-05	**7001	7020K	9069	1130K	40700-CK002	NO	A0801	MRXNG33MA4S
Nissan	Titan(Steel) (Post April)	07-13	**7001	7020K	9204	2030K	40700-1AA0D	NO	A0801	KOBHT05ATPM
Nissan	Versa	07-11	**7001	7020K	9204	2030K	40700-1AA0D	NO	A0801	KOBHT05ATPM
Nissan	Versa-- 1.8 S & SL Models	12	**7001	7020K	9204	2030K	40700-1AA0D	NO	A0801	KOBHT05ATPM
Nissan	VERSA-HB(>1/12)-- 1.6 S & SL & SV Models	12-13	**7001	7020K	9204	1100K	40700-JK00C	NO	A0801	KOBHT05ATPM
Nissan	Versa--Sedan	12-13	**7001	7020K	NEW	7000K	40700-3AN0A	VS70	A0801	KR5S18052033
Nissan	Xterra	03-04	**7001	7020K	9064	1080K	40700-CD001	NO	A0801	MRXSUZ3MA4
Nissan	Xterra	05-06	**7001	7020K	9161	1080K	40700-CK001	NO	A0801	MRXNG33MA4S
Nissan	Xterra(Steel)	06-07	**7001	7020K	9069	1130K	40700-CK002	NO	A0801	MRXNG33MA4S
Nissan	Xterra	07-12	**7001	7020K	9204	2030K	40700-1AA0D	NO	A0801	KOBHT05ATPM
Nissan	Xterra	13	**7001	7020K	NEW	7000K	40700-3AN0A	VS70	A0801	KR5S18052033
**Utilize the ATEQ VT-55 or Bartec OBD-enabled tools(Rev 45) for the vehicle relearn.										
Pontiac	G3	09			9153	VS950	25920615	VS950	D0305	MRXG53MA4S
Pontiac	G5	08	7001	7020K	9158	1050K	15921013	NO	D0305	MRXGMX272RS
Pontiac	G5	09-10	7001-R	VS80	9153	VS950	25920615	VS950	D0305	MRXG53MA4S
Pontiac	G6(Pre-10/15)	08	7001	7020K	9158	1050K	15921013	NO	D0305	MRXGMX272RS
Pontiac	G6(Post-10/15)	08-10	7001-R	VS80	9153	VS950	25920615	VS950	D0305	MRXG53MA4S
Pontiac	G8	08-09	7001-R	VS80	9153	VS950	25920615	VS950	D0305	MRXG53MA4S
Pontiac	Grand Prix	07-08	7001	7020K	9158	1050K	15921013	NO	D0305	MRXGMX272RS
Pontiac	Grand Prix	08	7001-R	VS80	9153	VS950	25920615	VS950	D0305	MRXG53MA4S
Pontiac	Montana	08	7001	7020K	9158	1070K	15268606	NO	D0305	MRXGMX272RS
Pontiac	Solstice	08-09	7001	7020K	9158	1050K	15921013	NO	D0305	MRXGMX272RS

DILL TPMS APPLICATIONS CHART ©

OE	Model	Model Year	Multi-App Sensor	Multi-App Kit	Dill Sensor	Dill Kit	OE Sensor Part #	Valve Stem Replacement	Relearn	FCC ID #
Pontiac	Torrent	07-09	7001	7020K	9158	1050K	10394110	NO	D0305	MRXGMX272RS
Pontiac	Vibe	08-10	1204-A	1100K	1204	1100K	88974915	NO	D0312	PAXPMV107J
Pontiac	Wave	08	7001-R	VS80	9153	VS950	25920615	VS950	D0305	MRXG53MA4S
**The 1050K is to be used on the Siemens sensors and the 1070K is to be used on the Schrader sensors.										
Porsche	911(433 Mhz)	05-08			9001	1090K	997 606 021 01	1092	E0901	OYGTSSRE4B
Porsche	911(433 Mhz)	09-13			9008	1090K	997 606 021 20	1092	E0901	OYG TSSRE4TC
Porsche	911(315 Mhz)	06-08			9004	1090K	997 606 023 21	1092	E0901	OYGTSSRE3B
Porsche	Boxster(433 Mhz)	06-08			9001	1090K	997 606 021 01	1092	E0901	OYGTSSRE4B
Porsche	Boxster(433 Mhz)-- Post November 2008	09-13			9008	1090K	997 606 021 20	1092	E0901	OYG TSSRE4TC
Porsche	Boxster(315 Mhz)	06-08			9004	1090K	997 606 023 21	1092	E0901	OYGTSSRE3B
Porsche	Carrera GT(433 Mhz)	03-06			9001	1090K	997 606 021 01	1092	E0901	OYGTSSRE4B
Porsche	Carrera GT(315 Mhz)	04-06			9004	1090K	997 606 023 21	1092	E0901	OYGTSSRE3B
Porsche	Cayenne(433 Mhz)	03-06			9005	1090K	955 361 661 01	1092	E0901	OYGTSSRE4PB
Porsche	Cayenne(315 Mhz)	09-10			9004	1090K	955 606 023 01	1092	E0901	OYGTSSRE3B
Porsche	Cayenne(433 Mhz)	07-10			9007	1090K	955 606 021 00	1092	E0901	OYG TSSRE4TB
Porsche	Cayenne(433 Mhz)	10-13			9011	2000K	958 361 661 00	1092	E0901	OYG TSSRE4TC
Porsche	Cayman(433 Mhz)	05-08			9001	1090K	997 606 021 01	1092	E0901	OYGTSSRE4B
Porsche	Cayman(315 Mhz)	05-08			9004	1090K	997 606 023 21	1092	E0901	OYGTSSRE3B
Porsche	Cayman(433 Mhz)	09-13			9008	1090K	997 606 021 20	1092	E0902	OYG TSSRE4TC
Porsche	GT3	07-09			9001	1090K	997 606 021 01	1092	E0901	OYGTSSRE4B
Porsche	GT3	10-12			9008	1090K	997 606 021 20	1092	E0901	OYG TSSRE4TC
Porsche	Panamera(315 Mhz)	10-13			9004	1090K	997 606 023 21	1092	E0901	OYGTSSRE3B
Porsche	Panamera(433 Mhz)	10-13			9008	1090K	997 606 021 20	1092	E0901	OYG TSSRE4TC
Rolls Royce	Phantom(433 Mhz)	07-12			1027	1090K	NA	1092 or 1094		OYGTSSRE4TC
Rolls Royce	Cabrio(433 Mhz)	10-12			1027	1090K	NA	1092 or 1094		OYGTSSRE4TC
Saab	9-3(433 Mhz)	04-07			9078	2010K	13172567	NO	E1001	MRXGME433TX2
Saab	9-3(433 Mhz)	08-12				2010K	13227143	NO	E1001	MRXGME433WAL
Saab	9-5(433 Mhz)	04-07			9078	2010K	13172567	NO	E1001	MRXGME433TX2
Saab	9-5(433 Mhz)	08-12				2010K	13227143	NO	E1001	MRXGME433WAL
Saab	9-7X(315 Mhz)	05-09	7001	7020K	9116	1070K	25774006	NO	E1002	MRXGMT51MAN
Saturn	Astra(433 Mhz)	08-09			9078	2010K	13172567	NO	D0305	MRXGME433TX2
Saturn	Aura(<10/14/07)	07-08	7001	7020K	9158	1050K	15921013	NO	D0305	MRXGMX272RS
Saturn	Aura(>10/14/07)	08-09	7001-R	VS80	9153	VS950	25920615	VS950	D0305	MRXG53MA4S
Saturn	Lamda Crossover	07-08	7001	7020K	9158	1070K	15268606	NO	D0305	MRXGMX272RS
Saturn	Outlook	07-08	7001	7020K	9158	1050K	15921013	NO	D0305	MRXGMX272RS
Saturn	Outlook	09-10	7001-R	VS80	9153	VS950	25920615	VS950	D0305	MRXG53MA4S
Saturn	Sky	08-09	7001	7020K	9158	1050K	15921013	NO	D0305	MRXGMX272RS
Saturn	Vue	07-10	7001-R	7020K	9153	VS950	25920615	VS950	D0305	MRXG53MA4S
**The 1050K is to be used on the Siemens sensors and the 1070K is to be used on the Schrader sensors.										
Scion	tC	06-13	7002 or 1204-A	7020K	1204	1100K	42607-33011	NO	A1101	PAXPMV107J
Scion	FR-S	13			1218	1100K	SU003-00754	NO	A1101	PAXPMVC010
Scion	iQ	12-13	7002 or 1204-A	7020K	1204	1100K	42607-33011	NO	A1101	PAXPMV107J
Scion	xB	08-12	7002 or 1204-A	7020K	1204	1100K	42607-33011	NO	A1101	PAXPMV107J
Scion	xD	08-13	7002 or 1204-A	7020K	1204	1100K	42607-33011	NO	A1101	PAXPMV107J
Smart	Fortwo(433 Mhz)	08			1049	1040K	004 542 1518	1040K	E1101	KR5S122228002
Smart	Fortwo(433 Mhz)	08-13			9214	2030K	003 540 0217	9066K	E1101	MRXMERCX1
Subaru	B9 Tribeca	06-07			9081	1080K	28103AG00A	NO	A0301	MRXSUZ3MA4
Subaru	BRZ	13			1218	1100K	28103-CA000	NO		PAXPMVC010
Subaru	Forester	08-13			9203	VS950	28103AG01C	VS950	A0302	MRXSMD3MA4
Subaru	Impreza	08-13			9203	VS950	28103AG01C	VS950	A0301	MRXSMD3MA4
Subaru	Legacy	04-07			9081	1080K	28103AG00A	NO	A0301	MRXSUZ3MA4
Subaru	Legacy	08-13			9203	VS950	28103AG01C	VS950	A0301	MRXSMD3MA4
Subaru	Outback	04-07			9081	1080K	28103AG00A	NO	A0301	MRXSUZ3MA4
Subaru	Outback	08-13			9203	VS950	28103AG01C	VS950	A0301	MRXSMD3MA4
Subaru	Tribeca	08-13			9203	VS950	28103AG01C	VS950	A0301	MRXSMD3MA4
Subaru	XV Crosstrek	13			9203	VS950	28103AG01C	VS950	A0301	MRXSMD3MA4
Suzuki	Equator	09-13	**7001	7020K	9204	2030K	43211-82Z10	NO	A1002	KOBHT05ATPM

DILL TPMS APPLICATIONS CHART ©

OE	Model	Model Year	Multi-App Sensor	Multi-App Kit	Dill Sensor	Dill Kit	OE Sensor Part #	Valve Stem Replacement	Relearn	FCC ID #
Suzuki	Forenza	07-08	7001-R	VS80	9153	VS950	43130-85Z03	VS950	A1002	MRXG53MA4S
Suzuki	Grand Vitara	07-13			9087	2010K	43130-54J21	NO	A1002	MRXNG33MA4S
Suzuki	Kizashi	10-13	7001	7020K	1051	7020K	43130-57L00	VS70	A1002	KR5S180052015B
Suzuki	Reno	07-08	7001-R	VS80	9153	VS950	43130-85Z00	VS950	A1002	MRXG53MA4S
Suzuki	SX4	07-13			9087	2010K	43130-54J21	NO	A1002	MRXNG33MA4S
Suzuki	Verona	05-06			9082	2010K	43130-86Z20	NO	A1002	MRXTG224AM01
Suzuki	XL-7	05-06			9087	2010K	43130-54J21	NO	A1002	MRXNG33MA4S
Suzuki	XL-7	07-09	7001	7020K	9158	1050K	43130-78J10	NO	A1003	MRXGMX272RS
**Utilize the ATEQ VT-55 or Bartec OBD-enabled tools(Rev 45) for the vehicle relearn.										
Tesla	Roadster	10-13			2112	2020K	6004985	NO		TZSTPMS201
Toyota	4 Runner	03-13	7002 or 1204-A	7020K	1204	1110K	42607-33021	NO	A1101	PAXPMV107J
Toyota	Avalon	07-13	7002 or 1204-A	7020K	1204	1100K	42607-06011/33011	NO	A1101	PAXPMV107J
Toyota	Avalon(Post 11/12)	13			1218	1100K	42607-06020	NO	A1101	PAXPMVC010
Toyota	Camry	07-11	7002 or 1204-A	7020K	1204	1100K	42607-06011/33011	NO	A1101	PAXPMV107J
Toyota	Camry	12-13			1218	1100K	42607-06020	NO	A1101	PAXPMVC010
Toyota	Corolla	07-13	7002 or 1204-A	7020K	1204	1100K	42607-06011/33011/33021	NO	A1101	PAXPMV107J
Toyota	FJ Cruiser	08-13	7002 or 1204-A	7020K	1204	1100K	42607-33011	NO	A1101	PAXPMV107J
Toyota	Highlander	07-13	7002 or 1204-A	7020K	1204	1100K	42607-06011	NO	A1101	PAXPMV107J
Toyota	Land Cruiser	05-13	7002 or 1204-A	7020K	1204	1100K	42607-33011	NO	A1101	PAXPMV107J
Toyota	Matrix	07-13	7002 or 1204-A	7020K	1204	1100K	42607-06011/33011	NO	A1101	PAXPMV107J
Toyota	Prius	06-13	7002 or 1204-A	7020K	1204	1100K	42607-06011	NO	A1101	PAXPMV107J
Toyota	Prius V	12-13	7002 or 1204-A	7020K	1204	1100K	42607-33011	NO	A1101	PAXPMV107J
Toyota	Prius C	12-13			1218	1100K	42607-52020	NO	A1101	PAXPMVC010
Toyota	RAV 4	06-13	7002 or 1204-A	7020K	1204	1100K	42607-06011	NO	A1101	PAXPMV107J
Toyota	RAV4(Post 1/13)--Smart Key	13			1218	1100K	42607-52020	NO	A1101	PAXPMVC010
Toyota	RAV4(Post 1/13)--RKE	13			NEW		42607-0R010			
Toyota	Sequoia(20 Degrees)	04-07	7002 or 1204-A	7020K	1204	1110K	42607-0C020	NO	A1101	PAXPMV107J
Toyota	Sequoia(40 Degrees)	04-07	7002 or 1204-A	7020K	1203	1110K	42607-0C010	NO	A1101	PAXPMV1037
Toyota	Sequoia(20 Degrees)	08-13	7002 or 1206-A	7020K	1206	1110K	42607-0C070/08010	NO	A1101	GQ4-32T
Toyota	Sequoia(40 Degrees)	08	7002 or 1206-A	7020K	1206	1110K	42607-0C060	NO	A1101	GQ4-32T
Toyota	Sienna(20 Degrees)	06-13	7002 or 1206-A	7020K	1206	1110K	42607-0C070/08010	NO	A1101	GQ4-32T
Toyota	Solara	06-08	7002 or 1204-A	7020K	1204	1100K	42607-06011	NO	A1101	PAXPMV107J

DILL TPMS APPLICATIONS CHART ©

OE	Model	Model Year	Multi-App Sensor	Multi-App Kit	Dill Sensor	Dill Kit	OE Sensor Part #	Valve Stem Replacement	Relearn	FCC ID #
Toyota	Tacoma(20 Degrees)	05-06	7002 or 1204-A	7020K	1204	1110K	42607-0C020/AD020	NO	A1101	PAXPMV107J
Toyota	Tacoma(40 Degrees)	05-13	7002 or 1204-A	7020K	1203	1110K	42607-0C010/AD010/04010	NO	A1101	PAXPMV1037
Toyota	Tacoma(20 Degrees)	07-13	7002 or 1204-A	7020K	1204	1100K	42607-06011	NO	A1101	PAXPMV107J
Toyota	Tundra(20 Degrees)	05-06	7002 or 1204-A	7020K	1204	1110K	42607-0C020	NO	A1101	PAXPMV107J
Toyota	Tundra(40 Degrees)	05-06	7002 or 1204-A	7020K	1203	1110K	42607-0C010	NO	A1101	PAXPMV1037
Toyota	Tundra(20 Degrees)	06-13	7002 or 1206-A	7020K	1206	1110K	42607-0C070/08010	NO	A1101	GQ4-32T
Toyota	Tundra(40 Degrees)	06-11	7002 or 1206-A	7020K	1206	1110K	42607-0C060	NO	A1101	GQ4-32T
Toyota	Venza	09-13	7002 or 1204-A	7020K	1204	1100K	42607-06011	NO	A1101	PAXPMV107J
Toyota	Yaris	07-11	7002 or 1204-A	7020K	1204	1100K	42607-33011	NO	A1101	PAXPMV107J
Toyota	Yaris	12-13			1218	1100K	42607-52020	NO	A1101	PAXPMVC010
Volkswagen	Beetle	08-10			1053	1030K	1K0907253D	NO	E1204	KR5S120123
Volkswagen	CC	09-10			1053	1030K	1K0907253D	NO	E1204	KR5S120123
Volkswagen	CC	12-13			9013	2000K	3AA 907 275D	1096	E1204	OYGTSSRE4D
Volkswagen	EOS	07-12			1053	1030K	1K0907253D	NO	E1204	KR5S120123
Volkswagen	GLI	08-09			1053	1030K	1K0907253D	NO	E1204	KR5S120123
Volkswagen	Golf	10			1053	1030K	1K0907253D	NO	E1204	KR5S120123
Volkswagen	GTI(Standard Hex)	06-11			1053	1030K	1K0907253D	NO	E1204	KR5S120123
Volkswagen	GTI(O-ring Hex)	06-07			1041	1031K	1K0907253E	NO	E1204	KR5S120123
Volkswagen	Jetta(Standard Hex)	06-10			1053	1030K	1K0907253D	NO	E1204	KR5S120123
Volkswagen	Jetta Sportwagen	13			NEW	2000K	5Q0 907 275	1096	E1204	UNKNOWN
Volkswagen	Passat CC(Standard Hex)	06-10			1053	1030K	1K0907253D	NO	E1204	KR5S120123
Volkswagen	Passat(433 Mhz)	10-13			9013	2000K	3AA 907 275D	1096	E1204	OYGTSSRE4D
Volkswagen	Passat(O-ring Hex)	06-08			1041	1031K	1K0907253E	NO	E1204	KR5S120123
Volkswagen	Phaeton(433 Mhz) (thru May 2007)	02-07			9001	1090K	4D0 907 275C	1092	E1202	OYGTSSRE4B
Volkswagen	Phaeton(433 Mhz) (June 2007)	07-10			9007	1090K	4F0 907 275B	1092	E1202	OYG TSSRE4TB
Volkswagen	Phaeton(433 Mhz)	11			9011	2000K	4F0 907 275D	1092	E1202	OYG TSSRE4TC
Volkswagen	Phaeton(315 Mhz)	03-07			9004	1090K	4D0 907 275A	1092	E1202	OYGTSSRE3B
Volkswagen	R32	08			1053	1030K	1K0907253D	NO	E1204	KR5S120123
Volkswagen	Rabbit(Standard Hex)	06-09			1053	1030K	1K0907253D	NO	E1204	KR5S120123
Volkswagen	Rabbit(O-ring Hex)	06-07			1041	1031K	1K0907253E	NO	E1204	KR5S120123
Volkswagen	Routan(433 Mhz)	09-11	7004	7020K	1043	1050K	7B0907253A	NO	E1205	KR5S180052020A
Volkswagen	Routan(433 Mhz)	12			9398	VS950	7B0907253C	VS950	E1205	MRXC4W4MA4
Volkswagen	Tiguan	09-11			1053	1030K	1K0907253D	NO	E1205	KR5S120123
Volkswagen	Tiguan	12-13			NEW	2000K	3AA 907 275D	1096	E1204	UNKNOWN
Volkswagen	Touareg(433 Mhz)-- (December 2006)	03-07			9005	1090K	7L0 907 275B	1092	E1203	OYGTSSRE4PB
Volkswagen	Touareg(433 Mhz)-- (January 2007)	07-10			9007	1090K	4F0 907 275B	1092	E1203	OYG TSSRE4TB
Volkswagen	Touareg(433 Mhz)	11-13			9011	1090K	7P0 907 275	1092	E1203	OYG TSSRE4TC
Volvo	C30(433 Mhz)	07-10		7020K	1044	1050K	31302096	NO	E1301	KR5S180020
Volvo	C30(433 Mhz)	10-13		7020K	1044	7020K	31302096	VS70	E1301	KR5S180020
Volvo	C70(433 Mhz)	07-10		7020K	1044	1050K	31302096	NO	E1301	KR5S180020
Volvo	C70(433 Mhz)	10-13		7020K	1044	7020K	31302096	VS70	E1301	KR5S180020
Volvo	S40(433 Mhz)	07-10		7020K	1044	1050K	31302096	NO	E1301	KR5S180020
Volvo	S40(433 Mhz)	10-11		7020K	1044	7020K	31302096	VS70	E1301	KR5S180020

DILL TPMS APPLICATIONS CHART ©

OE	Model	Model Year	Multi-App Sensor	Multi-App Kit	Dill Sensor	Dill Kit	OE Sensor Part #	Valve Stem Replacement	Relearn	FCC ID #
Volvo	S60(315 Mhz)	04-08			9156	2010K	86517000	NO	E1301	MRXTG315AM04
Volvo	S60(315 Mhz)	09-10			NEW	VS950	31200923	VS950	E1301	MRXSMD3MA4
Volvo	S60(315 Mhz)	09-10			9156	2010K	OE Sensor Replacement	NO	E1301	MRXTG315AM04
Volvo	S60(433 Mhz)	11-13		7020K	1044	7020K	31302096	VS70	E1301	KR5S180020
Volvo	S80(315 Mhz)	04-06			9156	2010K	86517000	NO	E1301	MRXTG315AM04
Volvo	S80(433 Mhz)	07-10		7020K	1044	1050K	31302096	NO	E1301	KR5S180020
Volvo	S80(433 Mhz)	10-13		7020K	1044	7020K	31302096	VS70	E1301	KR5S180020
Volvo	V50(433 Mhz)	08-10		7020K	1044	1050K	31302096	NO	E1301	KR5S180020
Volvo	V50(433 Mhz)	10-11		7020K	1044	7020K	31302096	VS70	E1301	KR5S180020
Volvo	V70(315 Mhz)	04-07			9156	2010K	86517000	NO	E1301	MRXTG315AM04
Volvo	V70(433 Mhz)	08-10		7020K	1044	1050K	31302096	NO	E1301	KR5S180020
Volvo	XC60	11-13		7020K	1044	7020K	31302096	VS70	E1301	KR5S180020
Volvo	XC70(315 Mhz)	04-07			9156	2010K	86517000	NO	E1301	MRXTG315AM04
Volvo	XC70(433 Mhz)	08-10		7020K	1044	1050K	31302096	NO	E1301	KR5S180020
Volvo	XC70(433 Mhz)	10-13		7020K	1044	7020K	31302096	VS70	E1301	KR5S180020
Volvo	XC90(315 Mhz)	05-13			9156	2010K	86517000	NO	E1301	MRXTG315AM04
Volvo	XC90(433 Mhz)	08		7020K	1044	1050K	31302096	NO	E1301	KR5S180020
Volvo Group	Volvo Bus	---	---	---	9010	VS9013 or VS9980	---	VS9013 or VS9980	---	OYGTSSRE4NB
Volvo Group	Prevost Bus	---	---	---	9010	VS9013 or VS9980	---	VS9013 or VS9980	---	OYGTSSRE4NB
Volvo Group	Nova Bus	---	---	---	9010	VS9013 or VS9980	---	VS9013 or VS9980	---	OYGTSSRE4NB

DISCLAIMER: The data presented in this document is accurate to the best of our knowledge and is regularly updated with the latest data available in the marketplace. We encourage you to check back for the latest edition of this data, however, we cannot guarantee accuracy of the information provided. Also, please note that several vehicle applications require knowledge of the VIN number as the sensor design could have changed mid-model year. **PLEASE DO NOT POST THIS DOCUMENT ON ANY WEBSITE.**