



SCHRADER TIRE PRESSURE MONITORING SYSTEMS

►► 2012 SENSOR & SERVICE PACK APPLICATION CATALOG




Table of Contents

TPMS Tools and Accessories.....	1-7
TPMS Sensors/Transmitters & Service Packs - Alphabetical Listing	8-66
Manufacturers' Part Numbers.....	67-68
TPMS Sensors/Transmitters - Numerical Listing.....	69-83
TPMS Service Packs - Numerical Listing	84-98
NHTSA TREAD Act.....	Inside Back Cover

Schrader International, Inc. Limited Warranty

Schrader International, Inc. ("Schrader") warrants that its products will be free from defects in materials and workmanship for a period of twelve (12) months from the date of shipment from Schrader's facility or delivery (whichever occurs first). Schrader will, at its option, replace or repair any product proved defective in materials or workmanship, or both, during the warranty period. This shall be the sole and exclusive remedy for breach of warranty. THE FOREGOING WARRANTY IS EXCLUSIVE AND IN LIEU OF ALL OTHER WARRANTIES EXCEPT THAT OF TITLE, WHETHER WRITTEN, ORAL OR IMPLIED, IN FACT OR IN LAW (INCLUDING ANY WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE). LIABILITY FOR SPECIAL, INDIRECT, INCIDENTAL, PUNITIVE OR CONSEQUENTIAL DAMAGES (INCLUDING, WITHOUT LIMITATION, DAMAGES FOR LOSS OF PROFITS, BUSINESS INTERRUPTION OR ANY OTHER LOSS), HEREBY ARE EXPRESSLY EXCLUDED TO THE EXTENT PERMITTED BY LAW, WHETHER BASED IN CONTRACT, NEGLIGENCE, TORT, WARRANTY OR OTHER WRONGFUL ACT OR OMISSION OF SELLER AND EVEN IF SELLER HAS BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES.

This warranty does not extend to (a) any defects or losses due to misuse, accident, abuse, neglect, or normal wear and tear; (b) any use not recommended in writing by Schrader; (c) any defects or losses relating to or caused by purchaser or a third party; or (d) any defects or losses relating to or caused by the effects of weathering, air pollution, corrosion, or exposure to harmful/caustic materials and/or chemicals.

Additionally, Schrader can not endorse the use of non-OE validated parts. Schrader has not validated testing of the compatibility of products of any supplier other than Schrader for fit and suitability of use in conjunction with Schrader parts. Therefore, use of BOTH Schrader sensors, and Schrader service packs or replacement "snap-in" stems, are required for warranty protection.

NHTSA TREAD Act

The Transportation Recall Enhancement, Accountability and Documentation (TREAD) Act was passed in the fall of 2000. The TREAD Act mandated that every new car manufactured for sale in the U.S. after September 1, 2007 must be equipped with sensors that monitor the pressure in all four tires. Sensors installed in the vehicle's wheels send a signal via RF to the vehicle's computer. The computer then processes the sensor data to alert the driver if pressure drops 25% below the specified cold placard pressure for the tire.

DID YOU KNOW

- 40% tire under-inflation increases braking distance by 10%.
- If every vehicle in the United States had properly inflated tires, we'd realize a savings of 4 million gallons of gasoline per day, everyday.
- An estimated 23,000 accidents and 535 fatal accidents annually involve blowouts or flat tires.
- 20% tire under-inflation reduces tire life by 20% and reduces fuel economy by 2% to 3%.
- Approximately 27% of passenger cars and 33% of light trucks on U.S. roadways are driven with one or more tires substantially under-inflated.

► Nut Torque Tool with Sockets – 20138

Torque wrench for valve nuts on TPMS installations. Kit includes 12mm and 11mm sockets for the two nut sizes used today, plus screwdriver handle for easy use. Torque range from 4.25 N.m. to 7.5 N.m. Accuracy plus or minus 4 percent. Includes plastic storage case. One per carton.



► Nut Torque Wrench Kit – 20139

Torque tool and precision quality torque wrench for installing TPMS sensor nuts. Includes 12 mm and 11 mm sockets. Torque range from 2 N.m. to 10 N.m. Accuracy plus or minus 2 percent. Includes plastic storage tray. One per carton.



► T-10 Torque Tool – 20140

Installs replacement snap-in valves to Schrader® OE sensors. T-10 Torx head installs screws to recommended torque for proper sealing and secure installation. Order individually. One per box.



► Valve Core Torque Tool – 20141

Tighten valve cores to OE specifications. Helps guard against over or under-torquing. Meets Tire and Rim Association (TRA) recommended torque values of 3" to 5" lbs. on TRC1 valve cores. Serves as both a core remover and installer. Order individually.



► Universal Nut Torque Tool – 20142

Serves as a torque wrench for valve nuts on TPMS installations. Kit includes 11mm and 12mm sockets and T-handle torque wrench with ergonomic design. Torque range from 30 to 90 in/lbs. One per plastic storage case.



► Replacement 11mm Socket – 21310

Order Individually

► Replacement 12mm Socket – 21315

Order Individually

► **Grommet Removal Tool – 20144**

This hand tool is designed to safely remove the rubber grommet from the aluminum stem of a TPMS sensor. Receiving hole can be used to install a new grommet. Ten per carton.



► **T-20 Torque Tool – 20145**

A pre-set torque tool specially designed for use with TPMS sensors that use a T-20 screw to attach the aluminum valve stem to the sensor body. The T-20 Torx head installs screws to recommended torque for proper sealing and secure installation.



► **Schrader TPMS Training DVD**

(English) – 21355

Order Individually

► **Schrader TPMS Training DVD**

(French) – 21356

Order Individually

► **Schrader TPMS Training DVD**

(Spanish) – 21357

Order Individually



► **Nissan® Reset Tool – 21370**

This trigger tool activates the TPMS learning mode on late model Nissans. One per carton.



Make your TPMS valve stems look as good as the rest of your ride with dress-up sleeves. Chrome finish dress up kits are available for both aluminum stems and rubber snap-in sensors. Each kit includes a fully plated sleeve and sealing cap to resist galvanic corrosion of TPMS sensors.

► **Chrome sleeves for rubber snap-in sensor**

22005 bulk 50 per carton



► **Complete snap-in valve service pack with chrome sleeves**

Complete with sleeve, cap and replacement TT valve.

22008 one per bag (50 bags per carton)



► **Banded TPMS Replacement Parts**

All of the components required to repair banded TPMS systems. These parts to be used with sensor part numbers 28385, 28390 and 28395.



► **Replacement Clip**

22100 bulk 25 per bag



► **Replacement Cradle**

22101 ten per carton
(style may vary)

► **Universal band**

Fits rims 14-26"

22102 one per bag



► Accessory and loose part items

20055 nickel-plated valve cores – 100/box _____ 

20395 plastic sealing valve caps – 100/box _____ 

20595 long black sealing valve caps for GM & Subaru snap-in sensors
(Sensors 20153 & 28203, service pack 20008) – 100/box _____ 

20695 long green (Nitrogen) sealing valve caps for snap-in sensors – 100/box _____ 

20795 green (Nitrogen) sealing valve caps – 100/box _____ 

20895 replacement T-10 screw – 25/bag _____ 

20995 Long black sealing valve caps for Ford snap-in sensors
(sensor 20315, service pack 20018) – 100/box _____ 

► TPMS Retrofit Kits

Schrader® TPMS Retrofit Kits install on vehicles not equipped with original equipment systems. The stand-alone kits include a dash-mounted receiver display, four wheel-mounted transmitters that fit most wheel applications and installation instructions.

TPMS retrofit kits:

- Continually monitor tire pressure in all four tires.
- Monitor tire temperature.
- Signal audible warning at under-inflation of 25 percent or more.
- Capable of monitoring spare tire. Fifth sensor sold separately. Order part no. **20154**.

TPMS systems monitor proper tire pressure to maintain vehicle performance and support safety.

Properly inflated tires:

- Improve vehicle handling.
- Reduce braking distances.
- Lower the risk of hydroplaning.
- Decrease tire wear.
- Improve fuel efficiency.



Schrader offers two kits:

- **20257** – hard wired to switched wires.
- **20256** – battery operated.
(two AA batteries included)
- **20154** – replacement sensor for Retrofit kits.

Learn Tools

► 21230 DBL + Learn and Test Tool with OBD Adapter

The Schrader® **21230** learn and test tool gives you all of the same benefits as the **21220** with the addition of the ability to perform TPMS service on vehicles requiring the sensor ID's to be directly uploaded to the vehicle's BCM.

- Enables TPMS relearn on imports such as Toyota, Nissan, Hyundai, Kia, Honda, Mitsubishi, Subaru and more.
- Comes with a universal OBD connector and cable to write sensors ID's directly to the BCM on vehicles that require OBD programming.
- Will not allow duplicate or wrong ID's to be written. Since you do not have to manually type the sensor ID's into the tool, there is no chance for human error.
- One simple-to-use tool with an easy four step process:
 - 1) Select Make - Model - Year
 - 2) Scan each sensor to capture the sensor ID into the tool's memory
 - 3) Connect to the OBD port
 - 4) Automatically download the sensor ID's with a push of a button
- After the first year, program updates are available with an update fee. Contact your Schrader sales representative for details.



The Schrader 21230 kit includes:

- **21230** DBL+ learn and test tool
- Hard plastic case - Part Number **21222**
- One USB cable - Part Number **21219**
- Magnet (necessary to activate some sensors) - Part Number **20143**
- Protective rubber boot - Part Number **21216**
- Rechargeable 9-volt battery - Part Number **21216**
- Charger - Part Number **21218**
- OBD connector and cable
- User guide

► OBD Adapter Accessories

The Schrader® **21225** OBD adapter kit enables current owners of the **21220** learn tool to upgrade their tool to a **21230** learn tool and enjoy all of the benefits listed above.

NOTE: Parts can be ordered separately.

- OBD Connector - Part Number **21225-OBD1**
- OBD Cable - Part Number **21225-OBD2**
- OBD tool only - Part Number **21230-R**



Learn Tools - Continued

► 21250 TPMS Toyota® Reset Tool

If a Toyota sensor has been broken or a new one installed (without being programmed to the car) AND THE RESET BUTTON WAS PUSHED, the vehicle can get caught in a "loop" and therefore cannot be repaired. There is only one way to fix this issue. The initialization process must be reset before new sensors can be registered to the vehicle. The Solution: The Toyota Reset Tool from Schrader. Simply plug the 21250 (Toyota Reset Tool) into the OBD and push and hold the button for 30 seconds. The system will reset and you can now repair and relearn the vehicle.



► EZ-sensor Programming Fixture – 35300

This fixture positions the 21230 scan/programming tool and EZ-sensor programmable sensor in the optimum orientation for programming.



► Aluminum clamp-in style valve – 34000

Aluminum stem service pack to rebuild the Schrader rubber valve snap-in sensor with an aluminum clamp-in style valve stem to match or upgrade existing look.

Fits Schrader OE replacement sensor part numbers: 20153, 20315, 20398, 28203, 28206, 28308, 28434, 28461

Fits Schrader EZ-sensor part numbers: 33000, 33100



► Service Pack Assortments

Schrader® offers two Service Pack Assortments that contain the most popular vehicle-specific service packs in a handy plastic box.

20397 assortment with 10 each of six service packs for Schrader sensors, 50 plastic caps and a valve core torque screwdriver.

Contents:	Qty.
20002	10
20003	10
20004	10
20005	10
20006	10
20007	10
20141	1
20195	50



20597 assortment with 8 each of six service packs for Schrader sensors, one service pack for Pacific® sensors, one service pack for Siemens® sensors, two service packs for TRW® sensors, 25 plastic caps, 100 cores and application chart.

Contents:	Qty.
20002	8
20003	8
20004	8
20005	8
20006	8
20007	8
20030	8
20031	8
20035	4
20036	4
20055	100
20195	25

CAUTION: Always use new grommets, nuts, valve caps and valve cores when performing any tire service. Use nickel-plated electroless valve cores with aluminum valve stems. Refer to manufacturer's specifications for proper torque requirements when replacing nuts and valve cores.



Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks Alphabetical Listing

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
Acura							
2012							
TL							
Sensor	20720	35	4	Sensor	20098	35	4
Service Pack	20019	35	4	Sensor	28981	35	4
2011							
MDX							
Sensor	20098	35	4	Sensor	20098	35	4
RL							
Sensor	28981	35	4	Sensor	28981	35	4
Service Pack; Includes Valve	20036	35	4	Service Pack; Includes Valve	20036	35	4
Service Pack; Does Not Include Valve	20021	35	4	Service Pack; Does Not Include Valve	20021	35	4
TL							
Sensor	20720	35	4	Sensor	20098	35	4
Service Pack	20019	35	4	Sensor	20098	35	4
TSX							
Sensor	20098	35	4	Sensor	20098	35	4
2010							
MDX; RDX							
Sensor	20098	35	4	Sensor	28981	35	4
RL							
Sensor	28981	35	4	Service Pack; Includes Valve	20036	35	4
Service Pack; Includes Valve	20036	35	4	Service Pack; Does Not Include Valve	20021	35	4
Service Pack; Does Not Include Valve	20021	35	4	Sensor	20098	35	4
TL							
Sensor	20720	35	4	Sensor	28981	35	4
Service Pack	20019	35	4	Sensor	20098	35	4
TSX							
Sensor	20098	35	4	Sensor	20098	35	4
2009							
CSX							
EZ-sensor - 315 MHz	✧33000	11.5	1.3	Sensor	28981	35	4
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Service Pack	20036	35	4
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack; Does Not Include Valve	20021	35	4
Sensor	28720	35	4	Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack	20019	35	4	Service Pack; W/48mm Green Insert ...	20038	35	4
MDX; RDX							
Sensor	20098	35	4	Service Pack; W/49mm Black Insert	20039	35	4
RL							
Sensor	28981	35	4	Service Pack; W/51mm Orange Insert ..	20040	35	4
Service Pack; Includes Valve	20036	35	4	Sensor	20103	35	4
Service Pack; Does Not Include Valve	20021	35	4	Service Pack; Does Not Include Valve	20023	35	4
TL							
Sensor	20720	35	4	Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack	20019	35	4	Service Pack; W/48mm Green Insert ...	20038	35	4
TSX							
Sensor	20098	35	4	Service Pack; W/49mm Black Insert	20039	35	4
2008							
CSX							
EZ-sensor - 315 MHz	✧33000	11.5	1.3	Sensor	20103	35	4
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Service Pack; Does Not Include Valve	20023	35	4
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack; W/48mm Green Insert ...	20038	35	4
Sensor	28720	35	4	Service Pack; W/49mm Black Insert	20039	35	4
Service Pack	20019	35	4	Service Pack; W/51mm Orange Insert ..	20040	35	4
2008							
Acura - Continued							
2008 - Continued							
MDX; RDX							
Sensor	20098	35	4	Sensor	28981	35	4
RL; TL							
Sensor	20036	35	4	Service Pack; Includes Valve	20021	35	4
Service Pack; Does Not Include Valve	20021	35	4	Sensor	20098	35	4
TSX							
Sensor	20098	35	4	Sensor	20098	35	4
2007							
MDX; RDX							
Sensor	20098	35	4	Sensor	28981	35	4
RL; TL							
Sensor	20036	35	4	Service Pack; Includes Valve	20021	35	4
Service Pack; Does Not Include Valve	20021	35	4	Sensor	20098	35	4
TSX							
Sensor	20098	35	4	Sensor	20098	35	4
2006-2005							
MDX; RL; TL							
Sensor	28981	35	4	Sensor	28981	35	4
Service Pack; Includes Valve	20036	35	4	Service Pack; Includes Valve	20036	35	4
Service Pack; Does Not Include Valve	20021	35	4	Service Pack; Does Not Include Valve	20021	35	4
2004							
MDX							
Sensor	28981	35	4	Sensor	20098	35	4
Service Pack; Includes Valve	20036	35	4	Service Pack; Does Not Include Valve	20021	35	4
Audi							
2012							
A3; A4; A5; Q5							
Sensor	20088	71	8	Sensor	20088	71	8
Service Pack	20017	71	8	Service Pack	20017	71	8
Q7							
Sensor; Includes Transmitter Only	20103	35	4	Sensor	20103	35	4
Service Pack; Does Not Include Valve	20023	35	4	Service Pack; Does Not Include Valve	20023	35	4
Service Pack; W/43mm Silver Insert	20037	35	4	Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert ...	20038	35	4	Service Pack; W/48mm Green Insert ...	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4	Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert ..	20040	35	4	Service Pack; W/51mm Orange Insert ..	20040	35	4
R8							
Sensor	20103	35	4	Sensor	20103	35	4
Service Pack; W/43mm Silver Insert	20037	35	4	Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert ...	20038	35	4	Service Pack; W/48mm Green Insert ...	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4	Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert ..	20040	35	4	Service Pack; W/51mm Orange Insert ..	20040	35	4
S5							
Sensor	20088	71	8	Sensor	20088	71	8
Service Pack	20017	71	8	Service Pack	20017	71	8
2011							
A3; A4; A5							
Sensor	20088	71	8	Sensor	20088	71	8
Service Pack	20017	71	8	Service Pack	20017	71	8

◊ Programming Tool Required.

Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
Audi - Continued				Audi - Continued			
2011 - Continued				2010 - Continued			
A6				S4; S5			
Sensor; Includes Transmitter Only	20077	35	4	Sensor	20088	71	8
Service Pack; Does Not Include Valve .	20023	35	4	Service Pack	20017	71	8
Service Pack; W/43mm Silver Insert	20037	35	4	S6			
Service Pack; W/48mm Green Insert ...	20038	35	4	Sensor; Includes Transmitter Only	20103	35	4
Service Pack; W/49mm Black Insert	20039	35	4	Service Pack; Does Not Include Valve .	20023	35	4
Service Pack; W/51mm Orange Insert .	20040	35	4	Service Pack; W/43mm Silver Insert	20037	35	4
Q5				Service Pack; W/48mm Green Insert ...	20038	35	4
Sensor	20088	71	8	Service Pack; W/49mm Black Insert	20039	35	4
Service Pack	20017	71	8	Service Pack; W/51mm Orange Insert .	20040	35	4
Q7				TT			
Sensor; Includes Transmitter Only	20077	35	4	Sensor	20088	71	8
Service Pack; Does Not Include Valve .	20023	35	4	Service Pack	20017	71	8
Service Pack; W/43mm Silver Insert	20037	35	4	2009			
Service Pack; W/48mm Green Insert ...	20038	35	4	A3; A4; A5			
Service Pack; W/49mm Black Insert	20039	35	4	Sensor	20088	71	8
Service Pack; W/51mm Orange Insert .	20040	35	4	Service Pack	20017	71	8
R8				A6			
Sensor	20103	35	4	Sensor; Includes Transmitter Only; Exc. Quattro	20078	35	4
Service Pack; W/43mm Silver Insert	20037	35	4	Sensor; Includes Transmitter Only; Quattro	20103	35	4
Service Pack; W/48mm Green Insert ...	20038	35	4	Service Pack; Does Not Include Valve .	20023	35	4
Service Pack; W/49mm Black Insert	20039	35	4	Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/51mm Orange Insert .	20040	35	4	Service Pack; W/48mm Green Insert ...	20038	35	4
S4; S5				Service Pack; W/49mm Black Insert	20039	35	4
Sensor	20088	71	8	Service Pack; W/51mm Orange Insert .	20040	35	4
Service Pack	20017	71	8	A8			
TT				Sensor; Includes Transmitter Only	20077	35	4
Sensor	20088	71	8	Service Pack; Does Not Include Valve .	20023	35	4
Service Pack	20017	71	8	Service Pack; W/43mm Silver Insert	20037	35	4
2010				Service Pack; W/48mm Green Insert ...	20038	35	4
A3; A4; A5				Service Pack; W/49mm Black Insert	20039	35	4
Sensor	20088	71	8	Service Pack; W/51mm Orange Insert .	20040	35	4
Service Pack	20017	71	8	Q5			
A6				Sensor	20088	71	8
Sensor; Includes Transmitter Only	20103	35	4	Service Pack	20017	71	8
Service Pack; Does Not Include Valve .	20023	35	4	Q7; R8; S4			
Service Pack; W/43mm Silver Insert	20037	35	4	Sensor; Includes Transmitter Only	20078	35	4
Service Pack; W/48mm Green Insert ...	20038	35	4	Service Pack; Does Not Include Valve .	20023	35	4
Service Pack; W/49mm Black Insert	20039	35	4	Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/51mm Orange Insert .	20040	35	4	Service Pack; W/48mm Green Insert ...	20038	35	4
A8				Service Pack; W/49mm Black Insert	20039	35	4
Sensor; Includes Transmitter Only	20077	35	4	Service Pack; W/51mm Orange Insert .	20040	35	4
Service Pack; Does Not Include Valve .	20023	35	4	S5			
Service Pack; W/43mm Silver Insert	20037	35	4	Sensor	20088	71	8
Service Pack; W/48mm Green Insert ...	20038	35	4	Service Pack	20017	71	8
Service Pack; W/49mm Black Insert	20039	35	4	S6			
Service Pack; W/51mm Orange Insert .	20040	35	4	Sensor; Includes Transmitter Only	20078	35	4
Q5				Service Pack; Does Not Include Valve .	20023	35	4
Sensor	20088	71	8	Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack	20017	71	8	Service Pack; W/48mm Green Insert ...	20038	35	4
Q7; R8				Service Pack; W/49mm Black Insert	20039	35	4
Sensor; Includes Transmitter Only	20103	35	4	Service Pack; W/51mm Orange Insert .	20040	35	4
Service Pack; Does Not Include Valve .	20023	35	4	S8			
Service Pack; W/43mm Silver Insert	20037	35	4	Sensor; Includes Transmitter Only	20077	35	4
Service Pack; W/48mm Green Insert ...	20038	35	4	Service Pack; Does Not Include Valve .	20023	35	4
Service Pack; W/49mm Black Insert	20039	35	4	Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/51mm Orange Insert .	20040	35	4	Service Pack; W/48mm Green Insert ...	20038	35	4
TT				Service Pack; W/49mm Black Insert	20039	35	4
Sensor	20088	71	8	Service Pack; W/51mm Orange Insert .	20040	35	4
Service Pack	20017	71	8				



Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.																																																																																																																																																																																																																																																																																																																																																																																																				
Audi - Continued																																																																																																																																																																																																																																																																																																																																																																																																											
2008																																																																																																																																																																																																																																																																																																																																																																																																											
A3				Audi - Continued																																																																																																																																																																																																																																																																																																																																																																																																							
Sensor	20088	71	8	Service Pack; Does Not Include Valve ..	20023	35	4																																																																																																																																																																																																																																																																																																																																																																																																				
Service Pack	20017	71	8	Service Pack; W/43mm Silver Insert	20037	35	4																																																																																																																																																																																																																																																																																																																																																																																																				
A4				Service Pack; W/48mm Green Insert ...	20038	35	4																																																																																																																																																																																																																																																																																																																																																																																																				
Sensor; Includes Transmitter Only	20078	35	4	Service Pack; W/49mm Black Insert	20039	35	4																																																																																																																																																																																																																																																																																																																																																																																																				
Service Pack; Does Not Include Valve ..	20023	35	4	Service Pack; W/51mm Orange Insert ..	20040	35	4																																																																																																																																																																																																																																																																																																																																																																																																				
Service Pack; W/43mm Silver Insert	20037	35	4	2007 - Continued																																																																																																																																																																																																																																																																																																																																																																																																							
Service Pack; W/48mm Green Insert ...	20038	35	4	Service Pack; W/49mm Black Insert	20039	35	4	A8 - Continued				Service Pack; W/51mm Orange Insert ..	20040	35	4	Sensor; Includes Transmitter Only	20078	35	4	A5				Service Pack; Does Not Include Valve ..	20023	35	4	Sensor	20088	71	8	Service Pack; W/43mm Silver Insert	20037	35	4	Service Pack	20017	71	8	Service Pack; W/48mm Green Insert ...	20038	35	4	A6				Service Pack; W/49mm Black Insert	20039	35	4	Sensor; Includes Transmitter Only	20078	35	4	Service Pack; W/51mm Orange Insert ..	20040	35	4	Service Pack; Does Not Include Valve ..	20023	35	4	2006								Service Pack; W/43mm Silver Insert	20037	35	4	Service Pack; W/48mm Green Insert ...	20038	35	4	A4; A6				Service Pack; W/49mm Black Insert	20039	35	4	Sensor; Includes Transmitter Only	20078	35	4	Service Pack; W/51mm Orange Insert ..	20040	35	4	Service Pack; Does Not Include Valve ..	20023	35	4	Q7; R8; RS4; S4				Service Pack; W/43mm Silver Insert	20037	35	4	Sensor; Includes Transmitter Only	20078	35	4	Service Pack; W/48mm Green Insert ...	20038	35	4	Service Pack; Does Not Include Valve ..	20023	35	4	Service Pack; W/49mm Black Insert	20039	35	4	Service Pack; W/43mm Silver Insert	20037	35	4	Service Pack; W/51mm Orange Insert ..	20040	35	4	Service Pack; W/48mm Green Insert ...	20038	35	4	2005								Service Pack; W/49mm Black Insert	20039	35	4	Service Pack; W/51mm Orange Insert ..	20040	35	4	A8				S5				Sensor; Includes Transmitter Only	20077	35	4	Sensor	20088	71	8	Service Pack; Does Not Include Valve ..	20023	35	4	Service Pack	20017	71	8	Service Pack; W/43mm Silver Insert	20037	35	4	S6				Service Pack; W/48mm Green Insert ...	20038	35	4	Sensor; Includes Transmitter Only	20078	35	4	Service Pack; W/49mm Black Insert	20039	35	4	Service Pack; Does Not Include Valve ..	20023	35	4	Service Pack; W/51mm Orange Insert ..	20040	35	4	Service Pack; W/43mm Silver Insert	20037	35	4	2004								Service Pack; W/48mm Green Insert ...	20038	35	4	Service Pack; W/49mm Black Insert	20039	35	4	A4; A6				Service Pack; W/51mm Orange Insert ..	20040	35	4	Sensor; Includes Transmitter Only	20078	35	4	S8				Service Pack; Does Not Include Valve ..	20023	35	4	Sensor; Includes Transmitter Only	20077	35	4	Service Pack; W/43mm Silver Insert	20037	35	4	Service Pack; Does Not Include Valve ..	20023	35	4	Service Pack; W/48mm Green Insert ...	20038	35	4	Service Pack; W/43mm Silver Insert	20037	35	4	Service Pack; W/49mm Black Insert	20039	35	4	Service Pack; W/48mm Green Insert ...	20038	35	4	Service Pack; W/51mm Orange Insert ..	20040	35	4	Service Pack; W/49mm Black Insert	20039	35	4	2003								Service Pack; W/51mm Orange Insert ..	20040	35	4	TT				A8				Sensor	20088	71	8	Sensor; Includes Transmitter Only	20077	35	4	Service Pack	20017	71	8	Service Pack; Does Not Include Valve ..	20023	35	4	2007				Service Pack; W/43mm Silver Insert	20037	35	4	A4; A6				Service Pack; W/48mm Green Insert ...	20038	35	4	Sensor; Includes Transmitter Only	20078	35	4	Service Pack; W/49mm Black Insert	20039	35	4	Service Pack; Does Not Include Valve ..	20023	35	4	Service Pack; W/51mm Orange Insert ..	20040	35	4	Service Pack; W/43mm Silver Insert	20037	35	4	Allroad Quattro								Service Pack; W/48mm Green Insert ...	20038	35	4	Service Pack; W/49mm Black Insert	20039	35	4	Sensor; Includes Transmitter Only	20079	35	4	Service Pack; W/51mm Orange Insert ..	20040	35	4	Service Pack; Does Not Include Valve ..	20023	35	4	A8				Service Pack; W/43mm Silver Insert	20037	35	4	Sensor; Includes Transmitter Only	20077	35	4	Service Pack; W/48mm Green Insert ...	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4	A8 - Continued																																																																																																																																																																																																																																																																																																																																																																																																							
Service Pack; W/51mm Orange Insert ..	20040	35	4	Sensor; Includes Transmitter Only	20078	35	4																																																																																																																																																																																																																																																																																																																																																																																																				
A5				Service Pack; Does Not Include Valve ..	20023	35	4																																																																																																																																																																																																																																																																																																																																																																																																				
Sensor	20088	71	8	Service Pack; W/43mm Silver Insert	20037	35	4																																																																																																																																																																																																																																																																																																																																																																																																				
Service Pack	20017	71	8	Service Pack; W/48mm Green Insert ...	20038	35	4																																																																																																																																																																																																																																																																																																																																																																																																				
A6				Service Pack; W/49mm Black Insert	20039	35	4																																																																																																																																																																																																																																																																																																																																																																																																				
Sensor; Includes Transmitter Only	20078	35	4	Service Pack; W/51mm Orange Insert ..	20040	35	4																																																																																																																																																																																																																																																																																																																																																																																																				
Service Pack; Does Not Include Valve ..	20023	35	4	2006																																																																																																																																																																																																																																																																																																																																																																																																							
Service Pack; W/43mm Silver Insert	20037	35	4	Service Pack; W/48mm Green Insert ...	20038	35	4	A4; A6				Service Pack; W/49mm Black Insert	20039	35	4	Sensor; Includes Transmitter Only	20078	35	4	Service Pack; W/51mm Orange Insert ..	20040	35	4	Service Pack; Does Not Include Valve ..	20023	35	4	Q7; R8; RS4; S4				Service Pack; W/43mm Silver Insert	20037	35	4	Sensor; Includes Transmitter Only	20078	35	4	Service Pack; W/48mm Green Insert ...	20038	35	4	Service Pack; Does Not Include Valve ..	20023	35	4	Service Pack; W/49mm Black Insert	20039	35	4	Service Pack; W/43mm Silver Insert	20037	35	4	Service Pack; W/51mm Orange Insert ..	20040	35	4	Service Pack; W/48mm Green Insert ...	20038	35	4	2005								Service Pack; W/49mm Black Insert	20039	35	4	Service Pack; W/51mm Orange Insert ..	20040	35	4	A8				S5				Sensor; Includes Transmitter Only	20077	35	4	Sensor	20088	71	8	Service Pack; Does Not Include Valve ..	20023	35	4	Service Pack	20017	71	8	Service Pack; W/43mm Silver Insert	20037	35	4	S6				Service Pack; W/48mm Green Insert ...	20038	35	4	Sensor; Includes Transmitter Only	20078	35	4	Service Pack; W/49mm Black Insert	20039	35	4	Service Pack; Does Not Include Valve ..	20023	35	4	Service Pack; W/51mm Orange Insert ..	20040	35	4	Service Pack; W/43mm Silver Insert	20037	35	4	2004								Service Pack; W/48mm Green Insert ...	20038	35	4	Service Pack; W/49mm Black Insert	20039	35	4	A4; A6				Service Pack; W/51mm Orange Insert ..	20040	35	4	Sensor; Includes Transmitter Only	20078	35	4	S8				Service Pack; Does Not Include Valve ..	20023	35	4	Sensor; Includes Transmitter Only	20077	35	4	Service Pack; W/43mm Silver Insert	20037	35	4	Service Pack; Does Not Include Valve ..	20023	35	4	Service Pack; W/48mm Green Insert ...	20038	35	4	Service Pack; W/43mm Silver Insert	20037	35	4	Service Pack; W/49mm Black Insert	20039	35	4	Service Pack; W/48mm Green Insert ...	20038	35	4	Service Pack; W/51mm Orange Insert ..	20040	35	4	Service Pack; W/49mm Black Insert	20039	35	4	2003								Service Pack; W/51mm Orange Insert ..	20040	35	4	TT				A8				Sensor	20088	71	8	Sensor; Includes Transmitter Only	20077	35	4	Service Pack	20017	71	8	Service Pack; Does Not Include Valve ..	20023	35	4	2007				Service Pack; W/43mm Silver Insert	20037	35	4	A4; A6				Service Pack; W/48mm Green Insert ...	20038	35	4	Sensor; Includes Transmitter Only	20078	35	4	Service Pack; W/49mm Black Insert	20039	35	4	Service Pack; Does Not Include Valve ..	20023	35	4	Service Pack; W/51mm Orange Insert ..	20040	35	4	Service Pack; W/43mm Silver Insert	20037	35	4	Allroad Quattro								Service Pack; W/48mm Green Insert ...	20038	35	4	Service Pack; W/49mm Black Insert	20039	35	4	Sensor; Includes Transmitter Only	20079	35	4	Service Pack; W/51mm Orange Insert ..	20040	35	4	Service Pack; Does Not Include Valve ..	20023	35	4	A8				Service Pack; W/43mm Silver Insert	20037	35	4	Sensor; Includes Transmitter Only	20077	35	4	Service Pack; W/48mm Green Insert ...	20038	35	4																																																																								
Service Pack; W/48mm Green Insert ...	20038	35	4	A4; A6																																																																																																																																																																																																																																																																																																																																																																																																							
Service Pack; W/49mm Black Insert	20039	35	4	Sensor; Includes Transmitter Only	20078	35	4																																																																																																																																																																																																																																																																																																																																																																																																				
Service Pack; W/51mm Orange Insert ..	20040	35	4	Service Pack; Does Not Include Valve ..	20023	35	4																																																																																																																																																																																																																																																																																																																																																																																																				
Q7; R8; RS4; S4				Service Pack; W/43mm Silver Insert	20037	35	4																																																																																																																																																																																																																																																																																																																																																																																																				
Sensor; Includes Transmitter Only	20078	35	4	Service Pack; W/48mm Green Insert ...	20038	35	4																																																																																																																																																																																																																																																																																																																																																																																																				
Service Pack; Does Not Include Valve ..	20023	35	4	Service Pack; W/49mm Black Insert	20039	35	4																																																																																																																																																																																																																																																																																																																																																																																																				
Service Pack; W/43mm Silver Insert	20037	35	4	Service Pack; W/51mm Orange Insert ..	20040	35	4																																																																																																																																																																																																																																																																																																																																																																																																				
Service Pack; W/48mm Green Insert ...	20038	35	4	2005																																																																																																																																																																																																																																																																																																																																																																																																							
Service Pack; W/49mm Black Insert	20039	35	4	Service Pack; W/51mm Orange Insert ..	20040	35	4	A8				S5				Sensor; Includes Transmitter Only	20077	35	4	Sensor	20088	71	8	Service Pack; Does Not Include Valve ..	20023	35	4	Service Pack	20017	71	8	Service Pack; W/43mm Silver Insert	20037	35	4	S6				Service Pack; W/48mm Green Insert ...	20038	35	4	Sensor; Includes Transmitter Only	20078	35	4	Service Pack; W/49mm Black Insert	20039	35	4	Service Pack; Does Not Include Valve ..	20023	35	4	Service Pack; W/51mm Orange Insert ..	20040	35	4	Service Pack; W/43mm Silver Insert	20037	35	4	2004								Service Pack; W/48mm Green Insert ...	20038	35	4	Service Pack; W/49mm Black Insert	20039	35	4	A4; A6				Service Pack; W/51mm Orange Insert ..	20040	35	4	Sensor; Includes Transmitter Only	20078	35	4	S8				Service Pack; Does Not Include Valve ..	20023	35	4	Sensor; Includes Transmitter Only	20077	35	4	Service Pack; W/43mm Silver Insert	20037	35	4	Service Pack; Does Not Include Valve ..	20023	35	4	Service Pack; W/48mm Green Insert ...	20038	35	4	Service Pack; W/43mm Silver Insert	20037	35	4	Service Pack; W/49mm Black Insert	20039	35	4	Service Pack; W/48mm Green Insert ...	20038	35	4	Service Pack; W/51mm Orange Insert ..	20040	35	4	Service Pack; W/49mm Black Insert	20039	35	4	2003								Service Pack; W/51mm Orange Insert ..	20040	35	4	TT				A8				Sensor	20088	71	8	Sensor; Includes Transmitter Only	20077	35	4	Service Pack	20017	71	8	Service Pack; Does Not Include Valve ..	20023	35	4	2007				Service Pack; W/43mm Silver Insert	20037	35	4	A4; A6				Service Pack; W/48mm Green Insert ...	20038	35	4	Sensor; Includes Transmitter Only	20078	35	4	Service Pack; W/49mm Black Insert	20039	35	4	Service Pack; Does Not Include Valve ..	20023	35	4	Service Pack; W/51mm Orange Insert ..	20040	35	4	Service Pack; W/43mm Silver Insert	20037	35	4	Allroad Quattro								Service Pack; W/48mm Green Insert ...	20038	35	4	Service Pack; W/49mm Black Insert	20039	35	4	Sensor; Includes Transmitter Only	20079	35	4	Service Pack; W/51mm Orange Insert ..	20040	35	4	Service Pack; Does Not Include Valve ..	20023	35	4	A8				Service Pack; W/43mm Silver Insert	20037	35	4	Sensor; Includes Transmitter Only	20077	35	4	Service Pack; W/48mm Green Insert ...	20038	35	4																																																																																																																																																
Service Pack; W/51mm Orange Insert ..	20040	35	4	A8																																																																																																																																																																																																																																																																																																																																																																																																							
S5				Sensor; Includes Transmitter Only	20077	35	4																																																																																																																																																																																																																																																																																																																																																																																																				
Sensor	20088	71	8	Service Pack; Does Not Include Valve ..	20023	35	4																																																																																																																																																																																																																																																																																																																																																																																																				
Service Pack	20017	71	8	Service Pack; W/43mm Silver Insert	20037	35	4																																																																																																																																																																																																																																																																																																																																																																																																				
S6				Service Pack; W/48mm Green Insert ...	20038	35	4																																																																																																																																																																																																																																																																																																																																																																																																				
Sensor; Includes Transmitter Only	20078	35	4	Service Pack; W/49mm Black Insert	20039	35	4																																																																																																																																																																																																																																																																																																																																																																																																				
Service Pack; Does Not Include Valve ..	20023	35	4	Service Pack; W/51mm Orange Insert ..	20040	35	4																																																																																																																																																																																																																																																																																																																																																																																																				
Service Pack; W/43mm Silver Insert	20037	35	4	2004																																																																																																																																																																																																																																																																																																																																																																																																							
Service Pack; W/48mm Green Insert ...	20038	35	4	Service Pack; W/49mm Black Insert	20039	35	4	A4; A6				Service Pack; W/51mm Orange Insert ..	20040	35	4	Sensor; Includes Transmitter Only	20078	35	4	S8				Service Pack; Does Not Include Valve ..	20023	35	4	Sensor; Includes Transmitter Only	20077	35	4	Service Pack; W/43mm Silver Insert	20037	35	4	Service Pack; Does Not Include Valve ..	20023	35	4	Service Pack; W/48mm Green Insert ...	20038	35	4	Service Pack; W/43mm Silver Insert	20037	35	4	Service Pack; W/49mm Black Insert	20039	35	4	Service Pack; W/48mm Green Insert ...	20038	35	4	Service Pack; W/51mm Orange Insert ..	20040	35	4	Service Pack; W/49mm Black Insert	20039	35	4	2003								Service Pack; W/51mm Orange Insert ..	20040	35	4	TT				A8				Sensor	20088	71	8	Sensor; Includes Transmitter Only	20077	35	4	Service Pack	20017	71	8	Service Pack; Does Not Include Valve ..	20023	35	4	2007				Service Pack; W/43mm Silver Insert	20037	35	4	A4; A6				Service Pack; W/48mm Green Insert ...	20038	35	4	Sensor; Includes Transmitter Only	20078	35	4	Service Pack; W/49mm Black Insert	20039	35	4	Service Pack; Does Not Include Valve ..	20023	35	4	Service Pack; W/51mm Orange Insert ..	20040	35	4	Service Pack; W/43mm Silver Insert	20037	35	4	Allroad Quattro								Service Pack; W/48mm Green Insert ...	20038	35	4	Service Pack; W/49mm Black Insert	20039	35	4	Sensor; Includes Transmitter Only	20079	35	4	Service Pack; W/51mm Orange Insert ..	20040	35	4	Service Pack; Does Not Include Valve ..	20023	35	4	A8				Service Pack; W/43mm Silver Insert	20037	35	4	Sensor; Includes Transmitter Only	20077	35	4	Service Pack; W/48mm Green Insert ...	20038	35	4																																																																																																																																																																																																																								
Service Pack; W/49mm Black Insert	20039	35	4	A4; A6																																																																																																																																																																																																																																																																																																																																																																																																							
Service Pack; W/51mm Orange Insert ..	20040	35	4	Sensor; Includes Transmitter Only	20078	35	4																																																																																																																																																																																																																																																																																																																																																																																																				
S8				Service Pack; Does Not Include Valve ..	20023	35	4																																																																																																																																																																																																																																																																																																																																																																																																				
Sensor; Includes Transmitter Only	20077	35	4	Service Pack; W/43mm Silver Insert	20037	35	4																																																																																																																																																																																																																																																																																																																																																																																																				
Service Pack; Does Not Include Valve ..	20023	35	4	Service Pack; W/48mm Green Insert ...	20038	35	4																																																																																																																																																																																																																																																																																																																																																																																																				
Service Pack; W/43mm Silver Insert	20037	35	4	Service Pack; W/49mm Black Insert	20039	35	4																																																																																																																																																																																																																																																																																																																																																																																																				
Service Pack; W/48mm Green Insert ...	20038	35	4	Service Pack; W/51mm Orange Insert ..	20040	35	4																																																																																																																																																																																																																																																																																																																																																																																																				
Service Pack; W/49mm Black Insert	20039	35	4	2003																																																																																																																																																																																																																																																																																																																																																																																																							
Service Pack; W/51mm Orange Insert ..	20040	35	4	TT				A8				Sensor	20088	71	8	Sensor; Includes Transmitter Only	20077	35	4	Service Pack	20017	71	8	Service Pack; Does Not Include Valve ..	20023	35	4	2007				Service Pack; W/43mm Silver Insert	20037	35	4	A4; A6				Service Pack; W/48mm Green Insert ...	20038	35	4	Sensor; Includes Transmitter Only	20078	35	4	Service Pack; W/49mm Black Insert	20039	35	4	Service Pack; Does Not Include Valve ..	20023	35	4	Service Pack; W/51mm Orange Insert ..	20040	35	4	Service Pack; W/43mm Silver Insert	20037	35	4	Allroad Quattro								Service Pack; W/48mm Green Insert ...	20038	35	4	Service Pack; W/49mm Black Insert	20039	35	4	Sensor; Includes Transmitter Only	20079	35	4	Service Pack; W/51mm Orange Insert ..	20040	35	4	Service Pack; Does Not Include Valve ..	20023	35	4	A8				Service Pack; W/43mm Silver Insert	20037	35	4	Sensor; Includes Transmitter Only	20077	35	4	Service Pack; W/48mm Green Insert ...	20038	35	4																																																																																																																																																																																																																																																																																																
TT				A8																																																																																																																																																																																																																																																																																																																																																																																																							
Sensor	20088	71	8	Sensor; Includes Transmitter Only	20077	35	4																																																																																																																																																																																																																																																																																																																																																																																																				
Service Pack	20017	71	8	Service Pack; Does Not Include Valve ..	20023	35	4																																																																																																																																																																																																																																																																																																																																																																																																				
2007				Service Pack; W/43mm Silver Insert	20037	35	4																																																																																																																																																																																																																																																																																																																																																																																																				
A4; A6				Service Pack; W/48mm Green Insert ...	20038	35	4																																																																																																																																																																																																																																																																																																																																																																																																				
Sensor; Includes Transmitter Only	20078	35	4	Service Pack; W/49mm Black Insert	20039	35	4																																																																																																																																																																																																																																																																																																																																																																																																				
Service Pack; Does Not Include Valve ..	20023	35	4	Service Pack; W/51mm Orange Insert ..	20040	35	4																																																																																																																																																																																																																																																																																																																																																																																																				
Service Pack; W/43mm Silver Insert	20037	35	4	Allroad Quattro																																																																																																																																																																																																																																																																																																																																																																																																							
Service Pack; W/48mm Green Insert ...	20038	35	4	Service Pack; W/49mm Black Insert	20039	35	4	Sensor; Includes Transmitter Only	20079	35	4	Service Pack; W/51mm Orange Insert ..	20040	35	4	Service Pack; Does Not Include Valve ..	20023	35	4	A8				Service Pack; W/43mm Silver Insert	20037	35	4	Sensor; Includes Transmitter Only	20077	35	4	Service Pack; W/48mm Green Insert ...	20038	35	4																																																																																																																																																																																																																																																																																																																																																																								
Service Pack; W/49mm Black Insert	20039	35	4	Sensor; Includes Transmitter Only	20079	35	4																																																																																																																																																																																																																																																																																																																																																																																																				
Service Pack; W/51mm Orange Insert ..	20040	35	4	Service Pack; Does Not Include Valve ..	20023	35	4																																																																																																																																																																																																																																																																																																																																																																																																				
A8				Service Pack; W/43mm Silver Insert	20037	35	4																																																																																																																																																																																																																																																																																																																																																																																																				
Sensor; Includes Transmitter Only	20077	35	4	Service Pack; W/48mm Green Insert ...	20038	35	4																																																																																																																																																																																																																																																																																																																																																																																																				



Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
Audi - Continued							
2005 - Continued							
S4							
Sensor; Includes Transmitter Only	20078	35	4	Sensor; Includes Transmitter Only; Chassis No. 4D3004999 & Before	20079	35	4
Service Pack; Does Not Include Valve .	20023	35	4	Service Pack; Does Not Include Valve .	20023	35	4
Service Pack; W/43mm Silver Insert	20037	35	4	Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert ...	20038	35	4	Service Pack; W/48mm Green Insert ...	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4	Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert .	20040	35	4	Service Pack; W/51mm Orange Insert .	20040	35	4
2004							
A4							
Sensor; Includes Transmitter Only	20078	35	4	Sensor; Includes Transmitter Only	20078	35	4
Service Pack; Does Not Include Valve .	20023	35	4	Service Pack; Does Not Include Valve .	20023	35	4
Service Pack; W/43mm Silver Insert	20037	35	4	Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/48mm Green Insert ...	20038	35	4	Service Pack; W/48mm Green Insert ...	20038	35	4
Service Pack; W/49mm Black Insert	20039	35	4	Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/51mm Orange Insert .	20040	35	4	Service Pack; W/51mm Orange Insert .	20040	35	4
A8							
Sensor; Includes Transmitter Only	20077	35	4	A8; Allroad Quattro; S8			
Service Pack; Does Not Include Valve .	20023	35	4	Sensor; Includes Transmitter Only	20079	35	4
Service Pack; W/43mm Silver Insert	20037	35	4	Service Pack; Does Not Include Valve .	20023	35	4
Service Pack; W/48mm Green Insert ...	20038	35	4	Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/49mm Black Insert	20039	35	4	Service Pack; W/48mm Green Insert ...	20038	35	4
Service Pack; W/51mm Orange Insert .	20040	35	4	Service Pack; W/49mm Black Insert	20039	35	4
Allroad Quattro							
Sensor; Includes Transmitter Only	20079	35	4	Service Pack; W/51mm Orange Insert .	20040	35	4
Service Pack; Does Not Include Valve .	20023	35	4	2001			
Service Pack; W/43mm Silver Insert	20037	35	4	A8; Allroad Quattro; S8			
Service Pack; W/48mm Green Insert ...	20038	35	4	Sensor; Includes Transmitter Only	20079	35	4
Service Pack; W/49mm Black Insert	20039	35	4	Service Pack; Does Not Include Valve .	20023	35	4
Service Pack; W/51mm Orange Insert .	20040	35	4	Service Pack; W/43mm Silver Insert	20037	35	4
S4				Service Pack; W/48mm Green Insert ...	20038	35	4
Sensor; Includes Transmitter Only	20078	35	4	Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; Does Not Include Valve .	20023	35	4	Service Pack; W/51mm Orange Insert .	20040	35	4
Service Pack; W/43mm Silver Insert	20037	35	4	Bentley			
Service Pack; W/48mm Green Insert ...	20038	35	4	2010-2006			
Service Pack; W/49mm Black Insert	20039	35	4	Continental			
Service Pack; W/51mm Orange Insert .	20040	35	4	Sensor; Includes Transmitter Only	20078	35	4
2003				Service Pack; Does Not Include Valve .	20023	35	4
A4				Service Pack; W/43mm Silver Insert	20037	35	4
Sensor; Includes Transmitter Only	20078	35	4	Service Pack; W/48mm Green Insert ...	20038	35	4
Service Pack; Does Not Include Valve .	20023	35	4	Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/43mm Silver Insert	20037	35	4	Service Pack; W/51mm Orange Insert .	20040	35	4
Service Pack; W/48mm Green Insert ...	20038	35	4	2005-2003			
Service Pack; W/49mm Black Insert	20039	35	4	Continental			
Service Pack; W/51mm Orange Insert .	20040	35	4	Sensor; Includes Transmitter Only	20077	35	4
A8				Service Pack; Does Not Include Valve .	20023	35	4
Sensor; Includes Transmitter Only; Chassis No. 4E3000001 & After	20077	35	4	Service Pack; W/43mm Silver Insert	20037	35	4
Sensor; Includes Transmitter Only; Chassis No. 4D3004999 & Before	20079	35	4	Service Pack; W/48mm Green Insert ...	20038	35	4
Service Pack; Does Not Include Valve .	20023	35	4	Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/43mm Silver Insert	20037	35	4	Service Pack; W/51mm Orange Insert .	20040	35	4
Service Pack; W/48mm Green Insert ...	20038	35	4	BMW			
Service Pack; W/49mm Black Insert	20039	35	4	2012			
Service Pack; W/51mm Orange Insert .	20040	35	4	128I; 135I; 328I; 335D; 335I; 528I; 535I; 550I; 640I; 650I; 740I; 740LI; 750I; 750LI; M1; X1; X3; X5; X6; Z4			
Allroad Quattro				Sensor; Includes Transmitter Only	28081	31	3.5
Sensor; Includes Transmitter Only	20079	35	4	Service Pack; Does Not Include Valve .	20023	31	3.5
Service Pack; Does Not Include Valve .	20023	35	4	Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/43mm Silver Insert	20037	35	4	Service Pack; W/48mm Green Insert ...	20038	31	3.5
Service Pack; W/48mm Green Insert ...	20038	35	4	Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/49mm Black Insert	20039	35	4	Service Pack; W/51mm Orange Insert .	20040	31	3.5
Service Pack; W/51mm Orange Insert .	20040	35	4	2011			
S8				128I			
Sensor; Includes Transmitter Only; Chassis No. 4E3000001 & After	20077	35	4	Sensor; Includes Transmitter Only	20083	31	3.5



Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
BMW - Continued				BMW - Continued			
2011 - Continued				2010 - Continued			
128I - Continued				528I; 535I; 550I; 650I; 750I; 750LI; 760LI			
Service Pack; W/43mm Silver Insert	20037	31	3.5	Sensor; Includes Transmitter Only	20083	31	3.5
Service Pack; W/48mm Green Insert ...	20038	31	3.5	Service Pack; Does Not Include Valve .	20023	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5	Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/51mm Orange Insert .	20040	31	3.5	Service Pack; W/48mm Green Insert ...	20038	31	3.5
328I; 335D; 335I				Service Pack; W/49mm Black Insert	20039	31	3.5
Sensor; Includes Transmitter Only	28081	31	3.5	Service Pack; W/51mm Orange Insert .	20040	31	3.5
Service Pack; Does Not Include Valve .	20023	31	3.5	M3			
Service Pack; W/43mm Silver Insert	20037	31	3.5	Sensor; Includes Transmitter Only	28081	31	3.5
Service Pack; W/48mm Green Insert ...	20038	31	3.5	Service Pack; Does Not Include Valve .	20023	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5	Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/51mm Orange Insert .	20040	31	3.5	Service Pack; W/48mm Green Insert ...	20038	31	3.5
528I				Service Pack; W/49mm Black Insert	20039	31	3.5
Sensor; Includes Transmitter Only	20083	31	3.5	Service Pack; W/51mm Orange Insert .	20040	31	3.5
535I; 550I; 740I; 740LI; 750I; 750LI				M5; M6			
Sensor; Includes Transmitter Only	20083	31	3.5	Sensor; Includes Transmitter Only	20083	31	3.5
Service Pack; Does Not Include Valve .	20023	31	3.5	Service Pack; Does Not Include Valve .	20023	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5	Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/48mm Green Insert ...	20038	31	3.5	Service Pack; W/48mm Green Insert ...	20038	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5	Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; W/51mm Orange Insert .	20040	31	3.5	Service Pack; W/51mm Orange Insert .	20040	31	3.5
760LI				X3; X5; X6			
Sensor; Includes Transmitter Only	20083	31	3.5	Sensor; Includes Transmitter Only	20083	35	4
Alpina B7				Service Pack; Does Not Include Valve .	20023	35	4
Sensor; Includes Transmitter Only	20080	31	3.5	Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; Does Not Include Valve .	20023	31	3.5	Service Pack; W/48mm Green Insert ...	20038	35	4
Service Pack; W/43mm Silver Insert	20037	31	3.5	Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; W/48mm Green Insert ...	20038	31	3.5	Service Pack; W/51mm Orange Insert .	20040	35	4
Service Pack; W/49mm Black Insert	20039	31	3.5	Z4			
Service Pack; W/51mm Orange Insert .	20040	31	3.5	Sensor; Includes Transmitter Only	20083	31	3.5
X3				Service Pack; Does Not Include Valve .	20023	31	3.5
Sensor; Includes Transmitter Only	20083	35	4	Service Pack; W/43mm Silver Insert	20037	31	3.5
X5				Service Pack; W/48mm Green Insert ...	20038	31	3.5
Sensor; Includes Transmitter Only	20083	35	4	Service Pack; W/49mm Black Insert	20039	31	3.5
Service Pack; Does Not Include Valve .	20023	35	4	Service Pack; W/51mm Orange Insert .	20040	31	3.5
Service Pack; W/43mm Silver Insert	20037	35	4	2009			
Service Pack; W/48mm Green Insert ...	20038	35	4	128I; 135I; 323I; 328I; 335D; 335I; 528I; 535I; 550I; 650I; 750I; 750LI; M3; M5; M6			
Service Pack; W/49mm Black Insert	20039	35	4	Sensor; Includes Transmitter Only	20083	31	3.5
Service Pack; W/51mm Orange Insert .	20040	35	4	Service Pack; Does Not Include Valve .	20023	31	3.5
X6				Service Pack; W/43mm Silver Insert	20037	31	3.5
Sensor; Includes Transmitter Only	20083	35	4	Service Pack; W/48mm Green Insert ...	20038	31	3.5
Z4				Service Pack; W/49mm Black Insert	20039	31	3.5
Sensor; Includes Transmitter Only	20083	31	3.5	Service Pack; W/51mm Orange Insert .	20040	31	3.5
Service Pack; Does Not Include Valve .	20023	31	3.5	X3; X5; X6			
Service Pack; W/43mm Silver Insert	20037	31	3.5	Sensor; Includes Transmitter Only	20083	35	4
Service Pack; W/48mm Green Insert ...	20038	31	3.5	Service Pack; Does Not Include Valve .	20023	35	4
Service Pack; W/49mm Black Insert	20039	31	3.5	Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; W/51mm Orange Insert .	20040	31	3.5	Service Pack; W/48mm Green Insert ...	20038	35	4
2010				Service Pack; W/49mm Black Insert	20039	35	4
128I; 135I; 323I				Service Pack; W/51mm Orange Insert .	20040	35	4
Sensor; Includes Transmitter Only	20083	31	3.5	Z4			
Service Pack; Does Not Include Valve .	20023	31	3.5	Sensor; Includes Transmitter Only	20083	31	3.5
Service Pack; W/43mm Silver Insert	20037	31	3.5	Service Pack; Does Not Include Valve .	20023	31	3.5
Service Pack; W/48mm Green Insert ...	20038	31	3.5	Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5	Service Pack; W/48mm Green Insert ...	20038	31	3.5
Service Pack; W/51mm Orange Insert .	20040	31	3.5	Service Pack; W/49mm Black Insert	20039	31	3.5
328I; 335D; 335I				Service Pack; W/51mm Orange Insert .	20040	31	3.5
Sensor; Includes Transmitter Only	28081	31	3.5	2008			
Service Pack; Does Not Include Valve .	20023	31	3.5	128I; 135I; 323I; 328I; 335XI; 335XI; 528I; 528XI; 535I; 535XI; 550I; 650I; 750I; 750LI; Alpina B7; M3; M5; M6			
Service Pack; W/43mm Silver Insert	20037	31	3.5	Sensor; Includes Transmitter Only	20083	31	3.5
Service Pack; W/48mm Green Insert ...	20038	31	3.5	Service Pack; Does Not Include Valve .	20023	31	3.5
Service Pack; W/49mm Black Insert	20039	31	3.5	Service Pack; W/43mm Silver Insert	20037	31	3.5
Service Pack; W/51mm Orange Insert .	20040	31	3.5	Service Pack; W/48mm Green Insert ...	20038	31	3.5



Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.				
BMW - Continued											
2008 - Continued											
128I; 135I; 323I; 328I; 328XI; 335I; 335XI; 528I; 528XI; 535I; 535XI; 550I; 650I; 750I; 750LI; 760LI; Alpina B7; M3; M5; M6 - Continued											
Service Pack; W/49mm Black Insert	20039	31	3.5	Sensor; Includes Transmitter Only	20083	31	3.5				
Service Pack; W/51mm Orange Insert ..	20040	31	3.5	Service Pack; Does Not Include Valve ..	20023	31	3.5				
X3; X5; X6											
Sensor; Includes Transmitter Only	20083	35	4	Service Pack; W/43mm Silver Insert	20037	31	3.5				
Service Pack; Does Not Include Valve ..	20023	35	4	Service Pack; W/48mm Green Insert	20038	31	3.5				
Service Pack; W/43mm Silver Insert	20037	35	4	Service Pack; W/49mm Black Insert	20039	31	3.5				
Service Pack; W/48mm Green Insert	20038	35	4	Service Pack; W/51mm Orange Insert ..	20040	31	3.5				
Service Pack; W/49mm Black Insert	20039	35	4	X3; X5							
Service Pack; W/51mm Orange Insert ..	20040	35	4	Sensor; Includes Transmitter Only	20083	35	4				
Z4											
Sensor; Includes Transmitter Only	20083	31	3.5	Service Pack; Does Not Include Valve ..	20023	35	4				
Service Pack; Does Not Include Valve ..	20023	31	3.5	Service Pack; W/43mm Silver Insert	20037	35	4				
Service Pack; W/43mm Silver Insert	20037	31	3.5	Service Pack; W/48mm Green Insert	20038	35	4				
Service Pack; W/48mm Green Insert	20038	31	3.5	Service Pack; W/49mm Black Insert	20039	35	4				
Service Pack; W/49mm Black Insert	20039	31	3.5	Service Pack; W/51mm Orange Insert ..	20040	35	4				
Service Pack; W/51mm Orange Insert ..	20040	31	3.5	Z4							
2007											
323I; 328I; 328XI; 335I; 335XI; 525I; 525XI; 530I; 530XI; 550I; 650I; 750I; 750LI; 760LI; Alpina B7; M5; M6											
Sensor; Includes Transmitter Only	20083	31	3.5	Sensor; Includes Transmitter Only	20083	31	3.5				
Service Pack; Does Not Include Valve ..	20023	31	3.5	Service Pack; Does Not Include Valve ..	20023	31	3.5				
Service Pack; W/43mm Silver Insert	20037	31	3.5	Service Pack; W/43mm Silver Insert	20037	31	3.5				
Service Pack; W/48mm Green Insert	20038	31	3.5	Service Pack; W/48mm Green Insert	20038	31	3.5				
Service Pack; W/49mm Black Insert	20039	31	3.5	Service Pack; W/49mm Black Insert	20039	31	3.5				
Service Pack; W/51mm Orange Insert ..	20040	31	3.5	Service Pack; W/51mm Orange Insert ..	20040	31	3.5				
X3; X5											
Sensor; Includes Transmitter Only	20083	35	4	Sensor; Includes Transmitter Only	20080	31	3.5				
Service Pack; Does Not Include Valve ..	20023	35	4	Service Pack; Does Not Include Valve ..	20023	31	3.5				
Service Pack; W/43mm Silver Insert	20037	35	4	Service Pack; W/43mm Silver Insert	20037	31	3.5				
Service Pack; W/48mm Green Insert	20038	35	4	Service Pack; W/48mm Green Insert	20038	31	3.5				
Service Pack; W/49mm Black Insert	20039	35	4	Service Pack; W/49mm Black Insert	20039	31	3.5				
Service Pack; W/51mm Orange Insert ..	20040	35	4	Service Pack; W/51mm Orange Insert ..	20040	31	3.5				
Z4											
Sensor; Includes Transmitter Only	20083	31	3.5	Sensor; Includes Transmitter Only	20083	31	3.5				
Service Pack; Does Not Include Valve ..	20023	31	3.5	Service Pack; Does Not Include Valve ..	20023	31	3.5				
Service Pack; W/43mm Silver Insert	20037	31	3.5	Service Pack; W/43mm Silver Insert	20037	31	3.5				
Service Pack; W/48mm Green Insert	20038	31	3.5	Service Pack; W/48mm Green Insert	20038	31	3.5				
Service Pack; W/49mm Black Insert	20039	31	3.5	Service Pack; W/49mm Black Insert	20039	31	3.5				
Service Pack; W/51mm Orange Insert ..	20040	31	3.5	Service Pack; W/51mm Orange Insert ..	20040	31	3.5				
2006											
323I											
Sensor; Includes Transmitter Only; Jun. & Newer	20083	31	3.5	Sensor; Includes Transmitter Only	20083	35	4				
Service Pack; Does Not Include Valve; Jun. & Newer	20023	31	3.5	Service Pack; Does Not Include Valve ..	20023	35	4				
Service Pack; W/43mm Silver Insert; Jun. & Newer	20037	31	3.5	Service Pack; W/43mm Silver Insert	20037	35	4				
Service Pack; W/48mm Green Insert; Jun. & Newer	20038	31	3.5	Service Pack; W/48mm Green Insert	20038	35	4				
Service Pack; W/49mm Black Insert; Jun. & Newer	20039	31	3.5	Service Pack; W/49mm Black Insert	20039	35	4				
Service Pack; W/51mm Orange Insert; Jun. & Newer	20040	31	3.5	Service Pack; W/51mm Orange Insert	20040	35	4				
325CI; 325I; 325XI; 330CI; 330I; 330XI											
Sensor; Includes Transmitter Only	20080	31	3.5	Sensor; Includes Transmitter Only	20083	31	3.5				
Service Pack; Does Not Include Valve ..	20023	31	3.5	Service Pack; Does Not Include Valve ..	20023	31	3.5				
Service Pack; W/43mm Silver Insert	20037	31	3.5	Service Pack; W/43mm Silver Insert	20037	31	3.5				
Service Pack; W/48mm Green Insert	20038	31	3.5	Service Pack; W/48mm Green Insert	20038	31	3.5				
Service Pack; W/49mm Black Insert	20039	31	3.5	Service Pack; W/49mm Black Insert	20039	31	3.5				
Service Pack; W/51mm Orange Insert ..	20040	31	3.5	Service Pack; W/51mm Orange Insert	20040	31	3.5				
2004											
320I; 325CI; 325I; 325XI; 330CI; 330I; 330XI; 525I; 530I; 545I; 645CI; 745I; 745LI; 760I											
Sensor; Includes Transmitter Only	20080	31	3.5	Sensor; Includes Transmitter Only	20080	31	3.5				
Service Pack; Does Not Include Valve ..	20023	31	3.5	Service Pack; Does Not Include Valve ..	20023	31	3.5				
Service Pack; W/43mm Silver Insert	20037	31	3.5	Service Pack; W/43mm Silver Insert	20037	31	3.5				
Service Pack; W/48mm Green Insert	20038	31	3.5	Service Pack; W/48mm Green Insert	20038	31	3.5				
Service Pack; W/49mm Black Insert	20039	31	3.5	Service Pack; W/49mm Black Insert	20039	31	3.5				
Service Pack; W/51mm Orange Insert ..	20040	31	3.5	Service Pack; W/51mm Orange Insert	20040	31	3.5				
760LI; M3											
Sensor; Includes Transmitter Only	20083	31	3.5	Sensor; Includes Transmitter Only	20083	31	3.5				
Service Pack; Does Not Include Valve ..	20023	31	3.5	Service Pack; Does Not Include Valve ..	20023	31	3.5				
Service Pack; W/43mm Silver Insert	20037	31	3.5	Service Pack; W/43mm Silver Insert	20037	31	3.5				



Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks



Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.				
BMW - Continued											
2000 - Continued											
X5 - Continued											
Service Pack; W/48mm Green Insert ...	20038	35	4	Service Pack	20008	11.5	1.3				
Service Pack; W/49mm Black Insert	20039	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3				
Service Pack; W/51mm Orange Insert .	20040	35	4	EZ-sensor Service Pack; Almnm. Valve	34000	62	7				
Z3; Z8											
Service Pack; Does Not Include Valve .	20023	31	3.5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Service Pack; W/43mm Silver Insert	20037	31	3.5	Sensor	28206	11.5	1.3				
Service Pack; W/48mm Green Insert ...	20038	31	3.5	Service Pack	20008	11.5	1.3				
Service Pack; W/49mm Black Insert	20039	31	3.5	2010							
Service Pack; W/51mm Orange Insert .	20040	31	3.5	Allure							
1999-1997											
528i; 540i; 740i; 740iL; 750iL											
Service Pack; Does Not Include Valve .	20023	31	3.5	EZ-sensor - 315 MHz	◇33000	11.5	1.3				
Service Pack; W/43mm Silver Insert	20037	31	3.5	EZ-sensor Service Pack; Almnm. Valve	34000	62	7				
Service Pack; W/48mm Green Insert ...	20038	31	3.5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Service Pack; W/49mm Black Insert	20039	31	3.5	Sensor	28206	11.5	1.3				
Service Pack; W/51mm Orange Insert .	20040	31	3.5	Service Pack	20008	11.5	1.3				
Bugatti											
2006											
Veyron											
Service Pack; Does Not Include Valve .	20023	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3				
Service Pack; W/43mm Silver Insert	20037	35	4	EZ-sensor Service Pack; Almnm. Valve	34000	62	7				
Service Pack; W/48mm Green Insert ...	20038	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Service Pack; W/49mm Black Insert	20039	35	4	Sensor	28206	11.5	1.3				
Service Pack; W/51mm Orange Insert .	20040	35	4	Service Pack	20008	11.5	1.3				
Buick											
2012											
Enclave; LaCrosse											
EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almnm. Valve	34000	62	7				
Sensor	20153	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Service Pack	20008	11.5	1.3	Sensor	20153	11.5	1.3				
Regal; Verano											
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack	20008	11.5	1.3				
EZ-sensor Service Pack; Almnm. Valve	34000	62	7	2009							
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Allure; Enclave; LaCrosse; Lucerne							
Sensor	28206	11.5	1.3	EZ-sensor - 315 MHz							
Service Pack	20008	11.5	1.3	EZ-sensor Service Pack; Almnm. Valve							
2011				EZ-sensor Service Pack; Rubber Valve							
Enclave				Sensor							
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack							
EZ-sensor Service Pack; Almnm. Valve	34000	62	7	EZ-sensor - 315 MHz							
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almnm. Valve							
Sensor	20153	11.5	1.3	EZ-sensor Service Pack; Rubber Valve							
Service Pack	20008	11.5	1.3	Service Pack							
LaCrosse				Sensor							
EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor - 315 MHz							
EZ-sensor Service Pack; Almnm. Valve	34000	62	7	EZ-sensor Service Pack; Almnm. Valve							
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve							
Sensor	28206	11.5	1.3	Service Pack							
Service Pack	20008	11.5	1.3	Service Pack							
Lucerne				Service Pack							
EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor - 315 MHz							
EZ-sensor Service Pack; Almnm. Valve	34000	62	7	EZ-sensor Service Pack; Almnm. Valve							
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve							
Sensor	20153	11.5	1.3	Sensor							
Service Pack	20008	11.5	1.3	Service Pack							
Regal				Service Pack							
EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor - 315 MHz							
EZ-sensor Service Pack; Almnm. Valve	34000	62	7	EZ-sensor Service Pack; Almnm. Valve							
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve							
Sensor	20153	11.5	1.3	Sensor							
Service Pack	20008	11.5	1.3	Service Pack							
2007				Service Pack							
Allure; LaCrosse				Service Pack							
EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor - 315 MHz							
EZ-sensor Service Pack; Almnm. Valve	34000	62	7	EZ-sensor Service Pack; Almnm. Valve							
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve							
Sensor	20158	62	7	Sensor							
Service Pack; W/Schrader Sensor	20004	62	7	Service Pack; W/Schrader Sensor							
Service Pack; W/Siemens Sensor	20030	80	9	Service Pack; W/Siemens Sensor							
Lucerne				Service Pack							
EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor - 315 MHz							
EZ-sensor Service Pack; Almnm. Valve	34000	62	7	EZ-sensor Service Pack; Almnm. Valve							
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve							
Sensor	20153	11.5	1.3	Sensor							
Service Pack	20008	11.5	1.3	Service Pack							

◊ Programming Tool Required.



PRINTED ON RECYCLED PAPER
WITH 100% POSTCONSUMER WASTE

Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.				
Buick - Continued											
2007 - Continued											
Rainier											
Sensor; OEM Part No. 25774006	20116	62	7	EZ-sensor - 315 MHz	◇33000	11.5	1.3				
Service Pack	20004	62	7	EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
2006											
Rainier											
Sensor; OEM Part No. 25774006	20116	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Service Pack	20004	62	7	Sensor; OEM Part No. 25920615; Exc. CTS V	20153	11.5	1.3				
Cadillac											
2012											
CTS											
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor; OEM Part No. 15268606; CTS V; W/315 MHz Sensor	20158	62	7				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Service Pack; OEM Part No. 25920615; Exc. CTS V	20008	11.5	1.3				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack; OEM Part No. 15268606; CTS V; W/315 MHz Sensor	20004	62	7				
Sensor; OEM Part No. 25920615; Exc. CTS V	20153	11.5	1.3	DTS; Escalade; SRX							
Sensor; OEM Part No. 15268606; CTS V; W/315 MHz Sensor	20158	62	7	EZ-sensor - 315 MHz	◇33000	11.5	1.3				
Service Pack; OEM Part No. 25920615; Exc. CTS V	20008	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
Service Pack; OEM Part No. 15268606; CTS V; W/315 MHz Sensor	20004	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Escalade											
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor	20153	11.5	1.3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Service Pack	20008	11.5	1.3				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	STS							
Sensor	20153	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3				
Service Pack	20008	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
SRX				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor; OEM Part No. 25920615; Exc. STS V	20153	11.5	1.3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Service Pack; OEM Part No. 25920615; Exc. STS V	20008	11.5	1.3				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	XLR							
Sensor	28206	11.5	1.3	Sensor; OEM Part No. 25758220	20076	62	7				
Service Pack	20008	11.5	1.3	Service Pack	20004	62	7				
2011-2010											
CTS											
EZ-sensor - 315 MHz	◇33000	11.5	1.3	2008							
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	CTS; DTS; Escalade; SRX							
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3				
Sensor; OEM Part No. 25920615; Exc. CTS V	20153	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
Sensor; OEM Part No. 15268606; CTS V; W/315 MHz Sensor	20158	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Service Pack; OEM Part No. 25920615; Exc. CTS V	20008	11.5	1.3	Sensor	20153	11.5	1.3				
Service Pack; OEM Part No. 15268606; CTS V; W/315 MHz Sensor	20004	62	7	Service Pack	20008	11.5	1.3				
DTS; Escalade											
EZ-sensor - 315 MHz	◇33000	11.5	1.3	2007							
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	CTS							
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; OEM Part No. 25774006	20116	62	7				
Sensor	20153	11.5	1.3	Service Pack	20004	62	7				
Service Pack	20008	11.5	1.3	DTS							
EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	20153	11.5	1.3	Sensor	20153	11.5	1.3				
Service Pack	20008	11.5	1.3	Service Pack	20008	11.5	1.3				
SRX											
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Escalade							
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
Sensor	28206	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Service Pack	20008	11.5	1.3	Sensor; Clamp-In Style Only; TRW Sensor; W/Almmn. Valve Stem	20158	62	7				
STS				Sensor; Snap-In Style Only; Schrader Sensor; W/Rubber Valve Stem	20153	11.5	1.3				
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack; Clamp-In Style Only; TRW Sensor; W/Almmn. Valve Stem	20015	80	9				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Service Pack; Snap-In Style Only; Schrader Sensor; W/Rubber Valve Stem	20008	11.5	1.3				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	SRX							
Sensor	20153	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3				
Service Pack	20008	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
SRX				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
EZ-sensor - 315 MHz	◇33000	11.5	1.3								
EZ-sensor Service Pack; Almmn. Valve	34000	62	7								
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3								
Sensor	20153	11.5	1.3								
Service Pack	20008	11.5	1.3								

◇ Programming Tool Required.



Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
Cadillac - Continued				Cadillac - Continued			
2007 - Continued				2003-2001			
SRX - Continued				Deville; Seville			
Sensor	20153	11.5	1.3	Sensor	●20117	62	7
Service Pack	20008	11.5	1.3	Service Pack	20003	62	7
STS; XLR				Chevrolet			
Sensor; OEM Part No. 25758220	20076	62	7	2012			
Service Pack	20004	62	7	Avalanche			
2006				EZ-sensor - 315 MHz	◊33000	11.5	1.3
CTS				EZ-sensor Service Pack; Almmn. Valve	34000	62	7
Sensor; OEM Part No. 25774006	20116	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Service Pack	20004	62	7	Sensor	20153	11.5	1.3
DTS				Service Pack	20008	11.5	1.3
EZ-sensor - 315 MHz	◊33000	11.5	1.3	Camaro			
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor - 315 MHz	◊33000	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7
Sensor	20158	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Service Pack	20004	62	7	Sensor	28206	11.5	1.3
Escalade				Service Pack	20008	11.5	1.3
Sensor	20107	62	7	Caprice			
Service Pack	20004	62	7	EZ-sensor - 315 MHz	◊33000	11.5	1.3
SRX				EZ-sensor Service Pack; Almmn. Valve	34000	62	7
Sensor; OEM Part No. 25774006	20116	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Service Pack	20004	62	7	Sensor	20158	62	7
STS; XLR				Service Pack	20004	62	7
Sensor; OEM Part No. 25758220	20076	62	7	Captiva			
Service Pack	20004	62	7	EZ-sensor - 315 MHz	◊33000	11.5	1.3
2005				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
CTS				Sensor	20153	11.5	1.3
Sensor	20116	62	7	Service Pack	20008	11.5	1.3
Service Pack	20004	62	7	Colorado			
Deville				Sensor	20131	62	7
Sensor	●20117	62	7	Service Pack	20006	62	7
Service Pack	20003	62	7	Corvette			
Escalade				EZ-sensor - 315 MHz	◊33000	11.5	1.3
Sensor	20107	62	7	EZ-sensor Service Pack; Almmn. Valve	34000	62	7
Service Pack	20004	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
SRX				Sensor	20158	62	7
Sensor	20116	62	7	Service Pack	20004	62	7
Service Pack	20004	62	7	Cruze; Equinox			
STS; XLR				EZ-sensor - 315 MHz	◊33000	11.5	1.3
Sensor; OEM Part No. 25758220	20076	62	7	EZ-sensor Service Pack; Almmn. Valve	34000	62	7
Service Pack	20004	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
2004				Sensor	28206	11.5	1.3
CTS				Service Pack	20008	11.5	1.3
Sensor	20116	62	7	Express; Impala; Malibu			
Service Pack	20004	62	7	EZ-sensor - 315 MHz	◊33000	11.5	1.3
Deville				EZ-sensor Service Pack; Almmn. Valve	34000	62	7
Sensor	●20117	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Service Pack	20003	62	7	Sensor	20153	11.5	1.3
Escalade				Service Pack	20008	11.5	1.3
Sensor	20115	62	7	Orlando			
Service Pack	20004	62	7	EZ-sensor - 315 MHz	◊33000	11.5	1.3
Seville				EZ-sensor Service Pack; Almmn. Valve	34000	62	7
Sensor	●20117	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Service Pack	20003	62	7	Sensor	28206	11.5	1.3
SRX				Service Pack	20008	11.5	1.3
Sensor	20116	62	7	Silverado Series Pickup			
Service Pack	20004	62	7	EZ-sensor - 315 MHz	◊33000	11.5	1.3
XLR				EZ-sensor Service Pack; Almmn. Valve	34000	62	7
Sensor; OEM Part No. 25758220	20076	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Service Pack	20004	62	7	Sensor; W/Single Rear Wheels	20153	11.5	1.3
				Service Pack; W/Single Rear Wheels ...	20008	11.5	1.3
Sonic				Sonic			
				EZ-sensor - 315 MHz	◊33000	11.5	1.3

◊ Programming Tool Required.

● Magnet Required to Activate Sensor.



PRINTED ON RECYCLED PAPER
WITH 100% POSTCONSUMER WASTE

Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
Chevrolet - Continued				Chevrolet - Continued			
2012 - Continued				2011 - Continued			
Sonic - Continued							
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Service Pack	20008	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3
Sensor	28206	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7
Service Pack	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Suburban				Sensor; W/Single Rear Wheels	20153	11.5	1.3
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack; W/Single Rear Wheels ...	20008	11.5	1.3
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Suburban; Tahoe; Traverse			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3
Sensor	20153	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7
Service Pack	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Tahoe; Traverse				Sensor	20153	11.5	1.3
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack	20008	11.5	1.3
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Volt			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3
Sensor	20153	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7
Service Pack	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Volt				Sensor	28206	11.5	1.3
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack	20008	11.5	1.3
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	2010			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Avalanche; Aveo			
Sensor	20153	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3
Service Pack	20008	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7
2011				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Avalanche; Aveo				Sensor	20153	11.5	1.3
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack	20008	11.5	1.3
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Camaro; Cobalt			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3
Sensor	20153	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7
Service Pack	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Camaro				Sensor	28206	11.5	1.3
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack	20008	11.5	1.3
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Colorado			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor	20131	62	7
Sensor	28206	11.5	1.3	Service Pack	20006	62	7
Service Pack	20008	11.5	1.3	Corvette			
Caprice				EZ-sensor - 315 MHz	◇33000	11.5	1.3
EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor	20158	62	7
Sensor	20158	62	7	Service Pack	20004	62	7
Service Pack	20004	62	7	Equinox			
Colorado				EZ-sensor - 315 MHz	◇33000	11.5	1.3
Sensor	20131	62	7	EZ-sensor Service Pack; Almmn. Valve	34000	62	7
Service Pack	20006	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Corvette				Sensor	28206	11.5	1.3
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack	20008	11.5	1.3
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Express			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3
Sensor	20158	62	7	EZ-sensor Service Pack; Almmn. Valve	34000	62	7
Service Pack	20004	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Cruze; Equinox				Sensor	20153	11.5	1.3
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack	20008	11.5	1.3
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	HHR			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3
Sensor	20158	62	7	EZ-sensor Service Pack; Almmn. Valve	34000	62	7
Service Pack	20004	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Corvette				Sensor	28206	11.5	1.3
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack	20008	11.5	1.3
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Impala			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3
Sensor	20158	62	7	EZ-sensor Service Pack; Almmn. Valve	34000	62	7
Service Pack	20004	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Caprice				Sensor	28206	11.5	1.3
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack	20008	11.5	1.3
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Express; HHR; Impala; Malibu			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3
Sensor	20158	62	7	EZ-sensor Service Pack; Almmn. Valve	34000	62	7
Service Pack	20004	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3

◊ Programming Tool Required.



Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
Chevrolet - Continued				Chevrolet - Continued			
2010 - Continued				2009 - Continued			
Impala - Continued				Impala; Malibu			
Sensor	20153	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3
Service Pack	20008	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7
Malibu				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor	20153	11.5	1.3
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Service Pack	20008	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Silverado Series Pickup			
Sensor	28206	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3
Service Pack	20008	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7
Silverado Series Pickup				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor; W/Single Rear Wheels	20153	11.5	1.3
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Service Pack; W/Single Rear Wheels ...	20008	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Suburban; Tahoe			
Sensor; W/Single Rear Wheels	20153	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3
Service Pack; W/Single Rear Wheels ...	20008	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7
Suburban; Tahoe; Traverse				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor	20153	11.5	1.3
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Service Pack	20008	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Trailblazer			
Sensor	20153	11.5	1.3	Sensor; OEM Part No. 25774006	20116	62	7
Service Pack	20008	11.5	1.3	Service Pack	20004	62	7
2009				Traverse			
Avalanche; Aveo				EZ-sensor - 315 MHz	◇33000	11.5	1.3
EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor	20153	11.5	1.3
Sensor	20153	11.5	1.3	Service Pack	20008	11.5	1.3
Service Pack	20008	11.5	1.3	Uplander			
Cobalt				EZ-sensor - 315 MHz	◇33000	11.5	1.3
EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor	20158	62	7
Sensor; Clamp-In Style Only; W/Almmn. Valve Stem	20158	62	7	Service Pack	20004	62	7
Sensor; Snap-In Style Only; W/Rubber Valve Stem	20153	11.5	1.3	2008			
Service Pack; Clamp-In Style Only; W/Almmn. Valve Stem	20004	80	9	Avalanche; Aveo			
Service Pack; Snap-In Style Only; W/Rubber Valve Stem	20008	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3
Colorado				EZ-sensor Service Pack; Almmn. Valve	34000	62	7
Sensor	20131	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Service Pack	20006	62	7	Sensor	20153	11.5	1.3
Corvette				Service Pack	20008	11.5	1.3
Sensor; OEM Part No. 25758220	20076	62	7	Cobalt			
Service Pack	20004	62	7	EZ-sensor - 315 MHz	◇33000	11.5	1.3
Equinox; Express				EZ-sensor Service Pack; Almmn. Valve	34000	62	7
EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; Clamp-In Style Only; W/Almmn. Valve Stem	20158	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; Snap-In Style Only; W/Rubber Valve Stem	20153	11.5	1.3
Sensor	20158	62	7	Service Pack; Clamp-In Style Only; W/Almmn. Valve Stem	20004	80	9
Service Pack; W/Schrader Sensor	20004	62	7	Service Pack; Snap-In Style Only; W/Rubber Valve Stem	20008	11.5	1.3
Service Pack; W/Siemens Sensor	20030	80	9	Colorado			
HHR				Sensor	20131	62	7
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack	20006	62	7
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Corvette			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; OEM Part No. 25758220	20076	62	7
Sensor; Clamp-In Style Only; W/Almmn. Valve Stem	20158	62	7	Service Pack	20004	62	7
Sensor; Snap-In Style Only; W/Rubber Valve Stem	20153	11.5	1.3	Equinox; Express			
Service Pack; Clamp-In Style Only; W/Almmn. Valve Stem	20004	80	9	EZ-sensor - 315 MHz	◇33000	11.5	1.3
Service Pack; Snap-In Style Only; W/Rubber Valve Stem	20008	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7

◊ Programming Tool Required.



PRINTED ON RECYCLED PAPER
WITH 100% POSTCONSUMER WASTE

Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.				
Chevrolet - Continued				Chevrolet - Continued							
2008 - Continued											
HHR											
EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7				
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; Hatchback	20153	11.5	1.3				
Sensor; Clamp-In Style Only; W/Almm. Valve Stem	20158	62	7	Service Pack	20008	11.5	1.3				
Sensor; Snap-In Style Only; W/Rubber Valve Stem	20153	11.5	1.3	Colorado							
Service Pack; Clamp-In Style Only; W/Almm. Valve Stem	20004	80	9	Sensor	20131	62	7				
Service Pack; Snap-In Style Only; W/Rubber Valve Stem	20008	11.5	1.3	Service Pack	20006	62	7				
Impala				Corvette							
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor; OEM Part No. 25758220	20076	62	7				
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Service Pack	20004	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Equinox							
Sensor	20153	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3				
Service Pack	20008	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7				
Malibu				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor	20158	62	7				
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Service Pack; W/Schrader Sensor	20004	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack; W/Siemens Sensor	20030	80	9				
Sensor; Clamp-In Style Only; W/Almm. Valve Stem	20158	62	7	Impala; Monte Carlo							
Sensor; Snap-In Style Only; W/Rubber Valve Stem	20153	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3				
Service Pack; Clamp-In Style Only; W/Almm. Valve Stem	20004	80	9	EZ-sensor Service Pack; Almm. Valve	34000	62	7				
Service Pack; Snap-In Style Only; W/Rubber Valve Stem	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Silverado Series Pickup				Sensor; Clamp-In Style Only; W/Almm. Valve Stem	20158	62	7				
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor; Snap-In Style Only; W/Rubber Valve Stem	20153	11.5	1.3				
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Service Pack; Clamp-In Style Only; W/Almm. Valve Stem	20004	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack; Snap-In Style Only; W/Rubber Valve Stem	20008	11.5	1.3				
Sensor; W/Single Rear Wheels	20153	11.5	1.3	Silverado Series Pickup							
Service Pack; W/Single Rear Wheels ...	20008	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3				
Suburban; Tahoe				EZ-sensor Service Pack; Almm. Valve	34000	62	7				
EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor; Clamp-In Style Only; TRW Sensor; W/Almm. Valve Stem; Exc. Classic	20158	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; Snap-In Style Only; Schrader Sensor; W/Rubber Valve Stem; Exc. Classic	20153	11.5	1.3				
Sensor	20153	11.5	1.3	Sensor; Classic	20107	62	7				
Service Pack	20008	11.5	1.3	Service Pack; Clamp-In Style Only; TRW Sensor; W/Almm. Valve Stem; Exc. Classic	20015	80	9				
Trailblazer				Service Pack; Snap-In Style Only; Schrader Sensor; W/Rubber Valve Stem; Exc. Classic	20008	11.5	1.3				
Sensor; OEM Part No. 25774006	20116	62	7	Service Pack; Classic	20004	62	7				
Service Pack	20004	62	7	Suburban; Tahoe							
Uplander				EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7				
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; Clamp-In Style Only; TRW Sensor; W/Almm. Valve Stem	20158	62	7				
Sensor	20158	62	7	Sensor; Snap-In Style Only; Schrader Sensor; W/Rubber Valve Stem	20153	11.5	1.3				
Service Pack	20004	62	7	Service Pack; Clamp-In Style Only; TRW Sensor; W/Almm. Valve Stem	20015	80	9				
2007				Service Pack; Snap-In Style Only; Schrader Sensor; W/Rubber Valve Stem	20008	11.5	1.3				
Avalanche				Trailblazer							
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor; OEM Part No. 25774006	20116	62	7				
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Service Pack	20004	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	2006							
Sensor; Clamp-In Style Only; TRW Sensor; W/Almm. Valve Stem	20158	62	7	Avalanche							
Sensor; Snap-In Style Only; Schrader Sensor; W/Rubber Valve Stem	20153	11.5	1.3	Sensor	20107	62	7				
Service Pack; Clamp-In Style Only; TRW Sensor; W/Almm. Valve Stem	20015	80	9	Service Pack	20004	62	7				
Service Pack; Snap-In Style Only; Schrader Sensor; W/Rubber Valve Stem	20008	11.5	1.3	2005							
Aveo				Cavalier							
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor	20107	62	7				

◇ Programming Tool Required.



Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
Chevrolet - Continued							
2006 - Continued							
Corvette							
Sensor; OEM Part No. 25758220	20076	62	7	Sensor	20398	11.5	1.3
Service Pack	20004	62	7	Service Pack	20018	11.5	1.3
Impala; Monte Carlo							
EZ-sensor - 315 MHz	◆33000	11.5	1.3	EZ-sensor - 315 MHz	◆33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor; W/Alloy Wheels	20158	62	7	Sensor	20066	58	6.5
Service Pack; W/Alloy Wheels	20004	62	7	or	28308	11.5	1.3
Silverado Series Pickup							
Sensor	20107	62	7	Service Pack; W/Schrader Sensor; Does Not Include Stem	20013	58	6.5
Service Pack	20004	62	7	Service Pack; W/Schrader Sensor; Includes Stem Only	20020	58	6.5
SSR							
Sensor; OEM Part No. 25774006	20116	62	7	Sensor	20398	11.5	1.3
Service Pack	20004	62	7	Service Pack	20008	11.5	1.3
Suburban; Tahoe							
Sensor	20107	62	7	2011			
Service Pack	20004	62	7	200			
Trailblazer							
Sensor; OEM Part No. 25774006	20116	62	7	EZ-sensor - 315 MHz	◆33000	11.5	1.3
Service Pack	20004	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
2005				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Avalanche				Sensor	20066	58	6.5
Sensor	20107	62	7	or	28308	11.5	1.3
Service Pack	20004	62	7	Service Pack; W/Schrader Sensor; Does Not Include Stem	20013	58	6.5
Corvette				Service Pack; W/Schrader Sensor; Includes Stem Only	20020	58	6.5
Sensor; OEM Part No. 25758220	20076	62	7	Service Pack; W/Siemens Sensor	20030	71	8
Service Pack	20004	62	7	300			
Silverado Series Pickup; Suburban; Tahoe				PT Cruiser			
Sensor	20107	62	7	EZ-sensor - 315 MHz	◆33000	11.5	1.3
Service Pack	20004	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
2004				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Avalanche				Sensor	20066	58	6.5
Sensor	20115	62	7	or	28308	11.5	1.3
Service Pack	20004	62	7	Service Pack; W/Schrader Sensor; Does Not Include Stem	20013	58	6.5
Corvette				Service Pack; W/Schrader Sensor; Includes Stem Only	20020	58	6.5
Sensor	●20117	62	7	Service Pack; W/Siemens Sensor	20030	71	8
Service Pack	20003	62	7	Sebring			
Silverado Series Pickup; Suburban; Tahoe				PT Cruiser			
Sensor	20115	62	7	EZ-sensor - 315 MHz	◆33000	11.5	1.3
Service Pack	20004	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
2003-2001				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Corvette				Sensor	20066	58	6.5
Sensor	●20117	62	7	or	28308	11.5	1.3
Service Pack	20003	62	7	Service Pack; W/Schrader Sensor; Does Not Include Stem	20013	58	6.5
2000-1997				Service Pack; W/Schrader Sensor; Includes Stem Only	20020	58	6.5
Corvette				2009			
Sensor	●28006	62	7	300			
Service Pack	20012	62	7	Sensor	28291	58	6.5
Chrysler				Service Pack; Does Not Include Stem ..	20016	58	6.5
2012				Service Pack; Includes Stem Only	20020	58	6.5
200				Aspen; PT Cruiser; Sebring			
EZ-sensor - 315 MHz	◆33000	11.5	1.3	EZ-sensor - 315 MHz	◆33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor	20066	58	6.5	Sensor	20066	58	6.5
or	28308	11.5	1.3	or	28308	11.5	1.3
Service Pack; W/Schrader Sensor; Does Not Include Stem	20013	58	6.5	Service Pack; W/Schrader Sensor; Does Not Include Stem	20013	58	6.5
Service Pack; W/Schrader Sensor; Includes Stem Only	20020	58	6.5	Service Pack; W/Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; W/Siemens Sensor	20030	71	8	Service Pack; W/Siemens Sensor	20030	71	8
Town & Country Van							
Sensor	28155	58	6.5	2012			
or	28434	11.5	1.3	300; Town & Country Van			
Service Pack; W/Schrader Sensor; Does Not Include Stem	20013	58	6.5	Sensor	20398	11.5	1.3
Service Pack; W/Schrader Sensor; Includes Stem Only	20020	58	6.5	Service Pack	20008	11.5	1.3
Service Pack; W/Siemens Sensor	20020	58	6.5	Service Pack; W/Schrader Sensor; Includes Stem Only	20020	58	6.5

◆ Programming Tool Required.

● Magnet Required to Activate Sensor.



PRINTED ON RECYCLED PAPER
WITH 100% POSTCONSUMER WASTE

Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.	
Chrysler - Continued				Chrysler - Continued				
2009 - Continued				2007 - Continued				
Town & Country Van - Continued				Pacifica; Sebring; Town & Country Van - Continued				
Service Pack; W/Siemens Sensor	20030	71	8	or	28308	11.5	1.3	
2008				Service Pack; W/Schrader Sensor; Does Not Include Stem	20013	58	6.5	
300	Sensor	28155	58	6.5	Service Pack; W/Schrader Sensor; Includes Stem Only	20020	58	6.5
	or	28434	11.5	1.3	Service Pack; W/Siemens Sensor	20030	71	8
Service Pack; W/Schrader Sensor; Does Not Include Stem	20013	58	6.5	2006				
Service Pack; W/Schrader Sensor; Includes Stem Only	20020	58	6.5	300				
Service Pack; W/Siemens Sensor	20030	71	8	EZ-sensor - 315 MHz	◆33000	11.5	1.3	
Aspen				EZ-sensor Service Pack; Almm. Valve	34000	62	7	
EZ-sensor - 315 MHz	◆33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor	20066	58	6.5	
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	or	28308	11.5	1.3	
Sensor	20066	58	6.5	Service Pack; W/Schrader Sensor; Does Not Include Stem	20013	58	6.5	
or	28308	11.5	1.3	Service Pack; W/Schrader Sensor; Includes Stem Only	20020	58	6.5	
Service Pack; W/Schrader Sensor; Does Not Include Stem	20013	58	6.5	Service Pack; W/Siemens Sensor	20030	71	8	
Service Pack; W/Schrader Sensor; Includes Stem Only	20020	58	6.5	Crossfire				
Service Pack; W/Siemens Sensor	20030	71	8	Sensor	●20028	35	4	
Crossfire				Service Pack; W/Schrader Sensor	20003	35	4	
Sensor	●20028	35	4	Service Pack; W/Siemens Sensor	20030	35	4	
Service Pack; W/Schrader Sensor	20003	35	4	Pacifica; Town & Country Van				
Service Pack; W/Siemens Sensor	20030	35	4	EZ-sensor - 315 MHz	◆33000	11.5	1.3	
Pacifica; PT Cruiser; Sebring				EZ-sensor Service Pack; Almm. Valve	34000	62	7	
EZ-sensor - 315 MHz	◆33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor	20066	58	6.5	
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	or	28308	11.5	1.3	
Sensor	20066	58	6.5	Service Pack; W/Schrader Sensor; Does Not Include Stem	20013	58	6.5	
or	28308	11.5	1.3	Service Pack; W/Schrader Sensor; Includes Stem Only	20020	58	6.5	
Service Pack; W/Schrader Sensor; Does Not Include Stem	20013	58	6.5	Service Pack; W/Siemens Sensor	20030	71	8	
Service Pack; W/Schrader Sensor; Includes Stem Only	20020	58	6.5	2005				
Service Pack; W/Siemens Sensor	20030	71	8	300				
Town & Country Van				EZ-sensor - 315 MHz	◆33000	11.5	1.3	
Sensor	28155	58	6.5	EZ-sensor Service Pack; Almm. Valve	34000	62	7	
or	28434	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	
Service Pack; W/Schrader Sensor; Does Not Include Stem	20013	58	6.5	Sensor	20066	58	6.5	
Service Pack; W/Schrader Sensor; Includes Stem Only	20020	58	6.5	or	28308	11.5	1.3	
Service Pack; W/Siemens Sensor	20030	71	8	Service Pack; W/Schrader Sensor; Does Not Include Stem	20013	58	6.5	
2007				Service Pack; W/Schrader Sensor; Includes Stem Only	20020	58	6.5	
300; Aspen				Service Pack; W/Siemens Sensor	20030	71	8	
EZ-sensor - 315 MHz	◆33000	11.5	1.3	Crossfire				
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor - 315 MHz	◆33000	11.5	1.3	
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7	
Sensor	20066	58	6.5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	
or	28308	11.5	1.3	Sensor; OEM Part No. 5142340AA	20066	58	6.5	
Service Pack; W/Schrader Sensor; Does Not Include Stem	20013	58	6.5	or	28308	11.5	1.3	
Service Pack; W/Schrader Sensor; Includes Stem Only	20020	58	6.5	Sensor; OEM Part No. 52088990AC	●20028	35	4	
Service Pack; W/Siemens Sensor	20030	71	8	Service Pack; OEM Part No. 5142340AA; Does Not Include Stem .	20013	58	6.5	
Pacifica; Sebring; Town & Country Van				Service Pack; OEM Part No. 5142340AA; Includes Stem Only	20020	58	6.5	
EZ-sensor - 315 MHz	◆33000	11.5	1.3	Service Pack; OEM Part No. 52088990AC	20003	35	4	
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Pacifica; Town & Country Van				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor	20335	71	8	
Sensor	20066	58	6.5	Service Pack	20030	71	8	
Crossfire				2004				
Sensor	●20028	35	4	300M; Concorde; Crossfire; Intrepid				
Service Pack; W/Schrader Sensor	20003	35	4	EZ-sensor - 433 MHz	◆33100	11.5	1.3	
Service Pack; W/Siemens Sensor	20030	35	4	EZ-sensor Service Pack; Almm. Valve	34000	62	7	

◆ Programming Tool Required.

● Magnet Required to Activate Sensor.



Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
Chrysler - Continued							
2004 - Continued							
300M; Concorde; Crossfire; Intrepid - Continued							
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor	●20028	35	4
Sensor	●20028	35	4	Service Pack; W/Schrader Sensor	20003	35	4
Service Pack; W/Siemens Sensor	20030	35	4	Service Pack; W/Schrader Sensor	20018	11.5	1.3
Pacifica							
EZ-sensor - 433 MHz	◆33100	11.5	1.3	EZ-sensor - 315 MHz	◆33000	11.5	1.3
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Almmn. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor; OEM Part No. 04727392AD	20335	71	8	Sensor	20066	58	6.5
Sensor; OEM Part No. 52088990AC	●20028	35	4	or	28308	11.5	1.3
Service Pack; OEM Part No. 04727392AD	20030	71	8	Service Pack; W/Schrader Sensor; Does Not Include Stem	20013	58	6.5
Service Pack; OEM Part No. 52088990AC	20003	35	4	Service Pack; W/Schrader Sensor; Includes Stem Only	20020	58	6.5
Town & Country Van							
Sensor	20335	71	8	Caliber			
Service Pack	20030	71	8	EZ-sensor - 315 MHz	◆33000	11.5	1.3
2003				EZ-sensor Service Pack; Almmn. Valve	34000	62	7
300M; Concorde; Intrepid				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor - 433 MHz	◆33100	11.5	1.3	Sensor	20066	58	6.5
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	or	28308	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack; Does Not Include Stem ..	20013	58	6.5
Sensor	●20028	35	4	Service Pack; Includes Stem Only	20020	58	6.5
Service Pack; W/Schrader Sensor	20003	35	4	Challenger			
Service Pack; W/Siemens Sensor	20030	35	4	Sensor; W/Metal Stem Clamp-in Sensor	28291	58	6.5
Town & Country Van; Voyager				Sensor; W/Rubber Stem Snap-in Sensor	20398	11.5	1.3
EZ-sensor - 433 MHz	◆33100	11.5	1.3	Service Pack; W/Metal Stem Clamp-in Sensor; Does Not Include Stem	20016	58	6.5
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Service Pack; W/Metal Stem Clamp-in Sensor; Includes Stem Only	20020	58	6.5
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack; W/Rubber Stem Snap-in Sensor	20008	11.5	1.3
Sensor	●20028	35	4	Dodge			
Service Pack	20003	35	4	EZ-sensor - 315 MHz	◆33000	11.5	1.3
2002				EZ-sensor Service Pack; Almmn. Valve	34000	62	7
300M; Concorde; Intrepid; Prowler				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor - 433 MHz	◆33100	11.5	1.3	Sensor	20066	58	6.5
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	or	28308	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack; Does Not Include Stem ..	20013	58	6.5
Sensor	●20028	35	4	Service Pack; Includes Stem Only	20020	58	6.5
Service Pack; W/Schrader Sensor	20003	35	4	Dakota			
Service Pack; W/Siemens Sensor	20030	35	4	EZ-sensor - 315 MHz	◆33000	11.5	1.3
Town & Country Van; Voyager				EZ-sensor Service Pack; Almmn. Valve	34000	62	7
EZ-sensor - 433 MHz	◆33100	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor	20066	58	6.5
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	or	28308	11.5	1.3
Sensor	●20028	35	4	Service Pack; Does Not Include Stem ..	20013	58	6.5
Service Pack	20003	35	4	Service Pack; Includes Stem Only	20020	58	6.5
2001				Journey; Nitro			
Prowler				EZ-sensor - 315 MHz	◆33000	11.5	1.3
Sensor	28004	35	4	EZ-sensor Service Pack; Almmn. Valve	34000	62	7
Service Pack; W/Black Sensor Body	20012	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Service Pack; W/Red Sensor Body	20003	35	4	Sensor	20066	58	6.5
Dodge				or	28308	11.5	1.3
2012				Service Pack; Does Not Include Stem ..	20013	58	6.5
Avenger				Service Pack; Includes Stem Only	20020	58	6.5
EZ-sensor - 315 MHz	◆33000	11.5	1.3	Ram Series Pickup			
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; W/Rubber Stem Snap-in Sensor	20398	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack; W/Rubber Stem Snap-in Sensor	20008	11.5	1.3
Sensor	20066	58	6.5	2010			
or	28308	11.5	1.3	Avenger			
Service Pack; W/Schrader Sensor; Does Not Include Stem	20013	58	6.5	EZ-sensor - 315 MHz	◆33000	11.5	1.3
Service Pack; W/Schrader Sensor; Includes Stem Only	20020	58	6.5	EZ-sensor Service Pack; Almmn. Valve	34000	62	7
Caliber				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor - 315 MHz	◆33000	11.5	1.3	Sensor	20066	58	6.5
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	or	28308	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack; W/Schrader Sensor; Does Not Include Stem	20013	58	6.5
Sensor	20066	58	6.5	Service Pack; W/Schrader Sensor; Includes Stem Only	20020	58	6.5

● Magnet Required to Activate Sensor.

◆ Programming Tool Required.



PRINTED ON RECYCLED PAPER
WITH 100% POSTCONSUMER WASTE

Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
Dodge - Continued				Dodge - Continued			
2010 - Continued				2009 - Continued			
Caliber - Continued							
Sensor	20066	58	6.5	Service Pack; W/Schrader Sensor; Does Not Include Stem	20013	58	6.5
or	28308	11.5	1.3	Service Pack; W/Schrader Sensor; Includes Stem Only	20020	58	6.5
Service Pack; W/Schrader Sensor; Includes Stem Only	20013	58	6.5	Service Pack; W/Siemens Sensor	20030	71	8
Service Pack; W/Schrader Sensor; Includes Stem Only	20020	58	6.5	Challenger; Charger			
Service Pack; W/Siemens Sensor	20030	71	8	Sensor	28291	58	6.5
Challenger; Charger				Service Pack; Does Not Include Stem	20016	58	6.5
Sensor; W/Metal Stem Clamp-in Sensor	28291	58	6.5	Service Pack; Includes Stem Only	20020	58	6.5
Sensor; W/Rubber Stem Snap-in Sensor	20398	11.5	1.3	Dakota			
Service Pack; W/Metal Stem Clamp-in Sensor; Does Not Include Stem	20016	58	6.5	EZ-sensor - 315 MHz	◆33000	11.5	1.3
Service Pack; W/Metal Stem Clamp-in Sensor; Includes Stem Only	20020	58	6.5	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Service Pack; W/Rubber Stem Snap-in Sensor	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Dakota				Sensor	28154	58	6.5
EZ-sensor - 315 MHz	◆33000	11.5	1.3	or	28461	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Service Pack; Does Not Include Stem	20013	58	6.5
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack; Includes Stem Only	20020	58	6.5
Sensor	28154	58	6.5	Durango			
or	28461	11.5	1.3	EZ-sensor - 315 MHz	◆33000	11.5	1.3
Service Pack; Does Not Include Stem	20013	58	6.5	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Service Pack; Includes Stem Only	20020	58	6.5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Grand Caravan; Journey				Sensor	20066	58	6.5
Sensor	28155	58	6.5	or	28308	11.5	1.3
or	28434	11.5	1.3	Service Pack; Does Not Include Stem	20013	58	6.5
Service Pack; W/Schrader Sensor; Does Not Include Stem	20013	58	6.5	Service Pack; Includes Stem Only	20020	58	6.5
Service Pack; W/Schrader Sensor; Includes Stem Only	20020	58	6.5	Grand Caravan; Journey			
Service Pack; W/Siemens Sensor	20030	71	8	Sensor	28155	58	6.5
Nitro				or	28434	11.5	1.3
EZ-sensor - 315 MHz	◆33000	11.5	1.3	Service Pack; W/Schrader Sensor; Does Not Include Stem	20013	58	6.5
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Service Pack; W/Schrader Sensor; Includes Stem Only	20020	58	6.5
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack; W/Siemens Sensor	20030	71	8
Sensor	20066	58	6.5	Nitro			
or	28308	11.5	1.3	EZ-sensor - 315 MHz	◆33000	11.5	1.3
Service Pack; Does Not Include Stem	20013	58	6.5	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Service Pack; Includes Stem Only	20020	58	6.5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Ram Series Pickup				Sensor	20066	58	6.5
Sensor; 1500, 2500; W/Metal Stem Clamp-in Sensor	28155	58	6.5	or	28308	11.5	1.3
or	28434	11.5	1.3	Service Pack; Does Not Include Stem	20013	58	6.5
Sensor; W/Rubber Stem Snap-in Sensor	20398	11.5	1.3	Service Pack; Includes Stem Only	20020	58	6.5
Service Pack; 1500, 2500; W/Metal Stem Clamp-in Sensor; Does Not Include Stem	20013	58	6.5	Ram Series Pickup			
Service Pack; 1500, 2500; W/Metal Stem Clamp-in Sensor; Includes Stem Only	20020	58	6.5	Sensor; 1500, 2500	28155	58	6.5
Service Pack; 1500, 2500; W/Rubber Stem Snap-in Sensor	20008	11.5	1.3	or	28434	11.5	1.3
Service Pack	20008	11.5	1.3	Service Pack; 1500, 2500; Does Not Include Stem	20013	58	6.5
Viper				Service Pack; 1500, 2500; Includes Stem Only	20020	58	6.5
EZ-sensor - 433 MHz	◆33100	11.5	1.3	Sprinter			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor - 315 MHz	◆33000	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor	●20028	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Service Pack	20003	35	4	Sensor	20089	53	6
2009				Service Pack; Does Not Include Valve	20021	53	6
Avenger; Caliber				Service Pack; Includes Valve	20036	53	6
EZ-sensor - 315 MHz	◆33000	11.5	1.3	Viper			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor - 433 MHz	◆33100	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor	20066	58	6.5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
or	28308	11.5	1.3	Sensor	●20028	35	4
2008				Service Pack	20003	35	4
Avenger; Caliber				2008			
EZ-sensor - 315 MHz	◆33000	11.5	1.3	EZ-sensor - 315 MHz	◆33000	11.5	1.3

◆ Programming Tool Required.

● Magnet Required to Activate Sensor.



Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
Dodge - Continued				Dodge - Continued			
2008 - Continued				2008 - Continued			
Avenger; Caliber - Continued							
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Ram Series Pickup - Continued			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack; 1500, 2500; Does Not Include Stem	20013	58	6.5
Sensor	20066	58	6.5	Service Pack; 1500, 2500; Includes Stem Only	20020	58	6.5
or	28308	11.5	1.3				
Service Pack; W/Schrader Sensor; Does Not Include Stem	20013	58	6.5				
Service Pack; W/Schrader Sensor; Includes Stem Only	20020	58	6.5				
Service Pack; W/Siemens Sensor	20030	71	8				
Challenger							
Sensor	28291	58	6.5				
Service Pack; Does Not Include Stem ..	20016	58	6.5				
Service Pack; Includes Stem Only	20020	58	6.5				
Charger							
Sensor	28155	58	6.5				
or	28434	11.5	1.3				
Service Pack; W/Schrader Sensor; Does Not Include Stem	20013	58	6.5				
Service Pack; W/Schrader Sensor; Includes Stem Only	20020	58	6.5				
Service Pack; W/Siemens Sensor	20030	71	8				
Dakota							
EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Almm. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	28154	58	6.5				
or	28461	11.5	1.3				
Service Pack; Does Not Include Stem ..	20013	58	6.5				
Service Pack; Includes Stem Only	20020	58	6.5				
Durango							
EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Almm. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	20066	58	6.5				
or	28308	11.5	1.3				
Service Pack; W/Schrader Sensor; Does Not Include Stem	20013	58	6.5				
Service Pack; W/Schrader Sensor; Includes Stem Only	20020	58	6.5				
Service Pack; W/Siemens Sensor	20030	71	8				
Grand Caravan; Magnum							
Sensor	28155	58	6.5				
or	28434	11.5	1.3				
Service Pack; W/Schrader Sensor; Does Not Include Stem	20013	58	6.5				
Service Pack; W/Schrader Sensor; Includes Stem Only	20020	58	6.5				
Service Pack; W/Siemens Sensor	20030	71	8				
Nitro							
EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Almm. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	20066	58	6.5				
or	28308	11.5	1.3				
Service Pack; W/Schrader Sensor; Does Not Include Stem	20013	58	6.5				
Service Pack; W/Schrader Sensor; Includes Stem Only	20020	58	6.5				
Service Pack; W/Siemens Sensor	20030	71	8				
Ram Series Pickup							
EZ-sensor - 315 MHz; 1500, 2500	◇33000	11.5	1.3				
EZ-sensor Service Pack; 1500, 2500; Almm. Valve	34000	62	7				
EZ-sensor Service Pack; 1500, 2500; Rubber Valve	20008	11.5	1.3				
Sensor; 1500, 2500	28154	58	6.5				
or	28461	11.5	1.3				
2007							
Caliber; Caravan; Charger; Durango; Grand Caravan; Magnum; Nitro							
EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Almm. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	20066	58	6.5				
or	28308	11.5	1.3				
Service Pack; W/Schrader Sensor; Does Not Include Stem	20013	58	6.5				
Service Pack; W/Schrader Sensor; Includes Stem Only	20020	58	6.5				
Service Pack; W/Siemens Sensor	20030	71	8				
Sprinter							
EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Almm. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	20066	58	6.5				
or	28308	11.5	1.3				
Service Pack; W/Schrader Sensor; Does Not Include Stem	20013	58	6.5				
Service Pack; W/Schrader Sensor; Includes Stem Only	20020	58	6.5				
Service Pack; W/Siemens Sensor	20030	71	8				
2006							
Caravan; Charger; Grand Caravan; Magnum							
EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Almm. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	20066	58	6.5				
or	28308	11.5	1.3				
Service Pack; W/Schrader Sensor; Does Not Include Stem	20013	58	6.5				
Service Pack; W/Schrader Sensor; Includes Stem Only	20020	58	6.5				
Service Pack; W/Siemens Sensor	20030	71	8				
Viper							
EZ-sensor - 433 MHz	◇33100	11.5	1.3				
EZ-sensor Service Pack; Almm. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	●20028	35	4				
Service Pack	20003	35	4				
2005							
Caravan; Grand Caravan							
Sensor	20335	71	8				
Service Pack	20030	71	8				
Magnum							
EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Almm. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				

◊ Programming Tool Required.
● Magnet Required to Activate Sensor.



PRINTED ON RECYCLED PAPER
WITH 100% POSTCONSUMER WASTE

Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.				
Dodge - Continued											
2005 - Continued											
Magnum - Continued											
Sensor	20066	58	6.5	Service Pack; W/Schrader Sensor; Does Not Include Stem	20013	58	6.5				
or	28308	11.5	1.3	Service Pack; W/Schrader Sensor; Includes Stem Only	20020	58	6.5				
Service Pack; W/Schrader Sensor; Includes Stem Only	20030	71	8	Service Pack; W/Siemens Sensor	20030	71	8				
Viper											
EZ-sensor - 433 MHz	◆33100	11.5	1.3	Service Pack; Almm. Valve	34000	62	7				
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	●20028	35	4	Sensor	●20028	35	4				
Service Pack	20003	35	4	Service Pack	20003	35	4				
2004											
Caravan; Grand Caravan											
Sensor	20335	71	8	Service Pack	20030	71	8				
Intrepid											
Sensor	●20028	35	4	Service Pack	20003	35	4				
Service Pack	20003	35	4	Viper							
EZ-sensor - 433 MHz	◆33100	11.5	1.3	EZ-sensor - 433 MHz	◆33100	11.5	1.3				
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	●20028	35	4	Sensor	●20028	35	4				
Service Pack	20003	35	4	Service Pack	20003	35	4				
2003											
Caravan; Grand Caravan; Intrepid; Viper											
EZ-sensor - 433 MHz	◆33100	11.5	1.3	Service Pack; Almm. Valve	34000	62	7				
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	●20028	35	4	Sensor	●20028	35	4				
Service Pack	20003	35	4	Service Pack	20003	35	4				
2002											
Caravan; Grand Caravan; Intrepid											
EZ-sensor - 433 MHz	◆33100	11.5	1.3	Service Pack; Almm. Valve	34000	62	7				
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	●20028	35	4	Sensor	●20028	35	4				
Service Pack	20003	35	4	Service Pack	20003	35	4				
Ferrari											
2009-2006											
612 Scaglietti; F430											
Sensor; Includes Transmitter Only	20077	35	4	Service Pack; Does Not Include Valve	20023	35	4				
Service Pack; Does Not Include Valve	20023	35	4	Service Pack; W/43mm Silver Insert	20037	35	4				
Service Pack; W/43mm Silver Insert	20037	35	4	Service Pack; W/48mm Green Insert	20038	35	4				
Service Pack; W/48mm Green Insert	20038	35	4	Service Pack; W/49mm Black Insert	20039	35	4				
Service Pack; W/49mm Black Insert	20039	35	4	Service Pack; W/51mm Orange Insert	20040	35	4				
2005											
575M Maranello; 612 Scaglietti; F430											
Sensor; Includes Transmitter Only	20077	35	4	Service Pack; Does Not Include Valve	20023	35	4				
Service Pack; Does Not Include Valve	20023	35	4	Service Pack; W/43mm Silver Insert	20037	35	4				
Service Pack; W/43mm Silver Insert	20037	35	4	Service Pack; W/48mm Green Insert	20038	35	4				
Service Pack; W/48mm Green Insert	20038	35	4	Service Pack; W/49mm Black Insert	20039	35	4				
Service Pack; W/49mm Black Insert	20039	35	4	Service Pack; W/51mm Orange Insert	20040	35	4				
2004											
575M Maranello; 612 Scaglietti											
Sensor; Includes Transmitter Only	20077	35	4	Service Pack; Does Not Include Valve	20023	35	4				
Service Pack; Does Not Include Valve	20023	35	4	Fiat							
Service Pack; W/Schrader Sensor; Does Not Include Stem	20013	58	6.5	2012							
Service Pack; W/Schrader Sensor; Includes Stem Only	20020	58	6.5	500							
Service Pack; W/Siemens Sensor	20030	71	8	Sensor	20077	35	4				
2003				Service Pack; Does Not Include Valve	20023	35	4				
575M Maranello; 575M Maranello				Service Pack; W/43mm Silver Insert	20037	35	4				
Sensor; Includes Transmitter Only	20077	35	4	Service Pack; W/48mm Green Insert	20038	35	4				
Service Pack; Does Not Include Valve	20023	35	4	Service Pack; W/49mm Black Insert	20039	35	4				
Service Pack; W/43mm Silver Insert	20037	35	4	Service Pack; W/51mm Orange Insert	20040	35	4				
2002				2001							
550 Maranello; 575M Maranello				550 Maranello							
Sensor; Includes Transmitter Only	20077	35	4	Sensor; Includes Transmitter Only	20077	35	4				
Service Pack; Does Not Include Valve	20023	35	4	Service Pack; Does Not Include Valve	20023	35	4				
Service Pack; W/43mm Silver Insert	20037	35	4	Service Pack; W/43mm Silver Insert	20037	35	4				
Service Pack; W/48mm Green Insert	20038	35	4	Service Pack; W/48mm Green Insert	20038	35	4				
Service Pack; W/49mm Black Insert	20039	35	4	Service Pack; W/49mm Black Insert	20039	35	4				
Service Pack; W/51mm Orange Insert	20040	35	4	Service Pack; W/51mm Orange Insert	20040	35	4				
2001											
Ford											
2012											
E Series Van; Edge; Escape; Expedition; Explorer; F Series Pickup; Fiesta; Flex; Focus; Fusion; Mustang; Super Duty Pickup; Taurus; Transit Connect											
EZ-sensor - 315 MHz	◆33000	11.5	1.3	Sensor	20398	11.5	1.3				
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Service Pack	20018	11.5	1.3				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	2011							
Sensor	20315	13	1.5	Crown Victoria							
Service Pack	20018	13	1.5	EZ-sensor - 315 MHz	◆33000	11.5	1.3				
2005											
575M Maranello; 612 Scaglietti; F430											
Sensor; Includes Transmitter Only	20077	35	4	2010							
Service Pack; Does Not Include Valve	20023	35	4	Mustang							
Service Pack; W/43mm Silver Insert	20037	35	4	Sensor	20398	11.5	1.3				
Service Pack; W/48mm Green Insert	20038	35	4	Service Pack	20018	11.5	1.3				
Service Pack; W/49mm Black Insert	20039	35	4	2009							
Service Pack; W/51mm Orange Insert	20040	35	4	Cougar							
2004											
575M Maranello; 612 Scaglietti											
Sensor; Includes Transmitter Only	20077	35	4	Sensor	20398	11.5	1.3				
Service Pack; Does Not Include Valve	20023	35	4	Service Pack	20018	11.5	1.3				
2003											
575M Maranello; 575M Maranello											
Sensor; Includes Transmitter Only	20077	35	4	Sensor	20398	11.5	1.3				
Service Pack; Does Not Include Valve	20023	35	4	Service Pack	20018	11.5	1.3				
Service Pack; W/43mm Silver Insert	20037	35	4	2008							
Service Pack; W/48mm Green Insert	20038	35	4	Cougar							
Service Pack; W/49mm Black Insert	20039	35	4	Sensor	20398	11.5	1.3				
Service Pack; W/51mm Orange Insert	20040	35	4	Service Pack	20018	11.5	1.3				
2002											
550 Maranello											
Sensor; Includes Transmitter Only	20077	35	4	Sensor	20398	11.5	1.3				
Service Pack; Does Not Include Valve	20023	35	4	Service Pack	20018	11.5	1.3				
Service Pack; W/43mm Silver Insert	20037	35	4	2007							
Service Pack; W/48mm Green Insert	20038	35	4	Cougar							
Service Pack; W/49mm Black Insert	20039	35	4	Sensor	20398	11.5	1.3				
Service Pack; W/51mm Orange Insert	20040	35	4	Service Pack	20018	11.5	1.3				
2001											
550 Maranello											
Sensor; Includes Transmitter Only	20077	35	4	Sensor	20398	11.5	1.3				
Service Pack; Does Not Include Valve	20023	35	4	Service Pack	20018	11.5	1.3				
Service Pack; W/43mm Silver Insert	20037	35	4	2006							
Service Pack; W/48mm Green Insert	20038	35	4	Cougar							
Service Pack; W/49mm Black Insert	20039	35	4	Sensor	20398	11.5	1.3				
Service Pack; W/51mm Orange Insert	20040	35	4	Service Pack	20018	11.5	1.3				
2000											
550 Maranello											
Sensor; Includes Transmitter Only	20077	35	4	Sensor	20398	11.5	1.3				
Service Pack; Does Not Include Valve	20023	35	4	Service Pack	20018	11.5	1.3				
Service Pack; W/43mm Silver Insert	20037	35	4	2005							
Service Pack; W/48mm Green Insert	20038	35	4	Cougar							
Service Pack; W/49mm Black Insert	20039	35	4	Sensor	20398	11.5	1.3				
Service Pack; W/51mm Orange Insert	20040	35	4	Service Pack	20018	11.5	1.3				
1999											
550 Maranello											
Sensor; Includes Transmitter Only	20077	35	4	Sensor	20398	11.5	1.3				
Service Pack; Does Not Include Valve	20023	35	4	Service Pack	20018	11.5	1.3				
Service Pack; W/43mm Silver Insert	20037	35	4	2004							
Service Pack; W/48mm Green Insert	20038	35	4								

Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
Ford - Continued				Ford - Continued			
2011 - Continued				2011 - Continued			
Crown Victoria - Continued							
EZ-sensor Service Pack; Almnm. Valve	34000	62	7	Sensor	20315	13	1.5
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz	◆33000	11.5	1.3
Sensor	28385	27	3	EZ-sensor Service Pack; Almnm. Valve	34000	62	7
Sensor Clip	22100			EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor Cradle	22101						
Sensor Universal Band	22102						
E Series Van; Edge							
Sensor	20315	13	1.5				
EZ-sensor - 315 MHz	◆33000	11.5	1.3				
EZ-sensor Service Pack; Almnm. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	20315	13	1.5				
Escape							
EZ-sensor - 315 MHz	◆33000	11.5	1.3				
EZ-sensor Service Pack; Almnm. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	20315	13	1.5				
Expedition; Explorer; F Series Pickup							
Sensor	20315	13	1.5				
EZ-sensor - 315 MHz	◆33000	11.5	1.3				
EZ-sensor Service Pack; Almnm. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	20315	13	1.5				
Fiesta							
EZ-sensor - 315 MHz	◆33000	11.5	1.3				
EZ-sensor Service Pack; Almnm. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	20315	13	1.5				
Service Pack	20018	13	1.5				
Flex							
Sensor	20315	13	1.5				
EZ-sensor - 315 MHz	◆33000	11.5	1.3				
EZ-sensor Service Pack; Almnm. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	20315	13	1.5				
Focus; Fusion							
EZ-sensor - 315 MHz	◆33000	11.5	1.3				
EZ-sensor Service Pack; Almnm. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	20315	13	1.5				
Mustang							
EZ-sensor - 315 MHz	◆33000	11.5	1.3				
EZ-sensor Service Pack; Almnm. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	20315	13	1.5				
Service Pack	20018	13	1.5				
Ranger							
EZ-sensor - 315 MHz	◆33000	11.5	1.3				
EZ-sensor Service Pack; Almnm. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	28385	27	3				
Sensor Clip	22100						
Sensor Cradle	22101						
Sensor Universal Band	22102						
Super Duty Pickup; Super Duty Van							
Sensor	20315	13	1.5				
EZ-sensor - 315 MHz	◆33000	11.5	1.3				
EZ-sensor Service Pack; Almnm. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Taurus							
EZ-sensor - 315 MHz	◆33000	11.5	1.3				
EZ-sensor Service Pack; Almnm. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	20315	13	1.5				
Service Pack	20018	13	1.5				
Transit Connect							
Sensor	20315	13	1.5				
EZ-sensor - 315 MHz	◆33000	11.5	1.3				
EZ-sensor Service Pack; Almnm. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
2010							
Crown Victoria							
EZ-sensor - 315 MHz	◆33000	11.5	1.3				
EZ-sensor Service Pack; Almnm. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	28385	27	3				
Sensor Clip	22100						
Sensor Cradle	22101						
Sensor Universal Band	22102						
E450 Super Duty							
EZ-sensor - 315 MHz	◆33000	11.5	1.3				
EZ-sensor Service Pack; Almnm. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	20315	13	1.5				
Service Pack	20018	13	1.5				
E Series Van							
EZ-sensor - 315 MHz; W/Alloy Wheels	◆33000	11.5	1.3				
EZ-sensor Service Pack; W/Alloy Wheels; Almnm. Valve	34000	62	7				
EZ-sensor Service Pack; W/Alloy Wheels; Rubber Valve	20008	11.5	1.3				
Sensor; W/Alloy Wheels	28395	27	3				
Sensor; W/Steel Wheels	20315	13	1.5				
Sensor Clip; W/Alloy Wheels	22100						
Sensor Cradle; W/Alloy Wheels	22101						
Sensor Universal Band; W/Alloy Wheels	22102						
Service Pack; W/Steel Wheels	20018	13	1.5				
Edge							
EZ-sensor - 315 MHz	◆33000	11.5	1.3				
EZ-sensor Service Pack; Almnm. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	28390	27	3				
Sensor Clip	22100						
Sensor Cradle	22101						
Sensor Universal Band	22102						
Escape							
EZ-sensor - 315 MHz	◆33000	11.5	1.3				
EZ-sensor Service Pack; Almnm. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	20315	13	1.5				
Service Pack	20018	13	1.5				
Expedition							
EZ-sensor - 315 MHz	◆33000	11.5	1.3				
EZ-sensor Service Pack; Almnm. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	28390	27	3				
Sensor Clip	22100						
Sensor Cradle	22101						
Sensor Universal Band	22102						
Explorer; Explorer Sport Trac							
EZ-sensor - 315 MHz	◆33000	11.5	1.3				
EZ-sensor Service Pack; Almnm. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	28385	27	3				
Sensor Clip	22100						
Sensor Cradle	22101						
Sensor Universal Band	22102						
F450 Super Duty; F550 Super Duty							
EZ-sensor - 315 MHz	◆33000	11.5	1.3				
EZ-sensor Service Pack; Almnm. Valve	34000	62	7				

◆ Programming Tool Required.



PRINTED ON RECYCLED PAPER
WITH 100% POSTCONSUMER WASTE

Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
Ford - Continued							
2010 - Continued							
F450 Super Duty; F550 Super Duty - Continued							
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor Universal Band; W/Alloy Wheels	22102		
Sensor	28395	27	3	Service Pack; W/Steel Wheels	20018	13	1.5
Sensor Clip	22100						
Sensor Cradle	22101						
Sensor Universal Band	22102						
F Series Pickup							
EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor - 315 MHz; Apr. & Older	◇33000	11.5	1.3
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Apr. & Older; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Apr. & Older; Rubber Valve	20008	11.5	1.3
Sensor	20315	13	1.5	Sensor; May & Newer	20315	13	1.5
Service Pack	20018	13	1.5	Sensor; Apr. & Older	28390	27	3
Flex							
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack; May & Newer	20018	13	1.5
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor Clip; Apr. & Older	22100		
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor Cradle; Apr. & Older	22101		
Sensor	28390	27	3	Sensor Universal Band; Apr. & Older	22102		
Focus; Fusion							
EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	20315	13	1.5				
Service Pack	20018	13	1.5				
Grand Marquis							
EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	28385	27	3				
Sensor Clip	22100						
Sensor Cradle	22101						
Sensor Universal Band	22102						
Mustang							
EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	20315	13	1.5				
Service Pack	20018	13	1.5				
Ranger							
EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	28385	27	3				
Sensor Clip	22100						
Sensor Cradle	22101						
Sensor Universal Band	22102						
Super Duty Pickup							
EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	28395	27	3				
Sensor Clip	22100						
Sensor Cradle	22101						
Sensor Universal Band	22102						
Super Duty Van							
EZ-sensor - 315 MHz; W/Alloy Wheels	◇33000	11.5	1.3				
EZ-sensor Service Pack; W/Alloy Wheels; Almm. Valve	34000	62	7				
EZ-sensor Service Pack; W/Alloy Wheels; Rubber Valve	20008	11.5	1.3				
Sensor; W/Alloy Wheels	28395	27	3				
Sensor; W/Steel Wheels	20315	13	1.5				
Sensor Clip; W/Alloy Wheels	22100						
Sensor Cradle; W/Alloy Wheels	22101						
Ford - Continued							
2010 - Continued							
Super Duty Van - Continued							
Sensor Universal Band; W/Alloy Wheels	22102						
Service Pack; W/Steel Wheels	20018	13	1.5				
Taurus							
EZ-sensor - 315 MHz; Apr. & Older	◇33000	11.5	1.3				
EZ-sensor Service Pack; Apr. & Older; Almm. Valve	34000	62	7				
EZ-sensor Service Pack; Apr. & Older; Rubber Valve	20008	11.5	1.3				
Sensor; May & Newer	20315	13	1.5				
Sensor; Apr. & Older	28390	27	3				
Service Pack; May & Newer	20018	13	1.5				
Sensor Clip; Apr. & Older	22100						
Sensor Cradle; Apr. & Older	22101						
Sensor Universal Band; Apr. & Older	22102						
Transit Connect							
EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Almm. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	20315	13	1.5				
Service Pack	20018	13	1.5				
2009							
Crown Victoria							
EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Almm. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	28385	27	3				
Sensor Clip	22100						
Sensor Cradle	22101						
Sensor Universal Band	22102						
E450 Super Duty; E Series Van							
EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Almm. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	28395	27	3				
Sensor Clip	22100						
Sensor Cradle	22101						
Sensor Universal Band	22102						
Edge							
EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Almm. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	28390	27	3				
Sensor Clip	22100						
Sensor Cradle	22101						
Sensor Universal Band	22102						
Escape							
EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Almm. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	20315	13	1.5				
Service Pack	20018	13	1.5				
Expedition							
EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Almm. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	28390	27	3				
Sensor Clip	22100						
Sensor Cradle	22101						
Sensor Universal Band	22102						
Explorer; Explorer Sport Trac							
EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Almm. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	28385	27	3				

◇ Programming Tool Required.



Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
Ford - Continued				Ford - Continued			
2009 - Continued				2008 - Continued			
Explorer; Explorer Sport Trac - Continued				E450 Super Duty; E Series Van - Continued			
Sensor Clip	22100			Sensor Cradle	22101		
Sensor Cradle	22101			Sensor Universal Band	22102		
Sensor Universal Band	22102			Edge			
F450 Super Duty				EZ-sensor - 315 MHz	◇33000	11.5	1.3
EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almnm. Valve	34000	62	7
EZ-sensor Service Pack; Almnm. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor: W/Chrome Plated Almnm. Wheels	28385	27	3
Sensor	28395	27	3	Sensor: W/O Chrome Plated Almnm. Wheels	28390	27	3
Sensor Clip	22100			Sensor Clip	22100		
Sensor Cradle	22101			Sensor Cradle	22101		
Sensor Universal Band	22102			Sensor Universal Band	22102		
F Series Pickup				Escape			
EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3
EZ-sensor Service Pack; Almnm. Valve	34000	62	7	EZ-sensor Service Pack; Almnm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor	20315	13	1.5	Sensor	28385	27	3
Service Pack	20018	13	1.5	Sensor Clip	22100		
Flex; Focus				Sensor Cradle	22101		
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor Universal Band	22102		
EZ-sensor Service Pack; Almnm. Valve	34000	62	7	Expedition			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3
Sensor	28390	27	3	EZ-sensor Service Pack; Almnm. Valve	34000	62	7
Sensor Clip	22100			EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor Cradle	22101			Sensor	28390	27	3
Sensor Universal Band	22102			Sensor Clip	22100		
Fusion; Grand Marquis; Mustang; Ranger				Sensor Cradle	22101		
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor Universal Band	22102		
EZ-sensor Service Pack; Almnm. Valve	34000	62	7	Explorer; Explorer Sport Trac			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3
Sensor	28385	27	3	EZ-sensor Service Pack; Almnm. Valve	34000	62	7
Sensor Clip	22100			EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor Cradle	22101			Sensor	28385	27	3
Sensor Universal Band	22102			Sensor Clip	22100		
Super Duty Pickup; Super Duty Van				Sensor Cradle	22101		
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor Universal Band	22102		
EZ-sensor Service Pack; Almnm. Valve	34000	62	7	F450 Super Duty			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3
Sensor	28395	27	3	EZ-sensor Service Pack; Almnm. Valve	34000	62	7
Sensor Clip	22100			EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor Cradle	22101			Sensor	28395	27	3
Sensor Universal Band	22102			Sensor Clip	22100		
Taurus; Taurus X				Sensor Cradle	22101		
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor Universal Band	22102		
EZ-sensor Service Pack; Almnm. Valve	34000	62	7	F Series Pickup			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3
Sensor	28390	27	3	EZ-sensor Service Pack; Almnm. Valve	34000	62	7
Sensor Clip	22100			EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor Cradle	22101			Sensor	28395	27	3
Sensor Universal Band	22102			Sensor Clip	22100		
2008				Sensor Cradle	22101		
Crown Victoria				Sensor Universal Band	22102		
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Focus			
EZ-sensor Service Pack; Almnm. Valve	34000	62	7	EZ-sensor - 315 MHz	◇33000	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almnm. Valve	34000	62	7
Sensor	28385	27	3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor Clip	22100			Sensor	28390	27	3
Sensor Cradle	22101			Sensor Clip	22100		
Sensor Universal Band	22102			Sensor Cradle	22101		
E450 Super Duty; E Series Van				Sensor Universal Band	22102		
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Fusion; Grand Marquis; Mustang; Ranger			
EZ-sensor Service Pack; Almnm. Valve	34000	62	7	EZ-sensor - 315 MHz	◇33000	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almnm. Valve	34000	62	7
Sensor	28395	27	3				
Sensor Clip	22100						

◊ Programming Tool Required.



PRINTED ON RECYCLED PAPER
WITH 100% POSTCONSUMER WASTE

Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.				
Ford - Continued											
2008 - Continued											
Fusion; Grand Marquis; Mustang; Ranger - Continued											
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3				
Sensor	28385	27	3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
Sensor Clip	22100			EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor Cradle	22101			Sensor	28385	27	3				
Sensor Universal Band	22102			Sensor Clip	22100						
Super Duty Pickup; Super Duty Van											
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor Cradle	22101						
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor Universal Band	22102						
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Freestar; Fusion; Grand Marquis; Mustang; Ranger							
Sensor	28395	27	3	EZ-sensor - 315 MHz	◇33000	11.5	1.3				
Sensor Clip	22100			EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
Sensor Cradle	22101			EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor Universal Band	22102			Sensor	28385	27	3				
Taurus; Taurus X											
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor Clip	22100						
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor Cradle	22101						
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor Universal Band	22102						
Sensor	28390	27	3	2006							
Sensor Clip	22100			Crown Victoria; Escape							
Sensor Cradle	22101			EZ-sensor - 315 MHz	◇33000	11.5	1.3				
Sensor Universal Band	22102			EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
2007				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Crown Victoria				Sensor	28385	27	3				
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor Clip	22100						
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor Cradle	22101						
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor Universal Band	22102						
Sensor	28385	27	3	Expedition							
Sensor Clip	22100			Sensor	●20135	44	5				
Sensor Cradle	22101			Service Pack	20002	44	5				
Sensor Universal Band	22102			Explorer							
Edge											
EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor; W/Chrome Plated Almmn. Wheels	28385	27	3	Sensor	28385	27	3				
Sensor; W/O Chrome Plated Almmn. Wheels	28390	27	3	Sensor Clip	22100						
Sensor Clip	22100			Sensor Cradle	22101						
Sensor Cradle	22101			Sensor Universal Band	22102						
Sensor Universal Band	22102			Five Hundred							
Escape											
EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	28385	27	3	Sensor	28390	27	3				
Sensor Clip	22100			Sensor Clip	22100						
Sensor Cradle	22101			Sensor Cradle	22101						
Sensor Universal Band	22102			Sensor Universal Band	22102						
Expedition											
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Freestar; Grand Marquis							
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
Sensor	28390	27	3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor Clip	22100			Sensor	28385	27	3				
Sensor Cradle	22101			Sensor Clip	22100						
Sensor Universal Band	22102			Sensor Cradle	22101						
Explorer; Explorer Sport Trac; F Series Pickup											
EZ-sensor - 315 MHz	◇33000	11.5	1.3	2005							
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Escape							
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3				
Sensor	28385	27	3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
Sensor Clip	22100			EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor Cradle	22101			Sensor	28385	27	3				
Sensor Universal Band	22102			Sensor Clip	22100						
Explorer; Explorer Sport Trac; F Series Pickup											
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Freestar							
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
Sensor	28385	27	3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor Clip	22100			Sensor	28385	27	3				
Sensor Cradle	22101			Sensor Clip	22100						
Sensor Universal Band	22102			Sensor Cradle	22101						
Expedition											
Sensor	●20135	44	5	Grand Marquis							
Service Pack	20002	44	5	EZ-sensor - 315 MHz	◇33000	11.5	1.3				

◊ Programming Tool Required.
 ● Magnet Required to Activate Sensor.



Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
Ford - Continued				GMC - Continued			
2005 - Continued				2012 - Continued			
Explorer				Terrain			
EZ-sensor - 433 MHz	◇33100	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Almmn. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor	●20096	44	5	Sensor	28206	11.5	1.3
Service Pack	20002	44	5	Service Pack	20008	11.5	1.3
Freestar				Yukon			
Sensor; W/Almmn. Valve Stem	●20135	44	5	EZ-sensor - 315 MHz	◇33000	11.5	1.3
Service Pack; W/Almmn. Valve Stem ...	20002	44	5	EZ-sensor Service Pack; Almmn. Valve	34000	62	7
2004				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Expedition; Explorer				Sensor	20153	11.5	1.3
EZ-sensor - 433 MHz	◇33100	11.5	1.3	Sensor; W/Single Rear Wheels	20153	11.5	1.3
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Service Pack	20008	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack; W/Single Rear Wheels ...	20008	11.5	1.3
Sensor	●20096	44	5	2011-2010			
Service Pack	20002	44	5	Acadia			
2003				EZ-sensor - 315 MHz	◇33000	11.5	1.3
Expedition				EZ-sensor Service Pack; Almmn. Valve	34000	62	7
EZ-sensor - 433 MHz	◇33100	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor	20153	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack	20008	11.5	1.3
Sensor	●20096	44	5	Canyon			
Service Pack	20002	44	5	Sensor	20131	62	7
Explorer				Service Pack	20006	62	7
EZ-sensor - 433 MHz	◇33100	11.5	1.3	Savana			
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor - 315 MHz	◇33000	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7
Sensor; Exc. Sport	●20096	44	5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Service Pack; Exc. Sport	20002	44	5	Sensor	20153	11.5	1.3
2002				Service Pack	20008	11.5	1.3
Explorer				Sierra Series Pickup			
EZ-sensor - 433 MHz	◇33100	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Almmn. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor; Exc. Sport	●20096	44	5	Sensor	20153	11.5	1.3
Service Pack; Exc. Sport	20002	44	5	Service Pack; W/Single Rear Wheels ...	20008	11.5	1.3
GMC				Terrain			
2012				EZ-sensor - 315 MHz	◇33000	11.5	1.3
Acadia				EZ-sensor Service Pack; Almmn. Valve	34000	62	7
EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor	20153	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack	20008	11.5	1.3
Sensor	20153	11.5	1.3	2009			
Service Pack	20008	11.5	1.3	Acadia			
Canyon				EZ-sensor - 315 MHz	◇33000	11.5	1.3
Sensor	20131	62	7	EZ-sensor Service Pack; Almmn. Valve	34000	62	7
Service Pack	20006	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Savana				Sensor	20153	11.5	1.3
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack	20008	11.5	1.3
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Canyon			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor	20131	62	7
Sensor	20153	11.5	1.3	Service Pack	20006	62	7
Service Pack	20008	11.5	1.3	Envoy			
Sierra Series Pickup				Sensor; OEM Part No. 25774006	20116	62	7
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack	20004	62	7
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Savana			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3
Sensor	20153	11.5	1.3				
Service Pack	20008	11.5	1.3				

● Magnet Required to Activate Sensor.

◇ Programming Tool Required.



PRINTED ON RECYCLED PAPER
WITH 100% POSTCONSUMER WASTE

Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
GMC - Continued				GMC - Continued			
2009 - Continued				2007 - Continued			
Savana - Continued				Envoy			
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; OEM Part No. 25774006	20116	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack	20004	62	7
Sensor	20158	62	7	Sierra Series Pickup			
Service Pack; W/Schrader Sensor	20004	62	7	EZ-sensor - 315 MHz	◇33000	11.5	1.3
Service Pack; W/Siemens Sensor	20030	80	9	EZ-sensor Service Pack; Almmn. Valve	34000	62	7
Sierra Series Pickup				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor; Clamp-In Style Only; TRW			
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; W/Almmn. Valve Stem; Exc.			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Classic	20158	62	7
Sensor; W/Single Rear Wheels	20153	11.5	1.3	Sensor; Snap-In Style Only; Schrader			
Service Pack; W/Single Rear Wheels ...	20008	11.5	1.3	Sensor; W/Rubber Valve Stem; Exc.			
Yukon				Classic	20153	11.5	1.3
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor; Classic	20107	62	7
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Service Pack; Clamp-In Style Only; TRW			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; W/Almmn. Valve Stem; Exc.			
Sensor	20153	11.5	1.3	Classic	20015	80	9
Service Pack	20008	11.5	1.3	Service Pack; Snap-In Style Only;			
2008				Schrader Sensor; W/Rubber Valve			
Acadia				Stem; Exc. Classic	20008	11.5	1.3
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack; Classic	20004	62	7
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Yukon			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3
Sensor	20158	62	7	EZ-sensor Service Pack; Almmn. Valve	34000	62	7
Service Pack; W/Schrader Sensor	20004	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Service Pack; W/Siemens Sensor	20030	80	9	Sensor; Clamp-In Style Only; TRW			
Canyon				Sensor; W/Almmn. Valve Stem	20158	62	7
Sensor	20131	62	7	Sensor; Snap-In Style Only; Schrader			
Service Pack	20006	62	7	Sensor; W/Rubber Valve Stem	20153	11.5	1.3
Envoy				Service Pack; Clamp-In Style Only; TRW			
Sensor; OEM Part No. 25774006	20116	62	7	Sensor; W/Almmn. Valve Stem	20015	62	7
Service Pack	20004	62	7	Service Pack; Snap-In Style Only;			
Savana				Schrader Sensor; W/Rubber Valve			
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Stem	20008	11.5	1.3
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	2006			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Envoy			
Sensor	20158	62	7	Sensor; OEM Part No. 25774006	20116	62	7
Service Pack; W/Schrader Sensor	20004	62	7	Service Pack	20004	62	7
Service Pack; W/Siemens Sensor	20030	80	9	Sierra Series Pickup; Yukon			
Sierra Series Pickup				Sensor	20107	62	7
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack	20004	62	7
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	2005			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sierra Series Pickup; Yukon			
Sensor	20158	62	7	Sensor	20107	62	7
Service Pack; W/Schrader Sensor	20004	62	7	Service Pack	20004	62	7
Service Pack; W/Siemens Sensor	20030	80	9	2004			
Yukon				Sierra Series Pickup; Yukon			
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor	20115	62	7
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Service Pack	20004	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Honda			
Sensor; W/Single Rear Wheels	20153	11.5	1.3	2012			
Service Pack; W/Single Rear Wheels ...	20008	11.5	1.3	Civic			
2007				EZ-sensor - 315 MHz	◇33000	11.5	1.3
Acadia				EZ-sensor Service Pack; Almmn. Valve	34000	62	7
EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor	28720	35	4
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack	20019	35	4
Sensor	20158	62	7	2011			
Service Pack; W/Schrader Sensor	20004	62	7	Accord			
Service Pack; W/Siemens Sensor	20030	80	9	EZ-sensor - 315 MHz; Exc. Crosstour ..	◇33000	11.5	1.3
2007				EZ-sensor Service Pack; Exc. Crosstour; Almmn. Valve	34000	62	7
Acadia				EZ-sensor Service Pack; Exc. Crosstour; Rubber Valve	20008	11.5	1.3
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor; Exc. Crosstour	20099	35	4
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	2011			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Civic			
Sensor	20158	62	7	EZ-sensor - 315 MHz	◇33000	11.5	1.3
Service Pack; W/Schrader Sensor	20004	62	7	EZ-sensor Service Pack; Almmn. Valve	34000	62	7
Service Pack; W/Siemens Sensor	20030	80	9	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Canyon				Sensor	28720	35	4
Sensor	20131	62	7	Service Pack	20019	35	4
Service Pack	20006	62	7	2011			

◇ Programming Tool Required.



Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
Honda - Continued				Honda - Continued			
2011 - Continued				2010 - Continued			
Accord - Continued				Ridgeline			
Sensor; Crosstour	20100	35	4	Sensor; RT	28981	35	4
Service Pack; Exc. Crosstour	20032	35	4	Service Pack; RT; Includes Valve	20036	35	4
Civic				Service Pack; Does Not Include Valve	20021	35	4
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor; Exc. RT	28981	35	4
EZ-sensor Service Pack; Almm. Valve	34000	62	7	2009			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Accord			
Sensor	28720	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3
Service Pack	20019	35	4	EZ-sensor Service Pack; Almm. Valve	34000	62	7
CR-V				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor	28720	35	4
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Service Pack	20019	35	4
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Civic			
Sensor	20099	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3
Service Pack	20032	35	4	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Element; Fit; Insight; Odyssey				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor	28720	35	4
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Service Pack	20019	35	4
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	CR-V			
Sensor	28720	35	4	EZ-sensor - 315 MHz; W/Alloy Wheels	◇33000	11.5	1.3
Service Pack	20019	35	4	EZ-sensor Service Pack; W/Alloy Wheels; Almm. Valve	34000	62	7
Pilot				EZ-sensor Service Pack; W/Alloy Wheels; Rubber Valve	20008	11.5	1.3
Sensor; Exc. LX	20098	35	4	Sensor; W/Alloy Wheels	20099	35	4
Service Pack; Exc. LX	20032	35	4	Service Pack	20032	35	4
Ridgeline				Element; Fit			
Sensor; RT	28981	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3
Service Pack; RT; Includes Valve	20036	35	4	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Service Pack; Does Not Include Valve	20021	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor; Exc. RT	28981	35	4	Sensor	28720	35	4
2010				Service Pack	20019	35	4
Accord				Odyssey			
EZ-sensor - 315 MHz; Exc. Crosstour	◇33000	11.5	1.3	Sensor	28983	31-40	3.5-4.5
EZ-sensor Service Pack; Exc. Crosstour; Almm. Valve	34000	62	7	Service Pack; Includes Valve	20036	31-40	3.5-4.5
EZ-sensor Service Pack; Exc. Crosstour; Rubber Valve	20008	11.5	1.3	Service Pack; Does Not Include Valve	20021	31-40	3.5-4.5
Sensor; Exc. Crosstour	20099	35	4	Pilot			
Sensor; Crosstour	20100	35	4	Sensor; W/Alloy Wheels	20098	35	4
Service Pack; Exc. Crosstour	20032	35	4	Service Pack; W/Alloy Wheels	20032	35	4
Civic				Ridgeline			
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor	28981	35	4
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Service Pack; Includes Valve	20036	35	4
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack; Does Not Include Valve	20021	35	4
Sensor	28720	35	4	S2000			
Service Pack	20019	35	4	Service Pack	20032	35	4
CR-V				2008			
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Accord			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor - 315 MHz	◇33000	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor	20099	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Service Pack	20032	35	4	Sensor	20099	35	4
Element; Fit; Insight				Service Pack	20032	35	4
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Civic			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor - 315 MHz	◇33000	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor	28720	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Service Pack	20019	35	4	Sensor	28720	35	4
Odyssey				Service Pack	20019	35	4
Sensor	28983	31-40	3.5-4.5	CR-V			
Service Pack; Includes Valve	20036	31-40	3.5-4.5	EZ-sensor - 315 MHz; W/Alloy Wheels	◇33000	11.5	1.3
Service Pack; Does Not Include Valve	20021	31-40	3.5-4.5	EZ-sensor Service Pack; W/Alloy Wheels; Almm. Valve	34000	62	7
Pilot				EZ-sensor Service Pack; W/Alloy Wheels; Rubber Valve	20008	11.5	1.3
Sensor; Exc. LX	20098	35	4	2008			
Service Pack; Exc. LX	20032	35	4	Accord			

◊ Programming Tool Required.



PRINTED ON RECYCLED PAPER
WITH 100% POSTCONSUMER WASTE

Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.				
Honda - Continued											
2008 - Continued											
CR-V - Continued											
Sensor; W/Alloy Wheels	20099	35	4	Sensor; RT	28982	35	4				
Service Pack	20032	35	4	Sensor; RTL, RTS	28981	35	4				
Element											
Service Pack; Includes Valve	20036	35	4	Service Pack; RT; Includes Valve	20035	35	4				
Service Pack; Does Not Include Valve	20021	35	4	Service Pack; RTL, RTS; Includes Valve	20036	35	4				
Fit											
EZ-sensor - 315 MHz	◆33000	11.5	1.3	Service Pack; Does Not Include Valve	20021	35	4				
EZ-sensor Service Pack; Almn. Valve	34000	62	7	2005							
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Odyssey							
Sensor	20099	35	4	Sensor; Touring	28981	35	4				
Service Pack	20032	35	4	Service Pack; Touring; Includes Valve	20036	35	4				
Pilot				Service Pack; Touring; Does Not Include Valve	20021	35	4				
Sensor	28981	35	4	Pilot							
Service Pack; Includes Valve	20036	35	4	Sensor; EX	28981	35	4				
Service Pack; Does Not Include Valve	20021	35	4	Sensor; LX; W/Long Stem Valve	28982	35	4				
Ridgeline				Sensor; LX; W/Short Stem Valve	28981	35	4				
Sensor; RT	28982	35	4	Service Pack; EX; Includes Valve	20036	35	4				
Sensor; RTL, RTS, RTX	28981	35	4	Service Pack; LX; W/Long Stem Valve; Includes Valve	20035	35	4				
Service Pack; RT; Includes Valve	20035	35	4	Service Pack; LX; W/Short Stem Valve; Includes Valve	20036	35	4				
Service Pack; RTL, RTS, RTX; Includes Valve	20036	35	4	Service Pack; Does Not Include Valve	20021	35	4				
Service Pack; Does Not Include Valve	20021	35	4	Hummer							
S2000											
Service Pack	20032	35	4	2010-2009							
2007				H2							
CR-V				EZ-sensor - 315 MHz	◆33000	11.5	1.3				
EZ-sensor - 315 MHz; W/Alloy Wheels	◆33000	11.5	1.3	EZ-sensor Service Pack; Almn. Valve	34000	62	7				
EZ-sensor Service Pack; W/Alloy Wheels; Almn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
EZ-sensor Service Pack; W/Alloy Wheels; Rubber Valve	20008	11.5	1.3	Sensor	20153	11.5	1.3				
Sensor; W/Alloy Wheels	20099	35	4	Service Pack	20008	11.5	1.3				
Service Pack	20032	35	4	H3; H3T							
Element				Sensor	20131	62	7				
Service Pack; Includes Valve	20036	35	4	Service Pack	20006	62	7				
Service Pack; Does Not Include Valve	20021	35	4	2008							
Odyssey				H2							
Sensor; Touring	28981	35	4	EZ-sensor - 315 MHz	◆33000	11.5	1.3				
Service Pack; Includes Valve	20036	35	4	EZ-sensor Service Pack; Almn. Valve	34000	62	7				
Service Pack; Does Not Include Valve	20021	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Pilot				Sensor	20153	11.5	1.3				
Sensor	28981	35	4	Service Pack	20008	11.5	1.3				
Service Pack; Includes Valve	20036	35	4	H3							
Service Pack; Does Not Include Valve	20021	35	4	Sensor	20131	62	7				
Ridgeline				Service Pack	20006	62	7				
Sensor; RT	28982	35	4	2007-2006							
Sensor; RTL, RTS, RTX	28981	35	4	H3							
Service Pack; RT; Includes Valve	20035	35	4	Sensor	20131	62	7				
Service Pack; RTL, RTS, RTX; Includes Valve	20036	35	4	Service Pack	20006	62	7				
Service Pack; Does Not Include Valve	20021	35	4	Hyundai							
2006				2012							
Odyssey				Accent							
Sensor; Touring	28981	35	4	Sensor	20092	31-40	3.5-4.5				
Service Pack; Touring; Includes Valve	20036	35	4								
Service Pack; Touring; Does Not Include Valve	20021	35	4								
Pilot				Equus							
Sensor	28981	35	4	Sensor	28849	31-40	3.5-4.5				
Service Pack; Includes Valve	20036	35	4	Service Pack	20022	31-40	3.5-4.5				
Service Pack; Does Not Include Valve	20021	35	4								
Genesis				Genesis							
Sensor; Coupe	20092	31-40	3.5-4.5								
Sensor; Sedan	28849	31-40	3.5-4.5								
Sonata											
Sensor	20092	31-40	3.5-4.5								

◆ Programming Tool Required.



Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
Hyundai - Continued				Hyundai - Continued			
2011				2009 - Continued			
Accent				Santa Fe - Continued			
Sensor	28849	31-40	3.5-4.5	Service Pack; Does Not Include Valve	20021	31-40	3.5-4.5
Service Pack	20022	31-40	3.5-4.5	Service Pack; Includes Valve	20036	31-40	3.5-4.5
Azera				Sonata			
Sensor; Includes Transmitter Only	20086	31-40	3.5-4.5	Sensor	28849	31-40	3.5-4.5
Service Pack; Does Not Include Valve ..	20021	31-40	3.5-4.5	Service Pack	20022	31-40	3.5-4.5
Service Pack; Includes Valve	20036	31-40	3.5-4.5	Tucson			
Elantra				Sensor	28983	31-40	3.5-4.5
Sensor; Includes Transmitter Only	20086	31-40	3.5-4.5	Service Pack; Includes Valve	20036	31-40	3.5-4.5
Equus				Service Pack; Does Not Include Valve	20021	31-40	3.5-4.5
Sensor	28849	31-40	3.5-4.5	Veracruz			
Service Pack	20022	31-40	3.5-4.5	Sensor; Includes Transmitter Only	20086	31-40	3.5-4.5
Genesis				Service Pack; Does Not Include Valve	20021	31-40	3.5-4.5
Sensor; Coupe	20092	31-40	3.5-4.5	Service Pack; Includes Valve	20036	31-40	3.5-4.5
Sensor; Sedan	28849	31-40	3.5-4.5	2008			
Sonata				Accent			
Sensor	20092	31-40	3.5-4.5	Sensor	28849	31-40	3.5-4.5
Tucson				Service Pack	20022	31-40	3.5-4.5
Sensor	28849	31-40	3.5-4.5	Azera; Elantra			
Service Pack	20022	31-40	3.5-4.5	Sensor; Includes Transmitter Only	20086	31-40	3.5-4.5
Veracruz				Service Pack; Does Not Include Valve	20021	31-40	3.5-4.5
Sensor; Includes Transmitter Only	20086	31-40	3.5-4.5	Service Pack; Includes Valve	20036	31-40	3.5-4.5
Service Pack; Does Not Include Valve ..	20021	31-40	3.5-4.5	Entourage; Santa Fe			
Service Pack; Includes Valve	20036	31-40	3.5-4.5	Sensor; Includes Transmitter Only	20085	31-40	3.5-4.5
2010				Service Pack; Does Not Include Valve	20021	31-40	3.5-4.5
Accent				Service Pack; Includes Valve	20036	31-40	3.5-4.5
Sensor	28849	31-40	3.5-4.5	Sonata; Tiburon; Tucson			
Service Pack	20022	31-40	3.5-4.5	Sensor	28983	31-40	3.5-4.5
Azera; Elantra				Service Pack; Includes Valve	20036	31-40	3.5-4.5
Sensor; Includes Transmitter Only	20086	31-40	3.5-4.5	Service Pack; Does Not Include Valve	20021	31-40	3.5-4.5
Service Pack; Does Not Include Valve ..	20021	31-40	3.5-4.5	Veracruz			
Service Pack; Includes Valve	20036	31-40	3.5-4.5	Sensor; Includes Transmitter Only	20085	31-40	3.5-4.5
Genesis				Service Pack; Does Not Include Valve	20021	31-40	3.5-4.5
Service Pack	20022	31-40	3.5-4.5	Service Pack; Includes Valve	20036	31-40	3.5-4.5
Santa Fe				2007			
Sensor; Includes Transmitter Only	20086	31-40	3.5-4.5	Azera			
Service Pack; Does Not Include Valve ..	20021	31-40	3.5-4.5	Sensor; Includes Transmitter Only	20086	31-40	3.5-4.5
Service Pack; Includes Valve	20036	31-40	3.5-4.5	Service Pack; Does Not Include Valve	20021	31-40	3.5-4.5
Sonata; Tucson				Service Pack; Includes Valve	20036	31-40	3.5-4.5
Sensor	28849	31-40	3.5-4.5	Entourage; Santa Fe			
Service Pack	20022	31-40	3.5-4.5	Sensor; Includes Transmitter Only	20085	31-40	3.5-4.5
Veracruz				Service Pack; Does Not Include Valve	20021	31-40	3.5-4.5
Sensor; Includes Transmitter Only	20086	31-40	3.5-4.5	Service Pack; Includes Valve	20036	31-40	3.5-4.5
Service Pack; Does Not Include Valve ..	20021	31-40	3.5-4.5	Sonata			
Service Pack; Includes Valve	20036	31-40	3.5-4.5	Sensor	28983	31-40	3.5-4.5
2009				Service Pack; Does Not Include Valve	20021	31-40	3.5-4.5
Accent				Service Pack; Includes Valve	20036	31-40	3.5-4.5
Sensor	28849	31-40	3.5-4.5	Tiburon; Tucson			
Service Pack	20022	31-40	3.5-4.5	Sensor	28983	31-40	3.5-4.5
Azera; Elantra				Service Pack; Includes Valve	20036	31-40	3.5-4.5
Sensor; Includes Transmitter Only	20086	31-40	3.5-4.5	Service Pack; Does Not Include Valve	20021	31-40	3.5-4.5
Service Pack; Does Not Include Valve ..	20021	31-40	3.5-4.5	Veracruz			
Service Pack; Includes Valve	20036	31-40	3.5-4.5	Sensor; Includes Transmitter Only	20085	31-40	3.5-4.5
Entourage				Service Pack; Does Not Include Valve	20021	31-40	3.5-4.5
Sensor; Includes Transmitter Only	20085	31-40	3.5-4.5	Service Pack; Includes Valve	20036	31-40	3.5-4.5
Service Pack; Does Not Include Valve ..	20021	31-40	3.5-4.5	2006			
Service Pack; Includes Valve	20036	31-40	3.5-4.5	Azera			
Genesis				Sensor; Includes Transmitter Only	20086	31-40	3.5-4.5
Service Pack	20022	31-40	3.5-4.5	Service Pack; Does Not Include Valve	20021	31-40	3.5-4.5
Santa Fe				Service Pack; Includes Valve	20036	31-40	3.5-4.5
Sensor; Includes Transmitter Only	20086	31-40	3.5-4.5				



Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
Hyundai - Continued							
2006 - Continued							
Tucson							
Sensor	28983	31-40	3.5-4.5				
Service Pack; Includes Valve	20036	31-40	3.5-4.5				
Service Pack; Does Not Include Valve	20021	31-40	3.5-4.5				
Infiniti							
2010-2009							
EX35; FX35; FX50; G37							
EZ-sensor - 315 MHz	◆33000	11.5	1.3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	28210	66	7.5				
Service Pack	20014	66	7.5				
M35; M45							
EZ-sensor - 315 MHz	◆33000	11.5	1.3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	28204	66	7.5				
Service Pack	20014	66	7.5				
QX56							
EZ-sensor - 315 MHz	◆33000	11.5	1.3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	28204	49	5.5				
Service Pack	20014	49	5.5				
2008							
EX35							
EZ-sensor - 315 MHz	◆33000	11.5	1.3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	28210	66	7.5				
Service Pack	20014	66	7.5				
FX35; FX45							
EZ-sensor - 315 MHz	◆33000	11.5	1.3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	28204	66	7.5				
Service Pack	20014	66	7.5				
G35; G37							
EZ-sensor - 315 MHz	◆33000	11.5	1.3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	28210	66	7.5				
Service Pack	20014	66	7.5				
M35; M45							
EZ-sensor - 315 MHz	◆33000	11.5	1.3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	28204	66	7.5				
Service Pack	20014	66	7.5				
QX56							
EZ-sensor - 315 MHz	◆33000	11.5	1.3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	28204	49	5.5				
Service Pack	20014	49	5.5				
2007							
FX35; FX45							
EZ-sensor - 315 MHz	◆33000	11.5	1.3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor; Jul. & Newer	28204	66	7.5				
Sensor; Jun. & Older	20064	66	7.5				
Service Pack; Jul. & Newer	20014	66	7.5				
Infiniti - Continued							
2007 - Continued							
FX35; FX45 - Continued							
Service Pack; Jun. & Older	20007	66	7.5				
G35							
EZ-sensor - 315 MHz	◆33000	11.5	1.3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor; Coupe	28204	66	7.5				
Sensor; Sedan	28210	66	7.5				
Service Pack	20014	66	7.5				
M35; M45							
EZ-sensor - 315 MHz	◆33000	11.5	1.3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	20064	66	7.5				
Service Pack	20007	66	7.5				
QX56							
EZ-sensor - 315 MHz	◆33000	11.5	1.3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor; Apr. 1 & Newer	28204	49	5.5				
Sensor; Mar. & Older	20161	49	5.5				
Service Pack; Apr. 1 & Newer	20014	49	5.5				
Service Pack; Mar. & Older	20007	49	5.5				
2006							
FX35; FX45							
EZ-sensor - 315 MHz	◆33000	11.5	1.3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	20064	66	7.5				
Service Pack	20007	66	7.5				
G35							
EZ-sensor - 315 MHz	◆33000	11.5	1.3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	20064	61-72	6.8-8.2				
Service Pack	20007	61-72	6.8-8.2				
M35; M45							
EZ-sensor - 315 MHz	◆33000	11.5	1.3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	20064	66	7.5				
Service Pack	20007	66	7.5				
Q45							
EZ-sensor - 315 MHz	◆33000	11.5	1.3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	28204	66	7.5				
Service Pack; Aug. & Newer	20064	66	7.5				
Service Pack; Aug. & Newer	20014	66	7.5				
Service Pack; Jul. & Older	20007	66	7.5				
QX56							
EZ-sensor - 315 MHz	◆33000	11.5	1.3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor; W/Alloy Wheels	20161	49	5.5				
Sensor; W/Steel Wheels	20069	49	5.5				
Service Pack; W/Alloy Wheels	20007	49	5.5				
Service Pack; W/Steel Wheels	20005	49	5.5				
2005							
FX35; FX45							
EZ-sensor - 315 MHz	◆33000	11.5	1.3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	20064	66	7.5				

◆ Programming Tool Required.



Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
Infiniti - Continued							
2005 - Continued							
FX35; FX45 - Continued							
Service Pack	20007	66	7.5	Sensor	20064	66	7.5
G35				Service Pack	20007	66	7.5
EZ-sensor - 315 MHz	◆33000	11.5	1.3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	20064	61-72	6.8-8.2				
Service Pack	20007	61-72	6.8-8.2				
Q45							
EZ-sensor - 315 MHz	◆33000	11.5	1.3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	20064	66	7.5				
Service Pack	20007	66	7.5				
QX56							
EZ-sensor - 315 MHz	◆33000	11.5	1.3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor; W/Alloy Wheels	20161	49	5.5				
Sensor; W/Steel Wheels	20069	49	5.5				
Service Pack; W/Alloy Wheels	20007	49	5.5				
Service Pack; W/Steel Wheels	20005	49	5.5				
2004							
FX35; FX45							
EZ-sensor - 315 MHz	◆33000	11.5	1.3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	20064	66	7.5				
Service Pack	20007	66	7.5				
G35							
EZ-sensor - 315 MHz	◆33000	11.5	1.3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	20064	61-72	6.8-8.2				
Service Pack	20007	61-72	6.8-8.2				
M45; Q45							
EZ-sensor - 315 MHz	◆33000	11.5	1.3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	20064	66	7.5				
Service Pack	20007	66	7.5				
QX56							
EZ-sensor - 315 MHz	◆33000	11.5	1.3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	20069	49	5.5				
Service Pack	20005	49	5.5				
2003							
FX35; FX45							
EZ-sensor - 315 MHz	◆33000	11.5	1.3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	20064	66	7.5				
Service Pack	20007	66	7.5				
G35							
EZ-sensor - 315 MHz	◆33000	11.5	1.3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor; Jun. & Newer	20064	61-72	6.8-8.2				
Service Pack; Jun. & Newer	20007	61-72	6.8-8.2				
M45; Q45; QX4							
EZ-sensor - 315 MHz	◆33000	11.5	1.3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
2003 - Continued							
2003 - Continued							
M45; Q45; QX4 - Continued							
Sensor	20064	66	7.5				
Service Pack	20007	66	7.5				
Isuzu							
2008-2007							
Ascender							
Sensor	20116	62	7				
Service Pack	20004	62	7				
I-290; I-370							
Sensor	20131	62	7				
Service Pack	20006	62	7				
2006							
Ascender							
Sensor	20116	62	7				
Service Pack	20004	62	7				
2004							
Rodeo							
EZ-sensor - 433 MHz	◆33100	11.5	1.3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	●20028	62	7				
Service Pack	20003	62	7				
Jaguar							
2012							
XF; XJ; XK							
Sensor; W/315 MHz Sensor	20090	71	8				
Sensor; W/433 MHz Sensor	20091	71	8				
Service Pack	20030	71	8				
2011-2010							
XF; XFR; XJ; XK; XKR							
Sensor; W/315 MHz Sensor	20090	71	8				
Sensor; W/433 MHz Sensor	20091	71	8				
Service Pack	20030	71	8				
2009							
Super V8; Vanden Plas; XF; XJ8; XJR; XK; XKR							
Sensor; W/315 MHz Sensor	20090	71	8				
Sensor; W/433 MHz Sensor	20091	71	8				
Service Pack	20030	71	8				
2008							
S-Type; Super V8; Vanden Plas; X-Type; XJ8; XJR; XK; XKR							
Sensor; W/315 MHz Sensor	20090	71	8				
Sensor; W/433 MHz Sensor	20091	71	8				
Service Pack	20030	71	8				
2007							
Super V8; Vanden Plas; XJ8; XJR; XK; XKR							
Sensor; W/315 MHz Sensor	20090	71	8				
Sensor; W/433 MHz Sensor	20091	71	8				
Service Pack	20030	71	8				
2006-2005							
Super V8; Vanden Plas; XJ8; XJR							
Sensor; W/315 MHz Sensor	20090	71	8				
Sensor; W/433 MHz Sensor	20091	71	8				
Service Pack	20030	71	8				
2004							
Vanden Plas; XJ8; XJR							
Sensor; W/315 MHz Sensor	20090	71	8				
Sensor; W/433 MHz Sensor	20091	71	8				
Service Pack	20030	71	8				

◆ Programming Tool Required.

● Magnet Required to Activate Sensor.

Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.				
Jeep				Jeep - Continued							
2012											
Grand Cherokee											
Sensor	20398	11.5	1.3	Service Pack; W/Schrader Sensor; Includes Stem Only	20020	58	6.5				
Service Pack	20018	13	1.5	Service Pack; W/Siemens Sensor	20030	71	8				
Liberty											
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor	28155	58	6.5				
Service Pack	20018	13	1.5	or	28434	11.5	1.3				
Sensor	20066	58	6.5	Service Pack; Does Not Include Stem ..	20013	58	6.5				
or	28308	11.5	1.3	Service Pack; Includes Stem Only	20020	58	6.5				
Patriot											
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Liberty	◇33000	11.5	1.3				
Sensor	20066	58	6.5	EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
or	28308	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Service Pack; W/Schrader Sensor; Does Not Include Stem	20013	58	6.5	Sensor	20066	58	6.5				
or	28308	11.5	1.3	or	28308	11.5	1.3				
Wrangler				Service Pack; Does Not Include Stem ..	20013	58	6.5				
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack; Includes Stem Only	20020	58	6.5				
Service Pack	20018	13	1.5	2011							
Sensor	20066	58	6.5	Compass							
or	28308	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3				
2011				EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
Compass				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor	20066	58	6.5				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	or	28308	11.5	1.3				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack; W/Schrader Sensor; Does Not Include Stem	20013	58	6.5				
Sensor	20066	58	6.5	Service Pack; W/Schrader Sensor; Includes Stem Only	20020	58	6.5				
or	28308	11.5	1.3	Service Pack; W/Siemens Sensor	20030	71	8				
Service Pack; W/Schrader Sensor; Does Not Include Stem	20013	58	6.5	Wrangler							
Service Pack; W/Schrader Sensor; Includes Stem Only	20020	58	6.5	Sensor	28155	58	6.5				
Grand Cherokee				or	28434	11.5	1.3				
Sensor	20398	11.5	1.3	Service Pack; Does Not Include Stem ..	20013	58	6.5				
Service Pack	20008	11.5	1.3	Service Pack; Includes Stem Only	20020	58	6.5				
Liberty				2009							
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Commander							
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor	28155	58	6.5				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	or	28434	11.5	1.3				
Sensor	20066	58	6.5	Service Pack; Does Not Include Stem ..	20013	58	6.5				
or	28308	11.5	1.3	Service Pack; Includes Stem Only	20020	58	6.5				
Service Pack; Does Not Include Stem ..	20013	58	6.5	Compass							
Service Pack; Includes Stem Only	20020	58	6.5	EZ-sensor - 315 MHz	◇33000	11.5	1.3				
Patriot; Wrangler				EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor	20066	58	6.5				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	or	28308	11.5	1.3				
Sensor	20066	58	6.5	Service Pack; W/Schrader Sensor; Does Not Include Stem	20013	58	6.5				
or	28308	11.5	1.3	Service Pack; W/Schrader Sensor; Includes Stem Only	20020	58	6.5				
Service Pack; W/Schrader Sensor; Does Not Include Stem	20013	58	6.5	Service Pack; W/Siemens Sensor	20030	71	8				
Service Pack; W/Schrader Sensor; Includes Stem Only	20020	58	6.5	Grand Cherokee							
2010				Sensor	28155	58	6.5				
Commander				or	28434	11.5	1.3				
Sensor	28155	58	6.5	Service Pack; Does Not Include Stem ..	20013	58	6.5				
or	28434	11.5	1.3	Service Pack; Includes Stem Only	20020	58	6.5				
Service Pack; Does Not Include Stem ..	20013	58	6.5	Liberty							
Service Pack; Includes Stem Only	20020	58	6.5	EZ-sensor - 315 MHz	◇33000	11.5	1.3				
Compass				EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; Exc. Sport	28155	58	6.5				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	or	28434	11.5	1.3				
Sensor	20066	58	6.5	Sensor; Sport	20066	58	6.5				
or	28308	11.5	1.3	or	28308	11.5	1.3				
Service Pack; W/Schrader Sensor; Does Not Include Stem	20013	58	6.5	Service Pack; Does Not Include Stem ..	20013	58	6.5				
Service Pack; W/Schrader Sensor; Includes Stem Only	20020	58	6.5	Service Pack; Includes Stem Only	20020	58	6.5				

◇ Programming Tool Required.



Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
Jeep - Continued				Jeep - Continued			
2009 - Continued				2006 - Continued			
Patriot				Commander; Grand Cherokee; Liberty - Continued			
EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor	20066	58	6.5
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	or	28308	11.5	1.3
Sensor	20066	58	6.5	Service Pack; W/Schrader Sensor; Does	20013	58	6.5
or	28308	11.5	1.3	Not Include Stem	20013	58	6.5
Service Pack; W/Schrader Sensor; Does	20013	58	6.5	Service Pack; W/Schrader Sensor;	20020	58	6.5
Not Include Stem	20013	58	6.5	Includes Stem Only	20020	58	6.5
Service Pack; W/Schrader Sensor;	20020	58	6.5	Service Pack; W/Siemens Sensor	20030	71	8
Includes Stem Only	20020	58	6.5				
Service Pack; W/Siemens Sensor	20030	71	8				
Wrangler							
Sensor	28155	58	6.5				
or	28434	11.5	1.3				
Service Pack; Does Not Include Stem ..	20013	58	6.5				
Service Pack; Includes Stem Only	20020	58	6.5				
2008							
Commander							
Sensor	28155	58	6.5				
or	28434	11.5	1.3				
Service Pack; Does Not Include Stem ..	20013	58	6.5				
Service Pack; Includes Stem Only	20020	58	6.5				
Compass							
EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	20066	58	6.5				
or	28308	11.5	1.3				
Service Pack; W/Schrader Sensor; Does	20013	58	6.5				
Not Include Stem	20013	58	6.5				
Service Pack; W/Schrader Sensor;	20020	58	6.5				
Includes Stem Only	20020	58	6.5				
Service Pack; W/Siemens Sensor	20030	71	8				
Grand Cherokee							
Sensor	28155	58	6.5				
or	28434	11.5	1.3				
Service Pack; Does Not Include Stem ..	20013	58	6.5				
Service Pack; Includes Stem Only	20020	58	6.5				
Liberty; Patriot; Wrangler							
EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	20066	58	6.5				
or	28308	11.5	1.3				
Service Pack; W/Schrader Sensor; Does	20013	58	6.5				
Not Include Stem	20013	58	6.5				
Service Pack; W/Schrader Sensor;	20020	58	6.5				
Includes Stem Only	20020	58	6.5				
Service Pack; W/Siemens Sensor	20030	71	8				
2007							
Commander; Compass; Grand Cherokee; Liberty; Patriot; Wrangler							
EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	20066	58	6.5				
or	28308	11.5	1.3				
Service Pack; W/Schrader Sensor; Does	20013	58	6.5				
Not Include Stem	20013	58	6.5				
Service Pack; W/Schrader Sensor;	20020	58	6.5				
Includes Stem Only	20020	58	6.5				
Service Pack; W/Siemens Sensor	20030	71	8				
2006							
Commander; Grand Cherokee; Liberty							
EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
2005							
Grand Cherokee; Liberty							
EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	20066	58	6.5				
or	28308	11.5	1.3				
Service Pack; W/Schrader Sensor; Does	20013	58	6.5				
Not Include Stem	20013	58	6.5				
Service Pack; W/Schrader Sensor;	20020	58	6.5				
Includes Stem Only	20020	58	6.5				
Service Pack; W/Siemens Sensor	20030	71	8				
2004							
Grand Cherokee; Liberty							
EZ-sensor - 433 MHz	◇33100	11.5	1.3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	●20028	64	7				
Service Pack	20003	64	7				
2003-2002							
Grand Cherokee							
EZ-sensor - 433 MHz	◇33100	11.5	1.3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	●20028	64	7				
Service Pack	20003	64	7				
Liberty							
EZ-sensor - 433 MHz	◇33100	11.5	1.3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Kia							
2012							
Sedona							
Sensor; Includes Transmitter Only	20086	31-40	3.5-4.5				
Service Pack; Does Not Include Valve ..	20021	31-40	3.5-4.5				
Service Pack; Includes Valve	20036	31-40	3.5-4.5				
2011							
Borrego; Rio							
Sensor	28849	35-35.7	3.5-4.5				
Service Pack	20022	35-35.7	3.5-4.5				
Sedona							
Sensor; Includes Transmitter Only	20086	31-40	3.5-4.5				
Service Pack; Does Not Include Valve ..	20021	31-40	3.5-4.5				
Service Pack; Includes Valve	20036	31-40	3.5-4.5				
Sorento; Soul							
Sensor	20092	31-40	3.5-4.5				
Sportage							
Sensor	28849	31-40	3.5-4.5				
Service Pack	20022	31-40	3.5-4.5				
2010							
Borrego							
Sensor	28849	31-40	3.5-4.5				
Service Pack	20022	31-40	3.5-4.5				

◊ Programming Tool Required.

● Magnet Required to Activate Sensor.



PRINTED ON RECYCLED PAPER
WITH 100% POSTCONSUMER WASTE

Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
Kia - Continued							
2010 - Continued							
Forte							
Sensor	20092	31-40	3.5-4.5	Rondo - Continued			
Magentis; Optima				Service Pack; Does Not Include Valve	20021	31-40	3.5-4.5
Sensor; Includes Transmitter Only	20086	31-40	3.5-4.5	Service Pack; Includes Valve	20036	31-40	3.5-4.5
Service Pack; Does Not Include Valve	20021	31-40	3.5-4.5	Sedona			
Service Pack; Includes Valve	20036	31-40	3.5-4.5	Sensor; Includes Transmitter Only	20085	31-40	3.5-4.5
Rio				Service Pack; Does Not Include Valve	20021	31-40	3.5-4.5
Sensor	28849	35-35.7	3.5-4.5	Service Pack; Includes Valve	20036	31-40	3.5-4.5
Service Pack	20022	35-35.7	3.5-4.5	Sorento			
Rondo; Sedona				Sensor	28983	35-35.7	3.5-4.5
Sensor; Includes Transmitter Only	20086	31-40	3.5-4.5	Service Pack; Includes Valve	20036	35-35.7	3.5-4.5
Service Pack; Does Not Include Valve	20021	31-40	3.5-4.5	Service Pack; Does Not Include Valve	20021	35-35.7	3.5-4.5
Service Pack; Includes Valve	20036	31-40	3.5-4.5	Spectra			
Soul				Sensor	28849	35-35.7	3.5-4.5
Sensor	20092	31-40	3.5-4.5	Service Pack	20022	35-35.7	3.5-4.5
Sportage				Sportage			
Sensor	28849	31-40	3.5-4.5	Sensor	28983	31-40	3.5-4.5
Service Pack	20022	31-40	3.5-4.5	Service Pack; Includes Valve	20036	31-40	3.5-4.5
2009				Service Pack; Does Not Include Valve	20021	31-40	3.5-4.5
Amanti				2007			
Sensor	28983	35-35.7	3.5-4.5	Amanti			
Service Pack; Includes Valve	20036	35-35.7	3.5-4.5	Sensor	28983	35-35.7	3.5-4.5
Service Pack; Does Not Include Valve	20021	35-35.7	3.5-4.5	Service Pack; Includes Valve	20036	35-35.7	3.5-4.5
Borrego				Service Pack; Does Not Include Valve	20021	35-35.7	3.5-4.5
Sensor	28849	31-40	3.5-4.5	Optima			
Service Pack	20022	31-40	3.5-4.5	Sensor; Includes Transmitter Only	20086	31-40	3.5-4.5
Magentis; Optima				Service Pack; Does Not Include Valve	20021	31-40	3.5-4.5
Sensor; Includes Transmitter Only	20086	31-40	3.5-4.5	Service Pack; Includes Valve	20036	31-40	3.5-4.5
Service Pack; Does Not Include Valve	20021	31-40	3.5-4.5	Rio			
Service Pack; Includes Valve	20036	31-40	3.5-4.5	Sensor	28849	35-35.7	3.5-4.5
Rio				Service Pack	20022	35-35.7	3.5-4.5
Sensor	28849	35-35.7	3.5-4.5	Rondo			
Service Pack	20022	35-35.7	3.5-4.5	Sensor; Includes Transmitter Only	20086	31-40	3.5-4.5
Rondo; Sedona				Service Pack; Does Not Include Valve	20021	31-40	3.5-4.5
Sensor; Includes Transmitter Only	20086	31-40	3.5-4.5	Service Pack; Includes Valve	20036	31-40	3.5-4.5
Service Pack; Does Not Include Valve	20021	31-40	3.5-4.5	Sedona			
Service Pack; Includes Valve	20036	31-40	3.5-4.5	Sensor; Includes Transmitter Only	20085	31-40	3.5-4.5
Sorento				Service Pack; Does Not Include Valve	20021	31-40	3.5-4.5
Sensor	28983	35-35.7	3.5-4.5	Service Pack; Includes Valve	20036	31-40	3.5-4.5
Service Pack; Includes Valve	20036	35-35.7	3.5-4.5	Sorento			
Service Pack; Does Not Include Valve	20021	35-35.7	3.5-4.5	Sensor	28983	35-35.7	3.5-4.5
Spectra				Service Pack; Does Not Include Valve	20021	35-35.7	3.5-4.5
Sensor	28849	35-35.7	3.5-4.5	Spectra			
Service Pack	20022	35-35.7	3.5-4.5	Sensor	28849	35-35.7	3.5-4.5
Sportage				Service Pack	20022	35-35.7	3.5-4.5
Sensor	28849	31-40	3.5-4.5	Sportage			
Service Pack	20022	31-40	3.5-4.5	Sensor	28983	31-40	3.5-4.5
2008				Service Pack; Includes Valve	20036	31-40	3.5-4.5
Amanti				Service Pack; Does Not Include Valve	20021	31-40	3.5-4.5
Sensor	28983	35-35.7	3.5-4.5	2006			
Service Pack; Includes Valve	20036	35-35.7	3.5-4.5	Optima			
Service Pack; Does Not Include Valve	20021	35-35.7	3.5-4.5	Sensor; Includes Transmitter Only	20086	31-40	3.5-4.5
Magentis; Optima				Service Pack; Does Not Include Valve	20021	31-40	3.5-4.5
Sensor; Includes Transmitter Only	20086	31-40	3.5-4.5	Service Pack; Includes Valve	20036	31-40	3.5-4.5
Service Pack; Does Not Include Valve	20021	31-40	3.5-4.5	Sedona			
Service Pack; Includes Valve	20036	31-40	3.5-4.5	Sensor; Includes Transmitter Only	20085	31-40	3.5-4.5
Rio				Service Pack; Does Not Include Valve	20021	31-40	3.5-4.5
Sensor	28849	35-35.7	3.5-4.5	Service Pack; Includes Valve	20036	31-40	3.5-4.5
Service Pack	20022	35-35.7	3.5-4.5	Spectra			
Rondo				Sensor	28849	35-35.7	3.5-4.5
Sensor; Includes Transmitter Only	20086	31-40	3.5-4.5	Service Pack	20022	35-35.7	3.5-4.5



Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.				
Kia - Continued											
2006 - Continued											
Sportage											
Sensor	28983	31-40	3.5-4.5	EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
Service Pack; Includes Valve	20036	31-40	3.5-4.5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Service Pack; Does Not Include Valve ..	20021	31-40	3.5-4.5	Sensor	28370	35	4				
2005											
Sportage											
Sensor; Jun. 15, 2005 & Newer	28983	31-40	3.5-4.5	Service Pack	20032	35	4				
Service Pack; Jun. 15, 2005 & Newer; Includes Valve	20036	31-40	3.5-4.5	2012 - Continued							
Service Pack; Jun. 15, 2005 & Newer; Does Not Include Valve ..	20021	31-40	3.5-4.5	LFA - Continued							
Land Rover											
2011-2010											
LR2											
Sensor	20090	71	8	EZ-sensor - 315 MHz	◇33000	11.5	1.3				
Service Pack	20030	71	8	EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
LR4; Range Rover				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor; W/315 MHz Sensor	20090	71	8	Sensor	28345	35	4				
Sensor; W/433 MHz Sensor	20091	71	8	Service Pack	20032	35	4				
Service Pack	20030	71	8	HS250h							
2009											
LR2											
Sensor	20090	71	8	EZ-sensor - 315 MHz	◇33000	11.5	1.3				
Service Pack	20030	71	8	EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
LR3; Range Rover				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor; W/315 MHz Sensor	20090	71	8	Sensor	28370	35	4				
Sensor; W/433 MHz Sensor	20091	71	8	Service Pack	20032	35	4				
Service Pack	20030	71	8	2010							
2008											
LR2				ES350; GS350; GS450h; GS460; GX460							
Service Pack	20030	71	8	EZ-sensor - 315 MHz	◇33000	11.5	1.3				
LR3; Range Rover				EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
Sensor; W/315 MHz Sensor	20090	71	8	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor; W/433 MHz Sensor	20091	71	8	Sensor	28345	35	4				
Service Pack	20030	71	8	Service Pack	20032	35	4				
2007-2006				HS250h							
LR3; Range Rover											
Sensor; W/315 MHz Sensor	20090	71	8	EZ-sensor - 315 MHz	◇33000	11.5	1.3				
Sensor; W/433 MHz Sensor	20091	71	8	EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
Service Pack	20030	71	8	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
2005				Sensor	28370	35	4				
LR3; Range Rover				Service Pack	20032	35	4				
Sensor; Includes Transmitter Only	28082	58	6.5	IS250; IS350; IS F; LS460; LS600h; LX570							
Service Pack; Does Not Include Valve ..	20023	58	6.5	EZ-sensor - 315 MHz	◇33000	11.5	1.3				
Service Pack; W/43mm Silver Insert	20037	58	6.5	EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
Service Pack; W/48mm Green Insert ...	20038	58	6.5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Service Pack; W/49mm Black Insert	20039	58	6.5	Sensor	28370	35	4				
Service Pack; W/51mm Orange Insert ..	20040	58	6.5	Service Pack	20032	35	4				
2004-2002				RX350							
Range Rover											
Sensor; Includes Transmitter Only	28082	58	6.5	EZ-sensor - 315 MHz	◇33000	11.5	1.3				
Service Pack; Does Not Include Valve ..	20023	58	6.5	EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
Service Pack; W/43mm Silver Insert	20037	58	6.5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Service Pack; W/48mm Green Insert ...	20038	58	6.5	Sensor; Models made in Japan	28370	35	4				
Service Pack; W/49mm Black Insert	20039	58	6.5	Service Pack	20032	35	4				
Service Pack; W/51mm Orange Insert ..	20040	58	6.5	RX450h							
Lexus											
2012											
LFA											
EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3				
◊ Programming Tool Required.											



PRINTED ON RECYCLED PAPER
WITH 100% POSTCONSUMER WASTE

Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.				
Lexus - Continued											
2009-2008											
ES350; GS350; GS450h; GS460; GX470; IS250; IS350; IS F; LS460; LS600h; LX570											
EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	28370	35	4	Sensor; Apr. 1 & Newer	28370	35	4				
Service Pack	20032	35	4	Sensor; Mar. & Older	28335	35	4				
RX350; RX400h											
EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor; Models made in Japan.	28370	35	4	Sensor; Aug. & Newer	28370	35	4				
Service Pack	20032	35	4	Sensor; Jul. & Older	28365	35	4				
SC430											
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack; Aug. & Newer	20032	35	4				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Service Pack; Jul. & Older	20031	35	4				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	RX330							
Sensor	28370	27	3	EZ-sensor - 315 MHz	◇33000	11.5	1.3				
Service Pack	20032	27	3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
2007											
ES350; GS350; GS430; GS450h; GX470; IS250; IS350; LS460; LX470											
EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; Models made in Japan.; Feb. & Newer	28370	35	4				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack; Feb. & Newer	20032	35	4				
Sensor	28370	35	4	Service Pack; Jan. 31 & Older	20031	35	4				
Service Pack	20032	35	4	SC430							
RX350; RX400h											
EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor; Models made in Japan.	28370	35	4	Sensor; Aug. & Newer	28370	27	3				
Service Pack	20032	35	4	Sensor; W/White I.D. Mark; Jul. & Older	28310	27	3				
SC430											
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor; W/Blue I.D. Mark; Jul. & Older	28315	27	3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; W/Red I.D. Mark; Jul. & Older	28320	27	3				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; W/Gold I.D. Mark; Jul. & Older	28325	27	3				
Sensor	28370	27	3	Service Pack; Aug. & Newer	20032	27	3				
Service Pack	20032	27	3	2005							
GS300											
EZ-sensor - 315 MHz	◇33000	11.5	1.3	GS430							
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
Sensor	28370	27	3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Service Pack	20032	27	3	Sensor	28335	35	4				
2006											
GS430											
EZ-sensor - 315 MHz	◇33000	11.5	1.3	GX470							
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
Sensor	28370	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Service Pack	20031	35	4	Sensor	28345	35	4				
GX470											
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack	20031	35	4				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	LX470							
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3				
Sensor; Jul. & Newer	28370	35	4	EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
Sensor; Jun. & Older	28335	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Service Pack; Jul. & Newer	20032	35	4	Sensor	28365	35	4				
Service Pack; Jun. & Older	20031	35	4	Service Pack	20031	35	4				
2004											
GX470											
EZ-sensor - 315 MHz	◇33000	11.5	1.3	SC430							
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; W/White I.D. Mark	28310	27	3				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; W/Blue I.D. Mark	28315	27	3				
Sensor; Feb. & Newer; W/Valve Cap ...	28365	35	4	Sensor; W/Red I.D. Mark	28320	27	3				
Sensor; Feb. & Newer; W/O Valve Cap .	28335	35	4	Sensor; W/Gold I.D. Mark	28325	27	3				
Sensor; Jan. 31 & Older	28345	35	4	2004							
Service Pack; Feb. & Newer	20032	35	4	GX470							
Service Pack; Jan. 31 & Older	20031	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3				

◊ Programming Tool Required.



Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
Lexus - Continued							
2004 - Continued							
SC430							
Sensor; W/White I.D. Mark	28310	27	3	Sensor Clip	22100		
Sensor; W/Blue I.D. Mark	28315	27	3	Sensor Cradle	22101		
Sensor; W/Red I.D. Mark	28320	27	3	Sensor Universal Band	22102		
Sensor; W/Gold I.D. Mark	28325	27	3				
2003-2002							
SC430							
Sensor; W/White I.D. Mark	28310	27	3	EZ-sensor - 315 MHz	♦33000	11.5	1.3
Sensor; W/Blue I.D. Mark	28315	27	3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7
Sensor; W/Red I.D. Mark	28320	27	3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor; W/Gold I.D. Mark	28325	27	3	Sensor	28385	27	3
Lincoln							
2012							
MKS; MKT; MKX; MKZ; Navigator							
EZ-sensor - 315 MHz	♦33000	11.5	1.3	EZ-sensor - 315 MHz	♦33000	11.5	1.3
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Almmn. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor	20315	13	1.5	Sensor	28390	27	3
Service Pack	20018	13	1.5	Sensor Clip	22100		
2011							
MKS; MKT; MKX; MKZ; Navigator; Town Car							
EZ-sensor - 315 MHz	♦33000	11.5	1.3	EZ-sensor - 315 MHz	♦33000	11.5	1.3
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Almmn. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor	20315	13	1.5	Sensor	28385	27	3
2010							
MKS; MKT; MKX							
EZ-sensor - 315 MHz	♦33000	11.5	1.3	EZ-sensor - 315 MHz	♦33000	11.5	1.3
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Almmn. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor	28390	27	3	Sensor	28385	27	3
Sensor Clip	22100			Sensor Clip	22100		
Sensor Cradle	22101			Sensor Cradle	22101		
Sensor Universal Band	22102			Sensor Universal Band	22102		
MKZ							
EZ-sensor - 315 MHz	♦33000	11.5	1.3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	20315	13	1.5				
Service Pack	20018	13	1.5				
Navigator							
EZ-sensor - 315 MHz	♦33000	11.5	1.3	EZ-sensor - 315 MHz	♦33000	11.5	1.3
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Almmn. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor	28390	27	3	Sensor	28390	27	3
Sensor Clip	22100			Sensor Clip	22100		
Sensor Cradle	22101			Sensor Cradle	22101		
Sensor Universal Band	22102			Sensor Universal Band	22102		
Town Car							
EZ-sensor - 315 MHz	♦33000	11.5	1.3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	28385	27	3				
Sensor Clip	22100						
Sensor Cradle	22101						
Sensor Universal Band	22102						
2009							
MKS; MKX							
EZ-sensor - 315 MHz	♦33000	11.5	1.3	EZ-sensor - 315 MHz	♦33000	11.5	1.3
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Almmn. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor	28390	27	3	Sensor	28390	27	3
Sensor Clip	22100			Sensor Clip	22100		
Sensor Cradle	22101			Sensor Cradle	22101		
Sensor Universal Band	22102			Sensor Universal Band	22102		
Lincoln - Continued							
2009 - Continued							
MKS; MKX - Continued							
Sensor Clip	22100						
Sensor Cradle	22101						
Sensor Universal Band	22102						
MKZ							
EZ-sensor - 315 MHz	♦33000	11.5	1.3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	28385	27	3				
Sensor Clip	22100						
Sensor Cradle	22101						
Sensor Universal Band	22102						
Navigator							
EZ-sensor - 315 MHz	♦33000	11.5	1.3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	28390	27	3				
Sensor Clip	22100						
Sensor Cradle	22101						
Sensor Universal Band	22102						
Town Car							
EZ-sensor - 315 MHz	♦33000	11.5	1.3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	28385	27	3				
Sensor Clip	22100						
Sensor Cradle	22101						
Sensor Universal Band	22102						
2008							
Mark LT							
EZ-sensor - 315 MHz	♦33000	11.5	1.3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	28385	27	3				
Sensor Clip	22100						
Sensor Cradle	22101						
Sensor Universal Band	22102						
MKX							
EZ-sensor - 315 MHz	♦33000	11.5	1.3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor; W/Chrome Plated Almmn. Wheels	28385	27	3				
Sensor; W/O Chrome Plated Almmn. Wheels	28390	27	3				
Sensor Clip	22100						
Sensor Cradle	22101						
Sensor Universal Band	22102						
MKZ							
EZ-sensor - 315 MHz	♦33000	11.5	1.3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	28385	27	3				
Sensor Clip	22100						
Sensor Cradle	22101						
Sensor Universal Band	22102						
Navigator							
EZ-sensor - 315 MHz	♦33000	11.5	1.3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	28390	27	3				
Sensor Clip	22100						
Sensor Cradle	22101						
Sensor Universal Band	22102						

◊ Programming Tool Required.



PRINTED ON RECYCLED PAPER
WITH 100% POSTCONSUMER WASTE

Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
Lincoln - Continued							
2008 - Continued							
Town Car							
EZ-sensor - 315 MHz	◆33000	11.5	1.3	EZ-sensor - 433 MHz	◆33100	11.5	1.3
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Almmn. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor	28385	27	3	Sensor	●20096	44	5
Sensor Clip	22100			Service Pack	20002	44	5
Sensor Cradle	22101						
Sensor Universal Band	22102						
2007							
Mark LT							
EZ-sensor - 315 MHz	◆33000	11.5	1.3	EZ-sensor - 433 MHz	◆33100	11.5	1.3
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Almmn. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor	28385	27	3	Sensor	●20096	44	5
Sensor Clip	22100			Service Pack	20002	44	5
Sensor Cradle	22101						
Sensor Universal Band	22102						
MKX							
EZ-sensor - 315 MHz	◆33000	11.5	1.3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor; W/Chrome Plated Almmn. Wheels	28385	27	3				
Sensor Clip	22100						
Sensor Cradle	22101						
Sensor Universal Band	22102						
Sensor; W/O Chrome Plated Almmn. Wheels	28390	27	3				
MKZ							
EZ-sensor - 315 MHz	◆33000	11.5	1.3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	28385	27	3				
Sensor Clip	22100						
Sensor Cradle	22101						
Sensor Universal Band	22102						
Navigator							
EZ-sensor - 315 MHz	◆33000	11.5	1.3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	28390	27	3				
Sensor Clip	22100						
Sensor Cradle	22101						
Sensor Universal Band	22102						
Town Car							
EZ-sensor - 315 MHz	◆33000	11.5	1.3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	28385	27	3				
Sensor Clip	22100						
Sensor Cradle	22101						
Sensor Universal Band	22102						
2006							
Navigator							
Sensor	●20135	44	5				
Service Pack	20002	44	5				
Town Car							
EZ-sensor - 315 MHz	◆33000	11.5	1.3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	28385	27	3				
Sensor Clip	22100						
Sensor Cradle	22101						
Sensor Universal Band	22102						
2005							
Aviator							
EZ-sensor - 433 MHz	◆33100	11.5	1.3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	●20096	44	5				
Service Pack	20002	44	5				
Navigator							
Sensor	●20135	44	5				
Service Pack	20002	44	5				
2004-2003							
Aviator; Navigator							
EZ-sensor - 433 MHz	◆33100	11.5	1.3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	●20096	44	5				
Service Pack	20002	44	5				
Maserati							
2006							
Coupe; GranSport; MC12; Quattroporte; Spyder							
Service Pack; Does Not Include Valve ..	20023						
Service Pack; W/43mm Silver Insert	20037						
Service Pack; W/48mm Green Insert ...	20038						
Service Pack; W/49mm Black Insert	20039						
Service Pack; W/51mm Orange Insert ..	20040						
2005-2004							
Coupe; GranSport; Quattroporte; Spyder							
Service Pack; Does Not Include Valve ..	20023						
Service Pack; W/43mm Silver Insert	20037						
Service Pack; W/48mm Green Insert ...	20038						
Service Pack; W/49mm Black Insert	20039						
Service Pack; W/51mm Orange Insert ..	20040						
2005							
Mazda							
2011							
2; 3; 6; CX-7; CX-9; MX-5 Miata; RX-8; Tribute							
Sensor	20093	71	8				
Service Pack	20030	71	8				
2010							
3; 5; 6; CX-7; CX-9; MX-5 Miata; RX-8							
Sensor	20093	71	8				
Service Pack	20030	71	8				
Tribute							
EZ-sensor - 315 MHz	◆33000	11.5	1.3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	20315	13	1.5				
Service Pack	20018	13	1.5				
2009							
3; 5; 6							
Sensor	20093	71	8				
Service Pack	20030	71	8				
B2300 Pickup; B4000 Pickup							
EZ-sensor - 315 MHz	◆33000	11.5	1.3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	28385	27	3				
Sensor Clip	22100						
Sensor Cradle	22101						
Sensor Universal Band	22102						
CX-7; CX-9; MX-5 Miata; RX-8							
Sensor	20093	71	8				
Service Pack	20030	71	8				

❖ Programming Tool Required

- Magnet Required to Activate Sensor.



PRINTED ON RECYCLED PAPER
WITH 100% POSTCONSUMER WASTE

Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
Mazda - Continued				Mercedes-Benz			
2009 - Continued				2012			
Tribute				C63; C250; C350; CL63; CL65; CL550; CL600; CLS63; CLS550; E350; GLK350; ML350; R350; SL63; SL550; SLK250; SLK350; SLS			
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor	28214	58	6.5
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Service Pack; Does Not Include Stem ..	20016	58	6.5
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack; Includes Stem Only	20020	58	6.5
Sensor	20315	13	1.5				
Service Pack	20018	13	1.5				
2008				2011			
3; 5; 6				C63; C300; C350; CL63; CL65; CL550			
Sensor	20093	71	8	Sensor	28214	58	6.5
Service Pack	20030	71	8	Service Pack; Does Not Include Stem ..	20016	58	6.5
B2300 Pickup; B3000 Pickup; B4000 Pickup				Service Pack; Includes Stem Only	20020	58	6.5
EZ-sensor - 315 MHz	◇33000	11.5	1.3	CLS63; CLS550			
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor	20094	53	6
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack; Does Not Include Valve ..	20021	53	6
Sensor	28385	27	3	Service Pack; Includes Valve	20036	53	6
Sensor Clip	22100			E63; E350; E550			
Sensor Cradle	22101			Sensor	28214	58	6.5
Sensor Universal Band	22102			Service Pack; Does Not Include Stem ..	20016	58	6.5
CX-7; CX-9; MX-5 Miata; RX-8				Service Pack; Includes Stem Only	20020	58	6.5
Sensor	20093	71	8	G55; G550; GL350; GL450; GL550; GLK350; ML63; ML350; ML450; ML550; R350			
Service Pack	20030	71	8	Sensor	28214	58	6.5
Tribute				Service Pack; Mar. & Newer; Does Not Include Stem ..	20016	58	6.5
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack; Mar. & Newer; Includes Stem Only	20020	58	6.5
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	S63; S65; S400; S550; S600			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor	28214	58	6.5
Sensor	28385	27	3	Service Pack; Does Not Include Stem ..	20016	58	6.5
Sensor Clip	22100			Service Pack; Includes Stem Only	20020	58	6.5
Sensor Cradle	22101			SL63; SL65			
Sensor Universal Band	22102			Sensor	20094	53	6
2007				SLK300; SLK350; SLS			
3; 5				Sensor	28214	58	6.5
Sensor	20093	71	8	Service Pack; Does Not Include Stem ..	20016	58	6.5
Service Pack	20030	71	8	Service Pack; Includes Stem Only	20020	58	6.5
B2300 Pickup; B3000 Pickup; B4000 Pickup				2010			
EZ-sensor - 315 MHz	◇33000	11.5	1.3	C63; C300; C350; CL63; CL65; CL550; CL600			
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor	28214	58	6.5
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack; Does Not Include Stem ..	20016	58	6.5
Sensor	28385	27	3	Service Pack; Includes Stem Only	20020	58	6.5
Sensor Clip	22100			CLS63; CLS550			
Sensor Cradle	22101			Sensor	20094	53	6
Sensor Universal Band	22102			Service Pack; Does Not Include Valve ..	20021	53	6
CX-7; CX-9; MX-5 Miata; RX-8				Service Pack; Includes Valve	20036	53	6
Sensor	20093	71	8	E63; E350; E550; G55; G550; GL350; GL450; GL550; GLK350; ML63; ML350; ML450; ML550; R350			
Service Pack	20030	71	8	Sensor	28214	58	6.5
2006				Service Pack; Does Not Include Stem ..	20016	58	6.5
3; 5; MX-5 Miata; RX-8				Service Pack; Includes Stem Only	20020	58	6.5
Sensor	20093	71	8	S63; S65; S400; S550; S600			
Service Pack	20030	71	8	Sensor	20094	53	6
Tribute				Service Pack; Does Not Include Valve ..	20021	53	6
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack; Includes Valve	20036	53	6
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	SLK55; SLK300; SLK350			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor	28214	58	6.5
Sensor	28385	27	3	Service Pack; Does Not Include Stem ..	20016	58	6.5
Sensor Clip	22100			Service Pack; Includes Stem Only	20020	58	6.5
Sensor Cradle	22101			2009			
Sensor Universal Band	22102			C63; C300; C350			
2005-2004				Sensor	28214	58	6.5
3; RX-8				Service Pack; Does Not Include Stem ..	20016	58	6.5
Sensor	20093	71	8	Service Pack; Includes Stem Only	20020	58	6.5
Service Pack	20030	71	8				

◊ Programming Tool Required.



PRINTED ON RECYCLED PAPER
WITH 100% POSTCONSUMER WASTE

Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
Mercedes-Benz - Continued				Mercedes-Benz - Continued			
2009 - Continued				2008 - Continued			
CL63; CL65; CL550; CL600							
Sensor	20094	53	6	Service Pack; Includes Stem Only	20020	58	6.5
Service Pack; Does Not Include Valve ..	20021	53	6	Service Pack; Does Not Include Valve ..	20021	53	6
Service Pack; Includes Valve	20036	53	6	Service Pack; Includes Valve	20036	53	6
CLK63; CLK350; CLK550							
Sensor	28214	58	6.5	Sensor	20095	53	6
Service Pack; Does Not Include Stem ..	20016	58	6.5	Service Pack; W/43mm Silver Insert	20037	53	6
Service Pack; Includes Stem Only	20020	58	6.5	Service Pack; W/48mm Green Insert ...	20038	53	6
CLS63; CLS550; E63; E320							
Sensor	20094	53	6	Service Pack; W/49mm Black Insert	20039	53	6
Service Pack; Does Not Include Valve ..	20021	53	6	Service Pack; W/51mm Orange Insert ..	20040	53	6
Service Pack; Includes Valve	20036	53	6	S63; S65; S550; S600; SL55; SL65; SL550; SL600			
E350; E550							
Sensor; W/315 MHz Sensor	20094	53	6	Sensor	20094	53	6
Sensor; W/433 MHz Sensor	20095	53	6	Service Pack; Does Not Include Valve ..	20021	53	6
Service Pack; Does Not Include Valve ..	20021	53	6	Service Pack; Includes Valve	20036	53	6
Service Pack; Includes Valve	20036	53	6	SLK55; SLK280; SLK350			
G55; G500							
Sensor	28214	58	6.5	Sensor	28214	58	6.5
Service Pack; Does Not Include Stem ..	20016	58	6.5	Service Pack; Does Not Include Stem ..	20016	58	6.5
Service Pack; Includes Stem Only	20020	58	6.5	Service Pack; Includes Stem Only	20020	58	6.5
GL320; GL450; GL550; ML63; ML320; ML350; ML550; R320; R350				SLR McLaren			
Sensor	20095	53	6	Sensor	20094	53	6
Service Pack; Does Not Include Valve ..	20021	53	6	Service Pack; Does Not Include Valve ..	20021	53	6
Service Pack; Includes Valve	20036	53	6	Service Pack; Includes Valve	20036	53	6
S63; S65; S550; S600; SL63; SL65; SL550; SL600				2007			
Sensor	20094	53	6	C350			
Service Pack; Does Not Include Valve ..	20021	53	6	Sensor; Jun. & Newer	28214	58	6.5
Service Pack; Includes Valve	20036	53	6	Service Pack; Jun. & Newer; Does Not Include Stem	20016	58	6.5
SLK55; SLK300; SLK350				Service Pack; Jun. & Newer; Includes Stem Only	20020	58	6.5
Sensor	28214	58	6.5	CL63; CL550; CL600			
Service Pack; Does Not Include Stem ..	20016	58	6.5	Sensor	20094	53	6
Service Pack; Includes Stem Only	20020	58	6.5	Service Pack; Does Not Include Valve ..	20021	53	6
SLR McLaren				Service Pack; Includes Valve	20036	53	6
Sensor	20094	53	6	CLK63; CLK350; CLK550			
Service Pack; Does Not Include Valve ..	20021	53	6	Sensor	28214	58	6.5
Service Pack; Includes Valve	20036	53	6	Service Pack; Does Not Include Stem ..	20016	58	6.5
2008				Service Pack; Includes Stem Only	20020	58	6.5
C63; C300; C350				CLS63; CLS550; E63; E320			
Sensor	28214	58	6.5	Sensor	20094	53	6
Service Pack; Does Not Include Stem ..	20016	58	6.5	Service Pack; Does Not Include Valve ..	20021	53	6
Service Pack; Includes Stem Only	20020	58	6.5	Service Pack; Includes Valve	20036	53	6
CL63; CL65; CL550; CL600				E350; E550			
Sensor	20094	53	6	Sensor; W/315 MHz Sensor	20094	53	6
Service Pack; Does Not Include Valve ..	20021	53	6	Sensor; W/433 MHz Sensor	20095	53	6
Service Pack; Includes Valve	20036	53	6	Service Pack; Does Not Include Valve ..	20021	53	6
CLK63; CLK350; CLK550				Service Pack; Includes Valve	20036	53	6
Sensor	28214	58	6.5	G55; G500			
Service Pack; Does Not Include Stem ..	20016	58	6.5	Sensor; Mar. & Newer	28214	58	6.5
Service Pack; Includes Stem Only	20020	58	6.5	Service Pack; Mar. & Newer; Does Not Include Stem	20016	58	6.5
CLS63; CLS550; E63; E320				Service Pack; Mar. & Newer; Includes Stem Only	20020	58	6.5
Sensor	20094	53	6	GL320; GL450; ML63; ML320; ML350; ML550; R63; R320; R350; R500			
Service Pack; Does Not Include Valve ..	20021	53	6	Sensor	20095	53	6
Service Pack; Includes Valve	20036	53	6	Service Pack; Does Not Include Valve ..	20021	53	6
E350; E550				Service Pack; Includes Valve	20036	53	6
Sensor; W/315 MHz Sensor	20094	53	6	S63; S65; S550; S600; SL55; SL65; SL550; SL600			
Sensor; W/433 MHz Sensor	20095	53	6	Sensor	20094	53	6
Service Pack; Does Not Include Valve ..	20021	53	6	Service Pack; Does Not Include Valve ..	20021	53	6
Service Pack; Includes Valve	20036	53	6	Service Pack; Includes Valve	20036	53	6
G55; G500				2009			
Sensor	28214	58	6.5	Sensor	20094	53	6
Service Pack; Does Not Include Stem ..	20016	58	6.5	Service Pack; Does Not Include Valve ..	20021	53	6



Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
Mercedes-Benz - Continued				Mercedes-Benz - Continued			
2007 - Continued				2004			
SLK55; SLK280; SLK350				CL55; CL500; CL600; E55; E320; E500; S55; S430; S500; S600; SL55; SL500; SL600; SLR McLaren			
Sensor; May & Newer	28214	58	6.5	Service Pack; Does Not Include Valve ..	20023	35	4
Service Pack; May & Newer; Does Not Include Stem	20016	58	6.5	Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; May & Newer; Includes Stem Only	20020	58	6.5	Service Pack; W/48mm Green Insert	20038	35	4
SLR McLaren				Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; Does Not Include Valve ..	20023	53	6	Service Pack; W/51mm Orange Insert ..	20040	35	4
Service Pack; W/43mm Silver Insert	20037	53	6	2003			
Service Pack; W/48mm Green Insert	20038	53	6	CL55; CL500; CL600; E55; E320; E500; S55; S430; S500; S600; SL55; SL500			
Service Pack; W/49mm Black Insert	20039	53	6	Service Pack; Does Not Include Valve ..	20023	35	4
Service Pack; W/51mm Orange Insert ..	20040	53	6	Service Pack; W/43mm Silver Insert	20037	35	4
2006				Service Pack; W/48mm Green Insert	20038	35	4
CL55; CL65; CL500; CL600				Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; Does Not Include Valve ..	20023	35	4	Service Pack; W/51mm Orange Insert ..	20040	35	4
Service Pack; W/43mm Silver Insert	20037	35	4	2002-2001			
Service Pack; W/48mm Green Insert	20038	35	4	CL55; CL500; CL600; E55; E320; E430; S55; S430; S500; S600; SL500; SL600			
Service Pack; W/49mm Black Insert	20039	35	4	Service Pack; Does Not Include Valve ..	20023	35	4
Service Pack; W/51mm Orange Insert ..	20040	35	4	Service Pack; W/43mm Silver Insert	20037	35	4
CLK55; CLK350; CLK500				Service Pack; W/48mm Green Insert	20038	35	4
Sensor	28214	58	6.5	Service Pack; W/49mm Black Insert	20039	35	4
Service Pack; Does Not Include Stem ..	20016	58	6.5	Service Pack; W/51mm Orange Insert ..	20040	35	4
Service Pack; Includes Stem Only	20020	58	6.5	2000			
CLS55; CLS500; E55; E320				CL500; E55; S430; S500			
Sensor	20094	53	6	Service Pack; Does Not Include Valve ..	20023	35	4
Service Pack; Does Not Include Valve ..	20021	53	6	Service Pack; W/43mm Silver Insert	20037	35	4
Service Pack; Includes Valve	20036	53	6	Service Pack; W/48mm Green Insert	20038	35	4
E350				Service Pack; W/49mm Black Insert	20039	35	4
Sensor; W/315 MHz Sensor	20094	53	6	Service Pack; W/51mm Orange Insert ..	20040	35	4
Sensor; W/433 MHz Sensor	20095	53	6	1999			
Service Pack; Does Not Include Valve ..	20021	53	6	E55			
Service Pack; Includes Valve	20036	53	6	Service Pack; Does Not Include Valve; Jul. & Newer	20023	35	4
ML350; ML500; R350; R500				Service Pack; W/43mm Silver Insert; Jul. & Newer	20037	35	4
Sensor	20095	53	6	Service Pack; W/48mm Green Insert; Jul. & Newer	20038	35	4
Service Pack; Does Not Include Valve ..	20021	53	6	Service Pack; W/49mm Black Insert; Jul. & Newer	20039	35	4
Service Pack; Includes Valve	20036	53	6	Service Pack; W/51mm Orange Insert; Jul. & Newer	20040	35	4
S55; S65; S350; S430; S500; S600				Mercury			
Service Pack; Does Not Include Valve ..	20023	35	4	2011			
Service Pack; W/43mm Silver Insert	20037	35	4	Grand Marquis; Mariner; Milan			
Service Pack; W/48mm Green Insert	20038	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3
Service Pack; W/49mm Black Insert	20039	35	4	EZ-sensor Service Pack; Almm. Valve ..	34000	62	7
Service Pack; W/51mm Orange Insert ..	20040	35	4	EZ-sensor Service Pack; Rubber Valve ..	20008	11.5	1.3
SL55; SL65; SL500; SL600				Sensor	20315	13	1.5
Sensor	20094	53	6	2010			
Service Pack; Does Not Include Valve ..	20021	53	6	Grand Marquis			
Service Pack; Includes Valve	20036	53	6	EZ-sensor - 315 MHz	◇33000	11.5	1.3
SLR McLaren				EZ-sensor Service Pack; Almm. Valve ..	34000	62	7
Service Pack; Does Not Include Valve ..	20023	35	4	EZ-sensor Service Pack; Rubber Valve ..	20008	11.5	1.3
Service Pack; W/43mm Silver Insert	20037	35	4	Sensor	28385	27	3
Service Pack; W/48mm Green Insert	20038	35	4	Sensor Clip	22100		
Service Pack; W/49mm Black Insert	20039	35	4	Sensor Cradle	22101		
Service Pack; W/51mm Orange Insert ..	20040	35	4	Sensor Universal Band	22102		
2005				Mariner; Milan			
CL55; CL65; CL500; CL600; E55; E320; E500; S55; S430; S500; S600; SL55; SL65; SL500; SL600; SLR McLaren				EZ-sensor - 315 MHz	◇33000	11.5	1.3
Service Pack; Does Not Include Valve ..	20023	35	4	EZ-sensor Service Pack; Almm. Valve ..	34000	62	7
Service Pack; W/43mm Silver Insert	20037	35	4	EZ-sensor Service Pack; Rubber Valve ..	20008	11.5	1.3
Service Pack; W/48mm Green Insert	20038	35	4	Sensor	28385	27	3
Service Pack; W/49mm Black Insert	20039	35	4	Sensor Clip	22100		
Service Pack; W/51mm Orange Insert ..	20040	35	4	Sensor Cradle	22101		
Grand Tool Required.				Sensor Universal Band	22102		



Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																								
Mercury - Continued																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																															
2010 - Continued																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																															
Mariner; Milan - Continued																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																															
Sensor	20315	13	1.5	Sensor	28385	27	3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																								
Service Pack	20018	13	1.5	Sensor Clip	22100																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																										
Mountaineer																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																															
EZ-sensor - 315 MHz	◆33000	11.5	1.3	Sensor Cradle	22101																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																										
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor Universal Band	22102																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																										
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Grand Marquis; Mariner; Milan - Continued																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
Sensor	28385	27	3	Sensor Clip	22100			EZ-sensor - 315 MHz	◆33000	11.5	1.3	Sensor Cradle	22101			EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor Universal Band	22102			EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	2009				Sensor	28390	27	3	Grand Marquis				Sensor Clip	22100			EZ-sensor - 315 MHz	◆33000	11.5	1.3	Sensor Cradle	22101			EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor Universal Band	22102			EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Monterey Van; Mountaineer								Sensor	28385	27	3	Sensor Clip	22100			EZ-sensor - 315 MHz	◆33000	11.5	1.3	Sensor Cradle	22101			EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor Universal Band	22102			EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Mariner				Sensor	28385	27	3	EZ-sensor - 315 MHz	◆33000	11.5	1.3	Sensor Clip	22100			EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor Cradle	22101			EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor Universal Band	22102			Sensor	20315	13	1.5	2006								Service Pack	20018	13	1.5	Grand Marquis; Mariner								Grand Marquis; Mariner				EZ-sensor - 315 MHz	◆33000	11.5	1.3	EZ-sensor - 315 MHz	◆33000	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor	28385	27	3	Sensor	28385	27	3	Sensor Clip	22100			Sensor Clip	22100			Sensor Cradle	22101			Sensor Cradle	22101			Sensor Universal Band	22102			Sensor Universal Band	22102			Milan; Mountaineer				Montego								EZ-sensor - 315 MHz	◆33000	11.5	1.3	EZ-sensor - 315 MHz	◆33000	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor	28385	27	3	Sensor	28390	27	3	Sensor Clip	22100			Sensor Clip	22100			Sensor Cradle	22101			Sensor Cradle	22101			Sensor Universal Band	22102			Sensor Universal Band	22102			Sable				Monterey Van; Mountaineer								EZ-sensor - 315 MHz	◆33000	11.5	1.3	EZ-sensor - 315 MHz	◆33000	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor	28390	27	3	Sensor	28385	27	3	Sensor Clip	22100			Sensor Clip	22100			Sensor Cradle	22101			Sensor Cradle	22101			Sensor Universal Band	22102			Sensor Universal Band	22102			2008				2005								Grand Marquis; Mariner; Milan; Mountaineer								Mariner				EZ-sensor - 315 MHz	◆33000	11.5	1.3	EZ-sensor - 315 MHz	◆33000	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor	28385	27	3	Sensor	28385	27	3	Sensor Clip	22100			Sensor Clip	22100			Sensor Cradle	22101			Sensor Cradle	22101			Sensor Universal Band	22102			Sensor Universal Band	22102			Sable				Monterey Van								EZ-sensor - 315 MHz	◆33000	11.5	1.3	Sensor	●20135	44	5	EZ-sensor Service Pack; Almm. Valve	34000	62	7	Service Pack	20002	44	5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Mountaineer								Sensor	28390	27	3	EZ-sensor - 433 MHz	◆33100	11.5	1.3	Sensor Clip	22100			EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor Cradle	22101			EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor Universal Band	22102			Sensor	●20096	44	5	2007				Service Pack	20002	44	5	Grand Marquis; Mariner; Milan				◆ Programming Tool Required.								EZ-sensor - 315 MHz	◆33000	11.5	1.3	● Magnet Required to Activate Sensor.								EZ-sensor Service Pack; Almm. Valve	34000	62	7									EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3								
Sensor Clip	22100			EZ-sensor - 315 MHz	◆33000	11.5	1.3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																								
Sensor Cradle	22101			EZ-sensor Service Pack; Almm. Valve	34000	62	7																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																								
Sensor Universal Band	22102			EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																								
2009				Sensor	28390	27	3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																								
Grand Marquis				Sensor Clip	22100																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																										
EZ-sensor - 315 MHz	◆33000	11.5	1.3	Sensor Cradle	22101																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																										
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor Universal Band	22102																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																										
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Monterey Van; Mountaineer																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
Sensor	28385	27	3	Sensor Clip	22100			EZ-sensor - 315 MHz	◆33000	11.5	1.3	Sensor Cradle	22101			EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor Universal Band	22102			EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Mariner				Sensor	28385	27	3	EZ-sensor - 315 MHz	◆33000	11.5	1.3	Sensor Clip	22100			EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor Cradle	22101			EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor Universal Band	22102			Sensor	20315	13	1.5	2006								Service Pack	20018	13	1.5	Grand Marquis; Mariner								Grand Marquis; Mariner				EZ-sensor - 315 MHz	◆33000	11.5	1.3	EZ-sensor - 315 MHz	◆33000	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor	28385	27	3	Sensor	28385	27	3	Sensor Clip	22100			Sensor Clip	22100			Sensor Cradle	22101			Sensor Cradle	22101			Sensor Universal Band	22102			Sensor Universal Band	22102			Milan; Mountaineer				Montego								EZ-sensor - 315 MHz	◆33000	11.5	1.3	EZ-sensor - 315 MHz	◆33000	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor	28385	27	3	Sensor	28390	27	3	Sensor Clip	22100			Sensor Clip	22100			Sensor Cradle	22101			Sensor Cradle	22101			Sensor Universal Band	22102			Sensor Universal Band	22102			Sable				Monterey Van; Mountaineer								EZ-sensor - 315 MHz	◆33000	11.5	1.3	EZ-sensor - 315 MHz	◆33000	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor	28390	27	3	Sensor	28385	27	3	Sensor Clip	22100			Sensor Clip	22100			Sensor Cradle	22101			Sensor Cradle	22101			Sensor Universal Band	22102			Sensor Universal Band	22102			2008				2005								Grand Marquis; Mariner; Milan; Mountaineer								Mariner				EZ-sensor - 315 MHz	◆33000	11.5	1.3	EZ-sensor - 315 MHz	◆33000	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor	28385	27	3	Sensor	28385	27	3	Sensor Clip	22100			Sensor Clip	22100			Sensor Cradle	22101			Sensor Cradle	22101			Sensor Universal Band	22102			Sensor Universal Band	22102			Sable				Monterey Van								EZ-sensor - 315 MHz	◆33000	11.5	1.3	Sensor	●20135	44	5	EZ-sensor Service Pack; Almm. Valve	34000	62	7	Service Pack	20002	44	5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Mountaineer								Sensor	28390	27	3	EZ-sensor - 433 MHz	◆33100	11.5	1.3	Sensor Clip	22100			EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor Cradle	22101			EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor Universal Band	22102			Sensor	●20096	44	5	2007				Service Pack	20002	44	5	Grand Marquis; Mariner; Milan				◆ Programming Tool Required.								EZ-sensor - 315 MHz	◆33000	11.5	1.3	● Magnet Required to Activate Sensor.								EZ-sensor Service Pack; Almm. Valve	34000	62	7									EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3																																																																																
Sensor Clip	22100			EZ-sensor - 315 MHz	◆33000	11.5	1.3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																								
Sensor Cradle	22101			EZ-sensor Service Pack; Almm. Valve	34000	62	7																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																								
Sensor Universal Band	22102			EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																								
Mariner				Sensor	28385	27	3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																								
EZ-sensor - 315 MHz	◆33000	11.5	1.3	Sensor Clip	22100																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																										
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor Cradle	22101																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																										
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor Universal Band	22102																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																										
Sensor	20315	13	1.5	2006																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
Service Pack	20018	13	1.5	Grand Marquis; Mariner								Grand Marquis; Mariner				EZ-sensor - 315 MHz	◆33000	11.5	1.3	EZ-sensor - 315 MHz	◆33000	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor	28385	27	3	Sensor	28385	27	3	Sensor Clip	22100			Sensor Clip	22100			Sensor Cradle	22101			Sensor Cradle	22101			Sensor Universal Band	22102			Sensor Universal Band	22102			Milan; Mountaineer				Montego								EZ-sensor - 315 MHz	◆33000	11.5	1.3	EZ-sensor - 315 MHz	◆33000	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor	28385	27	3	Sensor	28390	27	3	Sensor Clip	22100			Sensor Clip	22100			Sensor Cradle	22101			Sensor Cradle	22101			Sensor Universal Band	22102			Sensor Universal Band	22102			Sable				Monterey Van; Mountaineer								EZ-sensor - 315 MHz	◆33000	11.5	1.3	EZ-sensor - 315 MHz	◆33000	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor	28390	27	3	Sensor	28385	27	3	Sensor Clip	22100			Sensor Clip	22100			Sensor Cradle	22101			Sensor Cradle	22101			Sensor Universal Band	22102			Sensor Universal Band	22102			2008				2005								Grand Marquis; Mariner; Milan; Mountaineer								Mariner				EZ-sensor - 315 MHz	◆33000	11.5	1.3	EZ-sensor - 315 MHz	◆33000	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor	28385	27	3	Sensor	28385	27	3	Sensor Clip	22100			Sensor Clip	22100			Sensor Cradle	22101			Sensor Cradle	22101			Sensor Universal Band	22102			Sensor Universal Band	22102			Sable				Monterey Van								EZ-sensor - 315 MHz	◆33000	11.5	1.3	Sensor	●20135	44	5	EZ-sensor Service Pack; Almm. Valve	34000	62	7	Service Pack	20002	44	5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Mountaineer								Sensor	28390	27	3	EZ-sensor - 433 MHz	◆33100	11.5	1.3	Sensor Clip	22100			EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor Cradle	22101			EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor Universal Band	22102			Sensor	●20096	44	5	2007				Service Pack	20002	44	5	Grand Marquis; Mariner; Milan				◆ Programming Tool Required.								EZ-sensor - 315 MHz	◆33000	11.5	1.3	● Magnet Required to Activate Sensor.								EZ-sensor Service Pack; Almm. Valve	34000	62	7									EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3																																																																																																																																																								
Grand Marquis; Mariner								Grand Marquis; Mariner																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																							
EZ-sensor - 315 MHz	◆33000	11.5	1.3	EZ-sensor - 315 MHz	◆33000	11.5	1.3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																								
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																								
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																								
Sensor	28385	27	3	Sensor	28385	27	3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																								
Sensor Clip	22100			Sensor Clip	22100																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																										
Sensor Cradle	22101			Sensor Cradle	22101																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																										
Sensor Universal Band	22102			Sensor Universal Band	22102																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																										
Milan; Mountaineer				Montego																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
EZ-sensor - 315 MHz	◆33000	11.5	1.3	EZ-sensor - 315 MHz	◆33000	11.5	1.3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																								
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																								
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																								
Sensor	28385	27	3	Sensor	28390	27	3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																								
Sensor Clip	22100			Sensor Clip	22100																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																										
Sensor Cradle	22101			Sensor Cradle	22101																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																										
Sensor Universal Band	22102			Sensor Universal Band	22102																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																										
Sable				Monterey Van; Mountaineer																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
EZ-sensor - 315 MHz	◆33000	11.5	1.3	EZ-sensor - 315 MHz	◆33000	11.5	1.3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																								
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																								
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																								
Sensor	28390	27	3	Sensor	28385	27	3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																								
Sensor Clip	22100			Sensor Clip	22100																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																										
Sensor Cradle	22101			Sensor Cradle	22101																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																										
Sensor Universal Band	22102			Sensor Universal Band	22102																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																										
2008				2005																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
Grand Marquis; Mariner; Milan; Mountaineer								Mariner																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																							
EZ-sensor - 315 MHz	◆33000	11.5	1.3	EZ-sensor - 315 MHz	◆33000	11.5	1.3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																								
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																								
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																								
Sensor	28385	27	3	Sensor	28385	27	3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																								
Sensor Clip	22100			Sensor Clip	22100																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																										
Sensor Cradle	22101			Sensor Cradle	22101																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																										
Sensor Universal Band	22102			Sensor Universal Band	22102																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																										
Sable				Monterey Van																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
EZ-sensor - 315 MHz	◆33000	11.5	1.3	Sensor	●20135	44	5																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																								
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Service Pack	20002	44	5																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																								
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Mountaineer																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
Sensor	28390	27	3	EZ-sensor - 433 MHz	◆33100	11.5	1.3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																								
Sensor Clip	22100			EZ-sensor Service Pack; Almm. Valve	34000	62	7																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																								
Sensor Cradle	22101			EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																								
Sensor Universal Band	22102			Sensor	●20096	44	5																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																								
2007				Service Pack	20002	44	5																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																								
Grand Marquis; Mariner; Milan				◆ Programming Tool Required.																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
EZ-sensor - 315 MHz	◆33000	11.5	1.3	● Magnet Required to Activate Sensor.																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
EZ-sensor Service Pack; Almm. Valve	34000	62	7																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																												
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																												



Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
Mercury - Continued				Mitsubishi - Continued			
2004				2010			
Monterey Van				Eclipse; Endeavor			
Sensor	●20135	44	5	EZ-sensor - 315 MHz	△33000	11.5	1.3
Service Pack	20002	44	5	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Mountaineer				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor - 433 MHz	△33100	11.5	1.3	Sensor	●20034	45-53	5-6
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Service Pack	20003	45-53	5-6
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Galant			
Sensor	●20096	44	5	EZ-sensor - 315 MHz	△33000	11.5	1.3
Service Pack	20002	44	5	EZ-sensor Service Pack; Almm. Valve	34000	62	7
2003-2002				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Mountaineer				Sensor; W/Alloy Wheels	20034	49	5.5
EZ-sensor - 433 MHz	△33100	11.5	1.3	Sensor; W/Steel Wheels	28129	45-53	5-6
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Lancer; Outlander			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor	28096	71	8
Sensor	●20096	44	5	Service Pack	20030	71	8
Service Pack	20002	44	5	2009			
Mini				Eclipse			
2012				EZ-sensor - 315 MHz	△33000	11.5	1.3
Cooper				EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor; Includes Transmitter Only	28081	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Service Pack; Does Not Include Valve .	20023	35	4	Sensor	●20034	45-53	5-6
2011				Service Pack	20003	45-53	5-6
Cooper				Galant			
Sensor; Includes Transmitter Only	28081	35	4	EZ-sensor - 315 MHz	△33000	11.5	1.3
Service Pack; Does Not Include Valve .	20023	35	4	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Service Pack; W/43mm Silver Insert	20037	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Service Pack; W/48mm Green Insert ...	20038	35	4	Sensor; W/Alloy Wheels	●20034	45-53	5-6
Service Pack; W/49mm Black Insert	20039	35	4	Sensor; W/Steel Wheels	28129	45-53	5-6
Service Pack; W/51mm Orange Insert .	20040	35	4	Service Pack; W/Alloy Wheels	20003	45-53	5-6
2009-2008				Service Pack; W/Steel Wheels	20010	45-53	5-6
Cooper				Lancer; Outlander			
Sensor; Includes Transmitter Only	20083	35	4	Sensor	28096	71	8
Service Pack; Does Not Include Valve .	20023	35	4	Service Pack	20030	71	8
Service Pack; W/43mm Silver Insert	20037	35	4	Raider			
Service Pack; W/48mm Green Insert ...	20038	35	4	EZ-sensor - 315 MHz	△33000	11.5	1.3
Service Pack; W/49mm Black Insert	20039	35	4	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Service Pack; W/51mm Orange Insert .	20040	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Mitsubishi				Sensor	28154	58	6.5
2011				or	28461	11.5	1.3
Eclipse; Endeavor				Service Pack; Does Not Include Stem ..	20013	58	6.5
EZ-sensor - 315 MHz	△33000	11.5	1.3	Service Pack; Includes Stem Only	20020	58	6.5
EZ-sensor Service Pack; Almm. Valve	34000	62	7	2008			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Eclipse; Endeavor			
Sensor	20034	49	5.5	EZ-sensor - 315 MHz	△33000	11.5	1.3
Galant				EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor - 315 MHz	△33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor	●20034	45-53	5-6
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack	20003	45-53	5-6
Sensor; W/Alloy Wheels	20034	49	5.5	Galant			
Sensor; W/Steel Wheels	28129	45-53	5-6	EZ-sensor - 315 MHz	△33000	11.5	1.3
Lancer; Outlander				EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor; W/Alloy Wheels	20398	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor; W/Steel Wheels	28096	71	8	Sensor	●20034	45-53	5-6
Service Pack; W/Steel Wheels	20030	71	8	Sensor; W/Steel Wheels	28129	45-53	5-6
Service Pack; W/Alloy Wheels	20008	11.5	1.3	Service Pack; W/Alloy Wheels	20003	45-53	5-6
Raider				Service Pack; W/Steel Wheels	20010	45-53	5-6
EZ-sensor - 315 MHz	△33000	11.5	1.3	Lancer; Outlander			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor	28096	71	8
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack	20030	71	8
Sensor	28154	58	6.5	Raider			

◊ Programming Tool Required.
● Magnet Required to Activate Sensor.



PRINTED ON RECYCLED PAPER
WITH 100% POSTCONSUMER WASTE

Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.				
Mitsubishi - Continued											
2008 - Continued											
Raider - Continued											
or	28461	11.5	1.3	Sensor	●20034	45-53	5-6				
Service Pack; Does Not Include Stem ..	20013	58	6.5	Service Pack	20003	45-53	5-6				
Service Pack; Includes Stem Only	20020	58	6.5	2005-2004 - Continued							
2007											
Eclipse											
EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor; W/Alloy Wheels	●20034	45-53	5-6	Sensor	●20034	45-53	5-6				
Sensor; W/Steel Wheels	28129	45-53	5-6	Service Pack	20003	45-53	5-6				
Service Pack; W/Alloy Wheels	20003	45-53	5-6	2003							
Service Pack; W/Steel Wheels	20010	45-53	5-6	Nissan							
Endeavor											
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Altima							
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
Sensor	●20034	45-53	5-6	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Service Pack	20003	45-53	5-6	Sensor	28204	66	7.5				
Galant				Service Pack	20014	71	8				
EZ-sensor - 315 MHz	◇33000	11.5	1.3	2012							
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Armada; Cube; Frontier; GT-R; Juke; Maxima; Murano; Pathfinder; Rogue							
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3				
Sensor; W/Alloy Wheels	●20034	45-53	5-6	EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
Sensor; W/Steel Wheels	28129	45-53	5-6	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Service Pack; W/Alloy Wheels	20003	45-53	5-6	Sensor	28204	49	5.5				
Service Pack; W/Steel Wheels	20010	45-53	5-6	Service Pack	20014	71	8				
Outlander				Sentra							
Sensor	28096	71	8	EZ-sensor - 315 MHz	◇33000	11.5	1.3				
Service Pack	20030	71	8	EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
2006				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Eclipse				Sensor	28204	66	7.5				
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack	20014	71	8				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Titan; Versa; Xterra							
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3				
Sensor; W/Alloy Wheels	●20034	45-53	5-6	EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
Sensor; W/Steel Wheels	28129	45-53	5-6	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Service Pack; W/Alloy Wheels	20003	45-53	5-6	Sensor	28204	49	5.5				
Service Pack; W/Steel Wheels	20010	45-53	5-6	Service Pack	20014	71	8				
Endeavor				2011							
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Altima							
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
Sensor; Sept. 1 & Newer	●20034	45-53	5-6	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor; Aug. & Older	●20028	45-53	5-6	Sensor	28204	49	5.5				
Service Pack	20003	45-53	5-6	Service Pack	20014	71	8				
Galant				Armada							
Sensor	●20028	45-53	5-6	EZ-sensor - 315 MHz	◇33000	11.5	1.3				
Service Pack	20003	45-53	5-6	EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
Montero				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor	28204	49	5.5				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Service Pack	20014	49	5.5				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Cube							
Sensor	●20034	45-53	5-6	EZ-sensor - 315 MHz	◇33000	11.5	1.3				
Service Pack	20003	45-53	5-6	EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
2005-2004				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Endeavor; Galant				Sensor	28204	49	5.5				
Sensor	●20028	45-53	5-6	Service Pack	20014	71	8				
Service Pack	20003	45-53	5-6	Frontier							
Montero				EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor	28204	49	5.5				
Sensor	●20034	45-53	5-6	Service Pack	20014	49	5.5				
Service Pack	20003	45-53	5-6								

◇ Programming Tool Required.
● Magnet Required to Activate Sensor.



Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
Nissan - Continued				Nissan - Continued			
2011 - Continued				2010 - Continued			
GT-R				Maxima - Continued			
EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Almnm. Valve	34000	62	7	Sensor	28204	68	7.7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack	20014	68	7.7
Sensor	28204	49	5.5				
Service Pack	20014	71	8				
Juke				Pathfinder			
EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3
EZ-sensor Service Pack; Almnm. Valve	34000	62	7	EZ-sensor Service Pack; Almnm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor	28204	49	5.5	Sensor	28204	49	5.5
Service Pack	20014	49	5.5	Service Pack	20014	49	5.5
Maxima				Sentra			
EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3
EZ-sensor Service Pack; Almnm. Valve	34000	62	7	EZ-sensor Service Pack; Almnm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor	28204	49	5.5	Sensor	28204	68	7.7
Service Pack	20014	71	8	Service Pack	20014	68	7.7
Murano; Pathfinder; Rogue				Titan			
EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3
EZ-sensor Service Pack; Almnm. Valve	34000	62	7	EZ-sensor Service Pack; Almnm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor	28204	49	5.5	Sensor	28204	49	5.5
Service Pack	20014	49	5.5	Service Pack	20014	49	5.5
Sentra				Versa			
EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3
EZ-sensor Service Pack; Almnm. Valve	34000	62	7	EZ-sensor Service Pack; Almnm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor	28204	49	5.5	Sensor	28204	71	8
Service Pack	20014	71	8	Service Pack	20014	71	8
Titan				Xterra			
EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3
EZ-sensor Service Pack; Almnm. Valve	34000	62	7	EZ-sensor Service Pack; Almnm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor	28204	49	5.5	Sensor	28204	49	5.5
Service Pack	20014	49	5.5	Service Pack	20014	49	5.5
Versa				2009			
EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Almnm. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	28204	49	5.5				
Service Pack	20014	71	8				
Xterra				350Z			
EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3
EZ-sensor Service Pack; Almnm. Valve	34000	62	7	EZ-sensor Service Pack; Almnm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor	28204	49	5.5	Sensor	28204	71	8
Service Pack	20014	49	5.5	Service Pack	20014	71	8
2010				370Z			
Altima				EZ-sensor - 315 MHz	◇33000	11.5	1.3
EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almnm. Valve	34000	62	7
EZ-sensor Service Pack; Almnm. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor	28204	71	8
Sensor	28204	49	5.5	Service Pack	20014	71	8
Service Pack	20014	71	8				
Armada; Frontier							
EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Almnm. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	28204	49	5.5				
Service Pack	20014	49	5.5				
Maxima				Altima			
EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3
EZ-sensor Service Pack; Almnm. Valve	34000	62	7	EZ-sensor Service Pack; Almnm. Valve	34000	62	7
				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
				Sensor	28204	71	8
				Service Pack	20014	71	8
Armada				Armada			
EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3
EZ-sensor Service Pack; Almnm. Valve	34000	62	7	EZ-sensor Service Pack; Almnm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor	28204	49	5.5	Sensor	28204	49	5.5
Service Pack	20014	49	5.5	Service Pack	20014	49	5.5
Cube				Cube			
EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3
EZ-sensor Service Pack; Almnm. Valve	34000	62	7	EZ-sensor Service Pack; Almnm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor	28204	71	8	Sensor	28204	71	8

◊ Programming Tool Required.



PRINTED ON RECYCLED PAPER
WITH 100% POSTCONSUMER WASTE

Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
Nissan - Continued							
2009 - Continued							
Cube - Continued							
Service Pack	20014	71	8	Service Pack; SE	20007	49	5.5
Frontier							
EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor	28204	49	5.5	Sensor; W/Alloy Wheels	20161	49	5.5
Service Pack	20014	49	5.5	Sensor; W/Steel Wheels	28204	49	5.5
GT-R							
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack; W/Alloy Wheels	20007	49	5.5
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Service Pack; W/Steel Wheels	20014	49	5.5
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	28204	71	8				
Service Pack	20014	71	8				
Maxima; Murano							
EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor	28204	68	7.7	Sensor	28204	68	7.7
Service Pack	20014	68	7.7	Service Pack	20014	68	7.7
Pathfinder; Quest							
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Pathfinder; Quest			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor - 315 MHz	◇33000	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor	28204	49	5.5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Service Pack	20014	49	5.5	Sensor	28204	49	5.5
Rogue; Sentra							
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack	20014	49	5.5
EZ-sensor Service Pack; Almm. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	28204	68	7.7				
Service Pack	20014	68	7.7				
Titan							
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Titan			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor - 315 MHz	◇33000	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor	28204	49	5.5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Service Pack	20014	49	5.5	Sensor	28204	71	8
Versa							
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack	20014	71	8
EZ-sensor Service Pack; Almm. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	28204	71	8				
Service Pack	20014	71	8				
Xterra							
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Xterra			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor - 315 MHz	◇33000	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Sensor	28204	49	5.5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Service Pack	20014	49	5.5	Sensor	28204	71	8
2008							
350Z; Altima							
EZ-sensor - 315 MHz	◇33000	11.5	1.3	2007			
EZ-sensor Service Pack; Almm. Valve	34000	62	7	350Z; Altima			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3
Sensor	28204	71	8	EZ-sensor Service Pack; Almm. Valve	34000	62	7
Service Pack	20014	71	8	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Armada							
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor	28204	71	8
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Service Pack	20014	71	8
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor; LE	28204	49	5.5				
Sensor; SE	20161	49	5.5				
Service Pack; LE	20014	49	5.5				

◊ Programming Tool Required.



Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
Nissan - Continued																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																							
2007 - Continued																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																							
Armada - Continued																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																							
Service Pack	20007	49	5.5	Sensor; OEM Part No. 40700JA01B	28204	49	5.5																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
Frontier																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																							
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack	20014	49	5.5																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	2006																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; W/Alloy Wheels	20161	49	5.5	350Z								Sensor; W/Steel Wheels	20069	49	5.5	Service Pack; W/Alloy Wheels	20007	49	5.5	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack; W/Steel Wheels	20005	49	5.5	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Maxima				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor	20064	49	5.5	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Service Pack	20007	49	5.5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Altima								Sensor; Apr. 1 & Newer	28204	68	7.7	EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; Mar. & Older	20161	49	5.5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack; Apr. 1 & Newer	20014	68	7.7	Sensor; Oct. 1 & Newer	28204	71	8	Service Pack; Mar. & Older	20007	49	5.5	Service Pack; Oct. 1 & Newer	20014	71	8	Murano								EZ-sensor - 315 MHz	◇33000	11.5	1.3	Armada; Frontier								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor	28204	71	8	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Service Pack	20014	71	8	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Pathfinder				EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor; W/Alloy Wheels	20161	49	5.5	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; W/Steel Wheels	20069	49	5.5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack; W/Alloy Wheels	20007	49	5.5	Sensor; OEM Part No. 40700JA01A	28167	49	5.5	Service Pack; W/Steel Wheels	20005	49	5.5	Sensor; OEM Part No. 40700JA01B	28204	49	5.5	Maxima								Service Pack	20014	49	5.5	EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor	28204	49	5.5	Sensor; Jun. & Newer	20161	49	5.5	Service Pack	20014	49	5.5	Service Pack; Jun. & Newer	20007	49	5.5	Quest				Murano								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor	28204	49	5.5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack	20014	49	5.5	Sensor	20064	66	7.5	Sentra				Service Pack	20007	66	7.5	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Pathfinder								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor; W/Alloy Wheels	20161	78	8.8	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; W/Steel Wheels	28204	71	8	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack; W/Alloy Wheels	20007	78	8.8	Sensor	20161	49	5.5	Service Pack; W/Steel Wheels	20014	71	8	Service Pack	20007	49	5.5	Titan				Quest								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; Apr. 1 & Newer	28204	49	5.5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; Mar. & Older	20161	49	5.5	Sensor	20161	78	8.8	Service Pack; Apr. 1 & Newer	20014	49	5.5	Sensor; W/Steel Wheels	20069	78	8.8	Service Pack; Mar. & Older	20007	49	5.5	Service Pack; W/Alloy Wheels	20007	78	8.8	Versa				Service Pack; W/Steel Wheels	20005	78	8.8	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Titan								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor; OEM Part No. 40700JA01A	28167	71	8	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; OEM Part No. 40700JA01B	28204	71	8	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack	20014	71	8	Sensor	20161	49	5.5	Xterra				Service Pack	20007	49	5.5	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Xterra								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor; OEM Part No. 40700JA01A	28167	49	5.5	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	PRINTED ON RECYCLED PAPER WITH 100% POSTCONSUMER WASTE				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	◊ Programming Tool Required.				Sensor; Submodel X	20069	49	5.5					Service Pack; Exc. Submodel X	20007	49	5.5					Service Pack; Submodel X	20005	49	5.5
Sensor; W/Alloy Wheels	20161	49	5.5	350Z																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																			
Sensor; W/Steel Wheels	20069	49	5.5	Service Pack; W/Alloy Wheels	20007	49	5.5	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack; W/Steel Wheels	20005	49	5.5	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Maxima				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor	20064	49	5.5	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Service Pack	20007	49	5.5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Altima								Sensor; Apr. 1 & Newer	28204	68	7.7	EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; Mar. & Older	20161	49	5.5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack; Apr. 1 & Newer	20014	68	7.7	Sensor; Oct. 1 & Newer	28204	71	8	Service Pack; Mar. & Older	20007	49	5.5	Service Pack; Oct. 1 & Newer	20014	71	8	Murano								EZ-sensor - 315 MHz	◇33000	11.5	1.3	Armada; Frontier								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor	28204	71	8	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Service Pack	20014	71	8	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Pathfinder				EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor; W/Alloy Wheels	20161	49	5.5	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; W/Steel Wheels	20069	49	5.5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack; W/Alloy Wheels	20007	49	5.5	Sensor; OEM Part No. 40700JA01A	28167	49	5.5	Service Pack; W/Steel Wheels	20005	49	5.5	Sensor; OEM Part No. 40700JA01B	28204	49	5.5	Maxima								Service Pack	20014	49	5.5	EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor	28204	49	5.5	Sensor; Jun. & Newer	20161	49	5.5	Service Pack	20014	49	5.5	Service Pack; Jun. & Newer	20007	49	5.5	Quest				Murano								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor	28204	49	5.5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack	20014	49	5.5	Sensor	20064	66	7.5	Sentra				Service Pack	20007	66	7.5	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Pathfinder								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor; W/Alloy Wheels	20161	78	8.8	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; W/Steel Wheels	28204	71	8	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack; W/Alloy Wheels	20007	78	8.8	Sensor	20161	49	5.5	Service Pack; W/Steel Wheels	20014	71	8	Service Pack	20007	49	5.5	Titan				Quest								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; Apr. 1 & Newer	28204	49	5.5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; Mar. & Older	20161	49	5.5	Sensor	20161	78	8.8	Service Pack; Apr. 1 & Newer	20014	49	5.5	Sensor; W/Steel Wheels	20069	78	8.8	Service Pack; Mar. & Older	20007	49	5.5	Service Pack; W/Alloy Wheels	20007	78	8.8	Versa				Service Pack; W/Steel Wheels	20005	78	8.8	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Titan								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor; OEM Part No. 40700JA01A	28167	71	8	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; OEM Part No. 40700JA01B	28204	71	8	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack	20014	71	8	Sensor	20161	49	5.5	Xterra				Service Pack	20007	49	5.5	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Xterra								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor; OEM Part No. 40700JA01A	28167	49	5.5	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	PRINTED ON RECYCLED PAPER WITH 100% POSTCONSUMER WASTE				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	◊ Programming Tool Required.				Sensor; Submodel X	20069	49	5.5					Service Pack; Exc. Submodel X	20007	49	5.5					Service Pack; Submodel X	20005	49	5.5																
Service Pack; W/Alloy Wheels	20007	49	5.5	EZ-sensor - 315 MHz	◇33000	11.5	1.3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
Service Pack; W/Steel Wheels	20005	49	5.5	EZ-sensor Service Pack; Almmn. Valve	34000	62	7																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
Maxima				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor	20064	49	5.5																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Service Pack	20007	49	5.5																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Altima																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																			
Sensor; Apr. 1 & Newer	28204	68	7.7	EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; Mar. & Older	20161	49	5.5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack; Apr. 1 & Newer	20014	68	7.7	Sensor; Oct. 1 & Newer	28204	71	8	Service Pack; Mar. & Older	20007	49	5.5	Service Pack; Oct. 1 & Newer	20014	71	8	Murano								EZ-sensor - 315 MHz	◇33000	11.5	1.3	Armada; Frontier								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor	28204	71	8	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Service Pack	20014	71	8	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Pathfinder				EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor; W/Alloy Wheels	20161	49	5.5	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; W/Steel Wheels	20069	49	5.5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack; W/Alloy Wheels	20007	49	5.5	Sensor; OEM Part No. 40700JA01A	28167	49	5.5	Service Pack; W/Steel Wheels	20005	49	5.5	Sensor; OEM Part No. 40700JA01B	28204	49	5.5	Maxima								Service Pack	20014	49	5.5	EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor	28204	49	5.5	Sensor; Jun. & Newer	20161	49	5.5	Service Pack	20014	49	5.5	Service Pack; Jun. & Newer	20007	49	5.5	Quest				Murano								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor	28204	49	5.5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack	20014	49	5.5	Sensor	20064	66	7.5	Sentra				Service Pack	20007	66	7.5	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Pathfinder								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor; W/Alloy Wheels	20161	78	8.8	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; W/Steel Wheels	28204	71	8	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack; W/Alloy Wheels	20007	78	8.8	Sensor	20161	49	5.5	Service Pack; W/Steel Wheels	20014	71	8	Service Pack	20007	49	5.5	Titan				Quest								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; Apr. 1 & Newer	28204	49	5.5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; Mar. & Older	20161	49	5.5	Sensor	20161	78	8.8	Service Pack; Apr. 1 & Newer	20014	49	5.5	Sensor; W/Steel Wheels	20069	78	8.8	Service Pack; Mar. & Older	20007	49	5.5	Service Pack; W/Alloy Wheels	20007	78	8.8	Versa				Service Pack; W/Steel Wheels	20005	78	8.8	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Titan								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor; OEM Part No. 40700JA01A	28167	71	8	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; OEM Part No. 40700JA01B	28204	71	8	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack	20014	71	8	Sensor	20161	49	5.5	Xterra				Service Pack	20007	49	5.5	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Xterra								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor; OEM Part No. 40700JA01A	28167	49	5.5	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	PRINTED ON RECYCLED PAPER WITH 100% POSTCONSUMER WASTE				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	◊ Programming Tool Required.				Sensor; Submodel X	20069	49	5.5					Service Pack; Exc. Submodel X	20007	49	5.5					Service Pack; Submodel X	20005	49	5.5																																																																								
EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
Sensor; Mar. & Older	20161	49	5.5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
Service Pack; Apr. 1 & Newer	20014	68	7.7	Sensor; Oct. 1 & Newer	28204	71	8																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
Service Pack; Mar. & Older	20007	49	5.5	Service Pack; Oct. 1 & Newer	20014	71	8																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
Murano																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																							
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Armada; Frontier																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																			
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor	28204	71	8	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Service Pack	20014	71	8	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Pathfinder				EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor; W/Alloy Wheels	20161	49	5.5	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; W/Steel Wheels	20069	49	5.5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack; W/Alloy Wheels	20007	49	5.5	Sensor; OEM Part No. 40700JA01A	28167	49	5.5	Service Pack; W/Steel Wheels	20005	49	5.5	Sensor; OEM Part No. 40700JA01B	28204	49	5.5	Maxima								Service Pack	20014	49	5.5	EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor	28204	49	5.5	Sensor; Jun. & Newer	20161	49	5.5	Service Pack	20014	49	5.5	Service Pack; Jun. & Newer	20007	49	5.5	Quest				Murano								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor	28204	49	5.5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack	20014	49	5.5	Sensor	20064	66	7.5	Sentra				Service Pack	20007	66	7.5	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Pathfinder								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor; W/Alloy Wheels	20161	78	8.8	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; W/Steel Wheels	28204	71	8	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack; W/Alloy Wheels	20007	78	8.8	Sensor	20161	49	5.5	Service Pack; W/Steel Wheels	20014	71	8	Service Pack	20007	49	5.5	Titan				Quest								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; Apr. 1 & Newer	28204	49	5.5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; Mar. & Older	20161	49	5.5	Sensor	20161	78	8.8	Service Pack; Apr. 1 & Newer	20014	49	5.5	Sensor; W/Steel Wheels	20069	78	8.8	Service Pack; Mar. & Older	20007	49	5.5	Service Pack; W/Alloy Wheels	20007	78	8.8	Versa				Service Pack; W/Steel Wheels	20005	78	8.8	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Titan								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor; OEM Part No. 40700JA01A	28167	71	8	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; OEM Part No. 40700JA01B	28204	71	8	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack	20014	71	8	Sensor	20161	49	5.5	Xterra				Service Pack	20007	49	5.5	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Xterra								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor; OEM Part No. 40700JA01A	28167	49	5.5	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	PRINTED ON RECYCLED PAPER WITH 100% POSTCONSUMER WASTE				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	◊ Programming Tool Required.				Sensor; Submodel X	20069	49	5.5					Service Pack; Exc. Submodel X	20007	49	5.5					Service Pack; Submodel X	20005	49	5.5																																																																																																																																
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
Sensor	28204	71	8	EZ-sensor Service Pack; Almmn. Valve	34000	62	7																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
Service Pack	20014	71	8	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
Pathfinder				EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor; W/Alloy Wheels	20161	49	5.5	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; W/Steel Wheels	20069	49	5.5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack; W/Alloy Wheels	20007	49	5.5	Sensor; OEM Part No. 40700JA01A	28167	49	5.5	Service Pack; W/Steel Wheels	20005	49	5.5	Sensor; OEM Part No. 40700JA01B	28204	49	5.5	Maxima								Service Pack	20014	49	5.5	EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor	28204	49	5.5	Sensor; Jun. & Newer	20161	49	5.5	Service Pack	20014	49	5.5	Service Pack; Jun. & Newer	20007	49	5.5	Quest				Murano								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor	28204	49	5.5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack	20014	49	5.5	Sensor	20064	66	7.5	Sentra				Service Pack	20007	66	7.5	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Pathfinder								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor; W/Alloy Wheels	20161	78	8.8	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; W/Steel Wheels	28204	71	8	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack; W/Alloy Wheels	20007	78	8.8	Sensor	20161	49	5.5	Service Pack; W/Steel Wheels	20014	71	8	Service Pack	20007	49	5.5	Titan				Quest								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; Apr. 1 & Newer	28204	49	5.5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; Mar. & Older	20161	49	5.5	Sensor	20161	78	8.8	Service Pack; Apr. 1 & Newer	20014	49	5.5	Sensor; W/Steel Wheels	20069	78	8.8	Service Pack; Mar. & Older	20007	49	5.5	Service Pack; W/Alloy Wheels	20007	78	8.8	Versa				Service Pack; W/Steel Wheels	20005	78	8.8	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Titan								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor; OEM Part No. 40700JA01A	28167	71	8	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; OEM Part No. 40700JA01B	28204	71	8	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack	20014	71	8	Sensor	20161	49	5.5	Xterra				Service Pack	20007	49	5.5	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Xterra								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor; OEM Part No. 40700JA01A	28167	49	5.5	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	PRINTED ON RECYCLED PAPER WITH 100% POSTCONSUMER WASTE				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	◊ Programming Tool Required.				Sensor; Submodel X	20069	49	5.5					Service Pack; Exc. Submodel X	20007	49	5.5					Service Pack; Submodel X	20005	49	5.5																																																																																																																																																												
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor; W/Alloy Wheels	20161	49	5.5																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; W/Steel Wheels	20069	49	5.5																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack; W/Alloy Wheels	20007	49	5.5																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
Sensor; OEM Part No. 40700JA01A	28167	49	5.5	Service Pack; W/Steel Wheels	20005	49	5.5																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
Sensor; OEM Part No. 40700JA01B	28204	49	5.5	Maxima																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																			
Service Pack	20014	49	5.5	EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor	28204	49	5.5	Sensor; Jun. & Newer	20161	49	5.5	Service Pack	20014	49	5.5	Service Pack; Jun. & Newer	20007	49	5.5	Quest				Murano								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor	28204	49	5.5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack	20014	49	5.5	Sensor	20064	66	7.5	Sentra				Service Pack	20007	66	7.5	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Pathfinder								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor; W/Alloy Wheels	20161	78	8.8	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; W/Steel Wheels	28204	71	8	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack; W/Alloy Wheels	20007	78	8.8	Sensor	20161	49	5.5	Service Pack; W/Steel Wheels	20014	71	8	Service Pack	20007	49	5.5	Titan				Quest								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; Apr. 1 & Newer	28204	49	5.5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; Mar. & Older	20161	49	5.5	Sensor	20161	78	8.8	Service Pack; Apr. 1 & Newer	20014	49	5.5	Sensor; W/Steel Wheels	20069	78	8.8	Service Pack; Mar. & Older	20007	49	5.5	Service Pack; W/Alloy Wheels	20007	78	8.8	Versa				Service Pack; W/Steel Wheels	20005	78	8.8	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Titan								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor; OEM Part No. 40700JA01A	28167	71	8	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; OEM Part No. 40700JA01B	28204	71	8	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack	20014	71	8	Sensor	20161	49	5.5	Xterra				Service Pack	20007	49	5.5	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Xterra								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor; OEM Part No. 40700JA01A	28167	49	5.5	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	PRINTED ON RECYCLED PAPER WITH 100% POSTCONSUMER WASTE				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	◊ Programming Tool Required.				Sensor; Submodel X	20069	49	5.5					Service Pack; Exc. Submodel X	20007	49	5.5					Service Pack; Submodel X	20005	49	5.5																																																																																																																																																																																																												
EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Almmn. Valve	34000	62	7																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
Sensor	28204	49	5.5	Sensor; Jun. & Newer	20161	49	5.5																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
Service Pack	20014	49	5.5	Service Pack; Jun. & Newer	20007	49	5.5																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
Quest				Murano																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																			
EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor	28204	49	5.5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack	20014	49	5.5	Sensor	20064	66	7.5	Sentra				Service Pack	20007	66	7.5	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Pathfinder								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor; W/Alloy Wheels	20161	78	8.8	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; W/Steel Wheels	28204	71	8	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack; W/Alloy Wheels	20007	78	8.8	Sensor	20161	49	5.5	Service Pack; W/Steel Wheels	20014	71	8	Service Pack	20007	49	5.5	Titan				Quest								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; Apr. 1 & Newer	28204	49	5.5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; Mar. & Older	20161	49	5.5	Sensor	20161	78	8.8	Service Pack; Apr. 1 & Newer	20014	49	5.5	Sensor; W/Steel Wheels	20069	78	8.8	Service Pack; Mar. & Older	20007	49	5.5	Service Pack; W/Alloy Wheels	20007	78	8.8	Versa				Service Pack; W/Steel Wheels	20005	78	8.8	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Titan								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor; OEM Part No. 40700JA01A	28167	71	8	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; OEM Part No. 40700JA01B	28204	71	8	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack	20014	71	8	Sensor	20161	49	5.5	Xterra				Service Pack	20007	49	5.5	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Xterra								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor; OEM Part No. 40700JA01A	28167	49	5.5	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	PRINTED ON RECYCLED PAPER WITH 100% POSTCONSUMER WASTE				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	◊ Programming Tool Required.				Sensor; Submodel X	20069	49	5.5					Service Pack; Exc. Submodel X	20007	49	5.5					Service Pack; Submodel X	20005	49	5.5																																																																																																																																																																																																																																																																				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor - 315 MHz	◇33000	11.5	1.3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
Sensor	28204	49	5.5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
Service Pack	20014	49	5.5	Sensor	20064	66	7.5																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
Sentra				Service Pack	20007	66	7.5																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Pathfinder																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																			
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor; W/Alloy Wheels	20161	78	8.8	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; W/Steel Wheels	28204	71	8	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack; W/Alloy Wheels	20007	78	8.8	Sensor	20161	49	5.5	Service Pack; W/Steel Wheels	20014	71	8	Service Pack	20007	49	5.5	Titan				Quest								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; Apr. 1 & Newer	28204	49	5.5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; Mar. & Older	20161	49	5.5	Sensor	20161	78	8.8	Service Pack; Apr. 1 & Newer	20014	49	5.5	Sensor; W/Steel Wheels	20069	78	8.8	Service Pack; Mar. & Older	20007	49	5.5	Service Pack; W/Alloy Wheels	20007	78	8.8	Versa				Service Pack; W/Steel Wheels	20005	78	8.8	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Titan								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor; OEM Part No. 40700JA01A	28167	71	8	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; OEM Part No. 40700JA01B	28204	71	8	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack	20014	71	8	Sensor	20161	49	5.5	Xterra				Service Pack	20007	49	5.5	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Xterra								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor; OEM Part No. 40700JA01A	28167	49	5.5	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	PRINTED ON RECYCLED PAPER WITH 100% POSTCONSUMER WASTE				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	◊ Programming Tool Required.				Sensor; Submodel X	20069	49	5.5					Service Pack; Exc. Submodel X	20007	49	5.5					Service Pack; Submodel X	20005	49	5.5																																																																																																																																																																																																																																																																																																																												
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
Sensor; W/Alloy Wheels	20161	78	8.8	EZ-sensor Service Pack; Almmn. Valve	34000	62	7																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
Sensor; W/Steel Wheels	28204	71	8	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
Service Pack; W/Alloy Wheels	20007	78	8.8	Sensor	20161	49	5.5																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
Service Pack; W/Steel Wheels	20014	71	8	Service Pack	20007	49	5.5																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
Titan				Quest																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																			
EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; Apr. 1 & Newer	28204	49	5.5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; Mar. & Older	20161	49	5.5	Sensor	20161	78	8.8	Service Pack; Apr. 1 & Newer	20014	49	5.5	Sensor; W/Steel Wheels	20069	78	8.8	Service Pack; Mar. & Older	20007	49	5.5	Service Pack; W/Alloy Wheels	20007	78	8.8	Versa				Service Pack; W/Steel Wheels	20005	78	8.8	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Titan								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor; OEM Part No. 40700JA01A	28167	71	8	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; OEM Part No. 40700JA01B	28204	71	8	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack	20014	71	8	Sensor	20161	49	5.5	Xterra				Service Pack	20007	49	5.5	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Xterra								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor; OEM Part No. 40700JA01A	28167	49	5.5	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	PRINTED ON RECYCLED PAPER WITH 100% POSTCONSUMER WASTE				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	◊ Programming Tool Required.				Sensor; Submodel X	20069	49	5.5					Service Pack; Exc. Submodel X	20007	49	5.5					Service Pack; Submodel X	20005	49	5.5																																																																																																																																																																																																																																																																																																																																																																																				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor - 315 MHz	◇33000	11.5	1.3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
Sensor; Apr. 1 & Newer	28204	49	5.5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
Sensor; Mar. & Older	20161	49	5.5	Sensor	20161	78	8.8																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
Service Pack; Apr. 1 & Newer	20014	49	5.5	Sensor; W/Steel Wheels	20069	78	8.8																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
Service Pack; Mar. & Older	20007	49	5.5	Service Pack; W/Alloy Wheels	20007	78	8.8																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
Versa				Service Pack; W/Steel Wheels	20005	78	8.8																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Titan																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																			
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor; OEM Part No. 40700JA01A	28167	71	8	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; OEM Part No. 40700JA01B	28204	71	8	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack	20014	71	8	Sensor	20161	49	5.5	Xterra				Service Pack	20007	49	5.5	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Xterra								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor; OEM Part No. 40700JA01A	28167	49	5.5	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	PRINTED ON RECYCLED PAPER WITH 100% POSTCONSUMER WASTE				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	◊ Programming Tool Required.				Sensor; Submodel X	20069	49	5.5					Service Pack; Exc. Submodel X	20007	49	5.5					Service Pack; Submodel X	20005	49	5.5																																																																																																																																																																																																																																																																																																																																																																																																																																																												
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
Sensor; OEM Part No. 40700JA01A	28167	71	8	EZ-sensor Service Pack; Almmn. Valve	34000	62	7																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
Sensor; OEM Part No. 40700JA01B	28204	71	8	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
Service Pack	20014	71	8	Sensor	20161	49	5.5																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
Xterra				Service Pack	20007	49	5.5																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Xterra																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																			
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor; OEM Part No. 40700JA01A	28167	49	5.5	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	PRINTED ON RECYCLED PAPER WITH 100% POSTCONSUMER WASTE				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	◊ Programming Tool Required.				Sensor; Submodel X	20069	49	5.5					Service Pack; Exc. Submodel X	20007	49	5.5					Service Pack; Submodel X	20005	49	5.5																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
Sensor; OEM Part No. 40700JA01A	28167	49	5.5	EZ-sensor Service Pack; Almmn. Valve	34000	62	7																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
PRINTED ON RECYCLED PAPER WITH 100% POSTCONSUMER WASTE				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
◊ Programming Tool Required.				Sensor; Submodel X	20069	49	5.5																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
				Service Pack; Exc. Submodel X	20007	49	5.5																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
				Service Pack; Submodel X	20005	49	5.5																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																



PRINTED ON RECYCLED PAPER
WITH 100% POSTCONSUMER WASTE

Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.				
Nissan - Continued											
2005											
350Z											
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor	20064	66	7.5				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Service Pack	20007	66	7.5				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Pathfinder							
Sensor	20064	49	5.5	EZ-sensor - 315 MHz	◇33000	11.5	1.3				
Service Pack	20007	49	5.5	EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
Armada; Frontier				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor; Armada	20069	49	5.5				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; Exc. Armada; Aug. & Newer	20069	49	5.5				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; Exc. Armada; Jul. & Older	20064	49	5.5				
Sensor; W/Alloy Wheels	20161	49	5.5	Service Pack; Armada	20005	49	5.5				
Sensor; W/Steel Wheels	20069	49	5.5	Service Pack; Exc. Armada; Aug. & Newer	20005	49	5.5				
Service Pack; W/Alloy Wheels	20007	49	5.5	Service Pack; Exc. Armada; Jul. & Older	20007	49	5.5				
Service Pack; W/Steel Wheels	20005	49	5.5	Quest							
Murano											
EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	20064	66	7.5	Sensor	20069	78	8.8				
Service Pack	20007	66	7.5	Service Pack	20005	78	8.8				
Pathfinder											
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Titan							
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
Sensor	20161	49	5.5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Service Pack	20007	49	5.5	Sensor	20069	49	5.5				
Quest				Service Pack	20005	49	5.5				
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Xterra							
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
Sensor; W/Alloy Wheels	20161	78	8.8	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor; W/Steel Wheels	20069	78	8.8	Sensor	20064	36-60	4.1-6.8				
Service Pack; W/Alloy Wheels	20007	78	8.8	Service Pack	20007	36-60	4.1-6.8				
Service Pack; W/Steel Wheels	20005	78	8.8	2003							
Titan											
EZ-sensor - 315 MHz	◇33000	11.5	1.3	350Z							
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
Sensor; Apr. 1 & Newer	20161	49	5.5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor; Mar. & Older	20069	49	5.5	Sensor	20064	49	5.5				
Service Pack; Apr. 1 & Newer	20007	49	5.5	Service Pack	20007	49	5.5				
Service Pack; Mar. & Older	20005	49	5.5	Frontier							
Xterra											
EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	20161	36-60	4.1-6.8	Sensor	20064	36-60	4.1-6.8				
Service Pack	20007	36-60	4.1-6.8	Service Pack	20007	36-60	4.1-6.8				
2004											
350Z											
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Murano							
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
Sensor	20064	49	5.5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Service Pack	20007	49	5.5	Sensor	20064	66	7.5				
Frontier				Service Pack	20007	66	7.5				
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Pathfinder							
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
Sensor	20064	36-60	4.1-6.8	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Service Pack	20007	36-60	4.1-6.8	Sensor	20064	49	5.5				
Murano				Service Pack	20007	49	5.5				
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Xterra							
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
Sensor	20064	36-60	4.1-6.8	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Service Pack	20007	36-60	4.1-6.8	Sensor	20064	36-60	4.1-6.8				

◇ Programming Tool Required.



Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
Plymouth							
2001-1999							
Prowler							
Sensor	28004	35	4				
Service Pack; W/Black Sensor Body	20012	35	4				
Service Pack; W/Red Sensor Body	20003	35	4				
1997							
Prowler							
Sensor	28004	35	4				
Service Pack; W/Black Sensor Body	20012	35	4				
Service Pack; W/Red Sensor Body	20003	35	4				
Pontiac							
2010							
G3; G5; G6; G8							
EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Almnm. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	20153	11.5	1.3				
Service Pack	20008	11.5	1.3				
Solstice							
EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Almnm. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	20158	62	7				
Service Pack; W/Schrader Sensor	20004	62	7				
Service Pack; W/Siemens Sensor	20030	80	9				
Vibe							
EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Almnm. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	28360	35	4				
Service Pack	20032	35	4				
2009							
G3; G3 Wave; G5; G6; G8							
EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Almnm. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	20153	11.5	1.3				
Service Pack	20008	11.5	1.3				
Montana; Solstice; Torrent							
EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Almnm. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	20158	62	7				
Service Pack; W/Schrader Sensor	20004	62	7				
Service Pack; W/Siemens Sensor	20030	80	9				
Vibe							
EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Almnm. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	28360	35	4				
Service Pack	20032	35	4				
2008							
G5; G6							
EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Almnm. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	20158	62	7				
Service Pack; W/Schrader Sensor	20004	62	7				
Service Pack; W/Siemens Sensor	20030	80	9				
G8							
EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Almnm. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	20153	62	7				
Pontiac - Continued							
2008 - Continued							
G8 - Continued							
Service Pack	20008	62	7				
Grand Prix							
EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Almnm. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor; Clamp-In Style Only; W/Almnm. Valve Stem	20158	62	7				
Sensor; Snap-In Style Only; W/Rubber Valve Stem	20153	11.5	1.3				
Service Pack; Clamp-In Style Only; W/Almnm. Valve Stem	20004	62	7				
Service Pack; Snap-In Style Only; W/Rubber Valve Stem	20008	11.5	1.3				
Montana; Solstice; Torrent							
EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Almnm. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	20158	62	7				
Service Pack; W/Schrader Sensor	20004	62	7				
Service Pack; W/Siemens Sensor	20030	80	9				
Vibe							
EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Almnm. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	28360	35	4				
Service Pack	20032	35	4				
Wave							
EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Almnm. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	20153	11.5	1.3				
Service Pack	20008	11.5	1.3				
2007							
Grand Prix; Torrent							
EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Almnm. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	20158	62	7				
Service Pack; W/Schrader Sensor	20004	62	7				
Service Pack; W/Siemens Sensor	20030	80	9				
Porsche							
2011							
911; Boxster							
Sensor; Includes Transmitter Only	20077	35	4				
Service Pack; Does Not Include Valve ..	20023	35	4				
Service Pack; W/43mm Silver Insert	20037	35	4				
Service Pack; W/48mm Green Insert	20038	35	4				
Service Pack; W/49mm Black Insert	20039	35	4				
Service Pack; W/51mm Orange Insert	20040	35	4				
Cayenne							
Sensor; Includes Transmitter Only	20103	35	4				
Service Pack; W/43mm Silver Insert	20037	35	4				
Service Pack; W/48mm Green Insert	20038	35	4				
Service Pack; W/49mm Black Insert	20039	35	4				
Service Pack; W/51mm Orange Insert	20040	35	4				
Cayman							
Sensor; Includes Transmitter Only	20077	35	4				
Service Pack; Does Not Include Valve ..	20023	35	4				
Service Pack; W/43mm Silver Insert	20037	35	4				
Service Pack; W/48mm Green Insert	20038	35	4				
Service Pack; W/49mm Black Insert	20039	35	4				
Service Pack; W/51mm Orange Insert	20040	35	4				

◊ Programming Tool Required.



PRINTED ON RECYCLED PAPER
WITH 100% POSTCONSUMER WASTE

Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
Porsche - Continued																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																							
2011 - Continued																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																							
Panamera																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																							
Sensor; Includes Transmitter Only	28087	31-40	3.5-4.5	Service Pack; Does Not Include Valve .	20023	31-40	3.5-4.5																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
Service Pack; W/43mm Silver Insert	20037	31-40	3.5-4.5	Service Pack; W/43mm Silver Insert	20037	31-40	3.5-4.5																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
Service Pack; W/48mm Green Insert ...	20038	31-40	3.5-4.5	Service Pack; W/48mm Green Insert ...	20038	31-40	3.5-4.5																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
Service Pack; W/49mm Black Insert	20039	31-40	3.5-4.5	Service Pack; W/49mm Black Insert	20039	31-40	3.5-4.5																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
Service Pack; W/51mm Orange Insert .	20040	31-40	3.5-4.5	Service Pack; W/51mm Orange Insert .	20040	31-40	3.5-4.5																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
2010																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																							
911; Boxster																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																							
Sensor; Includes Transmitter Only	28087	31-40	3.5-4.5	Service Pack; Does Not Include Valve .	20023	31-40	3.5-4.5																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
Service Pack; Does Not Include Valve .	20023	31-40	3.5-4.5	Service Pack; W/43mm Silver Insert	20037	31-40	3.5-4.5																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
Service Pack; W/43mm Silver Insert	20037	31-40	3.5-4.5	Service Pack; W/48mm Green Insert ...	20038	31-40	3.5-4.5																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
Service Pack; W/48mm Green Insert ...	20038	31-40	3.5-4.5	Service Pack; W/49mm Black Insert	20039	31-40	3.5-4.5																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
Service Pack; W/49mm Black Insert	20039	31-40	3.5-4.5	Service Pack; W/51mm Orange Insert .	20040	31-40	3.5-4.5																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
Cayenne				2004																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																			
Service Pack; Does Not Include Valve .	20023	31-40	3.5-4.5	Carrera GT; Cayenne																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																			
Service Pack; W/43mm Silver Insert	20037	31-40	3.5-4.5	Service Pack; W/48mm Green Insert ...	20038	31-40	3.5-4.5	Service Pack; Does Not Include Valve .	20023	31-40	3.5-4.5	Service Pack; W/49mm Black Insert	20039	31-40	3.5-4.5	Service Pack; W/43mm Silver Insert	20037	31-40	3.5-4.5	Service Pack; W/51mm Orange Insert .	20040	31-40	3.5-4.5	Service Pack; W/48mm Green Insert ...	20038	31-40	3.5-4.5	Cayman; Panamera								Sensor; Includes Transmitter Only	28087	31-40	3.5-4.5	Service Pack; W/49mm Black Insert	20039	31-40	3.5-4.5	Service Pack; Does Not Include Valve .	20023	31-40	3.5-4.5	Service Pack; W/51mm Orange Insert .	20040	31-40	3.5-4.5	Service Pack; W/43mm Silver Insert	20037	31-40	3.5-4.5	2003								Service Pack; W/48mm Green Insert ...	20038	31-40	3.5-4.5	Rolls-Royce								Service Pack; W/49mm Black Insert	20039	31-40	3.5-4.5	2010-2007								Service Pack; W/51mm Orange Insert .	20040	31-40	3.5-4.5	Phantom								2009								911; Boxster; Cayenne								Service Pack; Does Not Include Valve .	20023	31-40	3.5-4.5	Service Pack; Does Not Include Valve .	20023	31-40	3.5-4.5	Service Pack; W/43mm Silver Insert	20037	31-40	3.5-4.5	Service Pack; W/43mm Silver Insert	20037	31-40	3.5-4.5	Service Pack; W/48mm Green Insert ...	20038	31-40	3.5-4.5	Service Pack; W/48mm Green Insert ...	20038	31-40	3.5-4.5	Service Pack; W/49mm Black Insert	20039	31-40	3.5-4.5	Service Pack; W/49mm Black Insert	20039	31-40	3.5-4.5	Service Pack; W/51mm Orange Insert .	20040	31-40	3.5-4.5	Service Pack; W/51mm Orange Insert .	20040	31-40	3.5-4.5	2008								911; Boxster; Cayenne; Cayman								Service Pack; Does Not Include Valve .	20023	31-40	3.5-4.5	Saab								Service Pack; W/43mm Silver Insert	20037	31-40	3.5-4.5	2012								Service Pack; W/48mm Green Insert ...	20038	31-40	3.5-4.5	9-3								Service Pack; W/49mm Black Insert	20039	31-40	3.5-4.5	Sensor	20159	88	10	Service Pack; W/51mm Orange Insert .	20040	31-40	3.5-4.5	Service Pack	20009	88	10	2007				9-4X								911; Boxster; Cayman				EZ-sensor - 315 MHz	◆33000	11.5	1.3	Service Pack; Does Not Include Valve .	20023	31-40	3.5-4.5	Sensor	28206	11.5	1.3	Service Pack; W/43mm Silver Insert	20037	31-40	3.5-4.5	Service Pack	20008	11.5	1.3	Service Pack; W/48mm Green Insert ...	20038	31-40	3.5-4.5	9-5								Service Pack; W/49mm Black Insert	20039	31-40	3.5-4.5	Sensor	20159	88	10	Service Pack; W/51mm Orange Insert .	20040	31-40	3.5-4.5	Service Pack	20009	88	10	2006				2011-2010								911; Boxster; Carrera GT; Cayenne; Cayman				9-3; 9-5								Service Pack; Does Not Include Valve .	20023	31-40	3.5-4.5	Sensor	20159	88	10	Service Pack; W/43mm Silver Insert	20037	31-40	3.5-4.5	Service Pack	20009	88	10	Service Pack; W/48mm Green Insert ...	20038	31-40	3.5-4.5	9-3; 9-5								Service Pack; W/49mm Black Insert	20039	31-40	3.5-4.5	Sensor	20159	88	10	Service Pack; W/51mm Orange Insert .	20040	31-40	3.5-4.5	Service Pack	20009	88	10	2005				2009-2008								9-3; 9-5				9-3; 9-5								Sensor	20159	88	10	Sensor	20159	88	10	Service Pack	20009	88	10	Service Pack	20009	88	10	9-7X				9-7X								Sensor	20116	62	7	Sensor	20116	62	7	Service Pack	20004	62	7	Service Pack	20004	62	7	2007-2005								9-3; 9-5				9-3; 9-5								Sensor	28078	62	7	Sensor	28078	62	7	Service Pack	20009	62	7	Service Pack	20009	62	7	9-7X				9-7X								Sensor	20116	62	7	Sensor	20116	62	7	Service Pack	20004	62	7	Service Pack	20004	62	7
Service Pack; W/48mm Green Insert ...	20038	31-40	3.5-4.5	Service Pack; Does Not Include Valve .	20023	31-40	3.5-4.5																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
Service Pack; W/49mm Black Insert	20039	31-40	3.5-4.5	Service Pack; W/43mm Silver Insert	20037	31-40	3.5-4.5																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
Service Pack; W/51mm Orange Insert .	20040	31-40	3.5-4.5	Service Pack; W/48mm Green Insert ...	20038	31-40	3.5-4.5																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
Cayman; Panamera																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																							
Sensor; Includes Transmitter Only	28087	31-40	3.5-4.5	Service Pack; W/49mm Black Insert	20039	31-40	3.5-4.5																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
Service Pack; Does Not Include Valve .	20023	31-40	3.5-4.5	Service Pack; W/51mm Orange Insert .	20040	31-40	3.5-4.5																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
Service Pack; W/43mm Silver Insert	20037	31-40	3.5-4.5	2003																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																			
Service Pack; W/48mm Green Insert ...	20038	31-40	3.5-4.5	Rolls-Royce																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																			
Service Pack; W/49mm Black Insert	20039	31-40	3.5-4.5	2010-2007																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																			
Service Pack; W/51mm Orange Insert .	20040	31-40	3.5-4.5	Phantom																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																			
2009																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																							
911; Boxster; Cayenne																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																							
Service Pack; Does Not Include Valve .	20023	31-40	3.5-4.5	Service Pack; Does Not Include Valve .	20023	31-40	3.5-4.5																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
Service Pack; W/43mm Silver Insert	20037	31-40	3.5-4.5	Service Pack; W/43mm Silver Insert	20037	31-40	3.5-4.5																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
Service Pack; W/48mm Green Insert ...	20038	31-40	3.5-4.5	Service Pack; W/48mm Green Insert ...	20038	31-40	3.5-4.5																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
Service Pack; W/49mm Black Insert	20039	31-40	3.5-4.5	Service Pack; W/49mm Black Insert	20039	31-40	3.5-4.5																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
Service Pack; W/51mm Orange Insert .	20040	31-40	3.5-4.5	Service Pack; W/51mm Orange Insert .	20040	31-40	3.5-4.5																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
2008																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																							
911; Boxster; Cayenne; Cayman																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																							
Service Pack; Does Not Include Valve .	20023	31-40	3.5-4.5	Saab																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																			
Service Pack; W/43mm Silver Insert	20037	31-40	3.5-4.5	2012																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																			
Service Pack; W/48mm Green Insert ...	20038	31-40	3.5-4.5	9-3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																			
Service Pack; W/49mm Black Insert	20039	31-40	3.5-4.5	Sensor	20159	88	10																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
Service Pack; W/51mm Orange Insert .	20040	31-40	3.5-4.5	Service Pack	20009	88	10																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
2007				9-4X																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																			
911; Boxster; Cayman				EZ-sensor - 315 MHz	◆33000	11.5	1.3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
Service Pack; Does Not Include Valve .	20023	31-40	3.5-4.5	Sensor	28206	11.5	1.3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
Service Pack; W/43mm Silver Insert	20037	31-40	3.5-4.5	Service Pack	20008	11.5	1.3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
Service Pack; W/48mm Green Insert ...	20038	31-40	3.5-4.5	9-5																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																			
Service Pack; W/49mm Black Insert	20039	31-40	3.5-4.5	Sensor	20159	88	10																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
Service Pack; W/51mm Orange Insert .	20040	31-40	3.5-4.5	Service Pack	20009	88	10																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
2006				2011-2010																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																			
911; Boxster; Carrera GT; Cayenne; Cayman				9-3; 9-5																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																			
Service Pack; Does Not Include Valve .	20023	31-40	3.5-4.5	Sensor	20159	88	10																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
Service Pack; W/43mm Silver Insert	20037	31-40	3.5-4.5	Service Pack	20009	88	10																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
Service Pack; W/48mm Green Insert ...	20038	31-40	3.5-4.5	9-3; 9-5																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																			
Service Pack; W/49mm Black Insert	20039	31-40	3.5-4.5	Sensor	20159	88	10																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
Service Pack; W/51mm Orange Insert .	20040	31-40	3.5-4.5	Service Pack	20009	88	10																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
2005				2009-2008																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																			
9-3; 9-5				9-3; 9-5																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																			
Sensor	20159	88	10	Sensor	20159	88	10																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
Service Pack	20009	88	10	Service Pack	20009	88	10																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
9-7X				9-7X																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																			
Sensor	20116	62	7	Sensor	20116	62	7																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
Service Pack	20004	62	7	Service Pack	20004	62	7																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
2007-2005																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																							
9-3; 9-5				9-3; 9-5																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																			
Sensor	28078	62	7	Sensor	28078	62	7																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
Service Pack	20009	62	7	Service Pack	20009	62	7																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
9-7X				9-7X																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																			
Sensor	20116	62	7	Sensor	20116	62	7																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
Service Pack	20004	62	7	Service Pack	20004	62	7																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																

◆ Programming Tool Required.



Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.				
Saab - Continued											
2004-2003											
9-3; 9-5											
Sensor	28078	62	7	EZ-sensor - 315 MHz	◇33000	11.5	1.3				
Service Pack	20009	62	7	EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
Saturn											
2010-2009											
Astra											
EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	28206	11.5	1.3	Sensor	20158	62	7				
Service Pack	20008	11.5	1.3	Service Pack; W/Schrader Sensor	20004	62	7				
Aura; Outlook											
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack; W/Siemens Sensor	20030	62	7				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Saturn - Continued							
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	2007							
Sensor	20153	11.5	1.3	Aura; Outlook							
Service Pack	20008	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3				
Sky				EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor	28365	35	4				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack	20032	35	4				
Sensor	20158	62	7	Scion							
Service Pack; W/Schrader Sensor	20004	62	7	2012							
Service Pack; W/Siemens Sensor	20030	80	9	iQ; TC; XB							
VUE											
EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	20153	11.5	1.3	Sensor	28365	35	4				
Service Pack	20008	11.5	1.3	Service Pack	20032	35	4				
2008											
Astra											
EZ-sensor - 315 MHz	◇33000	11.5	1.3	2011							
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	iQ; TC; XB; XD							
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz							
Sensor	28078	80	9	EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
Service Pack	20009	80	9	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Aura				Sensor	28365	35	4				
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack	20032	35	4				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	2010-2008							
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	TC; XB; XD							
Sensor	20153	11.5	1.3	EZ-sensor - 315 MHz							
Service Pack	20008	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
Outlook				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor	28365	35	4				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Service Pack	20032	35	4				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	2007							
Sensor	20158	62	7	TC							
Service Pack; W/Schrader Sensor	20004	62	7	EZ-sensor - 315 MHz							
Service Pack; W/Siemens Sensor	20030	62	7	EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
Sky				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor	28365	35	4				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Service Pack	20032	35	4				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	2006							
Sensor	20158	62	7	TC							
Service Pack; W/Schrader Sensor	20004	62	7	EZ-sensor - 315 MHz							
Service Pack; W/Siemens Sensor	20030	62	7	EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
VUE				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor	28365	35	4				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Service Pack	20032	35	4				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	2006							
Sensor	20153	11.5	1.3	TC							
Service Pack	20008	11.5	1.3	EZ-sensor - 315 MHz							
Smart				EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
2012-2008				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Fortwo				Sensor	28365	35	4				
Sensor	28214	53	6	Service Pack	20032	35	4				
Service Pack; Does Not Include Stem ..	20016	53	6	Subaru							
Service Pack; Includes Stem Only	20020	53	6	2012							
Forester; Impreza; Legacy; Outback											
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Forester; Impreza; Legacy; Outback							
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
Sensor	28203	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Service Pack	20008	11.5	1.3	Sensor	28203	11.5	1.3				
2011				Service Pack	20008	11.5	1.3				
Forester; Impreza; Legacy; Outback				2011							
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Forester; Impreza; Legacy; Outback							

◊ Programming Tool Required.



PRINTED ON RECYCLED PAPER
WITH 100% POSTCONSUMER WASTE

Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.				
Subaru - Continued											
2011 - Continued											
Forester; Impreza; Legacy; Outback - Continued											
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
Sensor	28203	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Service Pack	20008	11.5	1.3	Sensor	20081	66	7.5				
Tribeca											
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack	20011	66	7.5				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Subaru - Continued							
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3								
Sensor	28203	11.5	1.3								
2010-2009											
Forester; Impreza; Legacy; Outback; Tribeca											
EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	28203	11.5	1.3	Sensor	20066	58	6.5				
Service Pack	20008	11.5	1.3	or	28308	11.5	1.3				
2008											
Forester; Impreza											
EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Almmn. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	28203	11.5	1.3	Sensor	20087	80	9				
Service Pack	20008	11.5	1.3	Service Pack	20009	80	9				
Legacy											
EZ-sensor - 315 MHz	◇33000	11.5	1.3	2011-2010							
EZ-sensor Service Pack; Almmn. Valve	34000	62	7								
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3								
Sensor; W/16" Or 17" Wheels	20081	66	7.5								
Sensor; W/18" Wheels	28203	11.5	1.3								
Service Pack; W/16" Or 17" Wheels	20011	66	7.5								
Service Pack; W/18" Wheels	20008	11.5	1.3								
Outback											
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Equator							
EZ-sensor Service Pack; Almmn. Valve	34000	62	7								
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3								
Sensor	28203	11.5	1.3								
Service Pack	20008	11.5	1.3								
Tribeca											
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Grand Vitara							
EZ-sensor Service Pack; Almmn. Valve	34000	62	7								
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3								
Sensor; W/Metal Stem Clamp-in Sensor	20081	66	7.5								
Sensor; W/Rubber Stem Snap-in Sensor	28203	11.5	1.3								
Service Pack; W/Metal Stem Clamp-in Sensor	20011	66	7.5								
Service Pack; W/Rubber Stem Snap-in Sensor	20008	11.5	1.3								
2007											
B9 Tribeca; Legacy											
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Kizashi							
EZ-sensor Service Pack; Almmn. Valve	34000	62	7								
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3								
Sensor	20081	66	7.5								
Service Pack	20011	66	7.5								
2006											
B9 Tribeca; Legacy; Outback											
EZ-sensor - 315 MHz	◇33000	11.5	1.3	SX4							
EZ-sensor Service Pack; Almmn. Valve	34000	62	7								
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3								
Sensor	20081	66	7.5								
Service Pack	20011	66	7.5								
2009											
Equator											
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Grand Vitara; SX4							
EZ-sensor Service Pack; Almmn. Valve	34000	62	7								
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3								
Sensor	20087	80	9								
Service Pack	20009	80	9								

◊ Programming Tool Required.



Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																				
Suzuki - Continued																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
2009 - Continued																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
Grand Vitara; SX4 - Continued																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor	28360	35	4																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack	20032	35	4																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																				
Sensor	20087	80	9	Toyota - Continued																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																							
Service Pack	20009	80	9	2012 - Continued								XL-7								EZ-sensor - 315 MHz	◆33000	11.5	1.3	Highlander - Continued								EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor	◆33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor	34000	62	7	Sensor	20158	62	7	Service Pack	2008	11.5	1.3	Service Pack; W/Schrader Sensor	20004	62	7	Prius								Service Pack; W/Siemens Sensor	20030	62	7	EZ-sensor - 315 MHz	◆33000	11.5	1.3	2008-2007				EZ-sensor Service Pack; Almm. Valve	34000	62	7	Forenza				EZ-sensor Service Pack; Rubber Valve	2008	11.5	1.3	EZ-sensor - 315 MHz	◆33000	11.5	1.3	Sensor	28365	35	4	EZ-sensor Service Pack; Almm. Valve	34000	62	7	Service Pack	20032	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Tacoma								Sensor	20153	11.5	1.3	EZ-sensor - 315 MHz	◆33000	11.5	1.3	Service Pack	20008	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7	Grand Vitara				EZ-sensor Service Pack; Rubber Valve	2008	11.5	1.3	EZ-sensor - 315 MHz	◆33000	11.5	1.3	Sensor; W/Angle Wheels; W/20 Deg.	28360	35	4	EZ-sensor Service Pack; Almm. Valve	34000	62	7	Angled Valve Sensor	28380	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack	20032	35	4	Sensor	20087	80	9	Tundra								Service Pack	20009	80	9	EZ-sensor - 315 MHz	◆33000	11.5	1.3	Reno				EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor - 315 MHz	◆33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	2008	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor	28670	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack	20022	35	4	Sensor	20153	11.5	1.3	Yaris								Service Pack	20008	11.5	1.3	EZ-sensor - 315 MHz	◆33000	11.5	1.3	SX4				EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor - 315 MHz	◆33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	2008	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor	28365	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack	20032	35	4	Sensor	20087	80	9	2011								Service Pack	20009	80	9	4 Runner								XL-7				EZ-sensor - 315 MHz	◆33000	11.5	1.3	EZ-sensor - 315 MHz	◆33000	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	2008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor	28370	35	4	Sensor	20158	62	7	Service Pack	20032	35	4	Service Pack; W/Schrader Sensor	20004	62	7	Avalon								Service Pack; W/Siemens Sensor	20030	62	7	EZ-sensor - 315 MHz	◆33000	11.5	1.3	2006-2005				EZ-sensor Service Pack; Almm. Valve	34000	62	7	Verona				EZ-sensor Service Pack; Rubber Valve	2008	11.5	1.3	EZ-sensor - 315 MHz	◆33000	11.5	1.3	Sensor	28360	35	4	EZ-sensor Service Pack; Almm. Valve	34000	62	7	Service Pack	20032	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Camry								Sensor	20082	80	9	EZ-sensor - 315 MHz	◆33000	11.5	1.3	Service Pack	20009	80	9	EZ-sensor Service Pack; Almm. Valve	34000	62	7	XL-7				EZ-sensor Service Pack; Rubber Valve	2008	11.5	1.3	EZ-sensor - 315 MHz	◆33000	11.5	1.3	Sensor; Models made in Japan.; OEM	28365	35	4	EZ-sensor Service Pack; Almm. Valve	34000	62	7	Part No. 4260733011	28365	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; Models made in USA.; OEM	28360	35	4	Sensor	20158	62	7	Part	20032	35	4	Service Pack; W/Schrader Sensor	20004	62	7	No. 4260706011	28360	35	4	Service Pack; W/Siemens Sensor	20030	62	7	Service Pack	20032	35	4	Toyota				Corolla								2012				EZ-sensor - 315 MHz	◆33000	11.5	1.3	Highlander				EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor - 315 MHz	◆33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	2008	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor; Models made in Japan.; OEM	28365	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Part No. 4260733011	28365	35	4	Sensor	20087	80	9	Sensor; Models made in Japan.; OEM	28370	35	4	Service Pack	20009	80	9	Part No. 4260733021	28365	35	4	Toyota				Sensor; Models made in USA.; W/15" Wheels	28360	35	4	2012				Sensor; Models made in USA.; W/16" Or 17" Wheels	28360	35	4	Highlander				Service Pack	20032	35	4	EZ-sensor - 315 MHz	◆33000	11.5	1.3					EZ-sensor Service Pack; Almm. Valve	34000	62	7					EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
2012 - Continued																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
XL-7																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
EZ-sensor - 315 MHz	◆33000	11.5	1.3	Highlander - Continued																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																							
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor	◆33000	11.5	1.3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor	34000	62	7																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																				
Sensor	20158	62	7	Service Pack	2008	11.5	1.3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																				
Service Pack; W/Schrader Sensor	20004	62	7	Prius																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																							
Service Pack; W/Siemens Sensor	20030	62	7	EZ-sensor - 315 MHz	◆33000	11.5	1.3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																				
2008-2007				EZ-sensor Service Pack; Almm. Valve	34000	62	7																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																				
Forenza				EZ-sensor Service Pack; Rubber Valve	2008	11.5	1.3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																				
EZ-sensor - 315 MHz	◆33000	11.5	1.3	Sensor	28365	35	4																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																				
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Service Pack	20032	35	4																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Tacoma																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																							
Sensor	20153	11.5	1.3	EZ-sensor - 315 MHz	◆33000	11.5	1.3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																				
Service Pack	20008	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																				
Grand Vitara				EZ-sensor Service Pack; Rubber Valve	2008	11.5	1.3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																				
EZ-sensor - 315 MHz	◆33000	11.5	1.3	Sensor; W/Angle Wheels; W/20 Deg.	28360	35	4																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																				
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Angled Valve Sensor	28380	35	4																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack	20032	35	4																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																				
Sensor	20087	80	9	Tundra																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																							
Service Pack	20009	80	9	EZ-sensor - 315 MHz	◆33000	11.5	1.3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																				
Reno				EZ-sensor Service Pack; Almm. Valve	34000	62	7																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																				
EZ-sensor - 315 MHz	◆33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	2008	11.5	1.3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																				
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor	28670	35	4																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack	20022	35	4																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																				
Sensor	20153	11.5	1.3	Yaris																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																							
Service Pack	20008	11.5	1.3	EZ-sensor - 315 MHz	◆33000	11.5	1.3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																				
SX4				EZ-sensor Service Pack; Almm. Valve	34000	62	7																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																				
EZ-sensor - 315 MHz	◆33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	2008	11.5	1.3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																				
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor	28365	35	4																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack	20032	35	4																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																				
Sensor	20087	80	9	2011																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																							
Service Pack	20009	80	9	4 Runner																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																							
XL-7				EZ-sensor - 315 MHz	◆33000	11.5	1.3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																				
EZ-sensor - 315 MHz	◆33000	11.5	1.3	EZ-sensor Service Pack; Almm. Valve	34000	62	7																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																				
EZ-sensor Service Pack; Almm. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	2008	11.5	1.3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor	28370	35	4																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																				
Sensor	20158	62	7	Service Pack	20032	35	4																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																				
Service Pack; W/Schrader Sensor	20004	62	7	Avalon																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																							
Service Pack; W/Siemens Sensor	20030	62	7	EZ-sensor - 315 MHz	◆33000	11.5	1.3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																				
2006-2005				EZ-sensor Service Pack; Almm. Valve	34000	62	7																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																				
Verona				EZ-sensor Service Pack; Rubber Valve	2008	11.5	1.3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																				
EZ-sensor - 315 MHz	◆33000	11.5	1.3	Sensor	28360	35	4																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																				
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Service Pack	20032	35	4																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Camry																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																							
Sensor	20082	80	9	EZ-sensor - 315 MHz	◆33000	11.5	1.3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																				
Service Pack	20009	80	9	EZ-sensor Service Pack; Almm. Valve	34000	62	7																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																				
XL-7				EZ-sensor Service Pack; Rubber Valve	2008	11.5	1.3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																				
EZ-sensor - 315 MHz	◆33000	11.5	1.3	Sensor; Models made in Japan.; OEM	28365	35	4																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																				
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Part No. 4260733011	28365	35	4																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; Models made in USA.; OEM	28360	35	4																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																				
Sensor	20158	62	7	Part	20032	35	4																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																				
Service Pack; W/Schrader Sensor	20004	62	7	No. 4260706011	28360	35	4																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																				
Service Pack; W/Siemens Sensor	20030	62	7	Service Pack	20032	35	4																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																				
Toyota				Corolla																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																							
2012				EZ-sensor - 315 MHz	◆33000	11.5	1.3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																				
Highlander				EZ-sensor Service Pack; Almm. Valve	34000	62	7																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																				
EZ-sensor - 315 MHz	◆33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	2008	11.5	1.3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																				
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor; Models made in Japan.; OEM	28365	35	4																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Part No. 4260733011	28365	35	4																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																				
Sensor	20087	80	9	Sensor; Models made in Japan.; OEM	28370	35	4																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																				
Service Pack	20009	80	9	Part No. 4260733021	28365	35	4																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																				
Toyota				Sensor; Models made in USA.; W/15" Wheels	28360	35	4																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																				
2012				Sensor; Models made in USA.; W/16" Or 17" Wheels	28360	35	4																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																				
Highlander				Service Pack	20032	35	4																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																				
EZ-sensor - 315 MHz	◆33000	11.5	1.3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																								
EZ-sensor Service Pack; Almm. Valve	34000	62	7																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																								
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																								

◆ Programming Tool Required.



PRINTED ON RECYCLED PAPER
WITH 100% POSTCONSUMER WASTE

Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
Toyota - Continued				Toyota - Continued			
2011 - Continued				2011 - Continued			
FJ Cruiser							
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack	20032	35	4
EZ-sensor Service Pack; Almm. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	28365	35	4				
Service Pack	20032	35	4				
Highlander							
EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Almm. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	28360	35	4				
Service Pack	20032	35	4				
Land Cruiser							
EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Almm. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	28365	35	4				
Service Pack	20032	35	4				
Matrix							
EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Almm. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor; Models made in Japan.; OEM Part No. 4260733011	28365	35	4				
Sensor; Models made in USA.; OEM Part No. 4260706011	28360	35	4				
Service Pack	20032	35	4				
Prius							
EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Almm. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	28365	35	4				
Service Pack	20032	35	4				
RAV4							
EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Almm. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	28370	35	4				
Service Pack	20032	35	4				
Sequoia; Sienna							
EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Almm. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	28670	35	4				
Service Pack	20022	35	4				
Tacoma							
EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Almm. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor	28360	35	4				
Sensor; W/Steel Wheels; W/40 Deg. Angled Valve Sensor	28380	35	4				
Service Pack	20032	35	4				
Tundra							
EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Almm. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	28670	35	4				
Service Pack	20022	35	4				
Venza							
EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Almm. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	28360	35	4				
2010				2010			
4 Runner							
EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Almm. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	28370	35	4				
Service Pack	20032	35	4				
Avalon							
EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Almm. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	28360	35	4				
Service Pack	20032	35	4				
Camry							
EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Almm. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor; Models made in Japan.; OEM Part No. 4260733011	28365	35	4				
Sensor; Models made in USA.; OEM Part No. 4260706011	28360	35	4				
Service Pack	20032	35	4				
Corolla							
EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Almm. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor; Models made in Japan.; OEM Part No. 4260733011	28365	35	4				
Sensor; Models made in Japan.; OEM Part No. 4260733021	28370	35	4				
Sensor; Models made in USA.; W/15" Wheels	28365	35	4				
Sensor; Models made in USA.; W/16" Or 17" Wheels	28360	35	4				
Service Pack	20032	35	4				
FJ Cruiser; Highlander; Land Cruiser							
EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Almm. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	28365	35	4				
Service Pack	20032	35	4				
Matrix							
EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Almm. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor; Models made in Japan.; OEM Part No. 4260733011	28365	35	4				
Sensor; Models made in USA.; OEM Part No. 4260706011	28360	35	4				
Service Pack	20032	35	4				
Prius							
EZ-sensor - 315 MHz	◇33000	11.5	1.3				
EZ-sensor Service Pack; Almm. Valve	34000	62	7				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor	28365	35	4				
Service Pack	20032	35	4				

◇ Programming Tool Required.



Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																									
Toyota - Continued																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
2010 - Continued																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
RAV4																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																									
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																									
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; Models made in Japan.; OEM Part No. 4260733011	28365	35	4																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																									
Sensor	28370	35	4	Sensor; Models made in Japan.; OEM Part No. 4260733021	28370	35	4																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																									
Service Pack	20032	35	4	Sensor; Models made in USA.; W/15" Wheels	28365	35	4																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																									
Sequoia; Sienna																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor; Models made in USA.; W/16" Or 17" Wheels	28360	35	4																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																									
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Service Pack	20032	35	4																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																									
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	FJ Cruiser; Highlander; Land Cruiser																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																												
Sensor	28670	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Service Pack	20022	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Tacoma				Sensor	28365	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack	20032	35	4	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Matrix								EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor	28360	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor; W/Steel Wheels; W/40 Deg. Angled Valve Sensor	28380	35	4	Service Pack	20032	35	4	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Tundra				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; Models made in Japan.; OEM Part No. 4260733011	28365	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor	28670	35	4	Sensor; Models made in USA.; OEM Part No. 4260706011	28360	35	4	Sensor; W/20 Deg. Angled Valve Sensor	28670	35	4	Service Pack	20022	35	4	Service Pack	20032	35	4	Venza				Prius								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor	28365	35	4	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor	28360	35	4	Service Pack	20032	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Yaris				EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor	28365	35	4	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack	20032	35	4	Sensor	28365	35	4	RAV4								Service Pack	20032	35	4	EZ-sensor - 315 MHz								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor								Sensor	28370	35	4	Service Pack								Service Pack	20032	35	4	2009								Sequoia; Sienna								4 Runner								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; W/Valve Cap	28365	35	4	Sensor; W/O Valve Cap	28370	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack	20032	35	4	Tacoma				Sensor	28670	35	4	Avalon				Service Pack	20022	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Camry								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor	28360	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack	20032	35	4	EZ-sensor - 315 MHz				EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor				Sensor; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor	28365	35	4	Service Pack				Corolla								Sensor; W/Steel Wheels; W/40 Deg. Angled Valve Sensor	28380	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack								Sensor	20032	35	4	Corolla								Tundra								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; Models made in Japan.; OEM Part No. 4260733011								EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; Models made in USA.; OEM Part No. 4260706011				Sensor; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor								28670	35	4	Service Pack				Service Pack								20022	35	4	Venza								Corolla - Continued								EZ-sensor - 315 MHz								EZ-sensor Service Pack; Almmn. Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor				Sensor; Models made in Japan.; OEM Part No. 4260733011								28365	35	4	Service Pack				Sensor; Models made in USA.; OEM Part No. 4260706011								28370	35	4	Corolla								Service Pack								EZ-sensor - 315 MHz	◇33000	11.5	1.3	2009 - Continued								Corolla - Continued								EZ-sensor Service Pack; Almmn. Valve								EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor				Sensor; Models made in Japan.; OEM Part No. 4260733011				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack				Sensor; Models made in USA.; OEM Part No. 4260706011				Sensor; Models made in USA.; W/15" Wheels								28365	35	4	Corolla								Sensor; Models made in USA.; W/16" Or 17" Wheels								28360	35	4	EZ-sensor - 315 MHz								Service Pack								20032	35	4
EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																									
Service Pack	20022	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Tacoma				Sensor	28365	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack	20032	35	4	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Matrix								EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor	28360	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor; W/Steel Wheels; W/40 Deg. Angled Valve Sensor	28380	35	4	Service Pack	20032	35	4	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Tundra				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; Models made in Japan.; OEM Part No. 4260733011	28365	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor	28670	35	4	Sensor; Models made in USA.; OEM Part No. 4260706011	28360	35	4	Sensor; W/20 Deg. Angled Valve Sensor	28670	35	4	Service Pack	20022	35	4	Service Pack	20032	35	4	Venza				Prius								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor	28365	35	4	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor	28360	35	4	Service Pack	20032	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Yaris				EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor	28365	35	4	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack	20032	35	4	Sensor	28365	35	4	RAV4								Service Pack	20032	35	4	EZ-sensor - 315 MHz								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor								Sensor	28370	35	4	Service Pack								Service Pack	20032	35	4	2009								Sequoia; Sienna								4 Runner								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; W/Valve Cap	28365	35	4	Sensor; W/O Valve Cap	28370	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack	20032	35	4	Tacoma				Sensor	28670	35	4	Avalon				Service Pack	20022	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Camry								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor	28360	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack	20032	35	4	EZ-sensor - 315 MHz				EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor				Sensor; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor	28365	35	4	Service Pack				Corolla								Sensor; W/Steel Wheels; W/40 Deg. Angled Valve Sensor	28380	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack								Sensor	20032	35	4	Corolla								Tundra								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; Models made in Japan.; OEM Part No. 4260733011								EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; Models made in USA.; OEM Part No. 4260706011				Sensor; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor								28670	35	4	Service Pack				Service Pack								20022	35	4	Venza								Corolla - Continued								EZ-sensor - 315 MHz								EZ-sensor Service Pack; Almmn. Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor				Sensor; Models made in Japan.; OEM Part No. 4260733011								28365	35	4	Service Pack				Sensor; Models made in USA.; OEM Part No. 4260706011								28370	35	4	Corolla								Service Pack								EZ-sensor - 315 MHz	◇33000	11.5	1.3	2009 - Continued								Corolla - Continued								EZ-sensor Service Pack; Almmn. Valve								EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor				Sensor; Models made in Japan.; OEM Part No. 4260733011				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack				Sensor; Models made in USA.; OEM Part No. 4260706011				Sensor; Models made in USA.; W/15" Wheels												28365	35	4	Corolla								Sensor; Models made in USA.; W/16" Or 17" Wheels								28360	35	4	EZ-sensor - 315 MHz								Service Pack								20032	35	4								
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																									
Tacoma				Sensor	28365	35	4																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																									
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack	20032	35	4																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																									
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Matrix																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																												
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor	28360	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor; W/Steel Wheels; W/40 Deg. Angled Valve Sensor	28380	35	4	Service Pack	20032	35	4	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Tundra				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; Models made in Japan.; OEM Part No. 4260733011	28365	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor	28670	35	4	Sensor; Models made in USA.; OEM Part No. 4260706011	28360	35	4	Sensor; W/20 Deg. Angled Valve Sensor	28670	35	4	Service Pack	20022	35	4	Service Pack	20032	35	4	Venza				Prius								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor	28365	35	4	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor	28360	35	4	Service Pack	20032	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Yaris				EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor	28365	35	4	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack	20032	35	4	Sensor	28365	35	4	RAV4								Service Pack	20032	35	4	EZ-sensor - 315 MHz								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor								Sensor	28370	35	4	Service Pack								Service Pack	20032	35	4	2009								Sequoia; Sienna								4 Runner								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; W/Valve Cap	28365	35	4	Sensor; W/O Valve Cap	28370	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack	20032	35	4	Tacoma				Sensor	28670	35	4	Avalon				Service Pack	20022	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Camry								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor	28360	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack	20032	35	4	EZ-sensor - 315 MHz				EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor				Sensor; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor	28365	35	4	Service Pack				Corolla								Sensor; W/Steel Wheels; W/40 Deg. Angled Valve Sensor	28380	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack								Sensor	20032	35	4	Corolla								Tundra								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; Models made in Japan.; OEM Part No. 4260733011								EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; Models made in USA.; OEM Part No. 4260706011				Sensor; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor								28670	35	4	Service Pack				Service Pack								20022	35	4	Venza								Corolla - Continued								EZ-sensor - 315 MHz								EZ-sensor Service Pack; Almmn. Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor				Sensor; Models made in Japan.; OEM Part No. 4260733011								28365	35	4	Service Pack				Sensor; Models made in USA.; OEM Part No. 4260706011								28370	35	4	Corolla								Service Pack								EZ-sensor - 315 MHz	◇33000	11.5	1.3	2009 - Continued								Corolla - Continued								EZ-sensor Service Pack; Almmn. Valve								EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor				Sensor; Models made in Japan.; OEM Part No. 4260733011				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack				Sensor; Models made in USA.; OEM Part No. 4260706011				Sensor; Models made in USA.; W/15" Wheels								28365	35	4	Corolla								Sensor; Models made in USA.; W/16" Or 17" Wheels								28360	35	4	EZ-sensor - 315 MHz								Service Pack								20032	35	4																																																				
Sensor; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor	28360	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																									
Sensor; W/Steel Wheels; W/40 Deg. Angled Valve Sensor	28380	35	4	Service Pack	20032	35	4	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Tundra				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; Models made in Japan.; OEM Part No. 4260733011	28365	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor	28670	35	4	Sensor; Models made in USA.; OEM Part No. 4260706011	28360	35	4	Sensor; W/20 Deg. Angled Valve Sensor	28670	35	4	Service Pack	20022	35	4	Service Pack	20032	35	4	Venza				Prius								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor	28365	35	4	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor	28360	35	4	Service Pack	20032	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Yaris				EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor	28365	35	4	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack	20032	35	4	Sensor	28365	35	4	RAV4								Service Pack	20032	35	4	EZ-sensor - 315 MHz								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor								Sensor	28370	35	4	Service Pack								Service Pack	20032	35	4	2009								Sequoia; Sienna								4 Runner								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; W/Valve Cap	28365	35	4	Sensor; W/O Valve Cap	28370	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack	20032	35	4	Tacoma				Sensor	28670	35	4	Avalon				Service Pack	20022	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Camry								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor	28360	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack	20032	35	4	EZ-sensor - 315 MHz				EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor				Sensor; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor	28365	35	4	Service Pack				Corolla								Sensor; W/Steel Wheels; W/40 Deg. Angled Valve Sensor	28380	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack								Sensor	20032	35	4	Corolla								Tundra								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; Models made in Japan.; OEM Part No. 4260733011								EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; Models made in USA.; OEM Part No. 4260706011				Sensor; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor								28670	35	4	Service Pack				Service Pack								20022	35	4	Venza								Corolla - Continued								EZ-sensor - 315 MHz								EZ-sensor Service Pack; Almmn. Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor				Sensor; Models made in Japan.; OEM Part No. 4260733011								28365	35	4	Service Pack				Sensor; Models made in USA.; OEM Part No. 4260706011								28370	35	4	Corolla								Service Pack								EZ-sensor - 315 MHz	◇33000	11.5	1.3	2009 - Continued								Corolla - Continued								EZ-sensor Service Pack; Almmn. Valve								EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor				Sensor; Models made in Japan.; OEM Part No. 4260733011				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack				Sensor; Models made in USA.; OEM Part No. 4260706011				Sensor; Models made in USA.; W/15" Wheels												28365	35	4	Corolla								Sensor; Models made in USA.; W/16" Or 17" Wheels								28360	35	4	EZ-sensor - 315 MHz								Service Pack								20032	35	4																																																												
Service Pack	20032	35	4	EZ-sensor Service Pack; Almmn. Valve	34000	62	7																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																									
Tundra				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																									
EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; Models made in Japan.; OEM Part No. 4260733011	28365	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor	28670	35	4	Sensor; Models made in USA.; OEM Part No. 4260706011	28360	35	4	Sensor; W/20 Deg. Angled Valve Sensor	28670	35	4	Service Pack	20022	35	4	Service Pack	20032	35	4	Venza				Prius								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor	28365	35	4	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor	28360	35	4	Service Pack	20032	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Yaris				EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor	28365	35	4	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack	20032	35	4	Sensor	28365	35	4	RAV4								Service Pack	20032	35	4	EZ-sensor - 315 MHz								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor								Sensor	28370	35	4	Service Pack								Service Pack	20032	35	4	2009								Sequoia; Sienna								4 Runner								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; W/Valve Cap	28365	35	4	Sensor; W/O Valve Cap	28370	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack	20032	35	4	Tacoma				Sensor	28670	35	4	Avalon				Service Pack	20022	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Camry								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor	28360	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack	20032	35	4	EZ-sensor - 315 MHz				EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor				Sensor; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor	28365	35	4	Service Pack				Corolla								Sensor; W/Steel Wheels; W/40 Deg. Angled Valve Sensor	28380	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack								Sensor	20032	35	4	Corolla								Tundra								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; Models made in Japan.; OEM Part No. 4260733011								EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; Models made in USA.; OEM Part No. 4260706011				Sensor; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor								28670	35	4	Service Pack				Service Pack								20022	35	4	Venza								Corolla - Continued								EZ-sensor - 315 MHz								EZ-sensor Service Pack; Almmn. Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor				Sensor; Models made in Japan.; OEM Part No. 4260733011								28365	35	4	Service Pack				Sensor; Models made in USA.; OEM Part No. 4260706011								28370	35	4	Corolla								Service Pack								EZ-sensor - 315 MHz	◇33000	11.5	1.3	2009 - Continued								Corolla - Continued								EZ-sensor Service Pack; Almmn. Valve								EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor				Sensor; Models made in Japan.; OEM Part No. 4260733011				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack				Sensor; Models made in USA.; OEM Part No. 4260706011				Sensor; Models made in USA.; W/15" Wheels								28365	35	4	Corolla								Sensor; Models made in USA.; W/16" Or 17" Wheels								28360	35	4	EZ-sensor - 315 MHz								Service Pack								20032	35	4																																																																																				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; Models made in Japan.; OEM Part No. 4260733011	28365	35	4																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																									
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor	28670	35	4	Sensor; Models made in USA.; OEM Part No. 4260706011	28360	35	4	Sensor; W/20 Deg. Angled Valve Sensor	28670	35	4	Service Pack	20022	35	4	Service Pack	20032	35	4	Venza				Prius								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor	28365	35	4	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor	28360	35	4	Service Pack	20032	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Yaris				EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor	28365	35	4	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack	20032	35	4	Sensor	28365	35	4	RAV4								Service Pack	20032	35	4	EZ-sensor - 315 MHz								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor								Sensor	28370	35	4	Service Pack								Service Pack	20032	35	4	2009								Sequoia; Sienna								4 Runner								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; W/Valve Cap	28365	35	4	Sensor; W/O Valve Cap	28370	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack	20032	35	4	Tacoma				Sensor	28670	35	4	Avalon				Service Pack	20022	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Camry								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor	28360	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack	20032	35	4	EZ-sensor - 315 MHz				EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor				Sensor; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor	28365	35	4	Service Pack				Corolla								Sensor; W/Steel Wheels; W/40 Deg. Angled Valve Sensor	28380	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack								Sensor	20032	35	4	Corolla								Tundra								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; Models made in Japan.; OEM Part No. 4260733011								EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; Models made in USA.; OEM Part No. 4260706011				Sensor; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor								28670	35	4	Service Pack				Service Pack								20022	35	4	Venza								Corolla - Continued								EZ-sensor - 315 MHz								EZ-sensor Service Pack; Almmn. Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor				Sensor; Models made in Japan.; OEM Part No. 4260733011								28365	35	4	Service Pack				Sensor; Models made in USA.; OEM Part No. 4260706011								28370	35	4	Corolla								Service Pack								EZ-sensor - 315 MHz	◇33000	11.5	1.3	2009 - Continued								Corolla - Continued								EZ-sensor Service Pack; Almmn. Valve								EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor				Sensor; Models made in Japan.; OEM Part No. 4260733011				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack				Sensor; Models made in USA.; OEM Part No. 4260706011				Sensor; Models made in USA.; W/15" Wheels												28365	35	4	Corolla								Sensor; Models made in USA.; W/16" Or 17" Wheels								28360	35	4	EZ-sensor - 315 MHz								Service Pack								20032	35	4																																																																																												
Sensor; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor	28670	35	4	Sensor; Models made in USA.; OEM Part No. 4260706011	28360	35	4																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																									
Sensor; W/20 Deg. Angled Valve Sensor	28670	35	4	Service Pack	20022	35	4	Service Pack	20032	35	4	Venza				Prius								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor	28365	35	4	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor	28360	35	4	Service Pack	20032	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Yaris				EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor	28365	35	4	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack	20032	35	4	Sensor	28365	35	4	RAV4								Service Pack	20032	35	4	EZ-sensor - 315 MHz								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor								Sensor	28370	35	4	Service Pack								Service Pack	20032	35	4	2009								Sequoia; Sienna								4 Runner								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; W/Valve Cap	28365	35	4	Sensor; W/O Valve Cap	28370	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack	20032	35	4	Tacoma				Sensor	28670	35	4	Avalon				Service Pack	20022	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Camry								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor	28360	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack	20032	35	4	EZ-sensor - 315 MHz				EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor				Sensor; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor	28365	35	4	Service Pack				Corolla								Sensor; W/Steel Wheels; W/40 Deg. Angled Valve Sensor	28380	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack								Sensor	20032	35	4	Corolla								Tundra								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; Models made in Japan.; OEM Part No. 4260733011								EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; Models made in USA.; OEM Part No. 4260706011				Sensor; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor								28670	35	4	Service Pack				Service Pack								20022	35	4	Venza								Corolla - Continued								EZ-sensor - 315 MHz								EZ-sensor Service Pack; Almmn. Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor				Sensor; Models made in Japan.; OEM Part No. 4260733011								28365	35	4	Service Pack				Sensor; Models made in USA.; OEM Part No. 4260706011								28370	35	4	Corolla								Service Pack								EZ-sensor - 315 MHz	◇33000	11.5	1.3	2009 - Continued								Corolla - Continued								EZ-sensor Service Pack; Almmn. Valve								EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor				Sensor; Models made in Japan.; OEM Part No. 4260733011				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack				Sensor; Models made in USA.; OEM Part No. 4260706011				Sensor; Models made in USA.; W/15" Wheels												28365	35	4	Corolla								Sensor; Models made in USA.; W/16" Or 17" Wheels								28360	35	4	EZ-sensor - 315 MHz								Service Pack								20032	35	4																																																																																																								
Service Pack	20022	35	4	Service Pack	20032	35	4																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																									
Venza				Prius																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																												
EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor	28365	35	4	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor	28360	35	4	Service Pack	20032	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Yaris				EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor	28365	35	4	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack	20032	35	4	Sensor	28365	35	4	RAV4								Service Pack	20032	35	4	EZ-sensor - 315 MHz								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor								Sensor	28370	35	4	Service Pack								Service Pack	20032	35	4	2009								Sequoia; Sienna								4 Runner								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; W/Valve Cap	28365	35	4	Sensor; W/O Valve Cap	28370	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack	20032	35	4	Tacoma				Sensor	28670	35	4	Avalon				Service Pack	20022	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Camry								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor	28360	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack	20032	35	4	EZ-sensor - 315 MHz				EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor				Sensor; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor	28365	35	4	Service Pack				Corolla								Sensor; W/Steel Wheels; W/40 Deg. Angled Valve Sensor	28380	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack								Sensor	20032	35	4	Corolla								Tundra								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; Models made in Japan.; OEM Part No. 4260733011								EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; Models made in USA.; OEM Part No. 4260706011				Sensor; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor								28670	35	4	Service Pack				Service Pack								20022	35	4	Venza								Corolla - Continued								EZ-sensor - 315 MHz								EZ-sensor Service Pack; Almmn. Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor				Sensor; Models made in Japan.; OEM Part No. 4260733011								28365	35	4	Service Pack				Sensor; Models made in USA.; OEM Part No. 4260706011								28370	35	4	Corolla								Service Pack								EZ-sensor - 315 MHz	◇33000	11.5	1.3	2009 - Continued								Corolla - Continued								EZ-sensor Service Pack; Almmn. Valve								EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor				Sensor; Models made in Japan.; OEM Part No. 4260733011				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack				Sensor; Models made in USA.; OEM Part No. 4260706011				Sensor; Models made in USA.; W/15" Wheels								28365	35	4	Corolla								Sensor; Models made in USA.; W/16" Or 17" Wheels								28360	35	4	EZ-sensor - 315 MHz								Service Pack								20032	35	4																																																																																																																																				
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor - 315 MHz	◇33000	11.5	1.3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																									
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor	28365	35	4	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor	28360	35	4	Service Pack	20032	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Yaris				EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor	28365	35	4	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack	20032	35	4	Sensor	28365	35	4	RAV4								Service Pack	20032	35	4	EZ-sensor - 315 MHz								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor								Sensor	28370	35	4	Service Pack								Service Pack	20032	35	4	2009								Sequoia; Sienna								4 Runner								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; W/Valve Cap	28365	35	4	Sensor; W/O Valve Cap	28370	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack	20032	35	4	Tacoma				Sensor	28670	35	4	Avalon				Service Pack	20022	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Camry								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor	28360	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack	20032	35	4	EZ-sensor - 315 MHz				EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor				Sensor; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor	28365	35	4	Service Pack				Corolla								Sensor; W/Steel Wheels; W/40 Deg. Angled Valve Sensor	28380	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack								Sensor	20032	35	4	Corolla								Tundra								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; Models made in Japan.; OEM Part No. 4260733011								EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; Models made in USA.; OEM Part No. 4260706011				Sensor; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor								28670	35	4	Service Pack				Service Pack								20022	35	4	Venza								Corolla - Continued								EZ-sensor - 315 MHz								EZ-sensor Service Pack; Almmn. Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor				Sensor; Models made in Japan.; OEM Part No. 4260733011								28365	35	4	Service Pack				Sensor; Models made in USA.; OEM Part No. 4260706011								28370	35	4	Corolla								Service Pack								EZ-sensor - 315 MHz	◇33000	11.5	1.3	2009 - Continued								Corolla - Continued								EZ-sensor Service Pack; Almmn. Valve								EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor				Sensor; Models made in Japan.; OEM Part No. 4260733011				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack				Sensor; Models made in USA.; OEM Part No. 4260706011				Sensor; Models made in USA.; W/15" Wheels												28365	35	4	Corolla								Sensor; Models made in USA.; W/16" Or 17" Wheels								28360	35	4	EZ-sensor - 315 MHz								Service Pack								20032	35	4																																																																																																																																												
Sensor	28365	35	4	EZ-sensor Service Pack; Almmn. Valve	34000	62	7																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																									
Sensor	28360	35	4	Service Pack	20032	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Yaris				EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor	28365	35	4	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack	20032	35	4	Sensor	28365	35	4	RAV4								Service Pack	20032	35	4	EZ-sensor - 315 MHz								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor								Sensor	28370	35	4	Service Pack								Service Pack	20032	35	4	2009								Sequoia; Sienna								4 Runner								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; W/Valve Cap	28365	35	4	Sensor; W/O Valve Cap	28370	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack	20032	35	4	Tacoma				Sensor	28670	35	4	Avalon				Service Pack	20022	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Camry								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor	28360	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack	20032	35	4	EZ-sensor - 315 MHz				EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor				Sensor; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor	28365	35	4	Service Pack				Corolla								Sensor; W/Steel Wheels; W/40 Deg. Angled Valve Sensor	28380	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack								Sensor	20032	35	4	Corolla								Tundra								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; Models made in Japan.; OEM Part No. 4260733011								EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; Models made in USA.; OEM Part No. 4260706011				Sensor; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor								28670	35	4	Service Pack				Service Pack								20022	35	4	Venza								Corolla - Continued								EZ-sensor - 315 MHz								EZ-sensor Service Pack; Almmn. Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor				Sensor; Models made in Japan.; OEM Part No. 4260733011								28365	35	4	Service Pack				Sensor; Models made in USA.; OEM Part No. 4260706011								28370	35	4	Corolla								Service Pack								EZ-sensor - 315 MHz	◇33000	11.5	1.3	2009 - Continued								Corolla - Continued								EZ-sensor Service Pack; Almmn. Valve								EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor				Sensor; Models made in Japan.; OEM Part No. 4260733011				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack				Sensor; Models made in USA.; OEM Part No. 4260706011				Sensor; Models made in USA.; W/15" Wheels												28365	35	4	Corolla								Sensor; Models made in USA.; W/16" Or 17" Wheels								28360	35	4	EZ-sensor - 315 MHz								Service Pack								20032	35	4																																																																																																																																																								
Service Pack	20032	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																									
Yaris				EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor	28365	35	4	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack	20032	35	4	Sensor	28365	35	4	RAV4								Service Pack	20032	35	4	EZ-sensor - 315 MHz								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor								Sensor	28370	35	4	Service Pack								Service Pack	20032	35	4	2009								Sequoia; Sienna								4 Runner								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; W/Valve Cap	28365	35	4	Sensor; W/O Valve Cap	28370	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack	20032	35	4	Tacoma				Sensor	28670	35	4	Avalon				Service Pack	20022	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Camry								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor	28360	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack	20032	35	4	EZ-sensor - 315 MHz				EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor				Sensor; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor	28365	35	4	Service Pack				Corolla								Sensor; W/Steel Wheels; W/40 Deg. Angled Valve Sensor	28380	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack								Sensor	20032	35	4	Corolla								Tundra								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; Models made in Japan.; OEM Part No. 4260733011								EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; Models made in USA.; OEM Part No. 4260706011				Sensor; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor								28670	35	4	Service Pack				Service Pack								20022	35	4	Venza								Corolla - Continued								EZ-sensor - 315 MHz								EZ-sensor Service Pack; Almmn. Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor				Sensor; Models made in Japan.; OEM Part No. 4260733011								28365	35	4	Service Pack				Sensor; Models made in USA.; OEM Part No. 4260706011								28370	35	4	Corolla								Service Pack								EZ-sensor - 315 MHz	◇33000	11.5	1.3	2009 - Continued								Corolla - Continued								EZ-sensor Service Pack; Almmn. Valve								EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor				Sensor; Models made in Japan.; OEM Part No. 4260733011				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack				Sensor; Models made in USA.; OEM Part No. 4260706011				Sensor; Models made in USA.; W/15" Wheels												28365	35	4	Corolla								Sensor; Models made in USA.; W/16" Or 17" Wheels								28360	35	4	EZ-sensor - 315 MHz								Service Pack								20032	35	4																																																																																																																																																																				
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor	28365	35	4																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																									
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack	20032	35	4	Sensor	28365	35	4	RAV4								Service Pack	20032	35	4	EZ-sensor - 315 MHz								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor								Sensor	28370	35	4	Service Pack								Service Pack	20032	35	4	2009								Sequoia; Sienna								4 Runner								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; W/Valve Cap	28365	35	4	Sensor; W/O Valve Cap	28370	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack	20032	35	4	Tacoma				Sensor	28670	35	4	Avalon				Service Pack	20022	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Camry								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor	28360	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack	20032	35	4	EZ-sensor - 315 MHz				EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor				Sensor; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor	28365	35	4	Service Pack				Corolla								Sensor; W/Steel Wheels; W/40 Deg. Angled Valve Sensor	28380	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack								Sensor	20032	35	4	Corolla								Tundra								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; Models made in Japan.; OEM Part No. 4260733011								EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; Models made in USA.; OEM Part No. 4260706011				Sensor; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor								28670	35	4	Service Pack				Service Pack								20022	35	4	Venza								Corolla - Continued								EZ-sensor - 315 MHz								EZ-sensor Service Pack; Almmn. Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor				Sensor; Models made in Japan.; OEM Part No. 4260733011								28365	35	4	Service Pack				Sensor; Models made in USA.; OEM Part No. 4260706011								28370	35	4	Corolla								Service Pack								EZ-sensor - 315 MHz	◇33000	11.5	1.3	2009 - Continued								Corolla - Continued								EZ-sensor Service Pack; Almmn. Valve								EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor				Sensor; Models made in Japan.; OEM Part No. 4260733011				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack				Sensor; Models made in USA.; OEM Part No. 4260706011				Sensor; Models made in USA.; W/15" Wheels												28365	35	4	Corolla								Sensor; Models made in USA.; W/16" Or 17" Wheels								28360	35	4	EZ-sensor - 315 MHz								Service Pack								20032	35	4																																																																																																																																																																																
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack	20032	35	4																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																									
Sensor	28365	35	4	RAV4																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																												
Service Pack	20032	35	4	EZ-sensor - 315 MHz								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor								Sensor	28370	35	4	Service Pack								Service Pack	20032	35	4	2009								Sequoia; Sienna								4 Runner								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; W/Valve Cap	28365	35	4	Sensor; W/O Valve Cap	28370	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack	20032	35	4	Tacoma				Sensor	28670	35	4	Avalon				Service Pack	20022	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Camry								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor	28360	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack	20032	35	4	EZ-sensor - 315 MHz				EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor				Sensor; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor	28365	35	4	Service Pack				Corolla								Sensor; W/Steel Wheels; W/40 Deg. Angled Valve Sensor	28380	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack								Sensor	20032	35	4	Corolla								Tundra								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; Models made in Japan.; OEM Part No. 4260733011								EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; Models made in USA.; OEM Part No. 4260706011				Sensor; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor								28670	35	4	Service Pack				Service Pack								20022	35	4	Venza								Corolla - Continued								EZ-sensor - 315 MHz								EZ-sensor Service Pack; Almmn. Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor				Sensor; Models made in Japan.; OEM Part No. 4260733011								28365	35	4	Service Pack				Sensor; Models made in USA.; OEM Part No. 4260706011								28370	35	4	Corolla								Service Pack								EZ-sensor - 315 MHz	◇33000	11.5	1.3	2009 - Continued								Corolla - Continued								EZ-sensor Service Pack; Almmn. Valve								EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor				Sensor; Models made in Japan.; OEM Part No. 4260733011				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack				Sensor; Models made in USA.; OEM Part No. 4260706011				Sensor; Models made in USA.; W/15" Wheels								28365	35	4	Corolla								Sensor; Models made in USA.; W/16" Or 17" Wheels								28360	35	4	EZ-sensor - 315 MHz								Service Pack								20032	35	4																																																																																																																																																																																																												
EZ-sensor - 315 MHz								EZ-sensor - 315 MHz	◇33000	11.5	1.3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																					
EZ-sensor Service Pack; Almmn. Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																					
EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																					
Sensor								Sensor	28370	35	4																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																					
Service Pack								Service Pack	20032	35	4																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																					
2009								Sequoia; Sienna																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																								
4 Runner								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; W/Valve Cap	28365	35	4	Sensor; W/O Valve Cap	28370	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack	20032	35	4	Tacoma				Sensor	28670	35	4	Avalon				Service Pack	20022	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Camry								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor	28360	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack	20032	35	4	EZ-sensor - 315 MHz				EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor				Sensor; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor	28365	35	4	Service Pack				Corolla								Sensor; W/Steel Wheels; W/40 Deg. Angled Valve Sensor	28380	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack								Sensor	20032	35	4	Corolla								Tundra								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; Models made in Japan.; OEM Part No. 4260733011								EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; Models made in USA.; OEM Part No. 4260706011				Sensor; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor								28670	35	4	Service Pack				Service Pack								20022	35	4	Venza								Corolla - Continued								EZ-sensor - 315 MHz								EZ-sensor Service Pack; Almmn. Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor				Sensor; Models made in Japan.; OEM Part No. 4260733011								28365	35	4	Service Pack				Sensor; Models made in USA.; OEM Part No. 4260706011								28370	35	4	Corolla								Service Pack								EZ-sensor - 315 MHz	◇33000	11.5	1.3	2009 - Continued								Corolla - Continued								EZ-sensor Service Pack; Almmn. Valve								EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor				Sensor; Models made in Japan.; OEM Part No. 4260733011				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack				Sensor; Models made in USA.; OEM Part No. 4260706011				Sensor; Models made in USA.; W/15" Wheels								28365	35	4	Corolla								Sensor; Models made in USA.; W/16" Or 17" Wheels								28360	35	4	EZ-sensor - 315 MHz								Service Pack								20032	35	4																																																																																																																																																																																																																																																																																												
EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																									
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; W/Valve Cap	28365	35	4	Sensor; W/O Valve Cap	28370	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack	20032	35	4	Tacoma				Sensor	28670	35	4	Avalon				Service Pack	20022	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Camry								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor	28360	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack	20032	35	4	EZ-sensor - 315 MHz				EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor				Sensor; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor	28365	35	4	Service Pack				Corolla								Sensor; W/Steel Wheels; W/40 Deg. Angled Valve Sensor	28380	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack								Sensor	20032	35	4	Corolla								Tundra								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; Models made in Japan.; OEM Part No. 4260733011								EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; Models made in USA.; OEM Part No. 4260706011				Sensor; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor								28670	35	4	Service Pack				Service Pack								20022	35	4	Venza								Corolla - Continued								EZ-sensor - 315 MHz								EZ-sensor Service Pack; Almmn. Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor				Sensor; Models made in Japan.; OEM Part No. 4260733011								28365	35	4	Service Pack				Sensor; Models made in USA.; OEM Part No. 4260706011								28370	35	4	Corolla								Service Pack								EZ-sensor - 315 MHz	◇33000	11.5	1.3	2009 - Continued								Corolla - Continued								EZ-sensor Service Pack; Almmn. Valve								EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor				Sensor; Models made in Japan.; OEM Part No. 4260733011				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack				Sensor; Models made in USA.; OEM Part No. 4260706011				Sensor; Models made in USA.; W/15" Wheels								28365	35	4	Corolla								Sensor; Models made in USA.; W/16" Or 17" Wheels								28360	35	4	EZ-sensor - 315 MHz								Service Pack								20032	35	4																																																																																																																																																																																																																																																																																																												
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																									
Sensor; W/Valve Cap	28365	35	4	Sensor; W/O Valve Cap	28370	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack	20032	35	4	Tacoma				Sensor	28670	35	4	Avalon				Service Pack	20022	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Camry								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor	28360	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack	20032	35	4	EZ-sensor - 315 MHz				EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor				Sensor; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor	28365	35	4	Service Pack				Corolla								Sensor; W/Steel Wheels; W/40 Deg. Angled Valve Sensor	28380	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack								Sensor	20032	35	4	Corolla								Tundra								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; Models made in Japan.; OEM Part No. 4260733011								EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; Models made in USA.; OEM Part No. 4260706011				Sensor; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor								28670	35	4	Service Pack				Service Pack								20022	35	4	Venza								Corolla - Continued								EZ-sensor - 315 MHz								EZ-sensor Service Pack; Almmn. Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor				Sensor; Models made in Japan.; OEM Part No. 4260733011								28365	35	4	Service Pack				Sensor; Models made in USA.; OEM Part No. 4260706011								28370	35	4	Corolla								Service Pack								EZ-sensor - 315 MHz	◇33000	11.5	1.3	2009 - Continued								Corolla - Continued								EZ-sensor Service Pack; Almmn. Valve								EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor				Sensor; Models made in Japan.; OEM Part No. 4260733011				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack				Sensor; Models made in USA.; OEM Part No. 4260706011				Sensor; Models made in USA.; W/15" Wheels												28365	35	4	Corolla								Sensor; Models made in USA.; W/16" Or 17" Wheels								28360	35	4	EZ-sensor - 315 MHz								Service Pack								20032	35	4																																																																																																																																																																																																																																																																																																																				
Sensor; W/O Valve Cap	28370	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																									
Service Pack	20032	35	4	Tacoma				Sensor	28670	35	4	Avalon				Service Pack	20022	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Camry								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor	28360	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack	20032	35	4	EZ-sensor - 315 MHz				EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor				Sensor; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor	28365	35	4	Service Pack				Corolla								Sensor; W/Steel Wheels; W/40 Deg. Angled Valve Sensor	28380	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack								Sensor	20032	35	4	Corolla								Tundra								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; Models made in Japan.; OEM Part No. 4260733011								EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; Models made in USA.; OEM Part No. 4260706011				Sensor; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor								28670	35	4	Service Pack				Service Pack								20022	35	4	Venza								Corolla - Continued								EZ-sensor - 315 MHz								EZ-sensor Service Pack; Almmn. Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor				Sensor; Models made in Japan.; OEM Part No. 4260733011								28365	35	4	Service Pack				Sensor; Models made in USA.; OEM Part No. 4260706011								28370	35	4	Corolla								Service Pack								EZ-sensor - 315 MHz	◇33000	11.5	1.3	2009 - Continued								Corolla - Continued								EZ-sensor Service Pack; Almmn. Valve								EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor				Sensor; Models made in Japan.; OEM Part No. 4260733011				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack				Sensor; Models made in USA.; OEM Part No. 4260706011				Sensor; Models made in USA.; W/15" Wheels												28365	35	4	Corolla								Sensor; Models made in USA.; W/16" Or 17" Wheels								28360	35	4	EZ-sensor - 315 MHz								Service Pack								20032	35	4																																																																																																																																																																																																																																																																																																																																
Tacoma				Sensor	28670	35	4																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																									
Avalon				Service Pack	20022	35	4																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																									
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Camry																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																												
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor	28360	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack	20032	35	4	EZ-sensor - 315 MHz				EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor				Sensor; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor	28365	35	4	Service Pack				Corolla								Sensor; W/Steel Wheels; W/40 Deg. Angled Valve Sensor	28380	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack								Sensor	20032	35	4	Corolla								Tundra								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; Models made in Japan.; OEM Part No. 4260733011								EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; Models made in USA.; OEM Part No. 4260706011				Sensor; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor								28670	35	4	Service Pack				Service Pack								20022	35	4	Venza								Corolla - Continued								EZ-sensor - 315 MHz								EZ-sensor Service Pack; Almmn. Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor				Sensor; Models made in Japan.; OEM Part No. 4260733011								28365	35	4	Service Pack				Sensor; Models made in USA.; OEM Part No. 4260706011								28370	35	4	Corolla								Service Pack								EZ-sensor - 315 MHz	◇33000	11.5	1.3	2009 - Continued								Corolla - Continued								EZ-sensor Service Pack; Almmn. Valve								EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor				Sensor; Models made in Japan.; OEM Part No. 4260733011				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack				Sensor; Models made in USA.; OEM Part No. 4260706011				Sensor; Models made in USA.; W/15" Wheels								28365	35	4	Corolla								Sensor; Models made in USA.; W/16" Or 17" Wheels								28360	35	4	EZ-sensor - 315 MHz								Service Pack								20032	35	4																																																																																																																																																																																																																																																																																																																																																																				
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor	28360	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack	20032	35	4	EZ-sensor - 315 MHz				EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor				Sensor; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor	28365	35	4	Service Pack				Corolla								Sensor; W/Steel Wheels; W/40 Deg. Angled Valve Sensor	28380	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack								Sensor	20032	35	4	Corolla								Tundra								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; Models made in Japan.; OEM Part No. 4260733011								EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; Models made in USA.; OEM Part No. 4260706011				Sensor; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor								28670	35	4	Service Pack				Service Pack								20022	35	4	Venza								Corolla - Continued								EZ-sensor - 315 MHz								EZ-sensor Service Pack; Almmn. Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor				Sensor; Models made in Japan.; OEM Part No. 4260733011								28365	35	4	Service Pack				Sensor; Models made in USA.; OEM Part No. 4260706011								28370	35	4	Corolla								Service Pack								EZ-sensor - 315 MHz	◇33000	11.5	1.3	2009 - Continued								Corolla - Continued								EZ-sensor Service Pack; Almmn. Valve								EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor				Sensor; Models made in Japan.; OEM Part No. 4260733011				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack				Sensor; Models made in USA.; OEM Part No. 4260706011								Sensor; Models made in USA.; W/15" Wheels								28365	35	4	Corolla								Sensor; Models made in USA.; W/16" Or 17" Wheels								28360	35	4	EZ-sensor - 315 MHz								Service Pack								20032	35	4																																																																																																																																																																																																																																																																																																																																																																				
Sensor	28360	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																									
Service Pack	20032	35	4	EZ-sensor - 315 MHz				EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor				Sensor; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor	28365	35	4	Service Pack				Corolla								Sensor; W/Steel Wheels; W/40 Deg. Angled Valve Sensor	28380	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack								Sensor	20032	35	4	Corolla								Tundra								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; Models made in Japan.; OEM Part No. 4260733011								EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; Models made in USA.; OEM Part No. 4260706011				Sensor; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor								28670	35	4	Service Pack				Service Pack								20022	35	4	Venza								Corolla - Continued								EZ-sensor - 315 MHz								EZ-sensor Service Pack; Almmn. Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor				Sensor; Models made in Japan.; OEM Part No. 4260733011								28365	35	4	Service Pack				Sensor; Models made in USA.; OEM Part No. 4260706011								28370	35	4	Corolla								Service Pack								EZ-sensor - 315 MHz	◇33000	11.5	1.3	2009 - Continued								Corolla - Continued								EZ-sensor Service Pack; Almmn. Valve								EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor				Sensor; Models made in Japan.; OEM Part No. 4260733011				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack				Sensor; Models made in USA.; OEM Part No. 4260706011				Sensor; Models made in USA.; W/15" Wheels												28365	35	4	Corolla								Sensor; Models made in USA.; W/16" Or 17" Wheels								28360	35	4	EZ-sensor - 315 MHz								Service Pack								20032	35	4																																																																																																																																																																																																																																																																																																																																																																																
EZ-sensor - 315 MHz				EZ-sensor Service Pack; Almmn. Valve	34000	62	7																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																									
EZ-sensor Service Pack; Rubber Valve				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																									
Sensor				Sensor; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor	28365	35	4																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																									
Service Pack				Corolla								Sensor; W/Steel Wheels; W/40 Deg. Angled Valve Sensor	28380	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack								Sensor	20032	35	4	Corolla								Tundra								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; Models made in Japan.; OEM Part No. 4260733011								EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; Models made in USA.; OEM Part No. 4260706011				Sensor; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor								28670	35	4	Service Pack				Service Pack								20022	35	4	Venza								Corolla - Continued								EZ-sensor - 315 MHz								EZ-sensor Service Pack; Almmn. Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor				Sensor; Models made in Japan.; OEM Part No. 4260733011								28365	35	4	Service Pack				Sensor; Models made in USA.; OEM Part No. 4260706011								28370	35	4	Corolla								Service Pack								EZ-sensor - 315 MHz	◇33000	11.5	1.3	2009 - Continued								Corolla - Continued								EZ-sensor Service Pack; Almmn. Valve								EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor				Sensor; Models made in Japan.; OEM Part No. 4260733011				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack				Sensor; Models made in USA.; OEM Part No. 4260706011				Sensor; Models made in USA.; W/15" Wheels								28365	35	4	Corolla								Sensor; Models made in USA.; W/16" Or 17" Wheels								28360	35	4	EZ-sensor - 315 MHz								Service Pack								20032	35	4																																																																																																																																																																																																																																																																																																																																																																																																																
Corolla								Sensor; W/Steel Wheels; W/40 Deg. Angled Valve Sensor	28380	35	4																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																					
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack								Sensor	20032	35	4	Corolla								Tundra								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; Models made in Japan.; OEM Part No. 4260733011								EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; Models made in USA.; OEM Part No. 4260706011				Sensor; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor								28670	35	4	Service Pack				Service Pack								20022	35	4	Venza								Corolla - Continued								EZ-sensor - 315 MHz								EZ-sensor Service Pack; Almmn. Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor				Sensor; Models made in Japan.; OEM Part No. 4260733011								28365	35	4	Service Pack				Sensor; Models made in USA.; OEM Part No. 4260706011								28370	35	4	Corolla								Service Pack								EZ-sensor - 315 MHz	◇33000	11.5	1.3	2009 - Continued								Corolla - Continued								EZ-sensor Service Pack; Almmn. Valve								EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor				Sensor; Models made in Japan.; OEM Part No. 4260733011				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack				Sensor; Models made in USA.; OEM Part No. 4260706011				Sensor; Models made in USA.; W/15" Wheels								28365	35	4	Corolla								Sensor; Models made in USA.; W/16" Or 17" Wheels								28360	35	4	EZ-sensor - 315 MHz								Service Pack								20032	35	4																																																																																																																																																																																																																																																																																																																																																																																																																																
Service Pack								Sensor	20032	35	4																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																					
Corolla								Tundra																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																								
EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve								EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; Models made in Japan.; OEM Part No. 4260733011								EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; Models made in USA.; OEM Part No. 4260706011				Sensor; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor								28670	35	4	Service Pack				Service Pack								20022	35	4	Venza								Corolla - Continued								EZ-sensor - 315 MHz								EZ-sensor Service Pack; Almmn. Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor				Sensor; Models made in Japan.; OEM Part No. 4260733011								28365	35	4	Service Pack				Sensor; Models made in USA.; OEM Part No. 4260706011								28370	35	4	Corolla								Service Pack								EZ-sensor - 315 MHz	◇33000	11.5	1.3	2009 - Continued								Corolla - Continued								EZ-sensor Service Pack; Almmn. Valve								EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor				Sensor; Models made in Japan.; OEM Part No. 4260733011				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack				Sensor; Models made in USA.; OEM Part No. 4260706011				Sensor; Models made in USA.; W/15" Wheels								28365	35	4	Corolla								Sensor; Models made in USA.; W/16" Or 17" Wheels								28360	35	4	EZ-sensor - 315 MHz								Service Pack								20032	35	4																																																																																																																																																																																																																																																																																																																																																																																																																																																																
EZ-sensor Service Pack; Almmn. Valve								EZ-sensor - 315 MHz	◇33000	11.5	1.3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																					
EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																					
Sensor; Models made in Japan.; OEM Part No. 4260733011								EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																					
Sensor; Models made in USA.; OEM Part No. 4260706011				Sensor; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor								28670	35	4																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																		
Service Pack				Service Pack								20022	35	4																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																		
Venza								Corolla - Continued																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																								
EZ-sensor - 315 MHz								EZ-sensor Service Pack; Almmn. Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor				Sensor; Models made in Japan.; OEM Part No. 4260733011								28365	35	4	Service Pack				Sensor; Models made in USA.; OEM Part No. 4260706011								28370	35	4	Corolla								Service Pack								EZ-sensor - 315 MHz	◇33000	11.5	1.3	2009 - Continued								Corolla - Continued								EZ-sensor Service Pack; Almmn. Valve								EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor				Sensor; Models made in Japan.; OEM Part No. 4260733011				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack				Sensor; Models made in USA.; OEM Part No. 4260706011				Sensor; Models made in USA.; W/15" Wheels								28365	35	4	Corolla								Sensor; Models made in USA.; W/16" Or 17" Wheels								28360	35	4	EZ-sensor - 315 MHz								Service Pack								20032	35	4																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																						
EZ-sensor Service Pack; Almmn. Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																					
EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																					
Sensor				Sensor; Models made in Japan.; OEM Part No. 4260733011								28365	35	4																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																		
Service Pack				Sensor; Models made in USA.; OEM Part No. 4260706011								28370	35	4																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																		
Corolla								Service Pack																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																								
EZ-sensor - 315 MHz	◇33000	11.5	1.3	2009 - Continued								Corolla - Continued																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																				
EZ-sensor Service Pack; Almmn. Valve								EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor				Sensor; Models made in Japan.; OEM Part No. 4260733011				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack				Sensor; Models made in USA.; OEM Part No. 4260706011				Sensor; Models made in USA.; W/15" Wheels								28365	35	4	Corolla								Sensor; Models made in USA.; W/16" Or 17" Wheels								28360	35	4	EZ-sensor - 315 MHz								Service Pack								20032	35	4																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																								
EZ-sensor Service Pack; Rubber Valve								EZ-sensor Service Pack; Almmn. Valve	34000	62	7																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																					
Sensor				Sensor; Models made in Japan.; OEM Part No. 4260733011				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																					
Service Pack				Sensor; Models made in USA.; OEM Part No. 4260706011				Sensor; Models made in USA.; W/15" Wheels								28365	35	4																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																														
Corolla								Sensor; Models made in USA.; W/16" Or 17" Wheels								28360	35	4																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																														
EZ-sensor - 315 MHz								Service Pack								20032	35	4																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																														

◊ Programming Tool Required.



PRINTED ON RECYCLED PAPER
WITH 100% POSTCONSUMER WASTE

Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.													
Toyota - Continued																				
2009 - Continued																				
Venza - Continued																				
Service Pack	20032	35	4	Toyota - Continued																
Yaris				2008 - Continued																
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sequoia; Sienna - Continued																
EZ-sensor Service Pack; Almnm. Valve	34000	62	7	Sensor	28670	35	4	2008 - Continued												
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack	20022	35	4	Sequoia; Sienna - Continued												
Sensor	28365	35	4	Solara				2008 - Continued												
Service Pack	20032	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor	28670	35	4	Sequoia; Sienna - Continued								
2008				EZ-sensor Service Pack; Almnm. Valve	34000	62	7	Service Pack	20022	35	4	2008 - Continued								
4 Runner				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Tacoma				2008 - Continued								
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor; W/Alloy Wheels; W/20 Deg.	28360	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3	2008 - Continued								
EZ-sensor Service Pack; Almnm. Valve	34000	62	7	Angled Valve Sensor	28360	35	4	EZ-sensor Service Pack; Almnm. Valve	34000	62	7	2008 - Continued								
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; W/Steel Wheels; W/40 Deg.	28380	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	2008 - Continued								
Sensor; W/Valve Cap; OEM Part No.	4260733011	28365	35	4	Angled Valve Sensor	28360	35	4	Sensor; W/Alloy Wheels; W/20 Deg.	28360	35	4	2008 - Continued							
Sensor; W/O Valve Cap; OEM Part No.	4260733021	28370	35	4	Service Pack	20032	35	4	Angled Valve Sensor	28360	35	4	2008 - Continued							
Service Pack	20032	35	4	Avalon				2008 - Continued												
Avalon				EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3	2008 - Continued								
EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almnm. Valve	34000	62	7	EZ-sensor Service Pack; Almnm. Valve	34000	62	7	2008 - Continued								
EZ-sensor Service Pack; Almnm. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	2008 - Continued								
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor; W/Alloy Wheels; W/20 Deg.	28670	35	4	Sensor; W/Alloy Wheels; W/20 Deg.	28670	35	4	2008 - Continued								
Sensor	28360	35	4	Angled Valve Sensor	28670	35	4	Angled Valve Sensor	28670	35	4	2008 - Continued								
Service Pack	20032	35	4	Camry; Corolla				2008 - Continued												
Camry; Corolla				EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3	2008 - Continued								
EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Almnm. Valve	34000	62	7	EZ-sensor Service Pack; Almnm. Valve	34000	62	7	2008 - Continued								
EZ-sensor Service Pack; Almnm. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	2008 - Continued								
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor	28365	35	4	Sensor	28365	35	4	2008 - Continued								
Sensor; Models made in Japan.; OEM Part No. 4260733011	28365	35	4	Service Pack	20032	35	4	Service Pack	20032	35	4	2008 - Continued								
Sensor; Models made in USA.; OEM Part No. 4260706011	28360	35	4	FJ Cruiser; Highlander; Land Cruiser				2008 - Continued												
Service Pack	20032	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3	2008 - Continued								
Matrix				EZ-sensor Service Pack; Almnm. Valve	34000	62	7	EZ-sensor Service Pack; Almnm. Valve	34000	62	7	2008 - Continued								
EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	2008 - Continued								
EZ-sensor Service Pack; Almnm. Valve	34000	62	7	Sensor	28365	35	4	Sensor	28365	35	4	2008 - Continued								
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack	20032	35	4	Service Pack	20032	35	4	2008 - Continued								
Sensor	28365	35	4	Avalon				2008 - Continued												
Sensor; Models made in Japan.; OEM Part No. 4260733011	28365	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3	2008 - Continued								
Sensor; Models made in USA.; OEM Part No. 4260706011	28360	35	4	EZ-sensor Service Pack; Almnm. Valve	34000	62	7	EZ-sensor Service Pack; Almnm. Valve	34000	62	7	2008 - Continued								
Service Pack	20032	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	2008 - Continued								
Prius				Sensor	28365	35	4	Sensor	28365	35	4	2008 - Continued								
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack	20032	35	4	Service Pack	20032	35	4	2008 - Continued								
EZ-sensor Service Pack; Almnm. Valve	34000	62	7	Corolla				2008 - Continued												
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3	2008 - Continued								
Sensor	28365	35	4	EZ-sensor Service Pack; Almnm. Valve	34000	62	7	EZ-sensor Service Pack; Almnm. Valve	34000	62	7	2008 - Continued								
Service Pack	20032	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	2008 - Continued								
RAV4				Sensor	28365	35	4	Sensor	28365	35	4	2008 - Continued								
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack	20032	35	4	Service Pack	20032	35	4	2008 - Continued								
EZ-sensor Service Pack; Almnm. Valve	34000	62	7	Sequoia; Sienna				2008 - Continued												
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3	2008 - Continued								
Sensor	28370	35	4	EZ-sensor Service Pack; Almnm. Valve	34000	62	7	EZ-sensor Service Pack; Almnm. Valve	34000	62	7	2008 - Continued								
Service Pack	20032	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	2008 - Continued								
Sequoia; Sienna				Sensor	28365	35	4	Sensor	28365	35	4	2008 - Continued								
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack	20032	35	4	Service Pack	20032	35	4	2008 - Continued								
EZ-sensor Service Pack; Almnm. Valve	34000	62	7	Camry				2008 - Continued												
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3	2008 - Continued								
Sensor	28365	35	4	EZ-sensor Service Pack; Almnm. Valve	34000	62	7	EZ-sensor Service Pack; Almnm. Valve	34000	62	7	2008 - Continued								
Service Pack	20032	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	2008 - Continued								
Corolla				Sensor	28365	35	4	Sensor	28365	35	4	2008 - Continued								
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack	20032	35	4	Service Pack	20032	35	4	2008 - Continued								
EZ-sensor Service Pack; Almnm. Valve	34000	62	7	RAV4				2008 - Continued												
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3	2008 - Continued								
Sensor	28370	35	4	EZ-sensor Service Pack; Almnm. Valve	34000	62	7	EZ-sensor Service Pack; Almnm. Valve	34000	62	7	2008 - Continued								
Service Pack	20032	35</																		

Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
Toyota - Continued				Toyota - Continued			
2007 - Continued				2007 - Continued			
Highlander				Tundra			
EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Almmn. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor; May & Newer	28365	35	4	Sensor; W/Aloy Wheels; W/20 Deg. Angled Valve Sensor	28670	35	4
Service Pack; May & Newer	20032	35	4	Service Pack	20022	35	4
Land Cruiser				Yaris			
EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor Service Pack; Almmn. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor	28365	35	4	Sensor; Aug. & Newer	28365	35	4
Service Pack	20032	35	4	Service Pack; Aug. & Newer	20032	35	4
Matrix				2006			
EZ-sensor - 315 MHz	◇33000	11.5	1.3	4 Runner			
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	EZ-sensor - 315 MHz	◇33000	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Almmn. Valve	34000	62	7
Sensor; Models made in Japan.; OEM Part No. 4260733011; Jun. & Newer .	28365	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor; Models made in USA.; OEM Part				Sensor; OEM Part No. 4260733011	28365	35	4
No. 4260706011; Jun. & Newer	28360	35	4	Sensor; OEM Part No. 4260733021	28370	35	4
Service Pack; Jun. & Newer	20032	35	4	Sensor; OEM Part No. 4260730030	28335	35	4
Prius				Sensor; OEM Part No. 4260735010	28345	35	4
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack; Jun. & Newer	20032	35	4
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Service Pack; May & Older	20031	35	4
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Avalon			
Sensor	28365	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3
Service Pack	20032	35	4	EZ-sensor Service Pack; Almmn. Valve	34000	62	7
RAV4				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor; Aug. & Newer	28360	35	4
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Service Pack; Aug. & Newer	20032	35	4
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Land Cruiser			
Sensor	28370	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3
Service Pack	20032	35	4	EZ-sensor Service Pack; Almmn. Valve	34000	62	7
Sequoia				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor	28365	35	4
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Service Pack; Apr. 1 & Newer	20032	35	4
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack; Mar. & Older	20031	35	4
Sensor; W/Aloy Wheels	28305	35	4	Prius; RAV4			
Sensor; W/Steel Wheels; W/20 Deg. Angled Valve Sensor	28305	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3
Sensor; W/Steel Wheels; W/40 Deg. Angled Valve Sensor	28300	35	4	EZ-sensor Service Pack; Almmn. Valve	34000	62	7
Service Pack	20031	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sienna				Sensor	28365	35	4
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack	20032	35	4
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sequoia			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor - 315 MHz	◇33000	11.5	1.3
Sensor	28670	35	4	EZ-sensor Service Pack; Almmn. Valve	34000	62	7
Service Pack	20022	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Solara				Sensor; W/Aloy Wheels	28305	35	4
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor; W/Steel Wheels; W/20 Deg. Angled Valve Sensor	28305	35	4
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; W/Steel Wheels; W/40 Deg. Angled Valve Sensor	28300	35	4
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack	20031	35	4
Sensor	28360	35	4	Solara			
Service Pack	20032	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3
Tacoma				EZ-sensor Service Pack; Almmn. Valve	34000	62	7
EZ-sensor - 315 MHz	◇33000	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Almmn. Valve	34000	62	7	Sensor; May & Newer	28360	35	4
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack; May & Newer	20032	35	4
Sensor; W/Aloy Wheels; W/20 Deg. Angled Valve Sensor	28360	35	4	Tacoma			
Sensor; W/Steel Wheels; W/40 Deg. Angled Valve Sensor	28380	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3
Service Pack	20032	35	4	EZ-sensor Service Pack; Almmn. Valve	34000	62	7

◊ Programming Tool Required.



PRINTED ON RECYCLED PAPER
WITH 100% POSTCONSUMER WASTE

Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.																																																																																																																																																																																																																																																																																																																																																																																																												
Toyota - Continued																																																																																																																																																																																																																																																																																																																																																																																																																			
2006 - Continued																																																																																																																																																																																																																																																																																																																																																																																																																			
Tacoma - Continued																																																																																																																																																																																																																																																																																																																																																																																																																			
Sensor; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor; Jul. & Older ...	28355	35	4	4 Runner																																																																																																																																																																																																																																																																																																																																																																																																															
Sensor; W/Steel Wheels; W/40 Deg. Angled Valve Sensor	28380	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3																																																																																																																																																																																																																																																																																																																																																																																																												
Service Pack; Aug. & Newer	20032	35	4	EZ-sensor Service Pack; Almm. Valve	34000	62	7																																																																																																																																																																																																																																																																																																																																																																																																												
Service Pack; Jul. & Older	20031	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3																																																																																																																																																																																																																																																																																																																																																																																																												
Tundra				Sensor	28345	35	4																																																																																																																																																																																																																																																																																																																																																																																																												
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack	20031	35	4																																																																																																																																																																																																																																																																																																																																																																																																												
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Volkswagen																																																																																																																																																																																																																																																																																																																																																																																																															
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	2012								Sensor; W/20 Deg. Angled Valve Sensor; Nov. 1 & Newer	28670	35	4	CC; Eos				Sensor; W/20 Deg. Angled Valve Sensor; Oct. 31 & Older	28305	35	4	Sensor	20088	71	8	Sensor; W/40 Deg. Angled Valve Sensor; Oct. 31 & Older	28300	35	4	Service Pack	20017	71	8	Service Pack; Nov. 1 & Newer	20022	35	4	2011								Service Pack; Oct. 31 & Older	20031	35	4	CC; Eos; Tiguan				2005				Sensor	20088	71	8	4 Runner				Service Pack	20017	71	8	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Touareg 2								EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor; W/315 MHz Sensor; Includes Transmitter Only	20077	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack; Does Not Include Valve; W/315 MHz Sensor	20023	35	4	Sensor	28345	35	4	Service Pack; W/43mm Silver Insert; W/315 MHz Sensor	20037	35	4	Service Pack	20031	35	4	Service Pack; W/48mm Green Insert; W/315 MHz Sensor	20038	35	4	Land Cruiser				Service Pack; W/49mm Black Insert; W/315 MHz Sensor	20039	35	4	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack; W/51mm Orange Insert; W/315 MHz Sensor	20040	35	4	EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor; W/433 MHz Sensor; Includes Transmitter Only	20103	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	2010								Sensor; May & Newer	28365	35	4	Beetle; CC; Eos; Golf; GTI; Jetta; Passat; Tiguan				Service Pack; May & Newer	20031	35	4	Sensor	20088	71	8	Sequoia				Service Pack	20017	71	8	EZ-sensor - 315 MHz	◇33000	11.5	1.3	Touareg 2								EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor; Includes Transmitter Only	20103	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack; Does Not Include Valve .	20023	35	4	Sensor; W/Alloy Wheels	28305	35	4	Service Pack; W/43mm Silver Insert	20037	35	4	Sensor; W/Steel Wheels; W/20 Deg. Angled Valve Sensor	28305	35	4	Service Pack; W/48mm Green Insert ...	20038	35	4	Sensor; W/Steel Wheels; W/40 Deg. Angled Valve Sensor	28300	35	4	Service Pack; W/49mm Black Insert	20039	35	4	Service Pack	20031	35	4	Service Pack; W/51mm Orange Insert ..	20040	35	4	Tacoma				2009								EZ-sensor - 315 MHz	◇33000	11.5	1.3	Beetle; CC; Eos				EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor	20088	71	8	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack	20017	71	8	Sensor; W/20 Deg. Angled Valve Sensor; Dec. 1 & Newer	28355	35	4	GLI								Sensor; W/20 Deg. Angled Valve Sensor; Nov. 30 & Older	28305	35	4	Service Pack	20017	71	8	Sensor; W/40 Deg. Angled Valve Sensor; Dec. 1 & Newer	28380	35	4	Golf; GTI; Jetta; Passat; Rabbit; Tiguan								Sensor; W/40 Deg. Angled Valve Sensor; Nov. 30 & Older	28300	35	4	Sensor	20088	71	8	Service Pack	20031	35	4	Service Pack	20017	71	8	Tundra				Touareg 2								EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor; Includes Transmitter Only	20078	35	4	EZ-sensor Service Pack; Almm. Valve	34000	62	7	Service Pack; Does Not Include Valve .	20023	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack; W/43mm Silver Insert	20037	35	4	Sensor; W/20 Deg. Angled Valve Sensor	28305	35	4	Service Pack; W/48mm Green Insert ...	20038	35	4	Sensor; W/40 Deg. Angled Valve Sensor	28300	35	4	Service Pack; W/49mm Black Insert	20039	35	4	Service Pack	20031	35	4	Service Pack; W/51mm Orange Insert ..	20040	35	4	2008								Beetle; Eos								Sensor	20088	71	8	Service Pack	20017	71	8
2012																																																																																																																																																																																																																																																																																																																																																																																																																			
Sensor; W/20 Deg. Angled Valve Sensor; Nov. 1 & Newer	28670	35	4	CC; Eos																																																																																																																																																																																																																																																																																																																																																																																																															
Sensor; W/20 Deg. Angled Valve Sensor; Oct. 31 & Older	28305	35	4	Sensor	20088	71	8																																																																																																																																																																																																																																																																																																																																																																																																												
Sensor; W/40 Deg. Angled Valve Sensor; Oct. 31 & Older	28300	35	4	Service Pack	20017	71	8																																																																																																																																																																																																																																																																																																																																																																																																												
Service Pack; Nov. 1 & Newer	20022	35	4	2011																																																																																																																																																																																																																																																																																																																																																																																																															
Service Pack; Oct. 31 & Older	20031	35	4	CC; Eos; Tiguan																																																																																																																																																																																																																																																																																																																																																																																																															
2005				Sensor	20088	71	8																																																																																																																																																																																																																																																																																																																																																																																																												
4 Runner				Service Pack	20017	71	8																																																																																																																																																																																																																																																																																																																																																																																																												
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Touareg 2																																																																																																																																																																																																																																																																																																																																																																																																															
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor; W/315 MHz Sensor; Includes Transmitter Only	20077	35	4																																																																																																																																																																																																																																																																																																																																																																																																												
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack; Does Not Include Valve; W/315 MHz Sensor	20023	35	4																																																																																																																																																																																																																																																																																																																																																																																																												
Sensor	28345	35	4	Service Pack; W/43mm Silver Insert; W/315 MHz Sensor	20037	35	4																																																																																																																																																																																																																																																																																																																																																																																																												
Service Pack	20031	35	4	Service Pack; W/48mm Green Insert; W/315 MHz Sensor	20038	35	4																																																																																																																																																																																																																																																																																																																																																																																																												
Land Cruiser				Service Pack; W/49mm Black Insert; W/315 MHz Sensor	20039	35	4																																																																																																																																																																																																																																																																																																																																																																																																												
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Service Pack; W/51mm Orange Insert; W/315 MHz Sensor	20040	35	4																																																																																																																																																																																																																																																																																																																																																																																																												
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor; W/433 MHz Sensor; Includes Transmitter Only	20103	35	4																																																																																																																																																																																																																																																																																																																																																																																																												
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	2010																																																																																																																																																																																																																																																																																																																																																																																																															
Sensor; May & Newer	28365	35	4	Beetle; CC; Eos; Golf; GTI; Jetta; Passat; Tiguan																																																																																																																																																																																																																																																																																																																																																																																																															
Service Pack; May & Newer	20031	35	4	Sensor	20088	71	8																																																																																																																																																																																																																																																																																																																																																																																																												
Sequoia				Service Pack	20017	71	8																																																																																																																																																																																																																																																																																																																																																																																																												
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Touareg 2																																																																																																																																																																																																																																																																																																																																																																																																															
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor; Includes Transmitter Only	20103	35	4																																																																																																																																																																																																																																																																																																																																																																																																												
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack; Does Not Include Valve .	20023	35	4																																																																																																																																																																																																																																																																																																																																																																																																												
Sensor; W/Alloy Wheels	28305	35	4	Service Pack; W/43mm Silver Insert	20037	35	4																																																																																																																																																																																																																																																																																																																																																																																																												
Sensor; W/Steel Wheels; W/20 Deg. Angled Valve Sensor	28305	35	4	Service Pack; W/48mm Green Insert ...	20038	35	4																																																																																																																																																																																																																																																																																																																																																																																																												
Sensor; W/Steel Wheels; W/40 Deg. Angled Valve Sensor	28300	35	4	Service Pack; W/49mm Black Insert	20039	35	4																																																																																																																																																																																																																																																																																																																																																																																																												
Service Pack	20031	35	4	Service Pack; W/51mm Orange Insert ..	20040	35	4																																																																																																																																																																																																																																																																																																																																																																																																												
Tacoma				2009																																																																																																																																																																																																																																																																																																																																																																																																															
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Beetle; CC; Eos																																																																																																																																																																																																																																																																																																																																																																																																															
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Sensor	20088	71	8																																																																																																																																																																																																																																																																																																																																																																																																												
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack	20017	71	8																																																																																																																																																																																																																																																																																																																																																																																																												
Sensor; W/20 Deg. Angled Valve Sensor; Dec. 1 & Newer	28355	35	4	GLI																																																																																																																																																																																																																																																																																																																																																																																																															
Sensor; W/20 Deg. Angled Valve Sensor; Nov. 30 & Older	28305	35	4	Service Pack	20017	71	8																																																																																																																																																																																																																																																																																																																																																																																																												
Sensor; W/40 Deg. Angled Valve Sensor; Dec. 1 & Newer	28380	35	4	Golf; GTI; Jetta; Passat; Rabbit; Tiguan																																																																																																																																																																																																																																																																																																																																																																																																															
Sensor; W/40 Deg. Angled Valve Sensor; Nov. 30 & Older	28300	35	4	Sensor	20088	71	8																																																																																																																																																																																																																																																																																																																																																																																																												
Service Pack	20031	35	4	Service Pack	20017	71	8																																																																																																																																																																																																																																																																																																																																																																																																												
Tundra				Touareg 2																																																																																																																																																																																																																																																																																																																																																																																																															
EZ-sensor - 315 MHz	◇33000	11.5	1.3	Sensor; Includes Transmitter Only	20078	35	4																																																																																																																																																																																																																																																																																																																																																																																																												
EZ-sensor Service Pack; Almm. Valve	34000	62	7	Service Pack; Does Not Include Valve .	20023	35	4																																																																																																																																																																																																																																																																																																																																																																																																												
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Service Pack; W/43mm Silver Insert	20037	35	4																																																																																																																																																																																																																																																																																																																																																																																																												
Sensor; W/20 Deg. Angled Valve Sensor	28305	35	4	Service Pack; W/48mm Green Insert ...	20038	35	4																																																																																																																																																																																																																																																																																																																																																																																																												
Sensor; W/40 Deg. Angled Valve Sensor	28300	35	4	Service Pack; W/49mm Black Insert	20039	35	4																																																																																																																																																																																																																																																																																																																																																																																																												
Service Pack	20031	35	4	Service Pack; W/51mm Orange Insert ..	20040	35	4																																																																																																																																																																																																																																																																																																																																																																																																												
2008																																																																																																																																																																																																																																																																																																																																																																																																																			
Beetle; Eos																																																																																																																																																																																																																																																																																																																																																																																																																			
Sensor	20088	71	8																																																																																																																																																																																																																																																																																																																																																																																																																
Service Pack	20017	71	8																																																																																																																																																																																																																																																																																																																																																																																																																

◊ Programming Tool Required.



Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.				
Volkswagen - Continued											
2008 - Continued											
GLI											
Service Pack	20017	71	8	Phaeton - Continued							
Golf; GTI; Jetta											
Sensor	20088	71	8	Service Pack; W/49mm Black Insert; W/315 MHz Sensor	20039	35	4				
Service Pack	20017	71	8	Service Pack; W/51mm Orange Insert; W/315 MHz Sensor	20040	35	4				
Passat											
Sensor; W/16" Or 17" Wheels	20088	71	8	Rabbit							
Service Pack; W/16" Or 17" Wheels	20017	71	8	Sensor; W/15" Wheels	20088	71	8				
R32; Rabbit				Service Pack; W/15" Wheels	20017	71	8				
Sensor	20088	71	8	Touareg							
Service Pack	20017	71	8	Service Pack; Does Not Include Valve ..	20023	62	7				
Touareg 2				Service Pack; W/43mm Silver Insert	20037	62	7				
Sensor; Includes Transmitter Only	20078	35	4	Service Pack; W/48mm Green Insert ...	20038	62	7				
Service Pack; Does Not Include Valve .	20023	35	4	Service Pack; W/49mm Black Insert	20039	62	7				
Service Pack; W/43mm Silver Insert	20037	35	4	Service Pack; W/51mm Orange Insert ..	20040	62	7				
Service Pack; W/48mm Green Insert ...	20038	35	4	2005-2004							
Service Pack; W/49mm Black Insert	20039	35	4								
Service Pack; W/51mm Orange Insert .	20040	35	4	Phaeton							
2007											
Eos											
Sensor	20088	71	8	Sensor; Includes Transmitter Only; W/315 MHz Sensor	20077	35	4				
Service Pack	20017	71	8	Sensor; Includes Transmitter Only; W/433 MHz Sensor	20078	35	4				
GTI				Service Pack; Does Not Include Valve; W/315 MHz Sensor	20023	35	4				
Sensor; W/16" Or 17" Wheels	20088	71	8	Service Pack; W/43mm Silver Insert; W/315 MHz Sensor	20037	35	4				
Service Pack; W/16" Or 17" Wheels	20017	71	8	Service Pack; W/48mm Green Insert; W/315 MHz Sensor	20038	35	4				
Jetta				Service Pack; W/49mm Black Insert; W/315 MHz Sensor	20039	35	4				
Sensor	20088	71	8	Service Pack; W/51mm Orange Insert; W/315 MHz Sensor	20040	35	4				
Service Pack	20017	71	8	Touareg							
Passat											
Sensor; W/16" Or 17" Wheels	20088	71	8	Service Pack; Does Not Include Valve ..	20023	62	7				
Service Pack; W/16" Or 17" Wheels	20017	71	8	Service Pack; W/43mm Silver Insert	20037	62	7				
Rabbit				Service Pack; W/48mm Green Insert ...	20038	62	7				
Sensor; W/15" Wheels	20088	71	8	Service Pack; W/49mm Black Insert	20039	62	7				
Service Pack; W/15" Wheels	20017	71	8	Service Pack; W/51mm Orange Insert ..	20040	62	7				
Touareg				Volvo							
Service Pack; Does Not Include Valve ..	20023	62	7	2012							
Service Pack; W/43mm Silver Insert	20037	62	7	C70; S60							
Service Pack; W/48mm Green Insert ...	20038	62	7	Sensor	20097	71	8				
Service Pack; W/49mm Black Insert	20039	62	7	Service Pack	20030	71	8				
Service Pack; W/51mm Orange Insert ..	20040	62	7	2011							
2006											
Golf				C30; C70; S40; S60; S80; V50; XC60; XC70; XC90							
Service Pack; GTI	20017	71	8	Sensor	20097	71	8				
GTI				Service Pack	20030	71	8				
Sensor; W/16" Or 17" Wheels	20088	71	8	2010							
Service Pack; W/16" Or 17" Wheels	20017	71	8	C30; C70; S40; S80; V50; V70; XC60; XC70; XC90							
Jetta				Sensor	20097	71	8				
Sensor	20088	71	8	Service Pack	20030	71	8				
Service Pack	20017	71	8	2009							
Passat				C30; C70; S40							
Sensor; W/16" Or 17" Wheels	20088	71	8	Sensor	20097	71	8				
Service Pack; W/16" Or 17" Wheels	20017	71	8	Service Pack	20030	71	8				
Phaeton				S60							
Sensor; Includes Transmitter Only; W/315 MHz Sensor	20077	35	4	Sensor	20156	44	5				
Sensor; Includes Transmitter Only; W/433 MHz Sensor	20078	35	4	Service Pack	20010	44	5				
Service Pack; Does Not Include Valve; W/315 MHz Sensor	20023	35	4	S80; V50; V70; XC70							
Service Pack; W/43mm Silver Insert; W/315 MHz Sensor	20037	35	4	Sensor	20097	71	8				
Service Pack; W/48mm Green Insert; W/315 MHz Sensor	20038	35	4	Service Pack	20030	71	8				



Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.
Volvo - Continued			
2008			
C30; C70; S40			
Sensor	20097	71	8
Service Pack	20030	71	8
S60			
Sensor	20156	44	5
Service Pack	20010	44	5
S80; V50; V70; XC70; XC90			
Sensor	20097	71	8
Service Pack	20030	71	8
2007			
C30			
Sensor	20097	71	8
Service Pack	20030	71	8
S60			
Sensor	20156	44	5
Service Pack	20010	44	5
S80			
Sensor	20097	71	8
Service Pack	20030	71	8
V70; XC70; XC90			
Sensor; W/315 MHz Sensor	20156	44	5
Service Pack; W/315 MHz Sensor	20010	44	5
2006			
S60; S80			
Sensor	20156	44	5
Service Pack	20010	44	5
V70; XC70; XC90			
Sensor; W/315 MHz Sensor	20156	44	5
Service Pack; W/315 MHz Sensor	20010	44	5
2005			
S60			
Sensor; W/315 MHz Sensor	20156	44	5
Service Pack; W/315 MHz Sensor	20010	44	5
S80			
Sensor	20156	44	5
Service Pack	20010	44	5
V70; XC70; XC90			
Sensor; W/315 MHz Sensor	20156	44	5
Service Pack; W/315 MHz Sensor	20010	44	5
2004			
S60			
Sensor; W/315 MHz Sensor	20156	44	5
Service Pack; W/315 MHz Sensor	20010	44	5
S80			
Sensor	20156	44	5
Service Pack	20010	44	5
V70; XC70			
Sensor; W/315 MHz Sensor	20156	44	5
Service Pack; W/315 MHz Sensor	20010	44	5
XC90			
Sensor	20156	44	5
Service Pack	20010	44	5



Manufacturers' Part Numbers

OEM Sensor No.	Schrader Sensor No.	OEM Sensor No.	Schrader Sensor No.	OEM Sensor No.	Schrader Sensor No.
C2C25519	20090	C2C40725	20091	15136883	20115
C2C40476	20090	C2S40710	20091	15254101	20153
C2C40725	20091	C2Z15016	20091	15268606	20158
C2S40710	20091	C2Z15017	20090	15825475	20158
C2Z15016	20091	GN3A37140B	20093	15921013	20158
C2Z15017	20090	GS1D37140	20093	15922396	20153
GN3A37140B	20093	LR010532	20091	1688333266	20153
GS1D37140	20093	LR010533	20090	1K0907253D	20088
LR010532	20091	LR018860	20090	19155710	20158
LR010533	20090	LR018861	20091	20922900	28206
LR018860	20090	LR021936	20090	224549	20077
LR018861	20091	LR0500461	20090	224551	20084
LR021936	20090	MN103033	20028	24437708	28078
LR0500461	20090	MN103081	20034	25731358	20117
MN103033	20028	RQH500461	20090	25758220	20076
MN103081	20034	RQH500471	20091	25773946	20117
RQH500461	20090	XR855949	20091	25774006	20116
RQH500471	20091	XR855950	20090	25799331	20153
XR855949	20091	YBD000060	28082	25858636	20153
XR855950	20090	YBD000061	28082	25920615	20153
YBD000060	28082	ZZC137140	28385	25952370	20153
YBD000061	28082	ZZDA37140	20315	28103AG00A	20081
ZZC137140	28385	0009054100	28214	28103AG01A	28203
ZZDA37140	20315	0025406817	20094	28103AG01B	28203
0009054100	28214	0025406917	20095	28103AG01C	28203
0025406817	20094	0025407917	20094	28103SA001	28203
0025406917	20095	0025408017	20095	307489910	20156
0025407917	20094	25409017	28214	312009230	20156
0025408017	20095	0025408617	28214	312802970	20097
25409017	28214	0045421518	28214	313020960	20097
0025408617	28214	06421S3VA01	28214	36106790054	28081
0045421518	28214	06421S3VA02	28981	36118378682	20080
06421S3VA01	28214	06421S3VA03	28981	36236779490	20083
06421S3VA02	28981	06421S3VA04	28981	36146752128	28082
06421S3VA03	28981	06421S9VA01	28982	36236781847	20083
06421S3VA04	28981	06421S9VA03	28982	40700-1AA0B	28204
06421S9VA01	28982	10394110	20158	407001AA0C	28204
06421S9VA03	28982	10438853	28006	40700-CD001	20064
10394110	20158	12768826	28206	40700-CK001	20161
10438853	28006	13172567	28078	40700-CK002	20069
12768826	28206	13227143	20159	40700-JA00C	28204
C2C25519	20090	15114379	20107	40700-JA00B	28204
C2C40476	20090	15122618	20131	40700-JA01A	28167



Manufacturers' Part Numbers

OEM Sensor No.	Schrader Sensor No.	OEM Sensor No.	Schrader Sensor No.	OEM Sensor No.	Schrader Sensor No.
40700-JA01B	28204	42753STKA04	20098	56029319AA	28154 / 28461
40700-JA01C	28204	42753SWA306	20099	56029319AB	28154 / 28461
40700-JA02B	28204	42753SWA316	20099	56029359AA	28155 / 28434
40700-JK00B	28210	42753TK4A01	20720	56029359AB	28155 / 28434
40700-JK00A	28210	42753TL2A51	20098	56029398AA	20398
40700-JK00C	28210	42753TL2A52	20098	56029398AB	20398
4250A030	28129	42753TP6A82	20100	56029400AB	28291
4250A225	28096	4313054J20	20087	56029400AC	28291
4250B668	20398	4313054J21	20087	56029400AD	28291
4250B875	28129	4313078J00	20158	56029465AB	20066 / 28308
4250B877	20034	4313078J10	20158	56029465AC	20066 / 28308
4260702010	28365	4313085Z00	20153	56029479AA	20066 / 28308
4260704010	28380	4313085Z01	20153	56029479AB	28308
4260706011	28360	4313085Z03	20153	56029481AB	28434
4260708010	28670	4313086Z20	20082	56053030AB	20066 / 28308
426070C010	28300	4321182Z10	28204	56053036AA	20066 / 28308
426070C020	28305	4815132	28004	56053036AA	20066 / 28308
426070C030	28670	4815132AB	28004	5L1Z 1A150 AA	20135
426070C050	28670	4D0907275	20077	68001696AA	20066 / 28308
426070E011	28370	4D0907275C	20077	68001696AB	20066 / 28308
4260724010	28310	4D0907275D	20079	68001698AA	28155 / 28434
4260724020	28315	4F0907275B	20078	68001698AB	28155 / 28434
4260724030	28320	4F0907275D	20103	68006771AA	20089
4260724040	28325	4F0907275H	20077	68038945AA	20089
4260730030	28335	4L2Z 1A150 BA	20096	68078861AA	20066 / 28308
4260733010	28365	5096808AA	20028	68137699AA	28461
4260733011	28365	5127335AB	20335	6F2Z1A189A	28385
4260733021	28370	5127335AD	20335	7L1Z1A189A	28390
4260735010	28345	5142340AA	20066 / 28308	7P0907275	20103
4260752010	28365	52088990AC	20028	7P0907275A	20077
4260775010	20101	529331F000	28983	8257740060	20116
42607AD010	28380	529331FA00	28983	86517000	20156
42607AD020	28355	529332F000	28849	88974915	28360
42753SHJA53	28981	529332G000	20086	8973271890	20028
42753SNA81	28720	529332G200	20086	8C2Z1A189A	28395
42753SHJA82	28983	529332M000	20092	95536105300	20077
42753SNA83	28720	529333E200	28983	95836166100	20103
42753STKA01	20098	529333X200	20086	99760602120	28087
42753STKA02	20098	529333D000	20085	9L3Z1A189A	20315
42753STKA03	20098	529334D200	20085	FE0137140A	20093



Numerical Listing

Sensors/Transmitters

20028 (433 MHz)



Chrysler; 300M; 2004-2002
 Chrysler; Concorde; 2004-2002
 Chrysler; Crossfire; 2008-2006
 Chrysler; Crossfire; 2005; OEM Part No. 52088990AC
 Chrysler; Crossfire; 2004
 Chrysler; Intrepid; 2004-2002
 Chrysler; Pacifica; 2004; OEM Part No. 52088990AC
 Chrysler; Prowler; 2002
 Chrysler; Town & Country Van; 2003-2002
 Chrysler; Voyager; 2003-2002
 Dodge; Caravan; 2003-2002
 Dodge; Grand Caravan; 2003-2002
 Dodge; Intrepid; 2004-2002
 Dodge; Viper; 2010-2008
 Dodge; Viper; 2006-2003
 Isuzu; Rodeo; 2004
 Jeep; Grand Cherokee; 2004-2002
 Jeep; Liberty; 2004
 Mitsubishi; Endeavor; 2006; Aug. & Older
 Mitsubishi; Endeavor; 2005-2004
 Mitsubishi; Galant; 2006-2004

20034 (315 MHz)



Mitsubishi; Eclipse; 2011-2008
 Mitsubishi; Eclipse; 2007-2006; W/Alloy Wheels
 Mitsubishi; Endeavor; 2011-2010
 Mitsubishi; Endeavor; 2008-2007
 Mitsubishi; Endeavor; 2006; Sept. 1 & Newer
 Mitsubishi; Galant; 2011-2007; W/Alloy Wheels
 Mitsubishi; Montero; 2006-2003

20064 (315 MHz)



Infiniti; FX35; 2007; Jun. & Older
 Infiniti; FX35; 2006-2003
 Infiniti; FX45; 2007; Jun. & Older
 Infiniti; FX45; 2006-2003
 Infiniti; G35; 2006-2004
 Infiniti; G35; 2003; Jun. & Newer
 Infiniti; M35; 2007-2006
 Infiniti; M45; 2007-2006
 Infiniti; M45; 2004-2003
 Infiniti; Q45; 2006; Jul. & Older
 Infiniti; Q45; 2005-2003
 Infiniti; QX4; 2003
 Nissan; 350Z; 2006-2003

20064 (315 MHz) - Continued

Nissan; Frontier; 2004-2003
 Nissan; Murano; 2006-2003
 Nissan; Pathfinder; 2004; Exc. Armada; Jul. & Older
 Nissan; Pathfinder; 2003
 Nissan; Xterra; 2004-2003

20066 (315 MHz)



Chrysler; 200; 2012-2011
 Chrysler; 300; 2007-2005
 Chrysler; Aspen; 2009-2007
 Chrysler; Crossfire; 2005; OEM Part No. 5142340AA
 Chrysler; Pacifica; 2008-2006
 Chrysler; PT Cruiser; 2010-2008
 Chrysler; Sebring; 2010-2007
 Chrysler; Town & Country Van; 2007-2006
 Dodge; Avenger; 2012
 Dodge; Avenger; 2010-2008
 Dodge; Caliber; 2011-2007
 Dodge; Caravan; 2007-2006
 Dodge; Charger; 2007-2006
 Dodge; Dakota; 2011
 Dodge; Durango; 2009-2007
 Dodge; Grand Caravan; 2007-2006
 Dodge; Journey; 2011
 Dodge; Magnum; 2007-2005
 Dodge; Nitro; 2011-2007
 Jeep; Commander; 2007-2006
 Jeep; Compass; 2011-2007
 Jeep; Grand Cherokee; 2007-2005
 Jeep; Liberty; 2012-2010
 Jeep; Liberty; 2009; Sport
 Jeep; Liberty; 2008-2005
 Jeep; Patriot; 2012-2007
 Jeep; Wrangler; 2012-2011
 Jeep; Wrangler; 2008-2007
 Suzuki; Kizashi; 2012-2010

20069 (315 MHz)



Infiniti; QX56; 2006-2005; W/Steel Wheels
 Infiniti; QX56; 2004
 Nissan; Armada; 2006-2005; W/Steel Wheels
 Nissan; Frontier; 2007-2005; W/Steel Wheels
 Nissan; Pathfinder; 2004; Armada
 Nissan; Pathfinder; 2004; Exc. Armada; Aug. & Newer
 Nissan; Quest; 2006-2005; W/Steel Wheels
 Nissan; Quest; 2004
 Nissan; Titan; 2005; Mar. & Older
 Nissan; Titan; 2004
 Nissan; Xterra; 2006; Submodel X



Numerical Listing

Sensors/Transmitters

20076 (315 MHz)



Cadillac; STS; 2008-2005; OEM Part No. 25758220
 Cadillac; XLR; 2009-2004; OEM Part No. 25758220
 Chevrolet; Corvette; 2009-2005; OEM Part No. 25758220

20077 (433 MHz)



Audi; A6; 2011
 Audi; A8; 2010-2004
 Audi; A8; 2003; Chassis No. 4E3000001 & After
 Audi; Q7; 2011
 Audi; S6; 2011
 Audi; S8; 2009-2007
 Audi; S8; 2003; Chassis No. 4E3000001 & After
 Bentley; Continental; 2005-2003
 Ferrari; 550 Maranello; 2002-2001
 Ferrari; 575M Maranello; 2005-2002
 Ferrari; 612 Scaglietti; 2009-2004
 Ferrari; F430; 2009-2005
 Porsche; 911; 2011
 Porsche; Boxster; 2011
 Porsche; Cayman; 2011
 Volkswagen; Phaeton; 2006-2004; W/315 MHz Sensor
 Volkswagen; Touareg 2; 2011; W/315 MHz Sensor

20078 (433 MHz)



Audi; A4; 2008-2002
 Audi; A6; 2009; Exc. Quattro
 Audi; A6; 2008-2005
 Audi; Q7; 2009-2007
 Audi; R8; 2009-2008
 Audi; RS4; 2008-2007
 Audi; S4; 2009-2004
 Audi; S6; 2009-2007
 Bentley; Continental; 2010-2006
 Volkswagen; Phaeton; 2006-2004; W/433 MHz Sensor
 Volkswagen; Touareg 2; 2009-2008

20079 (315 MHz)



Audi; A8; 2003; Chassis No. 4D3004999 & Before
 Audi; A8; 2002-2001
 Audi; Allroad Quattro; 2005-2001
 Audi; S8; 2003; Chassis No. 4D3004999 & Before
 Audi; S8; 2002-2001

20080 (433 MHz)



BMW; 320I; 2005-2003
 BMW; 320I; 2002; W/433 MHz Sensor
 BMW; 325CI; 2006-2003
 BMW; 325CI; 2002; W/433 MHz Sensor
 BMW; 325I; 2006-2003
 BMW; 325I; 2002; W/433 MHz Sensor
 BMW; 325XI; 2006-2003
 BMW; 325XI; 2002; W/433 MHz Sensor
 BMW; 330CI; 2006-2003
 BMW; 330CI; 2002; W/433 MHz Sensor
 BMW; 330I; 2006-2003
 BMW; 330I; 2002; W/433 MHz Sensor
 BMW; 330XI; 2006-2003
 BMW; 330XI; 2002; W/433 MHz Sensor
 BMW; 525I; 2005-2003
 BMW; 525I; 2002; W/433 MHz Sensor
 BMW; 530I; 2005-2003
 BMW; 530I; 2002; W/433 MHz Sensor
 BMW; 540I; 2003
 BMW; 540I; 2002; W/433 MHz Sensor
 BMW; 545I; 2005-2004
 BMW; 645CI; 2005-2004
 BMW; 745I; 2005-2003
 BMW; 745I; 2002; W/433 MHz Sensor
 BMW; 745LI; 2005-2003
 BMW; 745LI; 2002; W/433 MHz Sensor
 BMW; 760I; 2005-2004
 BMW; 760I; 2003
 BMW; Alpina B7; 2011
 BMW; M3; 2003
 BMW; M3; 2002; W/433 MHz Sensor
 BMW; M5; 2003-2000; W/433 MHz Sensor
 BMW; Z8; 2003; W/433 MHz Sensor



Numerical Listing

Sensors/Transmitters

20081 (315 MHz)



Subaru; B9 Tribeca; 2007-2008
Subaru; Legacy; 2008; W/16" Or 17" Wheels
Subaru; Legacy; 2007-2004
Subaru; Outback; 2006-2004
Subaru; Tribeca; 2008; W/Metal Stem Clamp-in Sensor

20082 (315 MHz)



Suzuki; Verona; 2006-2005

20083 (315 MHz)



BMW; 128i; 2011-2008
BMW; 135i; 2010-2008
BMW; 323i; 2010-2007
BMW; 323i; 2006; Jun. & Newer
BMW; 328i; 2009-2007
BMW; 328xi; 2008-2007
BMW; 335D; 2009
BMW; 335i; 2009-2007
BMW; 335xi; 2008-2007
BMW; 525i; 2007-2006
BMW; 525xi; 2007-2006
BMW; 528i; 2011-2008
BMW; 528xi; 2008
BMW; 530i; 2007-2006
BMW; 530xi; 2007-2006
BMW; 535i; 2011-2008
BMW; 535xi; 2008
BMW; 550i; 2011-2006
BMW; 650i; 2010-2006
BMW; 740i; 2011
BMW; 740Li; 2011
BMW; 750i; 2011-2006
BMW; 750Li; 2011-2006
BMW; 760i; 2006
BMW; 760Li; 2011-2010
BMW; 760Li; 2008-2004
BMW; Alpina B7; 2008-2007
BMW; M3; 2009-2008
BMW; M3; 2006-2004
BMW; M5; 2010-2006
BMW; M6; 2010-2006
BMW; X3; 2011-2006
BMW; X5; 2011-2005
BMW; X6; 2011-2008

20083 (315 MHz) - Continued

BMW; Z4; 2011-2003
Mini; Cooper; 2009-2008

20084 (433 MHz)



Ferrari; Enzo; 2004-2003

20085 (315 MHz)



Hyundai; Entourage; 2009-2007
Hyundai; Santa Fe; 2008-2007
Hyundai; Veracruz; 2008-2007
Kia; Sedona; 2008-2006

20086 (315 MHz)



Hyundai; Azera; 2011-2006
Hyundai; Elantra; 2011-2008
Hyundai; Santa Fe; 2010-2009
Hyundai; Veracruz; 2011-2009
Kia; Magentis; 2010-2008
Kia; Optima; 2010-2006
Kia; Rondo; 2010-2007
Kia; Sedona; 2012-2009

20087 (315 MHz)



Suzuki; Grand Vitara; 2011-2007
Suzuki; SX4; 2012-2007
Suzuki; XL-7; 2006-2005



Numerical Listing

Sensors/Transmitters

20088 (315 MHz)



Audi; A3; 2012-2008
 Audi; A4; 2012-2009
 Audi; A5; 2012-2008
 Audi; Q5; 2012-2009
 Audi; S4; 2011-2010
 Audi; S5; 2012-2008
 Audi; TT; 2011-2008
 Volkswagen; Beetle; 2010-2008
 Volkswagen; CC; 2012-2009
 Volkswagen; Eos; 2012-2007
 Volkswagen; Golf; 2010-2008
 Volkswagen; GTI; 2010-2008
 Volkswagen; GTI; 2007-2006; W/16" Or 17" Wheels
 Volkswagen; Jetta; 2010-2006
 Volkswagen; Passat; 2010-2009
 Volkswagen; Passat; 2008-2006; W/16" Or 17" Wheels
 Volkswagen; R32; 2008
 Volkswagen; Rabbit; 2009-2008
 Volkswagen; Rabbit; 2007-2006; W/15" Wheels
 Volkswagen; Tiguan; 2011-2009

20089 (315 MHz)



Dodge; Sprinter; 2009-2007

20090 (315 MHz)



Jaguar; S-Type; 2008; W/315 MHz Sensor
 Jaguar; Super V8; 2009-2005; W/315 MHz Sensor
 Jaguar; Vanden Plas; 2009-2004; W/315 MHz Sensor
 Jaguar; X-Type; 2008; W/315 MHz Sensor
 Jaguar; XF; 2012-2009; W/315 MHz Sensor
 Jaguar; XFR; 2011-2010; W/315 MHz Sensor
 Jaguar; XJ; 2012-2010; W/315 MHz Sensor
 Jaguar; XJ8; 2009-2004; W/315 MHz Sensor
 Jaguar; XJR; 2009-2004; W/315 MHz Sensor
 Jaguar; XK; 2012-2007; W/315 MHz Sensor
 Jaguar; XKR; 2011-2007; W/315 MHz Sensor
 Land Rover; LR2; 2011-2009
 Land Rover; LR3; 2009-2006; W/315 MHz Sensor
 Land Rover; LR4; 2011-2010; W/315 MHz Sensor
 Land Rover; Range Rover; 2011-2006; W/315 MHz Sensor

20091 (315 MHz)



Jaguar; S-Type; 2008; W/433 MHz Sensor
 Jaguar; Super V8; 2009-2005; W/433 MHz Sensor
 Jaguar; Vanden Plas; 2009-2004; W/433 MHz Sensor
 Jaguar; X-Type; 2008; W/433 MHz Sensor
 Jaguar; XF; 2012-2009; W/433 MHz Sensor
 Jaguar; XFR; 2011-2010; W/433 MHz Sensor
 Jaguar; XJ; 2012-2010; W/433 MHz Sensor
 Jaguar; XJ8; 2009-2004; W/433 MHz Sensor
 Jaguar; XJR; 2009-2004; W/433 MHz Sensor
 Jaguar; XK; 2012-2007; W/433 MHz Sensor
 Jaguar; XKR; 2011-2007; W/433 MHz Sensor
 Land Rover; LR3; 2009-2006; W/433 MHz Sensor
 Land Rover; LR4; 2011-2010; W/433 MHz Sensor
 Land Rover; Range Rover; 2011-2006; W/433 MHz Sensor

20092 (315 MHz)



Hyundai; Accent; 2012
 Hyundai; Genesis; 2012-2011; Coupe
 Hyundai; Sonata; 2012-2011
 Kia; Forte; 2010
 Kia; Sorento; 2011
 Kia; Soul; 2011-2010

20093 (315 MHz)



Mazda; 2; 2011
 Mazda; 3; 2011-2004
 Mazda; 5; 2010-2006
 Mazda; 6; 2011-2008
 Mazda; CX-7; 2011-2007
 Mazda; CX-9; 2011-2007
 Mazda; MX-5 Miata; 2011-2006
 Mazda; RX-8; 2011-2004
 Mazda; Tribute; 2011



Numerical Listing

Sensors/Transmitters

20094 (433 MHz)



Mercedes-Benz; CL63; 2009-2007
 Mercedes-Benz; CL65; 2009-2008
 Mercedes-Benz; CL550; 2009-2007
 Mercedes-Benz; CL600; 2009-2007
 Mercedes-Benz; CLS55; 2006
 Mercedes-Benz; CLS63; 2011-2007
 Mercedes-Benz; CLS500; 2006
 Mercedes-Benz; CLS550; 2011-2007
 Mercedes-Benz; E55; 2006
 Mercedes-Benz; E63; 2009-2007
 Mercedes-Benz; E320; 2009-2006
 Mercedes-Benz; E350; 2009-2006; W/315 MHz Sensor
 Mercedes-Benz; E500; 2006
 Mercedes-Benz; E550; 2009-2007; W/315 MHz Sensor
 Mercedes-Benz; S63; 2010-2007
 Mercedes-Benz; S65; 2010-2007
 Mercedes-Benz; S400; 2010
 Mercedes-Benz; S550; 2010-2007
 Mercedes-Benz; S600; 2010-2007
 Mercedes-Benz; SL55; 2008-2006
 Mercedes-Benz; SL63; 2011
 Mercedes-Benz; SL63; 2009
 Mercedes-Benz; SL65; 2011
 Mercedes-Benz; SL65; 2009-2006
 Mercedes-Benz; SL500; 2006
 Mercedes-Benz; SL550; 2009-2007
 Mercedes-Benz; SL600; 2009-2006
 Mercedes-Benz; SLR McLaren; 2009-2008

20095 (433 MHz)



Mercedes-Benz; E350; 2009-2006; W/433 MHz Sensor
 Mercedes-Benz; E550; 2009-2007; W/433 MHz Sensor
 Mercedes-Benz; GL320; 2009-2007
 Mercedes-Benz; GL450; 2009-2007
 Mercedes-Benz; GL550; 2009-2008
 Mercedes-Benz; ML63; 2009-2007
 Mercedes-Benz; ML320; 2009-2007
 Mercedes-Benz; ML350; 2009-2006
 Mercedes-Benz; ML500; 2007-2006
 Mercedes-Benz; ML550; 2009-2008
 Mercedes-Benz; R63; 2007
 Mercedes-Benz; R320; 2009-2007
 Mercedes-Benz; R350; 2009-2006
 Mercedes-Benz; R500; 2007-2006

20096 (433 MHz)



Ford; Expedition; 2004-2003
 Ford; Explorer; 2005-2004
 Ford; Explorer; 2003-2002; Exc. Sport
 Lincoln; Aviator; 2005-2003
 Lincoln; Navigator; 2004-2003
 Mercury; Mountaineer; 2005-2002

20097 (433 MHz)



Volvo; C30; 2011-2007
 Volvo; C70; 2012-2008
 Volvo; S40; 2011-2008
 Volvo; S60; 2012-2011
 Volvo; S80; 2011-2007
 Volvo; V50; 2011-2008
 Volvo; V70; 2010-2008
 Volvo; XC60; 2011-2010
 Volvo; XC70; 2011-2008
 Volvo; XC90; 2011-2010
 Volvo; XC90; 2008

20098 (315 MHz)



Acura; MDX; 2011-2007
 Acura; RDX; 2010-2007
 Acura; TSX; 2011-2007
 Honda; Pilot; 2011-2010; Exc. LX
 Honda; Pilot; 2009; W/Alloy Wheels

20099 (315 MHz)



Honda; Accord; 2011-2010; Exc. Crosstour
 Honda; Accord; 2009-2008
 Honda; CR-V; 2011-2010
 Honda; CR-V; 2009-2007; W/Alloy Wheels
 Honda; Fit; 2008



Numerical Listing

Sensors/Transmitters

20100 (315 MHz)



Honda; Accord; 2011-2010; Crosstour

20103 (433 MHz)



Audi; A6; 2010
 Audi; A6; 2009; Quattro
 Audi; Q7; 2012
 Audi; Q7; 2010
 Audi; R8; 2012-2011
 Audi; R8; 2010
 Audi; S6; 2010
 Porsche; Cayenne; 2011
 Volkswagen; Touareg 2; 2011; W/433 MHz Sensor
 Volkswagen; Touareg 2; 2010

20107 (315 MHz)



Cadillac; Escalade; 2006-2005
 Chevrolet; Avalanche; 2006-2005
 Chevrolet; Silverado Series Pickup; 2007; Classic
 Chevrolet; Silverado Series Pickup; 2006-2005
 Chevrolet; Suburban; 2006-2005
 Chevrolet; Tahoe; 2006-2005
 GMC; Sierra Series Pickup; 2007; Classic
 GMC; Sierra Series Pickup; 2006-2005
 GMC; Yukon; 2006-2005

20115 (315 MHz)



Cadillac; Escalade; 2004
 Chevrolet; Avalanche; 2004
 Chevrolet; Silverado Series Pickup; 2004
 Chevrolet; Suburban; 2004
 Chevrolet; Tahoe; 2004
 GMC; Sierra Series Pickup; 2004
 GMC; Yukon; 2004

20116 (315 MHz)



Buick; Rainier; 2007-2006; OEM Part No. 25774006
 Cadillac; CTS; 2007-2006; OEM Part No. 25774006
 Cadillac; CTS; 2005-2004
 Cadillac; SRX; 2006; OEM Part No. 25774006
 Cadillac; SRX; 2005-2004
 Chevrolet; SSR; 2006; OEM Part No. 25774006
 Chevrolet; Trailblazer; 2009-2006; OEM Part No. 25774006
 GMC; Envoy; 2009-2006; OEM Part No. 25774006
 Isuzu; Ascender; 2008-2006
 Saab; 9-7X; 2009-2005

20117 (315 MHz)



Cadillac; Deville; 2005-2001
 Cadillac; Seville; 2004-2001
 Chevrolet; Corvette; 2004-2001

20131 (315 MHz)



Chevrolet; Colorado; 2012-2007
 GMC; Canyon; 2012-2007
 Hummer; H3; 2010-2006
 Hummer; H3T; 2010-2009
 Isuzu; I-290; 2008-2007
 Isuzu; I-370; 2008-2007

20135 (315 MHz)



Ford; Expedition; 2006-2005
 Ford; Freestar; 2005-2004; W/Almmn. Valve Stem
 Lincoln; Navigator; 2006-2005
 Mercury; Monterey Van; 2005-2004



Numerical Listing

Sensors/Transmitters

20153 (315 MHz)



Buick; Allure; 2009
 Buick; Enclave; 2012-2009
 Buick; LaCrosse; 2012
 Buick; LaCrosse; 2009
 Buick; Lucerne; 2011-2007
 Cadillac; CTS; 2012-2009; OEM Part No. 25920615; Exc. CTS V
 Cadillac; CTS; 2008
 Cadillac; DTS; 2011-2007
 Cadillac; Escalade; 2012-2008
 Cadillac; Escalade; 2007; Snap-In Style Only; Schrader Sensor;
 W/Rubber Valve Stem
 Cadillac; SRX; 2009-2007
 Cadillac; STS; 2011-2010
 Cadillac; STS; 2009; OEM Part No. 25920615; Exc. STS V
 Chevrolet; Avalanche; 2012-2008
 Chevrolet; Avalanche; 2007; Snap-In Style Only; Schrader Sensor;
 W/Rubber Valve Stem
 Chevrolet; Aveo; 2011-2008
 Chevrolet; Aveo; 2007; Hatchback
 Chevrolet; Captiva; 2012
 Chevrolet; Cobalt; 2009-2008; Snap-In Style Only; W/Rubber Valve Stem
 Chevrolet; Express; 2012-2010
 Chevrolet; HHR; 2011
 Chevrolet; HHR; 2009-2008; Snap-In Style Only; W/Rubber Valve Stem
 Chevrolet; Impala; 2012-2008
 Chevrolet; Impala; 2007; Snap-In Style Only; W/Rubber Valve Stem
 Chevrolet; Malibu; 2012-2011
 Chevrolet; Malibu; 2009
 Chevrolet; Malibu; 2008; Snap-In Style Only; W/Rubber Valve Stem
 Chevrolet; Monte Carlo; 2007; Snap-In Style Only; W/Rubber Valve Stem
 Chevrolet; Silverado Series Pickup; 2012-2008; W/Single Rear Wheels
 Chevrolet; Silverado Series Pickup; 2007; Snap-In Style Only;
 Schrader Sensor; W/Rubber Valve Stem; Exc. Classic
 Chevrolet; Suburban; 2012-2008
 Chevrolet; Suburban; 2012; W/Single Rear Wheels
 Chevrolet; Suburban; 2007; Snap-In Style Only; Schrader Sensor;
 W/Rubber Valve Stem
 Chevrolet; Tahoe; 2012-2008
 Chevrolet; Tahoe; 2007; Snap-In Style Only; Schrader Sensor; W/Rubber Valve Stem
 Chevrolet; Traverse; 2012-2009
 GMC; Acadia; 2012-2009
 GMC; Savana; 2012-2010
 GMC; Sierra Series Pickup; 2012-2008; W/Single Rear Wheels
 GMC; Sierra Series Pickup; 2007; Snap-In Style Only; Schrader Sensor;
 W/Rubber Valve Stem; Exc. Classic
 GMC; Yukon; 2012-2008
 GMC; Yukon; 2012; W/Single Rear Wheels
 GMC; Yukon; 2007; Snap-In Style Only; Schrader Sensor; W/Rubber Valve Stem
 Hummer; H2; 2010-2008
 Pontiac; G3; 2010-2009
 Pontiac; G3 Wave; 2009
 Pontiac; G5; 2010-2009
 Pontiac; G6; 2010-2009
 Pontiac; G8; 2010-2008
 Pontiac; Grand Prix; 2008; Snap-In Style Only; W/Rubber Valve Stem
 Pontiac; Wave; 2008
 Saturn; Aura; 2010-2008
 Saturn; Outlook; 2010-2009
 Saturn; VUE; 2010-2008

20153 (315 MHz) - Continued

Suzuki; Forenza; 2008-2007
 Suzuki; Reno; 2008-2007

20156 (315 MHz)



Volvo; S60; 2009-2006
 Volvo; S60; 2005-2004; W/315 MHz Sensor
 Volvo; S80; 2006-2004
 Volvo; V70; 2007-2004; W/315 MHz Sensor
 Volvo; XC70; 2007-2004; W/315 MHz Sensor
 Volvo; XC90; 2009; W/315 MHz Sensor
 Volvo; XC90; 2007-2005; W/315 MHz Sensor
 Volvo; XC90; 2004

20158 (315 MHz)



Buick; Allure; 2008-2007
 Buick; Enclave; 2008
 Buick; LaCrosse; 2008-2007
 Cadillac; CTS; 2012-2009; OEM Part No. 15268606; CTS V; W/315 MHz Sensor
 Cadillac; DTS; 2006
 Cadillac; Escalade; 2007; Clamp-In Style Only; TRW Sensor; W/Almm. Valve Stem
 Chevrolet; Avalanche; 2007; Clamp-In Style Only; TRW Sensor;
 W/Almm. Valve Stem
 Chevrolet; Caprice; 2012-2011
 Chevrolet; Cobalt; 2009-2008; Clamp-In Style Only; W/Almm. Valve Stem
 Chevrolet; Corvette; 2012-2010
 Chevrolet; Equinox; 2009-2007
 Chevrolet; Express; 2009-2008
 Chevrolet; HHR; 2009-2008; Clamp-In Style Only; W/Almm. Valve Stem
 Chevrolet; Impala; 2007; Clamp-In Style Only; W/Almm. Valve Stem
 Chevrolet; Impala; 2006; W/Alloy Wheels
 Chevrolet; Malibu; 2008; Clamp-In Style Only; W/Almm. Valve Stem
 Chevrolet; Monte Carlo; 2007; Clamp-In Style Only; W/Almm. Valve Stem
 Chevrolet; Monte Carlo; 2006; W/Alloy Wheels
 Chevrolet; Silverado Series Pickup; 2007; Clamp-In Style Only; TR Sensor;
 W/Almm. Valve Stem; Exc. Classic
 Chevrolet; Suburban; 2007; Clamp-In Style Only; TRW Sensor;
 W/Almm. Valve Stem
 Chevrolet; Tahoe; 2007; Clamp-In Style Only; TRW Sensor; W/Almm. Valve Stem
 Chevrolet; Uplander; 2009-2008
 GMC; Acadia; 2008-2007
 GMC; Savana; 2009-2008
 GMC; Sierra Series Pickup; 2007; Clamp-In Style Only; TRW Sensor;
 W/Almm. Valve Stem; Exc. Classic
 GMC; Yukon; 2007; Clamp-In Style Only; TRW Sensor; W/Almm. Valve Stem
 Pontiac; G5; 2008
 Pontiac; G6; 2008
 Pontiac; Grand Prix; 2008; Clamp-In Style Only; W/Almm. Valve Stem
 Pontiac; Grand Prix; 2007
 Pontiac; Montana; 2009-2008
 Pontiac; Solstice; 2010-2008



Numerical Listing

Sensors/Transmitters

20158 (315 MHz) - Continued

Pontiac; Torrent; 2009-2007
 Saturn; Aura; 2007
 Saturn; Outlook; 2008-2007
 Saturn; Sky; 2010-2008
 Suzuki; XL-7; 2009-2007

20159 (433 MHz)



Saab; 9-3; 2012-2008
 Saab; 9-5; 2012-2008

20161 (315 MHz)



Infiniti; QX56; 2007; Mar. & Older
 Infiniti; QX56; 2006-2005; W/Alloy Wheels
 Nissan; Armada; 2008; SE
 Nissan; Armada; 2007
 Nissan; Armada; 2006-2005; W/Alloy Wheels
 Nissan; Frontier; 2008-2005; W/Alloy Wheels
 Nissan; Maxima; 2007; Mar. & Older
 Nissan; Maxima; 2006; Jun. & Newer
 Nissan; Pathfinder; 2006-2005
 Nissan; Quest; 2006-2005; W/Alloy Wheels
 Nissan; Sentra; 2007; W/Alloy Wheels
 Nissan; Titan; 2007; Mar. & Older
 Nissan; Titan; 2006
 Nissan; Titan; 2005; Apr. 1 & Newer
 Nissan; Xterra; 2006; Exc. Submodel X
 Nissan; Xterra; 2005

20315 (315 MHz)



Ford; E450 Super Duty; 2010
 Ford; E Series Van; 2012-2011
 Ford; E Series Van; 2010; W/Steel Wheels
 Ford; Edge; 2012-2011
 Ford; Escape; 2012-2009
 Ford; Expedition; 2012-2011
 Ford; Explorer; 2012-2011
 Ford; F Series Pickup; 2012-2009
 Ford; Fiesta; 2012-2011
 Ford; Flex; 2012-2011
 Ford; Focus; 2012-2010
 Ford; Fusion; 2012-2010
 Ford; Mustang; 2012-2010
 Ford; Super Duty Pickup; 2012-2011

20315 (315 MHz) - Continued

Ford; Super Duty Van; 2011
 Ford; Super Duty Van; 2010; W/Steel Wheels
 Ford; Taurus; 2012-2011
 Ford; Taurus; 2010; May & Newer
 Ford; Transit Connect; 2012-2010
 Lincoln; MKS; 2012-2011
 Lincoln; MKT; 2012-2011
 Lincoln; MKX; 2012-2011
 Lincoln; MKZ; 2012-2010
 Lincoln; Navigator; 2012-2011
 Lincoln; Town Car; 2011
 Mazda; Tribute; 2010-2009
 Mercury; Grand Marquis; 2011
 Mercury; Mariner; 2011-2009
 Mercury; Milan; 2011-2010

20335 (315 MHz)



Chrysler; Pacifica; 2005
 Chrysler; Pacifica; 2004; OEM Part No. 04727392AD
 Chrysler; Town & Country Van; 2005-2004
 Dodge; Caravan; 2005-2004
 Dodge; Grand Caravan; 2005-2004

20398 (433 MHz)



Chrysler; 300; 2012-2011
 Chrysler; Town & Country Van; 2012-2011
 Dodge; Challenger; 2012
 Dodge; Challenger; 2011-2010; W/Rubber Stem Snap-in Sensor
 Dodge; Charger; 2012
 Dodge; Charger; 2011-2010; W/Rubber Stem Snap-in Sensor
 Dodge; Durango; 2012-2011
 Dodge; Grand Caravan; 2012-2011
 Dodge; Journey; 2012
 Dodge; Ram Series Pickup; 2012
 Dodge; Ram Series Pickup; 2011-2010; W/Rubber Stem Snap-in Sensor
 Fiat; 500; 2012
 Jeep; Grand Cherokee; 2012-2011
 Mitsubishi; Lancer; 2011; W/Alloy Wheels
 Mitsubishi; Outlander; 2011; W/Alloy Wheels



Numerical Listing

Sensors/Transmitters

20720 (433 MHz)



Acura; TL; 2012-2009

28004 (315 MHz)



Chrysler; Prowler; 2001
Plymouth; Prowler; 2001-1999
Plymouth; Prowler; 1997

28006 (315 MHz)



Chevrolet; Corvette; 2000-1997

28078 (433 MHz)



Saab; 9-3; 2007-2003
Saab; 9-5; 2007-2003
Saturn; Astra; 2008

28081 (433 MHz)



BMW; 128i; 2012
BMW; 135i; 2012
BMW; 328i; 2012-2010
BMW; 335D; 2012-2010
BMW; 335i; 2012-2010
BMW; 335iS; 2012
BMW; 528i; 2012
BMW; 535i; 2012
BMW; 550i; 2012
BMW; 640i; 2012

28081 (433 MHz) - Continued

BMW; 650i; 2012
BMW; 740i; 2012
BMW; 740Li; 2012
BMW; 750i; 2012
BMW; 750Li; 2012
BMW; M1; 2012
BMW; M3; 2010
BMW; X1; 2012
BMW; X3; 2012
BMW; X5; 2012
BMW; X6; 2012
BMW; Z4; 2012
Mini; Cooper; 2012-2010

28082 (433 MHz)



BMW; X5; 2004-2000
Land Rover; LR3; 2005
Land Rover; Range Rover; 2005-2002

28087 (433 MHz)



Porsche; 911; 2010
Porsche; Boxster; 2010
Porsche; Cayman; 2010-2009
Porsche; Panamera; 2011-2010

28096 (315 MHz)



Mitsubishi; Lancer; 2011; W/Steel Wheels
Mitsubishi; Lancer; 2010-2008
Mitsubishi; Outlander; 2011; W/Steel Wheels
Mitsubishi; Outlander; 2010-2007



Numerical Listing

Sensors/Transmitters

28129 (315 MHz)



Mitsubishi; Eclipse; 2007-2006; W/Steel Wheels
Mitsubishi; Galant; 2011-2007; W/Steel Wheels

28154 (315 MHz)



Dodge; Dakota; 2010-2008
Dodge; Ram Series Pickup; 2008; 1500, 2500
Mitsubishi; Raider; 2009-2008

28155 (433 MHz)



Chrysler; 300; 2008
Chrysler; Town & Country Van; 2009-2008
Dodge; Charger; 2008
Dodge; Grand Caravan; 2010-2008
Dodge; Journey; 2010-2009
Dodge; Magnum; 2008
Dodge; Ram Series Pickup; 2010; 1500, 2500; W/Metal Stem Clamp-in Sensor
Dodge; Ram Series Pickup; 2009; 1500, 2500
Jeep; Commander; 2010-2008
Jeep; Grand Cherokee; 2010-2008
Jeep; Liberty; 2009; Exc. Sport
Jeep; Wrangler; 2010-2009

28167 (315 MHz)



Nissan; Pathfinder; 2007; OEM Part No. 40700JA01A
Nissan; Versa; 2007; OEM Part No. 40700JA01A
Nissan; Xterra; 2007; OEM Part No. 40700JA01A

28203 (315 MHz)



Subaru; Forester; 2012-2008
Subaru; Impreza; 2012-2008
Subaru; Legacy; 2012-2009
Subaru; Legacy; 2008; W/18" Wheels
Subaru; Outback; 2012-2008
Subaru; Tribeca; 2011-2009
Subaru; Tribeca; 2008; W/Rubber Stem Snap-in Sensor

28204 (315 MHz)



Infiniti; FX35; 2008
Infiniti; FX35; 2007; Jul. & Newer
Infiniti; FX45; 2008
Infiniti; FX45; 2007; Jul. & Newer
Infiniti; G35; 2007; Coupe
Infiniti; M35; 2010-2008
Infiniti; M45; 2010-2008
Infiniti; Q45; 2006; Aug. & Newer
Infiniti; QX56; 2010-2008
Infiniti; QX56; 2007; Apr. 1 & Newer
Nissan; 350Z; 2009-2007
Nissan; Altima; 2012-2007
Nissan; Altima; 2006; Oct. 1 & Newer
Nissan; Armada; 2012-2009
Nissan; Armada; 2008; LE
Nissan; Cube; 2012-2011
Nissan; Cube; 2009
Nissan; Frontier; 2012-2009
Nissan; Frontier; 2008; W/Steel Wheels
Nissan; GT-R; 2012-2011
Nissan; GT-R; 2009
Nissan; Juke; 2012-2011
Nissan; Maxima; 2012-2008
Nissan; Maxima; 2007; Apr. 1 & Newer
Nissan; Murano; 2012-2011
Nissan; Murano; 2009
Nissan; Murano; 2007
Nissan; Pathfinder; 2012-2008
Nissan; Pathfinder; 2007; OEM Part No. 40700JA01B
Nissan; Quest; 2009-2007
Nissan; Rogue; 2012-2011
Nissan; Rogue; 2009-2008
Nissan; Sentra; 2012-2008
Nissan; Sentra; 2007; W/Steel Wheels
Nissan; Titan; 2012-2008
Nissan; Titan; 2007; Apr. 1 & Newer
Nissan; Versa; 2012-2008
Nissan; Versa; 2007; OEM Part No. 40700JA01B
Nissan; Xterra; 2012-2008
Nissan; Xterra; 2007; OEM Part No. 40700JA01B
Suzuki; Equator; 2011-2009



Numerical Listing

Sensors/Transmitters

28206 (314.9 MHz)



Buick; Allure; 2010
 Buick; LaCrosse; 2011-2010
 Buick; Regal; 2012-2011
 Buick; Verano; 2012
 Cadillac; SRX; 2012-2010
 Chevrolet; Camaro; 2012-2010
 Chevrolet; Cobalt; 2010
 Chevrolet; Cruze; 2012-2011
 Chevrolet; Equinox; 2012-2010
 Chevrolet; HHR; 2010
 Chevrolet; Malibu; 2010
 Chevrolet; Orlando; 2012
 Chevrolet; Sonic; 2012
 Chevrolet; Volt; 2012-2011
 GMC; Terrain; 2012-2010
 Saab; 9-4X; 2012
 Saturn; Astra; 2010-2009

28210 (315 MHz)



Infiniti; EX35; 2010-2008
 Infiniti; FX35; 2010-2009
 Infiniti; FX50; 2010-2009
 Infiniti; G35; 2008
 Infiniti; G35; 2007; Sedan
 Infiniti; G37; 2010-2008
 Nissan; 370Z; 2009

28214 (433 MHz)



Mercedes-Benz; C63; 2012-2008
 Mercedes-Benz; C250; 2012
 Mercedes-Benz; C300; 2011-2008
 Mercedes-Benz; C350; 2012-2008
 Mercedes-Benz; C350; 2007; Jun. & Newer
 Mercedes-Benz; CL63; 2012-2010
 Mercedes-Benz; CL65; 2012-2010
 Mercedes-Benz; CL550; 2012-2010
 Mercedes-Benz; CL600; 2012
 Mercedes-Benz; CL600; 2010
 Mercedes-Benz; CLK55; 2006
 Mercedes-Benz; CLK63; 2009-2007
 Mercedes-Benz; CLK350; 2009-2006
 Mercedes-Benz; CLK500; 2006

28214 (433 MHz) - Continued

Mercedes-Benz; CLK550; 2009-2007
 Mercedes-Benz; CLS63; 2012
 Mercedes-Benz; CLS550; 2012
 Mercedes-Benz; E63; 2011-2010
 Mercedes-Benz; E350; 2012-2010
 Mercedes-Benz; E550; 2011-2010
 Mercedes-Benz; G55; 2011-2008
 Mercedes-Benz; G55; 2007; Mar. & Newer
 Mercedes-Benz; G500; 2008
 Mercedes-Benz; G500; 2007; Mar. & Newer
 Mercedes-Benz; G550; 2011-2009
 Mercedes-Benz; GL350; 2011-2010
 Mercedes-Benz; GL450; 2011-2010
 Mercedes-Benz; GL550; 2011-2010
 Mercedes-Benz; GLK350; 2012-2010
 Mercedes-Benz; ML63; 2011-2010
 Mercedes-Benz; ML350; 2012-2010
 Mercedes-Benz; ML450; 2011-2010
 Mercedes-Benz; ML550; 2011-2010
 Mercedes-Benz; R350; 2012-2010
 Mercedes-Benz; S63; 2011
 Mercedes-Benz; S65; 2011
 Mercedes-Benz; S400; 2011
 Mercedes-Benz; S550; 2011
 Mercedes-Benz; S600; 2011
 Mercedes-Benz; SL63; 2012
 Mercedes-Benz; SL550; 2012
 Mercedes-Benz; SLK55; 2010-2008
 Mercedes-Benz; SLK55; 2007; May & Newer
 Mercedes-Benz; SLK250; 2012
 Mercedes-Benz; SLK280; 2008
 Mercedes-Benz; SLK280; 2007; May & Newer
 Mercedes-Benz; SLK300; 2011-2009
 Mercedes-Benz; SLK350; 2012-2008
 Mercedes-Benz; SLK350; 2007; May & Newer
 Mercedes-Benz; SLS; 2012-2011
 Smart; Fortwo; 2012-2008

28291 (433 MHz)



Chrysler; 300; 2010-2009
 Dodge; Challenger; 2011-2010; W/Metal Stem Clamp-in Sensor
 Dodge; Challenger; 2009-2008
 Dodge; Charger; 2010; W/Metal Stem Clamp-in Sensor
 Dodge; Charger; 2009



Numerical Listing

Sensors/Transmitters

28300 (315 MHz)



Toyota; Sequoia; 2007-2005; W/Steel Wheels; W/40 Deg. Angled Valve Sensor
 Toyota; Tacoma; 2005; W/40 Deg. Angled Valve Sensor; Nov. 30 & Older
 Toyota; Tundra; 2006; W/40 Deg. Angled Valve Sensor; Oct. 31 & Older
 Toyota; Tundra; 2005; W/40 Deg. Angled Valve Sensor

28305 (315 MHz)



Toyota; Sequoia; 2007-2005; W/Alloy Wheels
 Toyota; Sequoia; 2007-2005; W/Steel Wheels; W/20 Deg. Angled Valve Sensor
 Toyota; Tacoma; 2005; W/20 Deg. Angled Valve Sensor; Nov. 30 & Older
 Toyota; Tundra; 2006; W/20 Deg. Angled Valve Sensor; Oct. 31 & Older
 Toyota; Tundra; 2005; W/20 Deg. Angled Valve Sensor

28308 (315 MHz)



Chrysler; 200; 2012-2011
 Chrysler; 300; 2007-2005
 Chrysler; Aspen; 2009-2007
 Chrysler; Crossfire; 2005; OEM Part No. 5142340AA
 Chrysler; Pacifica; 2008-2006
 Chrysler; PT Cruiser; 2010-2008
 Chrysler; Sebring; 2010-2007
 Chrysler; Town & Country Van; 2007-2006
 Dodge; Avenger; 2012
 Dodge; Avenger; 2010-2008
 Dodge; Caliber; 2011-2007
 Dodge; Caravan; 2007-2006
 Dodge; Charger; 2007-2006
 Dodge; Dakota; 2011
 Dodge; Durango; 2009-2007
 Dodge; Grand Caravan; 2007-2006
 Dodge; Journey; 2011
 Dodge; Magnum; 2007-2005
 Dodge; Nitro; 2011-2007
 Jeep; Commander; 2007-2006
 Jeep; Compass; 2011-2007
 Jeep; Grand Cherokee; 2007-2005
 Jeep; Liberty; 2012-2010
 Jeep; Liberty; 2009; Sport
 Jeep; Liberty; 2008-2005
 Jeep; Patriot; 2012-2007
 Jeep; Wrangler; 2012-2011
 Jeep; Wrangler; 2008-2007
 Suzuki; Kizashi; 2012-2010

28310 (315 MHz)



Lexus; SC430; 2006; W/White I.D. Mark; Jul. & Older
 Lexus; SC430; 2005-2002; W/White I.D. Mark

28315 (315 MHz)



Lexus; SC430; 2006; W/Blue I.D. Mark; Jul. & Older
 Lexus; SC430; 2005-2002; W/Blue I.D. Mark

28320 (315 MHz)



Lexus; SC430; 2006; W/Red I.D. Mark; Jul. & Older
 Lexus; SC430; 2005-2002; W/Red I.D. Mark

28325 (315 MHz)



Lexus; SC430; 2006; W/Gold I.D. Mark; Jul. & Older
 Lexus; SC430; 2005-2002; W/Gold I.D. Mark

28335 (315 MHz)



Lexus; GS300; 2006
 Lexus; GS430; 2006; Jun. & Older
 Lexus; GS430; 2005
 Lexus; GX470; 2006; Feb. & Newer; W/O Valve Cap
 Lexus; IS250; 2006; Mar. & Older
 Lexus; IS350; 2006; Mar. & Older
 Toyota; 4 Runner; 2006; OEM Part No. 4260730030



Numerical Listing

Sensors/Transmitters

28345 (315 MHz)



Lexus; GX470; 2006; Jan. 31 & Older
 Lexus; GX470; 2005-2004
 Lexus; HS250h; 2011-2010
 Toyota; 4 Runner; 2006; OEM Part No. 4260735010
 Toyota; 4 Runner; 2005-2003

28355 (315 MHz)



Toyota; Tacoma; 2006; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor;
 Jul. & Older
 Toyota; Tacoma; 2005; W/20 Deg. Angled Valve Sensor; Dec. 1 & Newer

28360 (315 MHz)



Pontiac; Vibe; 2010-2008
 Toyota; Avalon; 2011-2007
 Toyota; Avalon; 2006; Aug. & Newer
 Toyota; Camry; 2011-2007; Models made in USA.; OEM Part No. 4260706011
 Toyota; Corolla; 2011-2009; Models made in USA.; W/16" Or 17" Wheels
 Toyota; Corolla; 2008; Models made in USA.; OEM Part No. 4260706011
 Toyota; Corolla; 2007; Models made in USA.; OEM Part No. 4260706011;
 Jun. & Newer
 Toyota; Highlander; 2012-2011
 Toyota; Matrix; 2011-2008; Models made in USA.; OEM Part No. 4260706011
 Toyota; Matrix; 2007; Models made in USA.; OEM Part No. 4260706011;
 Jun. & Newer
 Toyota; Solara; 2008-2007
 Toyota; Solara; 2006; May & Newer
 Toyota; Tacoma; 2012-2007; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor
 Toyota; Tacoma; 2006; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor;
 Aug. & Newer
 Toyota; Venza; 2011-2009

28365 (315 MHz)



Lexus; GX470; 2006; Feb. & Newer; W/Valve Cap
 Lexus; LX470; 2006; Jul. & Older
 Lexus; LX470; 2005

28365 (315 MHz) - Continued

Scion; iQ; 2012-2011
 Scion; TC; 2012-2007
 Scion; TC; 2006; May & Newer
 Scion; XB; 2012-2008
 Scion; XD; 2011-2008
 Toyota; 4 Runner; 2009; W/Valve Cap
 Toyota; 4 Runner; 2008; W/Valve Cap; OEM Part No. 4260733011
 Toyota; 4 Runner; 2007; W/Valve Cap
 Toyota; 4 Runner; 2006; OEM Part No. 4260733011
 Toyota; Camry; 2011-2007; Models made in Japan.; OEM Part No. 4260733011
 Toyota; Corolla; 2011-2008; Models made in Japan.; OEM Part No. 4260733011
 Toyota; Corolla; 2011-2009; Models made in USA.; W/15" Wheels
 Toyota; Corolla; 2007; Models made in Japan.; OEM Part No. 4260733011;
 Jun. & Newer
 Toyota; FJ Cruiser; 2011-2008
 Toyota; Highlander; 2010-2008
 Toyota; Highlander; 2007; May & Newer
 Toyota; Land Cruiser; 2011-2006
 Toyota; Land Cruiser; 2005; May & Newer
 Toyota; Matrix; 2011-2008; Models made in Japan.; OEM Part No. 4260733011
 Toyota; Matrix; 2007; Models made in Japan.; OEM Part No. 4260733011;
 Jun. & Newer
 Toyota; Prius; 2012-2006
 Toyota; RAV4; 2006
 Toyota; Yaris; 2012-2008
 Toyota; Yaris; 2007; Aug. & Newer

28370 (315 MHz)



Lexus; CT200h; 2011
 Lexus; ES350; 2011-2007
 Lexus; GS350; 2011-2007
 Lexus; GS430; 2007
 Lexus; GS430; 2006; Jul. & Newer
 Lexus; GS450h; 2011-2007
 Lexus; GS460; 2011-2008
 Lexus; GX460; 2011-2010
 Lexus; GX470; 2009-2007
 Lexus; IS250; 2011-2007
 Lexus; IS250; 2006; Apr. 1 & Newer
 Lexus; IS350; 2011-2007
 Lexus; IS350; 2006; Apr. 1 & Newer
 Lexus; IS F; 2011-2008
 Lexus; LFA; 2012-2011
 Lexus; LS460; 2011-2007
 Lexus; LS600h; 2011-2008
 Lexus; LX470; 2007
 Lexus; LX470; 2006; Aug. & Newer
 Lexus; LX570; 2011-2008
 Lexus; RX330; 2006; Models made in Japan.; Feb. & Newer
 Lexus; RX350; 2011
 Lexus; RX350; 2010-2007; Models made in Japan.
 Lexus; RX400h; 2009-2007; Models made in Japan.
 Lexus; RX450h; 2011-2010
 Lexus; SC430; 2010-2007
 Lexus; SC430; 2006; Aug. & Newer
 Toyota; 4 Runner; 2011-2010
 Toyota; 4 Runner; 2009; W/O Valve Cap
 Toyota; 4 Runner; 2008; W/O Valve Cap; OEM Part No. 4260733021



Numerical Listing

Sensors/Transmitters

28370 (315 MHz) - Continued

Toyota; 4 Runner; 2007; W/O Valve Cap
 Toyota; 4 Runner; 2006; OEM Part No. 4260733021
 Toyota; Corolla; 2011-2009; Models made in Japan.; OEM Part No. 4260733021
 Toyota; RAV4; 2011-2007

28380 (315 MHz)



Toyota; Tacoma; 2012-2006; W/Steel Wheels; W/40 Deg. Angled Valve Sensor
 Toyota; Tacoma; 2005; W/40 Deg. Angled Valve Sensor; Dec. 1 & Newer

28385 (315 MHz)



Ford; Crown Victoria; 2011-2006
 Ford; Edge; 2008-2007; W/Chrome Plated Almmn. Wheels
 Ford; Escape; 2008-2006
 Ford; Escape; 2005; Oct. 3, 2005 & Newer
 Ford; Explorer; 2010-2006
 Ford; Explorer Sport Trac; 2010-2007
 Ford; F Series Pickup; 2008; W/O H.D. Payload Pkg.
 Ford; F Series Pickup; 2007
 Ford; Freestar; 2007-2006
 Ford; Fusion; 2009-2007
 Ford; Grand Marquis; 2010-2006
 Ford; Mustang; 2009-2007
 Ford; Ranger; 2011-2007
 Lincoln; Mark LT; 2008-2007
 Lincoln; MKX; 2008-2007; W/Chrome Plated Almmn. Wheels
 Lincoln; MKZ; 2009-2007
 Lincoln; Town Car; 2010-2006
 Mazda; B2300 Pickup; 2009-2007
 Mazda; B3000 Pickup; 2008-2007
 Mazda; B4000 Pickup; 2009-2007
 Mazda; Tribute; 2008
 Mazda; Tribute; 2006
 Mercury; Grand Marquis; 2010-2006
 Mercury; Mariner; 2008-2006
 Mercury; Mariner; 2005; Oct. 3, 2005 & Newer
 Mercury; Milan; 2009-2007
 Mercury; Monterey Van; 2007-2006
 Mercury; Mountaineer; 2010-2006

28390 (315 MHz)



Ford; Edge; 2010-2009
 Ford; Edge; 2008-2007; W/O Chrome Plated Almmn. Wheels
 Ford; Expedition; 2010-2007
 Ford; Five Hundred; 2007-2006
 Ford; Flex; 2010-2009
 Ford; Focus; 2009-2008
 Ford; Taurus; 2010; Apr. & Older

28390 (315 MHz) - Continued

Ford; Taurus; 2009-2008
 Ford; Taurus X; 2009-2008
 Lincoln; MKS; 2010-2009
 Lincoln; MKT; 2010
 Lincoln; MKX; 2010-2009
 Lincoln; MKX; 2008-2007; W/O Chrome Plated Almmn. Wheels
 Lincoln; Navigator; 2010-2007
 Mercury; Montego; 2007-2006
 Mercury; Sable; 2009-2008

28395 (315 MHz)



Ford; E450 Super Duty; 2009-2008
 Ford; E Series Van; 2010; W/Alloy Wheels
 Ford; E Series Van; 2009-2008
 Ford; F450 Super Duty; 2010-2008
 Ford; F550 Super Duty; 2010
 Ford; F Series Pickup; 2008; W/H.D. Payload Pkg.
 Ford; Super Duty Pickup; 2010-2008
 Ford; Super Duty Van; 2010; W/Alloy Wheels
 Ford; Super Duty Van; 2009-2008

28434 (433 MHz)



Chrysler; 300; 2008
 Chrysler; Town & Country Van; 2009-2008
 Dodge; Charger; 2008
 Dodge; Grand Caravan; 2010-2008
 Dodge; Journey; 2010-2009
 Dodge; Magnum; 2008
 Dodge; Ram Series Pickup; 2010; 1500, 2500; W/Metal Stem Clamp-in Sensor
 Dodge; Ram Series Pickup; 2009; 1500, 2500
 Jeep; Commander; 2010-2008
 Jeep; Grand Cherokee; 2010-2008
 Jeep; Liberty; 2009; Exc. Sport
 Jeep; Wrangler; 2010-2009

28461 (315 MHz)




Dodge; Dakota; 2010-2008
 Dodge; Ram Series Pickup; 2008; 1500, 2500
 Mitsubishi; Raider; 2009-2008



Numerical Listing

Sensors/Transmitters

28670 (315 MHz)



Toyota; Sequoia; 2011-2008
Toyota; Sienna; 2011-2007
Toyota; Tundra; 2012-2011
Toyota; Tundra; 2010-2007; W/Alloy Wheels; W/20 Deg. Angled Valve Sensor
Toyota; Tundra; 2006; W/20 Deg. Angled Valve Sensor; Nov. 1 & Newer

28981 (315 MHz)



Acura; MDX; 2006-2004
Acura; RL; 2011-2005
Acura; TL; 2008-2005
Honda; Odyssey; 2007-2005; Touring
Honda; Pilot; 2008-2006
Honda; Pilot; 2005; EX
Honda; Pilot; 2005; LX; W/Short Stem Valve
Honda; Ridgeline; 2011-2010; Exc. RT
Honda; Ridgeline; 2011-2010; RT
Honda; Ridgeline; 2009
Honda; Ridgeline; 2008-2007; RTL, RTS, RTX
Honda; Ridgeline; 2006; RTL, RTS

28720 (315 MHz)



Acura; CSX; 2009-2008
Honda; Civic; 2012-2008
Honda; Element; 2011-2009
Honda; Fit; 2011-2009
Honda; Insight; 2011-2010
Honda; Odyssey; 2011

28849 (315 MHz)



Hyundai; Accent; 2011-2008
Hyundai; Equus; 2012-2011
Hyundai; Genesis; 2012-2011; Sedan
Hyundai; Sonata; 2010-2009
Hyundai; Tucson; 2011-2010
Kia; Borrego; 2011-2009
Kia; Rio; 2011-2007
Kia; Spectra; 2009-2006
Kia; Sportage; 2011-2009

28982 (315 MHz)



Honda; Pilot; 2005; LX; W/Long Stem Valve
Honda; Ridgeline; 2008-2006; RT

28983 (315 MHz)



Honda; Odyssey; 2010-2009
Hyundai; Sonata; 2008-2007
Hyundai; Tiburon; 2008-2007
Hyundai; Tucson; 2009-2006
Kia; Amanti; 2009-2007
Kia; Sorento; 2009-2007
Kia; Sportage; 2008-2006
Kia; Sportage; 2005; Jun. 15, 2005 & Newer



Numerical Listing

Service Packs

20002



Ford; Expedition; 2006-2003
 Ford; Explorer; 2005-2004
 Ford; Explorer; 2003-2002; Exc. Sport
 Ford; Freestar; 2005-2004; W/Almm. Valve Stem
 Lincoln; Aviator; 2005-2003
 Lincoln; Navigator; 2006-2003
 Mercury; Monterey Van; 2005-2004
 Mercury; Mountaineer; 2005-2002

20003



Cadillac; Deville; 2005-2001
 Cadillac; Seville; 2004-2001
 Chevrolet; Corvette; 2004-2001
 Chrysler; 300M; 2004-2002; W/Schrader Sensor
 Chrysler; Concorde; 2004-2002; W/Schrader Sensor
 Chrysler; Crossfire; 2008-2006; W/Schrader Sensor
 Chrysler; Crossfire; 2005; OEM Part No. 52088990AC
 Chrysler; Crossfire; 2004; W/Schrader Sensor
 Chrysler; Intrepid; 2004-2002; W/Schrader Sensor
 Chrysler; Pacifica; 2004; OEM Part No. 52088990AC
 Chrysler; Prowler; 2002; W/Schrader Sensor
 Chrysler; Prowler; 2001; W/Red Sensor Body
 Chrysler; Town & Country Van; 2003-2002
 Chrysler; Voyager; 2003-2002
 Dodge; Caravan; 2003-2002
 Dodge; Grand Caravan; 2003-2002
 Dodge; Intrepid; 2004-2002
 Dodge; Viper; 2010-2008
 Dodge; Viper; 2006-2003
 Isuzu; Rodeo; 2004
 Jeep; Grand Cherokee; 2004-2002
 Jeep; Liberty; 2004
 Mitsubishi; Eclipse; 2010-2008
 Mitsubishi; Eclipse; 2007-2006; W/Alloy Wheels
 Mitsubishi; Endeavor; 2010
 Mitsubishi; Endeavor; 2008-2004
 Mitsubishi; Galant; 2009-2007; W/Alloy Wheels
 Mitsubishi; Galant; 2006-2004
 Mitsubishi; Montero; 2006-2003
 Plymouth; Prowler; 2001-1999; W/Red Sensor Body
 Plymouth; Prowler; 1997; W/Red Sensor Body

20004




Buick; Allure; 2008-2007; W/Schrader Sensor
 Buick; Enclave; 2008; W/Schrader Sensor
 Buick; LaCrosse; 2008-2007; W/Schrader Sensor
 Buick; Rainier; 2007-2006
 Cadillac; CTS; 2012-2009; OEM Part No. 15268606; CTS V; W/315 MHz Sensor
 Cadillac; CTS; 2007-2004
 Cadillac; DTS; 2006
 Cadillac; Escalade; 2006-2004
 Cadillac; SRX; 2006-2004
 Cadillac; STS; 2008-2005
 Cadillac; XLR; 2009-2004
 Chevrolet; Avalanche; 2006-2004
 Chevrolet; Caprice; 2012-2011
 Chevrolet; Cobalt; 2009-2008; Clamp-In Style Only; W/Almm. Valve Stem
 Chevrolet; Corvette; 2012-2005
 Chevrolet; Equinox; 2009-2007; W/Schrader Sensor
 Chevrolet; Express; 2009-2008; W/Schrader Sensor
 Chevrolet; HHR; 2009-2008; Clamp-In Style Only; W/Almm. Valve Stem
 Chevrolet; Impala; 2007; Clamp-In Style Only; W/Almm. Valve Stem
 Chevrolet; Impala; 2006; W/Alloy Wheels
 Chevrolet; Malibu; 2008; Clamp-In Style Only; W/Almm. Valve Stem
 Chevrolet; Monte Carlo; 2007; Clamp-In Style Only; W/Almm. Valve Stem
 Chevrolet; Monte Carlo; 2006; W/Alloy Wheels
 Chevrolet; Silverado Series Pickup; 2007; Classic
 Chevrolet; Silverado Series Pickup; 2006-2004
 Chevrolet; SSR; 2006
 Chevrolet; Suburban; 2006-2004
 Chevrolet; Tahoe; 2006-2004
 Chevrolet; Trailblazer; 2009-2006
 Chevrolet; Uplander; 2009-2008
 GMC; Acadia; 2008-2007; W/Schrader Sensor
 GMC; Envoy; 2009-2006
 GMC; Savana; 2009-2008; W/Schrader Sensor
 GMC; Sierra Series Pickup; 2007; Classic
 GMC; Sierra Series Pickup; 2006-2004
 GMC; Yukon; 2006-2004
 Isuzu; Ascender; 2008-2006
 Pontiac; G5; 2008; W/Schrader Sensor
 Pontiac; G6; 2008; W/Schrader Sensor
 Pontiac; Grand Prix; 2008; Clamp-In Style Only; W/Almm. Valve Stem
 Pontiac; Grand Prix; 2007; W/Schrader Sensor
 Pontiac; Montana; 2009-2008; W/Schrader Sensor
 Pontiac; Solstice; 2010-2008; W/Schrader Sensor
 Pontiac; Torrent; 2009-2007; W/Schrader Sensor
 Saab; 9-7X; 2009-2005
 Saturn; Aura; 2007; W/Schrader Sensor
 Saturn; Outlook; 2008-2007; W/Schrader Sensor
 Saturn; Sky; 2010-2008; W/Schrader Sensor
 Suzuki; XL-7; 2009-2007; W/Schrader Sensor



Numerical Listing

Service Packs

20005



Infiniti; QX56; 2006-2005; W/Steel Wheels
 Infiniti; QX56; 2004
 Nissan; Armada; 2006-2005; W/Steel Wheels
 Nissan; Frontier; 2007-2005; W/Steel Wheels
 Nissan; Pathfinder; 2004; Armada
 Nissan; Pathfinder; 2004; Exc. Armada; Aug. & Newer
 Nissan; Quest; 2006-2005; W/Steel Wheels
 Nissan; Quest; 2004
 Nissan; Titan; 2005; Mar. & Older
 Nissan; Titan; 2004
 Nissan; Xterra; 2006; Submodel X

20006



Chevrolet; Colorado; 2012-2007
 GMC; Canyon; 2012-2007
 Hummer; H3; 2010-2006
 Hummer; H3T; 2010-2009
 Isuzu; I-290; 2008-2007
 Isuzu; I-370; 2008-2007

20007



Infiniti; FX35; 2007; Jun. & Older
 Infiniti; FX35; 2006-2003
 Infiniti; FX45; 2007; Jun. & Older
 Infiniti; FX45; 2006-2003
 Infiniti; G35; 2006-2004
 Infiniti; G35; 2003; Jun. & Newer
 Infiniti; M35; 2007-2006
 Infiniti; M45; 2007-2006
 Infiniti; M45; 2004-2003
 Infiniti; Q45; 2006; Jul. & Older
 Infiniti; Q45; 2005-2003
 Infiniti; QX4; 2003
 Infiniti; QX56; 2007; Mar. & Older
 Infiniti; QX56; 2006-2005; W/Alloy Wheels
 Nissan; 350Z; 2006-2003
 Nissan; Armada; 2008; SE
 Nissan; Armada; 2007
 Nissan; Armada; 2006-2005; W/Alloy Wheels
 Nissan; Frontier; 2008-2005; W/Alloy Wheels
 Nissan; Frontier; 2004-2003
 Nissan; Maxima; 2007; Mar. & Older
 Nissan; Maxima; 2006; Jun. & Newer

20007 - Continued

Nissan; Murano; 2006-2003
 Nissan; Pathfinder; 2006-2005
 Nissan; Pathfinder; 2004; Exc. Armada; Jul. & Older
 Nissan; Pathfinder; 2003
 Nissan; Quest; 2006-2005; W/Alloy Wheels
 Nissan; Sentra; 2007; W/Alloy Wheels
 Nissan; Titan; 2007; Mar. & Older
 Nissan; Titan; 2006
 Nissan; Titan; 2005; Apr. 1 & Newer
 Nissan; Xterra; 2006; Exc. Submodel X
 Nissan; Xterra; 2005-2003

20008



Buick; Allure; 2010-2009
 Buick; Enclave; 2012-2009
 Buick; LaCrosse; 2012-2009
 Buick; Lucerne; 2011-2007
 Buick; Regal; 2012-2011
 Buick; Verano; 2012
 Cadillac; CTS; 2012-2009; OEM Part No. 25920615; Exc. CTS V
 Cadillac; CTS; 2008
 Cadillac; DTS; 2011-2007
 Cadillac; Escalade; 2012-2008
 Cadillac; Escalade; 2007; Snap-In Style Only; Schrader Sensor;
 W/Rubber Valve Stem
 Cadillac; SRX; 2012-2007
 Cadillac; STS; 2011-2010
 Cadillac; STS; 2009; OEM Part No. 25920615; Exc. STS V
 Chevrolet; Avalanche; 2012-2008
 Chevrolet; Avalanche; 2007; Snap-In Style Only; Schrader Sensor;
 W/Rubber Valve Stem
 Chevrolet; Aveo; 2011-2007
 Chevrolet; Camaro; 2012-2010
 Chevrolet; Captiva; 2012
 Chevrolet; Cobalt; 2010
 Chevrolet; Cobalt; 2009-2008; Snap-In Style Only; W/Rubber Valve Stem
 Chevrolet; Cruze; 2012-2011
 Chevrolet; Equinox; 2012-2010
 Chevrolet; Express; 2012-2010
 Chevrolet; HHR; 2011-2010
 Chevrolet; HHR; 2009-2008; Snap-In Style Only; W/Rubber Valve Stem
 Chevrolet; Impala; 2012-2008
 Chevrolet; Impala; 2007; Snap-In Style Only; W/Rubber Valve Stem
 Chevrolet; Malibu; 2012-2009
 Chevrolet; Malibu; 2008; Snap-In Style Only; W/Rubber Valve Stem
 Chevrolet; Monte Carlo; 2007; Snap-In Style Only; W/Rubber Valve Stem
 Chevrolet; Orlando; 2012
 Chevrolet; Silverado Series Pickup; 2012-2008; W/Single Rear Wheels
 Chevrolet; Silverado Series Pickup; 2007; Snap-In Style Only; Schrader Sensor;
 W/Rubber Valve Stem; Exc. Classic
 Chevrolet; Sonic; 2012
 Chevrolet; Suburban; 2012-2008
 Chevrolet; Suburban; 2012; W/Single Rear Wheels
 Chevrolet; Suburban; 2007; Snap-In Style Only; Schrader Sensor;
 W/Rubber Valve Stem
 Chevrolet; Tahoe; 2012-2008
 Chevrolet; Tahoe; 2007; Snap-In Style Only; Schrader Sensor;
 W/Rubber Valve Stem
 Chevrolet; Traverse; 2012-2009
 Chevrolet; Volt; 2012-2011



Numerical Listing

Service Packs

20008 - Continued

Chrysler; 300; 2011
 Chrysler; Town & Country Van; 2011
 Dodge; Challenger; 2011-2010; W/Rubber Stem Snap-in Sensor
 Dodge; Charger; 2011-2010; W/Rubber Stem Snap-in Sensor
 Dodge; Durango; 2011
 Dodge; Grand Caravan; 2011
 Dodge; Ram Series Pickup; 2011-2010; W/Rubber Stem Snap-in Sensor
 GMC; Acadia; 2012-2009
 GMC; Savana; 2012-2010
 GMC; Sierra Series Pickup; 2012-2008; W/Single Rear Wheels
 GMC; Sierra Series Pickup; 2007; Snap-In Style Only; Schrader Sensor;
 W/Rubber Valve Stem; Exc. Classic
 GMC; Terrain; 2012-2010
 GMC; Yukon; 2012-2008
 GMC; Yukon; 2012; W/Single Rear Wheels
 GMC; Yukon; 2007; Snap-In Style Only; Schrader Sensor; W/Rubber Valve Stem
 Hummer; H2; 2010-2008
 Jeep; Grand Cherokee; 2011
 Mitsubishi; Lancer; 2011; W/Alloy Wheels
 Mitsubishi; Outlander; 2011; W/Alloy Wheels
 Pontiac; G3; 2010-2009
 Pontiac; G3 Wave; 2009
 Pontiac; G5; 2010-2009
 Pontiac; G6; 2010-2009
 Pontiac; G8; 2010-2008
 Pontiac; Grand Prix; 2008; Snap-In Style Only; W/Rubber Valve Stem
 Pontiac; Wave; 2008
 Saab; 9-4X; 2012
 Saturn; Astra; 2010-2009
 Saturn; Aura; 2010-2008
 Saturn; Outlook; 2010-2009
 Saturn; VUE; 2010-2008
 Subaru; Forester; 2012-2008
 Subaru; Impreza; 2012-2008
 Subaru; Legacy; 2012-2009
 Subaru; Legacy; 2008; W/18" Wheels
 Subaru; Outback; 2012-2008
 Subaru; Tribeca; 2010-2009
 Subaru; Tribeca; 2008; W/Rubber Stem Snap-in Sensor
 Suzuki; Forenza; 2008-2007
 Suzuki; Reno; 2008-2007

20009



Saab; 9-3; 2012-2003
 Saab; 9-5; 2012-2003
 Saturn; Astra; 2008
 Suzuki; Grand Vitara; 2011-2007
 Suzuki; SX4; 2012-2007
 Suzuki; Verona; 2006-2005
 Suzuki; XL-7; 2006-2005

20010



Mitsubishi; Eclipse; 2007-2006; W/Steel Wheels
 Mitsubishi; Galant; 2009-2007; W/Steel Wheels
 Volvo; S60; 2009-2006
 Volvo; S60; 2005-2004; W/315 MHz Sensor
 Volvo; S80; 2006-2004
 Volvo; V70; 2007-2004; W/315 MHz Sensor
 Volvo; XC70; 2007-2004; W/315 MHz Sensor
 Volvo; XC90; 2009; W/315 MHz Sensor
 Volvo; XC90; 2007-2005; W/315 MHz Sensor
 Volvo; XC90; 2004

20011



Subaru; B9 Tribeca; 2007-2006
 Subaru; Legacy; 2008; W/16" Or 17" Wheels
 Subaru; Legacy; 2007-2004
 Subaru; Outback; 2006-2004
 Subaru; Tribeca; 2008; W/Metal Stem Clamp-in Sensor

20012



Chevrolet; Corvette; 2000-1997
 Chrysler; Prowler; 2001; W/Black Sensor Body
 Plymouth; Prowler; 2001-1999; W/Black Sensor Body
 Plymouth; Prowler; 1997; W/Black Sensor Body

20013



Chrysler; 200; 2012-2011; W/Schrader Sensor
 Chrysler; 300; 2008-2005; W/Schrader Sensor
 Chrysler; Aspen; 2009-2007; W/Schrader Sensor
 Chrysler; Crossfire; 2005; OEM Part No. 5142340AA
 Chrysler; Pacifica; 2008-2006; W/Schrader Sensor
 Chrysler; PT Cruiser; 2010-2008; W/Schrader Sensor
 Chrysler; Sebring; 2010-2007; W/Schrader Sensor
 Chrysler; Town & Country Van; 2009-2006; W/Schrader Sensor
 Dodge; Avenger; 2012; W/Schrader Sensor
 Dodge; Avenger; 2010-2008; W/Schrader Sensor



Numerical Listing

Service Packs

20013 - Continued

Dodge; Caliber; 2011-2007; W/Schrader Sensor
 Dodge; Caravan; 2007-2006; W/Schrader Sensor
 Dodge; Charger; 2008-2006; W/Schrader Sensor
 Dodge; Dakota; 2011-2008
 Dodge; Durango; 2009
 Dodge; Durango; 2008-2007; W/Schrader Sensor
 Dodge; Grand Caravan; 2010-2006; W/Schrader Sensor
 Dodge; Journey; 2011
 Dodge; Journey; 2010-2009; W/Schrader Sensor
 Dodge; Magnum; 2008-2005; W/Schrader Sensor
 Dodge; Nitro; 2011-2009
 Dodge; Nitro; 2008-2007; W/Schrader Sensor
 Dodge; Ram Series Pickup; 2010; 2500; W/Metal Stem Clamp-in Sensor
 Dodge; Ram Series Pickup; 2009-2008; 2500
 Jeep; Commander; 2010-2008
 Jeep; Commander; 2007-2006; W/Schrader Sensor
 Jeep; Compass; 2011-2007; W/Schrader Sensor
 Jeep; Grand Cherokee; 2010-2008
 Jeep; Grand Cherokee; 2007-2005; W/Schrader Sensor
 Jeep; Liberty; 2011-2009
 Jeep; Liberty; 2008-2005; W/Schrader Sensor
 Jeep; Patriot; 2012-2007; W/Schrader Sensor
 Jeep; Wrangler; 2011; W/Schrader Sensor
 Jeep; Wrangler; 2010-2009
 Jeep; Wrangler; 2008-2007; W/Schrader Sensor
 Mitsubishi; Raider; 2009-2008
 Suzuki; Kizashi; 2012-2010; W/Schrader Sensor

20014



Infiniti; EX35; 2010-2008
 Infiniti; FX35; 2010-2008
 Infiniti; FX35; 2007; Jul. & Newer
 Infiniti; FX45; 2008
 Infiniti; FX45; 2007; Jul. & Newer
 Infiniti; FX50; 2010-2009
 Infiniti; G35; 2008-2007
 Infiniti; G37; 2010-2008
 Infiniti; M35; 2010-2008
 Infiniti; M45; 2010-2008
 Infiniti; Q45; 2006; Aug. & Newer
 Infiniti; QX56; 2010-2008
 Infiniti; QX56; 2007; Apr. 1 & Newer
 Nissan; 350Z; 2009-2007
 Nissan; 370Z; 2009
 Nissan; Altima; 2012-2007
 Nissan; Altima; 2006; Oct. 1 & Newer
 Nissan; Armada; 2012-2009
 Nissan; Armada; 2008; LE
 Nissan; Cube; 2012-2011
 Nissan; Cube; 2009
 Nissan; Frontier; 2012-2009
 Nissan; Frontier; 2008; W/Steel Wheels
 Nissan; GT-R; 2012-2011
 Nissan; GT-R; 2009
 Nissan; Juke; 2012-2011
 Nissan; Maxima; 2012-2008
 Nissan; Maxima; 2007; Apr. 1 & Newer
 Nissan; Murano; 2012-2011

20014 - Continued

Nissan; Murano; 2009
 Nissan; Murano; 2007
 Nissan; Pathfinder; 2012-2007
 Nissan; Quest; 2009-2007
 Nissan; Rogue; 2012-2011
 Nissan; Rogue; 2009-2008
 Nissan; Sentra; 2012-2008
 Nissan; Sentra; 2007; W/Steel Wheels
 Nissan; Titan; 2012-2008
 Nissan; Titan; 2007; Apr. 1 & Newer
 Nissan; Versa; 2012-2007
 Nissan; Xterra; 2012-2007
 Suzuki; Equator; 2011-2009

20015



Cadillac; Escalade; 2007; Clamp-In Style Only; TRW Sensor; W/Almmn. Valve Stem
 Chevrolet; Avalanche; 2007; Clamp-In Style Only; TRW Sensor;
 W/Almmn. Valve Stem
 Chevrolet; Silverado Series Pickup; 2007; Clamp-In Style Only; TRW Sensor;
 W/Almmn. Valve Stem; Exc. Classic
 Chevrolet; Suburban; 2007; Clamp-In Style Only; TRW Sensor;
 W/Almmn. Valve Stem
 Chevrolet; Tahoe; 2007; Clamp-In Style Only; TRW Sensor; W/Almmn. Valve Stem
 GMC; Sierra Series Pickup; 2007; Clamp-In Style Only; TRW Sensor;
 W/Almmn. Valve Stem; Exc. Classic
 GMC; Yukon; 2007; Clamp-In Style Only; TRW Sensor; W/Almmn. Valve Stem

20016



Chrysler; 300; 2010-2009
 Dodge; Challenger; 2011-2010; W/Metal Stem Clamp-in Sensor
 Dodge; Challenger; 2009-2008
 Dodge; Charger; 2010; W/Metal Stem Clamp-in Sensor
 Dodge; Charger; 2009
 Mercedes-Benz; C63; 2012-2008
 Mercedes-Benz; C250; 2012
 Mercedes-Benz; C300; 2011-2008
 Mercedes-Benz; C350; 2012-2008
 Mercedes-Benz; C350; 2007; Jun. & Newer
 Mercedes-Benz; CL63; 2012-2010
 Mercedes-Benz; CL65; 2012-2010
 Mercedes-Benz; CL550; 2012-2010
 Mercedes-Benz; CL600; 2012
 Mercedes-Benz; CL600; 2010
 Mercedes-Benz; CLK55; 2006
 Mercedes-Benz; CLK63; 2009-2007
 Mercedes-Benz; CLK350; 2009-2006
 Mercedes-Benz; CLK500; 2006
 Mercedes-Benz; CLK550; 2009-2007
 Mercedes-Benz; CLS63; 2012
 Mercedes-Benz; CLS550; 2012



Numerical Listing

Service Packs

20016 - Continued

Mercedes-Benz; E63; 2011-2010
 Mercedes-Benz; E350; 2012-2010
 Mercedes-Benz; E550; 2011-2010
 Mercedes-Benz; G55; 2011; Mar. & Newer
 Mercedes-Benz; G55; 2010-2008
 Mercedes-Benz; G55; 2007; Mar. & Newer
 Mercedes-Benz; G500; 2008
 Mercedes-Benz; G500; 2007; Mar. & Newer
 Mercedes-Benz; G500; 2011; Mar. & Newer
 Mercedes-Benz; G500; 2010-2009
 Mercedes-Benz; GL350; 2011; Mar. & Newer
 Mercedes-Benz; GL350; 2010
 Mercedes-Benz; GL450; 2011; Mar. & Newer
 Mercedes-Benz; GL450; 2010
 Mercedes-Benz; GL550; 2011; Mar. & Newer
 Mercedes-Benz; GL550; 2010
 Mercedes-Benz; GLK350; 2012
 Mercedes-Benz; GLK350; 2011; Mar. & Newer
 Mercedes-Benz; GLK350; 2010
 Mercedes-Benz; ML63; 2011; Mar. & Newer
 Mercedes-Benz; ML63; 2010
 Mercedes-Benz; ML350; 2012
 Mercedes-Benz; ML350; 2011; Mar. & Newer
 Mercedes-Benz; ML350; 2010
 Mercedes-Benz; ML450; 2011; Mar. & Newer
 Mercedes-Benz; ML450; 2010
 Mercedes-Benz; ML550; 2011; Mar. & Newer
 Mercedes-Benz; ML550; 2010
 Mercedes-Benz; R350; 2012
 Mercedes-Benz; R350; 2011; Mar. & Newer
 Mercedes-Benz; R350; 2010
 Mercedes-Benz; S63; 2011
 Mercedes-Benz; S65; 2011
 Mercedes-Benz; S400; 2011
 Mercedes-Benz; S550; 2011
 Mercedes-Benz; S600; 2011
 Mercedes-Benz; SL63; 2012
 Mercedes-Benz; SL550; 2012
 Mercedes-Benz; SLK55; 2010-2008
 Mercedes-Benz; SLK55; 2007; May & Newer
 Mercedes-Benz; SLK250; 2012
 Mercedes-Benz; SLK280; 2008
 Mercedes-Benz; SLK280; 2007; May & Newer
 Mercedes-Benz; SLK300; 2011-2009
 Mercedes-Benz; SLK350; 2012-2008
 Mercedes-Benz; SLK350; 2007; May & Newer
 Mercedes-Benz; SLS; 2012-2011
 Smart; Fortwo; 2012-2008

20017

Audi; A3; 2012-2008
 Audi; A4; 2012-2009
 Audi; A5; 2012-2008
 Audi; Q5; 2012-2009
 Audi; S4; 2011-2010
 Audi; S5; 2012-2008
 Audi; TT; 2011-2008



20017 - Continued

Volkswagen; Beetle; 2010-2008
 Volkswagen; CC; 2012-2009
 Volkswagen; Eos; 2012-2007
 Volkswagen; GLI; 2009-2008
 Volkswagen; Golf; 2010-2008
 Volkswagen; Golf; 2006; GTI
 Volkswagen; GTI; 2010-2008
 Volkswagen; GTI; 2007-2006; W/16" Or 17" Wheels
 Volkswagen; Jetta; 2010-2006
 Volkswagen; Passat; 2010-2009
 Volkswagen; Passat; 2008-2006; W/16" Or 17" Wheels
 Volkswagen; R32; 2008
 Volkswagen; Rabbit; 2009-2008
 Volkswagen; Rabbit; 2007-2006; W/15" Wheels
 Volkswagen; Tiguan; 2011-2009

20018



Chrysler; 300; 2012
 Chrysler; Town & Country Van; 2012
 Dodge; Challenger; 2012
 Dodge; Charger; 2012
 Dodge; Durango; 2012
 Dodge; Grand Caravan; 2012
 Dodge; Journey; 2012
 Dodge; Ram Series Pickup; 2012
 Fiat; 500; 2012
 Ford; E450 Super Duty; 2010
 Ford; E Series Van; 2012
 Ford; E Series Van; 2010; W/Steel Wheels
 Ford; Edge; 2012
 Ford; Escape; 2012
 Ford; Escape; 2010-2009
 Ford; Expedition; 2012
 Ford; Explorer; 2012
 Ford; F Series Pickup; 2012
 Ford; F Series Pickup; 2010-2009
 Ford; Fiesta; 2012-2011
 Ford; Flex; 2012
 Ford; Focus; 2012
 Ford; Focus; 2010
 Ford; Fusion; 2012
 Ford; Fusion; 2010
 Ford; Mustang; 2012-2010
 Ford; Super Duty Pickup; 2012
 Ford; Super Duty Van; 2010; W/Steel Wheels
 Ford; Taurus; 2012-2011
 Ford; Taurus; 2010; May & Newer
 Ford; Transit Connect; 2012
 Ford; Transit Connect; 2010
 Jeep; Grand Cherokee; 2012
 Jeep; Liberty; 2012
 Jeep; Wrangler; 2012
 Lincoln; MKS; 2012
 Lincoln; MKT; 2012
 Lincoln; MKX; 2012
 Lincoln; MKZ; 2012
 Lincoln; MKZ; 2010



Numerical Listing

Service Packs

20018 - Continued

Lincoln; Navigator; 2012
 Mazda; Tribute; 2010-2009
 Mercury; Mariner; 2010-2009
 Mercury; Milan; 2010

20019



Acura; CSX; 2009-2008
 Acura; TL; 2012-2009
 Honda; Civic; 2012-2008
 Honda; Element; 2011-2009
 Honda; Fit; 2011-2009
 Honda; Insight; 2011-2010
 Honda; Odyssey; 2011

20020



Chrysler; 200; 2012-2011; W/Schrader Sensor
 Chrysler; 300; 2010-2009
 Chrysler; 300; 2008-2005; W/Schrader Sensor
 Chrysler; Aspen; 2009-2007; W/Schrader Sensor
 Chrysler; Crossfire; 2005; OEM Part No. 5142340AA
 Chrysler; Pacifica; 2008-2006; W/Schrader Sensor
 Chrysler; PT Cruiser; 2010-2008; W/Schrader Sensor
 Chrysler; Sebring; 2010-2007; W/Schrader Sensor
 Chrysler; Town & Country Van; 2009-2006; W/Schrader Sensor
 Dodge; Avenger; 2012; W/Schrader Sensor
 Dodge; Avenger; 2010-2008; W/Schrader Sensor
 Dodge; Caliber; 2011-2007; W/Schrader Sensor
 Dodge; Caravan; 2007-2006; W/Schrader Sensor
 Dodge; Challenger; 2011-2010; W/Metal Stem Clamp-in Sensor
 Dodge; Challenger; 2009-2008
 Dodge; Charger; 2010; W/Metal Stem Clamp-in Sensor
 Dodge; Charger; 2009
 Dodge; Charger; 2008-2006; W/Schrader Sensor
 Dodge; Dakota; 2011-2008
 Dodge; Durango; 2009
 Dodge; Durango; 2008-2007; W/Schrader Sensor
 Dodge; Grand Caravan; 2010-2006; W/Schrader Sensor
 Dodge; Journey; 2011
 Dodge; Journey; 2010-2009; W/Schrader Sensor
 Dodge; Magnum; 2008-2005; W/Schrader Sensor
 Dodge; Nitro; 2011-2009
 Dodge; Nitro; 2008-2007; W/Schrader Sensor
 Dodge; Ram Series Pickup; 2010; 2500; W/Metal Stem Clamp-in Sensor
 Dodge; Ram Series Pickup; 2009-2008; 2500
 Jeep; Commander; 2010-2008
 Jeep; Commander; 2007-2006; W/Schrader Sensor
 Jeep; Compass; 2011-2007; W/Schrader Sensor
 Jeep; Grand Cherokee; 2010-2008
 Jeep; Grand Cherokee; 2007-2005; W/Schrader Sensor
 Jeep; Liberty; 2011-2009
 Jeep; Liberty; 2008-2005; W/Schrader Sensor
 Jeep; Patriot; 2011-2007; W/Schrader Sensor
 Jeep; Wrangler; 2011; W/Schrader Sensor

20020 - Continued

Jeep; Wrangler; 2010-2009
 Jeep; Wrangler; 2008-2007; W/Schrader Sensor
 Mercedes-Benz; C63; 2012-2008
 Mercedes-Benz; C250; 2012
 Mercedes-Benz; C300; 2011-2008
 Mercedes-Benz; C350; 2012-2008
 Mercedes-Benz; C350; 2007; Jun. & Newer
 Mercedes-Benz; CL63; 2012-2010
 Mercedes-Benz; CL65; 2012-2010
 Mercedes-Benz; CL550; 2012-2010
 Mercedes-Benz; CL600; 2012
 Mercedes-Benz; CL600; 2010
 Mercedes-Benz; CLK55; 2006
 Mercedes-Benz; CLK63; 2009-2007
 Mercedes-Benz; CLK350; 2009-2006
 Mercedes-Benz; CLK500; 2006
 Mercedes-Benz; CLK550; 2009-2007
 Mercedes-Benz; CLS63; 2012
 Mercedes-Benz; CLS550; 2012
 Mercedes-Benz; E63; 2011-2010
 Mercedes-Benz; E350; 2012-2010
 Mercedes-Benz; E550; 2011-2010
 Mercedes-Benz; G55; 2011; Mar. & Newer
 Mercedes-Benz; G55; 2010-2008
 Mercedes-Benz; G55; 2007; Mar. & Newer
 Mercedes-Benz; G500; 2008
 Mercedes-Benz; G500; 2007; Mar. & Newer
 Mercedes-Benz; G550; 2011; Mar. & Newer
 Mercedes-Benz; GL350; 2011; Mar. & Newer
 Mercedes-Benz; GL350; 2010
 Mercedes-Benz; GL450; 2011; Mar. & Newer
 Mercedes-Benz; GL450; 2010
 Mercedes-Benz; GL550; 2011; Mar. & Newer
 Mercedes-Benz; GL550; 2010
 Mercedes-Benz; GLK350; 2012
 Mercedes-Benz; GLK350; 2011; Mar. & Newer
 Mercedes-Benz; GLK350; 2010
 Mercedes-Benz; ML63; 2011; Mar. & Newer
 Mercedes-Benz; ML63; 2010
 Mercedes-Benz; ML350; 2012
 Mercedes-Benz; ML350; 2011; Mar. & Newer
 Mercedes-Benz; ML350; 2010
 Mercedes-Benz; ML450; 2011; Mar. & Newer
 Mercedes-Benz; ML450; 2010
 Mercedes-Benz; ML550; 2011; Mar. & Newer
 Mercedes-Benz; ML550; 2010
 Mercedes-Benz; R350; 2012
 Mercedes-Benz; R350; 2011; Mar. & Newer
 Mercedes-Benz; R350; 2010
 Mercedes-Benz; S63; 2011
 Mercedes-Benz; S65; 2011
 Mercedes-Benz; S400; 2011
 Mercedes-Benz; S550; 2011
 Mercedes-Benz; S600; 2011
 Mercedes-Benz; SL63; 2012
 Mercedes-Benz; SL550; 2012
 Mercedes-Benz; SLK55; 2010-2008
 Mercedes-Benz; SLK55; 2007; May & Newer
 Mercedes-Benz; SLK250; 2012
 Mercedes-Benz; SLK280; 2008
 Mercedes-Benz; SLK280; 2007; May & Newer
 Mercedes-Benz; SLK300; 2011-2009
 Mercedes-Benz; SLK350; 2012-2008
 Mercedes-Benz; SLK350; 2007; May & Newer



Numerical Listing

Service Packs

20020 - Continued

Mercedes-Benz; SLS; 2012-2011
 Mitsubishi; Raider; 2009-2008
 Smart; Fortwo; 2012-2008
 Suzuki; Kizashi; 2012-2010; W/Schrader Sensor

20021



Acura; MDX; 2006-2004
 Acura; RL; 2011-2005
 Acura; TL; 2008-2005
 Dodge; Sprinter; 2009-2007
 Honda; Element; 2008-2007
 Honda; Odyssey; 2010-2009
 Honda; Odyssey; 2007
 Honda; Odyssey; 2006-2005; Touring
 Honda; Pilot; 2008-2005
 Honda; Ridgeline; 2011-2006
 Hyundai; Azera; 2011-2006
 Hyundai; Elantra; 2010-2008
 Hyundai; Entourage; 2009-2007
 Hyundai; Santa Fe; 2010-2007
 Hyundai; Sonata; 2008-2007
 Hyundai; Tiburon; 2008-2007
 Hyundai; Tucson; 2009-2006
 Hyundai; Veracruz; 2011-2007
 Kia; Amanti; 2009-2007
 Kia; Magentis; 2010-2008
 Kia; Optima; 2010-2006
 Kia; Rondo; 2010-2007
 Kia; Sedona; 2012-2006
 Kia; Sorento; 2009-2007
 Kia; Sportage; 2008-2006
 Kia; Sportage; 2005; Jun. 15, 2005 & Newer
 Mercedes-Benz; CL63; 2009-2007
 Mercedes-Benz; CL65; 2009-2008
 Mercedes-Benz; CL550; 2009-2007
 Mercedes-Benz; CL600; 2009-2007
 Mercedes-Benz; CLS55; 2006
 Mercedes-Benz; CLS63; 2011-2007
 Mercedes-Benz; CLS500; 2006
 Mercedes-Benz; CLS550; 2011-2007
 Mercedes-Benz; E55; 2006
 Mercedes-Benz; E63; 2009-2007
 Mercedes-Benz; E320; 2009-2006
 Mercedes-Benz; E350; 2009-2006
 Mercedes-Benz; E500; 2006
 Mercedes-Benz; E550; 2009-2007
 Mercedes-Benz; GL320; 2009-2007
 Mercedes-Benz; GL450; 2009-2007
 Mercedes-Benz; GL550; 2009-2008
 Mercedes-Benz; ML63; 2009-2007
 Mercedes-Benz; ML320; 2009-2007
 Mercedes-Benz; ML350; 2009-2006
 Mercedes-Benz; ML500; 2007-2006
 Mercedes-Benz; ML550; 2009-2008
 Mercedes-Benz; R63; 2007
 Mercedes-Benz; R320; 2009-2007
 Mercedes-Benz; R350; 2009-2006
 Mercedes-Benz; R500; 2007-2006

20021 - Continued

Mercedes-Benz; S63; 2010-2007
 Mercedes-Benz; S65; 2010-2007
 Mercedes-Benz; S400; 2010
 Mercedes-Benz; S550; 2010-2007
 Mercedes-Benz; S600; 2010-2007
 Mercedes-Benz; SL55; 2008-2006
 Mercedes-Benz; SL63; 2009
 Mercedes-Benz; SL65; 2009-2006
 Mercedes-Benz; SL500; 2006
 Mercedes-Benz; SL550; 2009-2007
 Mercedes-Benz; SL600; 2009-2006
 Mercedes-Benz; SLR McLaren; 2009-2008

20022



Hyundai; Accent; 2011-2008
 Hyundai; Equus; 2012-2011
 Hyundai; Genesis; 2010-2009
 Hyundai; Sonata; 2010-2009
 Hyundai; Tucson; 2011-2010
 Kia; Borrego; 2011-2009
 Kia; Rio; 2011-2007
 Kia; Spectra; 2009-2006
 Kia; Sportage; 2011-2009
 Toyota; Sequoia; 2011-2008
 Toyota; Sienna; 2011-2007
 Toyota; Tundra; 2012-2007
 Toyota; Tundra; 2006; Nov. 1 & Newer

20023



Audi; A4; 2008-2002
 Audi; A6; 2011-2005
 Audi; A8; 2010-2001
 Audi; Allroad Quattro; 2005-2001
 Audi; Q7; 2012-2007
 Audi; R8; 2010-2008
 Audi; RS4; 2008-2007
 Audi; S4; 2009-2004
 Audi; S6; 2011-2007
 Audi; S8; 2009-2007
 Audi; S8; 2003-2001
 Bentley; Continental; 2010-2003
 BMW; 128i; 2012-2008
 BMW; 135i; 2012
 BMW; 135i; 2010-2008
 BMW; 320i; 2005-2001
 BMW; 323Ci; 2000
 BMW; 323i; 2010-2007
 BMW; 323i; 2006; Jun. & Newer



Numerical Listing

Service Packs

20023 - Continued

BMW; 323i; 2000
 BMW; 325Ci; 2006-2001
 BMW; 325i; 2006-2001
 BMW; 325Xi; 2006-2001
 BMW; 328Ci; 2000
 BMW; 328i; 2012-2007
 BMW; 328i; 2000
 BMW; 328Xi; 2008-2007
 BMW; 330Ci; 2006-2001
 BMW; 330i; 2006-2001
 BMW; 330Xi; 2006-2001
 BMW; 335D; 2012-2009
 BMW; 335i; 2012-2007
 BMW; 335IS; 2012
 BMW; 335Xi; 2008-2007
 BMW; 525i; 2007-2001
 BMW; 525Xi; 2007-2006
 BMW; 528i; 2012
 BMW; 528i; 2010-2008
 BMW; 528i; 2000-1997
 BMW; 528Xi; 2008
 BMW; 530i; 2007-2001
 BMW; 530Xi; 2007-2006
 BMW; 535i; 2012-2008
 BMW; 535Xi; 2008
 BMW; 540i; 2003-1997
 BMW; 545i; 2005-2004
 BMW; 550i; 2012-2006
 BMW; 640i; 2012
 BMW; 645Ci; 2005-2004
 BMW; 650i; 2012
 BMW; 650i; 2010-2006
 BMW; 740i; 2012-2011
 BMW; 740i; 2001-1997
 BMW; 740iL; 2001-1997
 BMW; 740Li; 2012-2011
 BMW; 745i; 2005-2002
 BMW; 745Li; 2005-2002
 BMW; 750i; 2012-2006
 BMW; 750iL; 2001-1997
 BMW; 750iL; 2012-2006
 BMW; 760i; 2006-2004
 BMW; 760iL; 2010
 BMW; 760iL; 2008-2003
 BMW; Alpina B7; 2011
 BMW; Alpina B7; 2008-2007
 BMW; M1; 2012
 BMW; M3; 2010-2008
 BMW; M3; 2006-2001
 BMW; M5; 2010-2006
 BMW; M5; 2003-2000
 BMW; M6; 2010-2006
 BMW; X1; 2012
 BMW; X3; 2012
 BMW; X3; 2010-2006
 BMW; X5; 2012-2000
 BMW; X6; 2012
 BMW; X6; 2010-2008
 BMW; Z3; 2002-2000
 BMW; Z4; 2012-2003
 BMW; Z8; 2003-2000
 Bugatti; Veyron; 2006
 Ferrari; 550 Maranello; 2002-2001
 Ferrari; 575M Maranello; 2005-2002
 Ferrari; 612 Scaglietti; 2009-2004

20023 - Continued

Ferrari; Enzo; 2004-2003
 Ferrari; F430; 2009-2005
 Land Rover; LR3; 2005
 Land Rover; Range Rover; 2005-2002
 Maserati; Coupe; 2006-2004
 Maserati; GranSport; 2006-2004
 Maserati; MC12; 2006
 Maserati; Quattroporte; 2006-2004
 Maserati; Spyder; 2006-2004
 Mercedes-Benz; CL55; 2006-2001
 Mercedes-Benz; CL65; 2006-2005
 Mercedes-Benz; CL500; 2006-2000
 Mercedes-Benz; CL600; 2006-2001
 Mercedes-Benz; E55; 2005-2000
 Mercedes-Benz; E55; 1999; Jul. & Newer
 Mercedes-Benz; E320; 2005-2001
 Mercedes-Benz; E430; 2002-2001
 Mercedes-Benz; E500; 2005-2003
 Mercedes-Benz; R550; 2008
 Mercedes-Benz; S55; 2006-2001
 Mercedes-Benz; S65; 2006
 Mercedes-Benz; S350; 2006
 Mercedes-Benz; S430; 2006-2000
 Mercedes-Benz; S500; 2006-2000
 Mercedes-Benz; S600; 2006-2001
 Mercedes-Benz; SL55; 2005-2003
 Mercedes-Benz; SL65; 2005
 Mercedes-Benz; SL500; 2005-2001
 Mercedes-Benz; SL600; 2005-2004
 Mercedes-Benz; SL600; 2002-2001
 Mercedes-Benz; SLR McLaren; 2007-2004
 Mini; Cooper; 2012
 Mini; Cooper; 2010-2008
 Porsche; 911; 2011-2005
 Porsche; Boxster; 2011-2005
 Porsche; Carrera GT; 2006-2004
 Porsche; Cayenne; 2010-2008
 Porsche; Cayenne; 2006-2003
 Porsche; Cayman; 2011-2006
 Porsche; Panamera; 2010
 Rolls-Royce; Phantom; 2010-2007
 Volkswagen; Phaeton; 2006-2004; W/315 MHz Sensor
 Volkswagen; Touareg; 2007-2004
 Volkswagen; Touareg 2; 2011; W/315 MHz Sensor
 Volkswagen; Touareg 2; 2010-2008

20030



Buick; Allure; 2008-2007; W/Siemens Sensor
 Buick; Enclave; 2008; W/Siemens Sensor
 Buick; LaCrosse; 2008-2007; W/Siemens Sensor
 Chevrolet; Equinox; 2009-2007; W/Siemens Sensor
 Chevrolet; Express; 2009-2008; W/Siemens Sensor
 Chrysler; 300; 2008-2005; W/Siemens Sensor
 Chrysler; 300M; 2004-2002; W/Siemens Sensor
 Chrysler; Aspen; 2009-2007; W/Siemens Sensor
 Chrysler; Concorde; 2004-2002; W/Siemens Sensor
 Chrysler; Crossfire; 2008-2006; W/Siemens Sensor



Numerical Listing

Service Packs

20030 - Continued

Chrysler; Crossfire; 2004; W/Siemens Sensor
 Chrysler; Intrepid; 2004-2002; W/Siemens Sensor
 Chrysler; Pacifica; 2008-2006; W/Siemens Sensor
 Chrysler; Pacifica; 2005
 Chrysler; Pacifica; 2004; OEM Part No. 04727392AD
 Chrysler; Prowler; 2002; W/Siemens Sensor
 Chrysler; PT Cruiser; 2010-2008; W/Siemens Sensor
 Chrysler; Sebring; 2009-2007; W/Siemens Sensor
 Chrysler; Town & Country Van; 2009-2006; W/Siemens Sensor
 Chrysler; Town & Country Van; 2005-2004
 Dodge; Avenger; 2009-2008; W/Siemens Sensor
 Dodge; Caliber; 2010-2007; W/Siemens Sensor
 Dodge; Caravan; 2007-2006; W/Siemens Sensor
 Dodge; Caravan; 2005-2004
 Dodge; Charger; 2008-2006; W/Siemens Sensor
 Dodge; Durango; 2008-2007; W/Siemens Sensor
 Dodge; Grand Caravan; 2010-2006; W/Siemens Sensor
 Dodge; Grand Caravan; 2005-2004
 Dodge; Journey; 2010-2009; W/Siemens Sensor
 Dodge; Magnum; 2008-2005; W/Siemens Sensor
 Dodge; Nitro; 2008-2007; W/Siemens Sensor
 GMC; Acadia; 2008-2007; W/Siemens Sensor
 GMC; Savana; 2009-2008; W/Siemens Sensor
 Jaguar; S-Type; 2008
 Jaguar; Super V8; 2009-2005
 Jaguar; Vanden Plas; 2009-2004
 Jaguar; X-Type; 2008
 Jaguar; XF; 2012-2009
 Jaguar; XFR; 2011-2010
 Jaguar; XJ; 2012-2010
 Jaguar; XJ8; 2009-2004
 Jaguar; XJR; 2009-2004
 Jaguar; XK; 2012-2007
 Jaguar; XKR; 2011-2007
 Jeep; Commander; 2007-2006; W/Siemens Sensor
 Jeep; Compass; 2010-2007; W/Siemens Sensor
 Jeep; Grand Cherokee; 2007-2005; W/Siemens Sensor
 Jeep; Liberty; 2008-2005; W/Siemens Sensor
 Jeep; Patriot; 2010-2007; W/Siemens Sensor
 Jeep; Wrangler; 2008-2007; W/Siemens Sensor
 Land Rover; LR2; 2011-2008
 Land Rover; LR3; 2009-2006
 Land Rover; LR4; 2011-2010
 Land Rover; Range Rover; 2011-2006
 Mazda; 2; 2011
 Mazda; 3; 2011-2004
 Mazda; 5; 2010-2006
 Mazda; 6; 2011-2008
 Mazda; CX-7; 2011-2007
 Mazda; CX-9; 2011-2007
 Mazda; MX-5 Miata; 2011-2006
 Mazda; RX-8; 2011-2004
 Mazda; Tribute; 2011
 Mitsubishi; Lancer; 2011; W/Steel Wheels
 Mitsubishi; Lancer; 2010-2008
 Mitsubishi; Outlander; 2011; W/Steel Wheels
 Mitsubishi; Outlander; 2010-2007
 Pontiac; G5; 2008; W/Siemens Sensor
 Pontiac; G6; 2008; W/Siemens Sensor
 Pontiac; Grand Prix; 2007; W/Siemens Sensor
 Pontiac; Montana; 2009-2008; W/Siemens Sensor
 Pontiac; Solstice; 2010-2008; W/Siemens Sensor
 Pontiac; Torrent; 2009-2007; W/Siemens Sensor
 Saturn; Aura; 2007; W/Siemens Sensor
 Saturn; Outlook; 2008-2007; W/Siemens Sensor

20030 - Continued

Saturn; Sky; 2010-2008; W/Siemens Sensor
 Suzuki; Kizashi; 2012-2010; W/Siemens Sensor
 Suzuki; XL-7; 2009-2007; W/Siemens Sensor
 Volvo; C30; 2011-2007
 Volvo; C70; 2012-2008
 Volvo; S40; 2011-2008
 Volvo; S60; 2012-2011
 Volvo; S80; 2011-2007
 Volvo; V50; 2011-2008
 Volvo; V70; 2010-2008
 Volvo; XC60; 2011-2010
 Volvo; XC70; 2011-2008
 Volvo; XC90; 2011-2010
 Volvo; XC90; 2008

20031



Lexus; GS300; 2006
 Lexus; GS430; 2006; Jun. & Older
 Lexus; GS430; 2005
 Lexus; GX470; 2006; Jan. 31 & Older
 Lexus; GX470; 2005-2004
 Lexus; IS250; 2006; Mar. & Older
 Lexus; IS350; 2006; Mar. & Older
 Lexus; LX470; 2006; Jul. & Older
 Lexus; LX470; 2005
 Lexus; RX330; 2006; Jan. 31 & Older
 Toyota; 4 Runner; 2006; May & Older
 Toyota; 4 Runner; 2005-2003
 Toyota; Land Cruiser; 2006; Mar. & Older
 Toyota; Land Cruiser; 2005; May & Newer
 Toyota; Sequoia; 2007-2005
 Toyota; Tacoma; 2006; Jul. & Older
 Toyota; Tacoma; 2005
 Toyota; Tundra; 2006; Oct. 31 & Older
 Toyota; Tundra; 2005

20032



Honda; Accord; 2011-2010; Exc. Crosstour
 Honda; Accord; 2009-2008
 Honda; CR-V; 2011-2007
 Honda; Fit; 2008
 Honda; Pilot; 2011-2010; Exc. LX
 Honda; Pilot; 2009; W/Alloy Wheels
 Honda; S2000; 2009-2008
 Lexus; CT200h; 2011
 Lexus; ES350; 2011-2007
 Lexus; GS350; 2011-2007
 Lexus; GS430; 2007
 Lexus; GS430; 2006; Jul. & Newer
 Lexus; GS450h; 2011-2007



Numerical Listing

Service Packs

20032 - Continued

Lexus; GS460; 2011-2008
 Lexus; GX460; 2011-2010
 Lexus; GX470; 2009-2007
 Lexus; GX470; 2006; Feb. & Newer
 Lexus; HS250h; 2011-2010
 Lexus; IS250; 2011-2007
 Lexus; IS250; 2006; Apr. 1 & Newer
 Lexus; IS350; 2011-2007
 Lexus; IS350; 2006; Apr. 1 & Newer
 Lexus; IS F; 2011-2008
 Lexus; LFA; 2012-2011
 Lexus; LS460; 2011-2007
 Lexus; LS600h; 2011-2008
 Lexus; LX470; 2007
 Lexus; LX470; 2006; Aug. & Newer
 Lexus; LX570; 2011-2008
 Lexus; RX330; 2006; Feb. & Newer
 Lexus; RX350; 2011-2007
 Lexus; RX400h; 2009-2007
 Lexus; RX450h; 2011-2010
 Lexus; SC430; 2010-2007
 Lexus; SC430; 2006; Aug. & Newer
 Pontiac; Vibe; 2010-2008
 Scion; iQ; 2012-2011
 Scion; TC; 2012-2007
 Scion; TC; 2006; May & Newer
 Scion; XB; 2012-2008
 Scion; XD; 2011-2008
 Toyota; 4 Runner; 2011-2007
 Toyota; 4 Runner; 2006; Jun. & Newer
 Toyota; Avalon; 2011-2007
 Toyota; Avalon; 2006; Aug. & Newer
 Toyota; Camry; 2011-2007
 Toyota; Corolla; 2011-2008
 Toyota; Corolla; 2007; Jun. & Newer
 Toyota; FJ Cruiser; 2011-2008
 Toyota; Highlander; 2012-2008
 Toyota; Highlander; 2007; May & Newer
 Toyota; Land Cruiser; 2011-2007
 Toyota; Land Cruiser; 2006; Apr. 1 & Newer
 Toyota; Matrix; 2011-2008
 Toyota; Matrix; 2007; Jun. & Newer
 Toyota; Prius; 2012-2006
 Toyota; RAV4; 2011-2006
 Toyota; Solara; 2008-2007
 Toyota; Solara; 2006; May & Newer
 Toyota; Tacoma; 2012-2007
 Toyota; Tacoma; 2006; Aug. & Newer
 Toyota; Venza; 2011-2009
 Toyota; Yaris; 2012-2008
 Toyota; Yaris; 2007; Aug. & Newer

20035



Honda; Pilot; 2005; LX; W/Long Stem Valve
 Honda; Ridgeline; 2008-2006; RT

20036



Acura; MDX; 2006-2004
 Acura; RL; 2011-2005
 Acura; TL; 2008-2005
 Dodge; Sprinter; 2009-2007
 Honda; Element; 2008-2007
 Honda; Odyssey; 2010-2009
 Honda; Odyssey; 2007
 Honda; Odyssey; 2006-2005; Touring
 Honda; Pilot; 2008-2006
 Honda; Pilot; 2005; EX
 Honda; Pilot; 2005; LX; W/Short Stem Valve
 Honda; Ridgeline; 2011-2010; RT
 Honda; Ridgeline; 2009
 Honda; Ridgeline; 2008-2007; RTL, RTS, RTX
 Honda; Ridgeline; 2006; RTL, RTS
 Hyundai; Azera; 2011-2006
 Hyundai; Elantra; 2010-2008
 Hyundai; Entourage; 2009-2007
 Hyundai; Santa Fe; 2010-2007
 Hyundai; Sonata; 2008-2007
 Hyundai; Tiburon; 2008-2007
 Hyundai; Tucson; 2009-2006
 Hyundai; Veracruz; 2011-2007
 Kia; Amanti; 2009-2007
 Kia; Magentis; 2010-2008
 Kia; Optima; 2010-2006
 Kia; Rondo; 2010-2007
 Kia; Sedona; 2012-2006
 Kia; Sorento; 2009-2007
 Kia; Sportage; 2008-2006
 Kia; Sportage; 2005; Jun. 15, 2005 & Newer
 Mercedes-Benz; CL63; 2009-2007
 Mercedes-Benz; CL65; 2009-2008
 Mercedes-Benz; CL550; 2009-2007
 Mercedes-Benz; CL600; 2009-2007
 Mercedes-Benz; CLS55; 2006
 Mercedes-Benz; CLS63; 2011-2007
 Mercedes-Benz; CLS500; 2006
 Mercedes-Benz; CLS550; 2011-2007
 Mercedes-Benz; E55; 2006
 Mercedes-Benz; E63; 2009-2007
 Mercedes-Benz; E320; 2009-2006
 Mercedes-Benz; E350; 2009-2006
 Mercedes-Benz; E500; 2006
 Mercedes-Benz; E550; 2009-2007
 Mercedes-Benz; GL320; 2009-2007
 Mercedes-Benz; GL450; 2009-2007
 Mercedes-Benz; GL550; 2009-2008
 Mercedes-Benz; ML63; 2009-2007
 Mercedes-Benz; ML320; 2009-2007
 Mercedes-Benz; ML350; 2009-2006
 Mercedes-Benz; ML500; 2007-2006
 Mercedes-Benz; ML550; 2009-2008
 Mercedes-Benz; R63; 2007
 Mercedes-Benz; R320; 2009-2007
 Mercedes-Benz; R350; 2009-2006
 Mercedes-Benz; R500; 2007-2006
 Mercedes-Benz; S63; 2010-2007



Numerical Listing

Service Packs

20036 - Continued

Mercedes-Benz; S65; 2010-2007
 Mercedes-Benz; S400; 2010
 Mercedes-Benz; S550; 2010-2007
 Mercedes-Benz; S600; 2010-2007
 Mercedes-Benz; SL55; 2008-2006
 Mercedes-Benz; SL63; 2009
 Mercedes-Benz; SL65; 2009-2006
 Mercedes-Benz; SL500; 2006
 Mercedes-Benz; SL550; 2009-2007
 Mercedes-Benz; SL600; 2009-2006
 Mercedes-Benz; SLR McLaren; 2009-2008

20037 (W/43mm Silver Insert)



Audi; A4; 2008-2002
 Audi; A6; 2011-2005
 Audi; A8; 2010-2001
 Audi; Allroad Quattro; 2005-2001
 Audi; Q7; 2012-2007
 Audi; R8; 2012-2008
 Audi; RS4; 2008-2007
 Audi; S4; 2009-2004
 Audi; S6; 2011-2007
 Audi; S8; 2009-2007
 Audi; S8; 2003-2001
 Bentley; Continental; 2010-2003
 BMW; 128i; 2012-2008
 BMW; 135i; 2012
 BMW; 135i; 2010-2008
 BMW; 320i; 2005-2001
 BMW; 323Ci; 2000
 BMW; 323i; 2010-2007
 BMW; 323i; 2006; Jun. & Newer
 BMW; 323i; 2000
 BMW; 325Ci; 2006-2001
 BMW; 325i; 2006-2001
 BMW; 325Xi; 2006-2001
 BMW; 328Ci; 2000
 BMW; 328i; 2012-2007
 BMW; 328i; 2000
 BMW; 328Xi; 2008-2007
 BMW; 330Ci; 2006-2001
 BMW; 330i; 2006-2001
 BMW; 330Xi; 2006-2001
 BMW; 335D; 2012-2009
 BMW; 335i; 2012-2007
 BMW; 335iS; 2012
 BMW; 335Xi; 2008-2007
 BMW; 525i; 2007-2001
 BMW; 525Xi; 2007-2006
 BMW; 528i; 2012
 BMW; 528i; 2010-2008
 BMW; 528i; 2000-1997
 BMW; 528Xi; 2008
 BMW; 530i; 2007-2001
 BMW; 530Xi; 2007-2006
 BMW; 535i; 2012-2008

20037 - Continued

BMW; 535Xi; 2008
 BMW; 540i; 2003-1997
 BMW; 545i; 2005-2004
 BMW; 550i; 2012-2006
 BMW; 640i; 2012
 BMW; 645Ci; 2005-2004
 BMW; 650i; 2012
 BMW; 650i; 2010-2006
 BMW; 740i; 2012-2011
 BMW; 740i; 2001-1997
 BMW; 740iL; 2001-1997
 BMW; 740Li; 2012-2011
 BMW; 745i; 2005-2002
 BMW; 745Li; 2005-2002
 BMW; 750i; 2012-2006
 BMW; 750iL; 2001-1997
 BMW; 750Li; 2012-2006
 BMW; 760i; 2006-2004
 BMW; 760Li; 2010
 BMW; 760Li; 2008-2003
 BMW; Alpina B7; 2011
 BMW; Alpina B7; 2008-2007
 BMW; M1; 2012
 BMW; M3; 2010-2008
 BMW; M3; 2006-2001
 BMW; M5; 2010-2006
 BMW; M5; 2003-2000
 BMW; M6; 2010-2006
 BMW; X1; 2012
 BMW; X3; 2012
 BMW; X3; 2010-2006
 BMW; X5; 2012-2000
 BMW; X6; 2012
 BMW; X6; 2010-2008
 BMW; Z3; 2002-2000
 BMW; Z4; 2012-2003
 BMW; Z8; 2003-2000
 Bugatti; Veyron; 2006
 Ferrari; 550 Maranello; 2002-2001
 Ferrari; 575M Maranello; 2005-2002
 Ferrari; 612 Scaglietti; 2009-2004
 Ferrari; Enzo; 2004-2003
 Ferrari; F430; 2009-2005
 Land Rover; LR3; 2005
 Land Rover; Range Rover; 2005-2002
 Maserati; Coupe; 2006-2004
 Maserati; GranSport; 2006-2004
 Maserati; MC12; 2006
 Maserati; Quattroporte; 2006-2004
 Maserati; Spyder; 2006-2004
 Mercedes-Benz; CL55; 2006-2001
 Mercedes-Benz; CL65; 2006-2005
 Mercedes-Benz; CL500; 2006-2000
 Mercedes-Benz; CL600; 2006-2001
 Mercedes-Benz; E55; 2005-2000
 Mercedes-Benz; E55; 1999; Jul. & Newer
 Mercedes-Benz; E320; 2005-2001
 Mercedes-Benz; E430; 2002-2001
 Mercedes-Benz; E500; 2005-2003
 Mercedes-Benz; R550; 2008
 Mercedes-Benz; S55; 2006-2001
 Mercedes-Benz; S65; 2006
 Mercedes-Benz; S350; 2006
 Mercedes-Benz; S430; 2006-2000
 Mercedes-Benz; S500; 2006-2000



Numerical Listing

Service Packs

20037 - Continued

Mercedes-Benz; S600; 2006-2001
 Mercedes-Benz; SL55; 2005-2003
 Mercedes-Benz; SL65; 2005
 Mercedes-Benz; SL500; 2005-2001
 Mercedes-Benz; SL600; 2005-2004
 Mercedes-Benz; SL600; 2002-2001
 Mercedes-Benz; SLR McLaren; 2007-2004
 Mini; Cooper; 2010-2008
 Porsche; 911; 2011-2005
 Porsche; Boxster; 2011-2005
 Porsche; Carrera GT; 2006-2004
 Porsche; Cayenne; 2011-2008
 Porsche; Cayenne; 2006-2003
 Porsche; Cayman; 2011-2006
 Porsche; Panamera; 2011-2010
 Rolls-Royce; Phantom; 2010-2007
 Volkswagen; Phaeton; 2006-2004; W/315 MHz Sensor
 Volkswagen; Toureg; 2007-2004
 Volkswagen; Toureg 2; 2011; W/315 MHz Sensor
 Volkswagen; Toureg 2; 2010-2008

20038 (W/48mm Green Insert)



Audi; A4; 2008-2002
 Audi; A6; 2011-2005
 Audi; A8; 2010-2001
 Audi; Allroad Quattro; 2005-2001
 Audi; Q7; 2012-2007
 Audi; R8; 2012-2008
 Audi; RS4; 2008-2007
 Audi; S4; 2009-2004
 Audi; S6; 2011-2007
 Audi; S8; 2009-2007
 Audi; S8; 2003-2001
 Bentley; Continental; 2010-2003
 BMW; 128i; 2012-2008
 BMW; 135i; 2012
 BMW; 135i; 2010-2008
 BMW; 320i; 2005-2001
 BMW; 323Ci; 2000
 BMW; 323i; 2010-2007
 BMW; 323i; 2006; Jun. & Newer
 BMW; 323i; 2000
 BMW; 325Ci; 2006-2001
 BMW; 325i; 2006-2001
 BMW; 325Xi; 2006-2001
 BMW; 328Ci; 2000
 BMW; 328i; 2012-2007
 BMW; 328i; 2000
 BMW; 328Xi; 2008-2007
 BMW; 330Ci; 2006-2001
 BMW; 330i; 2006-2001
 BMW; 330Xi; 2006-2001
 BMW; 335D; 2012-2009
 BMW; 335i; 2012-2007
 BMW; 335iS; 2012
 BMW; 335Xi; 2008-2007

20038 - Continued

BMW; 525i; 2007-2001
 BMW; 525Xi; 2007-2006
 BMW; 528i; 2012
 BMW; 528i; 2010-2008
 BMW; 528i; 2000-1997
 BMW; 528Xi; 2008
 BMW; 530i; 2007-2001
 BMW; 530Xi; 2007-2006
 BMW; 535i; 2012-2008
 BMW; 535Xi; 2008
 BMW; 540i; 2003-1997
 BMW; 545i; 2005-2004
 BMW; 550i; 2012-2006
 BMW; 640i; 2012
 BMW; 645Ci; 2005-2004
 BMW; 650i; 2012
 BMW; 650i; 2010-2006
 BMW; 740i; 2012-2011
 BMW; 740i; 2001-1997
 BMW; 740iL; 2001-1997
 BMW; 740Li; 2012-2011
 BMW; 745i; 2005-2002
 BMW; 745Li; 2005-2002
 BMW; 750i; 2012-2006
 BMW; 750iL; 2001-1997
 BMW; 750Li; 2012-2006
 BMW; 760i; 2006-2004
 BMW; 760Li; 2010
 BMW; 760Li; 2008-2003
 BMW; Alpina B7; 2011
 BMW; Alpina B7; 2008-2007
 BMW; M1; 2012
 BMW; M3; 2010-2008
 BMW; M3; 2006-2001
 BMW; M5; 2010-2006
 BMW; M5; 2003-2000
 BMW; M6; 2010-2006
 BMW; X1; 2012
 BMW; X3; 2012
 BMW; X3; 2010-2006
 BMW; X5; 2012-2000
 BMW; X6; 2012
 BMW; X6; 2010-2008
 BMW; Z3; 2002-2000
 BMW; Z4; 2012-2003
 BMW; Z8; 2003-2000
 Bugatti; Veyron; 2006
 Ferrari; 550 Maranello; 2002-2001
 Ferrari; 575M Maranello; 2005-2002
 Ferrari; 612 Scaglietti; 2009-2004
 Ferrari; Enzo; 2004-2003
 Ferrari; F430; 2009-2005
 Land Rover; LR3; 2005
 Land Rover; Range Rover; 2005-2002
 Maserati; Coupe; 2006-2004
 Maserati; GranSport; 2006-2004
 Maserati; MC12; 2006
 Maserati; Quattroporte; 2006-2004
 Maserati; Spyder; 2006-2004
 Mercedes-Benz; CL55; 2006-2001
 Mercedes-Benz; CL65; 2006-2005
 Mercedes-Benz; CL500; 2006-2000
 Mercedes-Benz; CL600; 2006-2001
 Mercedes-Benz; E55; 2005-2000
 Mercedes-Benz; E55; 1999; Jul. & Newer



Numerical Listing

Service Packs

20038 - Continued

Mercedes-Benz; E320; 2005-2001
 Mercedes-Benz; E430; 2002-2001
 Mercedes-Benz; E500; 2005-2003
 Mercedes-Benz; R550; 2008
 Mercedes-Benz; S55; 2006-2001
 Mercedes-Benz; S65; 2006
 Mercedes-Benz; S350; 2006
 Mercedes-Benz; S430; 2006-2000
 Mercedes-Benz; S500; 2006-2000
 Mercedes-Benz; S600; 2006-2001
 Mercedes-Benz; SL55; 2005-2003
 Mercedes-Benz; SL65; 2005
 Mercedes-Benz; SL500; 2005-2001
 Mercedes-Benz; SL600; 2005-2004
 Mercedes-Benz; SL600; 2002-2001
 Mercedes-Benz; SLR McLaren; 2007-2004
 Mini; Cooper; 2010-2008
 Porsche; 911; 2011-2005
 Porsche; Boxster; 2011-2005
 Porsche; Carrera GT; 2006-2004
 Porsche; Cayenne; 2011-2008
 Porsche; Cayenne; 2006-2003
 Porsche; Cayman; 2011-2006
 Porsche; Panamera; 2011-2010
 Rolls-Royce; Phantom; 2010-2007
 Volkswagen; Phaeton; 2006-2004; W/315 MHz Sensor
 Volkswagen; Touareg; 2007-2004
 Volkswagen; Touareg 2; 2011; W/315 MHz Sensor
 Volkswagen; Touareg 2; 2010-2008

20039 (W/49mm Black Insert)



Audi; A4; 2008-2002
 Audi; A6; 2011-2005
 Audi; A8; 2010-2001
 Audi; Allroad Quattro; 2005-2001
 Audi; Q7; 2012-2007
 Audi; R8; 2012-2008
 Audi; RS4; 2008-2007
 Audi; S4; 2009-2004
 Audi; S6; 2011-2007
 Audi; S8; 2009-2007
 Audi; S8; 2003-2001
 Bentley; Continental; 2010-2003
 BMW; 128i; 2012-2008
 BMW; 135i; 2012
 BMW; 135i; 2010-2008
 BMW; 320i; 2005-2001
 BMW; 323Ci; 2000
 BMW; 323i; 2010-2007
 BMW; 323i; 2006; Jun. & Newer
 BMW; 323i; 2000
 BMW; 325Ci; 2006-2001
 BMW; 325i; 2006-2001
 BMW; 325Xi; 2006-2001
 BMW; 328Ci; 2000
 BMW; 328i; 2012-2007
 BMW; 328i; 2000
 BMW; 328Xi; 2008-2007
 BMW; 330Ci; 2006-2001
 BMW; 330i; 2006-2001
 BMW; 330Xi; 2006-2001
 BMW; 335D; 2012-2009
 BMW; 335i; 2012-2007
 BMW; 335iS; 2012
 BMW; 335Xi; 2008-2007
 BMW; 525i; 2007-2001
 BMW; 525xi; 2007-2006
 BMW; 528i; 2012
 BMW; 528i; 2010-2008
 BMW; 528i; 2000-1997
 BMW; 528xi; 2008
 BMW; 530i; 2007-2001
 BMW; 530xi; 2007-2006
 BMW; 535i; 2012-2008
 BMW; 535xi; 2008
 BMW; 540i; 2003-1997
 BMW; 545i; 2005-2004
 BMW; 550i; 2012-2006
 BMW; 640i; 2012
 BMW; 645Ci; 2005-2004
 BMW; 650i; 2012
 BMW; 650i; 2010-2006
 BMW; 740i; 2012-2011
 BMW; 740i; 2001-1997
 BMW; 740iL; 2001-1997
 BMW; 740Li; 2012-2011
 BMW; 745i; 2005-2002
 BMW; 745Li; 2005-2002
 BMW; 750i; 2012-2006
 BMW; 750iL; 2001-1997
 BMW; 750Li; 2012-2006
 BMW; 760i; 2006-2004
 BMW; 760Li; 2010
 BMW; 760Li; 2008-2003
 BMW; Alpina B7; 2011
 BMW; Alpina B7; 2008-2007
 BMW; M1; 2012
 BMW; M3; 2010-2008
 BMW; M3; 2006-2001
 BMW; M5; 2010-2006
 BMW; M5; 2003-2000
 BMW; M6; 2010-2006
 BMW; X1; 2012
 BMW; X3; 2012
 BMW; X3; 2010-2006
 BMW; X5; 2012-2000
 BMW; X6; 2012
 BMW; X6; 2010-2008
 BMW; Z3; 2002-2000
 BMW; Z4; 2012-2003
 BMW; Z8; 2003-2000
 Bugatti; Veyron; 2006
 Ferrari; 550 Maranello; 2002-2001
 Ferrari; 575M Maranello; 2005-2002
 Ferrari; 612 Scaglietti; 2009-2004
 Ferrari; Enzo; 2004-2003
 Ferrari; F430; 2009-2005
 Land Rover; LR3; 2005
 Land Rover; Range Rover; 2005-2002
 Maserati; Coupe; 2006-2004
 Maserati; GranSport; 2006-2004

20039 - Continued

PRINTED ON RECYCLED PAPER
 WITH 100% POSTCONSUMER WASTE



Numerical Listing

Service Packs

20039 - Continued

Maserati; MC12; 2006
 Maserati; Quattroporte; 2006-2004
 Maserati; Spyder; 2006-2004
 Mercedes-Benz; CL55; 2006-2001
 Mercedes-Benz; CL65; 2006-2005
 Mercedes-Benz; CL500; 2006-2000
 Mercedes-Benz; CL600; 2006-2001
 Mercedes-Benz; E55; 2005-2000
 Mercedes-Benz; E55; 1999; Jul. & Newer
 Mercedes-Benz; E320; 2005-2001
 Mercedes-Benz; E430; 2002-2001
 Mercedes-Benz; E500; 2005-2003
 Mercedes-Benz; R550; 2008
 Mercedes-Benz; S55; 2006-2001
 Mercedes-Benz; S65; 2006
 Mercedes-Benz; S350; 2006
 Mercedes-Benz; S430; 2006-2000
 Mercedes-Benz; S500; 2006-2000
 Mercedes-Benz; S600; 2006-2001
 Mercedes-Benz; SL55; 2005-2003
 Mercedes-Benz; SL65; 2005
 Mercedes-Benz; SL500; 2005-2001
 Mercedes-Benz; SL600; 2005-2004
 Mercedes-Benz; SL600; 2002-2001
 Mercedes-Benz; SLR McLaren; 2007-2004
 Mini; Cooper; 2010-2008
 Porsche; 911; 2011-2005
 Porsche; Boxster; 2011-2005
 Porsche; Carrera GT; 2006-2004
 Porsche; Cayenne; 2011-2008
 Porsche; Cayenne; 2006-2003
 Porsche; Cayman; 2011-2006
 Porsche; Panamera; 2011-2010
 Rolls-Royce; Phantom; 2010-2007
 Volkswagen; Phaeton; 2006-2004; W/315 MHz Sensor
 Volkswagen; Touareg; 2007-2004
 Volkswagen; Touareg 2; 2011; W/315 MHz Sensor
 Volkswagen; Touareg 2; 2010-2008

20040 (W/51mm Orange Insert)



Audi; A4; 2008-2002
 Audi; A6; 2011-2005
 Audi; A8; 2010-2001
 Audi; Allroad Quattro; 2005-2001
 Audi; Q7; 2012-2007
 Audi; R8; 2012-2008
 Audi; RS4; 2008-2007
 Audi; S4; 2009-2004
 Audi; S6; 2011-2007
 Audi; S8; 2009-2007
 Audi; S8; 2003-2001
 Bentley; Continental; 2010-2003
 BMW; 128i; 2012-2008
 BMW; 135i; 2012
 BMW; 135i; 2010-2008
 BMW; 320i; 2005-2001
 BMW; 323i; 2000

20040 - Continued

BMW; 323i; 2010-2007
 BMW; 323i; 2006; Jun. & Newer
 BMW; 323i; 2000
 BMW; 325Ci; 2006-2001
 BMW; 325i; 2006-2001
 BMW; 325xi; 2006-2001
 BMW; 328Ci; 2000
 BMW; 328i; 2012-2007
 BMW; 328i; 2000
 BMW; 328xi; 2008-2007
 BMW; 330Ci; 2006-2001
 BMW; 330i; 2006-2001
 BMW; 330xi; 2006-2001
 BMW; 335D; 2012-2009
 BMW; 335i; 2012-2007
 BMW; 335is; 2012
 BMW; 335xi; 2008-2007
 BMW; 525i; 2007-2001
 BMW; 525xi; 2007-2006
 BMW; 528i; 2012
 BMW; 528i; 2010-2008
 BMW; 528i; 2000-1997
 BMW; 528xi; 2008
 BMW; 530i; 2007-2001
 BMW; 530xi; 2007-2006
 BMW; 535i; 2012-2008
 BMW; 535xi; 2008
 BMW; 540i; 2003-1997
 BMW; 545i; 2005-2004
 BMW; 550i; 2012-2006
 BMW; 640i; 2012
 BMW; 645Ci; 2005-2004
 BMW; 650i; 2012
 BMW; 650i; 2010-2006
 BMW; 740i; 2012-2011
 BMW; 740i; 2001-1997
 BMW; 740il; 2001-1997
 BMW; 740li; 2012-2011
 BMW; 745i; 2005-2002
 BMW; 745li; 2005-2002
 BMW; 750i; 2012-2006
 BMW; 750il; 2001-1997
 BMW; 750li; 2012-2006
 BMW; 760i; 2006-2004
 BMW; 760li; 2010
 BMW; 760li; 2008-2003
 BMW; Alpina B7; 2011
 BMW; Alpina B7; 2008-2007
 BMW; M1; 2012
 BMW; M3; 2010-2008
 BMW; M3; 2006-2001
 BMW; M5; 2010-2006
 BMW; M5; 2003-2000
 BMW; M6; 2010-2006
 BMW; X1; 2012
 BMW; X3; 2012
 BMW; X3; 2010-2006
 BMW; X5; 2012-2000
 BMW; X6; 2012
 BMW; X6; 2010-2008
 BMW; Z3; 2002-2000
 BMW; Z4; 2012-2003
 BMW; Z8; 2003-2000
 Bugatti; Veyron; 2006
 Ferrari; 550 Maranello; 2002-2001



Numerical Listing

Service Packs

20040 - Continued

Ferrari; 575M Maranello; 2005-2002
Ferrari; 612 Scaglietti; 2009-2004
Ferrari; Enzo; 2004-2003
Ferrari; F430; 2009-2005
Land Rover; LR3; 2005
Land Rover; Range Rover; 2005-2002
Maserati; Coupe; 2006-2004
Maserati; GranSport; 2006-2004
Maserati; MC12; 2006
Maserati; Quattroporte; 2006-2004
Maserati; Spyder; 2006-2004
Mercedes-Benz; CL55; 2006-2001
Mercedes-Benz; CL65; 2006-2005
Mercedes-Benz; CL500; 2006-2000
Mercedes-Benz; CL600; 2006-2001
Mercedes-Benz; E55; 2005-2000
Mercedes-Benz; E55; 1999; Jul. & Newer
Mercedes-Benz; E320; 2005-2001
Mercedes-Benz; E430; 2002-2001
Mercedes-Benz; E500; 2005-2003
Mercedes-Benz; R550; 2008
Mercedes-Benz; S55; 2006-2001
Mercedes-Benz; S65; 2006
Mercedes-Benz; S350; 2006
Mercedes-Benz; S430; 2006-2000
Mercedes-Benz; S500; 2006-2000
Mercedes-Benz; S600; 2006-2001
Mercedes-Benz; SL55; 2005-2003
Mercedes-Benz; SL65; 2005
Mercedes-Benz; SL500; 2005-2001
Mercedes-Benz; SL600; 2005-2004
Mercedes-Benz; SL600; 2002-2001
Mercedes-Benz; SLR McLaren; 2007-2004
Mini; Cooper; 2010-2008
Porsche; 911; 2011-2005
Porsche; Boxster; 2011-2005
Porsche; Carrera GT; 2006-2004
Porsche; Cayenne; 2011-2008
Porsche; Cayenne; 2006-2003
Porsche; Cayman; 2011-2006
Porsche; Panamera; 2011-2010
Rolls-Royce; Phantom; 2010-2007
Volkswagen; Phaeton; 2006-2004; W/315 MHz Sensor
Volkswagen; Touareg; 2007-2004
Volkswagen; Touareg 2; 2011; W/315 MHz Sensor
Volkswagen; Touareg 2; 2010-2008



Notes



PRINTED ON RECYCLED PAPER
WITH 100% POSTCONSUMER WASTE

Notes



SCHRADER-USA

205 FRAZIER ROAD
ALTAVISTA, VA 24517

CUSTOMER SUPPORT LINE // 1.800.288.1804 ►► SCHRADERINTERNATIONAL.COM